1. No.	2. County	3. Location of No	legatives 4. Current Name(s)
45	Audrain	MCRI	Action Security
5. Other	Name(s)	6a. Township 6b. Range	e 6c. Section 6d. Street Address
Penny Un	nstattd Cope, PC	T51N R9W	26 112 & 110 North Clark
7. City or	Town	7b, Vicinit 8. Descriptio	on of Location 9. UTM Coordinates
Mexico		SW 1/4 of L	Lot 3 Block 13,
10a. Site	10b. Building 10c.	Structure I Od. Objec 11.	On National Register? 12, Is it eligible? 13. Part of Historic District
14. Distrir	ct Potential? 15. Na	me of District 16	5. Thematic Category
17. Date(s) or Period	18. Style or Design	19. Architect or Engineer
circa 194			
20. Contr	ractor or Bullder	21. Original Use	22. Present Use
		commercial	commercial
23. Owne	ership	24. Owner's Name and	Address 25. Open to Public
private	•		Jefferson, Mexico MO 65265
26. Local	Contact Person or C	Organization	27. Other Surveys in Which Included
Lura Willi			n/a
28. No. c	of Storie 29. Baseme	ent 30. Foundation Material	1 31. Wall Construction
1		brick	brick
Roof Type	e and Material	33a. No. of Bays, front	33b. No. of bays, side
flat/aspha		4	
	Treatment	35. Plin Shape	36a. Changes, addition (see 42) 36b. Changes, altered (see 42
brick		rectangular	
	mayed (see 42) 37	a. Condition, Interior	37b. Condition, Exterior 38. Preservation underway?
	The state of the s		
TQa. Fn/s	angered 39b. Endar	ngered by what? 40 V	/isible from public road?
	777.	✓	
41. Dierar	nce from and frontag	re on road	
42 Furth	er Description of Im	nortant Fratures	
and the second s			a window between it and the corner. One window
is a 54 lis	ght stationary and t		. A brick panel runs along the fascade above the
	d windows.		
	ry and Significance		ad "OV Pubba Waldam" Is has been as 550
	ie 1940's for tire red ince circa 1960.	Capping, by 1947 it was calle	ed "OK Rubber Welders". It has been an office
			- Company of the Comp
1000 - 1000 - 1 Aug 1 g 7 Aug 12 Aug	iption of Environme	nt and Outbuildings	
4000.0000a.i.i.g.,g.,n.a.eeiidi	V	nt and Outbuildings	
	V	nt and Outbuildings	
44. Descri	lption of Environme		
44. Descri	iption of Environment	48. Prepared by	47: Organization
44. Descri	iption of Environment res of Information Maps, G. Craddock,		



1. No. 2. County	3. Loca	tion of Negative	s 4. Current Name(s)		
44 Audrain	MCRI		Foster Muffler	7 N. 35 V. 3 Grand	
5. Other Name(s)	6a. Township	6b. Range 6c.	Section 6d. Street Address		
	T51N	R9W 26	116 North Clark		
7. City or Town	7b. Vicinit 8.	Description of L	ocation 9. UTM Coord	inates	
Mexico	□ w	74' of Lot 3 &	W 74' of Lo		
10a. Site 10b. Building 10c.	Structure 10d. Ob	jec 11. On Na	ational Register? 12. Is it eligi	ble? 13. Part of Histo	oric District
				у Дорогия	
14. District Potential? 15. Na	ame of District	16. Ther	natic Category		
17. Date(s) or Period	18. Style or De	sign	19. Architect or Engineer		
circa 1925					
20. Contractor or Builder	21. Original Us		22. Present Use		
	commercial		commerical	193	
23. Ownership	24. Owner's N			25. Open to	Public
private		O-053 Highway	E, Centralia MO 65240	V	
26. Local Contact Person or C	Organization		27. Other Surveys in Which	Included	
Lura Williams			n/a		
28. No. of Storie 29. Basem	ent 30. Foundation	i Material	31. Wall Construction		
1 📙 🚉	concrete		concrete block		
Roof Type and Material	33a. No. of Ba	s, front	33b. No. of bays, side		
flat/asphalt	4	and the second s	3	4	
34. Wall Treatment	35. Plan Shape		36a. Changes, addition (see	42) 36b. Changes,	altered (see 4)
painted concrete block	rectangular			V	
Changes, moved (see 42) 37	7a. Condition, Inter	or 37b	. Condition, Exterior	38. Preservation unde	rway?
	-			-	
39a, Endangered 39b, Enda	ngered by what?	the state of the state of the state of	rom public road?		
	8. AN (1980 A 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1	V			
41. Distance from and frontag	ge on road				
	58.58.58.0° <u>2</u> .5°		. (2002)		
42. Further Description of Im			l course dear with a first of	or onto	
plate glass canted corner wind between them and the corner				or entry	
				<u> </u>	
43. History and Significance					
This building first appears on station. In the 1980's it because			n. By 1935 it was a Standard	Oil service	
Station. In the 1980's it Deca	anie a service statior	i olliy.			
44. Description of Environme	nt and Outbuilding				
			,		
45. Sources of Information	46. Prepared by		47. Organization		
Sanborn Maps, G. Craddock,			City of Mexico		
	vision Date(s)	a garaga			
3/10/2002	POUR Derelot				
				And the second s	



1. No. 2. County	3. Loc	ation of N	Neaatives	4. Current Name(s	5]
01 Audrain	MCRI			208 North Clark		
5. Other Name(s)	6a. Township	6b. Ranc	o 6c. Sec	otio od Street Address		
	T51N	R9W	26	208 Clark		
7. City or Town	7b. Vicinit 8.	Descripti	on of Loc	ation 9. UTM Coordi	nates	
Mexico	The same of the sa	54' of Lot				
10a. Site 10b. Buildin 10c. S	Structur 10d O	bie 117	On Natio	nal Register 12. Is it eligib	ole 13. Part of	Historic District
	L. U.			usa Unas i	<u> Б</u> П 199	
14. District Potential 15. Na	me of District	16	. Themat	ic Category		
17. Date(s) or Period	18. Style or D	esign	ī	9. Architect or Engineer	112	
circa 1920	vernacular			•		
20. Contractor or Builder	21. Original U	lse	2	2. Present Use		
	residence		3	esidence		
23. Ownership	24. Ovener's N	lame and	d Address		25, Op€	n to Publi
private	Dan Erdel, 10	03 West M	lonroe, M	lexico MO 65265	LI,	
26. Local Contact Person o	r Organization		27	Other Surveys in Which	n Included	
Lura Williams			n/	/a		
28. No. of Stories 29. Basemi	en 30. Foundati	on Mater	ial 3	31. Wall Construction		
1	brick		\	wood frame		
Roof Type and Material	33a. No. of B	ays, front	3	3b, No. of bays, side		144
gable, asphalt shingles	5		2			
34. Wall Treatment	35. Pkan Shap	ЭӨ		6a. Changes, addition (see 36b. Cha	nges, altered (:
siding	irregular		·		∠	
Changes, moved (see 37a	a. Condilion, Int	erior	37b. C	ondition, Exterior	38. Preservation	underwa
		······································				
39a. Endangere 39b. Enda	ngered by what		sible from	public road?		
	and a succession of the contradition of the co	<u> </u>				
41. Distance from and front	age on 'oad					
						
42. Further Description of Im						
addition built circa 1940 ar	nd asbestos sidir	ng added	d circa 19	260.	:	
43. History and Significance					18 18 18 18 18 18 18 18 18 18 18 18 18 1	
This house started out as a :	single family dw	elling but	has beer	n rental property since c	circa 1970.	
44. Description of Environme	ent and Outbuild	dings				
at ou many resultant and the	AL DISCOULT	h.r	, i	7 Oranolyatica		
45. Sources of Information Sanborn Maps, Dan Erdel, C	46. Prepared	Committee of the second		7. Organization City of Mexico		
		.0.1011			3941 1990. Sell	
48. Date 49. Rev 2/18/2002	ision Date(s					
L, 10/2002						



1. No. 2. County	3. Location of Negat	tives 4. Current Name(s)					
24 Audrain	MCRI	105 North Coal					
5. Other Name(s)	6a. Townshi 6b. Rang 6c.	Sectio 6d. Street Address					
Smith Brothers' Hatchery	T51N R9W 26	105 North Coal					
7. City or Town	7b. Vicini 8. Description of	F Location 9. UTM Coordinates					
Mexico	S 6.5' of Lot 2, a						
10a. Sit 10b. Buildin 10c. St	ructu 10d. Objec 11. On Na	itional Regist 12. Is it eligibl 13. Part of Historic Distr					
<u> </u>							
14. District Potenti 15. Name	e of District 16. Ther	matic Category					
V							
17. Date(s) or Period	18. Style or Design	19. Architect or Engineer					
circa 1917							
20. Contractor or Builder	21. Original Use	22. Present Use					
20. Contractor or Bando.	commercial	vacant					
23. Ownership	24. Owner's Name and Add						
private	والمستحد والمستحدين والمستحدث والمستحدث والمراجع والمستحدث والمستح	5 North Coal, Mexico MO 65265					
26. Local Contact Person or							
Lura Williams	Di gariizacion	27. Other Surveys in Which included					
	70 Foundation Material	<u></u>					
28. No. of Stori 29. Baseme	30. Foundation Material	31. Wall Construction					
Roof Type and Material	33a. No. of Bays, front	33b. No. of bays, side					
flat/asphalt	8						
34. Wall Treatment	35. Plan Shape	36a. Changes, addition (see 36b. Changes, altered (see					
brick	rectangular						
Changes, moved (see 37a.	Condition, Interior 37b	. Condition, Exterior 38. Preservation underw					
39a. Endangere 39b. Endang		from public road?					
	<u> </u>						
41. Distance from and fronta	age on road						
42. Further Description of In	nportant Features						
		windows on the first floor with burick					
them, corbeiling, and corbe	Batures five windows with to light dentils along the roof!	orick lug sills, three brick panels above					
43. History and Significance	nea actuis along the room	ne.					
	n a map in 1926 as a hatche	ry. It was Smith Brothers' Hatchery					
until circa 1960. It became a	a bowling alley and then in t	the 1970's a restaurant. One Eyed					
Willie's and Barbary Coast were the last occupants.							
44. Description of Environm	ent and Outbuildings						
1							
45. Sources of Information	46. Prepared by	47. Organization					
Sanborn Maps, G. Craddock	Mary Aue Mitchell	City of Mexico					
48. Date 49. Revis	lon Date(•					
3/1/2002							



Missouri Historic/Architectural Inventory Form 2. County 3. Location of Negatives 4. Current Name(s) Audrain Coal Street Antiques 5. Other Name(s) 6a. Township 6b. Rang 6c. Sectio 6d. Street Address 111 North Coal T51N R9W 26 7b. Vicinit 8. Description of Location 9. UTM Coordinates 7. City or Town Lot 2, Block 12, except N 6,5' Mexico 10a. Site 10b. Buildin 10c. Structur 10d. Obje 11. On National Register 12. Is it eligible 13. Part of Historic District 14. District Potential 15. Name of District 16. Thematic Category 18. Style or Design 19. Architect or Engineer 17. Date(s) or Period circa 1892 20. Confractor or Bullder 21. Original Use 22. Present Use commercial commerical 23. Ownership 24. Owner's Name and Address 25. Open to Publi Pat Lawrence, 1304 Rosebud, Mexico MO 65265 27. Other Surveys in Which Included 26, Local Contact Person or Organization Lura Williams n/a 28. No. of Stories 29. Basemen 30. Foundation Material 31. Wall Construction brick: brick 33a. No. of Bays, front 33b. No. of bays, side Roof Type and Material flat/asphalt 34. Wall Treatment 35, Plan Shape 36a. Changes, addition (see 36b. Changes, attered (see rectangular painted brick Changes, moved (see 37a. Condition, Interior 37b. Condition, Exterior 38. Preservation underwa 39a. Endangere 39b. Endangered by what? 40. Visible from public road? 41. Distance from and frontage on road 42. Further Description of Important Features recessed arched doorway, a barn door filling in a garage door center and a recessed door near the corner of the building. Stationary display windows with lug sills. Six 10 light stationary windows at the roof line as well as one 6 light casement window. 43. History and Significance The earliest map - 1894 - shows it as an agricultural implement store. 1899, 1908, 1914 no change. 1926 shows it as Mexico Fruit Wholesale House and 1934 lists it as Wetterau wholesale grocery. It became a part of Cline's Furniture (cont.) 44. Description of Environment and Outbuildings 47. Organization 45, Sources of Information 46, Prepared by Sanborn Maps, G. Craddock Mary Aue Mitchell City of Mexico 49. Revision Date(s 48. Date

23

111 North Coal

- 44. Store in the 1970's. Circa 1990 it became Coal Street Antiques which is primarily a wholesale business.
- 45. City Directories, Telephone Books



1. No. 2. County	3. Loc	ation of Negat	lives	4. Current Name(s)		
34 Audrain	MCRI			Audrain County Cour	thouse	
5. Other Name(s)	6a. Township	6b. Rang 6c.	Sectio	6d. Street Address		
	T51N	R9W 26		Courthouse Square		
7. City or Town	7b. Vicinit 8.	Description of	Locatio	n 9. UTM Coordinate	∍s	
Mexico		ourthouse Squ				
10a. Site 10b. Bulldin 10c. St	ructur 10d.O	bje 11. On No	ational F	egister 12, Is it eligible	13. Part of H	Istoric District
		Ш		V		
14. District Potential 15. Nam	e of District	16. Ther	natic Co	afegory		
⊻						
17. Date(s) or Period	18, Style or D		4	chitect or Engineer		
1951	Art Moderne		Bonso	ack and Pearce, St. Lou	is MO	
20. Contractor or Builder	21. Original U			esent Use		
John Epple and Sons, Colum	government	al .	gove	rnmental		
23. Ownership		lame and Ado	m.v/codestantantantantantanta		25. Open	to Publi
public		nty Governme	ent, Mexi	co MO 65265	<u> </u>	
26. Local Contact Person or 0	Organization			ner Surveys in Which Inc	luded	
Lura Williams	A		n/a			
28, No. of Stories 29, Basemer	n 30. Foundati	on Material		/all Construction		185
3 ✓	concrete		brick			3.00
Roof Type and Material	33a, No, of B	ays, front	33b. I	lo, of bays, side		
flat/asphalt	11		11		-	
34. Wall Treatment	35. Plan Shap	Ө	36a. (Changes, addition (see	36b. Chan	ges, altered (se
brick	square		Ш		Ш	
Changes, moved (see 37a.	Condition, Int	erior 37t	o. Condi	tion, Exterior 38. F	reservation	underwa
			Salara Cara Salara	1_1		
39a. Endangere 39b. Endang	gered by what	? 40. Visible t	from pul	olic road?	15	
	502.230 1 No. 1000 - 1000 - 1000 - 1000 - 1000 - 1000 - 1000 - 1000 - 1000 - 1000 - 1000 - 1000 - 1000 - 1000 - 1000 - 1000 - 1000 - 1000 - 1000 - 1000 - 1000 - 1000 - 1000 - 1000 - 1000 - 1000 - 1000 - 1000 - 1000 - 1000 - 1000 - 1000 - 1000 - 1000 - 1000 - 1000 - 1000 - 1000 - 1000 - 1000 - 1000 - 1000 - 1000 - 1000 - 1000 - 1000 - 1000 - 1000 - 1000 - 1000 - 1000 - 1000 - 1000 - 1000 - 1000 - 1000 - 1000 - 1000 - 1000 - 1000 - 1000 - 1000 - 1000 - 1000 - 1000 - 1000 - 1000 - 1000 - 1000 - 1000 - 1000 - 1000 - 1000 - 1000 - 1000 - 1000 - 1000 - 1000 - 1000 - 1000 - 1000 - 1000 - 1000 - 1000 - 1000 - 1000 - 1000 - 1000 - 1000 - 1000 - 1000 - 1000 - 1000 - 1000 - 1000 - 1000 - 1000 - 1000 - 1000 - 1000 - 1000 - 1000 - 1000 - 1000 - 1000 - 1000 - 1000 - 1000 - 1000 - 1000 - 1000 - 1000 - 1000 - 1000 - 1000 - 1000 - 1000 - 1000 - 1000 - 1000 - 1000 - 1000 - 1000 - 1000 - 1000 - 1000 - 1000 - 1000 - 1000 - 1000 - 1000 - 1000 - 1000 - 1000 - 1000 - 1000 - 1000 - 1000 - 1000 - 1000 - 1000 - 1000 - 1000 - 1000 - 1000 - 1000 - 1000 - 1000 - 1000 - 1000 - 1000 - 1000 - 1000 - 1000 - 1000 - 1000 - 1000 - 1000 - 1000 - 1000 - 1000 - 1000 - 1000 - 1000 - 1000 - 1000 - 1000 - 1000 - 1000 - 1000 - 1000 - 1000 - 1000 - 1000 - 1000 - 1000 - 1000 - 1000 - 1000 - 1000 - 1000 - 1000 - 1000 - 1000 - 1000 - 1000 - 1000 - 1000 - 1000 - 1000 - 1000 - 1000 - 1000 - 1000 - 1000 - 1000 - 1000 - 1000 - 1000 - 1000 - 1000 - 1000 - 1000 - 1000 - 1000 - 1000 - 1000 - 1000 - 1000 - 1000 - 1000 - 1000 - 1000 - 1000 - 1000 - 1000 - 1000 - 1000 - 1000 - 1000 - 1000 - 1000 - 1000 - 1000 - 1000 - 1000 - 1000 - 1000 - 1000 - 1000 - 1000 - 1000 - 1000 - 1000 - 1000 - 1000 - 1000 - 1000 - 1000 - 1000 - 1000 - 1000 - 1000 - 1000 - 1000 - 1000 - 1000 - 1000 - 1000 - 1000 - 1000 - 1000 - 1000 - 1000 - 1000 - 1000 - 1000 - 1000 - 1000 - 1000 - 1000 - 1000 - 1000 - 1000 - 1000 - 1000 - 1000 - 1000 - 1000 - 1000 - 1000 - 1000 - 1000 - 1000 - 1000 - 1000 - 1000 - 1000 - 1000 - 1000 - 1000 - 1000 - 1000 - 1000 - 1000 - 1000 - 1000 - 1000 - 1000 - 1000 - 10	A		15.79		
41. Distance from and fronta	ge on road					
	Ca	2 24,4600 k				
42. Further Description of Imp						
recessed entrance with a sto carvings. Beyond each pillas					'a	
carved cornice. The window					3	
43. History and Significance						
This is the third courthouse to						
unsafe and too small. This or except for the ramp added t				.300. It has remained ui	naltered	
44. Description of Environmen	Control of the Contro	estable of the control of the contro	/			
- Joyospierios camo mos						
No. 35 cm	40.2.2.2.2.2.2.2.2.2.2.2.2.2.2.2.2.2.2.2				i de verse	
45. Sources of Information	46. Prepared		_	ganization		
Sanborn Maps, "Audrain Co	Mary Aue Mi	icneii	Louis	of Mexico		
	on Date(s					
3/4/2002						

1. No. 2. County	3. Location of Ne	gatives 4. Current Name(s)			
34 Audrain	MCRI	Audrain County Courthouse			
5. Other Name(s)	6a. Townshi 6b. Rang	6c. Sectio 6d. Street Address			
		26 Courthouse Square			
7. City or Town	7b. Vicini 8. Description	n of Location 9. UTM Coordinates			
Mexico ,	Courthouse 9	Square			
10a. Sit 10b. Buildin 10c	Structu 10d. Objec 11. On	National Regist 12. is it eligibl 13. Part of Historic Distr			
14. District Potenti 15. N	ame of District 16. T	hematic Category			
✓					
17. Date(s) or Period	18. Style or Design	19. Architect or Engineer			
1951	Art Deco	Bonsack and Pearce, St. Louis MO			
20. Contractor or Builder	21. Original Use	22. Present Use			
John Epple and Sons, Co		governmental			
23. Ownership	24. Owner's Name and A				
public		ment, Mexico MO 65265			
26. Local Contact Person		27. Other Surveys in Which Included			
Lura Williams		n/a			
28. No. of Stori 29. Baser	ne 30. Foundation Materia	I 31. Wall Construction			
3	concrete	brick			
Roof Type and Material	33a. No. of Bays, front	33b. No. of bays, side			
flat/asphalt	111	11			
34. Wall Treatment	35. Plan Shape	36a. Changes, addition (see 36b. Changes, altered (see			
brick	square	Soa. Changes, addition (see Sob. Changes, artered (see			
		37b. Condition, Exterior 38. Preservation underw			
Changes, moved too	a. Contained I, Miccirio.	57 S. CONTRICTOR, EXCEPTOR			
39a. Endangere 39b. End	angered by what? 40 Visit	ple from public road?			
Joa. Endangere Job. End	7. 190.00 by White: 40. 110.0	ore from public road:			
41. Distance from and from	ntage on road				
- 1. Distance in Oill and II C	TIMES OF TOOL				
42. Further Description of	f Important Features				
	· · · · · · · · · · · · · · · · · · ·	e and topped by a clock and stone			
		o story pillaster. These are topped by a			
	dows are 1/1 double hung a				
43. History and Significar		We the state of th			
		previous courthouse was considered to			
	ramp added to the south e	at a cost of \$527,300. It has remained			
44. Description of Enviro					
		<u> </u>			
	,				
AP Courses of information	an AC Theorem de les	47 Owner tradion			
45. Sources of Information Sanborn Maps, "Audrain		47. Organization City of Mexico			
		City of Mexico			
	evision Date(
3/4/2002					

#34

Audrain County Memorial Courthouse Courthouse Square

42.

There are 12 windows on the first story on each side of the building and 13 windows on each of the second and third stories on each side. Each side on the building is identical with the exception of the east side which has a ramp replacing the stairs at the entrance.

- 43. in 1990. This virtually intact building dominates the courthouse square and is the seat of county government.
- 45 Missouri, 1945-2000" by Gayle Messer, "Encyclopedia of Missouri Courthouses" by University of Missouri.

















1. No.	2. County	3, Location of Ne	gatives 4 Current Name(s)	J
31	Audrain	MCRI	Farm Bureau Insurance Service	98
5. Other	Name(s)	6a. Township 6b. Rang	6c. Sectio 6d. Street Address	
		T51N R9W	26 113 East Jackson	
7. City or	Town	7b. Vicinit 8. Description	of Location 9, UTM Coordinates	No.
Mexico		W 24' Lot 4, B	lock 12	Marin January (1997)
10a. Site	10b. Buildin 10c.	Structur 10d. Obje 11. Or	n National Register 12: Is it eligible 13, Part o	of Historic District
Ш		ļ . "U.,		
14. Distric	ct Potential 15. Na	me of District 6. Ti	hematic Category	
✓				
17. Date	(s) or Period	18. Style or Design	19. Architect or Engineer	
circa 189	92			
20. Cont	ractor or Bullder	21. Orlginal Use	22. Present Use	
		commercial	commercial	
23. Owne	ership	24. Owner's Name and A	Actoress 25. Op	oen to Publi
private		Missouri Farm Bureau, PC	D Box 431, Mexico MO 65265	
26. Loca	l Contact Person o	r Organization	27. Other Surveys in Which included	
Lura Willi	ams		n/a	
28. No. o	f Stories 29. Basem	en 30. Foundation Material	31. Wall Construction	
1		stone	brick	
Roof Typ	e and Material	33a No. of Bays, front	33b. No. of bays, side	
flat/asph	nalt	3	4	
34, Wall T	reatment	35. Plan Shape	36a. Changes, addition (see 36b. Ch	anges, altered (see
brick		rectangular		
Change	s, moved (see 37	a. Condition, Interior	37b. Condition, Exterior 38. Preservati	on underwa
39a. End	angere 39b. Enda	ngered by what? 40. Visib	ole from public road?	
			or the Control of the	
41. Distar	nce from and front	age on road		
			-	
42. Furthe	er Description of Im	portant Features		
			stationary window on each side. These	
windows	replace larger on a as well as brick o	e that nave been partially f corbelled dentals at roofline	illed in. Above the windows are two rows o	
coccession of the contract of the co-	y and Significance	provided 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1		
			printing shop. 1899, 1908, 1914, no	
change.	1926 it was a vari	ety store. In 1932 the buildir	ng shows as vacant. In the 1940's and	Sept.
No. 1 1 10 10 10 10 10 10 10 10 10 10 10 10	was Tolson's Came	Annual Control of the	The state of the s	_
44. Descr	iption of Environm	ent and Outbuildings		
	gasonco			
	***************************************	46. Prepared by	47. Organization	
Sanborn	Maps, G. Craddoo	ck Mary Aue Mitchell	City of Mexico	
48. Date		ision Date(s		
3/3/2002				
AND TO CALL WAS ARREST				

AU-AS-001 007

Missouri Historic/Architectural Inventory Form City of Mexico/HPF FY 2001 Grant #29-01-16425-534 Continuation Sheet

#31

113 East Jackson

43. In the 1960's and 1970's this building housed an Antique store before becoming Insurance offices circa 1985.

45 City Directories, Telephone Books



1. No. 2. County	3. Location of f	Negatives 4: Current Name(s)
32 Audrain	MCRI	Leonatti & Baker PC Attorneys
5. Other Name(s)	6a. Township 6b. Rang	g 6c. Sectio 6d. Street Address
	T51N R9W	26 123 East Jackson
7. City or Town	7b. Vicinit 8. Descripti	ion of Location 9. UTM Coordinates
Mexico	E 1/2 of Lo	rt 4, Block 12
	Structur 10d. Obje 11.	On National Register 12. Is it eligible 13. Part of Historic District
14. District Potential 15. Nar	me of District 16	6. Thematic Category
17. Date(s) or Period	18. Style or Design	19. Architect or Engineer
circa 1890	romanesque	
20. Contractor or Builder	21. Örlginal Use	22. Present Use
	commercial	commercial
23. Ownership	24. Ciwner's Name and	d Address 25. Open to Publi
private	Leonatti & Baker, 123	East Jackson, Mexico MO 65265
26. Local Contact Person or	Organization	27. Other Surveys in Which Included
Lura Williams		n/a
28. No. of Stories 29. Baseme	en 30. Foundation Mate	rial 31. Wall Construction
1	stone	brick
Roof Type and Material	33a. No. of Bays, front	33b. No. of bays, side
flat/asphalt	9	
34. Wall Treatment	35. Plan Shape	36a. Changes, addition (see 36b. Changes, altered (see
brick	rectangular	
Changes, moved (see 37a	a. Conclition, Interior	37b. Condition, Exterior 38. Preservation underwa
	3300.330 _ A.D	
39a, Endangere 39b, Endar		/isible from public road?
	<u> </u>	
41. Distance from and front	age on road	
42. Further Description of Im	portan Features	
		vindow on each side. A fixed metal awning
covers the entry and these balistrade.	two windows. Above th	ne awning are three brick panels and a stone
43. History and Significance		
	ows this to be an office b	ouilding, It has remained an office building its
		nen the maps indicate it was a store. It was
primarily doctors' offices un 44. Description of Environme		
	an die Onbaldigs	
45. Sources of Information	46. Prepared by	47. Organization
Sanborn Maps, G. Craddoc		City of Mexico
	sion Date(s	
3/3/2002		

#32

- 123 East Jackson
- 43. it became the office of the Audrain Abstract Company. In the 1980's it became law offices.,
- 45 City Directories, Telephone Books



1. No. 2. County 33 Audrain	3. Location of No	egatives 4. Current Name(s)
Nuarain	MCRI	Leonatti & Baker PC Attorneys 2
5. Other Name(s)	6a. Township 6b. Rang	6c. Sectio 6d. Street Address
	T51N R9W	26 123 East Jackson 2
7. City of Town	7b. Vicinit 8. Descriptio	n of Location 9. UTM Coordinates
Mexico	E 1/2 of Lot	4, Block 12
10a. Site 10b. Buildin	10c. Structur 10d. Obje 11. C	on National Register 12. Is it eligible 13. Part of Historic Distric
14. District Potential 15	i. Name of District 16.	Thematic Category
✓ .		
17. Date(s) or Period	18. Style or Design	19. Architect or Engineer
	romanesque	
20. Contractor or Build	er 21. Original Use	22. Present Use
	commercial	commercila
23. Ownership	24. Owner's Name and	
private	Leonatti & Baker, 123 E	ast Jackson, Mexico MO 65265 ✓
26. Local Contact Pers	on or Organization	27. Other Surveys in Which Included
Lura Williams		n/a
28. No. of Stories 29. Bo	semen 30. Foundation Materia	at 31. Wall Construction
ī L	stone	brick
Roof Type and Materia	al 33a, No. of Bays, front	33b. No. of bays, side
flat/asphalt	6	5
34. Wall Treatment	35, Plan Shape	36a. Changes, addition (see 36b. Changes, altered
brick	rectangular	
		Tal
Changes, moved (see	37a. Condition, Interior	37b. Condition, Exterior 38. Preservation underwa
Changes, moved (see	37a. Condition, Interior	37b. Condition, Exterior 38. Preservation underwa
	ndangered by what? 40. Vis	
	indangered by what? 40. Vis	
39a, Endangere 39b. E	indangered by what? 40. Vis	
39a, Endangere 39b. E	indangered by what? 40. Vis	
39a, Endangere 39b, E 41. Distance from and 42. Further Description arched doorway turne	indangered by what? 40. Vis frontage on road of Importar it Features ed into a window with a station	ible from public road? ary picture window on either side. There are
39a, Endangere 39b. E 41. Distance from and 42. Further Description arched doorway turne brick panels and corb	frontage on road of Important Features ed into a window with a station elling between the window and	ible from public road?
39a, Endangere 39b. E 41. Distance from and 42. Further Description arched doorway turns brick panels and corb with #32 and has no e	frontage on road of Importarit Features ed into a window with a station elling between the window and exterior entry.	ible from public road? ary picture window on either side. There are
39a. Endangere 39b. E 41. Distance from and 42. Further Description arched doorway turns brick panels and corb with #32 and has no e: 43. History and Significe	frontage on road of Important Features ed into a window with a station elling between the window and exterior entry.	ible from public road? ary picture window on either side. There are
39a. Endangere 39b. E 41. Distance from and 42. Further Description arched doorway turns brick panels and corb with #32 and has no e: 43. History and Significa This building first appea building except the ed	frontage on road of Important Features ed into a window with a station elling between the window and atterior entry. cance castern most portion which was a	ible from public road? The public road?
39a. Endangere 39b. E 41. Distance from and 42. Further Description arched doorway turne brick panels and corb with #32 and has no e 43. History and Significe This building first appea	frontage on road of Importarit Features ed into a window with a station elling between the window and sterior entry. cance ars on the 1908 map as an office astern most portion which was a the the rest circa 1950 and beca	ible from public road? The public road?
39a. Endangere 39b. E 41. Distance from and 42. Further Description arched doorway turne brick panels and corb with #32 and has no e 43. History and Significe This building first appea	frontage on road of Important Features ed into a window with a station elling between the window and atterior entry. cance castern most portion which was a	ible from public road? The public road?
39a. Endangere 39b. E 41. Distance from and 42. Further Description arched doorway turne brick panels and corb with #32 and has no e 43. History and Significe This building first appea	frontage on road of Importarit Features ed into a window with a station elling between the window and sterior entry. cance ars on the 1908 map as an office astern most portion which was a the the rest circa 1950 and beca	ible from public road? The public road?
39a. Endangere 39b. E 41. Distance from and 42. Further Description arched doorway turne brick panels and corb with #32 and has no e 43. History and Significe This building first appea	frontage on road of Importarit Features ed into a window with a station elling between the window and exterior entry. cance ars on the 1908 map as an offic astern most portion which was o in the rest circa 1950 and beca	adry picture window on either side. There are at the roofline. This building has been united be building. It has remained an office added circa 1930 as a store. The eastername offices.
39a, Endangere 39b, E 41. Distance from and 42. Further Description arched doorway turne brick panels and corb with #32 and has no e: 43. History and Significe This building first appea building except the ec portion was united with 44. Description of Envir	frontage on road of Important Features ed into a window with a station elling between the window and exterior entry. cance ars on the 1908 map as an office astern most portion which was a the the rest circa 1950 and beca- oniment and Outbuildings	ary picture window on either side. There are at the roofline. This building has been united be building. It has remained an office added circa 1930 as a store. The eastername offices.
39a. Endangere 39b. E 41. Distance from and 42. Further Description arched doorway turne brick panels and corb with #32 and has no e 43. History and Significat This building first appea building except the ec portion was united with 44. Description of Envir	frontage on road of Importarit Features ed into a window with a station elling between the window and xterior entry. cance as on the 1908 map as an office astern most portion which was on the rest circa 1950 and beca comment and Outbuildings	adry picture window on either side. There are at the roofline. This building has been united be building. It has remained an office added circa 1930 as a store. The eastername offices.
39a, Endangere 39b, E 41. Distance from and 42. Further Description arched doorway turne brick panels and corb with #32 and has no e: 43. History and Significate This building first appear building except the eco portion was united with 44. Description of Envir	frontage on road of Important Features ed into a window with a station elling between the window and exterior entry. cance ars on the 1908 map as an office astern most portion which was a the the rest circa 1950 and beca- oniment and Outbuildings	ary picture window on either side. There are at the roofline. This building has been united be building. It has remained an office added circa 1930 as a store. The eastername offices.
39a. Endangere 39b. E 41. Distance from and 42. Further Description arched doorway turne brick panels and corb with #32 and has no e 43. History and Significat This building first appea building except the ec portion was united with 44. Description of Envir	frontage on road of Importarit Features ed into a window with a station elling between the window and xterior entry. cance as on the 1908 map as an office astern most portion which was on the rest circa 1950 and beca comment and Outbuildings	ary picture window on either side. There are at the roofline. This building has been united be building. It has remained an office added circa 1930 as a store. The eastername offices.



1. No. 2. County		ation of Nes	atives	4. Current Name(s)	
71 Audrain	MCRI	***************************************		Chamber of Commerce	
5. Other Name(s)			6c. Section	6d. Street Address	<u> </u>
Commerce Bank	T51N	R9W	26	100 West Jackson	
7. City or Town	7b. Vicinit 8.		The second secon	9. UTM Coordinates	
Mexico	LJ: E	40' & N 8!	5' of Lot 8, B	lock	
10a. Site 10b. Building 10c. Str	ucture 10d. O	bjec 11. C	n National R	egister? 12. Is it eligible? 13. Part	of Historic District
	Ш	Щ.		∠	
14. District Potential? 15. Name	of District	16.	Thematic Car	egory	
17. Date(s) or Period	18. Style or D	esign	19. A	rchitect or Engineer	
1935			Bonsa	ck & Pearce Inc.	
20. Contractor or Bullder	21. Original U	se	22. Pr	esent Use	
John Epple Construction Comp	commercial		comm	ercial	
23. Ownership	24. Owner's N	lame and A	ddress	25. (Open to Public
public	Chamber Rest	oration Fund	d Inc, 100 W	est Jackson, Mexico MO 6 🗹	
26. Local Contact Person or Org	anization		27. Ot	her Surveys in Which Included	
Lura Williams			n/a		
28. No. of Storle 29. Basement	30. Foundation	n Material	31. V	Vall Construction	\Box
1	concrete		brick		
Roof Type and Material	33a. No. of B	ays, front	336. 1	No. of bays, side	
flat/asphalt	3		7		
34. Wall Treatment	35. Plan Shape		36a. (Changes, addition (see 42) 36b. C	hanges, altered (see 42)
brick	rectangular			, s. J	
Changes, moved (see 42) 37a.	Conclition, Inte	rior	37b. Condit	ion, Exterior 38. Preservat	ion underway?
39a. Endangered 39b. Endange	red by what?	40. Vk	ible from pub	fic road?	
		_			
41. Distance from and frontage	on road				
42. Further Description of Impo	rtant Features				
•		-		windows are 12/12 double hung	
	•	low and a ke	eystone arch.	There are three such window on	
each side of the Jefferson St. (co	nic.)	(37) (47)			
	the site of the	Ringo Hotel	, it was bough	nt by Commerce Bank circa 1965.	
The Chamber Restoration Fund	bought the build				
preserved buildings on the square	A CHARLE TO PERSONNELLE	000	Oliver Com to the Section		
44. Description of Environment	and Outbuilding	3			والمراجع المراجع المراجع المراجع
45. Sources of Information	46. Prepared I	у	47. 0	rganization	
Sanborn Maps, Sue Caine, (con	Mary Aue Mit	chell	City o	f Mexico	
48. Date 49. Revisi	on Date(s)				
6/5/2002					

#71

100 West Jackson

- 42. entrance and one on each side of the Jackson Street entrance. Above these is a concrete belt course and the roofline features a balistrade with a decorative pediment. This building features solid concrete construction with walls 18 to 24 inches thick. Even the mezzanine has concrete floors. The marble work inside was done by James Shaw and Sons of St. Louis.
- 44. "A Gathering of Our Days" by Leta Hodge and "Audrain County Missouri, Reflections of the Past 1945-2000" by Gayle Messer.





1. No. 2. County 3. Location			ation of Negatives 4. Current Name(s)						
72 Audrain	-	MCRI			Dollar Store				
5. Other Name(s)		wnshi 6b. R	ang 6c	. Sectio 6	d. Street Addre	ss			
	T51N	R9W	26	5 1	10 West Jackson	n			
7. City or Town	7b. VI	cini 8. Desci	iption	of Location	9. UTM COOL	rdinate	es		
Mexico		all Lot 8	except	t E 40' & N					
10a. Sit 10b. Buildin 10c.	Structu	10d. Oblec	11. On N	lational Re	gist 12. is it el	laibi '	13. Part of Historic Distr		
			J						
14. District Potenti 15. Na	ne of Dis	strict	16 The	ematic Cat	egory				
V					90.7				
17. Date(s) or Period	18 St	le or Desigr	<u> </u>	10 Arci	nitect or Engine	oor .			
circa 1935	10. 00,	ne or begign		19. AICI	intect of Eligina	CC1			
20. Contractor or Builder	24 Orl	Iginal Use		22 Dro	cont Hea				
20. Contractor of Bulluer	عندة فالتكاكفين الفاح	nercial		comme	sent Use				
					——————————————————————————————————————				
23. Ownership	عودت ويتحاضلون أمخط	vner's Name		******	240 4	· · · · ·	25. Open to Publ		
private	<u> </u>		Barnes,		210, Auxvasse, I				
26. Local Contact Person	r Organi:	zation			r Surveys in Wi	nich In	cluded		
Lura Williams				n/a					
28. No. of Stori 29. Basen	e 30. Fo	30. Foundation Material			31. Wall Construction				
1 \Box	brick			brick	brick				
Roof Type and Material	33a. N	o. of Bays, fr	ont	nt 33b. No. of bays, side					
flat/asphalt	3								
34. Wall Treatment	35. Pla	Plan Shape		36a. Ch	36a. Changes, addition (see 36b. Cha		36b. Changes, altered (see		
brick	rectar	rectangular							
Changes, moved (see 37	a. Condit	ion, Interior	37	b. Condition	on, Exterior	38. P	reservation underw		
39a. Endangere 39b. Enda	ngered b	v what? 40	. Visible	from pub	lic road?				
		✓							
41. Distance from and fro	tage on	road							
41. Distance from and fro	icage on	1000							
40 Further Becarintian of	Importo	nt Footures							
42. Further Description or recessed central entry fla		Letter 1	OWE and	d tonned w	vith a boarded	over			
transom. Above these ar							th a		
decorative carving of a sa									
43. History and Significan	e								
Built on the site of the Ri									
After that Montgomery V		artment Sto	e occu	pied the bi	uilding until cir	ca 198	0. The		
Dollar Store moved in cir 44. Description of Enviror		d Outhuildin	ac						
44. DESCRIPTION OF ENVIRON	incin all	a Jumunulli	Äo						
45. Sources of Informatio		epared by		47. Org	anization				
Sanborn Maps, G. Craddo	Aue Mitchell		City of	Mexico					
48. Date 49. Re	ision Dat	te(•					
6/5/2002									



Café T51N R9W 26 112, 114 W. Jackson 7. City or Town 7b. Vicinit 8. Description of Location 9. UTM Coordinates	
5. Other Name(s) 6a. Township 6b. Range 6c. Section 6d. Street Address Café T51N R9W 26 112, 114 W. Jackson 7. City or Town 7b. Vicinit 8. Description of Location Lot 7, Block 8	
Café T51N R9W 26 112, 114 W. Jackson 7. Clty or Town 7b. Vicinit 8. Description of Location 9. UTM Coordinates Mexico Lot 7, Block 8	
7. City or Town 7b. Vicinit 8. Description of Location 9. UTM Coordinates Mexico Lot 7, Block 8	
Mexico Lot 7, Block 8	
	_
I Va. JIC I VV. DUNUNIK I V. JUDCUIC I VV. VVICC I I I. VII ITARRIMI REKIMEI: II Z. 15 II FIIVII P. I. J. FAII	of Uleraria Dies
	OI FISIONE DISU
14. District Potential? 15. Name of District 16. Thematic Category	
13. District electron. 13. Nonic of Poster	
17. Date(s) or Period 18. Style or Design 19. Architect or Engineer	
circa 1930	-
20. Contractor or Builder 21. Original Use 22. Present Use	7
commercial commercial	
	Open to Public
private Robert & Barbara Barnes, Rt. 2, Box 210, Auxvasse MO 65231	Spen to Fublic
26. Local Contact Person or Organization 27. Other Surveys in Which Included	$\mathbf{\eta}$
Lura Williams n/a	┵
28. No. of Storie 29. Basement 30. Foundation Material 31. Wall Construction	
2 brick brick	
Roof Type and Material 33a. No. of Bays, front 33b. No. of bays, side	an in the
flat/asphalt 6	
34. Wall Treatment 35. Plan Shape 36a. Changes, addition (see 42) 36b. Cl	hanene aleanad
brick and wood siding rectangular John Changes, addition (see 42) 350. C	nanges, altered
	na under a
Changes, moved (see 42) 37a. Conclition, Interior 37b. Condition, Exterior 38. Preservati	ion underway?
39a. Endangered 39b. Endangered by what? 40. Visible from public road?	
39a. Endangered (1) What? 40. Visible from public road?	
41. Distance from and frontage on road	\exists
11. Distance from and promage on your	لاند
42. Further Description of Important Features	7
recessed double entries flanked by display windows and topped with a boarded over transom. Above that are	re
three window set each of which consists of a central picture window flanked by a 1/1 double hung window	-
and topped by stationary windows (cont.)	
43. History and Significance	
Built on the site of the Ringo Hotel, this building was first occupied by Montgomery Ward Department Store It remained Montgomery Wards' store until circa 1980. Since then it has held a mini mall and a café.	.
terrorined a zonegomeny wards store until ened a zoot, since then it has nell a little a little and a cale.	
44. Description of Environment and Outbuildings	
45. Sources of Information 46. Prepared by 47. Organization	
Sanborn Maps, G. Craddock, Ci Mary Aue Mitchell City of Mexico	-
The state of the s	
48. Date 49. Revision Date(s)	

#73

112, 114 West Jackson

42. with the "V" shape in them. Above the windows is a row of dentals and central urn tops the building at the roofline.







A DE LOCKET	3. Location of Ne		
1. No. 2. County 74 Audrain	MCRI	egatives 4. Current Name(s) Countryside Home Loans	
5. Other Name(s)		6c. Section 6d. Street Address	
Merle Norman Studio	T51N R9W	26 118, 120 W. Jackson	
7. City or Town	7b. Vicinit 8. Descriptio		
Mexico	Lot 6, Bock		_
		On National Register? 12. Is it eligible? 13. Part	of Historic District
			or ribuora politica
14. District Potential? 15. N	lame of District 16	. Thematic Category	\Box
✓			
17. Date(s) or Period	18. Style or Design	19, Architect or Engineer	
circa 1885			
20. Contractor or Builder	21. Original Use	22. Present Use	
	commercial	commercial	
23. Ownership	24. Owner's Name and A	Address 25 (Open to Public
private		20 West Jackson, Mexico, MO 65265	
26. Local Contact Person or		27. Other Surveys in Which Included	
Lura Williams		n/a	
	nent 30. Foundation Material		
2	brick	brick	
Roof Type and Material	33a. No. of Bays, front		π
flat/asphalt	4		-
34. Wall Treatment	35. Plan Shape	36a. Changes, addition (see 42) 36b. C	hanges altered (see 42)
brick	rectangular		minger, attered (See 12)
	7a. Condition, Interior	37b. Condition, Exterior 38 Precentari	ion underway?
			<u>-1 -1 -1 -1 -1 -1 -1 -1 -1 -1 -1 -1 -1 -</u>
39a. Endangered 39b. Enda	ingered by what? 40. V	isible from public road?	\neg $0 \le i \le j \le j$
	V		
41. Distance from and fronta	see on road	Property of the second	
42. Further Description of Im	nportant Features		
		sides. A cloth awning separates the first and	-
second stories. The second s	story features five 1/1 double	hung windows with brick lintels and lug sills.	
Above them are three rows of	of corbelling.		
43. History and Significance		. 1890,1894,1899, drugstore and meat store.	J
A CONTRACTOR OF THE PROPERTY O	OUR 3 OF SCOTI SEA MASS CO.		
The earliest map - 1885 - she			
The earliest map - 1885 - she 1908, drugstore and optical		confectionary. 1929, music and candy store.	ASSESSMENT OF THE PROPERTY OF
The earliest map - 1885 - she 1908, drugstore and optical 1935 beauty and dress shop.	shop. 1914, drugstore and c . Circa 1980 Merle Norman.	confectionary. 1929, music and candy store.	
The earliest map - 1885 - she 1908, drugstore and optical 1935 beauty and dress shop.	shop. 1914, drugstore and c . Circa 1980 Merle Norman.	confectionary. 1929, music and candy store.	
The earliest map - 1885 - she 1908, drugstore and optical 1935 beauty and dress shop.	shop. 1914, drugstore and c . Circa 1980 Merle Norman.	confectionary. 1929, music and candy store.	
The earliest map - 1885 - she 1908, drugstore and optical 1935 beauty and dress shop. 44. Description of Environment	shop. 1914, drugstore and c . Circa 1980 Merle Norman. ent and Outbulldings	confectionary. 1929, music and candy store.	
The earliest map - 1885 - she 1908, drugstore and optical 1935 beauty and dress shop.	shop. 1914, drugstore and common. Circa 1980 Merle Norman. ent and Outbuildings.	confectionary. 1929, music and candy store.	
The earliest map - 1885 - she 1908, drugstore and optical 1935 beauty and dress shop. 44. Description of Environme 45. Sources of Information Sanborn Maps, G. Craddock,	shop. 1914, drugstore and common. Circa 1980 Merle Norman. ent and Outbuildings.	tonfectionary. 1929, music and candy store.	



1. No. 2. County		cation of N	egatives	4. Current Name(s)
75 Audrain	MCR	-		SOS Shipping
5. Other Name(s)				6d. Street Address
Cellular Today	T51N	R9W	26	122, 122A W. Jackson
7. City or Town	7b. Vicinit 8			9. UTM Coordinates
Mexico		W 24' Lot 6	-	
10a. Site 10b. Building 10c. St	ructure 10d. (Objec 11.	On National	Register? 12. Is it eligible? 13. Part of Historic District
14. District Potential? 15. Nam	e of Elistrict	16	. Thematic C	ategory
V				
17. Date(s) or Period	18. Style or I	Design	19.	Architect or Engineer
circa 1885		and the second s		
20. Contractor or Builder	21, Original	Use	22.	Present Use
1 (A. 1900) A. 1900 A.	commercial		com	mercial
23. Ownership	24. Owner's			25. Open to Public
private	R. Newton &	Joyce Rile	y, 7 North 9t	th St., Columbia MO 65201 🗹
26. Local Contact Person or Or	ganization		27. 0	Other Surveys in Which Included
Lura Williams			n/a	
28. No. of Storie 29. Basement	t 30. Foundati	ion Material	31.	Wall Construction
2	brick		bric	ck
Roof Type and Material	33a. No. of I	Bays, front	33b.	No. of bays, side
flat/asphalt	4			
34. Wall Treatment	35. Plan Shap)e	36a.	. Changes, addition (see 42) 36b. Changes, altered (see 42)
brick	rectangular		L.	
Changes, moved (see 42) 37a.	Condition, Int	erior	37b. Cond	dition, Exterior 38. Preservation underway?
		I COMMISSION OF THE PARTY OF TH		
39a. Endangered 39b. Endange	ered by what?	40. V	isible from pu	ublic road?
∐		✓		The grant of the second second second second
41. Distance from and frontage	on road			
42. Further Description of Impo				
-				a single door corner entry. A fixed
wood shingled awning runs the learning runs the	•	scade. The	second story	has three 1/1 double hung windows
43. History and Significance	,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,			
The earliest maps - 1885, 1899				890 through circa 1925, it was a
musical instrument store. After	that it was a ha	ardware sto	re until circa	1965.
44. Description of Environment	and Outbuildir	182		
45. Sources of Information	46. Prepared	by	47	Organization
Sanborn Maps, G. Craddock, Ci				of Mexico
	ion Date(s)		1/	
6/5/2002	OII 200(3)			
10.0.2002				

#75

122, 122A W. Jackson

42. dentals and a decorative frieze below the cornice. These decorative elements are interrupted by a central break in the design. The awning was added circa 1980.



76 Audrain				
The second of th	MCRI		11.	Audrain Ballet Company
5. Other Name(s)		The state of the s		n 6d. Street Address
and the second s		R9W	26	124 West Jackson
7. City or Town	7b. Vicinit 8. I			n 9. UTM Coordinates
Mexico	□ E 2	5' of Lot	5, Block 8	
10a. Site 10b. Building 10	c. Structure 10d. Ob	ec 11. 0	On Nationa	Register? 12. Is it eligible? 13. Part of Historic Dis
	L. L.	Ш		
14. District Potential? 15.	Name of District	16.	Thematic	Category
<u> </u>				
17. Date(s) or Period	18. Style or Des	ign	19.	Architect or Engineer
circa 1885				
20. Contractor or Builder	21. Original Us			Present Use
	commerical	days abbasens a second	cor	nmercial
23. Ownership	24. Owner's Na			25. Open to Public
private	R. Newton & Jo	yce Riley		Pth St., Columbia MO 65201 ✓
26. Local Contact Person o	r Organization		27.	Other Surveys in Which Included
Lura Williams			n/a	
28. No. of Størie 29. Base		Material		. Wall Construction
2 🗆 🗀	brick		bri	ck
Roof Type and Material	33a. No. of Bay	s, front	331	o. No. of bays, side
flat/asphalt	3			
7.4 VIV.II T	7E N. C	(Phy. 31)	74.	
34. Wall Treatment	35. Plan Shape		, 306	i. Changes, addition (see 42) 36b. Changes, altered
s4. Wall I reatment brick	rectangular			i. Changes, addition (see 42) 36b. Changes, aftered ✓
	rectangular	or		
brick Changes, moved (see 42)	rectangular 37a. Conclidon, Interi		37b. Con	dition, Exterior 38. Preservation underway?
brick	rectangular 37a. Conclidon, Interi	40, VI	37b. Con	
brick Changes, moved (see 42)	rectangular 37a. Conclidon, Interi		37b. Con	dition, Exterior 38. Preservation underway?
brick Changes, moved (see 42)	rectangular 37a. Conclition, Interidangered by what?	40, VI	37b. Con	dition, Exterior 38. Preservation underway?
brick Changes, moved (see 42) 39a. Endangered 39b. End	rectangular 37a. Conclition, Interidangered by what?	40, VI	37b. Con	dition, Exterior 38. Preservation underway?
brick Changes, moved (see 42) 39a. Endangered 39b. End 41. Distance from and fron	rectangular 37a. Conclition, Interidangered by what? tage on road Important Features	40. VI	37b. Con	dition, Exterior 38. Preservation underway? public road?
brick Changes, moved (see 42) 39a. Endangered 39b. End 41. Distance from and from 42. Further Description of recessed single door central	rectangular 37a. Conclition, Interior dangered by what? tage on road Important Features Lentry with a pilaster a	40. VI	37b. Con sible from p	dition, Exterior 38. Preservation underway? public road? on each side. A fixed wood shingled
brick Changes, moved (see 42) 39a. Endangered 39b. End 41. Distance from and from 42. Further Description of recessed single door central	rectangular 37a. Conclition, Interior dangered by what? tage on road Important Features Lentry with a pilaster a	40. VI	37b. Con sible from p	dition, Exterior 38. Preservation underway? public road?
brick Changes, moved (see 42) 39a. Endangered 39b. End 41. Distance from and from 42. Further Description of recessed single door central awning runs the length of the	rectangular 37a. Conclition, Interior dangered by what? tage on road Important Features entry with a pilaster a he fascade. The secon	40. VI	37b. Con sible from p	dition, Exterior 38. Preservation underway? public road? on each side. A fixed wood shingled
brick Changes, moved (see 42) 39a. Endangered 39b. End 41. Distance from and from 42. Further Description of I recessed single door central awning runs the length of the pediments. (cont.) 43. History and Significance The earliest maps - 1885,	rectangular 37a. Conclition, Interior dangered by what? stage on road Important Features entry with a pilaster a the fascade. The second	nd a pictud story ha	37b. Con sible from p are window as three 1/1	dition, Exterior 38. Preservation underway? public road? on each side. A fixed wood shingled
brick Changes, moved (see 42) 39a. Endangered 39b. End 41. Distance from and from 42. Further Description of I recessed single door central awning runs the length of the pediments. (cont.) 43. History and Significance	rectangular 37a. Conclition, Interior dangered by what? stage on road Important Features entry with a pilaster a the fascade. The second	nd a pictud story ha	37b. Con sible from p are window as three 1/1	dition, Exterior 38. Preservation underway? sublic road? on each side. A fixed wood shingled double hung windows with decorative
brick Changes, moved (see 42) 39a. Endangered 39b. End 41. Distance from and from 42. Further Description of I recessed single door central awning runs the length of the pediments. (cont.) 43. History and Significance The earliest maps - 1885, istore. From circa 1905 to	rectangular 37a. Conclition, Interior dangered by what? tage on road Important Features lentry with a pilaster a the fascade. The second e 1890 - show it as a dright or it as a dright of the circa 1965, it was a free circa 1965.	nd a pictud story ha	37b. Con sible from p are window as three 1/1	dition, Exterior 38. Preservation underway? sublic road? on each side. A fixed wood shingled double hung windows with decorative
brick Changes, moved (see 42) 39a. Endangered 39b. End 41. Distance from and from 42. Further Description of I recessed single door central awning runs the length of the pediments. (cont.) 43. History and Significance The earliest maps - 1885,	rectangular 37a. Conclition, Interior dangered by what? tage on road Important Features lentry with a pilaster a the fascade. The second e 1890 - show it as a dright or it as a dright of the circa 1965, it was a free circa 1965.	nd a pictud story ha	37b. Con sible from p are window as three 1/1	dition, Exterior 38. Preservation underway? sublic road? on each side. A fixed wood shingled double hung windows with decorative
brick Changes, moved (see 42) 39a. Endangered 39b. End 41. Distance from and from 42. Further Description of I recessed single door central awning runs the length of the pediments. (cont.) 43. History and Significance The earliest maps - 1885, istore. From circa 1905 to	rectangular 37a. Conclition, Interior dangered by what? tage on road Important Features lentry with a pilaster a the fascade. The second e 1890 - show it as a dright or it as a dright of the circa 1965, it was a free circa 1965.	nd a pictud story ha	37b. Con sible from p are window as three 1/1	dition, Exterior 38. Preservation underway? sublic road? on each side. A fixed wood shingled double hung windows with decorative
brick Changes, moved (see 42) 39a. Endangered 39b. End 41. Distance from and from 42. Further Description of I recessed single door central awning runs the length of the pediments. (cont.) 43. History and Significance The earliest maps - 1885, isore. From circa 1905 to 44. Description of Environments	rectangular 37a. Conclition, Interior dangered by what? tage on road Important Features I entry with a pilaster a the fascade. The second 1890 - show it as a dri circa 1965, it was a free circa 1965, it was a free circa and Outbuildings	nd a pictud story ha	37b. Con sible from p ure window as three 1/1	on each side. A fixed wood shingled double hung windows with decorative re. 1894, shoes only. 1899, Racket
brick Changes, moved (see 42) 39a. Endangered 39b. End 41. Distance from and from 42. Further Description of I recessed single door central awning runs the length of the pediments. (cont.) 43. History and Significance The earliest maps - 1885, istore. From circa 1905 to 44. Description of Environmental Sources of Information	rectangular 37a. Conclition, Interior dangered by what? tage on road Important Features I entry with a pilaster a he fascade. The second circa 1965, it was a from the factor and Coutbuildings 46. Prepared by	nd a pictud story ha	37b. Con sible from pure windows three 1/1 and shoe storestore.	on each side. A fixed wood shingled double hung windows with decorative re. 1894, shoes only. 1899, Racket
brick Changes, moved (see 42) 39a. Endangered 39b. End 41. Distance from and from 42. Further Description of I recessed single door central awning runs the length of the pediments. (cont.) 43. History and Significance The earliest maps - 1885, istore. From circa 1905 to 44. Description of Environmental Processed Sanborn Maps, G. Craddoc	rectangular 37a. Conclition, Interior dangered by what? stage on road Important Features lentry with a pilaster a the fascade. The second e 1890 - show it as a driver a circa 1965, it was a from the second and Coutbuildings 46. Prepared by Mary Aue Mitch	nd a pictud story ha	37b. Con sible from pure windows three 1/1 and shoe storestore.	on each side. A fixed wood shingled double hung windows with decorative re. 1894, shoes only. 1899, Racket
brick Changes, moved (see 42) 39a. Endangered 39b. End 41. Distance from and from 42. Further Description of I recessed single door central awning runs the length of the pediments. (cont.) 43. History and Significance The earliest maps - 1885, istore. From circa 1905 to 44. Description of Environmental Processed Sanborn Maps, G. Craddoc	rectangular 37a. Conclition, Interior dangered by what? tage on road Important Features I entry with a pilaster a he fascade. The second circa 1965, it was a from the factor and Coutbuildings 46. Prepared by	nd a pictud story ha	37b. Con sible from pure windows three 1/1 and shoe storestore.	on each side. A fixed wood shingled double hung windows with decorative re. 1894, shoes only. 1899, Racket

#76

124 West Jackson

42. The roofline has two decorative friezes and a cornice. There is a pilaster at each end of the roofline. The fixed awning was added circa 1980.



77 Audrain MCRI 126 West Jackson	
5. Other Name(s) 6a. Township 6b. Range 6c; Section 6d. Street Address	
T51N R9W 26 126 West Jackson	
7. City or Town 7b. Vicinit 8. Description of Location 9. UTM Coordinates	
Mexico Central 20' of Lot 5, Block 8	
10a. Sire 10b. Building 10c. Structure 10d. Objec 11. On National Register? 12. Is it eligible? 13. Part of Historic	District
14. District Potential? 15. Name of District 16. Thematic Category	
17. Date(s) or Period 18. Style or Design 19. Architect or Engineer	
circa 1885	
20. Contractor or Builder 21. Original Use 22. Present Use	
com merical vacant	
23. Ownership 24. Owner's Name and Address 25. Open to Pt	iblic
private R. Newton & Joyce Riley, 7 North 9th St., Columbia MO 65201	
26. Local Contact Person or Organization 27. Other Surveys in Which Included	
Lura Williams n/a	
28. No. of Storie 29. Basement 30. Foundation Material 31. Wall Construction	
2 brick brick	
Roof Type and Material 33a. No. of Bays, front 33b. No. of bays, side	
flat/asphalt 3	
34. Wall Treatment 35. Plan Shape 36a. Changes, addition (see 42) 36b. Changes, all	ered (see 42)
brick rectangular ✓	
Changes, moved (see 42) 37a. Condition, Interior 37b. Condition, Exterior 38. Preservation underv	vay?
39a. Endangered 39b. Endangered by what? 40. Visible from public road?	
41. Distance from and frontage on road	
42. Further Description of Important Features	
recessed central entry with a pilaster and a stationary window on each side. A fixed wood shingled awning	
runs the length of the fascade. The second story features three boarded over arched windows with dripstone lintels and lug sills. (cont.)	
43. History and Significance	
The earliest map -1885 - shows a restaurant and confectionary. 1890, 1894,1899, show a lunch room and	
billiard hall. 1908, restaurant, billiards, and cigar factory. 1914, restaurant only. From circa 1925	
through circa 1965 it was a hardware store.	
44. Description of Environment and Outbuildings	
45. Sources of Information 46. Prepared by 47. Organization	
Sanborn Maps, G. Craddock, Ci Mary Aue Mitchell City of Mexico	
48. Date 49. Revision Date(s)	
6/6/2002	agency means at the decision of 1871 to 177 of 177 of 177.

#77

126 West Jackson

42. The roofline features two decorative friezes and three brackets blow the cornice. Awning added circa 1980.



10-15-001-017

and the second s	MCRI		City Incubator	
5. Other Name(s)			6d. Street Address	
	T51N R9W	26	128 West Jackson	
7. City or Town	7b. Vicinit 8. Desc		9. UTM Coordinates	
Mexico		of Lot 5, Block 8		
10a. Site 10b. Building 10	c. Structure 10d. Objec	11. On National	Register? 12. Is it eligible? 1	3. Part of Historic District
	ж. Н	<u>.</u>	e in Heritalia L	
14. District Potential? 15.	Name of District	16. Thematic C	ategory	
Y			<u> </u>	
17. Date(s) or Period	18. Style or Design	19.	Architect or Engineer	
circa 1885				
20. Contractor or Builder	21. Original Use	22.	Present Use	
	commercial	com	merical	
23. Ownership	24. Owner's Name			25. Open to Public
private	R. Newton & Joyce		th St., Columbia MO 6520	
26. Local Contact Person o	r Organization		Other Surveys in Which Inclu	<u>led</u>
Lura Williams		n/a		
28. No. of Storie 29. Base			Wall Construction	
2	brick	brio	Paris (1984)	
Roof Type and Material	33a. No. of Bays, fi	ont 33b	. No. of bays, side	
flat/asphalt	12			
34. Wall Treatment	35. Plan Shape	36a	Changes, addition (see 42)	36b. Changes, altered (see 42
brick	recungular			✓
	recungular			The state of the s
brick Changes, moved (see 42)	rectangular 37a. Condition, Interior	37b. Conc	lition, Exterior 38. P	✓
brick	rectangular 37a. Condition, Interior dangered by what?	37b, Cond	lition, Exterior 38. P	✓
brick Changes, moved (see 42) 39a. Endangered 39b. End	rectangular 37a: Condition, Interior dangered by what?	37b. Conc	lition, Exterior 38. P	✓
brick Changes, moved (see 42)	rectangular 37a: Condition, Interior dangered by what?	37b, Cond	lition, Exterior 38. P	✓
brick Changes, moved (see 42) 39a. Endangered 39b. End 41. Distance from and from	rectangular 37a. Condition, Interior dangered by what? 4 tage on road	37b, Cond	lition, Exterior 38. P	✓
brick Changes, moved (see 42) 39a. Endangered 41. Distance from and from 42. Further Description of	rectangular 37a: Condition, Interior dangered by what? 4 tage on road important Features	37b. Cond	dition, Exterior 38. Problem of the control of the	eservation underway?
brick Changes, moved (see 42) 39a: Endangered 39b: Endangered 1. Distance from and from 42. Further Description of glass door with display wince	rectangular 37a: Condition, Interior dangered by what? 4 tage on road important Features lows to the east side. A fi	37b. Cond	dition, Exterior 38. Problem 138. Problem 13	eservation underway?
brick Changes, moved (see 42) 39a: Endangered 39b: Endangered 1. Distance from and from 42. Further Description of glass door with display wince	rectangular 37a: Condition, Interior dangered by what? tage on road important Features lows to the east side. A fifeatures three boarded over	37b. Cond	dition, Exterior 38. Problem of the control of the	eservation underway?
brick Changes, moved (see 42) 39a. Endangered 39b. End 41. Distance from and from 42. Further Description of I glass door with display wind fascade. The second story two decorative friezes and 843. History and Significance	rectangular 37a: Condition, Interior dangered by what? tage on road important Features lows to the east side. A fifeatures three boarded over or ackets (cont.)	37b. Cond 10. Visible from pro- 2 xed wood shingleder windows with line	dition, Exterior 38. Problem of the standing runs the length of the standing sills. The roofling sills and lug sills.	reservation underway?
brick Changes, moved (see 42) 39a. Endangered 39b. End 41. Distance from and from 42. Further Description of 19 glass door with display wind fascade. The second story two decorative friezes and 1843. History and Significance The earliest map - 1885 - s	rectangular 37a: Condition, Interior dangered by what? tage on road important Features lows to the east side. A fifeatures three boarded over or ackets (cont.) thow a jewelry, millinery, a	37b. Cond 10. Visible from pro- exed wood shingled er windows with line	dition, Exterior 38. Problem 1 awning runs the length of the notels and lug sills. The roofling store. 1890, barber and salo	reservation underway?
brick Changes, moved (see 42) 39a. Endangered 39b. End 41. Distance from and from 42. Further Description of I glass door with display wince fascade. The second story two decorative friezes and the 43. History and Significance The earliest map - 1885 - s 1894, 1899, 1908, 1914,	rectangular 37a: Condition, Interior dangered by what? tage on road important Features lows to the east side. A fifeatures three boarded overackets (cont.) show a jewelry, millinery, a saloon, bowling alley, with	37b. Cond 10. Visible from pro- exed wood shingled er windows with line	dition, Exterior 38. Problem of the standing runs the length of the standing sills. The roofling sills and lug sills.	reservation underway?
brick Changes, moved (see 42) 39a. Endangered 39b. End 41. Distance from and from 42. Further Description of 19 glass door with display wind fascade. The second story two decorative friezes and 1843. History and Significance The earliest map - 1885 - s	rectangular 37a: Condition, Interior dangered by what? tage on road important Features lows to the east side. A fifeatures three boarded overackets (cont.) show a jewelry, millinery, a saloon, bowling alley, with a hardware store.	37b. Cond 10. Visible from pro- exed wood shingled er windows with line	dition, Exterior 38. Problem 1 awning runs the length of the notels and lug sills. The roofling store. 1890, barber and salo	reservation underway?
brick Changes, moved (see 42) 39a. Endangered 39b. End 41. Distance from and from 42. Further Description of I glass door with display wind fascade. The second story two decorative friezes and be 43. History and Significance The earliest map - 1885 - s 1894,1899,1908, 1914, through circa 1965, it was	rectangular 37a: Condition, Interior dangered by what? tage on road important Features lows to the east side. A fifeatures three boarded overackets (cont.) show a jewelry, millinery, a saloon, bowling alley, with a hardware store.	37b. Cond 10. Visible from pro- exed wood shingled er windows with line	dition, Exterior 38. Problem 1 awning runs the length of the notels and lug sills. The roofling store. 1890, barber and salo	reservation underway?
brick Changes, moved (see 42) 39a. Endangered 39b. End 41. Distance from and from 42. Further Description of I glass door with display wind fascade. The second story two decorative friezes and be 43. History and Significance The earliest map - 1885 - s 1894,1899,1908, 1914, through circa 1965, it was	rectangular 37a: Condition, Interior dangered by what? tage on road important Features lows to the east side. A fifeatures three boarded overackets (cont.) show a jewelry, millinery, a saloon, bowling alley, with a hardware store.	37b. Cond 10. Visible from pro- exed wood shingled er windows with line	dition, Exterior 38. Problem 1 awning runs the length of the notels and lug sills. The roofling store. 1890, barber and salo	reservation underway?
brick Changes, moved (see 42) 39a. Endangered 39b. End 41. Distance from and from 42. Further Description of glass door with display wind fascade. The second story two decorative friezes and be 43. History and Significance The earliest map - 1885 - s 1894,1899,1908, 1914, through circa 1965, it was 44. Description of Environr	rectangular 37a: Condition, Interior dangered by what? 4 tage on road important Features lows to the east side. A fifeatures three boarded overackets (cont.) show a jewelry, millinery, a saloon, bowling alley, with a hardware store. nent and Outbuildings	37b. Cond 10. Visible from pro- exed wood shingled er windows with line and dress making son a cigar factory and	dition, Exterior 38. Problem 18. Problem 1	reservation underway?
brick Changes, moved (see 42) 39a. Endangered 39b. End 41. Distance from and from 42. Further Description of glass door with display wind fascade. The second story two decorative friezes and be a second story two decorative friezes and be 1894, 1899, 1908, 1914, through circa 1965, it was 1944. Description of Environmental Sources of Information	rectangular 37a: Condition, Interior dangered by what? tage on road important Features lows to the east side. A fi features three boarded overackets (cont.) show a jewelry, millinery, a saloon, bowling alley, with a hardware store. nent and Outbuildings	37b. Cond 10. Visible from pro- exed wood shingled er windows with line and dress making son a cigar factory and	dition, Exterior 38. Property of the store. 1890, barber and salo dded in 1914. From circa 1	reservation underway?
Changes, moved (see 42) 39a. Endangered 39b. End 41. Distance from and from 42. Further Description of 1 glass door with display wind fascade. The second story two decorative friezes and be 43. History and Significance. The earliest map - 1885 - s 1894,1899,1908, 1914, through circa 1965, it was 44. Description of Environmental Control of C	rectangular 37a: Condition, Interior dangered by what? tage on road important Features lows to the east side. A fifeatures three boarded oworackets (cont.) show a jewelry, millinery, a saloon, bowling alley, with a hardware store. nent and Outbuildings 46. Prepared by k, Ci Mary Aue Mitchell	37b. Cond 10. Visible from pro- exed wood shingled er windows with line and dress making son a cigar factory and	dition, Exterior 38. Problem 18. Problem 1	reservation underway?
brick Changes, moved (see 42) 39a. Endangered 39b. Em 41. Distance from and from 42. Further Description of glass door with display wind fascade. The second story two decorative friezes and the s	rectangular 37a: Condition, Interior dangered by what? tage on road important Features lows to the east side. A fi features three boarded overackets (cont.) show a jewelry, millinery, a saloon, bowling alley, with a hardware store. nent and Outbuildings	37b. Cond 10. Visible from pro- exed wood shingled er windows with line and dress making son a cigar factory and	dition, Exterior 38. Property of the store. 1890, barber and salo dded in 1914. From circa 1	reservation underway?

#78

128 West Jackson

42. with dentals at the cornice. The Washington Street side of the building nine windows in the same style on the second story. The features of the roofline also continue. The fixed awning was added circa 1980.



Missouri	i Historic/Arcl	hitectural Inventory Form	
		HENRY CONTRACTOR FOR THE	
1. No. 2. County 47 Audrain	3. Location of Ne	gatives 4. Current Name(s) Steve's Style and Barber	
5. Other Name(s)		oc. Section 6d. Street Address	
5. Other Name(s)	T51N R9W	26 211 West Jackson	
7. City or Town	7b. Vicinit 8. Description		
Mexico	W 50' of Lot		
10a, Site 10b. Building 10c.	Structure 10d. Objec 11. 0	On National Register? 12. Is it eligible? 13. Part of Historic	District
14. District Potential? 15. Na	ame of District 16.	Thematic Category	
∠			
17. Date(s) or Period	18. Style or Design	19. Architect or Engineer	
circa 1920			
20. Contractor or Builder	21. Original Use	22. Present Use	
Scale S part of Section 2 The Section 2	commercial	commercial	og kriste flysk filman og eller og etter. År g rotte flyske og eller og eller
23. Ownership	24. Owner's Name and A		lic .
private		. 12435 Audrain Rd 9931, Mexico MO 🗹	
26. Local Contact Person or C Lura Williams	<u> Organizacion</u>	27. Other Surveys in Which Included	
28. No. of Storie 29. Basem			
28. No. or Storie Zy, basemi	concrete	brick	
Roof Type and Material	33a. No. of Bays, front	33b. No. of bays, side	
flat/asphalt	2		
34. Wall Treatment	35. Plan Shape	36a. Changes, addition (see 42) 36b. Changes, alte	red (see 42)
brick	square		
Changes, moved (see 42) 37	/a. Condition, Interior	37b. Condition, Exterior 38. Preservation underwa	w?
	<u>ari ada amanida kata pula anima na kiri iku adi iki kata kirin adi iki anima kata ani di iki anima kata ani d</u>		
39a. Endangered 39b. Enda	ngered by what? 40. Vi	sible from public road?	
	y		
41. Distance from and frontag	ge On road		
42. Further Description of Im			
single entry with a picture win length of the fascade.	dow next to it. The window	has a brick lug sill., A metal awning runs the	
length of the lastage.			
43. History and Significance			
		it was the Toastwich Shop run by Scotty Goe	- 1 13 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1
barber shop circa 1995.	prietly in the 1940's when Mr	Goe was in the military service. It became a	
44. Description of Environme	nt and Outbuildings		
		Padi, and Colored	
45. Sources of Information	46. Prepared by	47. Organization	
Sanborn Maps, G. Craddock,		City of Mexico	생물에 되었는데 등에 있다. 그렇게 보고 그렇게 되고
The second secon	vision Date(s)		
3/10/2002			
			



52	2. County Audrain	MCRI	ition of Ne		4. Current Name(s) Dr. Hodge Office,	
5. Other N	lame(s)	6a. Township	6b. Range	6c. Sect	ion 6d. Street Address	
Hair World		T51N	R9W	26	212,214,216 W. Jackson	
7. City or	Town	7b. Vicinit 8.	Description	n of Locat	ion 9, UTM Coordinates	
Mexico		L N	1 00' of Lo	ot 6, Block	< 7	
10a. Site 1	Ob. Building 10c.	Structure 10d. Of	ojec 1 1. (On Nation	al Register? 12. Is it eligible? 13. Part of Historic	District
J		· · · · · · · · · · · · · · · · · · ·				
14. District	Potential? 15. Na	ame of District	16.	Thematic	Category	
✓		•				
17. Date(s)	or Period	18. Style or De	sign	1	9. Architect or Engineer	
circa 1945	5					
20. Contra	ctor or Builder	21. Original U	se .	2:	2. Present Use	
		commercial		co	ommercial	
23. Owner	ship	24. Owner's N	The Pillar and The Pi	- total control of the section of	25. Open to Put	Alic
private		McDonald Rea	ity, PO Bo	x 2130, E	Bay St. Louis, MS 39521	
26. Local (Contact Person or (Organization		27	Other Surveys in Which Included	
Lura Willia	ms			n/a	1	
28. No. of	Storle 29. Basem	ent 30. Foundatio	n Material	3	I. Wall Construction	
1		concrete		b	rick	
Roof Type	and Material	33a. No. of Ba	ys, front	3.	5b. No. of bays, side	
flat/asphalt		8				Bought,
34. Wall T	reatment	35. Plan Shape		3/	5a. Changes, addition (see 42) 36b. Changes, alte	red (see 4
brick		rectangular				
Changes, m	ioved (see 42) 37	7a. Condition, Inter	ior	37b. Cc	ondition, Exterior 38. Preservation underwa	ny?
39a, Endan	igered 39b, Enda	ngered by what?	· · · · · · · · · · · · · · · · · · ·	sible from	public road?	
J. Marie			V			
41. Distanc	e from and fronta	ge on road	H & GARAGE			
42. Further	r Description of Im	portant Features				
					. One 1/1 double hung window on	
	of the doors. The a prick panel above the		iave been f	illed in. A	A metal awning covers the doors, and	
	r and Significance	752 - 12 Cat				
		site of the Windson	Hotel whi	ich burned	in 1934. This was built as an office	
I IIIS Dunan	•	nysicians' offices.				
	- p				* · · · · · · · · · · · · · · · · · · ·	
building an			<u> </u>	22 × 1850 1786		
building an		nt and Outbuilding	. 2003. j			
building an		nt and Outbuilding				
building an		nt and Outbuilding				
building and 44. Descript 45. Source	otion of Environme	46. Prepared b			7. Organization	
building and 44. Descript 45. Source	otion of Environme s of Information laps, G. Craddock,	46. Prepared b			7. Organization ity of Mexico	
building and 44. Descript 45. Source	s of Information aps, G. Craddock,	46. Prepared b				



Missouri Historic/Architectural Inventory Form 1. No. 2. County 3. Location of Negatives 4. County Negatives

46 Audrain	MCRI		Audrain Insurance Agency	
5. Other Name(s)	6a. Township 6b. Ra	nge 6c. Sectio	n Sd. Street Address	
Edward D. Jones	T51N R9W	26	217 & 213 West Jackson	
7. City or Town	7b. Vicinit 8. Descri	otion of Locatio	n 9. UTM Coordinates	
Mexico	E 50.50'	of Lots 187 2,	Block	
10a. Site 10b. Building 10c.	Structure 10d. Objec 1	1. On National	Register? 12. Is it eligible? 13. Part of Histo	ric District
14. District Potential? 15. Na	me of District	16. Thematic (ategory	
✓				
17. Date(s) or Period	18. Style or Design	19.	Architect or Engineer	
circa 1895	romanesque			Artuita
20. Contractor or Builder	21. Original Use	<u> </u>	Present Use	
و من خود نام در من	commercial	con	nmercial	
23. Ownership	24. Owner's Name a		25. Open to	Public
private			n, Mexico MO 65265	
26. Local Contact Person or	Organization		Other Surveys in Which Included	
Lura Williams		n/a		
28. No. of Storle 29. Basem			Wall Construction	
2 📙	stone	bri		
Roof Type and Material	33a. No. of Bays, fro	nt 33b	No. of bays, side	
flat/asphalt	16			
34. Wall Treatment	35. Plan Shape	36a	Changes, addition (see 42) 36b. Changes,	iltered (see 42)
brick	rectangular	البيا		
	ALCA TO LOS CONTROLES CONTROLES			
Changes, moved (see 42) 3	7a. Conclition, Interior	37b. Con	dition, Exterior 38, Preservation unde	rway?
				nway?
Changes, moved (see 42) 3. 39a. Endangered 39b. Enda		37b. Con		iwby?
39a. Endangered 39b. Enda	ngered by what? 40			may?
	ngered by what? 40			ndy?
39a. Endangered 39b. Enda 41. Distance from and fronta	ngered by what? 40			nvby?
39a. Endangered 39b. Enda 41. Distance from and fronta 42. Further Description of Im	ngered by what? 40 ge on road portant Features	Visible from p	ublic road?	nvby?
39a. Endangered 39b. Enda 41. Distance from and fronta 42. Further Description of Im three single door entries separation. The second story feature	rigered by what? 40 ge on road portant Features rated by arched stone picties afternating large and sr	. Visible from p		ndy?
39a. Endangered 39b. Enda 41. Distance from and fronta 42. Further Description of Im three single door entries sepai door. The second story featur roofline features a brick and s	rigered by what? 40 ge on road portant Features rated by arched stone picties afternating large and sr	. Visible from p	ublic road? here is a stone pediment above each	n/by?
39a. Endangered 39b. Enda 41. Distance from and fronta 42. Further Description of Im three single door entries separ door. The second story featur roofline features a brick and s 43. History and Significance	portant Features rated by arched stone pictives alternating large and strone battlement.	Visible from p	here is a stone pediment above each ich have been boarded up. The	niby?
39a. Endangered 39b. Enda 41. Distance from and fronta 42. Further Description of Im three single door entries separadoor. The second story featur roofline features a brick and s 43. History and Significance First listed in 1899 with office	portant Features rated by arched stone pictres alternating large and strone battlement.	Visible from pure windows. The mail windows what the rooms on the	here is a stone pediment above each ich have been boarded up. The	ndy?
39a. Endangered 39b. Enda 41. Distance from and fronta 42. Further Description of Im three single door entries separadoor. The second story featur roofline features a brick and s 43. History and Significance First listed in 1899 with office	portant Features rated by arched stone pictres alternating large and stone battlement. es on the ground floor and with officces below and residue to the stone of the ground floor and with officces below and residue to the ground floor and	Visible from pure windows. The mail windows what the rooms on the	here is a stone pediment above each ich have been boarded up. The	noy?
41. Distance from and fronta 42. Further Description of Im three single door entries sepandoor. The second story featur roofline features a brick and s 43. History and Significance First listed in 1899 with offic Planters' Hotel and continued	ge on road portant Features rated by arched stone pictres alternating large and strone battlement. ses on the ground floor and with officces below and rided in 1980.	Visible from pure windows. The mail windows what the rooms on the	here is a stone pediment above each ich have been boarded up. The	
39a. Endangered 39b. Enda 41. Distance from and fronta 42. Further Description of Im three single door entries sepal door. The second story featur roofline features a brick and s 43. History and Significance First listed in 1899 with offic Planters' Hotel and continued office building. Windows boa	ge on road portant Features rated by arched stone pictres alternating large and strone battlement. ses on the ground floor and with officces below and rided in 1980.	Visible from pure windows. The mail windows what the rooms on the	here is a stone pediment above each ich have been boarded up. The	
39a. Endangered 39b. Enda 41. Distance from and fronta 42. Further Description of Im three single door entries sepal door. The second story featur roofline features a brick and s 43. History and Significance First listed in 1899 with offic Planters' Hotel and continued office building. Windows boa	ge on road portant Features rated by arched stone pictres alternating large and strone battlement. ses on the ground floor and with officces below and rided in 1980.	Visible from pure windows. The mail windows what the rooms on the	here is a stone pediment above each ich have been boarded up. The	
39a. Endangered 39b. Enda 41. Distance from and fronta 42. Further Description of Im three single door entries sepal door. The second story featur roofline features a brick and s 43. History and Significance First listed in 1899 with offic Planters' Hotel and continued office building. Windows boa	ge on road portant Features rated by arched stone pictres alternating large and strone battlement. ses on the ground floor and with officces below and rided in 1980.	ure windows. The all windows what rooms on the cooms above unto	here is a stone pediment above each ich have been boarded up. The	
39a. Endangered 39b. Enda 41. Distance from and fronta 42. Further Description of Im three single door entries separ door. The second story featur roofline features a brick and s 43. History and Significance First listed in 1899 with office Planters' Hotel and continued office building. Windows boa 44. Description of Environme	portant Features rated by arched stone pictors alternating large and sortione battlement. es on the ground floor and with officces below and rarded in 1980. Int and Outbuildings	ure windows. The all windows who come above until	there is a stone pediment above each ich have been boarded up. The second floor. By 1914 it was the il circa 1935 when it became only an	
39a. Endangered 39b. Enda 41. Distance from and fronta 42. Further Description of Im three single door entries sepal door. The second story featur roofline features a brick and s 43. History and Significance First listed in 1899 with offic Planters' Hotel and continued office building. Windows boa 44. Description of Environme 45. Sources of Information Sanborn Maps, G. Craddock,	portant Features rated by arched stone pictors alternating large and sortione battlement. es on the ground floor and with officces below and rarded in 1980. Int and Outbuildings	ure windows. The all windows who come above until	there is a stone pediment above each ich have been boarded up. The second floor. By 1914 it was the il circa 1935 when it became only an	n-riby?



AU-45 (0) (2)

Missouri I	Historic	Arcl	hitectu	ural Inventol	ry Form	
1. No. 2. County		tion of Ne	gatives	4. Current Name(s)		
51 Audrain	MCRI			Mexico - Audrain Libra	гу	
5. Other Name(s)		** ***********************************	7	6d. Street Address		
Post Office		R9W	26	305 West Jackson		
7. City or Town	7b. Vicinit 8.		of Location 1 & 2, Bloc		<u>es</u>	
Mexico 10a. Site 10b. Building 10c. Si					1. * K	
I Va. Site I Viv. building I VC. Si	incore 100. Of	nec i i i c	JII INALIONAL I	Register: 12. is it eligible? ✓	13. Part of Historic D	SUICE
14. District Potential? 15. Nam	e of District	II.A	Thematic Ca	remany		
Z	e or planes		Eliciliatic Ca	ice got y		
17. Date(s) or Period	18. Style or De	sien	19.7	Architect or Engineer		Jak.
1912	Beaux Arts	- Z	The second secon	s K. Taylor		
20. Contractor or Builder	21. Original U	se .	22. P	resent Use		
George W. Stiles Construction	post office		librar			er.
23. Ownership	24. Owner's N	ame and A	\ddress		25. Open to Publi	c
public	Audrain Co. Li	brary Disti	ct, 305 West	Jackson, Mexico MO 65	26 ✔	
26. Local Contact Person or Or	ganization		27.0	ther Surveys in Which Incl	uded	
Lura Williams			n/a			
28. No. of Storie 29. Basemen	t 30. Foundatio	n Material	31.1	Wall Construction		
2 ⊈	concrete		stone	e and brick		
Roof Type and Material	33a. No. of Ba	ys, front		No. of bays, side		
hip roof/raised metal seams	5	and the state of t	5			
34. Wall Treatment	35. Plan Shape		36a.	Changes, addition (see 42) 36b. Changes, altere	d (see
smooth finished stone	rectangular		L_1		<u> </u>	
Changes, moved (see 42) 37a.	Conclition, Inter	ior	37b. Condi	tion, Exterior 38.	Preservation underway	
			1	<u></u>	 -	
39a, Endangered 39b. Endang	ered by what?	40. VI	sible from pu	DIIC FORG?		
41. Distance from and frontage	AB #2.3	T-1				
11. Distance from and nomage.	Ollyona					
42. Further Description of Impo	vrtant Features					
raised central entry with double		d by an ar	ched window	with a keystone. This ent	ry is	
flanked by identical plaladian wi	th keystone arch	es. Near e	ach corner of	the fascade is a 2/2 doub	le hung	
window with a lentil. (cont.) 43. History and Significance						
This building was first built as a	United States Pos	t Office.	In 1967 a ne	w post office was built, an	d this one	
became the Mexico-Audrain Lit						
listing in the National (cont.)	To a second	<u>.</u> 1000 100 100 100	Cara Trafo			
44. Description of Environment	and Quidunding	NG B RE				og Miller
						si isa Matsan
	150 s = 1 - 1 - 1 - 1 - 1 - 1 - 1 - 1 - 1 - 1	androne and	750.5 1.2			
45. Sources of Information	46. Prepared b		7	Organization		
Sanborn Maps, G. Craddock (c		nen Lagi da da	July (of Mexico		
	ion Date(s)					Min
3/13/2002	8.3			wa ji ka Mada		43.28

#51

Mexico – Audrain Library 305 West Jackson Street

- 42. The central part of the fascade with the entry and palladian windows projects out slightly. The second floor has a 1/1 double hung window above each of the first story corner windows. There are dentals along the eves and stone carved panels above the eves. The changes to this building are primarily interior ones. The second floor inside was added in 1966 when it was converted to a library. The front steps were changed in 1980 and the basement was remodeled in 1984.
- 43. Register of Historic Places in 1988 by the State Historic Preservation Program.
- 45 "Audrain County Missouri, Reflections of the Past 1945-2000," by Gayle Messer.



48 Audrain	MCRI		Mexico Audrain Co. Library Annex
5. Other Name(s)	6a. Township 6b. R	lange 6c. Section	n 6d. Street Address
Carnegie Library	T51N R9W	26	305 West Jackson
7. City or Town	7b. Vicinit 8. Desci		
Mexico	N 1/2	of Lots 1 & 2, Ble	ock 14
10a. Site 10b. Building 10c. Str	ucture 10d. Objec	11. On National	Register? 12. Is it eligible? 13. Part of Historic Dist
			
14. District Potential? 15. Name	e of District	16. Thematic (ategory
∠			
17. Date(s) or Period	18. Style or Design		Architect or Engineer
1913	classical influence	Ben	Elliot
20. Contractor or Builder	21. Original Use		Present Use
L.M. Lake	library	libra	and the second s
23. Ownership	24, Owner's Name		25. Open to Public
public			Vest Jackson, Mexico MO 65 💆
26. Local Contact Person or On	anization .		Other Surveys In Which Included
Lura Williams		n/a	
28. No. of Storie 29. Basement		Accession of the second se	Wall Construction
1 💆	concrete	bri	ck
Roof Type and Material	33a. No. of Bays, fr	ont 33b	. No. of bays, side
hip roof/clay tiles	5	2	
34. Wall Treatment	35. Plan Shape	36a	. Changes, addition (see 42) 36b. Changes, altered
brick	rectangular		
Changes, moved (see 42) 37a.	Condition, Interior	37b. Con	dition, Exterior 38. Preservation underway?
<u> </u>			
39a. Endangered 39b. Endange	red by what? 4	O. Visible from p	ublic road?
	Y		
41. Distance from and frontage	on road		
42. Further Description of Impo			
			liment with dentals. Dentals also run is on each side of the entry and under
each a 3/1 stationary window (_	C.O WINI CHANCOIII	
43. History and Significance			
			67. At that time Robert White of the
Mexico Ledger bought it and use Ledger gave it to (cont)	ed it for storage as we	ii as for Mexico's	s Television studio. In 1989 the
44. Description of Environment	and Ourbuildings	STORY STREET	
		on the second	
45. Sources of Information	46. Prepared by		Organization
G. Craddock, Leta Hodge, (con		JCIN	y of Mexico
	on Date(s)		
3/11/2002			

#48

Carnegie Library 305 West Jackson

- 42. in the basement. There are fourteen steps that lead from the sidewalk up to the entrance,.
- 43. the city on the condition that it be moved and used for a library. It was moved from 314 North Washington to its current location in 1990 and a short walkway connects it to the Audrain County Library. This building was determined eligible for listing in the National Register of Historic Places in 1988 by the State Historic Preservation Office.
- 44. "Audrain County Missouri, Reflections of the Past 1945-2000" by Gayle Messer.



1. No. 2. County	3. Location o	of Negatives	4. Current Nam	eine la disconnitivitamenti libiliti i interfere li interfere	
50 Audrain	MCRI		First Christian C	hurch	
5. Other Name(s)	6a. Township 6b. R				
	T51N R9W	26	307 West Jacksor	1	
7. City or Town	7b. Vicinit 8. Descr			ordinates	
Mexico	Lots 3,4	1,5, & 6, Block 1	4		
10a. Site 10b. Building 10c.	Structure 10d. Objec	11. On National	and the second of the second o	ligible? 13. Part o	f Historic District
14. District Potential? 15. Na	ime of District	16. Thematic C	Category		
✓					
17. Date(s) or Period	18. Style or Design	19.	Architect or Enginee		
1905			9.00.00		
20, Contractor or Builder	21. Original Use	22.	Present Use		
H.H. Meyer, Mexico MO	church	chui	rch		
23. Ownership	24. Owner's Name:			2111	pen to Public
private	Randall Sawyer, Past	er, 307 West Jac	kson, Mexico MO	65265	
26. Local Contact Person or C	Organization	27. (Other Surveys in Wh	ich Included	
Lura Williams		n/a	300 philosophia		
28. No. of Storie 29. Baseme	ent 30. Foundation Mai		Wall Construction		
2	stone	bric	:k		
Roof Type and Material	33a. No. of Bays, fro	ont 33b	. No. of bays, side		
hip roof/tiles	[5	5			
34. Wall Treatment	35. Plan Shape	The same of the sa	. Changes, addition (see 42) 36b. Ch	anges, altered (see 42)
brick	rectangular	V			
Changes, moved (see 42) 37	a. Condition, Interior	37b. Cond	Iltion, Exterior	38. Preservatio	n underway?
				Light of	
39a. Endangered 39b. Endar		O. Visible from p	ublic road?		
	∀				
41. Distance from and frontag	e on road				
42. Further Description of Im					
triple arched recessed entry su					
There is one 1/2 window on e	each side of the arches.	The second story	leatures a Central ga	iibe with returned	
43. History and Significance					
Built in 1905, the education of					
the 1950's. The First Christia		l in Mexico in 18	42 and is best know	n for its living	
nativity which is now in its 45 44. Description of Environment	de la companya de la				
TATE SECURIOR OF CAMPORIUS	nt and Coupunding				
Markey Control of the	a and a second s	tere and the second of the sec	1		
45. Sources of Information	46. Prepared by		Organization		
Sanborn Maps, G. Craddock (City	of Mexico	n socialists (Miller and Str.	
	/ision Date(s)			ni setti	
3/13/2002					

#50

First Christian Church 307 West Jackson Street

- 42. arched palladian window with a ½ double hung window on each side. This building had an addition which was built in 1953.
- 45. "Audrain County Missouri, Reflections of the Past 1945-2000" by Gayle Messer and "A Gathering of Our Days," by Leta Hodge.



AU-AS MI-124

1. No. 2. County	3. Location of Negativ	ves 4. Current Name(s)
30 Audrain	MCRI	Hagan Clothing Company
5. Other Name(s)	6a. Townshi 6b. Rang 6c. Se	ectio 6d. Street Address
	T51N R9W 26	100 North Jefferson
7. City or Town	7b. Vicini 8. Description of I	Location 9. UTM Coordinates
Mexico S 40' of Lot 5, Block 12		
10a. Sit 10b. Buildin 10c. Structu 10d. Objec 11. On National Regist 12. Is it eligibi 13. Part of Historic Distr		
14. District Potenti 15. Name of District 16. Thematic Category		
17. Date(s) or Period	18. Style or Design	19. Architect or Engineer
circa 1880		
20. Contractor or Builder	21. Original Use	22. Present Use
	commercial	vacant
23. Ownership	24. Owner's Name and Addre	ess 25. Open to Publ
private	Mary Thomas, 100 North Jef	
26. Local Contact Person or (27. Other Surveys in Which Included
Lura Williams		n/a
28. No. of Stori 29. Baseme	30. Foundation Material	31. Wall Construction
2	brick	brick
Roof Type and Material	33a. No. of Bays, front	33b. No. of bays, side
flat/asphalt	5	4
34. Wall Treatment	35. Plan Shape	36a. Changes, addition (see 36b. Changes, altered (see
brick	rectangular	Soa. Crianges, addition (See Sob. Crianges, area of the
		Condition, Exterior 38. Preservation underw
Changes, moved (see 37a.)	condition, interior 37b.	So. Preservation under w
39a. Endangere 39b. Endangered by what? 40. Visible from public road?		
39a. Elidangere 35b. Elidangered by What: 40. Visible from public road:		
41. Distance from and frontage on road		
41. Distance from and from age of road		
42. Further Description of Important Features		
recessed entry flanked by large display windows. A metal awning with square brick columns		
		e façade and wraps around the
corner. There is metal sheathing over second floor façade (circa 1980).		
43. History and Significance		
The earliest map - 1885 - shows the building was a bank. It remained a bank, Mexico Savings		
Bank, until 1935. At that time the building was aquired by Woolworths. It was extensively remodeled at that time. (cont.)		
44. Description of Environment and Outbuildings		
	Ten Billion and	
45. Sources of Information	46. Prepared by	47. Organization
Sanborn Maps, G. Craddock Mary Aue Mitchell City of Mexico		
48. Date 49. Revision Date(
3/3/2002		

#30

100 North Jefferson

43. In 1974 it was bought by the Hagan family, and it became a clothing store. The building was extensively remodeled again and the fixed awning added. Hagan clothing went out of business in the spring of 2002 and the building became the home of the Jefferson Street Trading company. It is a gift and clothing shop.

45 "A Gathering of Our Days" by Leta Hodge





1, No. 2. County	3. Location of Neg	gatives 4. Current Name(s)
29 Audrain	MCRI	Safford Shoe Store
5. Other Name(s)	6a, Township 6b, Rana	6c. Sectio 6d. Street Address
		26 104 North Jefferson
7. City or Town	7b. Vicinit 8. Description	of Location 9. UTM Coordinates
Mexico	N 20' of Lot 5,	, Block 12
10a. Site 10b. Buildin 10c. :	Structur 10d. Obje 11. Or	National Register 12. Is it eligible 13. Part of Historic District
14. District Potential 15. Na	me of District 16. T	hematic Category
U.		
17. Date(s) or Period	18. Style or Design	19. Architect or Engineer
20. Contractor or Builder		22. Present Use
	comrnercial	commercial
23. Ownership	24. Owner's Name and A	
private		North Jefferson, Mexico MO 65265
26. Local Contact Person o	r Organi <mark>ration</mark>	27. Other Surveys in Which Included
Lura Williams		n/a
28. No. of Stories 29. Basem		
2	brick	brick
Roof Type and Material	33a. No. of Bays, front	33b. No. of bays, side
flat/asphalt	3	
34. Wall Treatment	35. Plan Shape	36a. Changes, addition (see 36b. Changes, altered (see
brick	rectangular	
Changes, moved (see 37)	a. Condition, Interior	37b. Condition, Exterior 38. Preservation underwa
39a. Endangere 39b. Enda	ngered by what? 40. Visib	ole from public road?
41. Distance from and front	age on road	
100 mm		
42. Further Description of Im	The state of the s	etal awning/walkway separates the two
		eral awiling/waikway separates the two ndows, stone pilasters, brick panels, and a
double row of corbelled de	entils. (cont.)	
43. History and Significance		1000
•		1899, no change. 1908, 1914, 1926, 1932, 35 show Wilkins Brothers Shoe Store. The
Safford family bought the k		A STOW THINING DICTION STOCK STORE. THE
44. Description of Environme	and the state of t	
		The state of the s
45. Sources of Information	46. Prepared by	47. Organization
Sanborne Maps, G. Craddo		City of Mexico
48. Date 49. Rev	rision Date(s	
3/3/2002		

#29

104 North Jefferson

42. The awning was added and entry remodeled in 1984.



#28

106 North Jefferson

- 42. The façade was remodeled circa 1980.
- 43. 1914, Western Union Telegraph, Jewelry and Books. 1926, variety store. 1934, Missouri Brokerage firm and Mattingley Brothers Department Store. Hallmark Gifts move in circa 1975.
- 45 City Directories, Telephone Books.



1. No. 2. County	3. Location of	Negatives	4. Current Name(s)	
27 Audrain	MCRI	rieganies	Seigfreid Law Firm	
5. Other Name(s)	lóg: Township lób. Ran	a lác. Seci	lo 6d. Street Address	
	T51N R9W	26	108 North Jefferson	
7. City or Town	7b. Vicinit 8. Descrip	ion of Loca	otion 9. UTM Coordinates	
Mexico		t 6, Block 1		
Oa. Site 10b. Buildin 110c.	Structur 10d Oble 11	On Nation	al Register 12. is it eligible 13. Part of His	toric Dis
4. District Potential 15. No	ame of District	6. Thematic	Category	
7. Date(s) or Period	18. Style or Design	119	. Architect or Engineer	
circa 1880				
20. Contractor or Builder	21. Original Use	22	. Present Use	
	commercial		ommercial	
23. Ownership	24. Ovner's Name ar	d Address	25. Open	o Publi
private			al Lake Place, Mexico MO 6	
26. Local Contact Person o	or Organization	27.	Other Surveys in Which included	
Lura Williams		n/d		
28. No. of Stories 29. Basen	nen 30. Foundation Mate	rial 3	I. Wall Construction	
2 🗀 🗀	brick	1	rick (A	
Roof Type and Material	33a, No. of Bays, fron	1 33	b. No. of bays, side	
flat/asphalt	3			
34. Wall Treatment	35. Plan Shape	36	a. Changes, addition (see 36b. Chang	es, alter
orick	rectangular		V	
Changes, moved (see 37	7a. Condition, Interior	37b. Co	ndition, Exterior 38. Preservation u	nderwa
19a. Endangere 39b. Endo	angered by what? 40. \	isible from	public road?	
J. T. S. T.	✓			
11. Distance from and fron	itage on road			
12. Further Description of Ir	nportant Features			
six light corner door. The c	center of the façade has		dow flanked by black metal	
			second story features three double	
nung windows. The façac 13. History and Significance	The second state of the second	SIGU CIICU	1770.	
		. In 1932 it	was a variety store and in 1954 it	
partially collapsed and wo				 15
V 5 (2)				
4. Description of Environm	tent and outbuildings			
45, Sources of Information			. Organization	167
Sanborn Maps, G. Craddo		Ci	ty of Mexico	
18. Date 49. Rei 3/3/2002	vision Date(s			
				aan aa ah



1. No. 2. County	3. Location of N	legatives 4. Current Name(s)	7
26 Audrain	MCRI	Mid Missouri Accounting	J.
5. Other Name(s)	L L	6c, Sectio 6d. Street Address	No.
Sticky Wicket	T51N R9W	26 110 and 112 North Jefferson	-
7. City or Town	7b. Vicinit 8. Description	on of Location 9. UTM Coordinates	
Mexico		6 and all Lot 7, BI	
The state of the s	Structur 10d Oble 11. C	On National Register 12. Is it eligible 13. Part of	Historic District
14, District Potential 15. N	lame of District	Thematic Category	
17. Date(s) or Period	18, Style or Design	19. Architect of Engineer	
circa 1885			
20. Contractor or Builder	21. Original Use	22. Present Use	
	comrnercial	commercial	
23, Ownership	24. Owner's Name and	Address 25. Op	en to Publi
private	Mark W. & Deborah K.	Thoenen, 1940 Windsor Court, O Box 9 🗹	
26. Local Contact Person	or Organization	27. Other Surveys in Which Included	I was
Lura Williams		n/a	
28. No. of Stories 29. Base	men 30. Foundation Materi		J. Santa
1 4 3	concrete	brick	10
Roof Type and Material	33a. No. of Bays, front	33b. No. of bays, side	
flat/asphalt	7		Britis Company
34. Wall Treatment	35. Plan Shape	36a. Changes, addition (see 36b. Cha	anges, altered (se
brick	rectangular		
Changes, moved (see 3	37a, Condition, Interior	37b. Condition, Exterior 38, Preservation	n underwa
			1
39a. Endangere 39b. End	langered by what? 40. Vis	sible from public road?	J
	V.		1
41. Distance from and fro	ntage on road		
42. Further Description of		ows. The length of the façade has a metal	
	•	e roof.This building was extensively remodeled	
circa 1955 and again circ	ca 1975.		
43. History and Significant		1000 1000 1000 1000	
		store. 1890, 1894,1899, 1908, 1914, no fice building since circa 1975.	Sec.
Grange, 1720, 1702, Valid	ory store. It has been all off	nee ballaning since ened 1770.	8
44. Description of Environ	ment and Outbuildings		
45. Sources of Information	1 46. Prepared by	47. Organization	
Sanborn Maps, G. Cradd		City of Mexico	
48. Date 49. Re	evision Date(s		190
3/1/2002			
L			



AU-A5001-029

1. No. 2. County	3. Location of Nega	tives 4. Current Name(s)	
25 Audrain	MCRI	Rite-Way to Rent	
5. Other Name(s)	6a, Township 6b, Rang 6c	Sectio 6d. Street Address	
Fredendoll Department Stor	T51N R9W 26	120 North Jefferson	
7. City or Town	7b. Vicinit 8. Description of	Location 9. UTM Coordinates	
Mexico	N 35.4' of Lot 8,	Block 12	
10a Site 10b Buildin 10c St	ructur 10d. Obje 11. On N	ational Register 12. Is it eligible 13. Part	of Historic District
14. District Potential 15. Nam	ne of District 16. The	matic Category	
		The state of the s	
17. Date(s) or Period circa 1885	18. Style or Design	19. Architect or Engineer	⊥
	modern commercial		
20. Contractor or Builder	21. Original Use	22. Present Use	4 (2)
	comrnercial	commercial	
23. Ownership	24. Owner's Name and Add		pen to Publi
private	Robert Barnes, 112 West Ja		
26. Local Contact Person or	<u>Organization</u>	27. Other Surveys in Which Included	4
Lura Williams		n/a	
28. No. of Stories 29. Baseme		31. Wall Construction	
	concrete	brick	
Roof Type and Material	33a. No. of Bays, front	33b. No. of bays, side	
mansard/asphalt shingles	2		
34. Wall Treatment	35. Plan Shape	36a. Changes, addition (see 36b. Ch	nanges, altered (see
brick	rectongular		
Changes, moved (see 37a	Condition, Interior 37	b. Condition, Exterior 38. Preservat	lon underwa
		L-d	_
39a. Endangere 39b. Endan	gered by what? 40. Visible	from public road?	J. Francisco
	<u> </u>		
41. Distance from and fronto	ige on road		4
42. Further Description of Imp	ontant Footures	· ' ' ' ' ' ' ' ' ' ' ' ' ' ' ' ' ' ' '	7
		ows run the legath of the façade with	
		d the building was extensively remodled	ı
43. History and Significance			
		e. 1890 no change. 1894, grocery. 1899	
millinery. 1908, 1914, hardwo Store until circa 1970.	are. 1926, 1934, department	store. It was the Fredendoll Department	
44. Description of Environme	nt and Outbuildings	Company of the Compan	
45. Sources of Information	46. Prepared by	47: Organization	
Sanborn Maps, G. Craddocl	Mary Aue Mitchell	City of Mexico	
48. Date 49. Revis	ion Date(s		
3/1/2002			



1. No. 2. County	3. Location of I	f Negatives 4: Current Name(s)	
17 Audrain	MCRI	Pearl Motor Company	
5. Other Name(s)	6a. Township 6b. Rang	ng 6c. Sectio 6d. Street Address	
	T51N R9W	26 220 North Jefferson	
7. City or Town	7b. Vicinit 8. Descript	otion of Location 9. UTM Coordinates	
Mexico	Lots 5,6,7,	, and 8 of Block 18	
10a. Site 10b. Buildin 10c. St	ructur 10d. Obje 111.	. On National Register 12, is it eligible 13. Part of Historic Distri	ct
14. District Potential 15. Nam	e of District	6. Thematic Category	
17, Date(s) or Period	18. Style or Design	19. Architect or Engineer	
circa 1915			
20. Contractor or Bullder	21. Original Use	22. Present Use	
	commercial	commercial	
23. Ownership	24. Owner's Name an	nd Address 25. Open to Publi	
private		1505 Webster Drive, Mexico MO 65265	
26. Local Contact Person or (Organi::ation	27. Other Surveys in Which Included	
Lura Williams		n/a	
28. No. of Stories 29. Baseme	n 30. Foundation Mate	erial 31. Wall Construction	
2	brick	brick	
Roof Type and Material	33a. No. of Bays, front	nt 33b. No. of bays, side	
flat/asphalt	6	4	
34. Wall Treatment	35, Plan Shape	36a. Changes, addition (see 36b. Changes, altered	d (see
brick	rectangular	Maria de la Carta	
Changes, moved (see 37a.	Condition, Interior	37b. Condition, Exterior 38. Preservation underwa	
39a. Endangere 39b. Endang	gered by what? 40. V	Visible from public road?	
	v		
41. Distance from and fronta	ge on road		
42. Further Description of Imp	ortant Features		
		room windows and glass doors in the "addition"	
	of garage doors and br	orick parapets at the roof are the main features	
on the orginal building.			
43. History and Significance The earliest man - 1885 - show	ws a livery stable on this	nis site. 1894, 1899, no change. 1914, 1908 livery	
		g station. By 1934 it was listed as auto sales and	
service.			
44. Description of Environmen	nt and Outbuildings		
45. Sources of Information	46 Prepared by	47. Organization	
Sanborn Maps, G. Craddock		City of Mexico	
48. Date 49. Revis	on Date(s		
2/27/2002		The state of the s	



1. No. 2. County	3. Location of	f Negatives 4. Current Name(s)
16 Audrain	MCRI	K & M Printing
5. Other Name(s)	6a. Township 6b. Rar	ng 6c. Sectio 6d. Street Address
Coca Cola Bottling Factor	/ T51N R9W	26 221 North Jefferson
7. City or Town	7b. Vicinit 8. Descrip	otion of Location 9. UTM Coordinates
Mexico	E 15' Lot 6	6 and all of Lots 7 &
10a. Site 10b. Buildin 10c. S	Structur 10d Obje 11	1. On National Register 12. Is it eligible 13. Part of Historic District
14. District Potential 15. Na	me of District	16. Thematic Category
✓ .		
17. Date(s) or Period	18. Style or Design	19. Architect or Engineer
1935		
20. Contractor or Builder	21. Original Use	22, Present Use
	commercial	commercial
23. Ownership	24. Owner's Name ar	nd Address 25. Open to Publi
private		oany, 221 North Jefferson, Mexico MO 65 🗹
26. Local Contact Person o	r Organization	27. Other Surveys in Which Included
Lura Williams		n/a
28. No. of Storles 29. Basem	en 30. Foundation Mate	erial 31. Wall Construction
2	brick	brick
Roof Type and Material	33a. No. of Bays, fron	nt 33b. No, of bays, side
flat/asphalt	7	6
34. Wall Treatment	35. Plan Shape	36a. Changes, addition (see 36b. Changes, altered (see
brick	rectangular	
Changes, moved (see 37a	a, Condition, Interior	37b. Condition, Exterior 38. Preservation underwa
39a, Endangere 39b, Endar	ngered by what? 40.1	Visible from public road?
	V	
41. Distance from and front	age on road	A CONTRACTOR OF THE PARTY OF TH
42. Further Description of Im	portant Features	
recessed entry frlanded by	large picture window to	opped by decorative wooden panels. The
		oden panel added by the current owner. There
is a partial second story with 43. History and Significance	GRANDSON TO AN INC. A COURT OF STREET	j tongnis. (COTL)
		tory in 1935. In 1970's it was used by the
Jefferson City Coca Cola B	ottling Company as a v	warehouse. Carl Myer of K & M Printing bought
the building in 1978. This is a		ctive (cont.)
44. Description of Environme	ent and Outbuildings	
	Andrew March Control of the Control	
45. Sources of Information	46. Prepared by	47. Organization
Sanborn Maps, C. Myer	Mary Aue Mitchell	City of Mexico
for the contract of the contra		
48. Date 49. Rev	ision Dcite(s	

#16

Coca Cola Bottling Factory 221 North Jefferson

- 42. There are carved stone Coca Cola signs at the center front along the roofline above the double row of corbelling and on the side. There are large wooden doors covering the loading entry on the façade and side. The side also had four 15 light stationary windows and a double row of corbelling near the roofline.
- 43. And recognizable buildings on the square. It is also one of the most intact.





AU- AS 000 000

1. No. 2. County	3. Location of Ne	egatives	4. Current Name	(s)	
82 Audrain	MCRI		Weddings by Pil	cher's	
5. Other Name(s)	6a. Townshi 6b. Rang	6c. Sectio 6	d. Street Addres	5	_
	T51N R9W	26 1	00 S. Jefferson		-
7. City or Town	7b. Vicini 8. Description	n of Location	9. UTM Coord	linates	
Mexico	☐ N 47' Lot 5, I	Block 9			
10a. Sit 10b. Buildin 10c. Str	uctu 10d. Objec 11. O	n National Re	gist 12. Is it elig	ibi 13. Part of	Historic Distr
					
14. District Potenti 15. Name	of District 16.	Thematic Car	egory		
v					
17. Date(s) or Period	18. Style or Design	19. Arc	hitect or Engine	er	
circa 1880	Italianate influence				
20. Contractor or Builder	21. Original Use	22. Pre	sent Use		
	commercial	comm	ercial		
23. Ownership	24. Owner's Name and	Address		25. Oper	n to Publ
private	Iva May Pilcher McDon		ach Ave., Bay St.		
26. Local Contact Person or	Organization	27. Oth	er Surveys in Whi	ch included	
Lura Williams	<u> </u>	n/a			
28. No. of Stori 29. Baseme	30. Foundation Materia	al 31. Wa	II Construction		
2	brick	brick			
Roof Type and Material	33a. No. of Bays, front	33b. No	o. of bays, side		
flat/asphalt	3	8	o. or buyo, side		
34. Wall Treatment	35. Plan Shape	36a Ct	anges addition	(see 36h Chan	ges, altered (see
brick	rectangular	300.01	arigos, addicion		300, 41.
	Condition, Interior	37h Conditi	on, Exterior	38. Preservatio	n underw
Changes, moved (see size.	oonarion, meerior	John Contain	OTT, EXCOTOR		
39a. Endangere 39b. Endang	ered by what? 40 Visi	ible from pu	nlic road?		
35a. Elicangere 35b. Elicang	y what:	ibic iroini pui	one roug:		
41. Distance from and front	age on road				
41. Distance from and from	age of Fodd				
42. Further Description of In	nnortant Features				
recessed central entry flank		and topped	with a glass page	el. A	
bracketed cornice separate	s the first and second s	tories. The s	econd story fasc	ade features	
three 1/1 double hung wind	tows with lug sills and s	surrounds. (c	cont.)		
43. History and Significance					
The earliest map shows a gr with a tin shop in the basen	rocery store and photo	studio. 1890	,1894,1899, boots	and shoes	
damaged by fire in 1913. Th	ne interior was rebuilt (c	ont.)	y. The building \	vas ricavily	
44. Description of Environm					
	46 Bronared by	A7 C	nanization		
45. Sources of Information Sanborn Maps, G. Craddock	46. Prepared by Mary Aue Mitchell		janization Mexico		
		Icity o	MEXICO		
	ion Date(
6/6/2002					

#82

Weddings by Pilcher's 100 South Jefferson

- 42. The Jackson Street side of the building has four 1/1 double hung windows on the east end and five stationary windows on the west end of the first story. The second story features eleven 1/1 double hung windows. Each of these windows has surrounds and lug sills.
- 43. and it was home the Hagan's Clothing Store from circa 1940-1975. After Hagan's moved out it become Children's World then Weddings by Pilcher's.







		2 CONTROL TO STATE OF THE PROPERTY OF THE PROP
1. No. 2. Count		
83 Audrain	MCRI	Pilcher Jewelry
5. Other Name(s)		6c. Section 6d. Street Address
	T51N R9W	26 102 S. Jefferson
7. City or Town	7b. Vicinit 8. Descriptio	
Mexico	N 47' of Lo	
10a. Site 10b. Building	g TOc. Structure TOd. Objec 11.	On National Register? 12. Is it eligible? 13. Part of Historic District
14. District Potential?	15. Name of District 16	5. Thematic Category
<u>'</u>		
17. Date(s) or Period	18. Style or Design	19. Architect or Engineer
circa 1880		
20. Contractor of Build		22, Present Use
1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1	commercial	commercial
23. Ownership	24. Owner's Name and	The state of the s
private		ld, 504 N. Beach Ave., Bay St. Louis MS
26. Local Contact Perso	on or Organization	27. Other Surveys in Which Included
Lura Williams		n/a
	Basement 30. Foundation Material	
2	brick	brick Republic Republ
Roof Type and Materia	33a. No. of Bays, front	33b. No. of bays, side
flat/asphalt	3	
34. Wall Treatment	35. Man Shape	36a, Changes, addition (see 42) 36b. Changes, altered (see 42)
brick	rectangular	
Changes, moved (see 4	2) 37a. Condition, Interior	37b. Condition, Exterior 38. Preservation underway?
39a. Endangered 39b.	Endangered by what? 40. V	sible from public road?
J. 1995	V	
41. Distance from and	frontage on road	
42. Further Description	of Important Features	
		ed with a cloth awning and a glass panel just below
		tories. The second story features three 1/1 double
hung with surrounds an 43. History and Signific	20 processor de la contrata del contrata del contrata de la contrata del la contrata de la contrata del la contrata de la contrata del la	
		0,1894,1899, dry goods store. 1908,1913,
clothing store. The bui		n 1913. Pilcher's Jewlery move in circa 1925 and
remains there.	1 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2	
44. Description of Envi	ronment and Clutbuildings	
45. Sources of Informa	cion 46. Prepared by	47. Organization
	ddock, Ci Mary Aue Mitchell	City of Mexico
48. Date 4	19. Revision Date(s)	
	** * ***** * * * * * * * * * * * * * *	



1. No. 2. County	3. Location of Neg	artives 4. Current Name(s)
84 Audrain	MCRI	Stitch In Time
5. Other Name(s)	6a. Township 6b. Range	6c. Section 6d. Street Address
	T51N R9W	26 104 South Jefferson
7. City or Town	7b. Vicinit 8. Description	of Location 9. UTM Coordinates
Mexico	S 45' of Lots	5 & 6, Block 9
10a. Site 10b. Building 1	Oc. Structure: 10d. Objec 11. O	n National Register? 12. Is it eligible? 13, Part of Historic District
14. District Potential? 15	. Name of District 16.	Thematic Category
✓.	-	
17. Date(s) or Period	18. Style or Design	19. Architect or Engineer
circa 1920		
20. Contractor or Builder	21. Original Use	22. Present Use
	commercial	commercial
23. Ownership	24. Owner's Name and A	ddress 25. Open to Public
private	James & Ann Stubblefield,	, 15389 Adurain Rd 821, Mexico MO
26. Local Contact Person	or Organization	27. Other Surveys in Which Included
Lura Williams		n/a
28. No. of Storle 29. Ba	sement 30. Foundation Material	31. Wall Construction
2 🗀 🚐	brick	brick
Roof Type and Material	33a. No. of Bays, front	33b. No. of bays, side
flat/asphalt	3	
34. Wall Treatment	35. Plan Shape	36a. Changes, addition (see 42) 36b. Changes, altered (see 42)
brick	rectangular	
Changes, moved (see 42)	37a. Condition, Interior	37b. Condition, Exterior 38. Preservation underway?
39a. Endangered 39b. E	ndangered by what? 40. Visi	ible from public road?
L.	Y	
41. Distance from and fro	ontage on road	
42. Further Description o		
		h bubble awning runs the length of the fascade.
row of corbelled brick det	_	ng windows with lug sills. Near the roofline is a
43. History and Significan		
		13. By 1929 it was vacant, but by 1935 it
	which remained there until circa 1	1965. Stitch in Time moved in in 1984 and
remains there. 44. Description of Environ	nonant and Chathwildform	The second secon
TA DESCRIPTION OF ERMIO	ment and Cathania	
Part of high size and higher and higher and	CONTROL OF A LOCAL CONTROL OF A	Property and the second
45. Sources of Informatio		47. Organization
Sanborn Maps, A. Stubble	the second secon	City of Mexico
	Revision Date(s)	
6/6/2002		



1. No. 2. County		ation of Negatives	4. Current Name		
70 Audrain	MCRI	B. 0823 127 " ASSILIN WY	US Army Recruit	ng	
5. Other Name(s)			tion 6d. Street Address	-	
Jefferson Beauty Shop	T51N	R9W 26	111,109 South Jet		
7. City or Town		Description of Local		dinates	
Mexico		40' of Lot 8, Block			
10a. Site 10b. Building 10	c. Structure 10d. O	bjec 11. On Natio	nal Register? 12. is it eli	gible? 13. Part of F	listoric District
		ll e per		. Ц.	
14. District Potential? 15.	Name or District	16. Themati	c Category		
17 8 (1 8 1 1	Tio C.J. B		A 1 - 1 - 2 - 1 - 2 - 2 - 2 - 2 - 2 - 2 -		
17. Date(s) or Period circa 1934	18. Style or De	esign i	9. Architect or Engineer		
	01 252224	68 76 112 3 8586 NO. 10	**************************************		
20. Contractor or Builder	21. Original U		2. Present Use ommercial		
37 A 3 4 5 5 5 5 5 5 5 5 5 5 5 5 5 5 5 5 5 5					
23. Ownership private		Name and Address	ox 210, Auxvasse, MO		i to Public
26, Local Contact Person o Lura Williams	I Organization	n/	7. Other Surveys In Whic	n menuea	
28. No. of Storle 29. Base			a S1. Wall Construction		
20. 140. O Storie ZY. 8850	concrete		orick		
Naud Times and Maradal			Water the same and		
Roof Type and Material flat/asphalt	33a. No. of Ba	ys, none 3	3b. No. of bays, side		
	35. Plan Shape		A Character Library	. 42\ T&L CL-	ene albaroad (saa digi
34. Wall Treatment brick	rectangular	2	6a. Changes, addition (s	E 12) 300, Chang	es, altered (See 42)
Changes, moved (see 42)		107 T71 C	ondition, Exterior	38. Preservation i	undenway2
Sildinges, moved (see 42)	J. J. Commiduit, illiei	3,0,0	Circulony LACTION	Jo. I reservation i	muer may.
39a. Endangered 39b. En	fangered by what?	40. Visible from	nublic road?		
J. J. S.		<u> </u>			
41. Distance from and fron	case on road				
		<u> </u>			
	AND THE RESERVE OF TH	<u> </u>		180	
42. Further Description of	mportant Features				
42. Further Description of recessed central entry flank		's and topped with a	boarded over transom.	There is a brick	
	ed by display window				
recessed central entry flank panel between them and th	ed by display window e belt course. The p				
recessed central entry flank panel between them and th	ed by display window e belt counse. The p	ediment at the roofli	ine features a carving of a	saling ship.	
recessed central entry flank panel between them and th	ed by display window e belt course. The po e o Hotel, this building	ediment at the roofli	ine features a carving of a	saling ship.	
recessed central entry flank panel between them and th 43. History and Significance Built on the site of the Ring circa 1970. It became the	ed by display window e belt course. The po g o Hotel, this building Army Recruiting off	ediment at the roofling first housed Epple Concerning in circa 1985.	ine features a carving of a	saling ship.	
recessed central entry flank panel between them and th 43. History and Significanc Built on the site of the Ring	ed by display window e belt course. The po g o Hotel, this building Army Recruiting off	ediment at the roofling first housed Epple Concerning in circa 1985.	ine features a carving of a	saling ship.	
recessed central entry flank panel between them and th 43. History and Significance Built on the site of the Ring circa 1970. It became the	ed by display window e belt course. The po g o Hotel, this building Army Recruiting off	ediment at the roofling first housed Epple Concerning in circa 1985.	ine features a carving of a	saling ship.	
recessed central entry flank panel between them and th 43. History and Significance Built on the site of the Ring circa 1970. It became the	ed by display window e belt course. The po g o Hotel, this building Army Recruiting off	ediment at the roofling first housed Epple Concerning in circa 1985.	ine features a carving of a	saling ship.	
recessed central entry flank panel between them and th 43. History and Significance Built on the site of the Ring circa 1970. It became the	ed by display window e belt course. The po g o Hotel, this building Army Recruiting offi ment and Gutbuilding	ediment at the roofling first housed Epple Clice in circa 1985.	ine features a carving of a	saling ship.	
recessed central entry flank panel between them and th 43. History and Significance Built on the site of the Ring circa 1970. It became the 44. Description of Environr	ed by display window e belt course. The page o Hotel, this building Army Recruiting offi ment and Cutbuilding	ediment at the roofling first housed Epple Clice in circa 1985.	ine features a carving of a	saling ship.	
recessed central entry flank panel between them and th 43. History and Significance Built on the site of the Ring circa 1970. It became the 44. Description of Environmental Sanborn Maps, G. Craddo	ed by display window e belt course. The page to Hotel, this building Army Recruiting offinent and Cutbuilding	ediment at the roofling first housed Epple Clice in circa 1985.	ine features a carving of a Construction Company w	saling ship.	



1. No. 2. County	3. Loc	ation of Ne	gatives	4. Current Name(s)	
85 Audrain	MCRI			Touch of Class	
5. Other Name(s)		The same of the sa	4	o 6d. Street Address	1.00
ىلىنى ئىلىنىڭ ھىۋىدىدىدىنىدىدىدىدىدىدىدىدىدىدىدىدىدىدىد	T51N	R9W	26	112 South Jefferson	and the second of the
7. City or Town	7b. Vicinit 8.				
Mexico	⊔ ≀ N	20.5' of L	ots 3 & 4,	Block 9	
10a. Site 10b. Building 10c. Sti	ucture 10d. O	bjec 11. C	On National	Register? 12. Is it eligible? 13. Part of	of Historic District
	$ \mu$				
14. District Potential? 15. Nami	of District	16.	Thematic C	ategory	
∠ .					
17. Date(s) or Period	18. Style or D	esign	19.	Architect or Engineer	
circa 1885					
20. Contractor or Builder	21, Original U	lse	22.	Present Use	
	commercial		com	ımercial	
23. Ownership	24. Owner's N	Name and A	address	25. 0	pen to Public
private	Shaun Nolan,	6377 Co. 1	Rd 262, Au	ixvasse, MO 65231 ✓	
26. Local Contact Person or Org	anization		27. (Other Surveys in Which Included	
Lura Williams			n/a		
28. No. of Storie 29. Basement	30. Foundation	n Material	['] 31.	Wall Construction	
2	brick		brio	ck	
Roof Type and Material	33a. No. of B.	ays, front	33b	. No. of bays, side	
flat/asphalt	2				
34. Wall Treatment	35. Plan Shape		36a	. Changes, addition (see 42) 36b. Ch	anges, altered (see
brick	rectangular			V	100
Changes, moved (see 42) 37a.	Condition, Inte	rior	37b. Cond	dition, Exterior 38. Preservation	on underway?
39a. Endangered 39b. Endange	red by what?		sible from p	ublic road?	
		V			
41. Distance from and frontage (on road				
42. Further Description of Impor					
				eparated by a fixed metal awing with	
brick pillers. The second story for is a frieze and cornice.	eatures a picture	e window to	ppea with s	even glass blocks. Above the window	5
43. History and Significance					4
This buliding served as a grocery	store from circ	a 1885 thre	ough circa 1	955. It held offices, then	
appliances. The fixed awning wa				·	
44. Description of Environment:	and Ciutbuildin	3			⊥
2 (1.00) - 1. (1.00) - 1. (1.00) - 1. (1.00) - 1. (1.00) - 1. (1.00) - 1. (1.00) - 1. (1.00) - 1. (1.00) - 1.	<u> </u>	and the second s			(Figure 1997)
	46. Prepared I	***************************************	A STATE OF THE PARTY OF THE PAR	Organization	
Sanborn Maps, K. McCue, City	Mary Aue Mit	chell	City	of Mexico	
	on Date(s)				
6/6/2002					



1. No. 2. County	3. Locatio			4. Current Name(s)
69 Audrain	MCRI			Ron's Barber Shop
5. Other Name(s)	6a. Township 6b	. Range	6c. Section	6d. Street Address
	T51N R9	w	26	113 South Jefferson
7. City or Town	7b, Vicinit 8. De	scription	of Location	9. UTM Coordinates
Mexico	N 20)' Lot 1,	Block 8	
10a. Site 10b. Building 10c. Str	ucture 10d. Obje	c 11. O	n National Re	egister? 12. Is it eligible? 13. Part of Historic District
	Ų			
14. District Potential? 15. Name	of District	16.	Thematic Cate	egory
✓				
17. Date(s) or Period	18. Style or Desig	n '	19. Ar	rchitect or Engineer
1886				
20. Contractor or Bullder	21. Original Use		22. Pro	esent Use
	commercial		comme	ercial
23. Ownership	24. Owner's Nan	ne and A	ddress	25. Open to Public
private	Iva May Pilcher N	1cDonald	, 504 N. Bea	nch Ave, Bay St. Louis, MS
26. Local Contact Person or Org	anization		27. Ott	her Surveys in Which Included
Lura Williams			n/a	
28. No. of Storie 29. Basement	30. Foundation 1	Material .	31. W	Vall Construction
2	brick		brick	
Roof Type and Material	33a. No. of Bays,	front	33b. N	No. of bays, side
flat/asphalt	3			
34. Wall Treatment	35, Flan Shape		36a. C	Changes, addition (see 42) 36b. Changes, altered (see 42)
brick	rectangular			
Changes, moved (see 42) 37a.	Condition, Interior		37b. Conditi	ion, Exterior 38. Preservation underway?
39a. Endangered 39b. Endange	red by what?	40. Vis	ble from publ	lic road?
		Y		
41. Distance from and frontage of	n road			
	-			
42. Further Description of Impor	tant Features	A PARTIES		AND THE RESIDENCE OF THE SECOND
two recessed single door entries v				
•	e decorative pilaste	ers on eac	th end. A cor	rnice with dentals separtes the first
and second stories. (cont.) 43. History and Significance				
	885, 1890, 189	4. cigar f	actory, 1899	9, jewlery store. By 1908 it was a
barber shop and still is one. In 1				Circa 1970, it was a siding store as
well. (cont.)		- 300000 ACC 200	Company	
44. Description of Environment a	ind Cutbuildings			
ANNO ANNO ANNO ANNO ANNO ANNO ANNO ANNO		A	**************************************	
	46. Prepared by			rganization
Sanborn Maps, G. Craddock, Ci	Mary Aue Mitche	ell	City of	f Mexico
48. Date 49. Revisio	on Date(s)			
6/5/2002			13.00	不是一个事一人。在 San Table

#69

113 South Jefferson

- 42. The second story features three boarded over windows with lugs sills and surrounds and wooden shutters on the upper half of the windows. A brick panel runs between them and the corbelling at the roofline.
- 43. This building has house barber shops by various operators for approximately 95 years.



4 24-	TIO OF SE			
1. No. 86	2. County Audrain	3. Location of Neg	datives 4. Current Name(s) Innovative technology	
5. Other			6c. Section 6d. Street Address	
2. Calel	rame(a)	T51N R9W	26 114 South Jefferson	
7. City or	Town	7b. Vicinit 8. Description		
Mexico		N 20' of Lot		
Some allowed with the second columns and	10b. Building 10c.		On National Register? 12. Is it eligible? 13. Part of Historic I	District
The second secon				
14. Distric	ct Potential? 15. N	ame of District 16.	Thematic Category	
✓				
17. Date(s) or Period	18. Style or Design	19. Architect or Engineer	
circa 188	5			
20. Contr	actor or Bullder	21. Original Use	22. Present Use	
		commercial	commercial	
23. Owne	ership	24. Owner's Name and A	ddress 25. Open to Pub	lc
private		Unison LLC, 11200 Audi	rain Rd 9907, Mexico MO 65265	
26. Local	Contact Person or	Organization	27. Other Surveys in Which Included	
Lura Willia	ams		n/a	
28. No. o	f Storle 29. Basem	ent 30. Foundation Material	31. Wall Construction	
2		brick	brick	
Roof Type	and Material	33a. No. of Bays, front	33b. No. of bays, side	
flat/asphal	lt	2		
34. Wall 7	reatment	35. I'lan Shape	36a. Changes, addition (see 42) 36b. Changes, alter	ed (see
brick		rectangular		
Changes, r	moved (see 42) 3	7a. Condition, Interior	37b. Condition, Exterior 38. Preservation underwa	y?
		essegar a playabla histolica med a papa a papa a mandanistan intellic a papapapanis disperance and sesses and ses		18
39a. Enda	ingered 39b. Enda		ible from public road?	
		<u> </u>		
41. Distan	ice from and fronta	ge on road		
	minella al Rossono S. C. C. C. C. C. C. C. C.	TRANSFER E. N. NEW MARK TO THE COMMITTEE OF THE COMMITTEE		
	er Description of In		N. W. San	
single side	entry and picture v	window. Fixed metal awning w o 1/1 double hung windows wi	rith pillars separates the first and second stories. ith lug sills. The roofline has a shed awning with	
	Awning added in 1			
The second second second second second	y and Significance			
		1899,1908,1914, millinery	shop. 1929, furniture store. 1935, dress shop.	
After that	it held offices.		A second	
44. Descri	iption of Environme	ent and Coutbuildings		
AS CAUSA	es of Information	46. Prepared by	47. Organization	
		ity Mary Aue Mitchell	City of Mexico	10.4
48. Date		vision Date(s)		
to. west	2	12.7.1 21 22 23		



Audrain MCRI Mechlin Furniture (2)	
Other Name(s) 6a. Township 6b. Range 6c. Section 6d. Street Address	
T51N R9W 26 115 South Jefferson	
City or Town 7b. Vicinit 8. Description of Location 9. UTM Coordinates	s
exico S 25' of N 45' of Lot 1 & E 20 Lot 2, Block 8	
la. Site 10b. Building 10c. Structure 10d. Objec 11. On National Register? 12. Is it eligible?	13. Part of Historic Distri
District Potential? 15. Name of District 16. Thematic Category	
Date(s) or Period 18. Style or Design 19. Architect or Engineer	
ca 1885	
. Contractor or Builder 21. Original Use 22. Present Use	
commercial commercial	
. Ownership 24. Owner's Name and Address	25. Open to Public
ivate Richard and Peggy Mechlin, 117 S. Jefferson, Mexico MO 65265	The second secon
. Local Contact Person or Organization 27. Other Surveys in Which Inclu	ded
ra Williams n/a	
. No. of Storle 29. Basement 30. Foundation Material 31. Wall Construction	
brick brick	
of Type and Material 33a. No. of Bays, front 33b. No. of bays, side	
t/asphalt 2	
. Wall Treatment 35. Plan Shape 36a. Changes, addition (see 42)	36b. Changes, altered (
one and painted brick rectangular	
	reservation underway?
angery more (see 12) 374. Considerly metro. 375.	reservation underways.
a. Endangered 39b. Endangered by what? 40. Visible from public road?	
A citaligated 570 and alignment 100 value in the pathological	
Distance from and frontage on road	
, Distance from the none of the local	
. Further Description of Important Features	
essed entry with two stone romanesque arches with a central support colume. The second story	features
ress 6/6/6 triple hung windows (top portion boarded over) with lug sills and surrounds. The roof	
ntures dentals and brackets.	
. History and Significance	
the earliest maps - 1885, 1890 - show a piano, organ and sewing machine shop. By 1894 it was a	
d remained on until circa 1960. Then it held law offices until circa 1990. In the mid 1990's it riture store.	decame a
. Description of Environment and Clutbuildings	
. Sources of Information 46. Prepared by 47. Organization nborn Maps, G. Craddock, Ci Mary Aue Mitchell City of Mexico	
Date 49. Revision Date(s) 5/2002	
2/40/4	



1. No.	2. County	3. Loc	ation of Ne	gatives	4. Current Name(s)	
87	Audrain	MCRI			116, 118 S. Jefferson	
5. Other N	ime(s)	6a. Township	6b. Range	6c. Sect	ion 6d. Street Address	
Morris Build	ling	T51N	R9W	26	116, 118 S. Jefferson	
7. City or T	own	7b. Vicinit 8.	Description	n of Locat	lon 9. UTM Coordinates	
Mexico		□ N	41' of Lot	4, Block	9	
10a. Site 1	Ob. Building 10c. Str	ucture 10d. O	bjec 11. C	On Nation	al Register? 12. Is it eligible? 13. Part of His	toric District
			П			
14. District	Potential? 15. Name	of District	16.	Thematic	: Category	
✓						
17. Date(s)	or Period	18. Style or D	esign	11	7. Architect or Engineer	
circa 1885						
20. Contrac	tor or Builder	21. Original U	se	2:	2. Present Use	
		commerical		va	icant	
23. Owners	hip	24. ()wner's 1	lame and A	\ddress	25. Open t	o Public
private		Unison LLC, 1	1200 Aud	rain Rd 9	907, Mexico MO 65265	
26. Local C	ontact Person or Org	anization		27	Other Surveys in Which Included	
Lura Willian	ns			n/a	3	
28. No. of :	Storie 29. Basement	30. Foundation	n Material	3	1. Wall Construction	
2	Ш	brick		b	rick	
Roof Type a	nd Material	33a. No. of B	ys, front	3:	Sb. No. of bays, side	
flat/asphalt		3				
34. Wall Tn	atment	35, Plan Shapi		30	5a. Changes, addition (see 42) 36b. Changes	, altered (see 42
brick		rectangular				
Changes, mo	wed (see 42) 37a.	Condition, Inte	rior	37b. Co	ndition, Exterior 38. Preservation uni	derway?
		•				
39a. Endanı	ered 39b. Endange	red by what?	40. VI	sible from	public road?	Taring and the
			~			100
41. Distance	from and frontage o	on road				
42. Further	Description of Impor	tant Features				All the state of
-				_	with brick pillars separates the first and	
	•		ral 1/1 dou	uble hung	window with another pair of 1/1 double	
	ws on each side. (cor and Significance	111.)	2000		MILES TO THE STATE OF THE STATE	and the second
		been a meat s	op from ci	rca 1885	through 1920. 118 S. Jefferson was:	
					ocery, 1908, plumbing, and 1914	
millinery. ((40) 1 (40) (40)	2007 2 117 (43.2.1	and a work of the second and a second assets a second assets as	
44. Descript	ion of Environment a	ind Cutbuilding	5			ilie iya Tarah
45. Sources	of Information	46. Prepared I	y	47	/. Organization	
Sanborn Ma	ps, K. McCue, City	Mary Aue Mit	cheli	C	ty of Mexico	
48. Date	49. Revision	on Date(s)		•		
6/6/2002						

#87

116, 118 South Jefferson

- 42. A continuous sill runs beneath them. Above the central windows is the word "Morris" and a cornice runs above that. The fixed awning was added 1978.
- 43. 1929, 116 S. Jefferson was a millinery shop and 118 S. Jefferson was a barber. 1935, 116 S. Jefferson was occupied by Hagan's Clothing and 118 S. Jefferson was a Radio Company.



1. No. 2. County	3. Location of Ne	273 J. W.
67 Audrain	MCRI	Mechlin Furniture
S. Other Name(s)		6c. Section 6d. Street Address
نائيت شينان د الرئيس المن المن ميان شين المن المن المن المن المن المن المن الم	T51N R9W	26 117, 117A South Jefferson
. City or Town	7b. Vicinit 8. Description	
M exico	S 25' of N 7	O' Lot 1 & S 25' Lot 2, Block 8
Oa. Site 10b. Building 10	c. Structure 10d. Objec 11. C	On National Register? 12. Is it eligible? 13. Part of Historic District
4. District Potential? 15.	Name of District 16.	Thematic Category
1		
7. Date(s) or Period	18. Style or Design	19. Architect or Engineer
irca 1885		
O. Contractor or Builder	21. Original Use	22. Present Use
	commercial	commercial
3. Ownership	24. Owner's Name and A	Address 25. Open to Public
rivate		in, 117 S. Jefferson Mexico MO 65265 ✓
6. Local Contact Person o	r Organization	27. Other Surveys in Which Included
ura Williams		n/a
8. No. of Storle 29. Race	ment 30. Foundation Material	31. Wall Construction
	brick	brick
oof Type and Material	33a. No. of Bays, front	33b. No. of bays, side
at/asphalt	4	1
4. Wall Treatment	35. Plan Shape	36a. Changes, addition (see 42) 36b. Changes, altered (see 42)
ainted brick	rectangular	Sour Crienges, auditority (CC TA) SOUR Crienges, ditte (1985 TA)
hanges, moved (see 42)		37b. Condition, Exterior 38. Preservation underway?
nanges, moved (see 42)	57a. Condition, Interior	37b. Condition, Exterior 38. Preservation underway?
<u> </u>		
9a. Endangered 39b. End	sangered by what? 40. Vis	sible from public road?
<u>, </u>	- 	
1. Distance from and from	tage on road	
2. Further Description of I		
		copped by a boarded up transom. The second and surrounds. The roofline features dentals and
rackets.	The hang timeons were tag sins	and sarrounds. The roomine reduces deptate and
3. History and Significance		
		confectionary shop. 1899, millinery and dry
oods. 1908, billiard parlo ecame a furniture store cir		rd parlor from circa 1925 through 1960. It
4. Description of Environn	сто неродить при при стория и прода Вене при при при при на при держите на при при при при при при при при при	
T. PESCIPERON OF ENVIROND	TOTAL CHEVEROLUBY	
	kalaninin sering gantik siylesilli ka, salan helikak si siyasilik yaki ahili k, shammadilin e salan hili kala Kan North	
5. Sources of Information		47. Organization
anborn Maps, G. Craddoo	The state of the s	City of Mexico
	tevision Date(s)	
/5/2002		



1. No. 2. County	3. Location of	Negatives 4. Current Name(s)
88 Audrain	MCRI	Century 21
5. Other Name(s)	6a. Township 6b. Ran	ge 6c. Section 6d. Street Address
Jefferson Hotel	T51N R9W	26 120 South Jefferson
7. City or Town	7b. Vicinit 8. Descript	
Mexico	S 52.5' Lo	ot 3 & S 32' Lot 4, B
10a. Site 10b. Building 10c. St	ructure 10d. Objec 11	. On National Register? 12. Is it eligible? 13. Part of Historic District
	· # 나 보	
14. District Potential? 15. Name	e of District	16. Thematic Category
✓		
17. Date(s) or Period	18. Style or Design	19. Architect or Engineer
circa 1885	V. V	
20. Contractor or Builder	21, Original Use	22. Present Use
	commercial	commercial
23. Ownership	24. Owner's Name and	
private	Unison LLC, 11200 A	Audrain Rd 9907, Mexico MO 65265
26. Local Contact Person or Org	zanization <u> </u>	27. Other Surveys in Which Included
Lura Williams		n/a
28. No. of Storle 29. Basement	30. Foundation Mater	tal 31. Wall Construction
2	brick:	brick
Roof Type and Material	33a. No. of Bays, from	t 33b. No. of bays, side
flat/asphalt	3	5
34. Wall Treatment	35. Plan Shape	36a. Changes, addition (see 42) 36b. Changes, altered (see 42)
brick	rectangular	
Changes, moved (see 42) 37a.	Condition, Interior	37b. Condition, Exterior 38. Preservation underway?
39a. Endangered 39b. Endange		Visible from public road?
	Y	
41. Distance from and frontage	on road	
42. Further Description of Impo		
		on to the side of the building. A fixed metal awing
with brick pillar separtates the fir second story features (cont.)	st and second stories and	d continues around the corner of the building. The
43. History and Significance		
A Lodge Hall occupied the third		through circa 1920. 1885,1890, dry good and
· ·	-	P9, clothing and vacant. 1908, lunch counter,
confectionary and business college 44. Description of Environment	Anna Caracana and	
Table provides a characteristic of the control of t	ano O depondungo	
A STATE OF THE STA	distribution of the state of th	
45. Sources of Information	46. Prepared by	47. Organization
Sanborn Maps, K. McCue, City	Mary Aue Mitchell	City of Mexico
	on Date(s)	
6/6/2002		TEXTS 40 279 582 2 型度研究量1 36 A

#88

120 South Jefferson

- 42. four boarded over slightly arched windows with slip sills and hoodmolds. The third story has four arched windows with slip sills and hoodmolds. Above the windows are pilasters and brick corbelled dentals at the roofline. The side of the features the same elements except no hoodmolds. The windows behind the boards are still intact. The fixed mental awning with brick pillars was added in 1978. The current owner is willing to remove it.
- 43. 1914, News stand and confectionary shop. Circa 1925 it became the Jefferson Hotel and café. By 1970 it was vacant and since then has held offices.



AU-AS-001-043

1. No.	. No. 2. County 3. Location of Negativ			/es	4. C	urrent M	Name(s	3)]				
66	Audrair)	MCRI			Modern Loan, Amercian Famil			•				
5. Other	Name(s)		6a. To	wnsh	6b. R	ang	6c. S	ectio (5d. S1	treet Ad	dress		<u>L</u>
			T51N		R9W		26	1	119 ,	121 Sou	th Jeff	erson	
7. City or	Town	-	7b. V	cini 8.	Descr	iptio	n of I	ocatio	n	9. UTM (Coordi	nates	
Mexico				S 4	14' LO	ts 18	& 2, BI	ock 8				18.4	
10a. Sit	10b. Build	in 10c. Str	uctu	10d. Ot	oiec	11. O	n Nati	ional R	eaist	12. IS	it eliali	ol 13. Part of	Historic Distr
$\overline{}$	✓	ليا											
14. Distri	ct Potenti	15. Name	of Dis	trict		16.	Them	atic Ca	teao	rv			
						1				. ,			
17 Date(s) or Perio	d	18 Stv	le or D	esian	!		19 Ar	hite	ct or En	alneer	,	1
circa 188			ن حصم	ate inf				10. 74	Silico	CC OI LII	giricci		.
	ractor or B	uilder		ginal U				22. Pre	cont	t lico			1
Zu. Conta	actor or b	under		ercial	36			comm					ļ.
07.00				mer's N	lama	and	8 el el e			<u> </u>		OF One	m to Dubl
23. Owner	rsnip						-		orco	n, Mexic	10 MO		n to Publ
<u> </u>			L		193, 11	10, 12				-			I .
	Contact P	erson or o	organi	zation	_				er Su	irveys ir	n Whici	n Included	·
Lura Will								n/a					•
	f Stori 29.	Baseme		undati	on M	ateria	al			nstruct	ion		k
2	<u> </u>		brick					brick					•
	e and Mat	erial	33a. N	o. of Ba	ays, fr	ont		33b. N	o. of	bays, si	de		ļ
flat/asph	nalt		6				3						
	reatment		35. Plan Shape					nges, altered (see					
wood sid	ding and b	rick	rectar	ngular								✓	
Changes,	, moved (s	ee 37a.	Condit	ion, Int	erior		37b.	Condit	ion, I	Exterior	· 38	3. Preservatio	on underw
												i	
39a. Enda	angere 39	o. Endang	ered lo	y what	? 40	. Visi	ble fr	om pu	blic r	road?			
					¥								
41. Distai	nce from a	nd fronta	ge or	road								-	
			-										
42. Furth	ner Descrip	tion of in	nportal	nt Feat	ures								
	corner e												'
	ure windo									ated by	anorti	ner single	
	try. The fi		ascade	in cov	erea	With	verti	cai (cor	1t.)				1
	ry and Sig		WC 2 12	ost off	ice c	onfo	ction	any cho	n ar	nd shoe	c and h	oots. 1890,	}
post office and confectionary shop. 1894, millinery and jewelry. 1899, millinery and books. 1908, restaurant and saloon on first floor and (cont.)													
44. Description of Environment and Outbuildings													
		_											
45 Sour	ces of Info	rmation	46 Dr	epared	by			47. Or	ganiz	ration	<u>.</u>		
	Maps, G. (City o					l
48. Date		49. Revis	<u> </u>					1					
3/18/200		-10. KCVI3		<u>~~:_</u>]									
10/200		1											

#66

119 and 121 South Jefferson

- 42. wood siding. The second story features seven 1/1 double hung windows that partially fill in the original arched openings. There was a major fire in the building in 1991. The alterations took place after the fire.
- 43. bowling and billiards on the second floor. In 1904 maps show it was vacant. By circa 1925 it held a jewelry and gift shop with a lodge on the second floor. 1935, restaurant and shoe store. From circa 1950-1990 it had clothing stores, a photo studio, a television repair shop, and a print shop.

•





1. No. 2. 0	County	3. Location of Negative	es 4. Current Name	∋(s)	
18 Au	drain	MCRI	Robinson Heatir	ng & Air Conditi	
5. Other Name	(s) 6a.1	ownship 6b. Rang 6c. Se	ectio 6d. Street Addres	s	
	T51N		107 East Monroe		1
7. City or Town	7b.\	icinit 8. Description of Lo	cation 9, UTM Coor	dinates	
Mexico		W 42.4' of Lot 3, Blo			
10a. Site 10b. B	ulldin 10c Structur	10d. Obje 11. On Nati		nible 13 Part of H	listoric District
100.316 100.0	Gildir Toc. orderal	TOO, COJE 11. OITHOR	Orial Register (2.18 if elig	giore 10.1 di 1011	istoric Danier
14 District Bate	ntial 15. Name of D	istrict to Thema	ello Catogoni	-	
74. DISHIGI FOIE	mai is name or o	BILLE 10. METIC	tic Category		
[17 Dist. (3 sep	110.0		10.4.4.4.3.5.5.		
17. Date(s) or P	GIOG 10. c	yle or Design	19. Architect or Engine	Э	
				i i	
20. Contractor			22. Present Use		34
si. Jiga ya 1997 Jawa mata mara		mercial	commercial	-7.2	
23. Ownership		wner's Name and Addre			to Publi
private		E. & Kristine Robinson, 107			
	act Person or Organ	zation 2	27, Other Surveys in Whi	ch Included	
Lura Williams			n/a		
28. No. of Storle	s 29. Basemen 30.	oundation Material	31. Wall Construction		
2	bric	<	brick		
Roof Type and	Material 33a.	No. of Bays, front	33b. No. of bays, side		
flat/asphalt	3			}	
34. Wall Treatm	ent 35. Pi	an Shape	36a. Changes, addittor	n (see 36b. Chan	ges, affered (see
brick	recto	angular		ing U	100
Changes, move	ed (see 37a. Cond	ition, Interior 37b. (Condition, Exterior	38. Preservation	underwa
					1
39a. Endangere	e 39b. Endangerec	by what? 40. Visible fro	m public road?		
		V			
41 Distance fro	. I om and frontage on	rood	All Sections		
42 Further Desc	cription of Important	Features			
		lass display windows. A b	orick panel separates th	ne two stories	
The second sto	ry features 1/1 doub	ole hung windows with bri			
A	Control Contro	belling near the roofline.	00000000000000000000000000000000000000	aan aan aan aan aan aan aan aan aan aan	
43. History and					
		agricultural implement sto			
	rniture store, 1914, i vas Austin's Bowling	926 shows a bracket and Alley. (cont.)	a FIORIOTE STOLE. 1934 SNO	wan vacant.	
***************************************	of Environment and	The state of the s			
45. Sources of Ir			47. Organization		
	G. Craddock Mary	and the second second second second second second	City of Mexico		
48. Date	49. Revision Da	te(s			
2/27/2002					1000

#18

- 107 East Monroe
- 43. The Sherwin Williams Paint Store.
- 45. City Directories, Telephone Books



1. No. 2. County	3. Location of Ne	egatives 4. Current Name(s)	
19 Audrain	MCRI	Mexico Travel Agency	
5. Other Name(s)	6a, Township 6b, Rang	6c. Sectio 6d. Street Address	
	T51N R9W	26 111 East Monroe	
7. City or Town	7b. Vicinit 8. Description	of Location 9. UTM Coordinates	
Mexico	W 4' of Lot 2	& E 16' of Lot 3,	14
10a. Site 10b. Buildin 10c.	Structui 10d. Obje 11. O	n National Register 12. Is it eligible 13. Par	of Historic District
14. District Potential 15. Na	me of District 16.	Thematic Category	
		-	
17. Date(s) or Period	18, Style or Design	19. Architect or Engineer	
Circa 1880			
20. Contractor or Builder	21. Original Use	22. Present Use	
	commercial	commercial	
23. Ownership	24. ()wner's Name and	Address 25. (Open to Publi
private	Mexico Travel Agency,	111 East Monroe, PO Box 618, Mexico 🗹	
26. Local Confact Person o	r Organization	27. Other Surveys in Which Included	
Lura Williams		n/a	199
28. No. of Stories 29. Basem	en 30. Foundation Materia	al 31. Wall Construction	
1	concrete	brick	- 115
Roof Type and Material	33a, No. of Bays, front	33b. No. of bays, side	
shed asphalt shingel, flat, c			
34. Wall Treatment	35. Plan Shape	36a. Changes, addition (see 36b. C	hanges, altered (see
brick	rectangular		
Changes, moved (see 37	a. Condition, Interior	37b. Condition, Exterior 38. Preservo	ation underwa
	'		
39a. Endangere 39b. Enda	ngered by what? 40. Visi	ble from public road?	
	✓		
41. Distance from and from	tage on road		
42. Further Description of Im	nportant Features		
		6/6 double hung windows have brick linte	ls .
with key stones. The eves f	eature dentils. This building	g was extensively remodeled circa 1968.	
43. History and Significance			
700 00 00 00 00 00 00 00 00 00 00 00 00		ng. 1890, 1894, 1899, 1908, no change. 19	14
, shows a plumming store .		doctor's office. It remained a doctor's office	
until circa 1965.			
44. Description of Environm	ent and Outbuildings		
	Million of the computer of the contract of the		
45. Sources of Information	46. Prepared by	47. Organization	
Sanborn Maps, G. Craddo	ck Mary Aue Mitchell	City of Mexico	
	/ision Date(s		
2/27/2002			



1. No. 2. County	3. Location of Nega	atives 4. Current Name(s)
22 Audrain	MCRI	Dug Out
5. Other Name(s)	6a. Townshi 6b. Rang 6c	Sectio 6d. Street Address
Cline Furniture Warehouse	T51N R9W 26	112 East Monroe
7. City or Town	7b. Vicini 8. Description of	of Location 9. UTM Coordinates
Mexico	All of Lot 1, Blo	ock 12
10a. Sit 10b. Buildin 10c. Str	uctu 10d. Objec 11. On N	iational Regist 12. is it eligibl 13. Part of Historic Distr
y		
14. District Potenti 15. Name	of District 16. The	ematic Category
v		
17. Date(s) or Period	18. Style or Design	19. Architect or Engineer
circa 1910	To. Othe Of Design	15. Alchitect of Eligitical
20. Contractor or Builder	21. Original Use	22. Present Use
20. Contractor of Builder	armory	commercial
23. Ownership	24. Owner's Name and Ad	
private		Monroe, Mexico MO 65265 ✓
26. Local Contact Person or	Organization	27. Other Surveys in Which Included
Lura Williams		n/a
28. No. of Stori 29. Baseme	30. Foundation Material	31. Wall Construction
2	brick	brick
Roof Type and Material	33a. No. of Bays, front	33b. No. of bays, side
flat/asphalt	11	3
34. Wall Treatment	35. Plan Shape	36a. Changes, addition (see 36b. Changes, altered (see
brick	rectangular	<u> </u>
Changes, moved (see 37a.	Condition, Interior 37	b. Condition, Exterior 38. Preservation underw
39a. Endangere 39b. Endang	iered by what? 40. Visible	e from public road?
	Y	
41. Distance from and fronta	age on road	
41. Distance from and from	igo carroda	
42. Further Description of In	nnortant Eastures	
		d one other double entry. Two garage
doors and six large showro	om windows filled in and s	mailer windows inserted. Three
stationary windows were re	tained at the top of each	showroom window. (cont.)
43. History and Significance		
		plement warehouse and garage. In
1926 it is a auto garage and MO National Guard. In 1950	by 1934 it became the Arm	nory for Battery "B" of the 128th F.A.
44. Description of Environm		(COTIL.)
44. DESCRIPTION OF ENVIRONMENT	one and oddodinings	
45. Sources of Information	46. Prepared by	47. Organization
Sanborn Maps, G. Craddock	Mary Aue Mitchell	City of Mexico
48. Date 49. Revis	sion Date(•
3/1/2002		

#22

112 East Monroe

- 42. A belt course separates the first and second stories. The second story features eight arched 1/1 double hung windows and brick panels near the roofline. The windows were blocked circa 1980.
- .43. while the current the current courthouse was being built. Circa 1970 it became Cline Furniture Store and remained a furniture store until circa 1980. It then became a restaurant but is currently vacant (2002).



1. No.	2. County	3. Location of Negat	flves 4. Current Name(s)	
20	Audrain	MCRI	American Express, Hawkings Ins	
5. Other No	ame(s)	6a. Township 6b. Rang 6c.	Sectio 6d. Street Address	
Corporate	Resource Manag	T51N R9W 26	113 East Monroe	
7. City or To	nwc	7b. Vicinit 8, Description of	Location 9: UTM Coordinates	
Mexico		E 20' of W 24' of	Lot 2, Block 1	
		uctur 10d. Obje 11. On No	ational Register 12 is it eligible 13. Part of Historic District	
		L Un L		
14. District	Potential 15. Name	e of District 16. Ther	matic Category	
17. Date(s)		18. Style or Design	19. Architect or Engineer	
circa 1880		1 000 6 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0		
20. Contra	ctor or Builder	21. Original Use	22. Present Use	
		commercial	commercial	
23. Owners	hlp	24. Owner's Name and Add		
private			man, 1401 Stella St, Montgomery	
	ontact Person or C	Organization	27. Other Surveys in Which included	
Lura Williar			n/a	
28. No. of S	tories 29. Basemer	30. Foundation Material	31, Wall Construction brick	
Root Type flat/aspha	and Material	33a. No. of Bays, front	33b. No. of bays, side	
		I I	Section 1	
34. Wall Tre brick	arment	35. Flan Shape rectangular	36a. Changes, addition (see 36b. Changes, altered (<u>see </u>
	10-		Control 20 Part No.	
Changes, r	noved (see 37a.	Condition, Interior 37t	b. Condition, Exterior 38. Preservation underwa	
30a Endar	ngere 39b. Endang	Jerec bywhat? 10 Visible i	from public road?	
570. <u>D</u> 100	igere 070, criading	V	normpacific teach	
41 Distanc	e from and frontag	ne on road		
41. Digitality				
42 Further	Description of Imp	ortant Features		
façade rer	modled circa 1985	. Glass panels and a glass d	door cover the lower portion of the	
			lding. There are two rows of dentils	
cerem at a contract has represent a 200	y corbelling above	e the awning.		
	and Significance t man - 1885 - shov	vs it was an office building. I	It remained a office building (primarily	
		ca 1975 it became an insurc		
44. Descrip	tion of Environmen	it and Outbuildings		
<u> </u>				
	of Information	46. Prepared by	47. Organization	
Sanborn M		Mary Aue Mitchell	City of Mexico	
48. Date	49. Revision	on Date(s		
2/27/2002				
				ATTEMPTED TO



1. No.	2. County	3. Location	n of Negatives	4. Current Name(s)		
21	Audrain	MCRI		C & S Business Service	es ·	
5. Other No	ıme(s)	6a. Township 6b.	Rang 6c. Sectio	d. Street Address		
		T51N R9V	V 26	117 East Monroe		
7. City or To	wn	7b. Vicinit 8, Des	cription of Location	9. UTM Coordinat	es	
Mexico		E 36' c	of Lot 2, Block 18			100
10a. Site 10	b. Buildin 10c. S	tructur 10d. Obje	11. On National R	egister 12. Is it eligible	13. Part of Histor	ic District
		Ш				
14. District F	otential 15. Nan	ne of District	16. Thernatic Co	tegory		
~						
17. Date(s)	or Period	18. Style or Design	n 19. Ar	chitect or Engineer	7 (10)	
circa 1899						
20. Contrac	tor or Builder	21, Original Use	22, Pre	sent Use		44.
		commerical	comn	nercial		4
23. Owners	nlp	24. Owner's Name	e and Address		25 Open to	Publi
private				Montgomery City MO		
26. Local C	ontact Person or	Organization	27, Oth	er Surveys in Which Inc	cluded	
Lura Willian	**********************************		n/a			
28. No. of S	ories 29. Baseme	n 30. Foundation N	Material 31. W	all Construction		
2		brick	brick			
Roof Type o	nd Material	33ci. No. of Bays,	front 335.N	o. of bays, side		
flat/asphal		5				
l 34. Wall Tre		35. Plan Shape	36a C	hanges, addition (see	36b. Changes	altered (see
brick		rectangular		The first of the second		
L Chanaes n	noved (see 37a	Coridition, Interior	37b. Condit	on, Exterior 38. F	Preservation und	erwa
39a. Endan	gere 39b. Endan	gered by what?	40. Visible from pub	lic road?		
41. Distance	e from and fronto	age on road	3 (1) (1) (1) (1) (1) (1) (1) (1) (1) (1)			
					tain	
42. Further I	Description of Imp	oortant Features				
			1/1 double hung w	indows on each side h	nave	
		·		and style of windows o	as well as	
		above and corbelle	ea dentiis.			140
	ind Significance		n office building. T	ne maps show it as an	office	
				it became an investor		
building.		COLUMN STATE OF THE STATE OF TH				
44. Descript	ion of Environme	nt and Outbuilding	S			
<u> </u>						
45, Sources	of Information	46. Prepared by	47. On	ganization		
		k Mary Aue Mitche		Mexico		
48. Date	49. Revis	sion Cate(s				
2/28/2002						



1. No. 2. County	3. Location of N	egatives 4. Current Name(s)	
15 Audrain	MCRI	101 West Monroe	
5. Other Name(s)	6a. Township 6b. Rang	6c. Sectio 6d. Street Address	
	T51N R9W	26 101 West Monroe	
7. City or Town	7b. Vicinit 8. Descriptio	on of Location 9. UTM Coordinates	
Mexico	23.4' of Lot	1, Block 17	
10a, Site 10b, Buildin 10c	Structur 10d. Obje 11. C	On National Register 12. is it eligible 13. Part	of Historic District
	i Le l		100 mg (100 mg)
4. District Potential 15. No	ame of District 16.	Thematic Category	
7. Date(s) or Period	18. Style or Design	19. Architect or Engineer	
circa 1880			
0. Contractor or Builder	21. Original Use	22. Present Use	
W	commercial	vacant	
23. Ownership	24. Owner's Name and	Address 25. C	pen to Publi
orivate		1. Brett, 11961 Audrain Road 901, Mexi	
6. Local Contact Person	or Organization	27. Other Surveys in Which Included	
ura Williams		n/a	
8. No. of Stories 29. Basen	nen 30. Foundation Materi	al 31. Wall Construction	
	brick	brick	
loof Type and Material	33a. No. of Bays, front	33b. No. of bays, side	74
lat/asphalt	3	3 first floor, 10 second floor	
4. Wall Treatment	35. Plan Shape	36a. Changes, addition (see 36b. C	hanges, altered (see
painted brick	rectangular		
Changes, moved (see 3)	7a. Condition, Interior	37b, Condition, Exterior 38. Preservo	ion underwa
19a, Endangere 39b. Endo	angered by what? 40. Vis	sible from public road?	
Joseph Jo	<u> </u>	a sa ang a sa Sangangangan ay ang ang ang ang	
Distance from and from	ntage on road		
	,		
2. Further Description of Ir	mportant Features		
ecessed entry flanked by	display windows and cove	ered with wood shingle awning. Second sto	У
-	windows with brick lintels a	and a brick panel above earch window.	
Corbelling at the roofline. I3: History and Significanc	6		
		irness shop. From 1890 to 1899 it was a dry	
		nd 1914 show it to be a clothing store. In the	
	and Radio Shop. (cont.)		
Description of Environn	nent and Outbuildings		
15. Sources of Information	46. Prepared by	47. Organization	
Sanborn MapsG. Craddoo	ck Mary Aue Mitchell	City of Mexico	
18. Date 49. Re	vision Date(s		
2/27/2002			
			The state of the s

#15

101 West Monroe

- 43. In the early 1930's it was the home of Hollywood Dress Shop. In 1935 Zims Rexall Drugs moved from next door to this building. In 1944 Howard Kizer bought the business which was known for its soda fountain and operated it until 1970 when he sold it to Robert Logan. Mr. Logan operated the business until circa 1985. In the fall of 2001 this was the home of the Sticky Wicket quilting and gift shop. This building is currently vacant (2002).
- 45. City Directories, "A Gathering of Our Days" by Leta Hodge.







1. No.	lo. 2. County			3. Location of Negatives					irrent Nar	ne(s)		
14	Audrain			MCRI					t, Erdel, V	e, & Tanz		
5. Other Name(s)			6a. Townshi		6b. Rang 6c. Se		ectio 6d. Street Add		reet Addr	ess		
			T51N		R9W			103 West Monroe				
7. City or Town 7b. Vicini 8. Description of Location 9. UTM Coordinates												
Mexico E 23.4 ' of W 36.6' Lot 1, Blo												
10a. Sit 10	b. Buildin	10c. Str	uctij 1	Od. Ol	ojec 11. (On Nat	ional R	egist	12. Is it e	eligibl	13. Part of 1	Historic Distr
											J	
14. District	Potenti	15. Name	of Dis	trict	16	. Them	atic Ca	tegor	ν			
✓									······································			
17. Date(s)	or Period		18. Style or Design				19. Architect or Engineer					
circa 1880			(A)									
20. Contractor or Builder			21. Original Use				22. Pr	22. Present Use				
20. 00110 0000, 01 201100			commercial				Icommercial					
23. Owners								25 Open	to Publ			
private			Brett and Erdel, 103 West Monroe, Mexico MO 65265									· · · · · · · · · ·
26. Local Contact Person or Organization 27. Other Surveys in Which included												
Lura Williams n/a												
28. No. of Stori 29. Baseme 30. Foundation Material 31. Wall Construction												
28. NO. OF SCOTT 29. Basefile			brick				brick					
Roof Type					33b. No. of bays, side							
flat/aspha	3 a. No. of Bays, front				33D. NO. Of Days, Side							
	35. Plan Shape				 36a. Changes, addition (see 36b. Changes, a					gos altored (see		
			rectangular				Soa. Changes, addition (see 38b. Chan				ges, altered (see	
					Condition, Exterior 38. Preservation				recentation	undeny		
Changes, moved (see 37a. C			Johandon, interior 37b.				So. Preservaci				i esei vatioi	I diluci w
39a. Endangere 39b. Endangered by what? 40. Visible from public road?												
35a. Eliuaii	igere 39b.	Liluariy	CICCID	VVIIC	₩ 40. V	SIDIC II	OIII PU	DIC I	Jau:			
44 Dictano	o from an	d fronts	ae on i	heor								
41. Distance from and frontage on road												
42. Further Description of Important Features												
recessed entry flanked by double hung windows with shutters, siding and wood shingle												
awning. The second story features double hung windows with lintels. Brick panel between												
them and roof. Façade and first story remodled in 1984.												
43. History and Significance The earliest map - 1885 - show this building as a drug store and office. 1890 and 1894 show a												
drugstore and dentist office. From 1908 to 1932 shows a drug store. Zims Rexall Drug was in this building until 1935 when it rnoved next door. (cont.)												
44. Description of Environment and Outbuildings												
an en una retire production de Dunmanad hu												
45. Sources of Information Sanborn Maps, D. Erdel			46. Prepared by Mary Aue Mitchell				47. Organization City of Mexico					
			<u> </u>		CONCH		I CITY O	INCX	ico			
	48. Date 49. Revision Date											
2/27/2002												

#14.

103 West Monroe

43. In the 1960's it became Cook's Paint and varnish Store. In 1984 the law firm of Brett and Erdel move in and extensively remodeled the building.



1. No. 2. County	3, Location of Negat	tives 4. Current Name(s)	
13 Audrain	MCRI	The Grapevine	
5. Other Name(s)	6a. Township 6b. Rang 6c.	Sectio 6d. Street Address	
McPheeters Building	T51N R9W 26	105 West Monreo	
7. City or Town	7b. Vicinit 8. Description of	Location 9. UTM Coordinates	
Mexico	W 13.2' of Lot 1 8	% 11' of Lot 2,	
10a, Site 10b, Buildin 10c, St	tructur 10d, Obje 11. On No	ational Register 12. Is It eligible 13. Part of Historic District	
		✓	
14. District Potential 15. Nam	ne of District 16. Then	matic Category	4,95.60
✓			
17. Date(s) or Perlod	18. Style or Design	19. Architect or Engineer	
circa 1880			
20. Contractor or Builder	21. Original Use	22. Present Use	
	commercial	commercial	
23. Ownership	24. Owner's Name and Add		
private	Merle L. & Rebecca A. Cliffo	on, 22775 Audarin Road 812, Mexi 🗹	
26. Local Contact Person or	Organization	27. Other Surveys in Which Included	
Lura Williams		n/a	
28. No. of Storles 29. Baseme	n 30. Foundation Material	31. Wall Construction	
2	brick	brick	
Roof Type and Material	33a No. of Bays, front	336. No. of bays, side	
flat/asphalt	2		
34. Wall Treatment	35. Plan Shape	36a. Changes, addition (see 36b. Changes, altered (see)
brick	rectangular		
Changes, moved (see 37a.	Condition, Interior 37b	b, Condition, Exterior 38. Preservation underwa	
Ц	10 Mars 2000 M. (1880 Mars 200 Mars 20		
39a. Endangere 39b. Endan	gered by what? 40. Visible t	from public road?	
	V		
41. Distance from and fronto	ige on road		
42. Further Description of Imp			
•	•	hed awning, brick lintel with bracket on Iallian between second story windows	
	s the initials "MCP" for McPhee		
43. History and Significance			
The earliest map - 1885 - sho	ws it was a dry goods store. T	The maps indicate from 1890 to 1932 it	
was a clothing store. The Mo the 1950's it was a Western A		ing store as well as a funeral parlor. In	
44. Description of Environme	<u> 2004 - P. A. Alban, Abrahla B. S. Waller and Name and State, and Silver and State of the State</u>	THE RESERVE OF THE STATE OF THE	
		17 Occasional	
45. Sources of Information Sanborn Maps, G. Craddocl	46. Prepared by Mary Aue Mitchell	47. Organization City of Mexico	
	sion Cate(s	Total Control of the	
2/27/2002	MOLL POLEGE		1
12,27,2002			



1. No. 2. County	3. Location of Negative	s 4. Current Name(s)
12 Audrain	MCRI	Pizza Works
5. Other Name(s)	éa. Township 6b. Rang éc. Se	ctio 6d. Street Address
	T51N R9W 26	107 West Monroe
7. City or Town	7b. Vicinit 8. Description of Loc	cation 9. UTM Coordinates
Mexico	W 10' of E 1/2 of Lot	2, Block
10a. Site 10b. Bulldin 10c. S	Structur 10d. Obje 11. On Natio	nal Register 12. Is it eligible 13. Part of Historic District
14. District Potential 15. Nar	me of District 16 Thema	lic Category
	no or pomor	
17. Date(s) or Period	18. Style or Design	19. Architect or Engineer
circa 1990		
20. Contractor or Builder	21. Original Use	22. Present Use
		commercial
23. Ownership	24. Owner's Name and Addres	s 25, Open to Publi
private	Kenneth A. & Wendy Castagn	
26. Local Contact Person or	Organization 2	7. Offier Surveys in Which Included
Lura Williams		/a
28, No. of Stories 29. Baseme	en 30. Foundation Material	31. Wall Construction
1		brick
Roof Type and Material	33ci, No. of Bays, front	33b. No. of bays, side
flat/asphalt	4	
34. Wall Treatment	35. Plan Shape	36a. Changes, addition (see 36b. Changes, altered (see
painted brick	rectangular	
Changes, moved (see 370	a. Con dition, interior 376. C	condition, Exterior 38. Preservation underwa
39a. Endangere 39b, Endar	ngered by what? 40. Visible from	n public road?
41. Distance from and front	age on road	
42. Further Description of Im	portant Features	
recessed entry flanked by s	mall clisplay windows, metal shed	awning the length of the façade.
43. History and Significance		
		rned in the late 1980's. This building
was designed to blend in w		
44. Description of Environme	sot and Outhwildings	
Description of Environme	and a consulating	
45. Sources of Information		17. Organization
Sanborn Maps, G. Craddoc		City of Mexico
	ision Date(s	
2/27/2002	en e	



1. No. 2. County	3. Location of Ne	egatives 4. Current Name(s)	
11 Audrain	MCRI	Erdel & Wood Home Improvem	
5. Other Name(s)	6a. Township 6b. Rang	6c. Sectio 6d. Street Address	100
	T51N R9W	26 109 West Monroe	
7. City or Town	7b. Vicinit 8. Descriptio	n of Location 9. UTM Coordinates	
Mexico	N 20' of Lot 2	2, Block 17	
10a. Site 10b. Buildin 10c.	Structur 10d. Obje 11. O	On National Register 12. Is it eligible 13. Part of Historic	District
14. District Potential 15. Na	me of District 16.	Thematic Category	
✓			
17. Date(s) or Period	18. Style or Design	19. Architect or Engineer	
circa 1880			
20. Contractor or Builder	21. Original Use	22. Present Use	
	commerical	commercial	
23. Ownership	24. Owner's Name and	Address 25. Open to Pu	bli
private	Stanley Erdel, 109 West	Monroe, Mexico MO 65265 ✓	
26. Local Contact Person o	or Organization	27. Other Surveys in Which Included	
Lura Williams		n/a	
28. No. of Stories 29. Basem	en 30. Foundation Materio	al 31. Wall Construction	
2	brick	brick	
Roof Type and Material	33ci. No. of Bays, front	33b. No. of bays, side	
flat, asphalt	3		
34. Wall Treatment	35. Plan Shape	36a. Changes, addition (see 36b. Changes, a	tered (see
painted brick	rectangular		
Changes, moved (see 37	a. Condition, interior	37b. Condition, Exterior 38. Preservation under	wal
Janes Harris			
39a. Endangere 39b. Enda	ngered by what? 40. Visi	ible from public road?	
	✓	\$ \$ \$ \$ \$ \$ \ \\ \\ \\ \\ \\ \\ \\ \\ \\	
41. Distance from and from	tage on road		
			rwi V - maaaaaaa (1888
42. Further Description of Im	portant Features		
Recessed entry with wood	shingled awning. The faço	ade has been altered with vertical board	
Recessed entry with wood siding and aluminum windo	shingled awning. The factors circa 1982. A belt cou	ade has been altered with vertical board urse separates the first and second stories.	
Recessed entry with wood siding and aluminum wind The second story has board	shingled awning. The factows circa 1982. A belt cou ded over windows (cont.)	ade has been altered with vertical board urse separates the first and second stories.	
Recessed entry with wood siding and aluminum wind The second story has board 43. History and Significance	shingled awning. The factows circa 1982. A belt couded over windows (cont.)	ade has been altered with vertical board urse separates the first and second stories.	
Recessed entry with wood siding and aluminum wind The second story has board 43. History and Significance The earliest map - 1885 - st	shingled awning. The factors ows circa 1982. A belt couded over windows (cont.)	ade has been altered with vertical board urse separates the first and second stories.	
Recessed entry with wood siding and aluminum window The second story has board 43. History and Significance The earliest map - 1885 - st 1930. In 1935 it housed the until circa 1980.	shingled awning. The factows circa 1982. A belt couded over windows (cont.) nows it to be a furniture stoe offices of McPheeter Brott	ade has been altered with vertical board urse separates the first and second stories. The property of the pro	
Recessed entry with wood siding and aluminum window The second story has board 43. History and Significance The earliest map - 1885 - st 1930. In 1935 it housed the until circa 1980.	shingled awning. The factows circa 1982. A belt couded over windows (cont.) nows it to be a furniture stoe offices of McPheeter Brott	ade has been altered with vertical board urse separates the first and second stories. The property of the pro	
Recessed entry with wood siding and aluminum window The second story has board 43. History and Significance The earliest map - 1885 - st 1930. In 1935 it housed the until circa 1980.	shingled awning. The factows circa 1982. A belt couded over windows (cont.) nows it to be a furniture stoe offices of McPheeter Brott	ade has been altered with vertical board urse separates the first and second stories. The property of the pro	
Recessed entry with wood siding and aluminum window The second story has board 43. History and Significance The earliest map - 1885 - st 1930. In 1935 it housed the until circa 1980.	shingled awning. The factows circa 1982. A belt couded over windows (cont.) nows it to be a furniture stoe offices of McPheeter Brott	ade has been altered with vertical board urse separates the first and second stories. The property of the pro	
Recessed entry with wood siding and aluminum window the second story has board 43. History and Significance The earliest map - 1885 - st 1930. In 1935 it housed the until circa 1980. 44. Description of Environm	shingled awning. The factows circa 1982. A belt couded over windows (cont.) nows it to be a furniture stoe offices of McPheeter Brott	ade has been altered with vertical board urse separates the first and second stories. The property of the pro	
siding and aluminum windo The second story has board 43. History and Significance The earliest map - 1885 - st 1930. In 1935 it housed the	shingled awning. The factows circa 1982. A belt couded over windows (cont.) hows it to be a furniture storoffices of McPheeter Brottent and Outbuildings	ade has been altered with vertical board urse separates the first and second stories. The separates the first and second stories are. It remained a furniture store until circa thers Funeral Home. It was an office building	
Recessed entry with wood siding and aluminum winds. The second story has board 43. History and Significance. The earliest map - 1885 - st 1930. In 1935 it housed the until circa 1980. 44. Description of Environm. 45. Sources of Information. Sanborn Maps, D. Erdel	shingled awning. The factows circa 1982. A belt couded over windows (cont.) anows it to be a furniture stoworfices of McPheeter Brottent and Outbuildings	ade has been altered with vertical board urse separates the first and second stories. The separates the first and second stories. The separates the first and second stories. The separates the first and second stories.	

#11

109 West Monroe

42 which still exist underneath. Above these windows are two decorative brick panels.



1. No. 2. County	3. Loca	tion of Negative	s 4. Current Name(s)	
1. No. 2. County 10 Audrain	MCRI		Congoleum Design Stu	olio
5. Other Name(s)	6a. Township 6	b. Rana 6c. Se	ctio 6d. Street Address	
	THE RESERVE AND ADDRESS OF THE PARTY OF THE	79W 26	111 West Monroe	
7. City or Town	7b. Vicinit 8, E	Description of Loc	cation 9. UTM Coordinates	
Mexico		ntral 20' of Lot 2,		
10a. Site 10b. Buildin 10c. S	tructur 10d. Ob	je 11. On Natio	nal Register 12. Is it eligible 13	. Part of Historic District
14. District Potential 15. Nar	ne of District	16. Themat	ric Category	
✓				
17. Date(s) or Period	18. Style or De	sign 1	9. Architect or Engineer	
circa 1880				
20. Contractor or Builder	21. Original Usi	9 2	22. Present Use	
	commercial		commercial	
23. Ownership	24. Owners No	ame and Addres		25. Open to Publi
private	Stanley Erdel,	109 West Monro	e, Mexico MO 65265	
26. Local Contact Person o	Órganization	2	7. Other Surveys in Which Inclu	ded
Lura Williams		n	/a	
28. No. of Stories 29. Basema	en 30. Foundatio	n Material	31, Wall Construction	
2	brick		brick	and the second s
Roof Type and Material	33ci, No. of Ba	ys, front	13b. No. of bays, side	
flat/asphalt	2			
34. Wall Treatment	35. Plan Shape		66a. Changes, addition (see	lób. Changes, altered (see
painted brick	rectangular			
Changes, moved (see 370	a, Condition, Inte	rior 37b. C	ondition, Exterior 38. Pre	servation underwa
39a, Endangere 39b, Endar	ngered by what?		n public road?	
		V		
41. Distance from and front	age on road			
41. Distance from and front	age on road			
42. Further Description of Im	portaint Features			
42. Further Description of Im Recessed glass entry flanke	portant Features d by display wind	dows. A wood sh	ningle awning covers the length	
42. Further Description of Im Recessed glass entry flanke the façade. Second story fo	portaint Features d by display wind eatures three arc	dows. A wood st		
42. Further Description of Im Recessed glass entry flanke the façade. Second story for windows had surround linte	portaint Features d by display wind eatures three arc	dows. A wood st	ningle awning covers the length	
42. Further Description of Im Recessed glass entry flanke the façade. Second story for windows had surround linte 43. History and Significance The earliest map - 1885 - sho	portant Features d by display wind eatures three ard is and corbelled bws it was a dry g	dows. A wood stiched windows widentils (cont.)	ningle awning covers the length th lug sills. Historic photos revenues and shop. 1890 millinery. 1899	al the
42. Further Description of Im Recessed glass entry flanke the façade. Second story for windows had surround linte 43. History and Significance The earliest map - 1885 - sho clothing. 1894 no change.	portant Features d by display wind eatures three ard is and corbelled ows it was a dry g 1899 cothing.	dows. A wood stehed windows widentils (cont.)	ningle awning covers the length th lug sills. Historic photos reve	al the
42. Further Description of Im Recessed glass entry flanke the façade. Second story for windows had surround linte 43. History and Significance The earliest map - 1885 - sho clothing. 1894 no change. no change. It was Gooch	portant Features d by display wind eatures three arc Is and corbelled ows it was a dry of 1899 cothing. 19 Hardware until c	dows. A wood standard windows with dentils (cont.) goods and cothin 208 grocery. 1914 irca 1985.	ningle awning covers the length lug sills. Historic photos revenues shop. 1890 millinery. 1899 Ino change. 1926 hardware.	al the
42. Further Description of Im Recessed glass entry flanke the façade. Second story for windows had surround linte 43. History and Significance The earliest map - 1885 - sho clothing. 1894 no change.	portant Features d by display wind eatures three arc Is and corbelled ows it was a dry of 1899 cothing. 19 Hardware until c	dows. A wood standard windows with dentils (cont.) goods and cothin 208 grocery. 1914 irca 1985.	ningle awning covers the length lug sills. Historic photos revenues shop. 1890 millinery. 1899 Ino change. 1926 hardware.	1834
42. Further Description of Im Recessed glass entry flanke the façade. Second story for windows had surround linte 43. History and Significance The earliest map - 1885 - sho clothing. 1894 no change. no change. It was Gooch	portant Features d by display wind eatures three arc Is and corbelled ows it was a dry of 1899 cothing. 19 Hardware until c	dows. A wood standard windows with dentils (cont.) goods and cothin 208 grocery. 1914 irca 1985.	ningle awning covers the length lug sills. Historic photos revenues shop. 1890 millinery. 1899 Ino change. 1926 hardware.	1834
42. Further Description of Im Recessed glass entry flanke the façade. Second story for windows had surround linte 43. History and Significance The earliest map - 1885 - sho clothing. 1894 no change. no change. It was Gooch 44. Description of Environment	portant Features d by display wind eatures three arc is and corbelled ows it was a dry g 1899 cothing. 19 Hardware until c ent and Outbuild	dows. A wood sthed windows widentils (cont.) goods and cothin 208 grocery, 1912 irca 1985.	ningle awning covers the length lug sills. Historic photos revenues and shop. 1890 millinery. 1899. In o change. 1926 hardware.	1834
42. Further Description of Im Recessed glass entry flanke the façade. Second story for windows had surround linte 43. History and Significance The earliest map - 1885 - sho clothing. 1894 no change. no change. It was Gooch 44. Description of Environmental	portant Features d by display wind eatures three arc is and corbelled by sit was a dry g 1899 cothing. 19 Hardware until c ent and Outbuild	dows. A wood stined windows with dentils (cont.) goods and cothin 208 grocery, 1914 irca 1985. lings	ningle awning covers the length lug sills. Historic photos revening shop. 1890 millinery. 1899 in o change. 1926 hardware.	1834
42. Further Description of Im Recessed glass entry flanke the façade. Second story for windows had surround linte 43. History and Significance The earliest map - 1885 - sho clothing. 1894 no change. no change. It was Gooch 44. Description of Environme 45. Sources of Information Sanborn Maps, G. Craddoo	portant Features d by display wind eatures three ard is and corbelled ows it was a dry g 1899 cothing. 19 Hardware until c ent and Outbuild	dows. A wood stined windows with dentils (cont.) goods and cothin 208 grocery, 1914 irca 1985. lings	ningle awning covers the length lug sills. Historic photos revenues and shop. 1890 millinery. 1899. In o change. 1926 hardware.	1834
42. Further Description of Im Recessed glass entry flanke the façade. Second story for windows had surround linte 43. History and Significance The earliest map - 1885 - sho clothing. 1894 no change. no change. It was Gooch 44. Description of Environmental 45. Sources of Information Sanborn Maps, G. Craddoo	portant Features d by display wind eatures three arc is and corbelled by sit was a dry g 1899 cothing. 19 Hardware until c ent and Outbuild	dows. A wood stined windows with dentils (cont.) goods and cothin 208 grocery, 1914 irca 1985. lings	ningle awning covers the length lug sills. Historic photos revening shop. 1890 millinery. 1899 in o change. 1926 hardware.	1834

#10

- 111 West Monroe
- 43. which have been removed. The windows are also boarded over but still exist underneath.
- 44. "The Pictorial History of Mexico, 1880-1959" Ed, by Max Thompson.



1. No. 2. County	3. Location o	of Negatives	4. Current Name(s)	
09 Audrain	MCRI		Imagine Tanning Salon	
5. Other Name(s)	6a. Township 6b. Ro	ang 6c. Sec	tio 6d. Street Address	$oldsymbol{\perp}$
	T51N R9W	26	115 West Monroe	
7. City or Town	7b. Vicinit 8, Descri	ption of Loc	ation 9. UTM Coordinates	
Mexico	S 30' of L	.ot 2, Block 1	7	
10a. Site 10b. Buildin 10c.	Structur 10d. Obje 1	1. On Nation	nal Register 12. Is it eligible 13. Part	of Historic District
]		100
14. District Potential 15. No	ame of District	6. Themati	c Category	
✓				
17. Date(s) or Period	18. Style or Design	1	9. Architect or Engineer	
circa 1880	ital:anate			
20. Contractor or Builder	21. Original Use	2	2. Present Use	
	commercial	С	ommercial	
23. Ownership	24. Owner's Name (and Address	25. 0	Open to Publi
private	Lawrence M. Barne	s Jr., 4703 C	alumet Road, Richmond VA 2 🗹	
26. Local Contact Person o	or Organization	27	Other Surveys in Which Included	
Lura Williams		n/	'a	
28. No. of Stories 29. Basem	nen 30. Foundation Ma	terial 3	1. Wall Construction	
2	brick	k	orick	
Roof Type and Material	33c. No. of Bays, fro	ont 3	3b. No. of bays, side	
flat, asphalt	3			
34. Wall Treatment	35. Plan Shape	3	6a. Changes, addition (see 36b. C	hanges, altered (see
painted brick	rectangular			
Changes, moved (see 37	a, Condition, Interior	37b. C	ondition, Exterior 38, Preserva	flon underwa
39a. Endangere 39b. Enda	naered by what? 40	Visible from	public road?	
41. Distance from and fron	tage on road		1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1	
42. Further Description of In	nportant Features			
		flanked by	display windows A belt course	
separates the two stories.	The second story featu	ires three 4/4	double hung windows with shutter	rs,
lug sills, and decorative su	LINESCONO CONTROL DE CARROLPORTA, A LINES ANTON CONTROL DE CARROLPORTA DE CARROLPO	ones.		
43. History and Significance		emained a	dry goods store through the 1930's.	
In the 1950's it was a wome				
	estationes, terminalista de la constitución de la c	S		
44. Description of Environm	nent and Outbuildings			
45. Sources of Information	46. Prepared by	[4	7. Organization	
Sanborn Maps, G. Craddo	ck Mary Aue Mitchell	C	city of Mexico	
48. Date 49. Rev	vision Date(s			
2/26/2002				
	The state of the s			



Misso	ıri Historic/Archit	tectural Inventory Form
No. 2. County	3. Location of Nega	titives 4. Current Name(s)
08 Audrain	MCRI	Ann's Fashions
o, Other Name(s)		Sectio 6d: Street Address
	T51N R9W 26	
. City or Town	7b. Vicinit 8. Description of	Location 9, UTM Coordinates
Mexico	Lot 3, Block 17	
0a. Site 10b. Buildin	Oc. Structur 10d. Obje 11. On N	ational Register 12. is it eligible 13. Part of Historic D
4. District Potential 15	. Name of District 6. The	matic Category
<u>'</u>		
7. Date(s) or Period	18. Style or Design	19. Architect or Engineer
circa 1880	ital anate	
Contractor or Build		22. Present Use
1.55 (1.55 (1.55 (1.55 (1.55 (1.55 (1.55 (1.55 (1.55 (1.55 (1.55 (1.55 (1.55 (1.55 (1.55 (1.55 (1.55 (1.55 (1.55 (1.55 (1.55 (1.55 (1.55 (1.55 (1.55 (1.55 (1.55 (1.55 (1.55 (1.55 (1.55 (1.55 (1.55 (1.55 (1.55 (1.55 (1.55 (1.55 (1.55 (1.55 (1.55 (1.55 (1.55 (1.55 (1.55 (1.55 (1.55 (1.55 (1.55 (1.55 (1.55 (1.55 (1.55 (1.55 (1.55 (1.55 (1.55 (1.55 (1.55 (1.55 (1.55 (1.55 (1.55 (1.55 (1.55 (1.55 (1.55 (1.55 (1.55 (1.55 (1.55 (1.55 (1.55 (1.55 (1.55 (1.55 (1.55 (1.55 (1.55 (1.55 (1.55 (1.55 (1.55 (1.55 (1.55 (1.55 (1.55 (1.55 (1.55 (1.55 (1.55 (1.55 (1.55 (1.55 (1.55 (1.55 (1.55 (1.55 (1.55 (1.55 (1.55 (1.55 (1.55 (1.55 (1.55 (1.55 (1.55 (1.55 (1.55 (1.55 (1.55 (1.55 (1.55 (1.55 (1.55 (1.55 (1.55 (1.55 (1.55 (1.55 (1.55 (1.55 (1.55 (1.55 (1.55 (1.55 (1.55 (1.55 (1.55 (1.55 (1.55 (1.55 (1.55 (1.55 (1.55 (1.55 (1.55 (1.55 (1.55 (1.55 (1.55 (1.55 (1.55 (1.55 (1.55 (1.55 (1.55 (1.55 (1.55 (1.55 (1.55 (1.55 (1.55 (1.55 (1.55 (1.55 (1.55 (1.55 (1.55 (1.55 (1.55 (1.55 (1.55 (1.55 (1.55 (1.55 (1.55 (1.55 (1.55 (1.55 (1.55 (1.55 (1.55 (1.55 (1.55 (1.55 (1.55 (1.55 (1.55 (1.55 (1.55 (1.55 (1.55 (1.55 (1.55 (1.55 (1.55 (1.55 (1.55 (1.55 (1.55 (1.55 (1.55 (1.55 (1.55 (1.55 (1.55 (1.55 (1.55 (1.55 (1.55 (1.55 (1.55 (1.55 (1.55 (1.55 (1.55 (1.55 (1.55 (1.55 (1.55 (1.55 (1.55 (1.55 (1.55 (1.55 (1.55 (1.55 (1.55 (1.55 (1.55 (1.55 (1.55 (1.55 (1.55 (1.55 (1.55 (1.55 (1.55 (1.55 (1.55 (1.55 (1.55 (1.55 (1.55 (1.55 (1.55 (1.55 (1.55 (1.55 (1.55 (1.55 (1.55 (1.55 (1.55 (1.55 (1.55 (1.55 (1.55 (1.55 (1.55 (1.55 (1.55 (1.55 (1.55 (1.55 (1.55 (1.55 (1.55 (1.55 (1.55 (1.55 (1.55 (1.55 (1.55 (1.55 (1.55 (1.55 (1.55 (1.55 (1.55 (1.55 (1.55 (1.55 (1.55 (1.55 (1.55 (1.55 (1.55 (1.55 (1.55 (1.55 (1.55 (1.55 (1.55 (1.55 (1.55 (1.55 (1.55 (1.55 (1.55 (1.55 (1.55 (1.55 (1.55 (1.55 (1.55 (1.55 (1.55 (1.55 (1.55 (1.55 (1.55 (1.55 (1.55 (1.55 (1.55 (1.55 (1.55 (1.55 (1.55 (1.55 (1.55 (1.55 (1.55 (1.55 (1.55 (1.55 (1.55 (1.55 (1.55 (1.55 (1.55 (1.55 (1.55 (1.55 (1.55 (1.55 (1.55 (1.55 (1.55 (1.55 (1.55 (1.55 (1.55 (1.55 (1.55 (1.55 (1.55 (1.55 (1.55 (commercial	commercial
3. Ownership	24. Owner's Name and Add	
orivate		inio. i o bex co, mexico me doz, o
& Local Contact Pers Lura Williams	on or Organization	27. Other Surveys in Which Included
	semen 30. Foundation Material	31. Wall Construction
o V	brick	brick
oof Type and Materia		33b. No. of bays, side
lat, asphalt	4	
4. Wall Treatment	35, Plan Shape	36a. Changes, addition (see 36b. Changes, alte
painted brick	rectangular	
Changes, moved (see	37a. Condition, Interior 37	b. Condition, Exterior 38. Preservation underwo
9a. Endangere 39b. E	ndangered by what? 40. Visible	from public road?
	Y	
 Distance from and 	frontage on road	
2. Further Description		
	anked by clisplay windows. A bubb separates the first and second sto	ble awning covers the length of the
	arded windows. (cont.)	
History and Significant		A TANK MARKET HOLD HOLD STATE
•	·	. 1894 - taylor. 1899 - variety store. 1908 - 💮 🌼 🦠 staurant. The building was gutted in
1945. By 1950 it was a		stadiani. The ballaing was garred in
000	onment and Outbuildings	
5. Sources of Informat	ion 46. Prepared by	47. Organization
	ddock Mary Aue Mitchell	City of Mexico
aribori Maps, G. Cia	,	
	Revision Cate(s	

#8 117 West Monroe

- 42 The windows still exist under the boards. There are brick panels above each set of windows. Boxed cornice with dentils at roofline.
- 44. City Directories and Telephone Books



1. No. 2. County	3. Loc	ation of Ne	egatives .	4. Current Name(s)	
07 Audrain	MCRI			Mexico Sewing Center/Security	
5. Other Name(s)	6a. Township	6b. Rang	6c. Sectio	6d. Street Address	
Moore's Grocery	T51N	R9W	26	123 and 121 West Monroe	
7. City or Town	7b. Vicinit 8.	Descriptio	n of Locatio	on 9. UTM Coordinates	
Mexico	Lo Lo	t 4, Block	17		
10a. Site 10b. Buildin 10c. St	ructur 10d. Ol	oje 11. O	n National	Register 12. is it eligible 13. Part of	Historic District
	\perp \perp \perp			[[於《 日為身 [[[[日]]]]][[[[]]]	
14. District Potential 15. Nam	e of District	16.	Thematic C	Category	
✓				× > 1.00	
17. Date(s) or Period	18. Style or De	esign	19.4	vchitect or Engineer	
circa 1880	ital anate				
20. Contractor or Builder	21. Original U	se	22. P	resent Use	
	commercial		com	nmercial	
23. Ownership	24. Owner's N	lame and	Address	25. Ope	en to Publi
private	Larıdmark Inv	vestment C	Company	_	
26. Local Contact Person or 0	Organization		27. O	ther Surveys in Which Included	
Lura Williams			n/a		4.00
28. No. of Stories 29. Basemer	30. Foundation	on Materia	al 31.\	Wall Construction	
2	brick		bric	k	
Roof Type and Material	33ci. No. of Bo	ays, front	33b.	No. of bays, side	China :
flat, asphalt	5				
34. Wall Treatment	35. Plan Shap	Ю	36a.	Changes, addition (see 36b. Cha	nges, altered (see
brick	rectangular				
Changes, moved (see 37a.	Condition, Int	erior	37b. Conc	dition, Exterior 38. Preservation	n underwa
39a. Endangere 39b. Endang	gereid by what	? 40. Visi	ble from pu	ublic road?	
		Y			
41. Distance from and fronta	ge on road				
42. Further Description of Imp	ortant Feature	ıS.		engararri	
recessed entries flanked by o	louble pane d	isplay wind		d shingled awing runs the length	
	•		second sto	ry. The second story has fixed	
pane windows with flaired lin 43. History and Significance	reis and lug siii	is. (COHL)			
	vs this building	as a aroc	erv. The bu	uilding remained a grocery until	
the late 1960's. For approxim	ately 50 of the	se years it	was Moore	e's Grocery which was famous for	
Meng cheese named after N			owner	P.O. W. Let William and W. Commission and W. Com	
44. Description of Environmer	<u>nt and Outbuild</u>	dings			
45. Sources of Information	46. Prepared	by	47. C	Drganization	
Sanborn Maps, G. Craddock	Mary Aue Mit	tchell	- 4	of Mexico	
48. Date 49. Revisi	on Date(s		1		
2/26/2002					
1				THE PROPERTY OF THE PARTY OF TH	

#7

42 There is a decorative cornice near the roofline. This building had a basement that was filled in circa 1960.



AU AU COLOGIA

Audrain MCRI Pillows Outlet Store				
Mexico Ledger Building T51N R9W 26 201 West Monroe 7. City or Town 7b. Vicini 8. Description of Location 9. UTM Coordinates Mexico Lot1, N 28.7' of E3.25' of Lot 10a, Sit 10b. Buildin 10c. Structu 10d. Objec 11. On National Regist 12. Is it eligibl 13. Part of Historic District 15. Name of District 15. Name of District 16. Thematic Category 17. Date(s) or Period 18. Style or Design 19. Architect or Engineer 1876 1talianate influence 20. Contractor or Builder 21. Original Use 22. Present Use 25. Open to Public 16. Owner's Name and Address 25. Open to Public 16. Local Contact Person or Organization 27. Other Surveys in Which Included 16. Lura Williams 17.4 28. No. of Stori 29. Baseme 30. Foundation Material 31. Wall Construction 25. Plan Shape 36a. Changes, addition (see 36b. Changes, altered (see painted brick 17. Condition, Interior 37b. Condition, Exterior 38. Preservation underw				
7. City or Town 7b. Vicini 8. Description of Location 9. UTM Coordinates Mexico Lot1, N 28.7' of E3.25' of Lot 10a. Sit 10b. Buildin 10c. Structu 10d. Objec 11. On National Regist 12. Is it eligibl 13. Part of Historic District 15. Name of District 15. Name of District 15. Name of District 16. Thematic Category 17. Date(s) or Period 18. Style or Design 19. Architect or Engineer 1876 1talianate influence 20. Contractor or Builder 21. Original Use 22. Present Use 23. Ownership 24. Owner's Name and Address 25. Open to Public Dan Erdel, 103 West Monroe, Mexico Mo 65265 26. Local Contact Person or Organization 27. Other Surveys in Which included 17/2 28. No. of Stori 29. Baseme 30. Foundation Material 31. Wall Construction 27. Other Surveys In Which Included 16. Style or Design 19. Available 17. Style or Design 19. Available 19. Style or Design 19. Available 19. Style or Design 19. Available 19. Style or Design 19. Architect or Engineer 18. Style or Design 19. Architect or Engineer 18. Open 19. Architect or Engineer 19. Open 19. Open 19. Architect or Engineer 19. Open 19. Ope				
Mexico 10a, Sit 10b, Buildin 10c, Structu 10d, Objec 11, On National Regist 12, is it eligibl 13, Part of Historic Distr 14. District Potenti 15, Name of District 16, Thematic Category 17. Date(s) or Period 18, Style or Design 19, Architect or Engineer 1876 Italianate influence 20. Contractor or Builder 21, Original Use 22, Present Use commercial commercial 23. Ownership 24, Owner's Name and Address 25, Open to Public Private Dan Erdel, 103 West Monroe, Mexico MO 65265 26. Local Contact Person or Organization 27, Other Surveys in Which included Lura Williams n/a 28. No. of Stori 29, Baseme 30, Foundation Material 31, Wall Construction 20 brick brick Roof Type and Material 33a, No. of Bays, front 33b, No. of bays, side 161, asphalt 7 3 34. Wall Treatment 35, Plan Shape 36a, Changes, addition (see 36b, Changes, altered (see painted brick rectangular 37b, Condition, Exterior 38, Preservation underw				
10a. Sit 10b. Buildin 10c. Structu 10d. Objec 11. On National Regist 12. Is it eligibi 13. Part of Historic District 14. District Potenti 15. Name of District 16. Thematic Category 17. Date(s) or Period 18. Style or Design 19. Architect or Engineer 1876 Italianate influence 20. Contractor or Builder 21. Original Use 22. Present Use 25. Open to Public Private Dan Erdel, 103 West Monroe, Mexico MO 65265 26. Local Contact Person or Organization 27. Other Surveys in Which Included Lura Williams n/a 28. No. of Storl 29. Baseme 30. Foundation Material 31. Wali Construction 27. Other Surveys In Which Included 17. April Dirick 17. April Dirick 18. No. of Bays, front 18. No. of bays, side 18. Applied 18. Septimber 19. Septimber 18. Septimber 19. Septimber				
14. District Potenti 15. Name of District 16. Thematic Category 17. Date(s) or Period 18. Style or Design 19. Architect or Engineer 1876 Italianate influence 20. Contractor or Builder 21. Original Use 22. Present Use 23. Ownership 24. Owner's Name and Address 25. Open to Publiprivate Dan Erdel, 103 West Monroe, Mexico MO 65265 26. Local Contact Person or Organization 27. Other Surveys in Which included Lura Williams n/a 28. No. of Storl 29. Baseme 30. Foundation Material 31. Wall Construction 2. Williams 33a. No. of Bays, front 33b. No. of bays, side 16tt, asphalt 7 3 34. Wall Treatment 35. Plan Shape 36a. Changes, addition (see 36b. Changes, altered (see painted brick rectangular 37b. Condition, Exterior 38. Preservation underw				
14. District Potenti				
17. Date(s) or Period 18. Style or Design 19. Architect or Engineer 1876 20. Contractor or Builder 21. Original Use 22. Present Use 23. Ownership 24. Owner's Name and Address 25. Open to Publ 26. Local Contact Person or Organization 27. Other Surveys in Which Included 28. No. of Stori 29. Baseme 30. Foundation Material 31. Wall Construction 2 brick 20. Contact Person or Organization 31. Wall Construction 33b. No. of bays, side 34. Wall Treatment 35. Plan Shape 36a. Changes, addition (see 36b. Changes, altered (see painted brick rectangular 37b. Condition, Exterior 38. Preservation underw				
17. Date(s) or Period 18. Style or Design 19. Architect or Engineer 1876 1talianate influence 20. Contractor or Builder 21. Original Use 22. Present Use 23. Ownership 24. Owner's Name and Address 25. Open to Publ 26. Local Contact Person or Organization 27. Other Surveys in Which included 28. No. of Stori 29. Baseme 30. Foundation Material 31. Wall Construction 2 brick 20. Foundation Material 31. Wall Construction 33. No. of Bays, front 34. Wall Treatment 35. Plan Shape 36a. Changes, addition (see 36b. Changes, altered (see painted brick 37a. Condition, Interior 37b. Condition, Exterior 38. Preservation underw				
1876 Italianate influence 20. Contractor or Builder 21. Original Use 22. Present Use Commercial Commercial Commercial Commercial Commercial 23. Ownership 24. Owner's Name and Address 25. Open to Publ Open Erdel, 103 West Monroe, Mexico MO 65265				
20. Contractor or Builder 21. Original Use				
commercial commercial 23. Ownership 24. Owner's Name and Address 25. Open to Publ private Dan Erdel, 103 West Monroe, Mexico MO 65265 26. Local Contact Person or Organization 27. Other Surveys in Which Included Lura Williams n/a 28. No. of Stori 29. Baseme 30. Foundation Material 31. Wall Construction brick brick Roof Type and Material 33a. No. of Bays, front 33b. No. of bays, side flat, asphalt 7 3 34. Wall Treatment 35. Plan Shape 36a. Changes, addition (see 36b. Changes, altered (see painted brick rectangular Changes, moved (see 37a. Condition, Interior 37b. Condition, Exterior 38. Preservation underw				
23. Ownership 24. Owner's Name and Address 25. Open to Publiprivate Dan Erdel, 103 West Monroe, Mexico MO 65265 26. Local Contact Person or Organization 27. Other Surveys in Which Included Lura Williams n/a 28. No. of Stori 29. Baseme 30. Foundation Material 31. Wall Construction brick brick brick Roof Type and Material 33a. No. of Bays, front 33b. No. of bays, side flat, asphalt 7 3 34. Wall Treatment 35. Plan Shape 36a. Changes, addition (see 36b. Changes, altered (see painted brick rectangular 37b. Condition, Exterior 38. Preservation underw				
private Dan Erdel, 103 West Monroe, Mexico MO 65265 26. Local Contact Person or Organization 27. Other Surveys in Which included Lura Williams n/a 28. No. of Stori 29. Baseme 30. Foundation Material 31. Wall Construction 2 brick brick Roof Type and Material 33a. No. of Bays, front 33b. No. of bays, side flat, asphalt 7 3 34. Wall Treatment 35. Plan Shape 36a. Changes, addition (see 36b. Changes, altered (see painted brick rectangular Changes, moved (see 37a. Condition, interior 37b. Condition, Exterior 38. Preservation underw				
private Dan Erdel, 103 West Monroe, Mexico MO 65265 26. Local Contact Person or Organization 27. Other Surveys in Which included Lura Williams n/a 28. No. of Stori 29. Baseme 30. Foundation Material 31. Wall Construction 2 brick brick Roof Type and Material 33a. No. of Bays, front 33b. No. of bays, side flat, asphalt 7 3 34. Wall Treatment 35. Plan Shape 36a. Changes, addition (see 36b. Changes, altered (see painted brick rectangular Changes, moved (see 37a. Condition, interior 37b. Condition, Exterior 38. Preservation underw				
Lura Williams n/a 28. No. of Stori 29. Baseme 30. Foundation Material 31. Wall Construction 2				
Lura Williams n/a 28. No. of Stori 29. Baseme 30. Foundation Material 31. Wall Construction 2				
2 brick brick Roof Type and Material 33a. No. of Bays, front 33b. No. of bays, side flat, asphalt 7 3 34. Wall Treatment 35. Plan Shape 36a. Changes, addition (see 36b. Changes, altered (see painted brick rectangular Changes, moved (see 37a. Condition, interior 37b. Condition, Exterior 38. Preservation underw				
2 brick brick Roof Type and Material 33a. No. of Bays, front 33b. No. of bays, side flat, asphalt 7 3 34. Wall Treatment 35. Plan Shape 36a. Changes, addition (see 36b. Changes, altered (see painted brick rectangular Changes, moved (see 37a. Condition, interior 37b. Condition, Exterior 38. Preservation underw				
flat, asphalt 7 3 34. Wall Treatment 35. Plan Shape 36a. Changes, addition (see 36b. Changes, altered (see painted brick rectangular Changes, moved (see 37a. Condition, interior 37b. Condition, Exterior 38. Preservation underw				
flat, asphalt 7 3 34. Wall Treatment 35. Plan Shape 36a. Changes, addition (see 36b. Changes, altered (see painted brick rectangular Changes, moved (see 37a. Condition, interior 37b. Condition, Exterior 38. Preservation underw				
34. Wall Treatment 35. Plan Shape 36a. Changes, addition (see 36b. Changes, altered (see painted brick rectangular Changes, moved (see 37a. Condition, Interior 37b. Condition, Exterior 38. Preservation underw				
painted brick rectangular Changes, moved (see 37a. Condition, Interior 37b. Condition, Exterior 38. Preservation underw				
39a. Endangere 39b. Endangered by what? 40. Visible from public road?				
Journal Jone Control C				
59a. Eridangere 59b. Eridangered by What: 40. Visible from public road?				
41, Distance from and frontage on road				
The state of the s				
42. Further Description of Important Features				
canted recessed entrance, picture display windows with pilasters, double wooden doors				
used for loading and unloading. Glass transoms still exist under the wooden panels that				
cover them. The second story features 1/1 double hung arched windows (cont.)				
43. History and Significance				
R. M. White had it built to house the Mexico Ledger newspaper. On the first map - 1885- it was also a millinery. 1890 and 1894 show no change. 1899 - printing, bicycle shop, baking				
powder factory. 1998 - printing and sporting goods. (cont.)				
44. Description of Environment and Outbuildings				
45. Sources of Information 46. Prepared by 47. Organization				
Sanborn Maps, Dan Erdel (c Mary Aue Mitchell City of Mexico				
48. Date 49. Revision Date(
140, mare 140, 140, 140, 140, 140, 140, 140, 140,				

#5

210 West Monroe

- 42. and a decorative partial cornice with dentils. At the end of the cornice is decorative brickwork.
- 43. 1914, no change. 1926, printing with a tin shop in the basement. 1932 no change. In 1956, after 75 years at 201 West Monroe, the Ledger built a new building and moved to its current location. The building then housed Erdel's Hardware and Gift shop until circa 1995. It was then a dance studio and in the fall of 2001 became the Pillow Outlet Store. This is one of the oldest and most intact buildings on the square.
- 45. G. Craddock, and "A Gathering of Our Days" by Leta Hodge.



1. No. 2. County	3. Location of Ne	egatives 4. Current Name(s)
06 Audrain	MCRI	Mexico Service Center
5. Other Name(s)	6a. Township 6b. Rang	oc. Sectio od. Street Address
Radio Shack	T51N R9W	26 211 West Monroe
7. City or Town	7b, Vicinit 8. Description	
Mexico	Lots 2,3, and	E55' & \$60' Lot
10a. Site 10b. Buildin 10c	Structur 10d. Obje 11. Or	n National Register 12. Is it eligible 13. Part of Historic District
	L U	
14. District Potential 15. No	ame of District 16. T	Thematic Category
_0%		
17. Date(s) or Period	18. Style or Design	19. Architect or Engineer
circa 1935 and 1950		
20. Contractor or Builder	21. Original Use	22. Present Use
	commercial	commercial
23, Ownership	24. Owner's Name and A	Address 25. Open to Publi
private	Dan Erdel, 103 West Mor	nroe, Mexico MO 65265
26. Local Contact Person	or Organization	27, Other Surveys in Which Included
Lura Williams		n/a
28. No. of Stories 29. Baser	nen 30. Foundation Material	al 31. Wall Construction
1 4	concrete	brick
Roof Type and Material	33c. No. of Bays, front	33b. No. of boys, side
flat, asphalt	4	
34. Wall Treatment	35. Plan Shape	36a. Changes, addition (see 36b. Changes, altered (see
wood siding	rectangular	
Changes, moved (see 3	7a. Condition, Interior	37b. Condition, Exterior 38. Preservation underwa
	AND THE THE PARTY OF THE PARTY	
39a, Endangere 39b, End	angered by what? 40. Visib	ble from public road?
	∠ ⊬	
41. Distance from and from	ntage on road	
42. Further Description of I		
•	wood shingled awning cover	er the length of the front. The siding was
added circa 1975		
43. History and Significand	ю .	
		but burned in 1914. 1926 showed the Grand
		auto sales and service on part of the lot. By
	d John Deere Implements (co	CONT.)
44. Description of Environn	Hern and Onibaliangs	
Start Comment of the	Mark & San E 1 and the last of the last	
45. Sources of Information		47. Organization
Sanborn Maps, Dan Erdel,	and the second s	City of Mexico
	evision <u>Cate(s</u>	Transferred to the major as a second of the second
2/26/2002		2.5.1.1.1.1.1.1.1.1.1.1.1.1.1.1.1.1.1.1.

#6

- 211 West Monroe
- 43. occupied the lots. In 1973 the building burned and was rebuilt in 1974.
- 45. G. Craddock



1. No. 2. County 43 Audrain	3, Locat MCRI	ion of Negatives	4. Current Name(s) Brighter Sides Painting	
		us nistrativa de		
5. Other Name(s) Treasure Chest		R9W 26	ection 6d. Street Address 216 & 218 West Monroe	
7. City or Town	7b. Vicinit 8. C			
Mexico		0' of Lot 4 & N		
	:. Structure 10d. Obj	ec 11. On Na	tional Register? 12. is it eligible? 13. Part	of Historic Distr
L Y L				
14. District Potential? 15. N	lame of District	16. Them	atic Category	
			WAA CAN WALL CO. A. C.	_
17. Date(s) or Period	18. Style or Des	ign	19. Architect or Engineer	
circa 1905				
20. Contractor or Builder	21. Original Use		22. Present Use	
	commercial		commercial	
23. Ownership	24. Owner's Na	me and Address	25. C	pen to Public
private	Amy Auwarter,	910 Ringo, Me	xico Mo 65265	
26. Local Contact Person or	Organization		27. Other Surveys in Which Included	
Lura Williams			n/a	
28. No. of Storle 29. Baser	nent 30. Foundation	Material	31. Wall Construction	
2	brick		brick	
- Roof Type and Material	33a. No. of Bay	s front	33b. No. of bays, side	
flat/asphalt	5 53a, NO. OF Bay	sy avin ()	2	
nac aspirait	1		j -	
TA TAKE TO SELECT SELECTION	TE NO OL	N. 188 A. 1773 W.	72. M	
34. Wall Treatment	35. Plan Shape		36a. Changes, addition (see 42) 36b. Cl	anges, altered (
wood and brick	rectangular			
	rectangular	372.		nanges, altered (
wood and brick Changes, moved (see 42) 3	rectangular 7a. Condition, Interio		Condition, Exterior 38. Preservati	
wood and brick	rectangular 7a. Condition, Interio	40. Visible fr		
wood and brick Changes, moved (see 42) 3 39a. Endangered 39b. End	rectangular 7a. Condition, Interior angered by what?		Condition, Exterior 38. Preservati	
wood and brick Changes, moved (see 42) 3	rectangular 7a. Condition, Interior angered by what?	40. Visible fr	Condition, Exterior 38. Preservati	
wood and brick Changes, moved (see 42) 3 39a. Endangered 39b. End 41. Distance from and front	rectangular 7a. Condition, Interior angered by what? age on road	40. Visible fr	Condition, Exterior 38. Preservati	
wood and brick Changes, moved (see 42) 3 39a. Endangered 39b. End 41. Distance from and front 42. Further Description of Ir	rectangular 17a. Condition, Interior angered by what? age on road nportant Features	40. Visible for	Condition, Exterior 38. Preservation public road?	
wood and brick Changes, moved (see 42) [3 39a. Endangered 39b. End 41. Distance from and front 42. Further Description of Ir two step up entries with pict	rectangular 17a. Condition, Interior angered by what? age on road mportant Features ure windows beside the	40. Visible for	Condition, Exterior 38. Preservation public road?	on underway?
wood and brick Changes, moved (see 42) 3 39a. Endangered 39b. End 41. Distance from and front 42. Further Description of Ir two step up entries with pict shingle awning. There are br	rectangular 17a. Condition, Interior angered by what? age on road mportant Features ure windows beside the	40. Visible for	Condition, Exterior 38. Preservation public road?	on underway?
wood and brick Changes, moved (see 42) 3 39a. Endangered 39b. End 41. Distance from and front 42. Further Description of Ir two step up entries with pict shingle awning. There are br in the 1970's.	rectangular 17a. Condition, Interior angered by what? age on road apportant Features ure windows beside the lick arches above second	40. Visible for	Condition, Exterior 38. Preservation public road?	on underway?
wood and brick Changes, moved (see 42) 3 39a. Endangered 39b. End 41. Distance from and front 42. Further Description of Ir two step up entries with pict shingle awning. There are br in the 1970's. 43. History and Significance	rectangular 17a. Condition, Interior angered by what? age on road mportant Features ure windows beside the lick arches above second	40. Visible fr	Condition, Exterior 38. Preservation public road? wood siding on first story with wood s. This building was extensively remodeled	on underway?
wood and brick Changes, moved (see 42) [3 39a. Endangered 39b. End 41. Distance from and front 42. Further Description of Ir two step up entries with pict shingle awning. There are br in the 1970's. 43. History and Significance This building first appears in	rectangular 17a. Condition, Interior angered by what? age on road mportant Features ure windows beside the ick arches above seconds, Blattner Brothers Potential Seconds.	40. Visible fr	Condition, Exterior 38. Preservation public road?	on underway?
wood and brick Changes, moved (see 42) 3 39a. Endangered 39b. End 41. Distance from and front 42. Further Description of Ir two step up entries with pict shingle awning. There are br in the 1970's. 43. History and Significance This building first appears in painting and tin shop. 1926	rectangular 17a. Condition, Interior angered by what? age on road mportant Features ure windows beside the ick arche: above seconds, Blattner Brothers Polies and TV repair.	40. Visible fr	condition, Exterior 38. Preservation public road? wood siding on first story with wood start in the st	on underway?
wood and brick Changes, moved (see 42) 3 39a. Endangered 39b. End 41. Distance from and front 42. Further Description of Ir two step up entries with pict shingle awning. There are br in the 1970's. 43. History and Significance This building first appears in painting and tin shop. 1926 1980's it housed office supp	rectangular 17a. Condition, Interior angered by what? age on road mportant Features ure windows beside the ick arche: above seconds, Blattner Brothers Polies and TV repair.	40. Visible fr	condition, Exterior 38. Preservation public road? wood siding on first story with wood start in the st	on underway?
wood and brick Changes, moved (see 42) 3 39a. Endangered 39b. End 41. Distance from and front 42. Further Description of Ir two step up entries with pict shingle awning. There are br in the 1970's. 43. History and Significance This building first appears in painting and tin shop. 1926 1980's it housed office supp	rectangular 17a. Condition, Interior angered by what? age on road mportant Features ure windows beside the ick arche: above seconds, Blattner Brothers Polies and TV repair.	40. Visible fr	condition, Exterior 38. Preservation public road? wood siding on first story with wood start in the st	on underway?
wood and brick Changes, moved (see 42) 3 39a. Endangered 39b. End 41. Distance from and front 42. Further Description of Ir two step up entries with pict shingle awning. There are br in the 1970's. 43. History and Significance This building first appears in painting and tin shop. 1926 1980's it housed office supp 44. Description of Environm	rectangular 17a. Condition, Interior angered by what? age on road apportant Features ure windows beside thick arche: above seconds, Blattner Brothers Polies and TV repair. ent and Outbuildings	40. Visible for vi	wood siding on first story with wood s. This building was extensively remodeled plement store. 1914 it was a produce, 1935, Burchfield Produce. 1970's-	on underway?
wood and brick Changes, moved (see 42) 3 39a. Endangered 39b. End 41. Distance from and front 42. Further Description of Ir two step up entries with pict shingle awning. There are br in the 1970's. 43. History and Significance This building first appears in painting and tin shop. 1926 1980's it housed office supp 44. Description of Environm	rectangular 17a. Condition, Interior angered by what? age on road apportant Features ure windows beside thick arches above seconds, Blattner Brothers Polices and TV repair. ent and Outbuildings	40. Visible for 10 decision with the story window of agricultural impoultry and Eggs.	condition, Exterior 38. Preservation public road? wood siding on first story with wood s. This building was extensively remodeled plement store. 1914 it was a produce, 1935, Burchfield Produce. 1970's-	on underway?
wood and brick Changes, moved (see 42) 3 39a. Endangered 39b. End 41. Distance from and front 42. Further Description of Ir two step up entries with pict shingle awning. There are br in the 1970's. 43. History and Significance This building first appears in painting and tin shop. 1926 1980's it housed office supp 44. Description of Environm 45. Sources of Information Sanborn Maps, G. Craddock	rectangular 17a. Condition, Interior angered by what? age on road apportant Features ure windows beside thick arches above seconds, Blattner Brothers Polices and TV repair. ent and Outbuildings	40. Visible for 10 decision with the story window of agricultural impoultry and Eggs.	wood siding on first story with wood s. This building was extensively remodeled plement store. 1914 it was a produce, 1935, Burchfield Produce. 1970's-	on underway?





I. No. 2. County 49 Audrain	3. Location of N	MALERIAN STATES	
		egatives 4. Current Name(s)	
	MCRI	Randy's Frozen Meat	
S. Other Name(s)	6a. Township 6b. Range	e 6c. Section 6d. Street Address	
	T51N R9W	26 310 West Monroe	
7. City or Town	7b. Vicinit 8. Descriptio	on of Location 9. UTM Coordinates	
Mexico	Lots 7 & 8,		
Oa. Site 10b. Building 10	lc. Structure 10d. Objec 11.	On National Register? 12. Is it eligible? 13. Part of Historic Dist	rict
4. District Potential? 15.	Name of District 16	. Thematic Category	
7. Date(s) or Period	18. Style or Design	19. Architect or Engineer	
irca 1940	20000000 AL ARABARA AR		
O. Contractor or Bullder	21. Original Use	22. Present Use	
A COMPANY OF THE PROPERTY OF T	commercial	commercial	
3. Ownership	24. Owner's Name and		Jállás:
rivate		luldrow, Mexico MO 65265 ✓	
6. Local Contact Person o	r Organization	27. Other Surveys in Which Included	
ura Williams		n/a	
8. No. of Storie 29. Base	ment 30. Foundation Material		
Ų.	concrete	brick	
oof Type and Material	33a. No. of Bays, front	33b. No. of bays, side	
at/asphalt	4	2	erak (f. m. 1904) Programa District (f. m. 1904) (f. m. 1904)
4. Wall Treatment	35. Plan Shape	36a. Changes, addition (see 42) 36b. Changes, altered	(see 42)
rick	rectangular		
hanges, moved (see 42)	37a. Condition, Interior	37b. Condition, Exterior 38, Preservation underway?	
9a, Endangered 39b. En	dangered by what? 40. V	sible from public road?	
1			
1. Distance from and fron	tage on road		
2. Further Description of I		and above. On each side of the entrance are	
		having a garage door beside it. There is a stepped	
ornice and brick panel at t	A COMP MY MOREAUCH SEAR TO AND THE PLAN TO THE		
3. History and Significance			
		owned by Frank Pearl. One of the automobile 's Frozen Meats since circa 1980, The display	
rindow was boarded over a		3 Frozen Fleats since circa 1700, The display	
4. Description of Environr	ment and Outbuildings		
5. Sources of Information	46. Prepared by	47. Organization	
anborn Maps, G. Craddoc		City of Mexico	
	Revision Date(s)		





AU-15-001061

1. No. 2. County	3. Location of Ne	legatives 4. Current Name(s)		
90 Audrain	MCRI	Arens Appt. Barber Shop		
5. Other Name(s)	6a. Townshi 6b. Rang	6c. Sectio 6d. Street Address		
Linnemeyer Appraisal Co.	T51N R9W	26 105,107,109 East Promenade		
7. City or Town 7b. Vicini 8. Description of Location 9. UTM Coordinates				
Mexico S 52.5' of Lot 3, Block 9				
10a. Sit 10b. Buildin 10c. Structu 10d. Objec 11. On National Regist 12. is it eligibi 13. Part of Historic Distr				
14. District Potenti 15. Name	e of District 16. T	Thematic Category		
17. Date(s) or Period	18. Style or Design	19. Architect or Engineer		
circa 1895				
20. Contractor or Builder	21. Original Use	22. Present Use		
	commercial	commercial		
23. Ownership	24. Owner's Name and A	Address 25. Open to Publ		
private	Unison LLC, 11200 Audra	rain Rd 9907, Mexico MO 65265		
26. Local Contact Person or	Organization	27. Other Surveys in Which Included		
Lura Williams		n/a		
28. No. of Stori 29. Baseme	30. Foundation Materia	ial 31. Wali Construction		
2	brick	brick		
Roof Type and Material	33a. No. of Bays, front	33b. No. of bays, side		
flat/asphalt	5			
34. Wall Treatment	35. Plan Shape	36a. Changes, addition (see 36b. Changes, altered (see		
brick	rectangular	✓		
Changes, moved (see 37a.	Condition, Interior	37b. Condition, Exterior 38. Preservation underw		
39a. Endangere 39b. Endang	ered by what? 40. Visit	ible from public road?		
Sa. Elidalige o Sa. Elidaliga e Sy Wilde. 45. Visible from public fodd.				
41. Distance from and frontage on road				
42. Further Description of In	nportant Features			
		ertical wood siding on the first story. A		
		of the façade. The second and third		
stories feature boarded win	idows with brick arches,	s, sup suis and corpelling		
43. History and Significance	and 1899 - Offices Inlum	nbing, and photo gallery. 1908 shows		
		r, and after that time only a series of		
offices.		· 		
44. Description of Environm	ent and Outbuildings			
45. Sources of Information	46. Prepared by	47. Organization		
Sanborn Maps, G. Craddock	Mary Aue Mitchell	City of Mexico		
48. Date 49. Revis	ion Date(•		
6/8/2002				



1. No. 2. County	3. Location of	Negatives 4. Current Name(s)
89 Audrain	MCRI	Dr. David Luke's Office
5. Other Name(s)	6a. Township 6b. Ran	nge 6c. Section 6d. Street Address
	T51N R9W	26 113 East Promenade
7. City or Town	7b. Vicinit 8. Descript	ition of Location 9. UTM Coordinates
Mexico	☐ W 23.5' o	of Lot 2, Block 9
10a. Site 10b. Building 10	Oc. Structure 10d. Objec 11	1. On National Register? 12. Is it eligible? 13. Part of Historic District
14. District Potential? 15.	Name of Elstrict	16. Thematic Category
<u> </u>		
17. Date(s) or Period	18. Style or Design	19. Architect or Engineer
circa 1910		
20. Contractor or Bullder	21. Original Use	22. Present Use
	commercial	commercial
23. Ownership	24. Owner's Name an	d Address 25. Open to Public
private		3 East Promenade, Mexico MO 65265
26. Local Contact Person o	or Organization	27. Other Surveys In Which Included
Lura Williams		n/a
28. No. of Storie 29. Basi	ement 30. Foundation Mater	rial 31. Wall Construction
2	brick	brick
Roof Type and Material	33a. No. of Bays, fron	nt 33b. No. of bays, side
flat/asphalt	4	
34. Wall Treatment	35. Plan Shape	36a. Changes, addition (see 42) 36b. Changes, aftered (see 42)
painted brick	rectangular	
Changes, moved (see 42)	37a. Condition. Interior	37b. Condition, Exterior 38. Preservation underway?
39a, Endangered 39b. En	dangered by what? 40.	Visible from public road?
	✓ 🗸	
41. Distance from and from	Mage on road	
42. Further Description of	Important Features	
		rindow on one side and two on the other. Siding
	le. A fixed shingled shed awn	ning separates the first and second stories. The second
story features (cont.)		
43. History and Significance		
		hop and bakery that replace an earlier tin shop. a news agency only. By 1950 it was used as an office
44. Description of Environ	ment and Outbuildings	
45. Sources of Information	46. Prepared by	47, Organization
	ck, Ci Mary Aue Mitchell	City of Mexico
Sanhorn Mans. 🕒 Craddoi		
and a supplied the supplied to	Revision Date(s)	City of Prexico

#89

113 East Promenade

42. two 1/1 double hung windows with a bricked in window beside them. Above the windows is a brick panel and below the roofline is a row of corbelled brick dentals. The siding on the first story fascade and the awning were added circa 1980.



1. No. 2. Coun	ty	3. Location of Negatives				rrent Name				
91 Audrain		MCRI			Brady	y's Paint &				
5. Other Name(s)	Other Name(s) 68			6c. Sectio	d. Str	eet Addres				
	1			26	108 We	est Promer				
7. City or Town	_	7b. Vicini 8.	Description	n of Locatio	n 9.	UTM Coord	dinate	es		
Mexico			t 7. Block					 		
10a. Sit 10b. Buildi	n 10c. Str	uctu 10d. Ot	olec 11. O	n National R	eaist	12. Is it elic	albl '	13. Part of Historic Distr		
V							<u></u>			
14. District Potenti	15. Name	e of District	16.	Thematic Ca	tegon					
14. District Potenti 15. Name of District 16. Thematic Category										
17. Date(s) or Period	d	18. Style or D	esian	10 Ar	hitec	t or Engine	or			
circa 1905	<u>u</u>	io. Style of L	Colgn	19. AI	i ii ce Ci	t or Engine	CI			
	24 Original I	22 Dr	cont I	lico						
20. Contractor or Builder		21. Original L commercial	22. Pre	esent i nercial						
OZ Oversant's		OF Owen to Built								
23. Ownership		24. Owner's I			+ D	monada **	ovice	25. Open to Publ		
private		Wayne A. & k	auie A. Br							
26. Local Contact Pe	erson or	organization			er Sur	veys in Wh	ich In	cluded		
Lura Williams				n/a						
The state of the s	The state of the s					struction				
3		brick	brick							
Roof Type and Material 33a. No. of Bays, front			33b. N	33b. No. of bays, side						
flat/asphalt	3									
34. Wall Treatment 35. Plan Shap			e 36a. Char			s, addition	(see	36b. Changes, altered (see		
brick		rectangular								
Changes, moved (se	ee 37a.	Condition, Interior 37b. C			ion, Ex	cterior	reservation underw			
39a. Endangere 39b. Endangered by what? 40. Visible from public road?										
41. Distance from and frontage on road										

42. Further Description of Important Features										
recessed central entry flanked by display windows. Glass panels separate the first and										
second stories. The second and third stories feature 1/1 double hung windows with stone										
lug sills. The roofline has brick corbelling and brick dentals.										
43. History and Significance										
The first map - 1908 - shows it as a farm empliment and seed store and again in 1914. In 1926 and 1932 it was a machinery warehouse. In 1935 held the Intelligencer newspaper office. By										
1950 it was a paint store.										
44. Description of Environment and Outbuildings										
	A		<u> </u>							
an Animara at Inta		46 Bronossi	· hou	47.6-		<u> </u>				
45. Sources of Infor		46. Prepared		47. Or	ganıza f Mexi					
		<u> </u>	CHEII	July 6	i MEXI	CO				
	49. Revis	ion Date(
6/8/2002	l									



1. No. 2. County	3. Locat	ion of Negatives	4. Current Name(s)	
65 Audrain	MCRI		Bob's Appilance Center, Curves, Sa	
5. Other Name(s)	6a. Township 6	ib. Range 6c. Sec	tion 6d. Street Address	
Hassen Creamery	T51N F	26 26	109,111,113 West Promenade	
7. City or Town	7b. Vicinit 8. I	Sescription of Loca	tion 9. UTM Coordinates	
Mexico		10' Lot 2, E 1/2 L	ot 3, Bloc	
10a. Site 10b. Building 10c.	. Structure 10d. Obj	ec 11. On Natio	nal Register? 12. Is it eligible? 13. Part of Histo	ric District
	Ш	Д.		
14. District Potential? 15. N	ame of District	16. Themat	ic Category	
✓				
17. Date(s) or Period	18. Style or Des	ign 1	9. Architect or Engineer	
circa 1920				
20. Contractor or Builder	21. Original Use	2	2. Present Use	
	commercial	Ir	neeting hall	
23. Ownership	24. Owner's Na	me and Address	25. Open to	Public
private	Robert & Betty	Rivers, 1003 Wes	t Street, Mexico MO 65265	
26. Local Contact Person or	Organization	2:	7. Other Surveys in Which Included	
Lura Williams		n/	′a	
28. No. of Storie 29. Basen	ient 30. Foundation	Material :	31. Wall Construction	
1 🔲 💮	concrete		brick	
Roof Type and Material	33a. No. of Bay	s, front 3	3b. No. of bays, side	
flat/asphalt	3			
34. Wall Treatment	35. Plan Shape	2	6a. Changes, addition (see 42) 36b. Changes,	altered (see 42)
brick	rectangular		ki ya kata kata 📙 🔨 🚉	
Changes, moved (see 42) 3	7a. Condition, Interl	or 376. C	ondition, Exterior 38. Preservation unde	rway?
39a. Endangered 39b. Enda	ingered by what?	40. Visible from	n public road?	
		✓		
41. Distance from and fronta	ige on road	337		
42. Further Description of In	nportant Features			
			by a small metal awning and a wood	
		he word "Hassen"	in white brick. A brick belt course runs	
above with a parapet at the r	oonne.			
	eld a shoe renair stor	e. a systems store	and Hassen Creamery. By 1935 there	
was a shoe repair store, beau	ty shop, and creamer		Hassens Creamery remained. In the early	
1970's it housed Talbert's N			The state of the s	
44. Description of Environme	ent and Outbuildings			
45. Sources of Information	46. Prepared by		7. Organization	
Sanborn Maps, G. Craddock	, Ci Mary Aue Mitch	nell (City of Mexico	
48. Date 49. Re	vision Date(s)			
3/18/2002				
				



1. No. 2. County 64 Audrain	3. Location of Nega	Aluminum, Brick & Glass Workers
5. Other Name(s)		5c. Section 6d. Street Address
Local 790		26 117-120 West Promenade
7. City or Town	7b. Vicinit 8. Description of	
Mexico	Lots 3 8t 4, Blo	
		National Register? 12. Is it eligible? 13. Part of Historic Dist
14. District Potential? 15. Na	me of District 16. T	hematic Category
17. Date(s) or Period	18. Style or Design	19. Architect or Engineer
circa 1885		
20. Contractor or Builder	21, Original Use	22. Present Use
	commercial	commercial
23. Ownership	24. Owner's Name and Ad	dress 25. Open to Public
private	Carl Roberts, Local 790, Po	O Box 277, Mexico MO 65265
26. Local Contact Person or C	Prganization .	27. Other Surveys in Which Included
Lura Williams		n/a
28. No. of Storle 29. Baseme	nt 30. Foundation Material	31. Wall Construction
2	brick	brick
Roof Type and Material	33a. No. of Bays, front	33b. No. of bays, side
flat/asphalt	7	3
34. Wall Treatment	35. Plan Shape	36a. Changes, addition (see 42) 36b. Changes, altered
stucco	rectangular	
Changes, moved (see 42) 37:	a. Condition, Interior	37b. Condition, Exterior 38. Preservation underway?
	25 Se San Jacob Se	
39a. Endangered 39b. Endan	gered by what? 40. Visib	ole from public road?
41. Distance from and frontag	e on road	
42. Further Description of Imp		windows have been filled in and replaced by long
		ered with stucco in approximately 1985 thus
obscuring the brick details.		
43. History and Significance	11.00	
		ng and second hand store on first floor, hotel on as a grocery store, then sheet metal until 1986
when the union moved into it.		and a growing chem street internal 1700
44. Description of Environmen	it and Outbuildings	
45. Sources of Information	46. Prepared by	47. Organization
Sanborn Maps, G. Craddock, G		City of Mexico
48. Date 49. Rev	Islon Date(s)	
3/18/2002		



1. No. 2. County	3. LOC	ation of N	egatives	4. Current	Name(s)	
92 Audrain	MCRI			Crown Line	en Service	
5. Other Name(s)	6a. Townshi	6b. Rang	6c. Sectio	6d. Street Ac	dress	
	T51N	R9W	26	118 West Pro	omenade	
7. City or Town	7b. Vicini 8.	Description	n of Locati	on 9. UTM	Coordinate	es .
Mexico	□ E	32' of Lot !	5, Block 3			
10a. Sit 10b. Buildin 10c. Str	uctu 10d. O	bjec 11. O	n National I	Regist 12. Is	it eligibi 1	3. Part of Historic Distr
14. District Potenti 15. Name	e of District	16.	Thematic C	ategory		
y						
17. Date(s) or Period	18. Style or I	Design	19. A	rchitect or Er	ngineer	
circa 1910					-	
20. Contractor or Builder	21. Original I	Jse	22. Pi	resent Use		
	commercial		com	mercial		
23. Ownership	24. Ov/ner's	Name and	Address			25. Open to Publ
private				South Jeffer	rson, Mexic	
26. Local Contact Person or				her Surveys i		
Lura Williams	or garnizacion		n/a	ilor Jai Voya	11 11111011111	514454
28. No. of Stori 29. Baseme	30. Foundat	ion Materi		Vall Construc	tion	
28. NO. OF Storr 29. Baseme	concrete	JOH Water	bric		LIOIT	
		leve frame				
Roof Type and Material	33a. No. of E	ays, front	33D.	No. of bays, s	ide	
flat/asphalt	ļ					
34. Wall Treatment	35. Plan Sha		36a. (changes, add	ition (see	36b. Changes, altered (see
brick	rectangular					
Changes, moved (see 37a.	Condition, In	terior	37b. Cond	tion, Exterio	r 38. P	reservation underw
39a. Endangere 39b. Endang	ered by wha	t? 40. Vis	ible from p	ublic road?		
41. Distance from and front	age on road		Mark.			
42. Further Description of In						
single recessed side entry v	vith a picture	window b	eside it and	a brick pilla	r separatin	git
from a garage door. The sec bracketed lintels. Two brick	condistory te chanels run :	atures 1/1 above the v	aoubie nui windows	ig windows v	with lug sill	is and
43. History and Significance	· pario o rairi	2010 010	************			
It first shows up on the map	os in 1914 as	a barber sh	10p. 1926 sl	nows it to be	a taylor sh	lop. In
1935 it was a beauty parlor	and barber sl	nop. By 19	50 it had be	come an app	liance sho	p with a
masonic lodge above.						
44. Description of Environm	ent and Outl	buildings			<u>.</u>	
45. Sources of Information	46. Prepared	yd by	47. 0	rganization		
Sanborn Maps, G. Craddock	Mary Aue M	itchell		of Mexico		
	lon Date(,			
6/8/2002						



1. No.	2. County		3. Loca	ation o	f Negativ	res 4	. Cu	rrent Nam	e(s)		
93	Audrain		MCRI			7	Crown Linen Service, B				
5. Other N	ame(s)	6a. To	wnshi	6b. Rar	ng 6c. S	ectio 6d	. Str	eet Addre	SS ·		_
		T51N		R9W	26	12	0 W	est Prome	nade		•
7. City or T	'own	7b. Vid	ini 8.	Descrip	otion of I	ocation.	9.	UTM Coor	rdinat	es	
Mexico			w	32' of I	Lot 5, Blo	ck 3	T	•		*	
10a. SIt 10	Ob. Buildin 100	. Structu	10d. Ot	ojec 11	. On Nat	onal Reg	ilst	12. Is it el	lgibi	13. Part of H	listoric Distr
~		Ĺ									
14. District	Potenti 15. N	ame of Dis	trict		16. Them	atic Cate	gor	v			
V								<u>-</u>		<u> </u>	
17. Date(s)	or Period	18. Sty	le or D	esign		19. Arch	itec	t or Engine	eer		
circa 1905											
	ctor or Bullde	r 21. Ori	ginal U	se		22. Pres	ent i	Use			
		comm				comme					
23. Owners	ship allo	24. Ov	mer's N	Name a	nd Addre	ess				25. Open	to Pub
private							uth	Jefferson	Mexi		
	ontact Person							veys in Wr			
Lura Willia		geilli				n/a	Vul			Judou	
	Stori 29. Base	me 30. Fc	undati	on Mat			Cor	struction			
2	20. 20.	conci		01111100	Cildi	brick	COI	isa accion			
	and Material			ays, fro	nt	,	~ F	pays, side			
flat/aspha		2	o. Or De	173, 110	110	9	01 1	Jays, side			
34. Wall Tre			n Shap	Δ			nae	s, addition	1500	ZSh Chang	jes, altered (see
brick	saurient.	rectar		<u> </u>		Joa. Cha	iige	s, auuilion	1366	Sob. Charry	jes, altered tsee
	noved (see 3	7a. Condit		erior	77h	 Conditio	n E	vtorior	70 D	reservation	undeny
Changes, i	noved (see 3	7a. Condit	OH, IH	.CI IOI	3/0.	conuluo	i i, E2	KLETIOI	30. P	1 CSCI VALIOII	under w
ZOo Endon	gere 39b. End	iangered h	v what	2 40 1	 Visible fr	om nuhl	io ra	nad2			
59a. Elluali	igere 39b. Enc	larigered L	y wilat	· · · · · · · · · · · · · · · · · · ·	AISIDIE II	om pubi	ic re	aur			
44 Dietema		ontago on	road								
41. DISTANC	e from and fr	Unitage Un	Jau								
40 5	r Description (of Imports	ot Foot	11500	_						
	r pescription or r entories wit				a the ler	ath of t	he f	irst story f	acade	and	
	a fixed awnin										
windows v	with lug sills a	nd bracket									
	and Significat										
	st map - 1908 -				ore. 191	4, dry go	ods	store and	1926	an auto	
supply sto	re. By 1950 it	nousea Ali	urain L	Jali Y.							
44. Descrir	otion of Enviro	nment and	1 Outb	ulidings	S						
		- 10 m	. marad	les e		an c	l	41			
	s of Informati		-			47. Orga					
	laps, G. Cradd			CHEII		City of I	viexi				
48. Date	49. R	evision Da	:e(
6/8/2002	1										



1. No.	2. County	3. Loc	ation of Ne	gatives	4. Current Na	me(s)		
63	Audrain	MCRI			Charlie's Pest	Control	giro il	
5. Other	r Name(s)	6a. Township	6b. Range	6c. Section	n 6d. Street Addr	TESS		
		T51N	R9W	26	209 West Prom	ienade		
7. City o	or Town	7b. Vicinit 8.	Description	of Location	n 9. UTM C	Coordinates		量
Mexico		S	22' of Lot	2, Block 7			7	
10a. Site	e 10b. Building 10c. S	tructure 10d. O	bjec 11. C	On Nationa	Register? 12. Is it	t eligible? 13. Part o	f Historic District	
		$=\Box$	П		áš 📗	Tarana		
14. Disti	rict Potential? 15. Nam	ne of District	16.	Thematic	Category] // // // // // // // // // // // // //	
✓								
17. Date	(s) or Period	18. Style or D	esign	19.	Architect or Engir	ieer		
circa 18	85						7	
20. Con	tractor or Bullder	21. Original U	se	22.	Present Use			
		commercial		cor	nmercial			
23. Owr	nership	24. Owner's h	Vame and A	ddress		25. O	pen to Public	
private		Charlie & Bre	nda Smith,	15534 Hig	hway JJ, Mexico M	10 65265 🗹		
26. Loca	l Contact Person or Or	ganization		27.	Other Surveys In V	Vhich included		
Lura Wil	lliams			n/a				
28. No.	of Storle 29. Basemen	it 30. Foundatio	n Material	31	. Wall Construction	1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1		
2	Ц.	brick		bri	ck			
Roof Ty	oe and Material	33a. No. of B.	ays, front	331	. No. of bays, side			
flat/asph	alt	11		3				
34. Wall	Treatment	35. Plan Shape		368	i. Changes, addition	n (see 42) 36b. Ch	anges, altered (see	42)
brick		rectangular		Ų				
Changes,	moved (see 42) 37a	. Condition, Inte	rior	37b. Con	dition, Exterior	38. Preservatio	n underway?	
Ш								
39a. End	langered 39b. Endang	ered by what?	The second secon	sible from p	ublic road?			
Ш			✓				de production	
41. Dista	ance from and frontage	on roac						
					VIII WARREN WARREN			
	her Description of Impo							
	y fascade has from west							
_	ndows, a door, two 1/1 ded by wood siding or s	-	noaws, a po	ost, and and	otner door. Each o	or these reatures is	1 mg	
	ory and Significance	P) /		550	14.5		78 - 12	
The earl	iest map - 1885 - show							
	1908 it was known as the		etween 192	26 and 192	29 the hotel closed	and it became a		
-	nt and laundry. (cont.)						-,	
TT. DESC	The state of the constant	and Altonomia					+	
1/1 <u>1/1</u>			north Cartonia	8. 7. 3 				
	rces of Information	46. Prepared I			Organization			
No. of a substance	Maps, G. Craddock, C		cnell	City	y of Mexico			
48. Date		ion Date(s)						
3/15/20	002							

#63

209 West Promenade

- 42. The second story features four 9/9 double hung windows with lintels and lug sills. A belt course runs between the windows and the corbelled brick dentals at the roofline. The façade was changed circa 1990. The alternations make it only marginally contributing to a historic district.
- 43. By 1970 it housed a liquor store and a television repair store.



AU Bearly

MCRI	1. No. 2. County	3. Location of Negat	tives 4. Current Name(s)
Kabrich Opera House T51N R9W 26 101 & 103 North Washington	35 Audrain	MCRI .	Mexico Music & TJ's Hair Affair
7. City or Town 7b. Vicini 8. Description of Location 9. UTM Coordinates Mexico 5 44' of Lot 8, Block 13 10a. Sit 10b. Buildin 10c. Structu 10d. Objec 11. On National Regist 12. Is it eligibl 13. Part of Historic Distr 14. District Potenti 15. Name of District 16. Thematic Category 17. Date(s) or Period 18. Style or Design 19. Architect or Engineer 1875 20. Contractor or Builder 21. Original Use 22. Present Use 22. Present Use 25. Open to Publ 24. Owner's Name and Address 25. Open to Publ 25. Open to Publ 26. Local Contact Person or Organization 27. Other Surveys in Which Included 17. Other Surveys in Which Included 17. Other Surveys in Which Included 18. Wall Construction 18. Wall Construction 18. Wall Construction 18. Wall Treatment 18. No. of Bays, front 18. No. of bays, side 18. Wall Treatment 18. Pian Shape 18. Ochanges, addition (see 18. Changes, altered (see painted brick 18. Condition, Interior 18. Condition, Exterior 18. Preservation underw 18. Figure 18. Under 18. Distance from and frontage on road 18. History and Significance 18. How on the First floor, the Kabrich Opera House on the second floor, and a masonic hall on the third floor. 1890, 1899, 1908, no change, in the Interior 1800, 1899, 1908, no change, in 1891, 1899, 1908, no change. In 1891, 1890, 1899, 1908, no change. In 1891, 1890, 1899, 1908, no change. In 1994 the masonic hall is no longer mentioned (cont.)	5. Other Name(s)	6a. Townshi 6b. Rang 6c.	Sectio 6d. Street Address
Mexico S 44' of Lot 8, Block 13 10b. Buildin 10c. Structu 10d. Objec 11. On National Regist 12. Is it eligibl 13. Part of Historic District 14. District Potenti 15. Name of District 16. Thematic Category 17. Date(s) or Period 18. Style or Design 19. Architect or Engineer 1875 17. Date(s) or Period 18. Style or Design 19. Architect or Engineer 1875 18. Owner's Name and Address 18. Owner's Na	Kabrich Opera House	T51N R9W 26	101 & 103 North Washington
10a. Sit 10b. Buildin 10c. Structu 10d. Objec 11. On National Regist 12. Is it eligibi 13. Part of Historic District 14. District Potenti 15. Name of District 16. Thematic Category 17. Date(s) or Period 18. Style or Design 19. Architect or Engineer 1875 20. Contractor or Builder 21. Original Use 22. Present Use 23. Ownership 24. Owner's Name and Address 25. Open to Publiprivate 17 Tamra K. Gibbons, 12435 Sufstin Tosf 9931, Mexico MO 652 16. Local Contact Person or Organization 27. Other Surveys in Which included 17. Ura Williams 17.4 28. No. of Stori 29. Baseme 30. Foundation Material 31. Wall Construction 2	7. City or Town	7b. Vicini 8. Description o	f Location 9. UTM Coordinates
14. District Potenti 15. Name of District 16. Thematic Category	Mexico	S 44' of Lot 8, BI	ock 13
14. District Potenti 15. Name of District 16. Thematic Category 17. Date(s) or Period 18. Style or Design 19. Architect or Engineer 1875 20. Contractor or Builder 21. Original Use 22. Present Use 23. Ownership 24. Owner's Name and Address 25. Open to Publ Private Tamra K. Gibbons, 12435 Sufstin Tosf 9931, Mexico Mo 652	10a. Sit 10b. Bulldin 10c. St	ructu 10d. Objec 11. On Na	ational Regist 12. Is it eligibl 13. Part of Historic Distr
17. Date(s) or Period 18. Style or Design 19. Architect or Engineer 1875 20. Contractor or Builder 21. Original Use 22. Present Use Commercial Commercial Commercial 23. Owner's Name and Address 25. Open to Publ Private Tamra K. Gibbons, 12435 Sufstin Tosf 9931, Mexico MO 652 26. Local Contact Person or Organization 27. Other Surveys in Which Included Lura Williams Dr/a 28. No. of Stori 29. Baseme 30. Foundation Material 31. Wall Construction 27. Other Surveys in Which Included 28. No. of Stori 29. Baseme 30. Foundation Material 31. Wall Construction 27. Other Surveys in Which Included 28. No. of Stori 29. Baseme 35. Poundation Material 31. Wall Construction 27. Other Surveys in Which Included 28. No. of Stori 29. Baseme 35. Poundation Material 31. Wall Construction 32. No. of Bays, side 34. Wall Treatment 35. Plan Shape 36a. Changes, addition (see 36b. Changes, altered (see painted brick rectangular			
17. Date(s) or Period 18. Style or Design 19. Architect or Engineer 1875 20. Contractor or Builder 21. Original Use 22. Present Use Commercial Commercial Commercial 23. Owner's Name and Address 25. Open to Publ Private Tamra K. Gibbons, 12435 Sufstin Tosf 9931, Mexico MO 652 26. Local Contact Person or Organization 27. Other Surveys in Which Included Lura Williams Dr/a 28. No. of Stori 29. Baseme 30. Foundation Material 31. Wall Construction 27. Other Surveys in Which Included 18. Wall Treatment 332. No. of Bays, front 330. No. of bays, side 6. 6. 6. 6. 6. 6. 6. 6	14. District Potenti 15. Nam	e of District 16. The	matic Category
20. Contractor or Builder 21. Original Use 22. Present Use commercial commercial commercial 23. Ownership 24. Owner's Name and Address 25. Open to Publ private Tamra K. Gibbons, 12435 Sufstin Tosf 9931, Mexico MO 652 26. Local Contact Person or Organization 27. Other Surveys in Which Included Lura Williams 10/4 28. No. of Stori 29. Baseme 30. Foundation Material 31. Wall Construction 2 stone brick Roof Type and Material 33a. No. of Bays, front 33b. No. of bays, side flat/asphalt 6 6 6 6 6 6 6 6 6 6 6 6 6 6 6 6 6 6 6			
22. Present Use Commercial Commercial Commercial	17. Date(s) or Period	18. Style or Design	19. Architect or Engineer
Commercial Commercial Commercial 23. Ownership 24. Owner's Name and Address 25. Open to Public Private Tamra K. Globons, 12435 Sufstin Tosf 9931, Mexico Mo 652 26. Local Contact Person or Organization 27. Other Surveys in Which Included Lura Williams In/a	1875		
Commercial Commercial 23. Ownership 24. Owner's Name and Address 25. Open to Public Private Tamra K. Glbbons, 12435 Sufstin Tosf 9931, Mexico Mo 652 26. Local Contact Person or Organization 27. Other Surveys in Which Included Lura Williams In/a	20. Contractor or Builder	21. Original Use	22. Present Use
private Tamra K. Gibbons, 12435 Sufstin Tosf 9931, Mexico Mo 652 26. Local Contact Person or Organization 27. Other Surveys in Which Included Lura Williams 28. No. of Stori 29. Baseme 30. Foundation Material 31. Wall Construction 2		commercial	
private Tamra K. Gibbons, 12435 Sufstin Tosf 9931, Mexico MO 652 26. Local Contact Person or Organization 27. Other Surveys in Which Included Lura Williams 28. No. of Stori 29. Baseme 30. Foundation Material 31. Wall Construction 2	23. Ownership	24. Owner's Name and Add	dress 25. Open to Publ
26. Local Contact Person or Organization 27. Other Surveys in Which Included Lura Williams 28. No. of Stori 29. Baseme 30. Foundation Material 31. Wall Construction 2 Stone brick Roof Type and Material 33a. No. of Bays, front 33b. No. of bays, side flat/asphalt 6 6 34. Wall Treatment 35. Plan Shape 36a. Changes, addition (see 36b. Changes, altered (see painted brick rectangular Spanitus Sp			AND THE PROPERTY OF THE PROPER
Lura Williams 28. No. of Stori 29. Baseme 30. Foundation Material 31. Wall Construction 2	<u> </u>	 	
28. No. of Stori 29. Baseme 30. Foundation Material 31. Wall Construction 2			
stone brick Roof Type and Material 33a. No. of Bays, front 33b. No. of bays, side flat/asphalt 6 6 6 34. Wall Treatment 35. Plan Shape 36a. Changes, addition (see 36b. Changes, altered (see painted brick rectangular Changes, moved (see 37a. Condition, Interior 37b. Condition, Exterior 38. Preservation underw 39a. Endangere 39b. Endangered by what? 40. Visible from public road? 41. Distance from and frontage on road 42. Further Description of Important Features two store fronts, recessed corner entry and recessed front entry. Each is flanked by display windows with brick panels above. The south side of the building has 5 double hung window and the second story has 3 on the front and 4 on the side. (cont.) 43. History and Significance The earliest map - 1885 - shows a dry goods and clothing store on the first floor, the Kabrich Opera House on the second floor, and a masonic hall on the third floor. 1890, 1899, 1908, no change. In 1914 the masonic hall is no longer mentioned (cont.)		30 Foundation Material	31 Wall Construction
Roof Type and Material 33a. No. of Bays, front 33b. No. of bays, side flat/asphalt 6 34. Wall Treatment 35. Plan Shape 36a. Changes, addition (see 36b. Changes, altered (see painted brick rectangular Changes, moved (see 37a. Condition, Interior 37b. Condition, Exterior 38. Preservation underw 39a. Endangere 39b. Endangered by what? 40. Visible from public road? 41. Distance from and frontage on road 42. Further Description of Important Features two store fronts, recessed corner entry and recessed front entry. Each is flanked by display windows with brick panels above. The south side of the building has 5 double hung window and the second story has 3 on the front and 4 on the side. (cont.) 43. History and Significance The earliest map - 1885 - shows a dry goods and clothing store on the first floor, the Kabrich Opera House on the second floor, and a masonic hall on the third floor. 1890, 1899, 1908, no change. In 1914 the masonic hall is no longer mentioned (cont.)			
flat/asphalt 34. Wall Treatment 35. Plan Shape 36a. Changes, addition (see 36b. Changes, altered (see painted brick Changes, moved (see 37a. Condition, Interior 37b. Condition, Exterior 38. Preservation underw 39a. Endangere 39b. Endangered by what? 40. Visible from public road? 41. Distance from and frontage on road 42. Further Description of Important Features two store fronts, recessed corner entry and recessed front entry. Each is flanked by display windows with brick panels above. The south side of the building has 5 double hung window and the second story has 3 on the front and 4 on the side. (cont.) 43. History and Significance The earliest map - 1885 - shows a dry goods and clothing store on the first floor, the Kabrich Opera House on the second floor, and a masonic hall on the third floor. 1890, 1899, 1908, no change. In 1914 the masonic hall is no longer mentioned (cont.)			
34. Wall Treatment 35. Plan Shape 36a. Changes, addition (see 36b. Changes, altered (see painted brick rectangular Changes, moved (see 37a. Condition, Interior 37b. Condition, Exterior 38. Preservation underw 39a. Endangere 39b. Endangered by what? 40. Visible from public road? 41. Distance from and frontage on road 42. Further Description of Important Features two store fronts, recessed corner entry and recessed front entry. Each is flanked by display windows with brick panels above. The south side of the building has 5 double hung window and the second story has 3 on the front and 4 on the side. (cont.) 43. History and Significance The earliest map - 1885 - shows a dry goods and clothing store on the first floor, the Kabrich Opera House on the second floor, and a masonic hall on the third floor. 1890, 1899, 1908, no change. In 1914 the masonic hall is no longer mentioned (cont.)			
Changes, moved (see 37a. Condition, Interior 37b. Condition, Exterior 38. Preservation underw 39a. Endangere 39b. Endangered by what? 40. Visible from public road? 41. Distance from and frontage on road 42. Further Description of Important Features two store fronts, recessed corner entry and recessed front entry. Each is flanked by display windows with brick panels above. The south side of the building has 5 double hung window and the second story has 3 on the front and 4 on the side. (cont.) 43. History and Significance The earliest map - 1885 - shows a dry goods and clothing store on the first floor, the Kabrich Opera House on the second floor, and a masonic hall on the third floor. 1890, 1899, 1908, no change. In 1914 the masonic hall is no longer mentioned (cont.)			<u> </u>
Changes, moved (see 37a. Condition, Interior 37b. Condition, Exterior 38. Preservation underw 39a. Endangere 39b. Endangered by what? 40. Visible from public road? 41. Distance from and frontage on road 42. Further Description of Important Features two store fronts, recessed corner entry and recessed front entry. Each is flanked by display windows with brick panels above. The south side of the building has 5 double hung window and the second story has 3 on the front and 4 on the side. (cont.) 43. History and Significance The earliest map - 1885 - shows a dry goods and clothing store on the first floor, the Kabrich Opera House on the second floor, and a masonic hall on the third floor. 1890, 1899, 1908, no change. In 1914 the masonic hall is no longer mentioned (cont.)	The second contract of the second of the sec		
39a. Endangere 39b. Endangered by what? 40. Visible from public road? 41. Distance from and frontage on road 42. Further Description of Important Features two store fronts, recessed corner entry and recessed front entry. Each is flanked by display windows with brick panels above. The south side of the building has 5 double hung window and the second story has 3 on the front and 4 on the side. (cont.) 43. History and Significance The earliest map - 1885 - shows a dry goods and clothing store on the first floor, the Kabrich Opera House on the second floor, and a masonic hall on the third floor. 1890, 1899, 1908, no change. In 1914 the masonic hall is no longer mentioned (cont.)		<u> </u>	Condition Exterior 29 Preservation underw
41. Distance from and frontage on road 42. Further Description of Important Features two store fronts, recessed corner entry and recessed front entry. Each is flanked by display windows with brick panels above. The south side of the building has 5 double hung window and the second story has 3 on the front and 4 on the side. (cont.) 43. History and Significance The earliest map - 1885 - shows a dry goods and clothing store on the first floor, the Kabrich Opera House on the second floor, and a masonic hall on the third floor. 1890, 1899, 1908, no change. In 1914 the masonic hall is no longer mentioned (cont.)	Changes, moved (see 57a.	Condition, interior 57L	5. Condition, Extendi So. Preservation underw
41. Distance from and frontage on road 42. Further Description of Important Features two store fronts, recessed corner entry and recessed front entry. Each is flanked by display windows with brick panels above. The south side of the building has 5 double hung window and the second story has 3 on the front and 4 on the side. (cont.) 43. History and Significance The earliest map - 1885 - shows a dry goods and clothing store on the first floor, the Kabrich Opera House on the second floor, and a masonic hall on the third floor. 1890, 1899, 1908, no change. In 1914 the masonic hall is no longer mentioned (cont.)	70e Endangero 70h Endang	nered by what? 40 Vicible	from public road?
42. Further Description of Important Features two store fronts, recessed corner entry and recessed front entry. Each is flanked by display windows with brick panels above. The south side of the building has 5 double hung window and the second story has 3 on the front and 4 on the side. (cont.) 43. History and Significance The earliest map - 1885 - shows a dry goods and clothing store on the first floor, the Kabrich Opera House on the second floor, and a masonic hall on the third floor. 1890, 1899, 1908, no change. In 1914 the masonic hall is no longer mentioned (cont.)	59a. Endangere 59b. Endang		Trom public roads
42. Further Description of Important Features two store fronts, recessed corner entry and recessed front entry. Each is flanked by display windows with brick panels above. The south side of the building has 5 double hung window and the second story has 3 on the front and 4 on the side. (cont.) 43. History and Significance The earliest map - 1885 - shows a dry goods and clothing store on the first floor, the Kabrich Opera House on the second floor, and a masonic hall on the third floor. 1890, 1899, 1908, no change. In 1914 the masonic hall is no longer mentioned (cont.)	A4 Distance from and front	age on road	
two store fronts, recessed corner entry and recessed front entry. Each is flanked by display windows with brick panels above. The south side of the building has 5 double hung window and the second story has 3 on the front and 4 on the side. (cont.) 43. History and Significance The earliest map - 1885 - shows a dry goods and clothing store on the first floor, the Kabrich Opera House on the second floor, and a masonic hall on the third floor. 1890, 1899, 1908, no change. In 1914 the masonic hall is no longer mentioned (cont.)	41. Distance morn and mont	age on road	
two store fronts, recessed corner entry and recessed front entry. Each is flanked by display windows with brick panels above. The south side of the building has 5 double hung window and the second story has 3 on the front and 4 on the side. (cont.) 43. History and Significance The earliest map - 1885 - shows a dry goods and clothing store on the first floor, the Kabrich Opera House on the second floor, and a masonic hall on the third floor. 1890, 1899, 1908, no change. In 1914 the masonic hall is no longer mentioned (cont.)	40 Province Becompiler of t	mnortent Eosturos	
windows with brick panels above. The south side of the building has 5 double hung window and the second story has 3 on the front and 4 on the side. (cont.) 43. History and Significance The earliest map - 1885 - shows a dry goods and clothing store on the first floor, the Kabrich Opera House on the second floor, and a masonic hall on the third floor. 1890, 1899, 1908, no change. In 1914 the masonic hall is no longer mentioned (cont.)			front entry Each is flanked by display
and the second story has 3 on the front and 4 on the side. (cont.) 43. History and Significance The earliest map - 1885 - shows a dry goods and clothing store on the first floor, the Kabrich Opera House on the second floor, and a masonic hall on the third floor. 1890, 1899, 1908, no change. In 1914 the masonic hall is no longer mentioned (cont.)	windows with brick panels	above. The south side of th	ne building has 5 double hung window
The earliest map - 1885 - shows a dry goods and clothing store on the first floor, the Kabrich Opera House on the second floor, and a masonic hall on the third floor. 1890, 1899, 1908, no change. In 1914 the masonic hall is no longer mentioned (cont.)			
Opera House on the second floor, and a masonic hall on the third floor. 1890, 1899, 1908, no change. In 1914 the masonic hall is no longer mentioned (cont.)			
change. In 1914 the masonic hall is no longer mentioned (cont.)	The earliest map - 1885 - sh	ows a dry goods and clothin	ng store on the first floor, the Kabrich
	change in 1914 the mason	a fioor, and a masonic nail o ic hall is no longer mention	n the third floor. 1890, 1899, 1908, no led. (cont.)
45. Sources of Information 46. Prepared by 47. Organization	45. Sources of Information	46. Prepared by	47. Organization
Sanborn Maps, G. Craddock Mary Aue Mitchell City of Mexico			
48. Date 49. Revision Date(<u> </u>	1
3/4/2002	10.1011		

#35

101 & 103 North Washington

- 42 There was a third floor which was removed circa 1950 and the building was rebricked.
- 43 and neither is the opera house. In 1926, 1934 the building housed Farmers' and Merchants' Bank as well as a roller rink on the second floor and a tin shop in the basement. By 1935 it was a shoe hospital. Radio Shack occupied the building circa 1990. This is one of the oldest buildings on the square and has played an active roll in the social life of downtown Mexico, Missouri.
- 45 City Directories, "A Gathering of Our Days" by Leta Hodge.







	3. Location of N	legatives 4. Current Name(s)
1. No. 2. County 36 Audrain	MCRI	Blattner's
5. Other Name(s)		óc. Sectio od. Street Address
J. One Name(s)	T51N R9W	26 105 North Washington
7.74.2.72.2		and the state of t
7. City or Town Mexico	7b. Vicinit 8. Description	on of Location 9. UTM Coordingtes and N 16' of Lot
10d. Site 10b. Buildin 10c. S	rructur (ud. Obje 1 1 1	On National Register 12 is it eligible 13, Part of Historic District
14. District Potential 15. Nan	ne of District 16.	Thematic Category
17. Date(s) or Period	18, Style or Design	19. Architect of Engineer
circa 1880		1777 ACHILOUT CITE TORRISO
	1. Original like	22. Present Use
20. Contractor or Builder	21. Original Use commercial	commercial
23. Ownership private	24. Oviner's Name and	1 Address 25. Open to Publi Court Street, Fulton MO 65251 ✓
26. Local Contact Person or Lura Williams	<u>Urganization</u>	27. Other Surveys in Which Included
	12.2	n/a
28. No. of Stories 29. Baseme		
2	brick	brick
Roof Type and Material	33a. No. of Bays, front	33b. No. of bays, side
flat/asphalt	3	
34. Wall Treatment	35. Plan Shape	36a. Changes, addition (see 36b. Changes, altered (see
painted brick and carrara g	l rectangular	
Changes, moved (see 37a	. Condition, Interior	37b. Condition, Exterior 38, Preservation underwa
Changes, moved (see 37a	Condition, Interior	37b. Condition, Exterior 38. Preservation underwa
Changes, moved (see 37a 39a. Endangere 39b. Endan		37b. Condition, Exterior 38, Preservation underwa
39a: Endangere 39b; Endan	gered by what? 40. Vis	
	gered by what? 40. Vis	
39a. Endangere 39b. Endan 41. Distance from and fronta	gered by what? 40. Vis	
39a: Endangere 39b; Endan 41. Distance from and fronto 42. Further Description of Imp	gered by what? 40. Vis ge on road contant Features	sible from public road?
39a. Endangere 39b. Endan 41. Distance from and fronto 42. Further Description of Imprecessed entry flanked by di	gered by what? 40. Vis ge on road portant Features splay vindows with blac	
39a. Endangere 39b. Endan 41. Distance from and fronto 42. Further Description of Imprecessed entry flanked by di Above the store sign on the panels and corbelled denta	gered by what? 40. Vis ge on road portant Features Isplay vindows with blact black glass are three 40.	sible from public road?
39a. Endangere 39b. Endan 41. Distance from and fronto 42. Further Description of Imprecessed entry flanked by di Above the store sign on the panels and corbelled denta 43. History and Significance	gered by what? 40. Vis ge on road cortant Features splay vindows with blact black glass are three 40 lils at the roof line	sible from public road? k carrara glass to the sides and above. light windows with slip sills and three brick
39a. Endangere 39b. Endan 41. Distance from and fronto 42. Further Description of Imprecessed entry flanked by di Above the store sign on the panels and corbelled denta 43. History and Significance The earliest map - 1885 - sho	gered by what? 40. Vis ge on road cortant Features splay vindows with blace black glass are three 40 lils at the roof line ws this building as a groot	sible from public road? k carrara glass to the sides and above. light windows with slip sills and three brick bery and dry goods store. 1890,1894,1899, no
39a. Endangere 39b. Endan 41. Distance from and fronto 42. Further Description of Imprecessed entry flanked by di Above the store sign on the panels and corbelled denta 43. History and Significance The earliest map - 1885 - sho change. 1908, 1914, 1926, 1	gered by what? 40. Vis ge on road portant Features isplay vindows with blace black glass are three 40 lils at the roof line ws this building as a groce 934 show grocery store of	sible from public road? k carrara glass to the sides and above. light windows with slip sills and three brick
41. Distance from and fronto 42. Further Description of Imprecessed entry flanked by di Above the store sign on the panels and corbelled denta 43. History and Significance The earliest map - 1885 - sho change. 1908, 1914, 1926, 1 as Ekenberger and Dent. (co	gered by what? 40. Visinge on road cortant Features splay vindows with blact black glass are three 40 lills at the roof line ws this building as a groce 934 show grocery store cont.)	sible from public road? k carrara glass to the sides and above. light windows with slip sills and three brick bery and dry goods store. 1890,1894,1899, no
39a. Endangere 39b. Endan 41. Distance from and fronto 42. Further Description of Imprecessed entry flanked by di Above the store sign on the panels and corbelled denta 43. History and Significance The earliest map - 1885 - sho change. 1908, 1914, 1926, 1	gered by what? 40. Visinge on road cortant Features splay vindows with blact black glass are three 40 lills at the roof line ws this building as a groce 934 show grocery store cont.)	sible from public road? k carrara glass to the sides and above. light windows with slip sills and three brick bery and dry goods store. 1890,1894,1899, no
41. Distance from and fronto 42. Further Description of Imprecessed entry flanked by di Above the store sign on the panels and corbelled denta 43. History and Significance The earliest map - 1885 - sho change. 1908, 1914, 1926, 1 as Ekenberger and Dent. (co	gered by what? 40. Visinge on road cortant Features splay vindows with blact black glass are three 40 lills at the roof line ws this building as a groce 934 show grocery store cont.)	sible from public road? k carrara glass to the sides and above. light windows with slip sills and three brick bery and dry goods store. 1890,1894,1899, no
41. Distance from and fronto 42. Further Description of Imprecessed entry flanked by di Above the store sign on the panels and corbelled denta 43. History and Significance The earliest map - 1885 - sho change. 1908, 1914, 1926, 1 as Ekenberger and Dent. (cd.) 44. Description of Environments	gered by what? 40. Visinge on road. Sortant Features splay vindows with blact black glass are three 40 list at the roof line ws this building as a groce opent.) Internal Outbuildings	k carrara glass to the sides and above. light windows with slip sills and three brick bery and dry goods store. 1890,1894,1899, no only. The 1935 city directory listed the grocery
39a. Endangere 39b. 1914, 1926, 1 as Ekenberger and Dent. (ca. 44. Description of Environmere 39b. Sources of Information.	gered by what? 40. Visinge on road portant Features Isplay vindows with blact black glass are three 40 lists at the roof line ws this building as a groce open.) ont and Outbuildings	k carrara glass to the sides and above. light windows with slip sills and three brick bery and dry goods store. 1890,1894,1899, no only. The 1935 city directory listed the grocery
41. Distance from and fronto 42. Further Description of Imprecessed entry flanked by di Above the store sign on the panels and corbelled denta 43. History and Significance The earliest map - 1885 - sho change. 1908, 1914, 1926, 1 as Ekenberger and Dent. (cc 44. Description of Environme 45. Sources of Information Sanborn Maps, G. Craddoci	gered by what? 40. Visinge on road contant Features splay vindows with blact black glass are three 40 lills at the roof line ws this building as a groce 934 show grocery store or cont.) ont and Outbuildings 46. Prepared by Mary Aue Mitchell	k carrara glass to the sides and above. light windows with slip sills and three brick bery and dry goods store. 1890,1894,1899, no only. The 1935 city directory listed the grocery
41. Distance from and fronto 42. Further Description of Imprecessed entry flanked by di Above the store sign on the panels and corbelled denta 43. History and Significance The earliest map - 1885 - sho change. 1908, 1914, 1926, 1 as Ekenberger and Dent. (cc 44. Description of Environme 45. Sources of Information Sanborn Maps, G. Craddool	gered by what? 40. Visinge on road portant Features Isplay vindows with blact black glass are three 40 lists at the roof line ws this building as a groce open.) ont and Outbuildings	k carrara glass to the sides and above. light windows with slip sills and three brick bery and dry goods store. 1890,1894,1899, no only. The 1935 city directory listed the grocery

#36

105 North Washington

- 43 Circa 1950 the stone trim was removed and the windows were made smaller.
- 44 City Directories, Telephone Books



10-15-001-07

1. No. 2. County	3. Location of Ne	egatives	4. Current Name(s)	
37 Audrain	MCRI		Trendies	_
5. Other Name(s)	6a. Townshi 6b. Rang	6c. Sectio	d. Street Address	7
Llewellyn Drugstore	T51N R9W	26	07 & 109 North Washington	
7. City or Town	7b. Vicini 8. Descriptio	n of Locatio	9. UTM Coordinates	
Mexico	Lot 7, Block	13 except N	20'	_
10a. Sit 10b. Buildin 10c. St	ructu 10d. Objec 11. Or	n National Re	egist 12. is it eligibi 13. Part (of Historic Distr
14. District Potenti 15. Name	e of District 16. 7	Thematic Cat	egory]
				_
17. Date(s) or Period	18. Style or Design	19. Arc	hitect or Engineer	
circa 1880				
20. Contractor or Builder	21. Original Use	22. Pre	sent Use	
	comrnercial	comm	ercial	•
23. Ownership	24. Owner's Name and	Address	25. Op	en to Publ
private	William Buckner Neate	, Jr., 4509 Sh	oram Court, Columbia	
26. Local Contact Person or	Organization	27. Oth	er Surveys in Which Included	7
Lura Williams	And the second s	n/a		ant
28. No. of Stori 29. Baseme	30. Foundation Materia	al 31. Wa	Il Construction	٦
2	brick	brick		-
Roof Type and Material	33a. No. of Bays, front	33b. No	o. of bays, side	7
flat/asphalt	4			
34. Wall Treatment	35. Plan Shape	36a. Cr	anges, addition (see 36b. Ch	anges, altered (see
brick	rectangular		✓	
Changes, moved (see 37a.	Condition, Interior	37b. Conditi	on, Exterior 38. Preservat	ion underw
39a. Endangere 39b. Endang	ered by what? 40. Visi	i ble from pul	DIIC road?	7
	~	<u> </u>		_
41. Distance from and front	age or road			
				-
42. Further Description of Ir	nportant Features			7
the company of the co		tucco and ti	ne display windows replaced	_
by a picture window. The s	econd story features co	rbelling, two	20 light casement windows,	
a brick panel and more cort	belling at the roofline. (cont.)		7
43. History and Significance The earliest map - 1885 - sho	ous a gracory and a dru	a ctoro 400	0 4006 4000 no change	
			istore until 1940 when part of	
it became a wallpaper store				_
44. Description of Environm	ent and Outbuildings			
45. Sources of Information	46. Prepared by	47. Ord	janization	
Sanborn Maps, G. Craddock			Mexico	
	sion Date(1		
3/4/2002				


#37

106 and 109 North Washington

- 42 remodeled in 1948.
- 43 It continued to serve as a drugstore under various owners until circa 1990.
- 45 City Directories, "A Gathering of Our Days" by Leta Hodge



1. No. 2. County	3. Location of Ne	egatives 4. Current Name(s)	
38 Audrain	MCRI	World Finance Corporation	
5. Other Name(s)	6a. To wnship 6b. Rang	6c. Sectio 6d. Street Address	
	T51N R9W	26 111 North Washington	
7. City or Town	7b. Vicinit 8. Description	n of Location 9. UTM Coordinates	
Mexico	N 20' of Lot 7		
10a. Site 10b. Buildin 10c.	Structur 10d Obje 11. O	n National Register 12. Is it eligible 13. Part	of Historic District
14. District Potential 15. Na	me of District 16.7	Thematic Category	The second
17. Date(s) or Period	18. Style or Design	19. Architect or Engineer	<u> </u>
circa 1880			
20. Contractor or Builder	21. Orginal Use	22. Present Use	
	commercial	commercial	
23. Ownership	24. Ovner's Name and	Address 25. O	pen to Publi
private	Leonatti & Baker, 123 Ed	ast Jackson, Mexico MO 65265	
26. Local Contact Person o	or Organization	27, Other Surveys in Which included	
Lura Williams		n/a	
28. No. of Stories 29. Basem	en 30. Foundation Materia	al 31. Wall Construction	
2	brick	brick	Akri
Roof Type and Material	33a. No. of Bays, front	33b. No. of bays, side	
flat/asphalt	3		
34. Wall Treatment	35, Pk in Shape	36a. Changes, addition (see 36b. C	hanges, altered (se
stucco	rectangular		
Changes, moved (see 37	a. Condition, Interior	37b. Condition, Exterior 38. Preservat	ion underwa
			<u>. 1</u> 00. 105
39a. Endangere 39b. Enda		ble from public road?	
	<u> </u>		<u>L</u> The Fa
41. Distance from and from	tage on road		J i
42. Further Description of In			
		windows and cover with a cloth awning.	
ine brick deralls are obscu	rea by studed which was a	applied after a fire circa 1975.	
43. History and Significance			<u> </u>
The earlist map - 1885 - sho	ws a restaurant and board	ding house. 1890, 1894, no change. 1899,	
1908, dry goods and notion and televison shop.	ns. 1914, 1926, 1932, notion	ns. Circa 1970 this building housed a radio	
and televison snop. 44. Description of Environm	ent and Outbuildings	T	
The Description of Living China	<u> </u>		
			-
45. Sources of Information	46. Prepared by	47. Organization	┙ 、、、、、
Sanborn Maps, G. Craddo	the state of the s	City of Mexico	
48. Date 49. Rev		The state of the s	
2 /4 /0000	vision Dote(s		
3/4/2002	dsion Dcte(s		



1. No. 2. County	3. Location of Negatives 4. Current Name(s)
39 Audrain	MCRI Rusty's Bakery
5. Other Name(s)	6a. Township 6b. Rang 6c. Sectlo 6d. Street Address
00 .007 * 20 6.40 (Jac. 2007 * 20)	T51N R9W 26 113 North Washington
7. City or Town	7b. Vicinit 8. Description of Location 9. UTM Coordinates
Mexico	S 21' of Lot 6, Block 13
10a. Site 10b. Buildin 10c	Structur 10d. Obje 11. On National Register 12. Is it eligible 13. Part of Historic District
14. District Potenfial 15. No	lame of District
17. Date(s) or Period	18. Style or Design 19. Architect or Engineer
circa 1885	197 Alchirect of Engineer
20. Contractor or Builder	21. Original Use 22. Present Use
	commercial commercial
23. Ownership	24. Owner's Name and Address 25. Open to Publi
private	Davicl W. & Virginia Robertson, PO Box 551, Mexico MO 6526
26. Local Contact Person	or Organization 27. Other Surveys in Which included
Lura Williams	n/a
	men 30. Foundation Material 31. Wall Construction
2 🗀	brick brick
	The state of the s
Roof Type and Material	33a. No. of Bays, front 33b. No. of bays, side
flat/asphalt	3
flat/asphalt 34. Wall Treatment	3 35. Plan Shape 36a. Changes, addition (see 36b. Changes, altered a
flat/asphalt 34. Wall Treatment brick	35. Plan Shape 36a. Changes, addition (see 36b. Changes, altered (rectangular
flat/asphalt 34. Wall Treatment brick	3 35. Plan Shape 36a. Changes, addition (see 36b. Changes, altered a
flat/asphalt 34. Wall Treatment brick Changes, moved (see 3	35. Plan Shape 36a. Changes, addition (see 36b. Changes, altered a rectangular 37a. Condition, Interior 37b. Condition, Exterior 38. Preservation underwa
flat/asphalt 34. Wall Treatment brick	35. Plan Shape 36a. Changes, addition (see 36b. Changes, altered a rectangular 37b. Condition, Exterior 38. Preservation underwa
flat/asphalt 34. Wall Treatment brick Changes, moved (see 3: 39a. Endangere 39b. End	35. Plan Shape 36a. Changes, addition (see 36b. Changes, altered of rectangular 37b. Condition, Exterior 38. Preservation underwall angered by what? 40. Visible from public road?
flat/asphalt 34. Wall Treatment brick Changes, moved (see 3	35. Plan Shape 36a. Changes, addition (see 36b. Changes, altered of rectangular 37b. Condition, Exterior 38. Preservation underwall angered by what? 40. Visible from public road?
flat/asphalt 34. Wall Treatment brick Changes, moved (see 3: 39a. Endangere 39b. End	35. Plan Shape 36a. Changes, addition (see 36b. Changes, altered) rectangular 7a. Condition, Interior 37b. Condition, Exterior 38. Preservation underwallangered by what? 40. Visible from public road?
flat/asphalt 34. Wall Treatment brick Changes, moved (see 3: 39a. Endangere 39b. Endangere 31b. Endangere 32b.	35. Plan Shape 36a. Changes, addition (see 36b. Changes, altered a rectangular 37b. Condition, Exterior 38. Preservation underwalliangered by what? 40. Visible from public road?
flat/asphalt 34. Wall Treatment brick Changes, moved (see 3: 39a. Endangere 39b. Endangere 39b	35. Plan Shape 36a. Changes, addition (see 36b. Changes, altered a rectangular 37b. Condition, Exterior 38. Preservation underwal langered by what? 40. Visible from public road? Important Features anked by large canted display windows with metal sheathing above 1980. The second story features corbelling and three window along with
flat/asphalt 34. Wall Treatment brick Changes, moved (see 3: 39a. Endangere 39b. Endangere 31b. Endangere 32b.	35. Plan Shape 36a. Changes, addition (see 36b. Changes, altered a rectangular 37b. Condition, Exterior 38. Preservation underwa diangered by what? 40. Visible from public road? Important Features sinked by large canted display windows with metal sheathing above 1980. The second story features corbelling and three window along with troofline.
flat/asphalt 34. Wall Treatment brick Changes, moved (see 3 39a. Endangere 39b. Enda 41. Distance from and from 42. Further Description of III recessed central entry flar which was added circa 1 corbelled brick dentals at 43. History and Significance 1899, 1890, 1894, hardwar	35. Plan Shape 36a. Changes, addition (see 36b. Changes, altered of rectangular 37a. Condition, Inferior 37b. Condition, Exterior 38. Preservation underwa langered by what? 40. Visible from public road? Important Features sinked by large canted display windows with metal sheathing above 1980. The second story features corbelling and three window along with the roofline. Description of the second story features corbelling and three window along with the roofline. Description of the second story features corbelling and three window along with the roofline. Description of the second story features corbelling and three window along with the roofline. Description of the second story features corbelling and three window along with the roofline. Description of the second story features corbelling and three window along with the roofline. Description of the second story features corbelling and three window along with the roofline. Description of the second story features corbelling and three window along with the roofline. Description of the second story features corbelling and three window along with the roofline. Description of the second story features corbelling and three window along with the roofline. Description of the second story features corbelling and three window along with the roofline.
flat/asphalt 34. Wall Treatment brick Changes, moved (see 3 39a. Endangere 39b. Enda 41. Distance from and from 42. Further Description of III recessed central entry flar which was added circa 1 corbelled brick dentals at 43. History and Significance 1899, 1890, 1894, hardwar	35. Plan Shape 36a. Changes, addition (see 36b. Changes, altered of rectangular 37b. Condition, Exterior 38. Preservation underwa dangered by what? 40. Visible from public road? Important Features anked by large canted display windows with metal sheathing above 1980. The second story features corbelling and three window along with the roofline.
flat/asphalt 34. Wall Treatment brick Changes, moved (see 3 39a. Endangere 39b. Enda 41. Distance from and from 42. Further Description of III recessed central entry flar which was added circa 1 corbelled brick dentals at 43. History and Significance 1899, 1890, 1894, hardwar goods, and notions. From	35. Plan Shape 36a. Changes, addition (see 36b. Changes, altered of rectangular 37a. Condition, Interior 37b. Condition, Exterior 38. Preservation underwa dangered by what? 40. Visible from public road? Important Features anked by large canted display windows with metal sheathing above 1980. The second story features corbelling and three window along with the roofline. Dee The store. 899, clothing, 1908, grocery. 1914, 1926, 1932, millinery, dry in circa 1940 to 1971 it was the Wester Auto Store.
flat/asphalt 34. Wall Treatment brick Changes, moved (see 3 39a. Endangere 39b. Enda 41. Distance from and from 42. Further Description of III recessed central entry flar which was added circa 1 corbelled brick dentals at 43. History and Significance 1899, 1890, 1894, hardwar	35. Plan Shape 36a. Changes, addition (see 36b. Changes, altered of rectangular 37a. Condition, Interior 37b. Condition, Exterior 38. Preservation underwa dangered by what? 40. Visible from public road? Important Features anked by large canted display windows with metal sheathing above 1980. The second story features corbelling and three window along with the roofline. Dee The store. 899, clothing, 1908, grocery. 1914, 1926, 1932, millinery, dry in circa 1940 to 1971 it was the Wester Auto Store.
flat/asphalt 34. Wall Treatment brick Changes, moved (see 3 39a. Endangere 39b. Enda 41. Distance from and from 42. Further Description of III recessed central entry flar which was added circa 1 corbelled brick dentals at 43. History and Significance 1899, 1890, 1894, hardwar goods, and notions. From	35. Plan Shape 36a. Changes, addition (see 36b. Changes, altered of rectangular 37a. Condition, Interior 37b. Condition, Exterior 38. Preservation underwa dangered by what? 40. Visible from public road? Important Features anked by large canted display windows with metal sheathing above 1980. The second story features corbelling and three window along with the roofline. Dee The store. 899, clothing, 1908, grocery. 1914, 1926, 1932, millinery, dry in circa 1940 to 1971 it was the Wester Auto Store.
flat/asphalt 34. Wall Treatment brick Changes, moved (see 3: 39a. Endangere 39b. Enda 41. Distance from and from 42. Further Description of livecessed central entry flat which was added circa 1 corbelled brick dentals at 43. History and Significance 1899, 1890, 1894, hardwar goods, and notions. From 44. Description of Environn	35. Plan Shape 36a. Changes, addition (see 36b. Changes, altered a rectangular 37b. Condition, Exterior 38. Preservation underwal sangered by what? 40. Visible from public road? Important Features anked by large canted display windows with metal sheathing above 1980. The second story features corbelling and three window along with the roofline. The second story features are store. 899, clothing, 1908, grocery. 1914, 1926, 1932, millinery, dry in circa 1940 to 1971 it was the Wester Auto Store. The second story features corbelling and three windows along with the second story features corbelling and three windows along with the second story features corbelling and three windows along with the second story features corbelling and three windows along with the second story features corbelling and three windows along with the second story features corbelling and three windows along with the second story features corbelling and three windows along with the second story features corbelling and three windows along with the second story features corbelling and three windows along with the second story features corbelling and three windows along with the second story features corbelling and three windows along with the second story features corbelling and three windows along with the second story features corbelling and three windows along with the second story features corbelling and three windows along with the second story features corbelling and three windows along with the second story features corbelling and three windows along with the second story features corbelling and three windows along with the second story features are second story features.
flat/asphalt 34. Wall Treatment brick Changes, moved (see 3 39a. Endangere 39b. Enda 41. Distance from and from 42. Further Description of III recessed central entry flar which was added circa 1 corbelled brick dentals at 43. History and Significance 1899, 1890, 1894, hardwar goods, and notions. From	35. Plan Shape 36a. Changes, addition (see 36b. Changes, altered a rectangular 37a. Condition, Interior 37b. Condition, Exterior 38. Preservation underwa dangered by what? 40. Visible from public road? Important Features Inked by large canted display windows with metal sheathing above 1980. The second story features corbelling and three window along with the roofline. The store is 899, clothing. 1908, grocery. 1914, 1926, 1932, millinery, dry in circa 1940 to 1971 it was the Wester Auto Store. The store is 899, clothing. 1908, grocery. 1914, 1926, 1932, millinery, dry in circa 1940 to 1971 it was the Wester Auto Store. The store is 899, clothing. 1908, grocery. 1914, 1926, 1932, millinery, dry in circa 1940 to 1971 it was the Wester Auto Store.
flat/asphalt 34. Wall Treatment brick Changes, moved (see 3 39a. Endangere 39b. Enda 41. Distance from and from 42. Further Description of Ill recessed central entry flat which was added circa 1 corbelled brick dentals at 43. History and Significance 1899, 1890, 1894, hardwar goods, and notions. From 44. Description of Environn 45. Sources of Information Sanborn Maps, G. Craddo	35. Plan Shape 36a. Changes, addition (see 36b. Changes, altered a rectangular 37a. Condition, Interior 37b. Condition, Exterior 38. Preservation underwa dangered by what? 40. Visible from public road? Important Features Inked by large canted display windows with metal sheathing above 1980. The second story features corbelling and three window along with the roofline. The store is 899, clothing. 1908, grocery. 1914, 1926, 1932, millinery, dry in circa 1940 to 1971 it was the Wester Auto Store. The store is 899, clothing. 1908, grocery. 1914, 1926, 1932, millinery, dry in circa 1940 to 1971 it was the Wester Auto Store. The store is 899, clothing. 1908, grocery. 1914, 1926, 1932, millinery, dry in circa 1940 to 1971 it was the Wester Auto Store.



1. No.	2. Count	ty		3. Loca	ation of	Negativ	ves 4.	Current N	ame(s)		
40	Audrain			MCRI			С	inema Plus			
5. Other Na	ame(s)		6a. To	wnshi	6b. Ran	g 6c. S	ectio 6d.	Street Add	dress		
			T51N		R9W	26		North Wa	•	n	
7. City or T	own		7b. Vic	ini 8.	Descrip	tion of	Location	9. UTM C	oordina	tes	
Mexico						ot 6, Blo					
10a. SIt 10	b. Buildir	10c. Str	uctu	10d. Ob	iec 11.	On Nat	lonal Red	st. 12. is it	t eligibi	13. Part of His	toric Distr
				ز							
14. District	Potenti	15. Name	of Dis	trict	h	6 Them	atic Cate	nrv			
								, . ,			
17. Date(s)	or Period	1	18. Stv	le or D	esian		19 Archi	tect or Eng	ineer		
circa 1885	0 0.,00		15.50,		00.9		10.74 0.11	COU OF LINE	3111001		
20. Contrac	tor or Ri	ilder	21. Ori	ninal II	<u>. </u>		22. Prese	nt Hea			
20. Conta ac	coi oi be	ander	comm		30		commer				
23. Owners	hin				lama a					OF Ones to	Dubl
private	iiib		-			nd Addre		k 551, Mexic	CO MO 4	25. Open to	Publ
<u> </u>			L					·			
26. Local Co		rson or (organiz	ation				Surveys In	wnich i	nciuaea	
Lura Willia							n/a				
28. No. of S	tori 29.	<u>Baseme</u>		undati	on Mate	erial		Construction	on		
2	i		brick				brick				
Roof Type		rial	_	o. of Ba	ys, fror	nt	33b. No.	of bays, sid	le		
flat/asphal	lt		3								
34. Wall Tre			35. Pla	n Shap	е		36a. Char	nges, addit	lon (see		, altered (see
brick and r	netal she	athing	rectan	gular						\checkmark	
Changes, n	noved (se	e 37a.	Condit:i	on, Int	erior	37b.	Condition	, Exterior	38.	Preservatio <u>n u</u>	nderw
					_						
39a. Endan	gere 39b	. Endang	ered b	y what	? 40.\	/isible fr	om publi	c road?			
					~						
41. Distanc	e from ar	nd fronta	ge on	road							
					,						
42. Further	r Descript	tion of in	nportair	nt Feat	ures						
central en	try flanke	d by dis	olay wir	ndows	and co						
The secon	d story is	covered	with v	ertical	metal s	heathin	g that wa	is added ci	rca 1975	i.	
43. History	and Sign	ificance		_							
1885, 1890,											
clothing st	-	narily Ne	ate Clo	thing (co.) from	n 1908 t	o 1980. It	was a spoi	rting go	ods	
store until		nvironm	ent ario	l Outbi	ildinge	<u> </u>					
44. Descrip	JUDIT OF E	I I WIT OF IT I I	crit ai l	Culbl	anuniys) 					
45. Source			46. Pre				47. Organ	nization			
Sanborn M	laps, G. Ci	raddock	Mary A	lue Mit	chell		City of N	lexico			
48. Date		49. Revis	on Dat	e(•				
3/4/2002	i			_							



1, No. 2. County 41 Audrain	MCRI	ation of Ne	gauve)	4. Current Name(s) Pro Nails		
5. Other Name(s)	6a. Township	6b. Range	6c. Section	6d. Street Address		
	T51N	R9W	26	119 North Washington		
7. City or Town	7b. Vicinit 8.	I Description	of Location	9. UTM Coordina	res .	
Mexico	and the same of th	The second secon	5, Biock 13			
1 Oa. Site 1 Ob. Building 1 Oc.				Register? 12 Is it eligible	2 1 3. Part of Historic District	7
						J
14. District Potential? 15. Na	me of District	16.	Thematic Ca	itegory		india. Kabupatèn
✓			in in the second			n is Hill
17. Date(s) or Period	18. Style or D	esign	19.7	Architect or Engineer		14. 14.
circa 1885						
20. Contractor or Builder	21, Original U	lse -	22. P	resent Use		
	commercial			nercial		
23. Ownership	24. Owner's 1	lame and A	\ddress	etan Sine and	25. Open to Public	
private	radional designation of the second	Comments of the Comments of th		916, Moberly MO 652	the state of the s	
26. Local Contact Person or C		Car State		ther Surveys in Which Inc		
Lura Williams		<u> </u>	n/a		Production	
28. No. of Storle 29. Baseme	nt 30. Foundatio	n Material	31.0	Wall Construction		
2	brick		brick			
Roof Type and Material	33a. No. of B	ws. front	33h.	No. of bays, side		
flat/asphalt	3					
34. Wall Treatment	35. Plan Shape		362	Changes, addition (see 4)	2) 36b. Changes, altered (see	421
brick and stucco	rectangular					•
Changes, moved (see 42) 37			37h Condi	tion, Exterior 38	Preservation underway?	
39a. Endangered 39b. Endar	opered by what?	40 Vi	I sible from pu	blic road2		
		✓				
41. Distance from and frontag	e on road					
	<u> </u>		odnia i Zbarillaisi i i			
42. Further Description of Imp	ontant Evatures	4 9534 4.5 .	MAR PAR			
recessed entry with display win		reen glass r	oanels and fea	sturing a cloth awning. T	he second	ia de la como. Provincia
story has two windows that ha						
dental at roofline.	Section 1					
43. History and Significance		1000 -1	l-! 100A	f 1000		
The earlist map - 1885 - show store. Starting in 1908 and coulding starting in 1946.						
44. Description of Environmen	nt and Outbuilding					
The Section of Standard				<u> </u>		
						e Bart
				daniel was service and the ser	Managaran and the additional state of the st	
45. Sources of Information	46. Prepared I			Organization S		٠.
Sanborn Maps, G. Craddock,		cnell	City	of Mexico		
	dsion Date(s)					
3/4/2002						



1. No. 2. County	3. Location	n of Negatives 4. Current Name(s)
42 Audrain	MCRI	Golden Palace
i. Other Name(s)		Range 6c. Section 6d. Street Address
	T51N R9	W 26 123 North Washington
. City or Town	7b. Vicinit 8. Des	cription of Location 9. UTM Coordinates
1exico	N 40'	of Lot 5, Block 13
Oa. Site 10b. Building 10c.	Structure 10d. Objec	11. On National Register? 12. Is it eligible? 13. Part of Historic District
4. District Potential? 15. N	ame of District	16, Thematic Category
1		
7. Date(s) or Period	18, Style or Design	n 19. Architect or Engineer
circa 1890		
20. Contractor or Builder	21. Original Use	22. Present Use
	commercial	commercial
3. Ownership	24. Owner's Name	e and Address 25. Open to Public
orivate	Bihn Van & Mua	Thi Truong, 123 North Washington, Mexico MO ✓
6. Local Contact Person or	Organization	27. Other Surveys in Which Included
Lura Williams	The second secon	n/a
28. No. of Storle 29. Basem	ent 30. Foundation M	faterial 31. Wall Construction
2	brick	brick
loof Type and Material	33a. No. of Bays,	front 33b. No. of bays, side
lat/asphalt	5	5
34. Wall Treatment	35. Plun Shape	36a. Changes, addition (see 42) 36b. Changes, altered (see 42)
painted brick	rectangular	
Changes, moved (see 42) 3	7a. Condition, Interior	37b. Condition, Exterior 38. Preservation underway?
19a. Endangered 39b. Enda	ngered by what?	40. Visible from public road?
		V
11. Distance from and fronta	ge on road	
12. Further Description of In	portant Fratures	
		s and featuring a decorative tile floor. The second story
	overed by wooden shut	ters, and ten brick panels and brackets and dentils at the
oof line.	787478 <u>85</u> 7 34867	
13. History and Significance The first man it appears on -	1890 - shows a drug a	nd dress making store. 1894, 1899, and 1908 show a
		d furniture. This was the JC Penney's Department Store
rom 1929 until circa 1990.		
4. Description of Environme	ent and Outbuildings	
15. Sources of Information	46. Prepared by	47. Organization
Sanborn Maps, G. Craddock,		
18. Date 49. Re	vision Date(s)	
3/4/2002		



1. No. 2. County	3. Location o	of Negatives 4. Current Name(s)	
04 Audrain	MCRI	After Five Nails & Boutique	
5. Other Name(s)	6a. Township 6b. Ro	ang 6c, Sectio 6d. Street Address	
	T51N R9W	26 203 North Washington	
7. City or Town	7b. Vicinit 8. Descri	ption of Location 9. UTM Coordinates	
Mexico	East 27'	of Lot 1, Block 16	
10a, Site 10b. Buildin 10c. St	ructur 10d Obje 1	1. On National Register 12. Is it eligible 13. Part of	of Historic District
14. District Potential 15. Nam	ne of District	16. Thematic Category	
17. Date(s) or Period	18, Style or Design	19. Architect or Engineer	
circa 1940			
20. Contractor or Builder	21. Original Use	22. Present Use	
	commercial	commercial	/ xig = 1
23. Ownership	24. Olyner's Name o		oen to Publi
pivate	Dan Erdel, 103 Wes	t Monroe, Mexico MO 65265	
26. Local Contact Person or	Organi:ation	27. Offier Surveys in Which Included	
Lura Williams		n/a	
28. No. of Storles 29. Baseme	n 30. Foundation Ma	terial 31, Wall Construction	
1	brick	brick	
Roof Type and Material	33a. No. of Bays, fro	ont 33b. No. of bays, side	
flat, asphalt	3		
34. Wall Treatment	35. Pkan Shape	36a. Changes, addition (see 36b. Ch	anges, altered (see
brick	rectangle		
Changes, moved (see 37a.	. Condition, Interior	37b. Condition, Exterior 38. Preservation	on underwa
39a, Endangere 39b, Endan	gered by what? 40.	. Visible from public road?	
	V		
41. Distance from and fronta	nge on road		
42. Further Description of Imp			
single door with 6 lights over	two panels, double p	oicture window with slip sill	
43. History and Significance			
		part of the Sam Morris Furniture Store circa 1955.	
It became a beauty salon c	ırca 1985. It has bee	n the After Five Nails & Boutique since 1995.	
44. Description of Environme	nt and Outbuildinas		
AE Common of lafa	M Danie In	A7 Occopylation	
45. Sources of Information Sanborn Maps, D. Erdel	46. Prepared by Mary Aue Mitchell	47. Organization City of Mexico	House and the
	ion Date(s		
48. Date 49. Revis	IOH DCIG(6)		



la Na la Calaba	18 18 18 18 18 18 18 18 18 18 18 18 18 1		The state of the state of the
1. No. 2. County 03 Audrain	3. Location of N	Negatives 4. Current Name(s) Manpower	
5. Other Name(s)	T51N R9W	6c. Sectio 6d. Street Address 26 205 North Washington	
7. City or Town	7b. Vicinit 8. Description		
Mexico		ot 1, Block 16	
10a, Site 10b, Buildin 10c.	Structur 10d, Obje 11.	On National Register 12. Is it eligible 13	. Part of Historic District
14. District Potential 15. No	ame of District 16	Thematic Category 7	للسلام
<u>V</u>	and the contract of the contra	7. Carlot 10 11 - 2. Carlot 2 10 10 10 10 10 10 10 10 10 10 10 10 10	
17. Date(s) or Period	18. Style or Design	19. Architect of Engineer	
circa 1940			
20. Contractor or Builder	21. Original Use	22. Present Use	
<u></u>	commercial	commercial	
23. Ownership	24. Ovner's Name and		25. Open to Publi
private	Dan Erdel, 103 West M	lonroe, Mexico MO 65265	∀
26. Local Contact Person o	or Organization	27. Other Surveys in Which Inclu	ded
Lura Williams		n/a	
28. No. of Stories 29. Basen	nen 30. Frundation Mater	ial 31. Wall Construction	Title (March 1997)
1	brick	brick	
Roof Type and Material	33a. No. of Bays, front	33b. No. of bays, side	
flat, asphalt	1		
34. Wall Treatment	35, Plan Shape	36a. Changes, addition (see 3	lób. Changes, altered (see
painted brick	rectangular		
Changes, moved (see 37	a. Condition, Interior	37b. Condition, Exterior 38. Pre	servation underwa
Light State of			78
39a. Endangere 39b. Endo	angered by what? 40 Vi	sible from public road?	
	V		
41. Distance from and from	tage on road		
42. Further Description of Ir	nnortant Features	The state of the s	
single door with 6 lights over		dow with slip sill	
angle door will ongine ov	or two partolo, plotaro with	acti wiii sap siii	
43. History and Significance			
built as office building, late building since circa 1990.	er used as part of the Sam	Morris Furniture Store. It has been and	office
puliding since circa 1990.			
44. Description of Environm	ent and Outbuildings		
45. Sources of Information	46. Prepared by	47. Organization	
Sanborn Maps, D. Erdel	Mary Aue Mitchell	City of Mexico	
	vision Date(s		
02/18/02			



1. No. 2. County	3. Location of Negati	ves 4. Current Name(s)	
02 Audrain	MCRI	207 North Washington	
5. Other Name(s)	6a. Township 6b. Rang 6c.	Sectio 6d. Street Address	
Craft Tech Custom Homes	T51N R9W 26	207 North Washington	
7. City or Town	7b. Vicinit 8. Description of I	ocation 9. UTM Coordinates	
Mexico	West 30 ' of Lot 1,	Block 16	
10a. Site 10b. Buildin 10c.	Structur 10d. Obje 11. On No	tional Register 12. Is it eligible 13. Part	of Historic District
14. District Potential 15. Na	me of District 16. Then	natic Category	
Y *			
17. Date(s) or Period	18. Style or Design	19. Architect of Engineer	
circa 1905			
20. Contractor or Builder		22. Present Use	
AND COLUMN TO SERVICE SERVICES	commercial	commercial	
23. Ownership	24. Ovner's Name and Add		pen to Publi
private	Dan Erdel, 103 West Monroe		
26. Local Contact Person o	or Organization	27. Other Surveys in Which Included	
Lura Williams		n/a	
	en 30. Foundation Material	31. Wall Construction	
5	brick	brick	
Roof Type and Material	33a. No. of Bays, front	33b. No. of bays, side	
flat, asphalt	lo T	5	
34. Wall Treatment	35. Pkin Shape	36a. Changes, addition (see 36b. C	hanges, altered (see
paint over brick	rectangular		
Changes, moved (see 37)	a. Condition, Interior 37b	. Condition, Exterior 38. Preserva	tion underwa
			_
39a. Endangere 39b, Enda	ngered by what? 40. Visible ti	om public road?	
			71 .65
41. Distance from and front	idge on jedd		
42. Further Description of Im	vocatorat Econtinos		
		hed windows with lug sills. There is a	
		are boarded up are intact underneath	١.
3200 Yago Salar Sagan Wand.	Additional Constitution, NEW Michigan		
43. History and Significance			J.
	ide and fur processing. In 1914 is well. Circa 1945 it no longer t	and 1926 no charge. In 1932 it nad hides but was part of the Sam	
Morris Furniture Store. In the			
44. Description of Environm	ent and Outbuildings		J
45. Sources of Information	46. Prepared by	47. Organization	
Sanborn Maps, D. Erdel	Mary Aue Mitchell	City of Mexico	
48. Date 49. Rev	rision Date(s		
02/18/02			
	and the second s	THE REPORT OF THE PROPERTY OF	The state of the s

#2

207 North Washington

43. it housed Craft Tech Custom Homes. Currently vacant and for rent (2002).





10-15-001-080

1. No.	2. Coun	ty		3. LOC	atior	of No	egativ	es	4. C	ur	rent Nam	e(s)			
53	Audrain			MCRI					Mel	ah	ın Insuran	ce Ag	ency	_	
5. Other Na	me(s)		6a. To	wnshi	6b. F	Rang	6c. Se	ectio (d. St	re	et Addres	SS		L_	
		İ	T51N		R9W		26	T.	101 S	Οl	ıth Washii	ngtor	1	_	
7. City or T	own		7b. V	cini 8.	Desc	riptic	n of L	ocatio	n !	9.	UTM Coor	dinat	es]	
Mexico				N	20.63	of L	ots 7 8	& 8, Blc	ck					•	
10a. SIt 10	b. Buildi	n 10c. Str	uctu	10d. Ol	ojec	11. 0	n Nati	onal R	egist	: 1	12. Is it ell	gibl	13. Part of	Historic Distr	-
			ĺ				-								
14. District	Potenti	15. Name	of Di	strict		16.	Thema	atic Ca	tego	ry					
Y															
17. Date(s)	or Perio	d c	18. St	yle or C	esig	n		19. Arc	hite	ct	or Engine	er			
circa 1885			Roma	nesqu	e infl	uence	9							•	
20. Contrac	tor or B	uilder	21. Or	iginal L	Jse			22. Pre	esent	t U	Ise				
			comr	nercial				comm	eric	al				•	
23. Owners	hlp		24. O\	vner's l	Name	and	Addre	SS					25. Ope	n to Publ	
private			Robe	rt & He	en F	enlon	, PO B	ox 26,	Mexi	CC	MO 6526	5	✓		
26. Local Co	ontact Pe	erson or (Organ	zation				27. Oth	er Su	īυ	eys in Wr	ich Ir	ncluded		
Lura Willia	ms							n/a							
28. No. of S	itori 29.	Baseme	30. F	oundat	ion N	lateri	al ,	31. Wa	all Co	n	struction				
2	✓		ston	9				stone							
Roof Type	and Mate	erial	33a. N	o. of B	ays, f	ront		33b. N	o. of	ba	ays, side				
flat/asphal	t		2					11							
34. Wall Tre	atment	_	35. Pl	n Shap	е			36a. CI	nang	es	, addition	(see	36b. Chai	nges, altered	(see
brick and s	tone		recta	ngular			į						✓	•	
Changes, n	noved (se	e 37a.	Condi	ion, In	terio	r	37b. (Condit	ion, I	Ex	terlor	38. F	reservation	on underw	
39a. Endan	gere 39t	. Endang	ered I	y what	t? 4	0. Visi	ble fr	om pu	blic r	0	ad?				
					٧	<u>.</u>								-	
41. Distanc	e from a	nd fronta	ge or	road					han desta						
														-	
42. Further															
recessed c	orner er	itry flank	ed by	display	wind	low a	nd co	vered v	with	a I	fixed woo	d shii	ngled	-	
awning. T	he Jackso	on Street	side (of the b	uildi	ng fea	atures	stone	bloc	KS	and arch	ed wi	indow		
43. History			· way:	. A uel	, vi at	146 DE		30 30	yai di	LG	J (COITE.)]	
The earlies			s a ci	ar sto	re, sa	loon	and p	hotogi	aphe	er'	s studio.	1890.	1894,	ı	
1899, it he	ld a salod	n, photo	graph	er's stu	Jdio,	and b	illiard	parlo	Ву	19	907 it was	had a	saloon		
and billiar							ies. (c	ont.)						1	
44. Descrip	tion of E	nvironm	ent ar	a outb	ullal	ngs								Ţ	
1															
														_	
45. Source		_	وسنسيب	epared				47. Or	ganiz	zat	tion		en e]	
Sanborn N	laps, G. C	raddock	Mary	Aue Mi	tche	II	i	City o	f Me	Xic	co				
48. Date		49. Revis	ion Da	te('	•							
3/13/2002															

#53

101 South Washington

- 42. the first and second stories. The second story features evenly spaced 1/1 double hung windows with transoms and stone quions at the corners. Above the windows are corbelled brick dentals with pilasters at the front corners. There is a belt course of record above the dentals. The fixed canopy was added circa 1980.
- 43. It was Smith Brothers Grocery until circa 1940. In the 1940's it became an office building housing primarily dentists and insurance agents.









1. No. 2. County	3. Location of Neg	atives 4. Current Name(s)
54 Audrain	MCRI	Melody's Quality Jewelry
5. Other Name(s)	6a. Township 6b. Range	6c. Section 6d. Street Address
	T51N R9W	26 103 South Washington
7. City or Town	7b. Vicinit 8. Description	of Location 9. UTM Coordinates
Mexico	S 22.4' of Lot	s 7 & 8, Block 7
10a, Site 10b, Building 10c.	Structure 10d. Objec 11. O	n National Register? 12. Is it eligible? 13. Part of Historic Di
14. District Potential? 15. N	ame of District 16.1	Fhematic Category
✓		
17. Date(s) or Period	18. Style or Design	19. Architect or Engineer
circa 1885		
20. Contractor or Builder	2.1. Original Use	22. Present Use
	commercial	commercial
23. Ownership	24. Owner's Name and Ad	ldress 25. Open to Public
private		outh Washington, Mexico MO 65265
26. Local Contact Person or		27. Other Surveys in Which Included
Lura Williams		n/a
28. No. of Storie 29. Basem	ent 30. Foundation Material	31. Wall Construction
2	stone	brick
Roof Type and Material	33a. No. of Bays, front	33b. No. of bays, side
flat/asphalt	4	
34. Wall Treatment	35. Plan Shape	36a. Changes, addition (see 42) 36b. Changes, altere
brick	rectangular	
Changes, moved (see 42) 3		37b. Condition, Exterior 38. Preservation underway
	C. Solvenskij interior	
39a. Endangered 39b. Enda	ngered by what? 40 Visi	ble from public road?
	V	
41. Distance from and fronta	ge on road	
TI. SAMELE IVIII GINA II VIII	**************************************	
42. Further Description of In	nortant Features	
		y display windowswith white brick below them.
A wood shingle awning runs	the length of the fascade. The se	econd story features 2 12/12 double hung
windows and brick corbelling	at the roofline.	
43. History and Significance	مام مراه مسا	to a la sometima de proprieta de la 1020 de la la
		store. It remained one until circa 1920 when it rrell Jewelry Store. Awning added circa 1980.
became a snoe store. Trom	LIICU I / II/ CO I / / L IC WGS WO	iner, jenera, store. Arming added ened 1700.
44. Description of Environme	ent and Outbuildings	
45. Sources of Information	46. Frepared by	47. Organization
Sanborn Maps, G. Craddock,		City of Mexico
	evision Date(s)	
48. Date 49. Re 3/15/2002	ADOL MEO	
3/13/2002		



1. No. 2. County	3. Location of Ne	egatives 4. Current Name(s)	
55 Audrain	MCRI	Total Printing	
5. Other Name(s)	6a Townshin Ah Range	6c. Section 6d. Street Address	
	T51N R9W	26 105 South Washington	
7. City or Town		n of Location 9, UTM Coordinates	
Mexico		ots 7 & 8, Block 7	
10a, Site 10b, Building 10c.		On National Register? 12. Is it eligible? 13. Part of	Historic District
14. District Potential? 15. N	ame of District 16	. Thematic Category	
17. Date(s) or Period	18. Style or Design	19. Architect or Engineer	
circa 1885			
20. Contractor or Builder	21. Original Use	22. Present Use	
	commercial	commercial	
23. Ownership	24. Owner's Name and	Address 25. One	n to Public
private		15534 Highway]], Mexico MO 65265	
26. Local Contact Person or 1	Organization	27. Other Surveys in Which Included	
Lura Williams		n/a	
28. No. of Storie 29. Basem	ent 30. Foundation Material	31. Wall Construction	
2 📗	stone	brick	
Roof Type and Material	33a. No. of Bays, front	33b. No. of bays, side	
flat/asphalt	3		
34. Wall Treatment	35. Plan Shape	36a. Changes, addition (see 42) 36b. Chan	ges, altered (see 42)
brick	rectangular		
Changes, moved (see 42) 37	7a, Condition, Interior	37b. Condition, Exterior 38. Preservation	underway?
39a. Endangered 39b. Enda	ngered by what? 40, V	sible from public road?	
41. Distance from and fronta	ge on toail		
42. Further Description of Im			
		windows between them. A fixed wood shingle	
awning runs the length of the corbelled brick dentals at the		atures 3 boarded over arched windows and	
43. History and Significance	-connect		
	ows it to be a dry goods store	. By 1890 it sold shoes and boots as well as dry	
		94 and remained one until circa 1970.	
44. Description of Environme	ent and Oatbulldings	美 學的學術學學學學學學學學學學學學學學學學學學學學學學學學學學學學學學學學學學	
45. Sources of Information	46. Prepared by	47. Organization	
Sanborn Maps, G. Craddock,	Ci Mary Aue Mitchell	City of Mexico	
48. Date 49. Re	vision Date(s)		
3/15/2002			



1. No. 2. County	3. Location of Negat	ives 4. Current Name(s)
56 Audrain	MCRI	Vic's Place
5. Other Name(s)	6a. Townshi 6b. Rang 6c. s	Sectio 6d. Street Address
	T51N R9W 26	107 South Washington
7. City or Town	7b. Vicini 8. Description of	Location 9. UTM Coordinates
Mexico	W 114' of Lots 7	
10a. Sit. 10b. Buildin 10c. St	ructu 10d. Objec 11. On Na	tional Regist 12. Is it eligibi 13. Part of Historic Distr
14. District Potenti 15. Nam	e of District 16. Then	natic Category
V		
17. Date(s) or Period	18. Style or Design	19. Architect or Engineer
circa 1885	to copie of peoign	10.74 different Engineer
20. Contractor or Builder	21. Original Use	22. Present Use
20. CONTRACTOR OF BUILDER	commecial	commercial
07 Oumorchin		
23. Ownership private	24. Owner's Name and Addi	Washington, Mexico MO 65265 ✓
		1
26. Local Contact Person or	Organization	27. Other Surveys in Which Included
Lura Williams		n/a
28. No. of Stori 29. Baseme		31. Wall Construction
2	storie	brick
Roof Type and Material	33a. No. of Bays, front	33b. No. of bays, side
flat/asphalt	4	
34. Wall Treatment	35. Plan Shape	36a. Changes, addition (see 36b. Changes, altered (see
painted brick	rectangular	
Changes, moved (see 37a.	Condition, Interior 37b	. Condition, Exterior 38. Preservation underw
39a. Endangere 39b. Endan	gered by what? 40. Visible 1	from public road?
	✓	
41. Distance from and front	tage on road	
42. Further Description of I	mportant Features	
two entries, one recessed	and flanked by display windo	ws. A boarded over transom runs the
length of the fascade. The	second story features 4 arch	ned windows which have been
	ng windows and corbelled br	rick dentais at the rootline.
43. History and Significance		00 shows a meat store and by 1899 it
contained offices on the se	econd floor, 1908 it was a bal	kery and by 1914 it had become a
second hand store. In 1929		
44. Description of Environn	nent and Outbuildings	
		
45 Courses of information	46 Prenared by	47. Organization
45. Sources of Information Sanborn Maps, G. Craddock		City of Mexico
		City of Monico
	sion Date(
3/15/2002		

#56

105 South Washington

42. In 1935 it became Worrell's Jewelry store. From circa 1965 to 1975 it was Burchfield Radio and Television.



Audrain MCRI 108 South Washington 5. Other Name(s) 6a. Township 6b. Range 6c. Section 6d. Street Address Hawaiian Shaved Ice 751N R9W 26 108 South Washington 7. City or Town 7b. Vicinit 8. Description of Location 9. UTM Coordinates Mexico SW 1/4 of Lot 5, Block 8 10a. Site 10b. Building 10c. Structure 10d. Objec 11. On National Register? 12. is it eligible? 13. Part of Historic District 14. District Potential? 15. Name of District 16. Thematic Category 17. Date(s) or Period 18. Style or Design 19. Architect or Engineer circa 1940 20. Contractor or Builder 21. Original Use 22. Présent Use commercial vacant
Hawaiian Shaved Ice T51N R9W 26 108 South Washington 7. City or Town 7b. Vicinit 8. Description of Location 9. UTM Coordinates Mexico SW 1/4 of Lot 5, Block 8 10a. Site 10b. Building 10c. Structure 10d. Objec 11. On National Register? 12. Is it eligible? 13. Part of Historic District 14. District Potential? 15. Name of District 16. Thematic Category 17. Date(s) or Period 18. Style or Design 19. Architect or Engineer 1940 20. Contractor or Builder 21. Original Use 22. Present Use
76. Vicinit 8. Description of Location 9. UTM Coordinates Mexico SW 1/4 of Lot 5, Block 8 10a. Site 10b. Building 10c. Structure 10d. Objec 11. On National Register? 12. Is it eligible? 13. Part of Historic District 14. District Potential? 15. Name of District 16. Thematic Category 17. Date(s) or Period 18. Style or Design 19. Architect or Engineer circa 1940 20. Contractor or Builder 21. Original Use 22. Present Use
Mexico SW 1/4 of Lot 5, Block 8 10a. Site 10b. Building 10c. Structure 10d. Objec I 1. On National Register? 12. Is it eligible? 13. Part of Historic District I 14. District Potential? 15. Name of District I 16. Thematic Category 17. Date(s) or Period 18. Style or Design 19. Architect or Engineer circa 1940 20. Contractor or Builder 21. Original Use 22. Present Use
10a. Site 10b. Building 10c. Structure 10d. Objec 11. On National Register? 12. Is it eligible? 13. Part of Historic District 14. District Potential? 15. Name of District 16. Thematic Category 17. Date(s) or Period 18. Style or Design 19. Architect or Engineer circa 1940 20. Contractor or Builder 21. Original Use 22. Present Use
14. District Potential? 15. Name of District 16. Thematic Category 17. Date(s) or Period 18. Style or Design 19. Architect or Engineer circa 1940 20. Contractor or Builder 21. Original Use 22. Present Use
14. District Potential? 15. Name of District 16. Thematic Category 17. Date(s) or Period 18. Style or Design 19. Architect or Engineer circa 1940 20. Contractor or Builder 21. Original Use 22. Present Use
217. Date(s) or Period 18. Style or Design 19. Architect or Engineer circa 1940 20. Contractor or Builder 21. Original Use 22. Present Use
17. Date(s) or Period 18. Style or Design 19. Architect or Engineer circa 1940 20. Contractor or Builder 21. Original Use 22. Present Use
circa 1940 20. Contractor or Builder 21. Original Use 22. Present Use
20. Contractor or Builder 21. Original Use 22. Present Use
commercial vacant such as the commercial such
23. Ownership 24. Owner's Name and Address 25. Open to Public
private R. Newton & Joyce Riley, 7 North 9th St., Columbia MO 65201
26. Local Contact Person or Organization 27. Other Surveys in Which Included
28. No. of Storie 29. Basement 30. Foundation Material 31. Wall Construction
1 brick brick
Roof Type and Material 33a. No. of Bays, front 33b. No. of bays, side
flat/asphalt 3
34. Wall Treatment 35. Plan Shape 36a. Changes, addition (see 42) 36b. Changes, altered (see 42)
brick rectarigular
Changes, moved (see 42) 37a. Condition, Interior 37b. Condition, Exterior 38. Preservation underway?
59a. Endangered 39b. Endangered by what? 40. Visible from public road?
F1. Distance from and frontage on road
12. Further Description of Important Features central recessed entry flanked by display windows. The windows and door are topped by a fixed wood
shingled awning. A double row of dentals runs the length of the fascade below the cornice.
13. History and Significance
This building was first used as a restaurant. Next it held an office and was later used for storage before becoming the Hawaiian Shaved Ice store.
Accounting the formulation for store.
14. Description of Environment and Outbuildings
15. Sources of Information 46. Prepared by 47. Organization
Sanborn Maps, G. Craddock, Cl Mary Aue Mitchell City of Mexico
18. Date 49. Revision Date(s)
5/6/2002



1. No. 2. County	3. Location of Neg	atives 4. Current Name(s)	
57 Audrain	MCRI	Sentimental Memories	
5. Other Name(s)		6c. Section 6d. Street Address	
Lakenan & Barnes	T51N R9W	26 109 South Washington	
7. City or Town	7b. Vicinit 8. Description		
Mexico	N 20' of S 34	' of Lot 8 & S 3 Lot 7, Block 7	
Oa. Site 10b. Building 10c	. Structure 10d. Objec 11. C	n National Register? 12. Is it eligible? 13. Part of	Historic District
	Ш		
4. District Potential? 15. N	lame of District 16.	Thematic Category	
4			
7. Date(s) or Period	18. Style or Design	19. Architect or Engineer	
1895	romanesque		
O. Contractor or Builder	21. Ciriginal Use	22. Present Use	
	commercial	commercial	
23. Ownership	24. Chwner's Name and A		en to Public
private	Susan McCulloch, 1100 S	outh Jefferson, Mexico MO 65265	
26. Local Contact Person or	Organization	27. Other Surveys in Which Included	
Lura Williams		n/a	
	nent 30. Foundation Material	31. Wall Construction	
2	stone	stone	
loof Type and Material	33a. No. of Bays, front	33b. No. of bays, side	
flat/asphalt	4		
54. Wall Treatment	35. Plan Shape	36a. Changes, addition (see 42) 36b. Cha	nges, altered (see 42)
stone	rectangular		
Changes, moved (see 42) 3	7a. Condition, Interior	37b. Condition, Exterior 38. Preservation	underway?
J. A. Carlotte			
39a. Endangered 39b. End		ble from public road?	
	V		
 Distance from and fronta 	age on road		
42. Further Description of In			
-		doors and a picture window on each side. The transoms and the center one of which is arched.	
The roofline has a decorative		and the center one of which is arched.	
43. History and Significance			
		890, a tailor shop, and 1894 a barber shop. It	
was extensively remodeled in floor at the entrance (cont.)	1 1895 and became an insuranc	e office. In addition to the stone fascade, a tile	
14. Description of Environm	ent and Crutbulldings		
45. Sources of Information	46. Prepared by	47. Organization	
Sanborn Maps, G. Craddock	Annual Committee of the	City of Mexico	
	evision Date(s)		
3/15/2002			

#57

- 109 South Washington
- 42. cornice with date carved on it. Below is carved the words" Lakenan & Barnes."
- 43. and a small safe were added inside. It was an office for insurance, real estate, and loan agents until circa 1929 when it became a barber shop as well. It continued in the hair and real estate business until circa 1975. It is now an antiques shop (spring 2002).



Missour	ri Historic	c/Arcl	hitectu	ıral Inventory F	'orm
A New York	ra.				
1. No. 2. County 58 Audrain	3. Loc	ation of Ne	gatives	4. Current Name(s) China Restaurant Annex	
5. Other Name(s)		Ah Dansa	Ac Cartina	6d. Street Address	- 1 m
3. Other Mannets/	T51N	R9W	26	111 South Washington	
7. City or Town	7b. Vicinit 8.	Descriptio	n of Location		parameter and the second
Mexico	The state of the s		ts 1 & 2, Bloc		
Oa. Site 10b. Building 10c	c. Structure 10d. O	blec 11.0	On National R	legister? 12. Is it eligible? 13. Pa	rt of Historic District
	a de la Caración de l	: 'U:			
4. District Potential? 15. h	Name of District	16	. Thematic Ca	tegory	
2	<u> </u>				
7. Date(s) or Period	18. Style or D	esign	19.7	Architect or Engineer	
circa 1885					
20. Contractor or Bullder	21. Original U	lse		resent Use	
	commercial	o promo a mario di care		nercial	
23. Ownership	24. C)wner's 1				. Open to Public
orivate		ng Fu, PO I		rico MO 65265	
26. Local Contact Person or	Organization			ther Surveys in Which Included	
Lura Williams	1785 1 Le 200 200 0 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1		n/a		
8. No. of Storle 29. Baser		on Material		Wall Construction	
2 📙	stone	500 175 ± 67 66 110	brick	and the second s	
Roof Type and Material	33a. No. of B	ays, front	33b.	No. of bays, side	
flat/asphalt	anitoral a decimanantalia di materiali di ministra		- 1 (V) - 2 - 1	0 1 2 3 3 3 3 3 3 3 3 3 3 3 3 3 3 3 3 3 3	
54. Wall Treatment brick	35. Plan Shap rectangular	e	30a.	Changes, addition (see 42) 36b.	Changes, altered (see 42)
Changes, moved (see 42)		rior	37h Condi	tion, Exterior 38. Preserv	ation underway?
Changes, moved (see 12)	27 a. Condition, into		770. COIIG	Jon	acon ancernos.
39a. Endangered 39b. End	langered by what?	40. V	isible from pu	blic road?	
j.		V			
11. Distance from and front	age on road				
12. Further Description of I	mportant Features				
				ng running the length of the fascac	le.
Second story features two be dentals near the roofline.	oarded up windows	with a brick	k panel betwe	en them and the corbelled brick	
13. History and Significance					
The first maps - 1885 - sho	ws a drug store. 18			re. 1894, racket shop. 1899,	
grocery. 1908, millinary sh	nop. 1914, second	hand store.	. Circa 1925-	1955, grocery store. In the 197	O's
والمستحدث والمستحدد					192 - SEAST WILLIAM STONESS STATE
	iant and Outhullala				
	nent and Outbuildin	B			
	eent and Outbuildin				
14. Description of Environm	andras la section of the section of		122-		
44. Description of Environm 45. Sources of Information	46. Prepared			Organization S Mayica	
it was a barber shop. 44. Description of Environm 45. Sources of Information Sanborn Maps, G. Craddocl 48. Date 49. R	46. Prepared			Organization of Mexico	



Oder Name(s) Od
Ox Building T5 IN R9W R9W R9W R9W R9W R9W R9W R9
City or Town 7b. Vicinit. 8. Description of Location 9. UTM Coordinates N 45' Lot 4 & N 45' of W 17 Block 8 Da. Site 10b. Building 10c. Structure 10d. Objec 11. On National Register? 12. Is it eligible? 13. Part of Historic District 4. District Potential? 15. Name of District 16. Thematic Category 7. Date(s) or Period 18. Siyle or Design 19. Architect or Engineer 1880 19. Architect or Engineer 19. Ownership 21. Ciriginal Use 22. Present Use commercial 20. Contractor or Builder 21. Ciriginal Use 22. Present Use commercial 21. Ownership 24. Civiner's Name and Address 25. Open to Public 25. Open to Public 26. Local Contact Person or Organization 27. Other Surveys in Which Included 27. Other Surveys in Which Included 27. Other Surveys in Which Included 28. No. of Storie 29. Basement 30. Foundation Material 31. Wall Construction 27. Other Surveys in Which Included 28. No. of Storie 29. Basement 30. Foundation Material 31. Wall Construction 27. Other Surveys in Which Included 28. No. of Storie 29. Basement 30. Foundation Material 31. Wall Construction 27. Other Surveys in Which Included 29. Soft Type and Material 33a. No. of Bays, front 33b. No. of bays, side 29. Wall Treatment 35. Plan Shape 36a. Changes, addition (see 42) 36b. Changes, altered (see 42) 37a. Condition, Interior 37b. Condition, Exterior 38. Preservation underway? 29a. Endangered 39b. Endangered by What? 40. Visible from public road?
N 45' Lot 4 &t N 45' of W 1/ Block 8
Da. Site 10b. Building 10c. Structure 10d. Object 11. On National Register? 12. Is it eligible? 13. Part of Historic District. 4. District Potential? 15. Name of District 16. Thematic Category 7. Date(s) or Period 18. Style or Design 19. Architect or Engineer 7. Date(s) or Period 18. Style or Design 19. Architect or Engineer 8. Ownership 24. Crimer's Name and Address 25. Open to Public City of Mexico, 300 North Coal, Mexico, MO 65265 8. Local Contact Person or Organization 27. Other Surveys in Which Included arra Williams 10. Country of Mexico, Mo 65265 8. No. of Storie 29. Basement 30. Coundation Material 31. Wall Construction brick brick brick brick brick 17. Stories 27. Description 28. No. of Bays, front 28. No. of Bays, side 28. Avail Treatment 25. Plan Shape 36a. Changes, addition (see 42) 36b. Changes, altered (stories in organization underway? 19. Endangered 39b. Endangered by what? 40. Visible from public road?
4. District Potential? 15. Name of District 16. Thematic Category 7. Date(s) or Period 18. Style or Design 19. Architect or Engineer 7. Date(s) or Period 18. Style or Design 19. Architect or Engineer 7. Date(s) or Period 18. Style or Design 19. Architect or Engineer 7. Date(s) or Period 18. Style or Design 19. Architect or Engineer 7. Date(s) or Period 18. Style or Design 19. Architect or Engineer 8. Occombastic 21. Criginal Use 22. Present Use Commercial Commercial 25. Open to Public 25. Open to Public 26. Local Contact Person or Organization 27. Other Surveys in Which Included 18. No. of Storie 29. Basement 30. Foundation Material 31. Wall Construction 19. Drick 31. Wall Construction 19. Drick 32. No. of Bays, front 33. No. of bays, side 26. Wall Treatment 35. Plan Shape 36a. Changes, addition (see 42) 36b. Changes, altered (see 12) 27. Date 39b. Endangered
4. District Potential? 15. Name of District 16. Thematic Category 7. Date(s) or Period 18. Style or Design 19. Architect or Engineer 7. Date(s) or Period 18. Style or Design 19. Architect or Engineer 8. Commercial 22. Present Use 8. Commercial 24. Commercial 9. City of Mexico, 300 North Coal, Mexico, MO 65265 9. Local Contact Person or Organization 27. Other Surveys in Which Included 9. Local Contact Person or Organization 27. Other Surveys in Which Included 9. No. of Storie 29. Basement 30. joundation Material 31. Wall Construction 9. brick 9. condition (see 42) 36b. Changes, altered (see 42) 9. Endangered 39b. Endangered 9. Visible from public road?
7. Date(s) or Period 18. Style or Design 19. Architect or Engineer 17. Date(s) or Period 18. Style or Design 19. Architect or Engineer 22. Present Use 23. Ownership 24. Ciwrier's Name and Address 25. Open to Public 24. Ciwrier's Name and Address 25. Open to Public 25. Open to Public 27. Other Surveys in Which Included 28. No. of Storie 29. Basement 30. Foundation Material 31. Wall Construction 28. No. of Storie 29. Basement 30. Foundation Material 31. Wall Construction 28. No. of Storie 29. Basement 30. Foundation Material 31. Wall Construction 29. Drick 25. Open to Public 25. Open to Pu
7. Date(s) or Period 18. Style or Design 19. Architect or Engineer (rea 1880) D. Contractor or Builder 21. Ciriginal Use commercial commercial commercial commercial (city of Mexico, 300 North Coal, Mexico, MO 65265) 6. Local Contact Person or Organization 27. Other Surveys in Which Included (ura Williams) 8. No. of Storie 29. Basement 30. Foundation Material 31. Wall Construction (brick) (brick) 25. Open to Public 27. Other Surveys in Which Included (ura Williams) 8. No. of Storie 29. Basement 30. Foundation Material 31. Wall Construction (brick) (brick) (brick) 26. Wall Treatment 33. Plan Shape 36a. Changes, addition (see 42) 36b. Changes, altered (see 42) 37a. Condition, Interior 37b. Condition, Exterior 38. Preservation underway?
Treatment Type and Material Type and Ty
D. Contractor or Builder 21. Criginal Use commercial 22. Present Use commercial 25. Open to Public Lity of Mexico, 300 North Coal, Mexico, MO 65265 6. Local Contact Person or Organization Lity of Mexico, 300 North Coal, Mexico, MO 65265 27. Other Surveys in Which Included Lity Williams 8. No. of Storie Lity of Mexico, 300 North Coal, Mexico, MO 65265 27. Other Surveys in Which Included Lity Williams 8. No. of Storie Lity of Mexico, 300 North Coal, Mexico, MO 65265 27. Other Surveys in Which Included Lity Williams 8. No. of Storie Lity of Mexico, 300 North Coal, Mexico, MO 65265 27. Other Surveys in Which Included Lity Williams 8. No. of Storie Lity of Mexico, 300 North Coal, Mexico, MO 65265 27. Other Surveys in Which Included Lity Williams 8. No. of Storie Lity of Mexico, 300 North Coal, Mexico, MO 65265 27. Other Surveys in Which Included Lity Williams 8. No. of Storie Lity of Mexico, 300 North Coal, Mexico, MO 65265 27. Other Surveys in Which Included Lity of Mexico, MO 65265 27. Other Surveys in Which Included Lity of Mexico, MO 65265 27. Other Surveys in Which Included Lity of Mexico, MO 65265 27. Other Surveys in Which Included Lity of Mexico, MO 65265 27. Other Surveys in Which Included Lity of Mexico, MO 65265 27. Other Surveys in Which Included Lity of Mexico, MO 65265 28. No. of Storie Lity of Mexico, MO 65265 29. Basement Lity of Mexico, MO 65265 20. Other Surveys in Which Included Lity of Mexico, MO 65265 20. Other Surveys in Which Included Lity of Mexico, MO 65265 27. Other Surveys in Which Included Lity of Mexico, MO 65265 29. Basement Lity of Mexico, MO 65265 20. Other Surveys in Which Included Lity of Mexico, MO 65265 20. Other Surveys in Which Included Lity of Mexico, MO 65265 27. Other Surveys in Which Included Lity of Mexico, MO 65265 29. Basement Lity of Mexico, MO 65
commercial commercial 3. Ownership 24. Commer's Name and Address 25. Open to Public sublic City of Mexico, 300 North Coal, Mexico, MO 65265 6. Local Contact Person or Organization 27. Other Surveys in Which Included ura Williams n/a 8. No. of Storie 29. Basement 30. Foundation Material 31. Wall Construction brick brick brick brick brick at/asphalt 7 4. Wall Treatment 35. Plan Shape 36a. Changes, addition (see 42) 36b. Changes, altered (see 42) 37a. Condition, Interior 37b. Condition, Exterior 38. Preservation underway? 9a. Endangered 39b. Endangered by what? 40. Visible from public road?
Lucial Contact Person or Organization 27. Other Surveys in Which Included ura Williams n/a B. No. of Storie 29. Basement 30. Foundation Material 31. Wall Construction brick brick of Type and Material 33a. No. of Bays, front 33b. No. of bays, side at/asphalt 7 4. Wall Treatment 35. Plan Shape 36a. Changes, addition (see 42) 36b. Changes, altered (see 42) 37a. Condition, Interior 37b. Condition, Exterior 38. Preservation underway? 9a. Endangered 39b. Endangered by what? 40. Visible from public road?
Lucial Contact Person or Organization 27. Other Surveys in Which Included ura Williams n/a B. No. of Storie 29. Basement 30. Foundation Material 31. Wall Construction brick brick of Type and Material 33a. No. of Bays, front 33b. No. of bays, side at/asphalt 7 4. Wall Treatment 35. Plan Shape 36a. Changes, addition (see 42) 36b. Changes, altered (see 42) 37a. Condition, Interior 37b. Condition, Exterior 38. Preservation underway? 9a. Endangered 39b. Endangered by what? 40. Visible from public road?
6. Local Contact Person or Organization 27. Other Surveys in Which Included ura Williams n/a 8. No. of Storie 29. Basement 30. Foundation Material 31. Wall Construction brick oof Type and Material 33a. No. of Bays, front 33b. No. of bays, side at/asphalt 7. 4. Wall Treatment 35. Plan Shape 36a. Changes, addition (see 42) 36b. Changes, altered (see 42) 37a. Condition, Interior 37b. Condition, Exterior 38. Preservation underway? 9a. Endangered 39b. Endangered by what? 40. Visible from public road?
B. No. of Storie 29. Basement 30. Foundation Material 31. Wall Construction brick poof Type and Material 33a. No. of Bays, front 33b. No. of bays, side at/asphalt 7 4. Wall Treatment 35. Plan Shape 36a. Changes, addition (see 42) 36b. Changes, altered (see 42) 37a. Condition, Interior 37b. Condition, Exterior 38. Preservation underway? 9a. Endangered 39b. Endangered by what? 40. Visible from public road?
brick 33a. No. of Bays, front 35b. No. of bays, side at/asphalt 7 4. Wall Treatment 35. Plan Shape 36a. Changes, addition (see 42) 36b. Changes, altered (see 42) 37a. Condition, Interior 37b. Condition, Exterior 38. Preservation underway? 9a. Endangered 39b. Endangered by what? 40. Visible from public road?
brick 33a. No. of Bays, front 35b. No. of bays, side at/asphalt 7 4. Wall Treatment 35. Plan Shape 36a. Changes, addition (see 42) 36b. Changes, altered (see 42) 37a. Condition, Interior 37b. Condition, Exterior 38. Preservation underway? 9a. Endangered 39b. Endangered by what? 40. Visible from public road?
A. Wall Treatment 35. Plan Shape 36a. Changes, addition (see 42) 36b. Changes, altered (see 42) 37a. Condition, Interior 37b. Condition, Exterior 38. Preservation underway? 9a. Endangered 39b. Endangered by what? 40. Visible from public road?
4. Wall Treatment 35. Plan Shape 36a. Changes, addition (see 42) 36b. Changes, altered (see 42) 37a. Condition, Interior 37b. Condition, Exterior 38. Preservation underway? 9a. Endangered 39b. Endangered by what? 40. Visible from public road?
rick rectangular 37b. Condition, Interior 37b. Condition, Exterior 38. Preservation underway? 9a. Endangered 39b. Endangered by what? 40. Visible from public road?
hanges, moved (see 42) 37a. Condition, Interior 37b. Condition, Exterior 38. Preservation underway? 9a. Endangered 39b. Endangered by what? 40. Visible from public road?
9a. Endangered 39b. Endangered by what? 40. Visible from public road?
L. Distance from and frontage on road
2. Further Description of Important Features aree entries the central one of which has a brick pillaster and decorative stone on each side and an arch
pove. The other two entries are centered between display windows and topped with transoms. There is
nother brick and stone pilaster on (cont.)
3. History and Significance he conflict man 1995, show it as a restaurant and billiard parlor, 1990, vacant on the porth side and
he earliest map - 1885 - show it as a restaurant and billiard parlor. 1890, vacant on the north side and undry and paint shop of the south. 1894, pawn shop, 2nd hand store and cobbler. 1899, pawn shop,
nd hand store and harness shop. (cont.)
1. Description of Environment and Outbuildings
5. Sources of Information 46. Prepared by 47. Organization
anborn Maps, G. Craddock, Ci Mary' Aue Mitchell City of Mexico
B. Date 49. Revision Date(s)
/6/2002

#80

- 112, 114 South Washington
- 42. A belt course separates the first and second stories. The second story features three 1/1 double hung windows with lintels and lug sills. Above them are featured two rows of corbelled brick denta s separated by four pilasters and another pilaster on each end.
- 43. 1908, 1914, barber and 2nd hand store. 1926, 1932, cleaners, restaurant, and real estate office. By 1950 it was a cleaners only. The building is now owned by the City of Mexico and preservation is underway.



Missour	i Historic/Arc	chitect	ural Inventory Form	
				
1. No. 2. County 59 Audrain	3. Location of I	vegatives	4. Current Name(s) China Restaurant	
5. Other Name(s)	6a. Township 6b. Ran	oe Ar Sartin		
J. Other (Name(s)	T51N R9W	26	113 South Washington	
7. City or Town	7b. Vicinit 8. Descript	ion of Locatio	and the second s	
Mexico		1 & 2, Block		
10a. Site 10b. Building 10c.	Structure 10d. Objec 11	. On National	Register? 12. Is it eligible? 13. Part of His	toric District
14. District Potential? 15. N	ame of District	6. Thematic (Category	
4				
17. Date(s) or Period	18. Style or Design	19.	Architect or Engineer	
circa 1885		· · · · · · · · · · · · · · · · · · ·		
20. Contractor or Builder	21. Original Use		Present Use	
22 Sec. 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2	commercial	a proper a company a super con-	nmercial	
23. Ownership	24. Owner's Name and		25. Open to	o Public
private	Frank Kuo-Yang Fu, PC			
26. Local Contact Person or Lura Williams	Organizati on	n/a	Other Surveys in Which Included	
28. No. of Storie 29. Basem	sant 30 Loundailes Meter		Wall Construction	
26. No. of Storie 27. Baseli	stone		ne and brick	
Roof Type and Material	33a. No. of Bays, from		. No. of bays, side	
flat/asphalt	3			
34. Wall Treatment	35. Plan Shape	36a	. Changes, addition (see 42) 36b. Changes	, altered (see 42)
stone and brick	rectangular		表。这是实现上面是	
Changes, moved (see 42) 3	7a. Condition, Interior	37b. Con	dition, Exterior 38. Preservation uni	derway?
39a. Endangered 39b. Enda	- 1 ····	Visible from p	ublic road?	
41. Distance from and fronta	ge on road			
<u> </u>				
42. Further Description of In		rang sa Tiga	Popular them Corond floor foreigns	
			between them. Second floor features dentals and pilasters at the roofline.	
		NO. 3.7	The state of the s	
43. History and Significance			1004	
			ore. 1894, a grocery store. 1899- 1929 to 1945 it was a billiard parlor.	
It was then a tavern until circ	a 1965 (cont)			
44. Description of Environme	ent and Outbuildings			
45. Sources of Information	46. Frepared by		Organization	
Sanborn Maps, G. Craddock	, Ci Mary Aue Mitchell	City	of Mexico	
	evision Date(s)	· ·		
3/15/2002				

#59

- 113 South Washington
- 43. when it become the Royal Café. It has remained a restaurant since that time.



1. No.	2, County	3. Location of Negative	
60	Audrain	MCRI	Dagwood's Subs & Sandwiches
5. Other	Name(s)	6a. Township 6b. Range 6c.	Section 6d. Street Address
		T51N R9W 26	
7. City or	Town	7b. Vicinit 8. Description of I	Location 9. UTM Coordinates
Mexico		S 22' of N 46' Lo	ots 1 &t 2, Blo
10a. Site	10b. Building 10c. !	Structure 10d. Objec 11. On N	ational Register? 12. Is it eligible? 13. Part of Historic District
14. Distri	ct Potential? 15. Na	me of District 16. The	matic Category
/			
17. Date(s) or Period	18. Style or Design	19. Architect or Engineer
circa 188			
20. Contr	ractor or Builder	21. Ciriginal Use	22. Present Use
		commercial	commercial
23. Owne	ership	24. Cwner's Name and Addre	ess 25. Open to Public
private			9871 Audrain Rd. 375, Mexico MO
26. Local	Contact Person or O	Prganization	27. Other Surveys in Which Included
Lura Willi			n/a
28. No. c	of Storie 29. Baseme	nt 30, Foundation Material	31, Wall Construction
2		stone stone	brick
Roof Type	e and Material	33a. No. of Bays, front	33b. No. of bays, side
flat/aspha		4	
34. Wall '	Treatment	35. Plan Shape	36a. Changes, addition (see 42) 36b. Changes, altered (see 4
brick and		rectangular	
Changes.	moved (see 42) 37:	a. Condition, Interior 37	b. Condition, Exterior 38. Preservation underway?
Jar			
39a. Enda	angered 39b. Endan	gered by what? 40. Visible	from public road?
		V	
41. Distar	nce from and frontage	e on road	
42. Furth	er Description of Imp	ortant Features	
single doo	or south corner entry	and a central entry flanked by dis	play windows. A boarded up transom
		story. Second story has three 1/1	double hung windows with corbelled brick
5	the roofline. ry and Significance		
			1000
In 1885 i	· · · · · · · · · · · · · · · · · · ·	second hand store 1894 telenh	IONE EXCHANGE. I 899. TELENHONE EXCHANGE
	it was vacant. 1890,	second hand store. 1894, teleph it was shoes and boots only. It is	remained a shoe store until circa 1960 when
and shoes it became	it was vacant. 1890, and boots. By 1908 an insurance office.	8 it was shoes and boots only. It	
and shoes it became	it was vacant. 1890, and boots. By 1908	8 it was shoes and boots only. It	
and shoes it became	it was vacant. 1890, and boots. By 1908 an insurance office.	8 it was shoes and boots only. It	
and shoes it became	it was vacant. 1890, and boots. By 1908 an insurance office.	8 it was shoes and boots only. It	
and shoes it became 44. Descr	it was vacant. 1890, and boots. By 1908 an insurance office.	8 it was shoes and boots only. It	
and shoes it became 44. Descri 45. Source	it was vacant. 1890, and boots. By 1908 an insurance office. Iption of Environmen	8 it was shoes and boots only. It is and Outbuildings 46. Prepared by	remained a shoe store until circa 1960 when
and shoes it became 44. Descri 45. Source	it was vacant. 1890, and boots. By 1908 an insurance office. iption of Environmen es of Information Maps, G. Craddock, G	8 it was shoes and boots only. It is and Outbuildings 46. Prepared by	47. Organization



1. No. 2. County	3. Location of Ne	gatives 4. Current Name(s)	
81 Audrain	MCRI	Smith Electronics	
5. Other Name(s)	6a. Township 6b. Range	6c. Section 6d. Street Address	
Mexico Barber Shop	T51N R9W	26 116, 118 S. Washington	
7. City or Town	7b. Vicinit 8. Description		
Mexico		SC S 58' Lot 4, Blo	
	. Structure 10d. Objec 11. C	On National Register? 12. Is it eligible? 13. Part	of Historic District
14. District Potential? 15. N	Name of District 16.	Thematic Category	
_			
17. Date(s) or Period	18. Style or Design	19. Architect or Engineer	
circa 1885			
20. Contractor or Bullder	21. Ciriginal Use	22. Present Use	
	commercial	commercial	
23. Ownership	24. Owner's Name and A		Open to Public
private		h Jefferson, Mexico MO 65265 (cont.)	
26. Local Contact Person or	Organization	27. Other Surveys in Which Included	_
Lura Williams		n/a	
28. No. of Storle 29. Baser	ment 30, Foundation Material	31. Wall Construction	
1 🕌	brick	brick	
Roof Type and Material	33a. No. of Bays, front	33b. No. of bays, side	
flat/asphalt	4		
34. Wall Treatment	35. Plan Shape	36a. Changes, addition (see 42) 36b. C	hanges, altered (see 42)
brick and painted brick	rectangular		
Changes, moved (see 42)	37a. Condition, Interior	37b. Condition, Exterior 38. Preservan	ion underway?
	<u> </u>		
39a. Endangered 39b. End		sible from public road?	
	⊻:		
41. Distance from and front	age on road	· 直接 (在) (1) (1) (1) (1)	
		AAA	
42. Further Description of I			
		the side. The northern most entry is flanked by	
decorative phasters. Covere	o cransoms run the length of th	e fascade between the windows and the roofline.	
43. History and Significance		"我们""说",没有一次 "人"。	
1885 map, vacant and a sh	oe shop. 1890, harnesses and	shoe shop. 1894, barber and shoe shop. 189	
		. 1914. Bicycles and cleaners. Barber shop and	
restaurant from circa 1950. 44. Description of Environm			
The Description of Charolin	en an Annahan		
Committee of the Commit	Yan all a Break was all a break and a second and a	the state of the harvest of the state of the	- L
45. Sources of Information	46. I repared by	47. Organization	
Sanborn Maps, G. Craddock	Manager Committee Committe	City of Mexico	
	evision Date(s)		
6/6/2002			



1. No. 2. County	3. Location of Nega	tives 4. Current Name(s)
61 Audrain	MCRI	Castle's and E & K Jewelry
5. Other Name(s)	6a. Townshi 6b. Rang 6c.	Sectio 6d. Street Address
	T51N R9W 26	117 - 119 South Washington
7. City or Town	7b. Vicini 8. Description o	f Location 9. UTM Coordinates
Mexico	S 40' of Lot 5, BI	OCK 13
10a. Sit 10b. Buildin 10c. Str	ructu 10d. Objec 11. On Na	ational Regist 12. Is it eligibl 13. Part of Historic Distr
14. District Potenti 15. Name	e of District 16. The	matic Category
17. Date(s) or Period	18. Style or Design	19. Architect or Engineer
circa 1885		
20. Contractor or Builder	21. Original Use	22. Present Use
	commercial	commercial
23. Ownership	24. Owner's Name and Add	
private	Phillip Chirillo, PO Box 219	
26. Local Contact Person or		27. Other Surveys in Which included
Lura Williams	or gamzacion	n/a
28. No. of Stori 29. Baseme	70 Foundation Material	31. Wall Construction
28. NO. OF Storr 29. baserie	brick	brick
Roof Type and Material	33a. No. of Bays, front	33b. No. of bays, side
flat/asphalt	<u> </u>	
34. Wall Treatment	35. Plan Shape	36a. Changes, addition (see 36b. Changes, altered (se
brick	rectangular	Name of the same o
Changes, moved (see 37a.	Condition, Interior 37t	o. Condition, Exterior 38. Preservation underw
39a. Endangere 39b. Endang		from public road?
	<u> </u>	
41. Distance from and fronta	age or road	
42. Further Description of In		
		between then as well as an entry on
the north side. A covers the fascade of the second floor	e recessed entries and ver This siding was added circ	tical metal siding covers the entire
43. History and Significance	Triis siding was added circ	<u>a 1973.</u>
	ows this building as a resta	urant and dry goods store. 1890,
barber and bakery. 1894, it v	was vacant on one side and	had a patent stove exhibit on the
other. 1899, grocery and ta		arber. (cont.)
44. Description of Environm	ent and Outbuildings	
45. Sources of Information	46. Prepared by	47. Organization
Sanborn Maps, G. Craddock		City of Mexico
	sion Date(1
3/15/2002		

#61

117, 119 South Washington

42 In 1914 it was a dry goods store and bakery. By 1926 it housed Lawrence Drug Company and shoe repair store. It continued to have shoe repair until circa 1970.



62 Audrain	MCRI		Terminal Barber Shop
5. Other Name(s)	óa. Township	6b. Range 6c. Sect	Jon 6d. Street Address
	T51N	R9W 26	121 South Washington
7. City or Town	7b. Vicinit 8.	Description of Local	lon 9. UTM Coordinates
Mexico	□ s:	22' of Lots 1 & 2, I	Block 7
10a. Site 10b. Building 10	C. Structure 10d. O	bjec 11. On Natio	nal Register? 12. Is it eligible? 13. Part of Historic District
			Secolar Company
14. District Potential? 15.	Name of District	16. Themati	C Category
✓			
17. Date(s) or Period	18. Style or Di	esign 1	9. Architect or Engineer
circa 1885			
20. Contractor or Builder	21. Ciriginal U	se 2	2. Present Use
	commercial	C.	ommercial
23. Ownership	24. Ciwner's N	lame and Address	25. Open to Public
private			1 South Washington, Mexico M
26. Local Contact Person o	or Organization	27	Other Surveys in Which Included
Lura Williams		n/	
28. No. of Storle 29. Base	ement 30. Foundatio	n Material	11. Wall Construction
2	brick	Ŀ	prick
Roof Type and Material	33a. No. of Ba	iys, front 3	3b. No. of bays, side
	T		
flat/asphalt	3	4	
	35. Plan Shape		6a. Changes, addition (see 42) 36b. Changes, altered (se
	35. Plan Shape rectangular		
34. Wall Treatment brick	rectangular		
flat/asphalt 34. Wall Treatment brick Changes, moved (see 42)	rectangular		6a. Changes, addition (see 42) 36b. Changes, altered (se
34. Wall Treatment brick	rectangular 37a. Condition, Inter		6a. Changes, addition (see 42) 36b. Changes, altered (se
34. Wall Treatment brick Changes, moved (see 42)	rectangular 37a. Condition, Inter	rior 376. C	6a. Changes, addition (see 42) 36b. Changes, altered (se
34. Wall Treatment brick Changes, moved (see 42) 39a. Endangered 39b. En	rectangular 37a, Condition, Inter dangered by what?	rior 376. C	6a. Changes, addition (see 42) 36b. Changes, altered (se
34. Wall Treatment brick Changes, moved (see 42)	rectangular 37a, Condition, Inter dangered by what?	rior 376. C	6a. Changes, addition (see 42) 36b. Changes, altered (se
34. Wall Treatment brick Changes, moved (see 42) 39a. Endangered 39b. En	rectangular 37a, Condition, Inter dangered by what? tage on roa 1	rior 376. C	6a. Changes, addition (see 42) 36b. Changes, altered (se
34. Wall Treatment brick Changes, moved (see 42) 39a. Eridangered 39b. En 41. Distance from and from 42. Further Description of central recessed entry flank	rectangular 37a. Condition, Inter dangered by what? tage on road Important Features ed by display window	rior 37b; Co	ondition, Exterior 38. Preservation underway? public road?
34. Wall Treatment brick Changes, moved (see 42) 39a. Eridangered 39b. Eridangered 41. Distance from and from 42. Further Description of central recessed entry flank The second story has two 1	rectangular 37a. Condition, Inter dangered by what? tage on road Important Features ed by display window	rior 37b; Co	6a. Changes, addition (see 42) 36b. Changes, altered (see ondition, Exterior 38. Preservation underway?
34. Wall Treatment brick Changes, moved (see 42) 39a. Endangered 39b. En 41. Distance from and from 42. Further Description of central recessed entry flank The second story has two identals at roof line	rectangular 37a. Condition, Inter dangered by what? tage on road Important Features ed by display window /1 double hung wind	rior 37b; Co	ondition, Exterior 38. Preservation underway? public road?
34. Wall Treatment brick Changes, moved (see 42) 39a. Endangered 39b. En 41. Distance from and from 42. Further Description of central recessed entry flank The second story has two 1 dentals at roof line 43. History and Significance	rectangular 37a. Condition, Inter dangered by what? itage on road Important Features sed by display window /1 double hung winds	AO. Visible from	ondition, Exterior 38. Preservation underway? public road? assom running the length of the fascade. nel between then and the corbelled brick
34. Wall Treatment brick Changes, moved (see 42) 39a. Endangered 39b. En 41. Distance from and from 42. Further Description of central recessed entry flank The second story has two 1 dentals at roof line 43. History and Significance The earliest map - 1885 - store with a lodge hall on the second story has two 1 dentals at roof line	rectangular 37a. Condition, Inter dangered by what? itage on road Important Features ted by display window // I double hung wind e show a grocery store, he second floor. 192	40. Visible from	ondition, Exterior 38. Preservation underway? public road?
34. Wall Treatment brick Changes, moved (see 42) 39a. Endangered 39b. En 41. Distance from and from 42. Further Description of central recessed entry flank The second story has two 1 dentals at roof line 43. History and Significance The earliest map - 1885 - store with a lodge hall on thas been a barber shop since	rectangular 37a. Condition, Inter dangered by what? tage on road Important Features ted by display window 1/1 double hung wind e show a grocery store, he second floor. 192 te circa 1970.	s with a covered train lows with a brick part 1890, 1894, 18929 it was vacant.	ondition, Exterior 38. Preservation underway? public road? assom running the length of the fascade. nel between then and the corbelled brick 9,1908, 1914 all show a dry goods
34. Wall Treatment brick Changes, moved (see 42) 39a. Endangered 39b. En 41. Distance from and from 42. Further Description of central recessed entry flank The second story has two 1 dentals at roof line 43. History and Significance The earliest map - 1885 - store with a lodge hall on the second story has two 1 dentals at roof line	rectangular 37a. Condition, Inter dangered by what? tage on road Important Features ted by display window 1/1 double hung wind e show a grocery store, he second floor. 192 te circa 1970.	s with a covered train lows with a brick part 1890, 1894, 18929 it was vacant.	ondition, Exterior 38. Preservation underway? public road? assom running the length of the fascade. nel between then and the corbelled brick 9,1908, 1914 all show a dry goods
34. Wall Treatment brick Changes, moved (see 42) 39a. Endangered 39b. En 41. Distance from and from 42. Further Description of central recessed entry flank The second story has two 1 dentals at roof line 43. History and Significance The earliest map - 1885 - store with a lodge hall on thas been a barber shop since	rectangular 37a. Condition, Inter dangered by what? tage on road Important Features ted by display window 1/1 double hung wind e show a grocery store, he second floor. 192 te circa 1970.	s with a covered train lows with a brick part 1890, 1894, 18929 it was vacant.	ondition, Exterior 38. Preservation underway? public road? assom running the length of the fascade. nel between then and the corbelled brick 9,1908, 1914 all show a dry goods
34. Wall Treatment brick Changes, moved (see 42) 39a. Endangered 39b. En 41. Distance from and from 42. Further Description of central recessed entry flank The second story has two 1 dentals at roof line 43. History and Significance The earliest map - 1885 - store with a lodge hall on thas been a barber shop since	rectangular 37a. Condition, Inter dangered by what? tage on road Important Features ted by display window 1/1 double hung wind e show a grocery store, he second floor. 192 te circa 1970.	s with a covered train lows with a brick part 1890, 1894, 18929 it was vacant.	ondition, Exterior 38. Preservation underway? public road? assom running the length of the fascade. nel between then and the corbelled brick 9,1908, 1914 all show a dry goods
34. Wall Treatment brick Changes, moved (see 42) 39a. Endangered 39b. En 41. Distance from and from 42. Further Description of central recessed entry flank The second story has two 1 dentals at roof line 43. History and Significance The earliest map - 1885 - store with a lodge hall on thas been a barber shop since	rectangular 37a. Condition, Inter dangered by what? Important Features ded by display window 1/1 double hung wind e show a grocery store. he second floor. 192 ce circa 1970. ment and Outbuilding	s with a covered trail lows with a brick part 1890, 1894, 189	ondition, Exterior 38. Preservation underway? public road? assom running the length of the fascade. nel between then and the corbelled brick 9,1908, 1914 all show a dry goods
34. Wall Treatment brick Changes, moved (see 42) 39a. Endangered 39b. En 41. Distance from and from 42. Further Description of central recessed entry flank The second story has two identals at roof line 43. History and Significanc The earliest map - 1885 - istore with a lodge hall on the control of t	rectangular 37a. Condition, Inter dangered by what? Intage on road Important Features ed by display window 1/1 double hung wind e show a grocery store, he second floor. 192 he circa 1970. ment and Outbuilding 46. Prepared b	s with a covered trail dows with a brick pare 1890, 1894, 18929 it was vacant.	ondition, Exterior 38. Preservation underway? public road? 1. public road?
34. Wall Treatment brick Changes, moved (see 42) 39a. Endangered 39b. En 41. Distance from and from 42. Further Description of central recessed entry flank The second story has two 1 dentals at roof line 43. History and Significanc The earliest map - 1885 - store with a lodge hall on thas been a barber shop sinc 44. Description of Environ 45. Sources of Information Sanborn Maps, G. Craddo	rectangular 37a. Condition, Inter dangered by what? Intage on road Important Features ed by display window 1/1 double hung wind e show a grocery store, he second floor. 192 he circa 1970. ment and Outbuilding 46. Prepared b	s with a covered trail dows with a brick pare 1890, 1894, 18929 it was vacant.	ondition, Exterior 38. Preservation underway? public road? soom running the length of the fascade. nel between then and the corbelled brick 9,1908, 1914 all show a dry goods 35 it held a women's clothing shop. It

