State Historical Survey and Planning Office, 909 University Avenue, Suite 215, Columbia, Missouri 65201 TORIC INVENTOR -AS-010-001 4. Present Name(s) WPT-2. County Janssen Place Entrance Gate 5. Other Name(s) Jackson 3. Location of Negatives K.C. Landmarks Commission 6. Specific Location 28. No. of Stories Intersection of Janssen Place 29. Basement? Yes ! Noxx and 36th St., Kansas City, MO 17. Date(s) or Period 30. Foundation Material 64109 18. Style or Design If Rural, Township & Vicinity Reunal cut limestone 7. City or Town 31. Wall Construction solid Kansas City Neo-Classic = Georgian 8./Site Plan with North Arrow 19. Architect or Engineer cut limestone George A. Mathews 32. Roof Type & Material 20. Contractor or Builder None 33. No. of Bays Unknown Front b 21. Original Use, if apparent 34. Wall Treatment Entrance Gate 22. Present Use limestone 35. Plan Shape linear Entrance Gate 36. Changes 23. Ownership Public 11 Addition (: Alteredxx 1aPrivate X (Explain in #42) Moved i 24. Owner's Name & Address if known Janssen Place Lot 37. Condition Owners Ass'n., Janssen Place Interior 9. Coordinates Kansas City, Mo. 64109 excellent Lal Exterior Long. 25. Open to Yes X 38. Preservation Yesxx Public? Noll Underway? Noil Site 11 Structure X Object 11 Building 11 26. Local Contact Person or Organization 39. Endangered? Yesxx O By What? Possible No 11 11. On National Yes II 12. Is It Yes X Janssen Place Lot Owners Assi Register? Eligible? No II No X 27. Other Surveys in Which Included rezoning of property 13. Part of Estab. Yes Li 14. District Yes X Preliminary Inventory of 40. Visible from Yesxx O Potent'l? Hist. Dist.? Nox Noll Public Road? Noil Architecture & Historic Sites 41. Distance from and 15. Name of Established District K.C. Landmarks Commission, Frontage on Road Kansas City, Mo., Nov., 1974 Adjacent to streetline 42. Further Description of Important Features Gateway consists of a central focal structure flanked by column pairs used for pedestrian and vehicular passageways. Central structure, occupying circular island, composed of two massive cylindrical piers, stone screen consisting of Ionic columns and pilasters set on solid stone pedestal walls. Entablature contains the words "Janssen Place." Cornice ornamented with dentils and antifixae string coursing. (Con't. p.2) 43. History and Significance The classic gateway, entirely original in detail, was designed by Mr. George A. Mathews in 1896. It was constructed of Arkansas limestone and bronze in 1897. 44. Description of Environment and Outbuildings Main entrance gate is situated east-west alligned with 36th st. To the south, east, and southwest are Janssen Place Residences. To the north are other Hyde Park Residences. 45. Sources of Information 46. Prepared by Victoria C The K.C. Star, Sat., Jan. 30, 1897, Vol. 17, No. 133, p.8 The K.C. Times, May 17, 1899. Karel & Edward Miszczuk 47. Organization Art Work on K.C., Mo. and Vicinity, Western PhotogravureCo K.C. Landmarks Comm

Chas. T. Daily & Co., Prop., Chicago, 1900, p.8.

(Con't. p. 2)

48. Date

11 - 75

49. Revision Date(s)

HISTORIC INVENTORY - State Historical Survey and Planning Office

Janssen Place Entrance Gate Intersection Janssen Place & 36th Street Kansas City, Me.

Page two

42. Furthur Description of Important Features

Each pier is capped by concentric circles and crowned with pointed finials. Bronze lanterns are placed to north and south of stone piers. Flanking stone columns are ornamented with anthemion frieze, crowned by ball finials.

Alterations: Include removal of bronze lanterns on north side of cylindrical piers.

45. Sources of Information

Tax Assessment Grid, Director of Records, Jackson County Courthouse, 415 E. 12th St., Kansas City, Mo. 64106



11-75

house, 415 E. 12th, Kansas City, Mo.

M

JA-AS-010-002

HISTORIC INVENTORY - State Historical Survey and Planning Office

Kenneth Space and Eric Van Benschoten Residence #2 Janssen Place Kansas City, Mo.

Page two

42. Further Description of Important Features

level contains centrally-place wall dormer with central segmented arch casement window flanked by smaller windows. Cut stone sills 5 lintels. Hipped roofed dormers placed on south and north facade. Bracket-supported box cornice. Wood frame roof surfaced with green glazed Spanish clay tiles. Larger red brick chimney on northwest corner. Engaged red brick chimney place along south wall.

Alterations: Originally-open south portico enclosed containing secondary entrance. Roof dormers surfaced with green glazed ceramics tiles.



County Courthouse, 415 W. 12th St., KCMO 64106

49. Revision Date(s)

11-75

10

HISTORIC INVENTORY -- State Historical Survey and Planning Office

Mr. William A. Bennett & Mr. John Jenkins Residence #3 Janssen Place Kansas City, Mo.

Page two

42. Furthur Description of Important Features

Stone string-coursing visually separates second and third stories. The majority of third story windows are of paired casement type divided into lozenge-shaped lights. Central group on west facade has a grilled balcony wall spaces ornamented with brick frames with stone blocks and surfaces with stucco. Leaded art glass windows placed on north facade. Wood frame hipped roof is surfaced with green glazed Mission day tiles. Overhanging box cornice, visually supported by paired brackets. An engaged brick chimney is located along the south facade.

Alterations: Removal of balastrades atop single story west and south extensions. Removal of balustrades from terrace along west facade. Southeast corner porch originally open, is presently enclosed. Originally, an open portico placed along the southwest corner of building; has been enclose with buff brick.



State Historical Survey and Planning Office, 909 University Avenue, Suite 215, Columbia, Missouri 65201 HISTORIC INVENTORY A-AS-010-004 4. Present Name(s) 1. No. WPT - 30 B 2. County #3 Janssen Place Garage 5. Other Name(s) Jackson 3. Location of Negatives K.C. Landmarks Commission 28. No. of Stories 6. Specific Location 16. Thematic Category #3 Janssen Place - Rear 29. Basement? Yes 0 NoXX 17. Date(s) or Period ks Kansas City, MO 30. Foundation Material 64109 1912 Masonry 7. City or Town If Rural, Township & Vicinity 18. Style or Design 31. Wall Construction Kansas City Italianate Revival 8. Site Plan with North Arrow 19. Architect or Engineer Masonry & Wood 32. Roof Type & Material 76-11-51 Shepard Farrar & Wiser 20. Contractor or Builder hipped glazed tile 33. No. of Bays Joseph Hellman Front 21. Original Use, if apparent 34. Wall Treatment Garage-servants quarter buff brick 22. Present Use & stucce 35. Plan Shape rectangul Garage--residence Public XX Private XX 36. Changes 23. Ownership Addition (Explain Altered | | Moved i in #42) 24. Owner's Name & Address. . . . Bennett 37. Condition #3 Janssen Place Interior 9. Coordinates Kansas City, MO 64109 Exterior Excellent Lat. Long. 25. Open to Preservation YesxiX Yes Public? Noxx Underway? No I Structure | Site ! BuildingXX Object ! ! 39. Endangered? Yes X 26. Local Contact Person or Organization pos^{By}White rezoning 11. On National 12 Is It YesXX Yes Janssen Place Lot Owners Assr Eligible? Register? NoXX No I 27. Other Surveys in Which Included of property 13. Part of Estab. Yes I I 14. District YesXX 40. Visible from Yes X Hist. Dist.? No IX Potent'l? No none Public Road? No II 41. Distance from and 15. Name of Established District Frontage on Road approx. 150 ft. 42. Further Description of Important Features Symmetrically designed facades. Other Name(s Three car garage. Main vehicular roller door, two cars wide, faces west. Secondary single car entrance door placed along north facade. Pedestrian entrance placed on extreme north bay of west facade. Second story has double hung sash windows. Stucco panels between windows Hipped roof surfaced with green glazed ceramic tiles. 43. History and Significance Garage erected by and served George W. Uitch, President of the George W. Ultch Lumber Co. in Kansas City, Mo. Erected in 1912. Mr. Uitch commissioned the local architectural firm of Shepard, Farrar, & Wiser to design the residence and the contracting firm of Joseph Hellman to construct it. 44. Description of Environment and Outbuildings Garage lies on eastern half of Janssen Place. the west lies accompanying residence #3 Janssen Place. To the south lies #3 Janssen Place Garage. 45. Sources of Information 46. Prepared by Victoria C. 1940 Tax Assesment Grid, Director of Rec-Karel & Edward Miszczuk ords, Jackson County Courthouse (Kansas City Annex) 47. Organization K.C. Landmarks Comm. 415 E. 12th Street, Kansas City, Mo 48. Date 49. Revision Date(s) 11 - 75



11-75

HISTORIC INVENTORY - State Historical Survey and Planning Office

John L. Bennet Residence #6 Janssen Place Kansas City, Mo.

Page two

32. Roof Type & Material

& gravel, slate shingle, clay tile. M. P. hip.

42. Further Description of Important Features

surmounted by transoms. Wood frame, ridged roog consists of gabled type, surfaced with asphalt shingles. Projecting cornices are supported by rafters. Gable ends placed on north, south, and east facades are surfaced with board and batten stick work and contain rectangular double-sash windows. Gabled roof dormers placed above roof line on north, south and west facades. Engaged, ribbed brick chimneys are placed along north, south and west facades.

45. Sources of Information

Western Contractor, Vol. 16, No. 12, March 20, 1909, p. 14.



State Historical Survey and Planning Office, 909 University Avenue, Suite 215, Columbia, Missouri 65201 5A-AS-010-006 4. Present Name(s) WPT-WPT-29A 2. County Mr. & Mrs. Richard L. Hetzel Residence 29 5. Other Name(s) Jackson 3KLocation of Negatives D K.C. Landmarks Commission Rodella G. Dwight Residence 16. Thematic Category 6. Specific Location 28. No. of Stories #7 Janssen Place 29. Basement? YesXX Kansas City, Mo. No I 64109 17. Date(s) or Period 30. Foundation Material 1909-10 18. Style or Design 7. City or Town If Rural, Township & Vicinity Masonry walls 31. Wall Construction Italianate Revival Kansas City 8. Site Plan with North Arrow 19. Architect or Engineer Masonry & Wood 32. Roof Type & Material L.P. hip; J.W. McKecknie 36-91. 20. Contractor or Builder wd.fra.Red Mission clay 11 33. No. of Bays G.E. Henry tile Side Front 21. Original Use, if apparent 34. Wall Treatment face brick Residence - Single family 22. Present Use /Indiana cut stone 35. Plan Shape i Residence - Multi-family rregular 36. Changes 23. Ownership Public 11 Addition 1 Private X (Explain Altered | in #42) Moved i 24. Owner's Name & Address, if knownMr. & Mrs. Richard L. 37. Condition Hetzel, #7 Janssen Place, 9. Coordinates Kansas City, Mo. Exterior Excellent Lat. Long 25. Open to Yes X 38. Preservation YesXX Public? restricted Underway? No Structure 11 Site Li Building X Object 11 39. Endangered? Yes**XX** 26. Local Contact Person or Organization Possible Noil By What? 11. On National Yes !! Yes X 12 Is It Janssen Place Lot Owners Assi No X Register? Eligible? Noll 27. Other Surveys in Which Included rezoning of property o 13. Part of Estab. Yes II 14. District Yes lx 40. Visible from Preliminary Inventory of Yesxx Hist. Dist.? No L Potent'l? Public Road? Noll Architecture & Historic Site Distance from and 15. Name of Established District K.C. Landmarks Commission, Frontage on Road Nov., 1974 Approx 75' from st. 42. Further Description of Important Features Symmetrically designed facades. Single story gabled roof extensions project from north, south and west elevations. Poticos have brick piers ornamented with cut stone blocks. An open terrace adjoins the west and south facade porticos. Main entrance containing double-leaf doors placed in the central bay. The fenestration consists of rectangular double-hung sash windows in single to multiple groupings. Cut stone is used (Cont.p2) 43. History and Significance Mrs Rodella G. Dwight, President of the Dwight Building in K.C., Mo, was the first owner and occupant of #7 Janssen Place. Erected in 1909-10 by Mrs. Dwight who commissioned the local architect John W. McKecknie to design the residence and the contracting firm of G.E. Henry to construct it in reference to Mr. G.E. Henry: "making a specialty of strictly high class residences, he builds no house for less than \$10,000 and (Con't. p.2) 44. Description of Environment and Outbuildings Residence lies on eastern half of Janssen Place. Main entrance faces west. To the north and south lie additional Janssen Place Residences. To the east are other Hyde Park Residences. 45. Sources of Information 46. Prepared by Victoria C Pen and Sunlight Sketches of Greater Kansas City, pub. by Karel & Edward Miszezuk The American Illustrating Co., Kansas City, Mo., 1914, pp. 47. Organization 65 & 89 K.C. Landmarks Comm The K.C. Star, Sunday, May 13, 1923, "A Janssen Place Bar-48. Date 49. Revision Date(s)

(Con't. p.2)

gain."

11-75

HISTORIC INVENTORY -- State Historical Survey and Planning Office

Mr. & Mrs. Richard L. Hetzel Residence #7 Janssen Place Kansas City, Mo.

Page two

42. Furthur Description of Important Features

for quoins and window frames. Stone string-coursing separates second and third story levels. Wood frame hipped roof is low-pitched with projecting box cornice supported by numerous brackets. Roofs of porches and main structure surfaced with Mission clay tile. Engaged brick chimney projects from the south facade. A two-story ovate enclosed conservatory with cut limestone base extends from the southeast corner in the rear of the residence. A porte-cochere is located along the north elevation.

43. History and Significance

among his most recent activities in this line is the elegant \$60,000.00 mansion at Janssen Place, a contract house, which is a fair sample of the general class of work he turns out."

45. Sources of Information

Building Permit, Division of Buildings and Inspection, Public Works Department, City Hall, 414 E. 12th St., Kansas City, Mo. 64106

Tax Assessment Grid, Director of Records, Jackson County Courthouse, 415 E. 12th St., Kansas City, Mo. 64106



11-75



47. Organization

48. Date

11 - 75

K.C. Landmarks Comm

49. Revision Date(s)

(1897-1964)," Martha Rowe Larson, Vol. V, No. 15, Nov.

1964, pp. 10-13.

(Con't. p. 2)

HISTORIC INVENTORY -- State Historical Survey and Planning Office

Mr. & Mrs. Robert D. Lawson Residence #17 Janssen Place Kansas City, Mo.

Page two

42. Furthur Description of Important Features

smaller rectangular lights. Windows are either in single or multiple groupings. Stone is used on window frames, parapets, quoins, and ornaments. The attic level consists of wall gabled dormers along west facade. Gabled roof dormers with overhanging eaves are placed in irregular groupings. Roofs surfaced with slate shingles. South facade contains single story extension. Secondary entrances are situated on north facade and south facade extension. Ribbed engaged chimneys containing paired flue-shafts are placed off-center along the north and west facades.

Alterations: Removal of open terrace originally extending

Alterations: Removal of open terrace originally extending the entire length of west facade 9now covered iwth foliage).

45. Sources of Information

Building Permit, jCity Hall, Division of Buildings & Inspection, Public Works Department, 414 E. 12th St., Kansas City, Mo. 64106
Tax Assessment Grid, Director of Records, Jackson County Courthouse, 415 E. 12th St., Kansas city, Mo. 64106



42. Further Description of Important Features Two car garage. garage doors, set in segmental arched frames, face west. Main pedestrian entranceway facing west is placed at extreme north corner of main facade. Fenestration consists of segmental arched double-hung sash windows. Brick piers along corner project above roof line. Gabled roof visually supported by overhanging brackets. Roof level ahs two

1. No.

liv

Lat.

Long

2. County

43. History and Significance Garage erected by and served Abram Rosenberger, who was employed with the A.M. Jones Distillery Company. Erected in 1912-13, Mr. Rosenberger commissioned the local architectural firm of Shepard, Farrar, & Wiser to design the residence and the contracting firm of K.C. Construction Co. to build it.

44. Description of Environment and Outbuildings Garage lies on eastern half of Janssen Place. the west lies accompanying residence, #17 Janssen Place. To the north lies #7 Janssen Place Garage; to the south lies additional lots and structures.

45. Sources of Information 1940 Tax Assessment Grid, Director of Records, Jackson County Courthouse, 415 E. 12th St., K.C., MO Building Permit Division of Buildings & Inspection, Public K.C. Works Dept., City Hall, 414 E. 12th St., K.C., MO 64106

46. Prepared by Victoria C Karel & Edward Miszczuk 47. Organization Landmarks Comm 48. Date 49. Revision Date(s) 111-75



State Historical Survey and Planning Office, 909 University Avenue, Suite 215, Columbia, Missouri 65201 HISTORIC INVENTORY 5A-AS-010-010 4. Present Name(s) 1. No. WPT-14A Ruth Sharples Residence 2. County Jackson 5. Other Name(s) 3. Location of Negatives Kansas City William A. Pickering Residence Landmarks Commission 28. No. of Stories 6. Specific Location 16. Thematic Category 29. Basement? Yes X #20 Janssen Place 17. Date(s) or Period No I Kansas City, Mo. 64109 30. Foundation Material 1910 Masonry walls "If "Rural," Township & Vicinity 18. Style or Design 7. City or Town Kansas City, Mo. 31. Wall Construction Italianate Revival 8. Site Plan with North Arrow Masonry and wood 19. Architect or Engineer 32. Roof Type & Material Hip, Shepard, Farrar, & Wiser うしれら 20. Contractor or Builder wood and clay tile 33. No. of Bays N A.E. Taylor Front Side 21. Original Use, if apparent Present 34. Wall Treatment Single family residence 12" face brick 22. Present Use 35. Plan Shape Rectangular Multi-family residence 36. Changes Addition 1 23. Ownership Public ! Private X (Explain Altered X Moved i in #42) 24. Owner's Name & Address, if known 37. Condition Ruth Sharples Interior #20 Janssen Place 9. Coordinates Excellent Exterior Lat. Kansas City, Mo. 64109 Long. 25. Open to Yes x 38 Preservation Yes X Public? Underway? No I Structure | Site ! ! Restricted Building X Object | | 39. Endangered? 26. Local Contact Person or Organization Yes X By What?. No II Yes X Janssen Place Lot Owners Ass 11. On National 12. Is It Yes Register? No X Eligible? Noll 27. Other Surveys in Which Included Possible rezoning 13. Part of Estab. Yes [] District Yes X 40. Visible from Preliminary Inventory of Yes X Hist. Dist.? No X Potent'l? Noll Public Road? No II Architecture & Historic Site Distance from and 15. Name of Established District Landmarks Commission of Frontage on Road Kansas City, Mo. - Nov. 1971 from street 42. Further Description of Important Features Projecting single story extensions from east, south, southwest and north. Northeast elevations ajoined by concrete balustrade terrace. Extensions consist of brick piers and cast iron columns supporting an entablature ornamental deck. Assymetrical designed facades. Main (east) facade contains main entrance portico place off-center to the The extreme south bay on first story has an engaged (cont. on attached sheet) 43. History and Significance William A. Pickering, Vice President of the W. R. Pickering Lumber Co., was the first owner and occupant of #20 Janssen Place. Erected in 1909-10, Mr. Pickering commissioned the local architectural firm of Shepard, Farrar, and Wiser to design the residence. The builder was A. E. Taylor. 44. Description of Environment and Outbuildings Residence lies on western ahlf of Janssen Place. Main entrance faces east. To the north and south lies additional Janssen Place residences. To the west are other Hyde Park residences. 45. Sources of Information 46. Prepared by Victoria The Southern Architect, First Annual Review of the Architectural Karel & Edward Miszczuk Exhibit, Ben J. Lubschez, ed. conducted by K. C. Chapter A.I. A7. Organization Kansas City Landmarks Commission Sept., 1912. 49. Revision Date(s) 48. Date (cont. on attached sheet) 11/75

HISTORIC INVENTORY - State Historical Survey and Planning Office

Ruth Sharples Residence #20 Janssen Place Kansas City, Mo.

Page two

42. Further Description of Important Features

brick chimney flanked by bow windows. Bow windows ornamented with leaded art glass panes places on north and east facades. Fenestration consists of rectangular double-hung sash windows outlined by cut stone frames placed on first and second story. Third story fenestration consists of double casement windows with lozenge-pattern lights. Wall spaces are ornamented with stone stringcoursing. The wood frame, low-pitched hip roof is surfaced with red clay Spanish tiles. Brackets in double or triple groups support a box cornice. Engaged brick chimneys are placed along south, east facades, and northwest corner. A porte-cochere is located along the north elevation.

Alterations: Brick face, exterior walls painted pink. Removal of balustrades from atop single story porticos. Originally, the open terrace adjoining south and southwest porticos has been enclosed. Removal of orb lamps and standards from main entrance portico.

45. Sources of Information

Encyclopedia of History of Missouri, Vol. 5, p. 130


Building Permits, Division of Buildings and Inspection, City Hall, 414 E. 12th St., Kansas City, Mo. 64106

Tax Assessment Grid, Director of Records, Jackson County Courthouse, 415 E. 12th Street, Kansas City, Mo. 64106

Western Contractor, Vol. 18, No. 478, March 9, 1910, p.5



A-AS-010-011



ting, upper portion is surfaced with stucco. Entrances are located on two-story main structure and on south exten sion. A bow window is located on second story, east fa-

43. History and Significance Garage erected by and served William A. Pickering, Vice President of the W.R. Pickering Lumber Co., the first owner and occupant of #20 Janssen Place. Erected in 1909-10, Mr. Pickering commissioned the local architectural firm of Shepard, Farrar, & Wiser to design the garage. builder is A.E. Taylor.

44. Description of Environment and Outbuildings Garage lies on west side of Janssen Place. the east lies accompanying residence, #20 Janssen Place, to the north lies #6 Janssen Place Garage; to the south lies additional lots and structures.

45. Sources of Information 1940 Tax Assessment Grid, Director of Records, Jackson County Courthouse, 415 E. 12th St., K.C., MO

46. Prepared by Victoria (Karel & Edward Miszdzuk 47. Organization C Landmarks Comm.

Date 49. Revision Date(s) 11-75



Landmarks Comm

49. Revision Date(s)

48. Date

111-75

IN

Chicago, 1908, pp. 307-8.

(Con't. p. 2)

HISTORIC INVENTORY -- State Planning Survey and Planning Office

Mr. & Mrs. Joseph Kostelac Residence #27 Janssen Place Kansas City, Mo.

Page two

32. Roof Type & Material

wood frame; asphalt composition and slate turret.

42. Further Description of Important Features

roof. Attic level dormers have A-shaped or pedimented gables. Fenestration consists of rectangular double-humg sash windows of various sizes. Two-story bays placed along south facade walls. Entranceways and some windows surmounted by rectangular transoms. Roofs of the porticos and main structure are high and multiple. An amalgom of Hipped and Gabled types. Roof lines and cornice meet at right angles. Entablatures contain dentils and bracket supported cornices. Roofs surfaced with asphalt shingles except for roof of north facade turret which is surfaced with slate shingling. Pointed finials cap the turret and main structure's roofs. Buff brick chimneys are placed near the northeast and southeast corners of the dwelling.

45. Sources of Information

Jackson County Historical Society Journal, "Janssen Place (1897-1964)," by Martha Rowe Larson, Vol. V, No. 15, Nov., 1964, pp. 10-13.
Tax Assessment Grid, Director of Records, Jackson County Courthouse, 415 E. 12th St., Kansas City, Mo. 64106



State Historical Survey and Planning Office, 909 University Avenue, Suite 215, Columbia, Missouri 65201 HISTORIC INVENTORY A-AS-010-012 1. No. WPT-15 A 4. Present Name(s) Mr. and Mrs. Herbert G. Kamen Residence 2. County Jackson 5. Other Name(s) Location of Negatives Kansas City Joseph M. Bernardin Residence Landmarks Commission 6. Specific Location 16. Thematic Category 28. No. of Stories 29. Basement? Yes X #42 Janssen Place No I 17. Date(s) or Period Kansas City, Mo. 64109 30. Foundation Material 1910 City or Town If Rural, Township & Vicinity Kansas City, Mo. Masonry walls 18. Style or Design = georgian 31. Wall Construction Neo-Colonial Revival 8. Site Plan with North Arrow 19. Architect or Engineer Masonry and wood 32. Roof Type & Material M.P. Unknown 20. Contractor or Builder gambrel, wood & shingle 36th St. 33. No. of Bays Joseph Hellman Front Side 21. Original Use, if apparent 34. Wall Treatment Single family residence 12" face brick 22. Present Use 35. Plan Shape Rectangular Single family residence Addition 36. Changes 23. Ownership Public !! Private 1x (Explain Altered i Moved i in #42) 24. Owner's Name & Address, f known 37. Condition Mr. and Mrs. Herbert G. Kamer Excellent Interior 9. Coordinates UTM #42 Janssen Place Excellent Exterior Lat Kansas City, Mo. Long 25. Open to Yes X 38. Preservation Yes X Public? Restricted Underway? No I Structure Site Building X Object 39. Endangered? 26. Local Contact Person or Organization Yes X By What?. No I Yes X 11. On National 12 Is It Yes Janssen Place Lot Owners Ass Possible rezoning Eligible? Register? Nox No 27. Other Surveys in Which Included Yes X 13. Part of Estab. Yes 11 14. District Visible from Preliminary Inventory Of Arc 40 Yes X Hist. Dist.? Nox Potent'l? No Public Road? No itecture and Historic Sites 41. Distance from and 15. Name of Established District Kansas City Landmarks Frontage on Road Commission, November, 1974 approx. 75' from street 42. Further Description of Important Features Symmetrically designed facades. Single story extension projecting from south elcuation. Main (east) facade contains centrally placed main entrance, surmounted by fan light. Main entrance is sheltered by the tabernacle frame Open concrete terrace ajoins east and south facades. Fenestration of main facades consists of rectangular double-hung sash windows with upper lights divided into smaller rectangular light (cont. on attached sheet) 43. History and Significance Joseph M. Bernardin of the Bernardin Lumber Co., erected 42 Janssen Place in 1910. Although the architect is unknown at this time, Mr. Joseph Hellman was commissioned to construct the residence. 44. Description of Environment and Outbuildings Residence lies on western half of Janssen Place. Main entrance faces east. To the north and south lies additional Janssen Place residences. To the west are other Hyde Park residences. 45. Sources of Information 46. Prepared by Victoria C. "Who's Who in Kansas City" Karel & Edward Miszczuk Kansas City Star, Sept. 24, 1922 47. Organization Kansas City Building Permit, Division of Buildings and Inspection, Public Landmarks Commission 49. Revision Date(s) 48. Date (cont. on attached sheet) 11-75

HISTORIC INVENTORY - State Historical Survey and Planning Office

Herbert G. Kamen Residence #42 Janssen Place Kansas City, Mo.

Page two

42. Further Description of Important Features

First story windows are placed in keystones. Second story windows are placed in rectangular architraves. Roof is of gambrel form surfaced with asphalt shingles. Dormers consist of gavled type with return, which are visually supported by engaged half-columns. Box cornice supported by brackets. Dormer windows quarded by wrought iron railings placed in round arched architraves. Engaged brick chimney is placed along north and south facade. A portecochere is located along the south facade.

45. Sources of Information

Works Dpt., City Hall, 414 E. 12th St., Kansas City, Mo. Tas Assessment Grid, Director of Records, Jackson County Courthouse, 415 E. 12th St., Kansas City, Mo.



42. Further Description of Important Features Two car, multi-level structure. Main garage entrances face east. Four hinged entrance doors with rectangular windows containing three over three Two gabled roof dormers. Alley entrance to struc ture's basement level. South and north facades contain double-hung sash windows. Gambrel roof has return ends.

1. No.

2. County

Lat.

Long

Register?

Jackson

43. History and Significance Garage erected by and served Joseph M. Bernardin of the Bernardin Lumber Co., who commissioned the contractor, Mr. Joseph Hellman, to construct it in 1910. The architect is unknown at this time.

44. Description of Environment and Outbuildings Garage lies on western side of Janssen Place. To the east lies accompanying residence, #42 Janssen Place. To the north lies additional lots & structures; to the south lies #48 Janssen Place Garage.

45. Sources of Information 1940 Tax Assessment Grid, Director of Records, Jackson County Couthouse, 415 E. 12th St., K.C. MO

46. Prepared by Victoria C Karel & Edward Miszdzuk 47. Organization K.C. Landmarks Comm. 49. Revision Date(s) 48. Date

11-75



State Historical Survey and Planning Office, 909 University Avenue, Suite 215, Columbia, Missouri 65201 HISTORIC INVENTOR 5A-AS-010-015 4. Present Name(s) 1. No. WPT-16 2. County Mr. Charles A. Hogt & Mr. Richard O. Barham Res Jackson 5. Other Name(s) 3. Location of Negatives K.C. Landmarks Commission Burton D. Hurd Residence 6. Specific Location 16. Thematic Category 28. No. of Stories #48 Janssen Place 29. Basement? YesXX Kansas City, Mo. No 1: 17. Date(s) or Period 30. Foundation Material 1900 18. Style or Design 7. City or Town If Rural, Township & Vicinity Masonry walls 31. Wall Construction Kansas City, Mo. Shingle Style 8. Site Plan with North Arrow 19. Architect or Engineer Masonry & wood 32. Roof Type & Material M.P. Unknown 36th St. 1 20. Contractor or Builder e; wd.fra.; slate shingle 33. No. of Bays Unknown 10 Side Front 21. Original Use, if apparent Residence-Single family 34. Wall Treatment native cut 22. Present Use stone; 50% slate shins 35. Plan Shape rectangular Residence - Multi-family 23. Ownership Public I I 36. Changes Addition ! ! Private X Altered | | (Explain in #42) Moved in 24. Owner's Name & Address, if knownMr. Chas. A. Hogt & 37. Condition Mr. R.O. Barham, #48 Janssen Interior 9. Coordinates Place, Kansas City, Mo.64109 Exterior Excellent Lat. YesXX 3 Long. 25. Open to Yes X 38. Preservation Public? Underway? restricted No 11 Noll Structure ! | Siteli Building XI Object 11 39. Endangered? 26. Local Contact Person or Organization YesXX By What? Noll Yes X Possible 11. On National Yes II 12 Is It Janssen Place Lot Owners Ass Register? Eligible? Noll No X 27. Other Surveys in Which Included rezoning of property Yes X 13. Part of Estab. Yes 11 14. District Yesxx Preliminary Inventory of 40. Visible from Ho No X Hist. Dist.? Potent'l? Noll Public Road? Architecture & Historic Site Distance from and 15. Name of Established District K.C. Landmarks Commission, Frontage on Road Nov. 1974 Approx. 75' from st 42. Further Description of Important Features Asymmetrically designed facades. First story surfaced with coursed rubble stone walls. ond & attic stories exterior walls surfaced with shingles. Main (east) facade is dominated by a stone veranda partially extending along wouth facade. Veranda consists of stone pedestal wall with fieldstone boulder columns supporting a shed roof. The southeast portions of the veranda are rounded & capped by convex-shaped roof. (Con't. p.2 43. History and Significance Burton D. Hurd, President of the Joseph O'Leary Machinery Co. was the earliest resident of #48 Janssen Place. Erected by H.D. Train in 1900 both architect and builder are unknown at this time. 44. Description of Environment and Outbuildings Residence lies on western half of Janssen Place. Main entrance faces east. To the north and south lie additional Janssen Place Residences. To the west lie other Hyde Park Residences. 45. Sources of Information 46. Prepared by Victoria C Tax Assessment Grid, Director of Records, Jackson County Karel & Edward Miszczuk Courthouse, 415 E. 12th St., Kansas City, Mo. 47. Organization Hoye, C.W., Hoye City Directories, Hoy City Directory Co., K.C. Landmarks Comm Kansas City, Mo., Years 1900-1905. 49. Revision Date(s) 48. Date 11 - 75

HISTORIC INVENTORY -- State Historical Survey & Planning Office

Mr. Charles A. Hogt & Mr. Richard O. <u>B</u>arham Residence #48 Janssen Place Kansas City, Mo.

Page two

42. Furthur Description of Important Features

Roofs surfaced with asphalt composition shingles sweep down adjoining roof of veranda. Polygonal-shaped, second story hipped roof dormer with bay windows. Fenestration consists of rectangular, small-paned, single & double sash windows. Second and attic levels have broad gabled ends. A Palladian window is employed on the attic story level of south facade. A rubble stone chimney is placed to the south.



State Historical Survey and Planning Office, 909 University Avenue, Suite 215, Columbia, Missouri 65201 ORIC INVEN JA-45-010-016 4. Present Name(s) 1. No. WPT-26 2. County Mr. & Mrs. Charles Conrad Residence 5. Other Name(s) Jackson 3. Location of Negatives K.C. Landmarks Commission Granville M. Smith Residence 6. Specific Location 16. Thematic Category 28. No. of Stories #53 Janssen Place 29. Basement? YesXX 17. Date(s) or Period No ! i Kansas City, MO 64109 SX 30. Foundation Material 1913-14 18. Style or Design 7. City or Town If Rural, Township & Vicinity Masonry Walls 31. Wall Construction Kansas City Italianate Revival 8. Site Plan with North Arrow 19. Architect or Engineer Masonry & Wood 32. Roof Type & Material . P. 36th St. Keene & Simpson 20. Contractor or Builder wd. fra.; clay Spanish 33. No. of Bays Bert L. Elmer side le Front 21. Original Use, if apparent 34. Wall Treatment Residence-single family 22. Present Use 12" face brick 35. Plan Shaperectangular Residence-multi-family 23. Ownership Public 1.1 36. Changes Addition 1: Private X Altered 11 (Explain Moved i in #42) 24. Owner's Name & Address, if known Mr. & Mrs. Charles 37. Condition Conrad, 107 E. Gregory, Interior 9. Coordinates Kansas City, MO Exterior Very good lat Long. 25. Open to Yes X 38. Preservation YesXX Public? No Underway? Noli restricted Site | | Structure 11 Object 11 Building XI 39. Endangered? 26. Local Contact Person or Organization By What Possible No! Yes X 12. Is It 11. On National Yes 14 Janssen Place Lot Owners Assi Register? Eligible? No II rezoning of propert No X 27. Other Surveys in Which Included 13. Part of Estab. Yes I I Yes X Preliminary Inventory of 14. District 40. Visible from Noll Public Road? Hist. Dist.? No X Potent'l? Noll Architecture & Historic Site Landmarks Commission of K.C. 41. Distance from and 15. Name of Established District Frontage on Road MO., Nov., 1974 Approx 75 feet 42. Further Description of Important Features Symmetrically designed facades. Landscaped central walkway. Two-story extensions project from north and south facades. Open concrete terrace extends along entire length of main (west) facade. entrance situated in center bay. Double-leaf doors surmounted by arched tabernacle frame consisting of engaged ornamented terracotta pilasters and centralarch. and fanlight guarded by wrought iron grills. (Con't p.2) 43. History and Significance Granville M. Smith, President of the Common Wealth National Bank, was the original owner and occupant of #53 Janssen Place. Erected in 1913-14, Mr. Smith commissioned the local architectural firm of Keene and Simpson to design the residence and the contracting firm of Bert L. Elmer to construct it. 44. Description of Environment and Outbuildings Residence lies on eastern half of Janssen Place. To the north and south lie additional Janssen Place Main entrance faces west. residences. The the east are other Hyde Park residences. 45. Sources of Information 46. Prepared by Victoria C American's Most Beautiful City, Commercial Club, K.C., Mo, Karel & Ed 1915 Building Permit, Division of Buildings and Inspection 47. Organization Karel & Edward Miszwuk

Dep't. of Public Works, City Hall, 414 E. 12th St., K.C.

64106

(Cont. p.2)

47. Organization

K.C. Landmarks Comm.
48. Date 49. Revision Date(s)

11-75

HISTORIC INVENTORY- State Historical Survey and Planning Office

Mr. & Mrs. Charles Conrad Residence #53 Janssen Place Kansas City, Mo.


Page two.

42. Further Description of Important Features

Fenestration consists of rectangular paired souble-hung sash windows in single or multiple groupings, outlined by brick frames with terracotta corner ornaments. Casement windows on second story above main entrance are grouped in three and outlined by ornamental terracotta frames with wrought iron balastrade. Stone strongcoursing separates second and third stories. Terracotta panels consist of swags and emblematic motifs are placed in wall spaces between third story windows. The wood frame hipped roofs have low projecting box cornice. Roofs are surfaced with green glazed Mission clay tiles. An engaged brick chimney with stone coping is placed along south facade.

45. Sources of Information

Tax Assessment Grid, Director of Records, Jackson County Courthouse, 415 E. 12th St., Kansas City, Mo. 64106



11-75

HISTORIC INVENTORY -- State Historical Survey and Planning Office

Mr. & Mrs. James Cooper Residence #54 Janssen Place Kansas City, Mo.

Page two


42. Further Description of Important Features

Secondary entrance placed in extreme south bay of main facade, consisting of double leaf door, flanked by side windows and columns, surmounted by transoms. Concrete terrace extends along main facade. Fenestration consists of rectangular, double-hung sash windows in single to multiple groupings per bay. First story windows on main facade and doorways are placed in segmental-arched architravy. Attic level consists of gabled roof surgaced with green glazed ceramic tiles. Remainder of roof has a flat-decked sundeck. Projecting box cornice visually supported by brackets. I Gabled roof dormers are symmetrically placed three to the east elevations. Broken pediment end on north facade. Secondary north facade entrance sheltered by tabernacle frame. Engaged brick chimneys placed to north and south facades. Alterations: First story south facade porch originally open; now enclosed.

45. Sources of Information

Tax Assessment Grid, Director of Records, Jackson County Courthouse, 415 E. 12th St., Kansas City, Mo. 64106
Western Contractor, October 25,1916, Vol. 30, No. 826, p. 19.





the J.W. Jenkins and Sons Music Company. The builder of the structure was the Long Construction Company, from designs by the local architectural firm of Shepard, Farrar, & Wiser.

44. Description of Environment and Outbuildings Garage lies on west side of Janssen Place. To the east lies accompanying residence, #54 Janssen Place. To the north lies #48 Janssen Place Garage; to the south lies #66 Janssen Place Garage.

45. Sources of Information 1940 Tax Assessment Grid, Director of Records, Jackson County Courthouse, 415 E. 12th St., K.C., MO

46. Prepared by Victoria Karel & Edward Miszczuk 47. Organization K.C. Landmards Comm, 49. Revision Date(s) 48. Date

11-75



State Historical Survey and Planning Office, 909 University Avenue, Suite 215, Columbia, Missouri 65201 ORIC INVEN 7A-AS-010-019 4. Present Name(s) WPT. 1 No WPT-25 2. County & Mrs. Robert Menees Residence 2 Jackson 3. Location of Negatives K.C. Landmarks Commission Dr. William H. Schutz Residence 6. Specific Location #55 Janssen Place Yesxx 29. Basement? 0 17. Date(s) or Period No 1 Kansas City, Mo. 64109 ks 1911 30. Foundation Material on 18. Style or Design 7. City or Town If Rural, Township & Vicinity Masonry walls 31. Wall Construction Kansas City Italianate Revival 8. Site Plan with North Arrow 19. Architect or Engineer Masonry & Wood Wilder & Wight 32. Roof Type & MateriaM.P. 20. Contractor or Builder wd.fra., clay Mission 33. No. of Baystile shing Nicholas Miller TN 21. Original Use, if apparent 34. Wall Treatment Residence--single family 22. Present Use 12" face brick 35. Plan Shaphear-rect Residence 36. Changes 23. Ownership Addition 1 ! Public 11 Private X (Explain Altered 11 in #42) Moved i 24. Owner's Name & Address, if known Dr. & Mrs. Robert 37. Condition Menees, #55 Janssen Place, Interior 9. Coordinates K.C., Mo. Exterior Excellent 64109 Lat. Long 25. Open to Yes X 38. Preservation Yesxx Public? No 11 Underway? Noll restricted Site 11 Structure 11 Building XI Object [] 26. Local Contact Person or Organization 39. Endangered? Yesxx By What Possible No! Yes X 11. On National Yes II 12 Is It Janssen Place Lot Owners Ass No X Register? Eligible? Noll rezoning of property 27. Other Surveys in Which Included Yes ix 13. Part of Estab. Yes | 1 14. District 40. Visible from Preliminary Inventory of YesXX 0 Hist. Dist.? No X Potent'l? Noll Public Road? Noll Architecture & Historic Site Distance from and 15. Name of Established District K.C. Landmarks Commission, Frontage on Road 75'from st. Approx. 42. Further Description of Important Features Symetrically designed facades. Main (west) facade has a concrete balustraded open terrace extending entire length at facade. Centrally placed main entrance is outlined by a Palladian-style tabernacle frame composed of combined columns & pilasters supporting a central arch ornamented with antemenon. Double leaf doors & flanking side windows are gaurded by wrought iron grills. Fenestration consists of rectangular (con't. p. 43. History and Significance William H. Schutz, M.D. (eye and ear physician) was the original owner and occupant fo #55 Janssen Place. Erected in 1911, Mr. Schutz commissioned the local architectural firm of Wilder and Wight to design the residence and the contracting firm of Nicholas Miller to construct it. 44. Description of Environment and Outbuildings Residence lies on eastern half of Janssen Place. To the north and south lie additional Janssen Main entrance faces west. Place residences. To the east are other Hyde Park residences. 45. Sources of Information 46. Prepared by Victoria C The K.C. Star, "A House Built for the Eye," Feb. 4, 1912 Karel & Edward Building Permit, Division of Buildings and Inspection, 47. Organization Miszczuk Public Works Dep't., City Hall, 414 E. 12th St., KCMO 6410 K.C. Landmarks Comm (con't. p. 2) 48. Date 49. Revision Date(s)

11-75

HISTORIC INVENTORY -- State Historical Survey and Planning Office

Dr. & Mrs. Robert Menees Residence #-55 Janssen Place Kansas City, Mo.

Page two

42. Further Description of Important Features

double-hung sash windows. Windows on first and second story outlined by brick frames. Medium-pitched hip roof is surfaced with green glazed Mission clay tiles. Overhanging eaves with exposed rafters. Hipped-roof dormers are symetrically placed and surfaced with glazed ceramic shingling with double-hung sash windows per dormer. Engaged brick chimney with stone coping are symetrically placed along the north and south facades.

45. Sources of Information

Tax Assessment Grid, Director of Records, Jackson County Courthouse, 415 E. 12th St., Kansas City, Mo. 64106



State Historical Survey and Planning Office, 909 University Avenue, Suite 215, Columbia, Missouri 65201 PRIC INVENTORY 5A-AS-010-020 4. Present Name(s) 1. No. WPT-24 2. County & Mrs. Albert J. Thornberry Residence Jackson 3. Location of Negatives K.C. Landmarks Commission Edna B. Peck Residence 6. Specific Location 16. Thematic Category 28. No. of Stories YesXX n 29. Basement? #61 Janssen Place 17. Date(s) or Period No I ks Kansas City, Mo. 64109 1909 30. Foundation Material 18. Style or Design = Georgian If Rural, Township & Vicinity 7. City or Town Masonry walls 31. Wall Construction Kansas City Neo-Colonial Revival 19. Architect or Engineer 8. Site Plan with North Arrow Masonry & wood 32. Roof Type & Material Amalgom Shepard & Farrar 20. Contractor or Builder gable & gambrel; (con't) 33. No. of Bays Joseph Hellman Front 21. Original Use, if apparent 34. Wall Treatment Residence - Single family 22. Present Use 12" face brick 35. Plan Shape rectangula Residence - Single family 36. Changes 23. Ownership Public 11 Addition I (Explain Altered 1 Moved i in #42) 24. Owner's Name & Address, if known Mr. & Mrs. Albert J. 37. Condition Thornberry, #61 Janssen Place 9. Coordinates Kansas City, Mo. 64109 Exterior Excellent Lat Long 25. Open to 38. Preservation Yes Ix Public? Noil Underway? Noll restricted Site Structure | | Object | | Building X 39. Endangered? 26. Local Contact Person or Organization Yesxx By What? Possible No 11 Yes IX Janssen Place Lot Owners Ass 11. On National Yes !! Eligible? Noll Register? No by 27. Other Surveys in Which Included rezoning of property Yes X 13. Part of Estab. Yes II Preliminary Inventory of 14. District 40. Visible from YesXX Hist. Dist.? No X Potent'l? Noll Public Road? No II Architecture & Historic Site 41. Distance from and K.C. Landmarks Commission. 15. Name of Established District Frontage on Road Nov., 1974 Approx. 75' from st 42. Further Description of Important Features Long axis situated east-west. Asymmetrically designed main (south) facade. First story dominated by a wood frame. L-shaped veranda consisting of paired Tuscan columns connected by balastrades which support a gabled roof with overhanging eaves. Extreme east bays of south facade protude from the building face. facade has two story colonnaded gallery. Fenestration consists of rectangular double-hung (con't. p.2) 43. History and Significance Edna B. Peck, widow of George B. Peck, who was founder of the George B. Peck Dry Goods Co., was the original owner and occupant of #61 Janssen Place. The residence was erected in 1909. The local architectural firm of Shepard & Farrar was commission do design it, and, although the contractor remains unknown, the 1910 addition was constructed by Mr. Joseph Hellman. 44. Description of Environment and Outbuildings Residence lies on eastern half of Janssen Place. Main entrance faces south. To the north and south lie additional Janssen Place Residences. To the west are other Hyde Park Residences. 45. Sources of Information 46. Prepared by Victoria C The K.C. Star, "Once a Residence in Millionaire's Row," Karel & Edward Miszezuk

(con't. p. 2)

April 3, 1932.

Bros. Mfg. Co., 1905, p. 31.

Prives in and About Kansas City, compiled by Studebaker

47. Organization

K.C. Landmarks Comm.

48. Date 49. Revision Date(s)

11-75

HISTORIC INVENTORY -- State Historical Survey and Planning Office

Mr. & Mrs. Albert J. Thornberry Residence #61 Janssen Place Kansas City, Mo.

Page two

- 32. Roof Type & Material asphalt composition shingles.
- sash windows. Some windows are outlined by stone frames. Wood frame roof consists of a combined a le-gam type with overhanging eaves and exposed rafters. Roof partially supported by brackets. Roof dormer contains central window group flanked by side windows. Brackets support a shed roof. An engaged brick chilley symmetrically divides the west facade.
- 45. Sources of Information

1940 Tax Assessment Grid, Director of Records, Jackson County Courthous, 415 E. 12th St., Kansas City, Mo. 64106

Western Contractor, Vol. 17, No. 5, August 4, 1909, p.3.



State Historical Survey and Planning Office, 909 University Avenue, Suite 215, Columbia, Missouri 65201 HISTORICHNVENT TA-AS-010-02 4. Present Name(s) WPT-18 2. County Mrs. J. Phillip Jones Residence Jackson 3. Location of Negatives K.C. Landmarks Commission Edward L. Foutch Residence 16. Thematic Category 28. No. of Stories 21 6. Specific Location #66 Janssen Place 29. Basement? YesXX 17. Date(s) or Period KansasCity, Mo. 64109 1912-13 30. Foundation Material 18. Style or Design Masonry walls If Rural, Township & Vicinity 7. City or Town Kansas City 31. Wall Construction Jacobethan Revival 8. Site Plan with North Arrow 19. Architect or Engineer Masonry & Wood 32. Roof Type & MateriaM. P. hip; Smith, Rea, & Lovitt 20. Contractor or Builder wd.fra.; asphaltcomp shingles Side T.E. Smith & Son 33. No. of Bays Front 3 21. Original Use, if apparent 34. Wall Treatment Residence - Single family 22 Present Use 12"face brick 35. Plan Shape rectangular Residence - Multi-family 23. Ownership Public 11 36. Changes Addition 1: Private X (Explain Altered 11 in #42) Moved in 24. Owner's Name & Address, if known Mr. & Mrs. J. Phillip37. Condition Jones, #66 Janssen Place, 9. Coordinates Exterior Excellent Kansas City, Mo. Lat. Long 25. Open to Yes X 38. Preservation Public? No 11 Underway? restricted Structure | Site Building X Object | | YesXX 39. Endangered? 26. Local Contact Person or Organization By What? Possible No!! Yes X 11. On National Yes !! 12. Is It Janssen Place Lot Owners Assi No X Noll Register? 27. Other Surveys in Which Included rezoning of property Yes X 13. Part of Estab. Yes I I 14. District 40. Visible from Preliminary Inventory of Yesxx Nox Hist. Dist.? Potent'l? Noll Public Road? Noll Architecture & Historic Site 41. Distance from and 15. Name of Established District K.C. Landmarks Commission Frontage on Road Nov., 1974 Approx. 42. Further Description of Important Features Asymmetrically designed facades Two story brick extension from south elevation. (east) facade dominated by a two-bay wide veranda composed of brick piers supporting a wood frame shed roof. Open terrace extensions adjoin south and east facade. Fenestra tion consists of rectangular double-hung sash windows outlined by stone frames. Upper sashes divided into rectangular lights. Extreme north bay of main (Con't. p.2) 43. History and Significance Edward L. Foutch, Vice President of the B-R Electric and Telephone Mf'g. Co., erected #66 Janssen Place in 1912-13. The local Architectural firm of Smith, Rea, and Lovitt was commissioned to design the residence and the contracting firm of T.E. Smith and Son was commission to construct 44. Description of Environment and Outbuildings Residence lies on western half of Janssen Place. Main entrance faces east. To the north and south lie additional Janssen Place of Residences. To the west are other Hyde Park Residences. 45. Sources of Information 46. Prepared by Victoria C

lic Works Department, City Hall, 414 E. 12th St., KCMO

Courthouse, 415 E. 12th St., Kansas City, Mo. 64106

Tax Assessment Grid, Director of Records, Jackson County

Building Permit, Division of Buildings & Inspection, Pub-Karel & Edward Miszczuk 47. Organization Landmarks Comm 48. Date 49. Revision Date(s) 11-75

HISTORIC INVENTORY -- State Historical Survey & Planning Office

Mr. & Mrs. J. Phillip Jones Residence #66 Janssen Place Kansas City, Mo.

Page two

42. Furthur Description of Important Features

facade protrudes. Wood framed, hipped roof surfaced with asphalt composition shingles. Roof contains gable wall and roof dormers surfaced with board and batten stickwork with projecting rafters and eaves. Roof dormers are placed along north and south elevations. Engaged brickkchimney is placed along south facade.



State Historical Survey and Planning Office, 909 University Avenue, Suite 215, Columbia, Missouri 65201 ORIC INVENT 5-010-07 4. Present Name(s) WPT-23 2. County & Mrs. E. Tom Newcomer Residence Jackson 3. Location of Negatives Ralph E. Byrne Residence K.C. Landmarks Commission 16. Thematic Category 28. No. of Stories 21/2 . Specific Location #67 Janssen Place YesXX 29. Basement? Kansas City, Mo. 64109 No 1: 17. Date(s) or Period 1912 30. Foundation Material Masonry walls 18. Style or Design = Georgian Kansas City If Rural, Township & Vicinity 31. Wall Construction Neo-Colonial Revival 8. Site Plan with North Arrow 19. Architect or Engineer Masonry & Wood Shepard, Farrar, & Wiser 32. Roof Type & MateriaM.P. gable 36th St 20. Contractor or Builder wd.fra.; asph.comp.over 33. No. of Bayswd shingle Eront 7 Christopher Heinz Front 3 21. Original Use, if apparent Residence - Single Family 34. Wall Treatment 22. Present Use Stone & Wood frame 35. Plan Shape rectangular Residence - Single family 23. Ownership Public 11 36. Changes Addition 1: AlteredXX Private IX (Explain in #42) Moved i 24. Owner's Name & Address, if known Mr. &Mrs. E. Tom New-37. Condition comer, #67 Janssen Place, 9. Coordinates Kansas City, Mo. Excellent Exterior Lat. Long 25. Open to Yes X 38. Preservation YesXX O Public? Underway? Noll restricted Siteli Structure 11 Building X Object 11 39. Endangered? 26. Local Contact Person or Organization By What? Possible Possible Yes X Janssen Place Lot Owners Ass 11. On National Yes !! 12 Is It No X Register? Eligible? Noll 27. Other Surveys in Which Included rezoning of propert Yes Ix 13. Part of Estab. Yes III Yes XX RO 14. District Preliminary Inventory of 40. Visible from No X Hist. Dist.? Potent'l? Noll Public Road? Architecture & Historic Site 41. Distance from and 15. Name of Established District K.C. Landmarks Commission, Frontage on Road Nov., 1974 42. Further Description of Important Features Symmetrically designed facades. First story surfaced with cut rubble stone laid in broken Second and attic stories gabled walls consist of stuccoed wood shingles. On main (west) facade, the first story has a projecting centrally placed main entrance, flanked by Tuscan columns which support a hipped roof with a low projecting box cornice. Flanking bays have Chicago style double-hung sash windows. Second story (Con't. p.2) 43. History and Significance Mr. Ralph E. Byrne, employed by the J.M. Byrne Lumber Co., was the earliest known resident of #67 Janssen Place. It was erected in 1912; the local architectural firm commission to design the residence was Shepard, Farrar, & Wiser. The construction firm of Christopher Heinz was the builder. 44. Description of Environment and Outbuildings Residence lies on eastern half of Janssen Place. Main entrance faces west. To the north and south lie additional Janssen Place Residences. To the west are other Hyde Park Residences. 46. Prepared by Victoria C 45. Sources of Information Building Permit, Division of Buildings & Inspection, Pub-Karel & Edward Miszczuk lic Works Department, City Hall, 414 E. 12th St., KCMO 47. Organization Tax Assessment Grid, Director of Records, Jackson County K.C. Landmarks Comm

Courthouse, 415 E. 12th St., Kansas City, Mo. 64106

48. Date

11-75

49. Revision Date(s)

HISTORIC INVENTORY -- State Historical Survey and Planning Office

Mr. & Mrs. E. Tom Newcomer Residence #67 Janssen Place Kansas City, Mo.

Page two

42. Furthur Description of Important Features

of west facade has a central double-hung sash window flanked by two narrow double-hung sash windows with panes divided into lozenge lights by leaded tracery. Fenestration consists primarily of double-hung sash windows. Wood frame roof is gabled with overhanging eaves. Attic level consists of a shed roof dormer. On west facade dormer contains a central group of three double-hung sash windows flanked by single double-hung sash windows. An engaged stone chimney is placed along the south facade.



48. Date

11-75

49. Revision Date(s)

HISTORIC INVENTORY -- State Historical Survey and Planning Office

Mrs. & Mrs. Les White Residence #73 Janssen Place Kansas City, Mo.

Page two

42. Further Description of Important Details

of rectangular double-hung sash windows. Stone string coursing separates red brick first story and buff brick second story. On the ce-ter bays of the second story are smaller double-sash windows with engages pilasters to either side of each window. Wall panels between center windows are ornamented with circular disks. Low, projecting box cornice. High pitch hipped roof. Attic level consists of hooded roof dormers symmetrically placed above the roof line of all four elevations. A high, projecting side slope brick chimney is located along south elevation. A porte-cochere is located along the north elevation.

45. Building Permit, Division of Buildings and Inspection, Public Works Dep't., City Hall, 414 E. 12th St., Kansas City, Mo. 64106

1940 Tax Assessment Grid, Director of Records, Jackson County Courthouse, 415 E. 12th St., Kansas City, Mo. 64106



State Historical Survey and Planning Office, 909 University Avenue, Suite 215,

HISTORIC INVENTORY - State Historical Survey & Planning Office

#73 Janssen Place Garage 73 Jannsen Place Kansas City, MO

page two

42. Further Description of Important Features placed rectangular Cupola.



(Con't. p.2)

49. Revision Date(s)

48. Date

11 - 75

HISTORIC INVENTORY -- State Historical Survey and Planning Office

Mr. & Mrs. George Tucker, Jr. Residence #80 Janssen Place Kansas City, Mo.

Page two

18. Style or Design

Influenced Amalgam

42. Furthur Description of Important Features

bay protrudes slightly outwards. Secondary entrance is placed in south facade wing. Fenestration consists of rectangular double-hung sash windows. Windows on first story placed in segmentally-arched architraves with radiating stepped voussoirs. Windows on second story placed in rectangular architraves and contain wrouth-iron balconies. Above main entrance is a Chicago sash bow window consisting of a central sash divided into rectangular lights, by leaded tracery which is flanked by narrow side windows. Massive ornate entablature visually separates second and attic stories. Entablature is composed of moulded architrave dentils and low projecting cornice supported by scrolled brackets. Corners of the building on the south facade wing and main entrance bay are recessed and pulvinated. Wood frame hipped roof is surfaced with green glazed ceramic tiles. Hipped roof shelter central structure. South facade wing is a flat sun deck. Symetrically placed hooded roof dormers with segmentally-arched windows placed on all four elevations. A massive brick chimney is located along south facade.

Alterations: Removal of stone balustrade from east facade terrace and south facade sun deck.

45. Sources of Information

Building Permit, Division of Buildings & Inspection, Public Works Dept., City Hall, 414 E. 12th St., KansasCity, Mo. 64106 Tax Assessment Grid, Director of Records, Jackson County Courthouse, 415 E. 12th St., Kansas City, Mo. 64106



County Courthouse, 415 E. 12th St., K.C., MO

K.C. Landmarks Comm.
48. Date 49. Revision Date(s)
11-75

47. Organization



M

April 22, 1928, p.66.

(con't. p. 2)

K.C. Landmarks Comm

48. Date 49. Revision Date(s)

11-75

HISTORIC INVENTORY -- State Historical Survey and Planning Office

Bishop Charles Helmsing Residence #88 Janssen Place Kansas City, Mo.

Page two

42. Furthur Description of Important Features

side windows surmounted by fanlight. The Fenestration consists of rectangular double-hung sash windows placed in rectangular architraves. Wood frame gabled roof is surfaces with asphalt composition shingles. Three pedimented roof dormers each containing sash windows placed symmetrically along east and west elevations. South facade gable end has a solitary double sash window. North facade has paired one-quarter circular casement windows. Brick chimneys placed on north and west facades.

45. Sources of Information Societ

Jackson County Historical Society Journal, "Janssen Place (1897-1964)," Martha Rowe Larson, Vol. V, Nov., 1964, No. 15, pp. 10-13.

Building Permit, Division of Buildings & Inspection, Public Works Department, City Hall, 414 E. 12th St., Kansas City, Mo. 64106

1940 Tax Assessment Grid, Director of Records, Jackson County Courthouse, 415 E. 12th St., Kansas City, Mo. 64106



State Historical Survey and Planning Office, 909 University Avenue, Suite 215,



State Historical Survey and Planning Office, 909 University Avenue, Suite 215, Columbia, Missouri 65201 4. Present Name(s) 1 No. WPT-21 2. County Mrs. Lou Caceres Residence Jackson 5. Other Name(s) 3. Location of Negatives K.C. LandmarksCommission William C. Bowman Residence 28. No. of Stories 21 6. Specific Location 16. Thematic Category #96 Janssen Place 29. Basement? YesXX Kansas City, Mo. 64109 Nol 17. Date(s) or Period 30. Foundation Material 1911 18. Style or Design = gurgium 7. City or Town If Rural, Township & Vicinity Masonry walls Kansas City 31. Wall Construction Neo-Colonial Revival 8. Site Plan with North Arrow 19. Architect or Engineer Wood frame Shepard, Farrar, & Wiser 32. Roof Type & Material M.P. gable 20. Contractor or Builder wd.fra.; asphaltcomp. shng 33. No. of Bays Carl A. Nilson TN Front 21. Original Use, if apparent 34. Wall Treatment surfaced Residence - Single family 22. Present Use wood claphoard 35. Plan Shape Rectangular Residence - Multi-family 36. Changes Addition ! 23. Ownership Private X (Explain AlteredXX in #42) Moved i 24. Owner's Name & Address. if known Mrs. Lou Caceres 37. Condition #96 Janssen Place, Kansas Interior 9. Coordinates City, Mo. 64109 Excellent Exterior Lat Long 25. Open to Yes X 38. Preservation YesX Public? Underway? Noll No Structure 1 restricted Site Building X Object | | 26. Local Contact Person or Organization 39. Endangered? Yesxx No 11 Yes X 11. On National Yes !! 12. Is It Possible Janssen Place Lot Owners Asst Register? No X Eligible? Noll rezoning of property 27. Other Surveys in Which Included Yes X 13. Part of Estab. Yes II 14. District Preliminary Inventory of 40. Visible from YesXX Noll Public Road? Hist. Dist.? No X Potent'l? Architecture & Historic Sites Noll K.C. Landmarks Commission, 41. Distance from and 15. Name of Established District Frontage on Road Nov., 1974 75' Approx. from st 42. Further Description of Important Features Symmetrically designed facades. Two single story extenstions project from south and east elevations. Main (east) facade is dominated by a threebay wide colonnaded veranda consisting of concrete deck with cast iron Tuscan columns clustered in three to four groupings which support a flat deck guarded by solid balustrade. Central portion of veranda protrudes slightly outward. Cast iron and glass canopy place (Con't. p.2) 43. History and Significance William C. Bowman, President of the W.C. Bowman Lumber Co., erected #96 Janssen Place in 1911. The local architectural firm selected to design the residence was Shepard, Farrar, & Wiser; the contracting firm commissioned for the construction was Carl A. Nilson. 44. Description of Environment and Outbuildings Residence lies on western half of Janssen Place. Main entrance faces east. To the north lie additional Janssen Place residence To the south lies the Notre Dame de Sion School. To the west are other Hyde Park Residences. 45. Sources of Information 46. Prepared by Victoria C The K.C. Star, "Glimpses of a Small, Distinctive Residen-Karel & Edward Miszczuk tial Section That was Platted by a Pioneer Promoter," Sun-47. Organization day, April 22, 1928, p. 6C. Landmarks Comm

(Con't. p.2)

49. Revision Date(s)

48. Date

11-75

HISTORIC INVENTORY -- State Historical Survey and Planning Office

Mrs. Lou Caceres Residence #96 Janssen Place Kansas City, Mo. 64109

Page two

42. Furthur Description of Important Features.

along north side of veranda. Main entrance placed in central bay consists of single leaf door flanked by anarrow side windows surmounted by fanlight. Secondary entrance placed on south facade wing is identical in design to main entrance. Fenestration consists of rectangular double-hung sash windows on first and second stories. Windows on first and second stories flanked by wooden shutters. Hinged windows on south side of south facade wing surmounted by transoms. Wood frame, gabled roof is surfaced with asphalt composition shingles. Gabled roof dormers with overhanging eaves contain sash windows symmetrically placed along east elevation. Engaged brick chimneys are placed one along the south facade and two along the north facade.

Alterations: Removal of balustrade wall which topped the south facade wing.

45. Sources of Information

Jackson County Historical Society Journal, "Janssen Place (1897-1964)," Martha Rowe Larson, Vol. V, Nov., 1964, No. 15, pp. 10-13.

Building Permit, Division of Buildings & Inspection, Public Works Department, City Hall, 414 E. 12th St., Kansas City, Mo.

Tax Assessment Grid, Director of Records, Jackson County Courthouse, 415 E. 12th St., Kansas City, Mo. 64106

