


Hall of Waters Survey District


37 Surveyed building

12 Prior survey - 1991



eyed building  Prior survey - 1991

Figure 2



S. Marietta Street Survey

- 95 Surveyed building
- 17 Prior survey - 1991


Figure 3



Central Park Survey District

134 Surveyed building

20 Prior survey - 1991



building  Prior survey - 1991




Figure 6