MISSOURI	HISTORIC	PRO	JPER	LA IN	VENT	ORY	FO	PRM						JA-AS-053-001
REFERENCE NU	IMBER	A	. HISTO	RIC NAM	IE						Tan Tan S			
93JA	7 0244		HIC	KORY	HILLS	FAI	RM C	COMP	LEX,	FA	RM HO	JSE		
B. COUNTY		C	C. OTHER	R NAME(S)									
09 5 JA	CKSON		EAS'	T HIG	н ѕсно	OOL	OUI	DOO	R LA	AND	RESEA	RCH LABORATORY	Z .	
D. ADDRESS								E. C	ITY					F. VICINITY G. RESTRICTED H. ACREAGE
47th St	reet								KAN	ISAS	CITY			100
I. SECTION	J. TOWNSHI	Р	K. RAI	NGE	L. S	SPAN	ISH L	AND C	RANT		M. QU	ARTER SECTIONS	N. OWNERSHIP	
29	49N			32W									PRIVATE	LOCAL STATE FEDERAL MIXED
O. AGENCY(S)	-													
1. KANSAS	CITY SCHOO	L D	ISTRI	CT								2.		
P. UTM ZONE	EASTING				NORTH	HING					USGS	QUADRANGLE		Q. AREA(S) OF SIGNIFICANCE/CONTEXT(S)
1.	/ /	/	/	/	/	/	/	/	/	/				1. O 1 O AGRICULTURE
2.	/ /	/	/	/	/	/	/	/	/	/				2.
3.	/ /	/	/	/	/	/	/	/	/	/				3.
4.	/ /	/	/	/	/	/								4.
R. SIGNIFICAN		•					T. 8	SIGNIF	ICAN	CE				
1. GOSSETT	, ALFRED N													
2.														
3.							1							
	T EVENT DATE(S)												
1.														
														☐ SEE CONTINUATION SHEET
2							1							L GEL CONTINUATION SHEET

MO 780-1257 (5-92)

MISSOURI DEPARTMENT OF NATURAL RESOURCES HISTORIC PRESERVATION PROGRAM

P.O. BOX 176 JEFFERSON CITY, MO 65102

2.A. ARCHITECT/BUILDER/DESIGNER/ENGINEER			
1.	2.	3.	
2.B. ARCHITECTURAL STYLE		2.C. VERNACULAR TYPE	
		4 9 UNDETERMINED	
2.D. CONSTRUCTION DATE (CIRCA) 2.E. ALTERATION	ON DATE	•	
EARLY 20th CENTURY 1.	2.	3.	4. 5.
2.F. RECONSTRUCTION DATE (CIRCA) 2.G. DATE MOV	ED 2.H. DESTRUCTION DATE	2.I. OWNER'S NAME & ADDRESS (IF DIFF	ERENT)
	JAN. 1993		
2.J. HISTORIC FUNCTION			
1. O DOMESTIC 2.	3.	4.	5
2.K. HISTORIC SUBFUNCTION			
1. O 1 A SINGLE DWELLING.	3.	4. -	5.
2.L. NO. OF ANCILLARY STRUCTURES	2.M. RESOURCE TYPE	2.N. STORIES	
	X BUILDING SITE STRUCTURE	ОВЈЕСТ 1	2 3
2.O. STRUCTURAL SYSTEMS	2.P. EXTERIOR WALL MATERIALS	2.Q. OTHER MATERIALS	
1. W W WOOD FRAME	1. 2 1 CLAPBOARD	1. []]	3
2.	2.	2.	4.
2.R. ROOF SHAPES	2.S. ROOF MATERIALS	2.T. ROOF FEATURES	
1. GBGABLE	1. <u>ββ</u> ASPHALT	1. []]	4.
			2.U. FOUNDATION MATERIALS
2. SD SHED	2.	2.	1. 4 3 LIMESTONE
3.	3.	3.	2.
2.V. PORCHES			2.W. PLAN
1. OBOTHER BAY	2.	3.	O T OTHER
2.X. FURTHER DESCRIPTION	(SEE CONTINUATION SHEET)	2.Y. DESCRIPTION OF ENVIRONMENT AN	ID OUTBUILDINGS (SEE CONTINUATION SHEET)
2.Z. SOURCES OF INFORMATION	PREPARED BY Java awers	ORGANIZATION	DATE
(SEE CONTINUATION SHEET)			

MISSOURI HISTORIC BUILDING INVENTORY FORM - CONTINUATION SHEET

JA-AS-033-001

REFERENCE NUMBER A. HISTORIC N			C. ADDRESS		
COSPANIES SERVICES SALVES SALV	Hills Farm Complex	Jackson	47th Street	Kansas City	
Farm Ho	use				

The frame farm house was constructued at the top of the hill south of the log house and was used as the caretakers residence during the years the farm was owned by Mr. Gossett. The original section of the house (which is one and one half stories with a one story section to the north) contain the sleeping and living areas. The apparent additions to the house include the kitchen and bathroom to the north, and the porch to the east. Both the original house and the additions were built on rubble limestone foundations with a basement under the kitchen and one story section of the original house only. A cistern was also added in the ground under the porch floor. Stone steps lead down from the porch to stone lined paths that connect to the front gate and drive and down the hill to the log house. This house sustained fire damage on the northwest corner of the kitchen probably from a wood burning stove that once stood there.

The squared and coursed rubble limestone foundation walls support the balloon framed structure of the house. The exterior of the walls is covered with beveled siding with 4" of the board exposed. This siding was trimmed around the doors and windows and at all corners with 4" trim pieces. The exterior was painted. The types of windows and doors on this structure are difficult to determine because of the deteriorated state of the structure. The roof is currently composed of asphalt shingles with one gutter on the north side which deposites water into the cistern.

Plumbing in the house was limited to the kitchen/bathroom addition and a hot water heater was added at some time. The house was wired for electricity but no evidence of a heating system other than stoves was found. Interior finishes include lath and plaster in the original part of the house with gypsum board walls in the addition. Wallpaper was used as a wall covering and the floors are hardwood.



















MISSOURI HISTORIC PROPERTY INVENTORY FORM

JA-AS-033-002

REFERENCE NUMBER	A. HISTORIC NAME			VII. VII. VII. VII.	
93JA 0245	HICKORY HILLS FARM	COMPLEX, LARGE	E BARN		
B. COUNTY	C. OTHER NAME(S)				
lo 1915 Jackson	EAST HIGH SCHOOL	L OUTDOOR LAND	RESEARCH LABORATO	TY	
D. ADDRESS		E. CITY		F. VICINITY G. RESTRICTED H. ACRE	EAGE
47 th STREET		KANSAS CIT	Y	100)
I. SECTION J. TOWNSHIP	K. RANGE L. SPAN	SH LAND GRANT	M. QUARTER SECTIONS	N. OWNERSHIP	
29 49N	32 <u>₩</u>			PRIVATE LOCAL STATE FEDER	RAL MIXED
O. AGENCY(S)					
1KANSAS CITY SCHOOL	DISTRICT		2.		
P. UTM ZONE EASTING	NORTHING		USGS QUADRANGLE	Q. AREA(S) OF SIGNIFICANCE/CONTEXT	(S)
1 / /	/ / / / /	/ / / /		1. [0 1 0]AGRICULTURE	
2 / /	/ / / / /	/ / / /		2.	
3 / /	/ / / / /	/ / / /		3.	
	/ / / / /	/ / / /		4.	
R. SIGNIFICANT PERSON(S)		T. SIGNIFICANCE			
1. GOSSETT, ALFRED N.					
2.					
3.					
S. SIGNIFICANT EVENT DATE(S)					
1.					
				-	
2.				☐ SEE CONTINUATION SHEET	

MO 780-1257 (5-92)

TA-AS-033-002

2.A. ARCHITECT/BUILDER/DESIGNI	ER/ENGINEER								
1.			2.			3.			
2.B. ARCHITECTURAL STYLE				2.C. VERNACULAR TYPE					
2.D. CONSTRUCTION DATE (CIRCA)	2.E. ALTERATIO	ON DATE							
EARLY 20th CENTURY	1, .		2.	3	i.		4.	5.	
2.F. RECONSTRUCTION DATE (CIRCA)	2.G. DATE MOVE	ED	2.H. DESTRUCTION DATE	2.I. OW	NER'S NAME	& ADDRESS (IF DIFF	ERENT)		
			JAN. 1993						
2.J. HISTORIC FUNCTION									
1. 0 9 AGRICULTURE	2.		3.		4.			5.	
2.K. HISTORIC SUBFUNCTION	,								
1.	2.		3.		4.			5.	
2.L. NO. OF ANCILLARY STRUCTUR		2.M. RESOUR				2.N. STORIES			
		BUILDIN	G SITE STRUCTURE	ОВЈЕС	т	11	2	<u>1</u> 3	
2.O. STRUCTURAL SYSTEMS		2.P. EXTERIO	R WALL MATERIALS	2.Q. O	THER MATER	The second secon			
LOAD GEARING	i	1. 14 3	LLIMESTONE	1. L			;	3.	
2. WWWOOD FRAME		2.	į.	2.				4.	
2.R. ROOF SHAPES		2.S. ROOF MA	TERIALS	2.T. R	OOF FEATUR	ES			
1. LIGIB GABLE		1. 6 3	LASPHALT	1. L				4.	
4322							2	2.U. FOUNDATION MATERIALS	
2.		2.		2				1. [4]3]LIMESTONE	
3.		3.	1	3.			- [:	2.	
2.V. PORCHES							2	2.W. PLAN	
1.		2.	1	3. [[]R [C] RECTANGLE	
2.X. FURTHER DESCRIPTION			(SEE CONTINUATION SHEET)	2.Y. DE	SCRIPTION	OF ENVIRONMENT A	ND OUTBL	JILDINGS (SEE CONTINUATION SHEET)	
2.Z. SOURCES OF INFORMATION		PREPARED BY	Jun avers		ORGANIZA	TION		DATE	
(SEE CONTINUATION SHEET)									

MISSOURI HISTORIC BUILDING INVENTORY FORM - CONTINUATION SHEET

JA-AS-033-002

A. HISTORIC NAME Hickory Hills Farm Complex	B. COUNTY	C. ADDRESS		_
Large Barn	Jackson	47th Street	Kansas City	

This barn was used for hay storage and winter livestock protection. A frame addition to the southeast is a Grade A milk barn. This barn has rubble limestone walls with wood center support posts and a wood end gable and trusses. The main floor and loft spaces were used for hay storage. A drive through runs the length of the barn from the northwest to the south east. Access is through sliding double doors at each end. Due to a rapid drop in grade the barn has a partial lower story which runs the full length of the northeast elevation. Another lower room, approximately 16' x 20' is under the southeast corner. The lower level can be accessed by large Roman-arched openings in the northwest and southeast elevations. There is no evidence of windows on the northeast elevation. The southwest elevation has square windows evenly spaced. Square windows flank each side of the double doors on the facade (northwest) elevation; there is no evidence of windows on the southeast elevation. An earthen ramp with a concrete walkway beneath, leads up to the double doors on the southeast elevation. The configuration of the milk barn addition and the livestock pens on the southwest elevation are unclear due to their state of deterioration. This barn was deemed a hazard by the school district and the roof was pulled down.















MISSOURI HISTORIC PROPERTY INVENTORY FORM

JA-AS-033-003

REFERENCE NU		A. HISTORIC NAME				
93JA	0239	HICKORY H	ILLS FARM	COMPLEX, LOG	HOUSE	
B. COUNTY		C. OTHER NAME(S)				
0 9 5 JA	CKOON	EAST HIGH	SCHOOL OU	UTDOOR LAND R	RESEARCH LABORATORY	
D. ADDRESS				E. CITY		F. VICINITY G. RESTRICTED H. ACREAGE
	Street			KANSAS C	CITY	100
I. SECTION	J. TOWNSHIP	K. RANGE	L. SPANISH	LAND GRANT	M. QUARTER SECTIONS	N. OWNERSHIP
29	49N	32W				PRIVATE LOCAL STATE FEDERAL MIXED
O. AGENCY(S)				-		
1. KANSAS	CITY SCHOOL I	DISTRICT			2.	
P. UTM ZONE	EASTING		NORTHING		USGS QUADRANGLE	Q. AREA(S) OF SIGNIFICANCE/CONTEXT(S)
1.	/ /	/ / /	/ /	/ / / /		1. 0 3 0 ARCHITECTURE
						EXPLORATION/
2.	/ / /	/ / /	/ /	/ / / /		2. \[\begin{array}{c cccc} 1 & 4 & 0 \end{array} \] SETTLEMENT
						0.1.0.450757777777
3.		/ / /	/ /	/ / / /		3. O AGRICULTURE
	, ,	, , ,	, ,	, , , ,		
R. SIGNIFICANT		, ,		/ / / /		4.
			1.	SIGNIFICANCE		
1. KIMSEY,	JAMES & JAM	ES, JOHN				
2. STRODE,	CHARLES E.					
3. GOSSETT	, ALFRED N.					
S. SIGNIFICANT	EVENT DATE(S)					
1.						
						П от оругин
2.						☐ SEE CONTINUATION SHEET

MO 780-1257 (5-92)

TA-AS-033-003

2.A. ARCHITECT/BUILDER/DESIGNER/ENGINEER							
1.	2.	3.					
2.B. ARCHITECTURAL STYLE		2.C. VERNACULAR TYPE					
		O 4 DOGTROT					
2.D. CONSTRUCTION DATE (CIRCA) 2.E. ALTERATIO	ON DATE						
-1838-(circa) 1. DATE UN	NKNOWN 2.	3. 4.	5.				
2.F. RECONSTRUCTION DATE (CIRCA) 2.G. DATE MOV	ED 2.H. DESTRUCTION DATE	2.1. OWNER'S NAME & ADDRESS (IF DIFFERENT					
2.J. HISTORIC FUNCTION							
1. 0 1 DOMESTIC 2.	3.	4.	5.				
2.K. HISTORIC SUBFUNCTION							
1. 01 A SINGLE 2	3.	4.	5.				
2.L. NO. OF ANCILLARY STRUCTURES	2.M. RESOURCE TYPE	2.N. STORIES					
	☑ BUILDING ☐ SITE ☐ STRUCTURE ☐	□ овјест 1. <u>1</u> 2.	<u>1</u> 3				
2.O. STRUCTURAL SYSTEMS	2.P. EXTERIOR WALL MATERIALS	2.Q. OTHER MATERIALS					
1. L G LOG CONTRUCTION	1123_LOG	1.	3.				
2. W U WOOD FRAME	2. 2 1 CLAPBOARD	0					
2.R. ROOF SHAPES	2.S. ROOF MATERIALS	2 2.T. ROOF FEATURES	4.				
1. GBGABLE	1. 6 3 ASPHALT	1	L.U. FOUNDATION MATERIALS				
2. S D SHED	2.	2.	1. L43 LIMESTONE				
3.	3	3.	2.				
2.V. PORCHES			2.W. PLAN				
1. FUJFULL (destroyed)	2.	3.	OTHER				
2.X. FURTHER DESCRIPTION	(SEE CONTINUATION SHEET)	2.Y. DESCRIPTION OF ENVIRONMENT AND OUT	BUILDINGS (SEE CONTINUATION SHEET)				
2.Z. SOURCES OF INFORMATION	PREPARED BY fair amers	ORGANIZATION	DATE				
(SEE CONTINUATION SHEET)	Just out						

MISSOURI HISTORIC BUILDING INVENTORY FORM - CONTINUATION SHEET


15-033-003

REFERENCE NUMBER	A. HISTORIC NAME	B. COUNTY	C. ADDRESS	
	Hickory Hills Farm Complex Log House	Jackson	47th Street	Kansas City

The log structure on the Hickory Hills Farm property has apparently seen many changes over time. As it stands today, it is a dog trot plan with frame additions on the north and east sides. The logs on the exterior were at some point covered with wood clapboards. The fireplace in the house is on the west side of the original log structure. Another stove chimney was added with the kitchen addition. The northeast addition has collapsed except for the lime stone basement and the south wall of the original log structure. The west half has rough- hewn log rafters, while the east side has milled lumber. Old records indicate the east and west halves of the structure may have been brought here from other sections of the property and joined together. A full length porch once existed on the south side of the house and brick pavers (in a herringbone pattern) form the floor surface between the two log rooms.

Plumbing in the house was apparently limited to the bathroom in an addition. The house was wired for electricity, but no evidence of a heating system other than a stove and fireplace was found.





















MISSOURI HISTORIC PROPERTY INVENTORY FORM

REFERENCE NUMBER A. HISTORIC NAME 93JA 0242 HICKORY HILLS FARM COMPLEX, SHED B. COUNTY C. OTHER NAME(S) 0 9 5 JACKSON EAST HIGH SCHOOL OUTDOOR LAND RESEARCH LABORATORY F. VICINITY G. RESTRICTED H. ACREAGE D. ADDRESS E. CITY 47th Street 100 KANSAS CITY I. SECTION J. TOWNSHIP K. RANGE L. SPANISH LAND GRANT M. QUARTER SECTIONS N. OWNERSHIP PRIVATE LOCAL STATE FEDERAL MIXED 29 49N 32W O. AGENCY(S) 1. KANSAS CITY SCHOOL DISTRICT . 2. P. UTM ZONE EASTING NORTHING USGS QUADRANGLE Q. AREA(S) OF SIGNIFICANCE/CONTEXT(S) 1. | 0 | 1 | 0 | AGRICULTURE / / / / / / 1. 2. / / / / / / / / / / / 2. / / / / / / 3. / / / / / / / / / / / / / / / / R. SIGNIFICANT PERSON(S) T. SIGNIFICANCE 1. GOSSETT, ALFRED N. 2. 3. S. SIGNIFICANT EVENT DATE(S) 1.

MO 780-1257 (5-92)

☐ SEE CONTINUATION SHEET

JA-AS-033-004

2.A. ARCHITECT/BUILDER/DESIGNER/ENGINEER			
1.	2.	3.	
2.B. ARCHITECTURAL STYLE		2.C. VERNACULAR TYPE	
TIT		1.1.1	
2.D. CONSTRUCTION DATE (CIRCA) 2.E. ALTERATION	ON DATE		
EARLY 20th CENTURY	2.		
(circa) 1. 2.F. RECONSTRUCTION DATE (CIRCA) 2.G. DATE MOV		3. 4. 2.I. OWNER'S NAME & ADDRESS (IF DIFFERENT)	5.
Land Bridge	Z.H. DESTROOTION DATE	Z.I. OWNERS NAME & ADDRESS (II DIFFERENT)	
2.J. HISTORIC FUNCTION			
1. Q9 AGRICULTURE 2.	3.	4.	5.
2.K. HISTORIC SUBFUNCTION			
1. Q9 F OUTBUILDING 2.	3	4.	5.
2.L. NO. OF ANCILLARY STRUCTURES	2.M. RESOURCE TYPE	2.N. STORIES	
	BUILDING SITE STRUCTURE] овјест 1. <u>1½</u> 2	3
2.O. STRUCTURAL SYSTEMS	2.P. EXTERIOR WALL MATERIALS	2.Q. OTHER MATERIALS	
1. LIS LOAD BEARING STONE	1. 4 3 LIMESTONE	1.	3.
2. W U WOOD FRAME	2. 2 1 CLAPBOARD	2.	4.
2.R. ROOF SHAPES	2.S. ROOF MATERIALS	2.T. ROOF FEATURES	
1. GBGABLE	1. [6]3 ASPHALT SHINGLES	1. []]	4.
			2.U. FOUNDATION MATERIALS
2.	2	2.	1. 43 LIMESTONE
3.	3.	3.	2. LSQSQUARE
2.V. PORCHES			2.W. PLAN
1.	2.	3.	
2.X. FURTHER DESCRIPTION	(SEE CONTINUATION SHEET)	2.Y. DESCRIPTION OF ENVIRONMENT AND OUT	BUILDINGS (SEE CONTINUATION SHEET)
2.Z. SOURCES OF INFORMATION	PREPARED BY	ORGANIZATION	DATE
(SEE CONTINUATION SHEET)	PREPARED BY Jun awers	S. G. Marian I. G.	5/10

JA-AS-033-004

MISSOURI HISTORIC BUILDING INVENTORY FORM - CONTINUATION SHEET

A. HISTORIC NAME		C. ADDRESS		
Hickory Hills Farm Complex	Jackson	47th Street	Kansas City	
Shed	Uackson	47 111 011001	ranoas ony	

The shed has five foot high rubble lime stone walls that are embedded into the hillside. A wood frame structure was constructed on top of these walls with a gable roof. The two gable end walls each contain three four light awning windows and the whole structure is sheathed in beveled siding. A small loft area is found under the roof with a steep wooden stair leading to it. The entrance is on the north side spanning the width of the structure.













MISSOURI H	ISTORIC PE	ROPER	TY INV	/ENTO	RY	FOR	RM					TA-AS-033-005
REFERENCE NUM	BER	A. HISTO	RIC NAME	E					-			
93JA	0243	HICK	ORY HI	LLS FA	ARM	COM	PLE.	X S	MALI	L BARN		
B. COUNTY		C. OTHER	R NAME(S	5)								
[0 9 5 JA0	KSON	EAST	HIGH	SCHOOL	UO L	TDO	OR :	LANI) RE	ESEARCH LABORATORY		
D. ADDRESS							E. CI	ГҮ				F. VICINITY G. RESTRICTED H. ACREAGE
47th "STRE	ET						K	ANS	AS C	CITY		100
I. SECTION	J. TOWNSHIP	K. RAI	NGE	L. SF	PANIS	SH LAI	ND GI	RANT		M. QUARTER SECTIONS	N. OWNERSHIP	
29	49N	32	2W								LOCAL STATE FEDERAL MIXED	
O. AGENCY(S)												
1. KANSAS CI	TY SCHOOL	DISTRI	CT							2.		
P. UTM ZONE E	ASTING			NORTHI	ING					USGS QUADRANGLE		Q. AREA(S) OF SIGNIFICANCE/CONTEXT(S)
1.	/ /	/ /	/	/	/	/	/	/	/			1. O 10 AGRICULTURE
2.	/ /	/ /	/	/	/	/	/	/	/			2.
17												
3.	/ /	/ /	/	/	/	/	/	/	/			3.
4.	/ /	/ /	/	,	/	/	/	/	/			4.
R. SIGNIFICANT F	PERSON(S)					T. SI	GNIFI	CANC	CE			
1. GOSSETT	ALFRED N.											
2.												
۷.					_							
3.												
S. SIGNIFICANT E	VENT DATE(S)											
1.												

MO 780-1257 (5-92)

2.

MISSOURI DEPARTMENT OF NATURAL RESOURCES HISTORIC PRESERVATION PROGRAM

☐ SEE CONTINUATION SHEET

JA-AS-073-005

2.A. ARCHITECT/BUILDER/DESIGNER/ENGINEER			
1.	2.	3.	
2.B. ARCHITECTURAL STYLE		2.C. VERNACULAR TYPE	
111			
2.D. CONSTRUCTION DATE (CIRCA) 2.E. ALTERATIO	ON DATE		
EARLY 20th CEN. (circa)	2.	3. 4.	5.
2.F. RECONSTRUCTION DATE (CIRCA) 2.G. DATE MOV	ED 2.H. DESTRUCTION DATE	2.I. OWNER'S NAME & ADDRESS (IF DIFFEREN	T)
SEPT. 1991			
2.J. HISTORIC FUNCTION			
1. 0 9 AGRICULTURE 2. 2.K. HISTORIC SUBFUNCTION	3.	4.	5.
	3.		5.
2.L. NO. OF ANCILLARY STRUCTURES	2.M. RESOURCE TYPE	2.N. STORIES	
	⊠ BUILDING □ SITE □ STRUCTURE □		3
2.O. STRUCTURAL SYSTEMS	2.P. EXTERIOR WALL MATERIALS	2.Q. OTHER MATERIALS	
1. W U WOOD FRAME	1. [2 1] CLAPBOARD	1.	3.
2.	2.	2.	4.
2.R. ROOF SHAPES	2.S. ROOF MATERIALS	2.T. ROOF FEATURES	
1. G B GABLE	1. [[6]3] ASPHALT	1.	4.
			2.U. FOUNDATION MATERIALS
2.	2	2.	1. L 4 3 LIMESTONE
3.	3.	3.	2.
2.V. PORCHES			2.W. PLAN
1.	2.	3	<u> IS IQ I</u> SQUARE
2.X. FURTHER DESCRIPTION	(SEE CONTINUATION SHEET)	2.Y. DESCRIPTION OF ENVIRONMENT AND OU	JTBUILDINGS (SEE CONTINUATION SHEET)
2.Z. SOURCES OF INFORMATION (SEE CONTINUATION SHEET)	PREPARED BY Show Mors	ORGANIZATION	DATE
LOLE CONTINUATION SHEET)			

MISSOURI HISTORIC BUILDING INVENTORY FORM - CONTINUATION SHEET

JA-AS-033-005

	A. HISTORIC NAME	B. COUNTY	C. ADDRESS	
40000000000000000000000000000000000000	Hickory Hills Farm Complex Small Barn	Jackson	47th Street	Kansas City

This structure which is just east of the farm house was recently rebuilt by the school district. The building was not restored according to HABS standards. Structural steel, masonite, and plywood siding were used in the reconstruction, and glass windows with shutters were installed. A concrete floor slab was also added, though it appears the original studs and rafters still remain. It appears the original use for this barn was as a garage though now it is used as a temporary classroom and storage.

This building is rectangular with a gabled roof. The small barn is entered through either one of two large sliding doors, one on the south facade and one on the north facade. There is also a small square window on each of these facades as well as three square windows each on the east and west facades.





MISSOURI	HISTOR	IC P	RO	PERT	'Y IN	VENT	OF	RY	FOI	RM						TA-AS-033-006
REFERENCE NU			A. 1	HISTOF	RIC NAM	IE										
93 JA	0240)	H	HICKO	RY H	ILLS	FAE	RM	COM	PLE	EX S	PRI	NG HOUSE			
B. COUNTY			C. (OTHER	NAME(S)										
10 9 5 JA	CKSON]	EAST	HIGH	SCHO	OOL	. 01	UTD	OOR	LA	ND R	ESEARCH LABO	RATORY		
D. ADDRESS										E. CI	TY				-	F. VICINITY G. RESTRICTED H. ACREAGE
47 th STF	REET									KAN	ISAS	G CI	ŢΥ	100		
I. SECTION	J. TOW	NSHIP		K. RAN	IGE	L.	SPA	ANIS	SH LAND GRANT M. QUARTER SECTIONS N. OWNERSHIP							IIP
29	24:	9N		3	32W										PRIVAT	e Local State Federal Mixed
O. AGENCY(S)																
1. KANSAS	CITY S	CHOO	r. DI	STRI	CT								2.			
P. UTM ZONE	EASTING					NORT	THIN	IG	USGS QUADRANGLE							Q. AREA(S) OF SIGNIFICANCE/CONTEXT(S)
1.	/	/	/	/	/	/	,	/	/	/	/	/				1. O 3 O ARCHITECTURE
															-	
2.	/	/	/	/	/	/	,	/	/	/	/	/				2.
3.	/	/	/	/	/	/	,	/	/	/	/	/				3.
4.			/	/	/	/	′	/	/	/	/	/				4.
R. SIGNIFICANT	PERSON(S	S)							T. SI	GNIF	ICAN	CE				
1. GOSSETT	, ALFR	e d n														
2.																
3.																
S. SIGNIFICANT	EVENT DA	TE(S)														
1.					٠											

MO 780-1257 (5-92)

MISSOURI DEPARTMENT OF NATURAL RESOURCES HISTORIC PRESERVATION PROGRAM

P.O. BOX 176 JEFFERSON CITY, MO 65102

☐ SEE CONTINUATION SHEET

JA-AS-033-006

2.A. ARCHITECT/BUILDER/DESIGNER/ENGINEER			
1.	2.	3.	
2.B. ARCHITECTURAL STYLE		2.C. VERNACULAR TYPE	
2.D. CONSTRUCTION DATE (CIRCA) 2.E. ALTERATION	ON DATE		
EARLY 20th CENTURY (c 1.	2.	3. 4.	5.
2.F. RECONSTRUCTION DATE (CIRCA) 2.G. DATE MOV	ED 2.H. DESTRUCTION DATE	2.1. OWNER'S NAME & ADDRESS (IF DIFFERENT)
2.J. HISTORIC FUNCTION			
1. 0 9 AGRICULTURE 2. 2.K. HISTORIC SUBFUNCTION	3.	4.	5. [] [
1. 0 9 B STORAGE 2.	3.		5.
2.L. NO. OF ANCILLARY STRUCTURES	2.M. RESOURCE TYPE STRUCTURE EXISTS STRUCTURE	2.N. STORIES 12 2.	3
2.O. STRUCTURAL SYSTEMS	2.P. EXTERIOR WALL MATERIALS	2.Q. OTHER MATERIALS	
LOAD BEARING 1. L S STONE	1. [1413] LIMESTONE, CUT	1. [2] WOOD GABLE ENDS	3.
		TABILE PHYTE	
2.	2. [4 3] LIMESTONE, RUBBLE	2.	4.
2.R. ROOF SHAPES	2.S. ROOF MATERIALS	2.T. ROOF FEATURES	
1. LIGIBIGABLE	1. L 16131 ASPHALT	1.	4.
			2.U. FOUNDATION MATERIALS
2	2. [6 2] TERRA COTTA	2.	1. 4 3 LIMESTONE
3.	3.	3.	2.
2.V. PORCHES		0	2.W. PLAN
1. [] .	2.	3.	L S Q SQAURE
2.X. FURTHER DESCRIPTION	(SEE CONTINUATION SHEET)	2.Y. DESCRIPTION OF ENVIRONMENT AND OUT	BUILDINGS SEE CONTINUATION SHEET)
2.Z. SOURCES OF INFORMATION (SEE CONTINUATION SHEET)	PREPARED BY Java aners	ORGANIZATION	DATE

MISSOURI HISTORIC BUILDING INVENTORY FORM - CONTINUATION SHEET

JA-AS-033-006

REFERENCE NUMBER	A. HISTORIC NAME	B. COUNTY	C. ADDRESS		
	Hickory Hills Farm Complex Spring House	Jackson	47th Street	Kansas City	

The spring house is constructed of rusticated random ashlar limestone on the south and east sides while the north and west sides are of squared and coursed rubble limestone. The difference in the stone type may be attributed to the possible reuse of stone from the grist mill that may have once stood here. Different types of arches were utilized for each of the windows and doors. These include a solid lintel, a jack arch, and a standard arch. Although different type of arches were used, it is interesting to note that not all of the arches have keystones.

The simple gable roof of the spring house was constructed of wood with asphalt shingles and a red clay tile ridge cap. The spring house is a two level structure with a ground level entrance on each level. An exterior stone stair leads from the upper level door on the east side of the south facade to the lower level door on the corner of the east facade. The spring itself ran through this lower level into a floor-level pool which was used to cool the spring house and flowed out through a pipe in the wall to the collecting pool below.



















MISSOURI	HISTO	RIC P	RO	PERT	TY IN	VEN	ТО	RY	FO	RM					JA-	AS-03:	4-007
REFERENCE NU	JMBER		Α.	HISTOR	RIC NAM	IE										10	<i>y</i> - <i>x</i> -
43JA	024	1		HICK	ORY H	ILL	S F	ARM	1 CC	MLP	EX,	STO	ONE SHELTER				
B. COUNTY	1000		C.	OTHER	NAME(S	S)											
09 5	IVCKEU	N		EAST	HIG	H S	СН	00	L O	UTI	000	R L	AND RESEARCH LAB	ORATORY			
D. ADDRESS	JAORDO	/ 14								E. C					F. VICINITY	G. RESTRICTED	H. ACREAGE
47th St	treet									KA	ANS.	AS	CITY				100
I. SECTION	J. TOV	WNSHIP		K. RAN			L. SF	PANIS	SH LA	ND G	RANT		M. QUARTER SECTIONS	N. OWNERSHIP			
29		49N			32W									X LOCAL	STATE	FEDERAL MIXED	
O. AGENCY(S)																	
1. KANSAS	CITY	SCH	00	L DI	STRI	CT							2.				
P. UTM ZONE	EASTING					NOI	RTHI	NG					USGS QUADRANGLE		Q. AREA(S)	OF SIGNIFICANO	CE/CONTEXT(S)
1.	/	/	/	/	/		/	/	/	/	/	/			1. [0]1	O AGRICU	JLTURE
2.	/	/	/	/	/		/	/	/	/	/	/			2.		
3.	_ /	/	/	/	/		/	/	/	/	/	/			3.		
4.			/	/	/		/	/	/	/	/	/			4.		
R. SIGNIFICAN	T PERSON	(S)							T. S	IGNIF	ICAN	CE					
1. GOSSET	TT, ALF	RED N	٧.														
2.																	
3.																	
S. SIGNIFICAN	T EVENT D	ATE(S)															
1.																	

MO 780-1257 (5-92)

2.

☐ SEE CONTINUATION SHEET

2.A. ARCHITECT/BUILDER/DESIGNER/ENGINEER			
1.	2.	3.	
2.B. ARCHITECTURAL STYLE		2.C. VERNACULAR TYPE	
2.D. CONSTRUCTION DATE (CIRCA) 2.E. ALTERATION	ON DATE		
EARLY 20th CENTURY 1.	2.	3. 4.	5.
2.F. RECONSTRUCTION DATE (CIRCA) 2.G. DATE MOV	ED 2.H. DESTRUCTION DATE	2.I. OWNER'S NAME & ADDRESS (IF DIFFERENT)	
2.J. HISTORIC FUNCTION			
1. LO 9 AGRICULTURE 2.	3. [] [4.	5.
2.K. HISTORIC SUBFUNCTION			
1. O 9D ANIMAL FAC. 2.	3.	4.	5.
2.L. NO. OF ANCILLARY STRUCTURES	2.M. RESOURCE TYPE	2.N. STORIES	
	■ BUILDING SITE STRUCTURE] овјест 11 2.	3
2.O. STRUCTURAL SYSTEMS	2.P. EXTERIOR WALL MATERIALS	2.Q. OTHER MATERIALS	
LOAD BEARING 1. LS STONE	1.	1	3.
Laip of one	LIMESTONE		
2. [] /, /,	2.	2.	4.
2.R. ROOF SHAPES	2.S. ROOF MATERIALS	2.T. ROOF FEATURES	
1. G B GABLE	1. LISO METAL	1.	4.
	THE		2.U. FOUNDATION MATERIALS
2	2.	2	1. 4 3 LIMESTONE
3.	3.	3.	2.
2.V. PORCHES			2.W. PLAN
1	2.	3.	LIRLC RECTANGLE
2.X. FURTHER DESCRIPTION	(SEE CONTINUATION SHEET)	2.Y. DESCRIPTION OF ENVIRONMENT AND OUT	
2.Z. SOURCES OF INFORMATION	PREPARED BY Java alivens	ORGANIZATION	DATE
(SEE CONTINUATION SHEET)	<i>3</i> · ·		

MISSOURI HISTORIC BUILDING INVENTORY FORM - CONTINUATION SHEET

JA-AS-033-007

A. HISTORIC NAME	B. COUNTY	C. ADI	DRESS		
Hickory Hills Farm Complex Stone Shelter	Jackson	47	7th Street	Kansas City	

The stone shelter built across the meadow to the northeast of the farmhouse was constructed of rubble limestone. Only two of the interior stone columns remain standing. It appears that animals were kept in the north side of the building because metal gate pins are still visible in the two remaining columns. Also, the surrounding terrain and the openings in the east and west walls make it look as if either carraiges or farm equipment were pulled in under the roof for protection. The portions that remain of the south wall show that the building was made up of seven bays, the end two of which are smaller than the other five.



