	A Pres	ent Name(s)	JA-AS-008-1301
1. No. 9-A			*
2. County	15	01 Oak	
Jackson		er Name(s) not entered	
Location of Negatives MT # Landmarks Commission	30-3	on Finance Company; 401 Truman Ro	24
The second second second	CII.	NAME OF TAXABLE PARTY.	The second second second second
Specific Location 1501 Oak		16. Thematic Category	28. No of Stories 1
1501 Oak		17. Date(s) or Period	29. Basement? Yes X
		1962	30. Foundation Material
City or Town . If Bural To	washin & Vicinity	18 Style or Design	concrete
City or Town II Aural, To Kansas City, Missouri	The street of th	Miesian	31. Wall Construction
Site Plan with North Arrow		19. Architect or Engineer	steel frame
.1	. 12.45	Howard Nearing	32 ool Type & Material flat; tar & gravel
N TRUM	AN ROAD	20. Contractor or Builder	
N _	_	Fogel Const. Co.	33. No. of Bays Front 4 Side 7
4		21. Original Use, if apparent	7.000
0		commercial 22 Present Use	glass; brick; marble
Ó			35. Plan Shape rectangular
1		commercial 23 Ownership Public ! !	36. Changes Addition :
		Private	(Explain Altered 1:
		24. Owner's Name & Address,	in #42) Moved
		if known	37. Condition
Coordinates UTM			Interior
Lat.			Exterior good
Long.		25. Open to Yes I i	38. Preservation Yes
Site!:	Structure	Public? No IX	Underway? No i x
Building Ki	Object ! !	26. Local Contact Person or Organization	39. Endangered? Yes I No I x
1. On National Yes   12 Register? No M	Is It Yes !:	Landmarks Commission	By What?
	District Yes	27. Other Surveys in Which Included	40. Visible from Yes! X
Hist. Dist.? No kl	Potent'l? No x		40. Visible from Yes! X Public Road? No!!
5 Name of Established District			41. Distance from and
o name or Established Plants		,	Frontage on Road
CALL STREET			48 feet on Oak
Purther Description of Impor	rtant Features T	ne main facade faces west. A flat	canopy protects the
		surface is glass. Glazed brick of are used next to the entrance.	
4,200 square reet.			



1. No. 8-	A 4. Pre	Midas Muffler Shop		8
2 County Jackson		ner Name(s) not		3-A
Landmarks Commission	T #108-15 on of KC	entered		
6 Specific Location	And the last of th	16. Thematic Category	28. No. of Stories 1	1
200			29. Basement? Yes	Jackson
1508 Oak		17. Date(s) or Period	No X	cks
7 64 4 7	. T	1984	30. Foundation Material	no
7 City or Town If Rura Kansas City, M		18. Style or Design	31. Wall Construction	
B. Site Plan with North Arr		19. Architect or Engineer	concrete block	200
	1,		32. Roof Type & Material	
1	W	20. Contractor or Builder	flat; tar and gravel	_
6	17/	DMT Const. Co. (Dallas, T) 21. Original Use, if apparent	X) 33. No. of Bays Front Side	
I u		Commercial	34. Wall Treatment	
L &		22. Present Use	brick	1
. 0		commercial	35. Plan Shaperectangular	
		The second secon	ublic   36. Changes Addition   :	
		24. Owner's Name & Address.	ivate 🖾 (Explain Altered I ' in #42) Moved I	
		if known	37. Condition	
9 Coordinates L	JTM	-	Interior	
Lat.	3,111		Exterior excellent	
Long.		25. Open to Public?	Yes X 38. Preservation Yes	
10 Site!: Building 1x	Structure   Object		No I Underway? No ix	1
	12 Is It Yes	26. Local Contact Person or Organizat	Ry What? No ly	ı
Register? No IX	Eligible? Nox:	Landmarks Commission of 27. Other Surveys in Which Included	of KC	
3 Part of Estab. Yes I I Hist. Dist.? No IX	14. District Yes : Potent'l? No X	The same surveys in thines includes	40. Visible from Yes X Public Road? No 1	
15. Name of Established Di			41. Distance from and Frontage on Road	802
			43 feet on Oak	1
at the east end of	this facade. Th	e remainder of the north fac window is on the east facade	entrance to an office area is ade is composed of overhead	
43 History and Significance	One of a chain	of muffler shops featuring a	standard design	
to matory and organicance	one of a chaffi	or marrier shops reacuring a	bedindard design.	
14. Description of Environm the south is a comm	ent and Outbuildings A ercial building.	small surface parking area Surface parking lots are al	is north of this building. To so to the east and west.	
			To	
5 Sources of Information			46. Prepared by PILAND	
BP #0161A WP #86331			47. Organization	
WF #60331			Landmarks Commission	
			48. Date 49. Revision Date(s) 10/26/84	

5A-AS-008 1302

HISTORIC INVENTORY



State Historical Survey and Planning Office, 909 University Avenue, Suite 215,

STORIC INV

45 Sources of Information

Kansas City Star, Sept. 26, 1926, p. 1D

BP #14719

WP #3835

-lumbia, Missouri 65201

46. Prepared by

47. Organization

48. Date 12/1/82

Piland /Uguccioni

Landmarks Commission

49. Revision Date(s)

A.AS-008-1303



-
=
C
-
0
=
=
B
64

1. No.	4. Pre	sent Name(s)	JA-AS-(XX8-1304
9-B 2 County	Li	epsner and Co., Inc.	
Jackson	5 011	er Name(s)	
Location of Negatives MT #30 Landmarks Commission	-5 Pc	ortage Tire and Rubber Company But	Iding
Specific Location		16. Thematic Category	28. No. of Stories 3
		030 050	29. Basement? Yes
1513 Oak		17. Date(s) or Period	No I .
		1920	30. Foundation Material
City or Town If Aural, Town Kansas City, Missouri	ship & Vicinity	18. Style or Design	31. Wall Construction
Site Plan with North Arrow	_	19. Architect or Engineer	masonry up
		Wilkinson and Crans 30 90	32. Roof Type & Material
N		20. Contractor or Builder	flat; tar & gravel Ft Re
17		W. R. Jewell, Jr. 21 Original Use, if apparent	33. No. of Bays 99
1 %		commercial ODE RI	34. Wall Treatment
1 3		22. Present Use	brick 30
, , ,	-1	commercial	35. Plan Shape rectangular
8		23 Ownership Public 11 Private	36. Changes Addition ( ) (Explain Altered )
4		24. Owner's Name & Address.	in #42) Moved
		if known	37. Condition
Coordinates UTM			Interior
Lat. Long		25. Open to Yes vv	Exterior good
Site ! ;	Structure	25. Open to Yes XX Public? No 11	38. Preservation Yes : Underway? No XX
Site ! : Building ! X	Object 11	26. Local Contact Person or Organization	39. Endangered? Yes [ ]
On National Yes   12 Is I		Landmarks Commission	By What? No XX
Part of Estab. Yes 11 14. Di	strict YesXX	27. Other Surveys in Which Included	an Marke Communication
	tent'l? No :		40. Visible from Yes XX Public Road? No ::
Name of Established District			41. Distance from and
			Frontage on Road 33 feet on Oak
Eusther Descriptive of Importor	Feetures Fo	llowing the grade on Oak Street the	AN ADDRESS OF THE PARTY OF THE
rindows. Fenestration on the central bay flank	of the second ted by a since and the room	e glass windows. A heavy cornice ind and third stories consists of the ngle rectangular window on each of of line and a bracketed stone strindows.	ree rectangular windows the side bays. The
		ment of this building was the Port	age Tire and Rubber
ompany.			
Description of Environment and	Outbuildings	Surface parking lots are to the no	
Description of Environment and ast and west are commer	Outbuildings	Surface parking lots are to the no	rth and south. To the
Description of Environment and ast and west are commer Sources of Information P #536	Outbuildings	Surface parking lots are to the no	rth and south. To the  46 Prepared by Piland
Description of Environment and ast and west are commer  Sources of Information P #536 P #12628	Outbuildings cial buildi	Surface parking lots are to the notings.	rth and south. To the  46. Prepared by Piland  47. Organization
Description of Environment and east and west are commer  Sources of Information  12 #536  13 #12628  14 ansas City Star, Dec. 3	Outbuildings cial buildi	Surface parking lots are to the notings.	rth and south. To the  46 Prepared by Piland



9-D	Present Name(s)	
Tackson Fil #100-1	Williams Plating Company	
3. Location of Negatives	Other Name(s)	
Landmarks Commission of KC	Titus & Son Printing and Envelope Co	empany Building
8. Specific Location	16. Thematic Category	28. No. of Stories 2
1517 Oak	030 050 17. Date(s) or Period	29. Basement? Yes I.
	1925	30. Foundation Material
City or Town If Rural, Township & Vicin		DI
Kansas City, Missouri	50 4	31. Wall Construction
Site Plan with North Arrow	19. Architect or Engineer	masonry 32. Roof Type & Material
1	20. Contractor or Builder	flat; tar & gravelF+Pe
N &	30 90	33. No. of Bays 99
	21. Original Use, if apparent commercial OPE	Front_3 Side  34. Wall Treatment \$5 30
2	22. Present Use Prich	brick; concrete block
1	commercial AW	35. Plan Shape rectangular
	23 Ownership Public 1 Private led	36. Changes Addition : (Explain Alteredx)
7	24. Owner's Name & Address.	in #42) Moved
	if known	37. Condition
Coordinates UTM		Interior
Lat. Long.	25 Open to Man I I	Exterior -good
Site!: Structure	25. Open to Yes 🔀 No 🖂	38. Preservation Yes : Underway? No ix
Building X: Object		39. Endangered? Yes I
I. On National Yes   12 Is It Yes	Landmarks Commission of Kt.	By What? No IX
Register? No X! Eligible? No I. Part of Estab. Yes I 14. District Yes	27. Other Surveys in Winch included	40 Ministration Was 19
Hist. Dist.? No 21 Potent'!? No		40. Visible from Yes !X Public Road? No !:
5. Name of Established District		41. Distance from and
		Frontage on Road
2 Surther Description of Important Features 7	The main facade faces west. The first	33 feet on Oak
n entrance to at the north and a	of the west facade and an overhead gar	th decorative concrete
ocated. The remaining first floo	or warr surrace has been riffed in wro	
ocated. The remaining first floo lock.		
ocated. The remaining first floo lock.  3. History and Significance This building	was originally occupied by the Titus	
ocated. The remaining first floo lock.  3. History and Significance This building		
ocated. The remaining first floo lock.  3. History and Significance This building		
ocated. The remaining first flood lock.  3. History and Significance This building invelope Company.	; was originally occupied by the Titus	& Son Printing and
ocated. The remaining first floor lock.  Description of Environment and Outbuilding	was originally occupied by the Titus s Surface parking lots are north, eas	& Son Printing and
ocated. The remaining first floodlock.  3. History and Significance This building invelope Company.  4. Description of Environment and Outbuilding ing. To the south is a commercial	was originally occupied by the Titus s Surface parking lots are north, eas	s & Son Printing and  st and west of this build-
ocated. The remaining first floodlock.  3. History and Significance This building Envelope Company.  4. Description of Environment and Outbuildinging. To the south is a commercial Sources of Information	was originally occupied by the Titus s Surface parking lots are north, eas	s & Son Printing and  st and west of this build-  46. Prepared by PILAND
ocated. The remaining first floodlock.  3. History and Significance This building invelope Company.  4. Description of Environment and Outbuilding ing. To the south is a commercial	was originally occupied by the Titus s Surface parking lots are north, eas	s & Son Printing and  st and west of this build-  46. Prepared by PILAND  47. Organization
ocated. The remaining first floodlock.  3. History and Significance This building Envelope Company.  4. Description of Environment and Outbuilding ang. To the south is a commercial Sources of Information	was originally occupied by the Titus s Surface parking lots are north, eas	s & Son Printing and  st and west of this build-  46. Prepared by PILAND



C
:
ċ
-
5
Ξ
E
C
-

HISTORIC INVENTORY A-AS 008-1506 1. No 4. Present Name(s) 9-E United Labor Member Assistance Inc. 2. County Jackson 5 Other Name(s) 3 Location of Negatives MT #71-9 American House and Window Cleaning Co. Landmarks Commission 6. Specific Location 16. Thematic Category 28. No. of Stories 1 Jackson 29. Basement? Yes I 1519 Oak 17 Date(s) or Period No I 1951 (alt. 1962) 30. Foundation Material 18 Style or Design 7. City or Town · If Rural, Township & Vicinity 31. Wall Construction Kansas City, Missouri concrete block 8. Site Plan with North Arrow 19. Architect or Engineer 32. Roof Type & Material 20. Contractor or Builder flat; tar & gravel Mark F. Doty 33. No. of Bays Front 2 Side 21. Original Use, if apparent Present Name commercial 34. Wall Treatment 19 22 Present Use brick commercial 35. Plan Shape rectangular 23 Ownership Public 1 36. Changes Addition Altered XX Private I. (Explain in #42) Moved i 24. Owner's Name & Address. if known 37. Condition Interior UTM Coordinates Exterior Lat. good Long 25. Open to Yes I 38. Preservation Yes i Public? Noxx Underway? No ix Sile! Structure Building 1x Object | | 26. Local Contact Person or Organization 39. Endangered? Yes No L By What? Landmarks Commission 11. On National Yes ! Yes II 12 Is It Register? Eligible? No X No 1x 27. Other Surveys in Which Included 13. Part of Estab. Yes I I Yes 14. District 40 Visible from Yes X No X Hist. Dist.? No W Potent'1? Public Road? No I 41. Distance from and 15. Name of Established District Frontage on Road 50 feet on Oak 42. Further Description of Important Features A "new" exterior treatment was accomplished on the west facade in 1962. An entrance is placed at the north end of this facade and surrounded with a large area of ceramic tile. Triple rectangular windows provide the fenestration at the south end. Bands of dark brick add visual interest to the parapet wall. 43. History and Significance The building was constructed at a cost of \$25,000. The original occupants were the American House & Window Cleaning firm. 44. Description of Environment and Outbuildings Surface parking lots are west and south of this building. Other commercial buildings are to the north and west. Kansas City Star, Nov. 4, 1951, p. 7D. 46. Prepared by 45 Sources of Information Uguccioni WP #12265 47. Organization BP #17566 Landmarks Commission BP #68317 49. Revision Date(s) 48. Date

State Historical Sur my and Planning Office, 909 University Avenue, Suite 215,

columbia, Missouri 65201

12/4/81



48. Date 49. Revision Date(s)

9/14/81

Kansas City Star, April 27, 1926.

Kansas City Post, Aug. 12, 1927.

State Historical Survey and Planning Office, 909 University Avenue, Suite 215.



No. 8-H	4. Pre	senl Name(s)	-*
County		1528-36 Oak Street	
Jackson	5. 011	ner Name(s)	
Location of Negatives	MT #61-19	eake Auto Supply Company Bulding	4
Landmarks Commissi Specific Location	ion	16. Thematic Category	28. No. of Stories 2
Charles and Charles		030 050	28. No. of Stories 2 29. Basement? Yes I
1528-36 Oak Street		17. Date(s) or Period	No I
		1921 (add. 1927)	30. Foundation Material
City or Town - If Rura	al, Township & Vicinity	18. Style or Design	01
ansas City, Misso		60 67	31. Wall Construction
Site Plan with North Art	row	19. Architect or Engineer other	masonry UD
	1.	20. Contractor or Builder	32. Roof Type & Malerial F† flat; tar & gravel
	· N	(see #43) Fogel Constr Co.	33. No. of Bays
	7 5 1	21. Original Use, if apparent ADE ADIA	Front Side
		commercial/warehouse	34. Wall Treatment
	NO	22. Present Use vacant	brick 30
	0	23 Ownership Public   1	35. Plan Shape rectangular 36. Changes Addition :
E. 1674 S	TT .	23 Ownership Public 11	(Explain Altered I
		24. Owner's Name & Address,	in #42) Moved
		if known	37. Condition
CARATON PREE	UTM		Interior good
Lat. Long.		25. Open to Yes II	
Site ! :	Structure 1	25. Open to Yes II Public? No 1	38. Preservation Yes No XX
Building L	Object 11	26. Local Contact Person or Organization	39. Endangered? Yes I
On National Yes II	12 Is It Yesxix	Landmarks Commission	By What?
Register? No 🚉	Eligible? No ::	27. Other Surveys in Which Included	By What? No 1:
Register? No ½	Eligible? No 1!		40. Visible from Yes tx
Register? No k' Part of Estab Yes     Hist. Dist.? No k	Eligible? No ::  14. District Yes <sub>X</sub> X Potent'!? No ::		40. Visible from Yes kx Public Road? No ii
Register? No k' Part of Estab. Yes     Hist. Dist.? No k	Eligible? No ::  14. District Yes <sub>X</sub> X Potent'!? No ::		40. Visible from Yes tx
Register? No 1/2 Part of Estab. Yes I I Hist. Dist.? No 1/2 Name of Established Di	Eligible? No !!  14. District Yesxix Potent'!? No !!  istrict  Important Features Rec	27. Other Surveys in Which Included	40. Visible from Yes kx Public Road? No
Register? No k  Part of Estab Yes     Hist. Dist.? No k  Name of Established Di  Further Description of intervals on both sultipaned windows	Eligible? No ::  14. District Yesxix Potent'!? No ::  istrict  Important Features Rec the south and ease enframed by the	27. Other Surveys in Which Included	40. Visible from Public Road? No 11  41. Distance from and Frontage on Road  95 feet on Oak  ays are placed at regular composed of tripartite cornice of the building
Register? No k  Part of Estab. Yes     Hist. Dist.? No k  Name of Established Di  Further Description of intervals on both oultipaned windows s distinguished b  History and Significance at a cost of \$40	Eligible? No ::  14. District YesxX Potent'!? No ::  istrict  Important Features Rec the south and ease enframed by the by a horizontal by  This build ,000. An addition the 1921 original	27. Other Surveys in Which Included  tangular store front and garage bast facades. The second story is controlled brick piers of the building. The	40. Visible from Public Road? No!:  41. Distance from and Frontage on Road  95 feet on Oak  The result of the building perimeter of the building.  Auto Supply Company the same company.
Register? No k' Part of Estab. Yes II Hist. Dist.? No k' Name of Established Di Further Description of Intervals on both ultipaned windows s distinguished by History and Significance at a cost of \$40 The contractor for Company built the	Eligible? No:  14. District Yesxix Potent'!? No:  istrict  Important Features Rec the south and ease enframed by the by a horizontal he  This build ,000. An addition or the 1921 original processors and the south and the second	tangular store front and garage bast facades. The second story is controlled band of brick that runs along the pand of brick that runs along the pand of brick that runs along the pand of the building in 1927 was for inal structure was Pratt-Thompson.	40. Visible from Public Road? No!:  41. Distance from and Frontage on Road 95 feet on Oak  Tys are placed at regular composed of tripartite cornice of the building perimeter of the building.  Auto Supply Company the same company.  The Fogel Construction
Part of Estab. Yes II Hist. Dist.? No II Name of Established Di Further Description of Intervals on both ultipaned windows s distinguished by History and Significance at a cost of \$40 The contractor for Company built the	Eligible? No ::  14. District YesxX Potent'!? No ::  istrict  Important Features Record the south and east enframed by the pay a horizontal horizontal horizontal the south addition the 1921 original entert and Outbuildings	tangular store front and garage bast facades. The second story is controlled brick piers of the building. The band of brick that runs along the principle was constructed for the Peake and to the building in 1927 was for	40. Visible from Public Road?  41. Distance from and Frontage on Road  95 feet on Oak  The regular composed of tripartite experimeter of the building perimeter of the building.  Auto Supply Company the same company.  The Fogel Construction
Part of Estab. Yes II Hist. Dist.? No II Name of Established Di  Further Description of Intervals on both ultipaned windows s distinguished by  History and Significance at a cost of \$40 The contractor for Company built the Description of Environm building. A commodulation	Eligible? No ::  14. District YesxX Potent'!? No ::  istrict  Important Features Record the south and east enframed by the pay a horizontal horizontal horizontal the south addition the 1921 original entert and Outbuildings	ctangular store front and garage bast facades. The second story is constructed for the Peake and of brick that runs along the property of the building of the building of the peaker of the building in 1927 was for inal structure was Pratt-Thompson.	40. Visible from Public Road?  41. Distance from and Frontage on Road  95 feet on Oak  The same placed at regular composed of tripartite cornice of the building perimeter of the building.  Auto Supply Company the same company.  The Fogel Construction  ast and west of this the south.
Part of Estab. Yes II Hist. Dist.? No 11 Name of Established Di  Further Description of Intervals on both ultipaned windows a distinguished by  History and Significance at a cost of \$40 The contractor for Company built the Description of Environmountaining. A common building.	Eligible? No ::  14. District YesxX Potent'!? No ::  istrict  Important Features Record the south and east enframed by the pay a horizontal horizontal horizontal the south addition the 1921 original entert and Outbuildings	ctangular store front and garage bast facades. The second story is constructed for the Peake and of brick that runs along the property of the building of the building of the peaker of the building in 1927 was for inal structure was Pratt-Thompson.	40. Visible from Public Road?  41. Distance from and Frontage on Road  95 feet on Oak  Tys are placed at regular composed of tripartite cornice of the building perimeter of the building.  Auto Supply Company the same company.  The Fogel Construction  ast and west of this the south.  46. Prepared by Uguccioni/Piland
Register? No k' Part of Estab Yes II Hist Dist.? No k' Name of Established Di  Further Description of Intervals on both ultipaned windows s distinguished by  History and Significance at a cost of \$40 The contractor for Company built the	Eligible? No ::  14. District YesxX Potent'!? No ::  istrict  Important Features Record the south and east enframed by the pay a horizontal horizontal horizontal the south addition the 1921 original entert and Outbuildings	ctangular store front and garage bast facades. The second story is constructed for the Peake and of brick that runs along the property of the building of the building of the peaker of the building in 1927 was for inal structure was Pratt-Thompson.	40. Visible from Public Road?  41. Distance from and Frontage on Road  95 feet on Oak  The same placed at regular composed of tripartite cornice of the building perimeter of the building.  Auto Supply Company the same company.  The Fogel Construction  ast and west of this the south.



1. No.	4. Present Name(s)		
25-G 2 County	1600-02 Oak		25-
Jackson	5. Other Name(s) Building		G
3 Location of Negatives MT #61-20 Landmarks Commission	Southwest News Company; 313 East 16t		
6 Specific Location	16. Thematic Category	28 No of Stories 5	4
1600-02 Oak	030 050 17. Date(s) or Period	29. Basement? Yes  X	ach
1000 02 048	1915	30. Foundation Material	Jackson
7 City or Town If Rural, Township & V Kansas City, Missouri	Vicinity 18. Style or Design	concrete 5	2
	60 69	31. Wall Construction RC St reinforced concrete; s	-001
B. Site Plan with North Arrow  East 16TH ST	Smith, Rea, & Lovitt	32. Roof Type & Material PR	Leci
N XAST /GIA	20. Contractor or Builder Older	flat; tar & gravel 99	
N N	Fogel Const. Co. 30 50	33. No. of Bays Front 6 Side 4	16
1   2	commercial O2A	34. Wall Treatment	1600-02
- B	22 Present Use vacant	brick 30	02
	23 Ownership Public II	35. Plan Shape rectangular 36. Changes Addition	0ak
	Private 🔀	(Explain Altered I in #42) Moved I	, 2
	24. Owner's Name & Address, if known	37. Condition	
9 Coordinates UTM		Interior	
Lat. Long		Exterior - good	
10 Site!: Struct	25. Open to Yes 1	38. Preservation Yes Underway?	
TO THE PARTY OF TH	ject 1 26. Local Contact Person or Organization	39. Endangered? Yes I	
	Yesxx Landmarks Commission	By What? No L	
13 Part of Estab. Yes 11 14 District	Yes XX	40. Visible from Yes X Public Road? No	
Hist. Dist.? No   Potent'1?	10	41. Distance from and	
To reside of Established District		Frontage on Road	
		50 feet on Oak	_
42. Further Description of Important Feature	es The building sited on a corner, from cade contains the main entrance which f		
	s elevated and is faced with smooth sto		1

by brick piers and spandrels decorated with round medallions. The parapet wall repeats the motif. An arched projection extends beyond the parapet wall on the east facade. Just below this projection are two small lion heads. The central bay of the north facade features triple windows. The building contains 35,000 square feet.

43. History and Significance This building was constructed for the Southwest News Company. In later years it was used by the Missouri cepartment of Health and Welfare.

44 Description of Environment and Outbuildings Other commercial buildings are to the north, south, east, and west.

## 45 Sources of Information

Western Contractor, Sept. 22, 1915, p. 29. Kansas City Star, Septem-WP #5969

ber 5, 1915, p. 8A

46. Prepared by Piland /Uguccioni

47. Organization

Landmarks Commission 49. Revision Date(s) 48. Date

10/12/81

BP #11605

Kansas City Star, Feb. 28, 1982, p. 2 H.



State Historical Survey and Planning Office, 909 University Avenue, Suite 215, Columbia, Missouri 65201 HISTORIC JVENT TA-A5-008=1310 4. Present Name(s) I. No. 26-A Tire Supply Co. 2 County 5 Other Name(s) 3 Location of Negatives Paige-Detroit Motor Car Company Building Landmarks Commission 6. Specific Location 16. Thematic Category 28. No. of Stories Jackson 030 050 29. Basement? Yes I 1601 Oak 17 Date(s) or Period No I 1918 30. Foundation Material 01 7 City or Town Kansas City, If Rural, Township & Vicinity Missouri 18 Style or Design 31. Wall Construction mill LLD B. Site Plan with North Arrow 19. Architect or Engineer 32. Roof Type & Material Robert J. Raney EAST 16TH S flat; tar & gravel # PR 20. Contractor or Builder other 40 30 33. No. of Bays Side Front 21. Original Use, if apparent commercial ODE 34. Wall Treatment Oak 22 Present Use brick; stone 35. Plan Shape rectangular commercial 23 Ownership Public 11 36. Changes Addition : Private XX (Explain Altered I Moved i in #42) 24. Owner's Name & Address. if known 37. Condition Interior 9 Coordinates UTM Exterior good Lat. Long 25. Open to Yes XX 38. Preservation Yes Public? No II Underway? No X Site! Structure ! Building 1x Object ! 39. Endangered? 26. Local Contact Person or Organization Yes I By What? No X 11. On National Landmarks Commission 12 Is It YesXX Yes Register? No It Eligible? No 27. Other Surveys in Which Included Yes 13 Part of Estab Yes II 14. District 40. Visible from Yes X No IX No Hist. Dist.? Potent'1? Public Road? No ! 41. Distance from and 15. Name of Established District Frontage on Road 42. Further Description of Important Features The building is sited on a corner and both the west and facades are articulated. The entrance is located at the northwest corner of the building and is distinguished by stone banding that enframe the bays. Garage bays are placed on the first story of the north facade, and the northewast corner of the building mirrors the stone banding of the main entrance. The parapet wall is shaped, and capped with stone coping. Decorative stone rectilinear motifs are placed at the corners of the building. 43. History and Significance This building was originally occupied by the Paige-Detroit Motor Car Company. 44. Description of Environment and Outbuildings A surface parking lot is to the north of this building. To the east, west, and south are other commercial structures. 46. Prepared by 45 Sources of Information Piland/Uguccioni WP #61942 BP #12374 47. Organization

Courty

Present Name(s)

Landmarks Commission

48. Date 11/9/81

49. Revision Date(s)



0
-
C
-
*
2
8
~
_
2
-
-
=
æ
-
54
e(5,

2 County

1. No. 25-F	4. Present Name(s) Harding Glass	*
County	nararing oraco	
Jackson	5. Other Name(s)	0
Location of Negatives MT #73-14 Landmarks Commission	V. V. Smith Auto Service	K DL
Specific Location	16. Thematic Category	28. No. of Stories
	to, thomatic datagraph	29. Basement? Yes
1604 Oak	17. Date(s) or Period	No I
	1922	30. Foundation Material
City or Town - If Rural, Township &	Vicinity 18 Style or Design	
Mansas City, Missouri		31. Wall Construction masonry
Site Plan with North Arrow	19. Architect or Engineer	32. Roof Type & Material
4	20. Contractor or Builder	flat; composition
	Andrew Ohleson	33. No. of Bays
1.6	21. Original Use, if apparent	Front 3 Side
,,	commercial	34. Wall Treatment
	22. Present Use	brick; metal 35 Plan Shape rectangula
8	commercial 23 Ownership Public !!	36. Changes Addition
	Private	(Explain Altered x
	24. Owner's Name & Address,.	in #42) Moved i
	- KNOWN	37. Condition Interior
Coordinates UTM		Exterior good
Long	25. Open to Yes lx	38. Preservation Yes
Site!: Struc	Public? No 11	Underway? No.x
Building X: OI	pject     26. Local Contact Person or Organization	39. Endangered? Yes
On National Yes   12 Is II	Yes X Landmarks Commission	By What? No X
Penister? No.X: Fligible?		
Register? No X: Eligible?	27. Other Surveys in Winch included	40 Visible from Ves V
Part of Estab. Yes   1   14. District Hist. Dist.? No x   Potent'!?	Yes X No X	
Part of Estab. Yes 11 14. District Hist. Dist.? No x1 Potent'1?	Yes X	Public Road? No I
Part of Estab. Yes   1	Yes X	Public Road? No I  41. Distance from and Frontage on Road
Part of Estab. Yes   1	Yes X No :.	Public Road? No 1  41. Distance from and Frontage on Road 50 feet on Oak has been considerably
Part of Estab. Yes   14. District Hist. Dist.? No x 1 Potent'1?  Name of Established District  Further Description of Important Featural Latered, with the application placed and is flanked by two	Yes X No 1.	Public Road? No!  41. Distance from and Frontage on Road 50 feet on Oak has been considerably garage bay is centrally
Part of Estab. Yes   14. District Hist. Dist.? No x 1 Potent' 1?  Name of Established District  Further Description of Important Featural Lered, with the application placed and is flanked by two access.  History and Significance The buil	Yes x No:	Public Road? No !  41. Distance from and Frontage on Road 50 feet on Oak has been considerably garage bay is centrally ways for pedestrian  mith Auto Service Compan
Part of Estab. Yes   14. District Hist. Dist.? No x 1 Potent' 1?  Name of Established District  Further Description of Important Featuratered, with the application placed and is flanked by two access.  History and Significance The builthe building was apparently be	Yes X No X N	Public Road? No 1  41. Distance from and Frontage on Road 50 feet on Oak has been considerably garage bay is centrally ways for pedestrian  mith Auto Service Compan
Part of Estab. Yes   14. District Hist. Dist.? No x   Potent'   Potent'     Name of Established District   Putter Description of Important Featuratered, with the application placed and is flanked by two access.  History and Significance The builtine building was apparently building was apparently building vice-president, respectively.	Yes X No  No  Yes The building which faces east on Oak I of corrugated metal to the facade. A storefront bays which each contain door ding was originally leased by the V.V. Suilt for Rufus Crosby Kemper and William	Public Road? No 1  41. Distance from and Frontage on Road 50 feet on Oak  mas been considerably garage bay is centrally ways for pedestrian  mith Auto Service Companion. Norman, president
Part of Estab. Yes   14. District Hist. Dist.? No x   Potent' ?  Name of Established District  Further Description of Important Feature of the Potent' of Important Feature of Itered, with the application laced and is flanked by two coess.  History and Significance The builtine building was apparently building was apparently building vice-president, respective of Description of Environment and Outbuilding the Potent' of Potent	Yes X No X N	Public Road? No 1  41. Distance from and Frontage on Road 50 feet on Oak  mas been considerably garage bay is centrally ways for pedestrian  mith Auto Service Companion. Norman, president
Part of Estab. Yes   1 Hist. Dist.? No x   14. District Potent'!?  Name of Established District  Further Description of Important Feature ltered, with the application laced and is flanked by two ccess.  History and Significance The built he building was apparently build vice-president, respective  Description of Environment and Outbuild and west of this structure.	Yes X No X N	Public Road? No 1  41. Distance from and Frontage on Road 50 feet on Oak has been considerably garage bay is centrally ways for pedestrian  mith Auto Service Compar O. Norman, president  the north, south, east,
Part of Estab. Yes   14. District Hist. Dist.? No x   Potent' ?  Name of Established District  Further Description of Important Feature laced, with the application laced and is flanked by two access.  History and Significance The built he building was apparently building was apparently building vice-president, respective and west of this structure.  Sources of Information IP #68020	Yes X No X N	Public Road? No 1  41. Distance from and Frontage on Road 50 feet on Oak has been considerably garage bay is centrally ways for pedestrian  mith Auto Service Companio. Norman, president  the north, south, east,  46. Prepared by Uguccioni
Part of Estab. Yes   14. District Hist. Dist.? No x   Potent' ?  Name of Established District  Further Description of Important Feature laced, with the application laced and is flanked by two ccess.  History and Significance The builtine building was apparently building was apparently building vice-president, respective and west of this structure.  Sources of Information IP #68020	Yes X No X N	Public Road? No 1  41. Distance from and Frontage on Road 50 feet on Oak has been considerably garage bay is centrally ways for pedestrian  mith Auto Service Compar O. Norman, president  the north, south, east,  46. Prepared by Uguccioni  47. Organization
Part of Estab. Yes   14. District Hist. Dist.? No x   14. District Potent'!?  Name of Established District  Further Description of Important Feature Potent's Potent'	Yes X No X N	Public Road? No 1  41. Distance from and Frontage on Road 50 feet on Oak has been considerably garage bay is centrally ways for pedestrian  mith Auto Service Compan O. Norman, president  the north, south, east,  46. Prepared by Uguccioni



/h_K	. Present Name(s)	+	
26-B 2 County Jackson	Lippelgoes Painting Company		26-
3 Location of Negatives MT #108-2 Landmarks Commission of KC	Other Name(s) Henry Lippelgoes Painting Company Bu	ilding	В
6. Specific Location	16. Thematic Category	28. No. of Stories 1	,
1607 Oak	17. Date(s) or Period	29. Basement? Yes I No I	Jack
1007 048	1940 (add.1950)	30. Foundation Material	Jackson
7 City or Town - If Rural, Township & Vic	inity 18. Style or Design	01	nos
Kansas City, Missouri  8. Site Plan with North Arrow	19. Architect or Engineer	31. Wall Construction concrete block	
11 /	To Allinest of Engineer	32. Roof Type & Material	
1	Bert J. Rumgardner	flat; tar & gravel 33. No. of Bays	
19 3	Bert J. Bumgardner	33. No. of Bays Front-5 Side	
1 4	commercial O⊃E AW	34. Wall Treatment	1607
8	22. Present Use commercial	brick 30 35. Plan Shape rectangular	07 (
0	23 Ownership Public !!	36. Changes Addition X	Oak
	Private k	(Explain Altered I in #42) Moved I	90
	24. Owner's Name & Address, if known	37. Condition	
9. Coordinates UTM		Interior	
Lat. Long.		Exterior - good	
10. Site!: Structur	25. Open to Yes XI Public? No II	38. Preservation Yes Underway? No ix	
Building 1x Object		39. Endangered? Yes I	
	Landmarks Commission of KC	By What? No lx	
	27. Other Surveys in Which Included	40. Visible from Yes !X	-
	0 X.	Public Road? No 11	
15. Name of Established District		41. Distance from and Frontage on Road	
		the state of the s	
42. Further Description of Important Features head garage door are at the sour	The main tacade taces west. A glass e th end of this facade. The building wa	ntrance door and an over- s enlarged in 1950.	Henry Lippels
head garage door are at the source.  43. History and Significance This was ori	th end of this facade. The building wa	s enlarged in 1950.	Henry Lippelgoes
head garage door are at the sou	th end of this facade. The building wa	s enlarged in 1950.	Henry Lippelgoes Pa
head garage door are at the source.  43. History and Significance This was ori	th end of this facade. The building wa	s enlarged in 1950.	Henry Lippelgoes Paint
head garage door are at the source.  43. History and Significance This was ori	th end of this facade. The building wa	s enlarged in 1950.	Henry Lippelgoes Painting
head garage door are at the source of the so	th end of this facade. The building wa	Lippelgoes Painting	Henry Lippelgoes Painting Co
head garage door are at the source of the so	ginally constructed to house the Henry ccupies the building.	Lippelgoes Painting	Henry Lippelgoes Painting Company
43. History and Significance This was ori Company. The same firm still o	ginally constructed to house the Henry ccupies the building.	Lippelgoes Painting  St and west of this	Henry Lippelgoes Painting Company
43. History and Significance This was ori Company. The same firm still o	ginally constructed to house the Henry ccupies the building.	Lippelgoes Painting	Henry Lippelgoes Painting Company
43. History and Significance This was ori Company. The same firm still o  44. Description of Environment and Outbuildingstructure. To the south is a su  45. Sources of Information	ginally constructed to house the Henry ccupies the building.	Lippelgoes Painting  St and west of this  46. Prepared by PILAND	Henry Lippelgoes Painting Company



49. Revision Date(s)

48. Date 5/17/82

BP #14666

State Historical Survey and Planning Office, 909 University Avenue, Suite 215



	C 4. Pres	sent Name(s)	
County		ker Electric & Tool Service	
County Jackson	5 Oth	er Name(s)	
Location of Negatives M	T #108-3	1611-1615 Oak Street Bin	Idiin
andmarks Commissi	on of KC	Property of the state of the st	THE RESIDENCE OF THE PERSON NAMED IN COLUMN 2 IS NOT THE OWNER, THE PERSON NAMED IN COLUMN 2 IS NOT THE OWNER,
Specific Location		16. Thematic Category	28. No. of Stories 1-/
1611-15 Oak		17 Date(s) or Period	29 Basement? Yes I No I
		1929 (add 1938)	30. Foundation Material
	al, Township & Vicinity	18 Style or Design	01
Kansas City, N		67	31 Wall Construction
Site Plan with North Ar	row	19. Architect or Engineer	masonry UD  32. Roof Type & Material F+PI
		20. Contractor or Builder	flat: tar & gravel 99
N		W. B. Kirkendall	33. No. of Bays
1 1)	-	21. Original Use, if apparent	Front -6 Side
1 2		commercial 02E	34 Wall Treatment brick 30
2		commercial	35. Plan Shape rectangular
1		23 Ownership Public I	36 Changes Addition 12
		Private X	(Explain Altered I in #42) Moved I
		24. Owner's Name & Address, if known	37. Condition
		, and the second	Interior
Coordinates Lat.	<b>ИТМ</b>		Exterior-good
Long		25. Open to Yes 🔀	38 Preservation Yes
Site ! :	Structure	Public? No II	Underway? Nox
Building X1	Object	26. Local Contact Person or Organization	39 Endangered? Yes I
	12 Is It Yes X	Landmarks Commission of KC	By What? Nox
		Estrange Ro Comment of the Ro	
Register? No X!	Eligible? No 1:	27. Other Surveys in Which Included	40. Visible from Yes Y
Register? No X!		27. Other Surveys in Which Included	40. Visible from YesX Public Road? No
Register? No X: Part of Estab Yes   1 Hist. Dist.? No X	Eligible? No 1:  14 District Yes x Potent'!? No 1:	27. Other Surveys in Which Included	Public Road? No i
Register? No X: Part of Estab Yes     Hist. Dist.? No X	Eligible? No 1:  14 District Yes x Potent'!? No 1:	27. Other Surveys in Which Included	Public Road? No i  41. Distance from and Frontage on Road
Part of Estab. Yes   1 Hist. Dist.? No X   Name of Established D  Further Description of the structure W	Eligible? No 1:  14 District Yes x Potent'!? No 1:  istrict  Important Features The as erected in 192	27. Other Surveys in Which Included  main facade of this building face and it was enlarged to the north	Public Road? No 1  41. Distance from and Frontage on Road  58 ft on Oak  s west. The south half in 1938. Each half of
Part of Estab Yes   1 Hist Dist.? No X   Name of Established D Further Description of f the structure Whe building contact ransom.	Eligible? No ::  14 District Yes x Potent'!? No ::  istrict  Important Features The as erected in 192 ins an overhead g	27. Other Surveys in Which Included  main facade of this building face 8 and it was enlarged to the north garage door, an entrance door, and	Public Road? No 14  41. Distance from and Frontage on Road  58 ft on Oak  s west. The south half in 1938. Each half of a plate glass window with
Part of Estab Yes   1 Hist. Dist.? No XI  Name of Established D  Further Description of f the structure Whe building contaransom.	Eligible? No ::  14 District Yes x Potent'!? No ::  istrict  Important Features The as erected in 192 ins an overhead g	27. Other Surveys in Which Included  main facade of this building face and it was enlarged to the north	Public Road? No 4  41. Distance from and Frontage on Road  58 ft on Oak  s west. The south half in 1938. Each half of a plate glass window with
Part of Estab. Yes   1 Hist. Dist.? No XI  Name of Established D  Further Description of f the structure whe building contaransom.  History and Significance and Coffey.	Eligible? No ::  14 District Yes x Potent'!? No ::  istrict  Important Features The as erected in 192 ins an overhead generated the second sec	27. Other Surveys in Which Included  28 main facade of this building face 28 and it was enlarged to the north 29 garage door, an entrance door, and  29 t of this building was an auto trip  30 tof this building was an auto trip  31 curface parking lots are north and	Public Road? No (41. Distance from and Frontage on Road 58 ft on Oak 58 west. The south half in 1938. Each half of a plate glass window with supply firm operated by
Part of Eslab Yes II Hist. Dist.? No XI  Name of Established D  Further Description of f the structure whe building contaransom.  History and Significance aude Coffey.  Description of Environment Sources of Information	Eligible? No ::  14 District Yes x Potent'!? No ::  istrict  Important Features The as erected in 192 ins an overhead generated the second sec	27. Other Surveys in Which Included  28 main facade of this building face 28 and it was enlarged to the north 29 garage door, an entrance door, and  29 t of this building was an auto trip  30 tof this building was an auto trip  31 curface parking lots are north and	Public Road? No 19 41. Distance from and Frontage on Road 58 ft on Oak s west. The south half in 1938. Each half of a plate glass window with supply firm operated by west of this building. To the south half in Supply firm operated by west of this building. To the south half in 1938. Each half of a plate glass window with supply firm operated by the supply firm ope
Part of Eslab Yes   1 Hist. Dist.? No X   Name of Eslablished D  Further Description of f the structure whe building contaransom.  History and Significance aude Coffey.  Description of Environment of the south and east Sources of Information of #15402; 15872	Eligible? No ::  14 District Yes x Potent'!? No ::  istrict  Important Features The as erected in 192 ins an overhead generated the second sec	27. Other Surveys in Which Included  28 main facade of this building face 28 and it was enlarged to the north 29 garage door, an entrance door, and  29 t of this building was an auto trip  30 tof this building was an auto trip  31 curface parking lots are north and	Public Road? No.  41. Distance from and Frontage on Road  58 ft on Oak  s west. The south half in 1938. Each half of a plate glass window with supply firm operated by west of this building. The south half in 1938. The south half in 1938 are supply firm operated by west of this building. The supply firm operated by PILAND
Part of Eslab Yes II Hist. Dist.? No XI  Name of Established D  Further Description of f the structure whe building contaransom.  History and Significance and Coffey.	Eligible? No ::  14 District Yes x Potent'!? No ::  istrict  Important Features The as erected in 192 ins an overhead generated the second sec	27. Other Surveys in Which Included  28 main facade of this building face 28 and it was enlarged to the north 29 garage door, an entrance door, and  29 t of this building was an auto trip  30 tof this building was an auto trip  31 curface parking lots are north and	Public Road? No id  41. Distance from and Frontage on Road  58 ft on Oak  s west. The south half in 1938. Each half of a plate glass window with the supply firm operated by  west of this building. The supply firm operated by



. No.	4. Pres	1VENTORY 54-AS-008-1315			
26-D	To	Tool and Industrial Sales, Inc.			
County Jackson	5 Oth	5 Other Name(s)			
Location of Negatives		7			
Landmarks Commiss:					
Specific Location		16. Thematic Category	28. No. of Stories 2		
617 Only Street B	a Stateman	030 050	29. Basement? Yes!		
517 Oak Street B	unaing	17. Date(s) or Period	No I		
City or Tayer II Book Tayership & Vicinia		1899 (alt. 1929; add. 1945)	30. Foundation Material		
City or Town II Rural, Township & Vicinity Kansas City, Missouri		To Style of Design	31. Wall Construction		
Site Plan with North Ar		19. Architect or Engineer other	masonry LB		
Vi		30 40	32. Roof Type & Material Ft PL		
N L		20. Contractor or Builder	flat; tar & gravel 99		
1 4		21. Original Use, if apparent Prich	33. No. of Bays Front Side		
12		unknown ODE AW	34. Wall Treatment		
2		22. Present Use	brick 30		
1		commercial	35. Plan Shape rectangular		
1		23 Ownership Public !!	36. Changes Addition &		
Ó		Private KI	(Explain Altered in #42) Moved		
		24. Owner's Name & Address, if known	37. Condition		
2. Coordinates UTM			Interior		
Lat.			Exterior good		
Long.		25. Open to Yes III	38. Preservation Yes		
Site!: Building!	Structure 1 Object 1 1	Public? , No k	Underway? No i <sub>X</sub>		
		26. Local Contact Person or Organization Landmarks Commission	39. Endangered? Yes II By What? No I <sub>x</sub> :		
On National Yes     Register? No   +	12 Is It Yes XX Eligible? No !!	27. Other Surveys in Which Included	- X		
		27. Other Surveys in Willen included	40. Visible from Yes !X		
Λ	14. District Yes XX				
Λ	14. District Yes XX Potent'1? No : .		Public Road? No 11		
Part of Estab. Yes II Hist. Dist.? No xx	Potent'l? No :		Public Road? No 11 41. Distance from and		
Part of Estab. Yes II Hist. Dist.? No xx	Potent'l? No :		Public Road? No 11		
Part of Estab. Yes     Hist. Dist.? No xx Name of Established D	Potent'l? No : .	The first story of the west facade	Public Road? No 11  41. Distance from and Frontage on Road 25 feet on Oak		
Part of Estab. Yes     Hist. Dist.? No xx  Name of Established D	Potent'l? No : . istrict Important Features	The first story of the west facade lows which flank a central entrance	Public Road? No!!  41. Distance from and Frontage on Road 25 feet on Oak has been altered, and		
Part of Estab. Yes     Hist. Dist.? Noxx  Name of Established D  Further Description of irrently contains	Potent'l? No: istrict Important Features plate glass wind	The first story of the west facade dows which flank a central entrance stone coping. A wrought iron raili	Public Road? No !!  41. Distance from and Frontage on Road 25 feet on Oak  has been altered, and door. The first story		
Part of Estab. Yes     Hist. Dist.? No xx  Name of Established D  Further Description of arrently contains erminates in two the two stories	Potent'l? No: istrict  Important Features plate glass wind projections and s The 2nd story	lows which flank a central entrance stone coping. A wrought iron raili is set back slightly and is fenest	Public Road? No!!  41. Distance from and Frontage on Road 25 feet on Oak  has been altered, and door. The first story and marks the division rated with three		
Part of Estab. Yes     Hist. Dist.? No xx  Name of Established D  Further Description of arrently contains erminates in two the two stories	Potent'l? No: istrict  Important Features plate glass wind projections and s The 2nd story	lows which flank a central entrance stone coping. A wrought iron raili	Public Road? No!!  41. Distance from and Frontage on Road 25 feet on Oak  has been altered, and door. The first story and marks the division rated with three		
Part of Estab. Yes II Hist. Dist.? No xx Name of Established D Further Description of arrently contains erminates in two the two stories	Potent'l? No: istrict  Important Features plate glass wind projections and s The 2nd story	lows which flank a central entrance stone coping. A wrought iron raili is set back slightly and is fenest	Public Road? No!!  41. Distance from and Frontage on Road 25 feet on Oak  has been altered, and door. The first story and marks the division rated with three		
Part of Estab. Yes II Hist. Dist.? No xx Name of Established D Further Description of arrently contains erminates in two fifthe two stories	Potent'l? No: istrict  Important Features plate glass wind projections and s The 2nd story	lows which flank a central entrance stone coping. A wrought iron raili is set back slightly and is fenest	Public Road? No!!  41. Distance from and Frontage on Road 25 feet on Oak  has been altered, and door. The first story and marks the division rated with three		
Part of Estab. Yes II Hist. Dist.? No xx  Name of Established D  Further Description of arrently contains erminates in two fithe two stories ectangular window	Potent'l? No: istrict  Important Features plate glass wind projections and s The 2nd story s. The cornice of	lows which flank a central entrance stone coping. A wrought iron raili is set back slightly and is fenest of the building is decorated with b	Public Road? No!!  41. Distance from and Frontage on Road 25 feet on Oak  has been altered, and door. The first story and marks the division rated with three		
Part of Estab. Yes     Hist. Dist.? Noxx  Name of Established D  Further Description of arrently contains erminates in two f the two stories ectangular window	Potent'l? No: istrict  Important Features plate glass wind projections and s The 2nd story s. The cornice of	lows which flank a central entrance stone coping. A wrought iron raili is set back slightly and is fenest	Public Road? No!!  41. Distance from and Frontage on Road 25 feet on Oak  has been altered, and door. The first story and marks the division rated with three		
Part of Estab. Yes II Hist. Dist.? No xx  Name of Established D  Further Description of arrently contains erminates in two fithe two stories ectangular window	Potent'l? No: istrict  Important Features plate glass wind projections and s The 2nd story s. The cornice of	lows which flank a central entrance stone coping. A wrought iron raili is set back slightly and is fenest of the building is decorated with b	Public Road? No!!  41. Distance from and Frontage on Road 25 feet on Oak  has been altered, and door. The first story and marks the division rated with three		
Part of Estab. Yes II Hist. Dist.? No xx  Name of Established D  Further Description of arrently contains erminates in two fithe two stories ectangular window	Potent'l? No: istrict  Important Features plate glass wind projections and s The 2nd story s. The cornice of	lows which flank a central entrance stone coping. A wrought iron raili is set back slightly and is fenest of the building is decorated with b	Public Road? No!!  41. Distance from and Frontage on Road 25 feet on Oak  has been altered, and door. The first story and marks the division rated with three		
Part of Estab. Yes II Hist. Dist.? Noxx  Name of Established D  Further Description of urrently contains erminates in two f the two stories ectangular window	Potent'l? No: istrict  Important Features plate glass wind projections and s The 2nd story s. The cornice of	lows which flank a central entrance stone coping. A wrought iron raili is set back slightly and is fenest of the building is decorated with b	Public Road? No!!  41. Distance from and Frontage on Road 25 feet on Oak  has been altered, and door. The first story and marks the division rated with three		
Part of Estab. Yes II Hist. Dist.? Noxx Name of Established D  Further Description of urrently contains erminates in two f the two stories ectangular window  History and Significance	Potent'l? No: istrict  Important Features   plate glass wind projections and s   The 2nd story s. The cornice of the cornice o	lows which flank a central entrance stone coping. A wrought iron raili is set back slightly and is fenest of the building is decorated with b	Public Road?  41. Distance from and Frontage on Road 25 feet on Oak  has been altered, and door. The first storying marks the division mated with three rick laid in patterns.		
Part of Estab. Yes II Hist. Dist.? Noxx Name of Established D Further Description of arrently contains erminates in two fifthe two stories ectangular window History and Significance Description of Environm	Potent'l? No: istrict  Important Features   plate glass wind projections and s . The 2nd story s. The cornice of the cornice of the early hist	dows which flank a central entrance stone coping. A wrought iron railing is set back slightly and is fenest of the building is decorated with become of this building is unknown.  A surface parking lot is south of the stone of the surface parking lot is south of the stone of the surface parking lot is south of the stone of the surface parking lot is south of the stone of the surface parking lot is south of the stone of the surface parking lot is south of the stone of the surface parking lot is south of the stone of the surface parking lot is south of the stone of the surface parking lot is south of the surface parking lot is surface parking lot is south of the surface parking lot is surface parking lot is south of the surface parking lot is surface parking lot is surface parking lot is surface parking lot is sur	Public Road?  41. Distance from and Frontage on Road 25 feet on Oak  has been altered, and door. The first story and marks the division rated with three rick laid in patterns.		
Part of Estab. Yes     Hist. Dist.? Noxx  Name of Established D  Further Description of arrently contains erminates in two the two stories ectangular window  History and Significance  Description of Environm	Potent'l? No: istrict  Important Features   plate glass wind projections and s . The 2nd story s. The cornice of the cornice of the early hist	lows which flank a central entrance stone coping. A wrought iron railing is set back slightly and is fenest of the building is decorated with become of this building is unknown.	Public Road?  41. Distance from and Frontage on Road 25 feet on Oak  has been altered, and door. The first story and marks the division rated with three rick laid in patterns.		
Part of Estab. Yes     Hist. Dist.? Noxx  Name of Established D  Further Description of arrently contains erminates in two the two stories ectangular window  History and Significance  Description of Environm	Potent'l? No: istrict  Important Features   plate glass wind projections and s . The 2nd story s. The cornice of the cornice of the early hist	dows which flank a central entrance stone coping. A wrought iron railing is set back slightly and is fenest of the building is decorated with become of this building is unknown.  A surface parking lot is south of the stone of the surface parking lot is south of the stone of the surface parking lot is south of the stone of the surface parking lot is south of the stone of the surface parking lot is south of the stone of the surface parking lot is south of the stone of the surface parking lot is south of the stone of the surface parking lot is south of the stone of the surface parking lot is south of the surface parking lot is surface parking lot is south of the surface parking lot is surface parking lot is south of the surface parking lot is surface parking lot is surface parking lot is surface parking lot is sur	Public Road?  41. Distance from and Frontage on Road 25 feet on Oak  has been altered, and door. The first story and marks the division rated with three wrick laid in patterns.		
Part of Estab. Yes II Hist. Dist.? Noxx Name of Established D  Further Description of arrently contains erminates in two erminates in two ectangular window  History and Significance  Description of Environma commercial buil	Potent'l? No: istrict  Important Features   plate glass wind projections and s . The 2nd story s. The cornice of the cornice of the early hist	dows which flank a central entrance stone coping. A wrought iron railing is set back slightly and is fenest of the building is decorated with become of this building is unknown.  A surface parking lot is south of the stone of the surface parking lot is south of the stone of the surface parking lot is south of the stone of the surface parking lot is south of the stone of the surface parking lot is south of the stone of the surface parking lot is south of the stone of the surface parking lot is south of the stone of the surface parking lot is south of the stone of the surface parking lot is south of the surface parking lot is surface parking lot is south of the surface parking lot is surface parking lot is south of the surface parking lot is surface parking lot is surface parking lot is surface parking lot is sur	Public Road?  41. Distance from and Frontage on Road 25 feet on Oak  has been altered, and door. The first story and marks the division rated with three rick laid in patterns.  this building. ace parking lot.		
Part of Estab. Yes II Hist Dist.? Noxx Name of Established D  Further Description of Irrently contains erminates in two is the two stories ectangular window  History and Significance  Description of Environman commercial buil  Sources of Information P #15962	Potent'l? No: istrict  Important Features   plate glass wind projections and s . The 2nd story s. The cornice of the cornice of the early hist	dows which flank a central entrance stone coping. A wrought iron railing is set back slightly and is fenest of the building is decorated with become of this building is unknown.  A surface parking lot is south of the stone of the surface parking lot is south of the stone of the surface parking lot is south of the stone of the surface parking lot is south of the stone of the surface parking lot is south of the stone of the surface parking lot is south of the stone of the surface parking lot is south of the stone of the surface parking lot is south of the stone of the surface parking lot is south of the surface parking lot is surface parking lot is south of the surface parking lot is surface parking lot is south of the surface parking lot is surface parking lot is surface parking lot is surface parking lot is sur	Public Road?  41. Distance from and Frontage on Road 25 feet on Oak  has been altered, and door. The first story and marks the division rated with three wick laid in patterns.  this building. The parking lot.  46. Prepared by Uguccioni		
Part of Estab. Yes II Hist. Dist.? Noxx  Name of Established D  Further Description of urrently contains erminates in two f the two stories ectangular window  History and Significance  Description of Environm  A commercial buil  Sources of Information P #15962 #91318	Potent'l? No: istrict  Important Features   plate glass wind projections and s . The 2nd story s. The cornice of the cornice of the early hist	dows which flank a central entrance stone coping. A wrought iron railing is set back slightly and is fenest of the building is decorated with become of this building is unknown.  A surface parking lot is south of the stone of the surface parking lot is south of the stone of the surface parking lot is south of the stone of the surface parking lot is south of the stone of the surface parking lot is south of the stone of the surface parking lot is south of the stone of the surface parking lot is south of the stone of the surface parking lot is south of the stone of the surface parking lot is south of the surface parking lot is surface parking lot is south of the surface parking lot is surface parking lot is south of the surface parking lot is surface parking lot is surface parking lot is surface parking lot is sur	Public Road?  41. Distance from and Frontage on Road 25 feet on Oak  has been altered, and door. The first story and marks the division rated with three rick laid in patterns.  this building. The parking lot.  46. Prepared by Uguccioni  47. Organization		
Part of Estab. Yes II Hist. Dist.? Noxx  Name of Established D  Further Description of urrently contains erminates in two f the two stories ectangular window  History and Significance  Description of Environm  A commercial buil  Sources of Information P #15962	Potent'l? No: istrict  Important Features   plate glass wind projections and s . The 2nd story s. The cornice of the cornice of the early hist	dows which flank a central entrance stone coping. A wrought iron railing is set back slightly and is fenest of the building is decorated with become of this building is unknown.  A surface parking lot is south of the stone of the surface parking lot is south of the stone of the surface parking lot is south of the stone of the surface parking lot is south of the stone of the surface parking lot is south of the stone of the surface parking lot is south of the stone of the surface parking lot is south of the stone of the surface parking lot is south of the stone of the surface parking lot is south of the surface parking lot is surface parking lot is south of the surface parking lot is surface parking lot is south of the surface parking lot is surface parking lot is surface parking lot is surface parking lot is sur	Public Road?  41. Distance from and Frontage on Road 25 feet on Oak  has been altered, and door. The first story and marks the division rated with three wick laid in patterns.  this building. The parking lot.  46. Prepared by Uguccioni		



-
ж.
-
-
=
~
-
-
~
-
-
-
-
-
-
10
C
-

		ventory	umbia, Missouri 65201	
1. No. 26-E 2 County Jackson 3 Location of Negatives MT Landmarks Commission	4. Pres Bi	sent Name(s)	JA-AS-008-1516 lan Tile Company Building	26-E
6 Specific Location 1625 Oak 7 City or Town If Rural, To Kansas City, Missouri		16. Thematic Category 030050  17. Date(s) or Period 1916  18. Style or Design 50 49	28. No. of Stories 2 29. Basement? Yes X No 1 30. Foundation Material	Jackson
8. Site Plan with North Arrow	חל גד	19. Architect or Engineer Edgar C. Faris 20. Contractor or Builder  21. Original Use, if apparent commercial ODE AW  22. Present Use commercial 23. Ownership Public 11	reinforced concrete  32. Roof Type & Material FPR flat; tar & gravel 94  33. No. of Bays Front 3 Side  34. Wall Treatment 50 50  brick; metal  35. Plan Shape rectangular  36. Changes Addition ::	1625 Oak
9. Coordinates UTM Lat. Long.  10. Site I:	Structure	24. Owner's Name & Address, if known  25. Open to Public?  Yes   X No	(Explain in #42)  37. Condition Interior  Exterior good  38. Preservation Yes Inderway?  No ix	5
Building X Object 1 1 11. On National Yes 1 12 Is It Yes X Register? No X Eligible? No 1 1 13 Part of Estab. Yes 1 1 14 District Yes X Potent'l? No 1 15 Name of Established District		26. Local Contact Person or Organization Landmarks Commission 27. Other Surveys in Which Included	39. Endangered? By What?  40. Visible from Public Road?  41. Distance from and Frontage on Road 58 feet on Oak	
small window is north facade. A 3rd window floor and all the 2nd panels in brick run in course enlivens the pa	of the entra is at the no floor window horizontal arapet wall. to the roof 1	e main entrance is at the south end nce door and another is around the rth end of the west facade. All of s are obscured by corrugated metal bands above the 1st and 2nd floors Terra cotta coping terminated the ine and round balls placed on the further decoration.	d of the west facade. A corner, on the south ther windows on the 1st panels. Rectangular. A terra cotta band building. Terra cotta	Control of the Contro
Company. Later, for The building contains	many years i 13,000 squar	of this Building was the Republic t was the home of the American and e feet.  A surface parking lot is north of 1 building is to the south. To the	Venetian Tile Company.	
WP #13210 Western Contractor, Aug. 2, 1916, p. 19.			46. Prepared by Piland 47. Organization	
Kansas City Star, July 12, 1981, p. 3H.			Landmarks Commission  48. Date 49. Revision Date(s)	



48. Date 49. Revision Date(s)

1/31/83

Kansas City Star, Sept. 18, 1929,

p.4D.



WP #135838

BP #4648

12-

1701

Oak

Piland

48. Date

1/28/83

47. Organization

Landmarks Commission

49 Revision Date(s)



41-L		sent Name(s)	+
2 County Jackson		1716 (A) Oak not	
3 Location of Negatives M	AT #8-21	er Name(s) Entered 1710 Oak	
Landmarks Commissi	on of KC		
6. Specific Location		16. Thematic Category	28. No. of Stories 1 29. Basement? Yes
1716 (A) Oak		17. Date(s) or Period .	29. Basement? Yes I
		1946	30. Foundation Material
7 City or Town If Rur		18 Style or Design	
Kansas City, 1		19. Architect or Engineer	31. Wall Construction concrete block
. One rian with from A	1	Emil Bayerl	32. Roof Type & Material
	1	20. Contractor or Builder	flat; tar and gravel
	r 18	Winn-Senter Const. Co.	33. No. of Bays Front Side
	p 14	21. Original Use, if apparent commercial	34. Wall Treatment
	y	22. Present Use	stucco
-	Neo /	commercial	35. Plan Shape rectangular
	9 1	23 Ownership Public   1 Private M	36. Changes Addition : (Explain Altered 🔀
		24. Owner's Name & Address, if known	
9. Coordinates	итм		37. Condition Interior
Lat.	UIM		Exterior good
Long		25. Open to Yes II	38. Preservation Yes
0 Site!: Building IX	Structure     Object	Public? No 11	Underway? No x
11. On National Yes	12 Is It Yes	26. Local Contact Person or Organization	39. Endangered? Yes I By What? No Ix
Register? No IX	Eligible? No x	Landmarks Commission of KC 27. Other Surveys in Which Included	
3. Part of Estab. Yes     Hist. Dist.? No lx	14. District Yes   Potent'l? No X		40. Visible from Yes X Public Road? No 1
	A CAMPANIA TO THE PARTY OF THE		
a Mame of Established D	HETTICI		M41. Distance from and
15. Name of Established D		main facade of this building fac	41. Distance from and Frontage on Road 27 feet on Oak
42. Further Description of a 41 foot space, a in with concrete bl	Important Features The twin structure. Lock and fenestra	main facade of this building fac Garage openings across the south ted with multipaned windows. Two rage openings were altered in 196	Frontage on Road 27 feet on Oak es south, to mirror across facade have been filled groups of four windows
42. Further Description of a 41 foot space, a in with concrete blace and the east of the east of the Bowntown Buick designed as grease of the Description of Environment.	Important Features The twin structure. Lock and fenestrate facade. The gate one of a pair Company, probably and service stall	Garage openings across the south ted with multipaned windows. Two rage openings were altered in 196 of structures, separated by a 41 as part of their used car operate	Frontage on Road 27 feet on Oak es south, to mirror across facade have been filled groups of four windows 1.  foot space, erected for tion. This building was th. Commercial buildings
12. Further Description of a 41 foot space, a in with concrete blue fenestrate the east of the Bowntown Buick designed as grease 4. Description of Environment to the north, east of the	Important Features The twin structure. Lock and fenestrate facade. The gate one of a pair Company, probably and service stall	Garage openings across the south ted with multipaned windows. Two rage openings were altered in 196 of structures, separated by a 41 as part of their used car operatels.	Frontage on Road 27 feet on Oak es south, to mirror across facade have been filled groups of four windows 1.  foot space, erected for tion. This building was th. Commercial buildings the east.
2. Further Description of a 41 foot space, a in with concrete blue fenestrate the east of the Bowntown Buick designed as grease 4. Description of Environment to the north, east of the sources of Information	Important Features The twin structure. Lock and fenestrate facade. The gate one of a pair Company, probably and service stall	Garage openings across the south ted with multipaned windows. Two rage openings were altered in 196 of structures, separated by a 41 as part of their used car operatels.	Frontage on Road 27 feet on Oak es south, to mirror across facade have been filled groups of four windows 1.  foot space, erected for tion. This building was the Commercial buildings the east.
12. Further Description of a 41 foot space, a in with concrete blue fenestrate the east of the Bountown Buick designed as grease of the north, east of the north, east of the sources of Information WP #3124	Important Features The twin structure. Lock and fenestrate facade. The gate one of a pair Company, probably and service stall	Garage openings across the south ted with multipaned windows. Two rage openings were altered in 196 of structures, separated by a 41 as part of their used car operatels.	Frontage on Road 27 feet on Oak es south, to mirror across facade have been filled groups of four windows 1.  foot space, erected for tion. This building was th. Commercial buildings the east.
12. Further Description of a 41 foot space, a in with concrete blue fenestrate the east of the Downtown Buick designed as grease are to the north, east of the north, east of the sources of Information	Important Features The twin structure. Lock and fenestrate facade. The gate one of a pair Company, probably and service stall	Garage openings across the south ted with multipaned windows. Two rage openings were altered in 196 of structures, separated by a 41 as part of their used car operatels.	Frontage on Road 27 feet on Oak es south, to mirror across facade have been filled groups of four windows 1.  foot space, erected for tion. This building was the cast.  46 Prepared by PILAND



HIS	TORIC I''	VENTORY	5x-45-008-1320	
1. No. 41-K	4. Pre	sent Name(s)	4	
		1716 (B) Oak not entered		4
2. County Jackson	5 Oth	er Name(s)		41-K
1 Landmarks Commissi	MT #8-20 on of KC	1710 Oak		
6. Specific Location		16. Thematic Category	28. No. of Stories 1	
1717791 0 1		17. Debutes on Booked	29. Basement? Yes	Jackson
1716(B) Oak		17 Date(s) or Period 1946	No I .	acks
7. City or Town - If Rur	al, Township & Vicinity	18 Style or Design	- So. Poundation Material	non
Kansas City, 1	Missouri		31. Wall Construction	1
B. Site Plan with North Ar	row	19 Architect or Engineer	concrete block	-
	.1	Emil Bayerl 20. Contractor or Builder	32. Roof Type & Material flat; tar and gravel	
	N	Winn-Senter Const. Co.	33. No. of Bays	1
	7 14	21. Original Use, if apparent	Front Side	
	.0	commercial 22. Present Use	34. Wall Treatment stucco	1 0
	*	commercial	35. Plan Shape rectangular	1716
	6	23 Ownership Public   1	36. Changes Addition :	-
		PrivateXX	(Explain Altered I in #42) Moved I	~
		24. Owner's Name & Address, if known	37. Condition	0ak
	UTM		Exterior good	
Lat. Long.		25. Open to Yes I		1
10. Site ! :	Structure 1	Public? No 11	Underway? No X	
Building X	Object !	26. Local Contact Person or Organization	39. Endangered? Yes III	
11. On National Yes     Register? No XI	12 Is It Yes : Eligible? No x	Landmarks Commission of KC 27. Other Surveys in Which Included	- By What?	
13 Part of Estab. Yes     Hist. Dist.? No tel	14 District Yes	27. Other derveys in Which included	40. Visible from Yes X. Public Road? No 11	
15. Name of Established D			41. Distance from and	
section at extreme 4.2			Frontage on Road	
		e main facade of this building fac	27 feet on Oak	$\vdash$
across a 41 foot s	space, a twin str	ucture. Garage openings line the rectangular windows on the east f	north facade, separated	Cinc. Hallets,
Downtown Buick  44. Description of Environm	Company, probably	of structures, separated by a 41 for a spart of their used car operation of their used car operation of the normal dings are to the south, east, and the south, east, east, east, east, east, east, ea	rth, across a 41 foot	
45 Sources of Information			46. Prepared by	
WP #3124		4	PILAND	
BP #16354			47. Organization Landmarks Commission	
			48. Date 49. Revision Date(s)	
			0.74.104	



	TORIC IN		DA-AS-008-1321	
1. No.	4. Pres	sent Name(s)		42-B
42-B 2 County	к.	C. Petroleum Maintenance Company		-B
Jackson		er Name(s)		1
3 Location of Negatives Landmarks Commiss	MT #45-3			
6 Specific Location	AND	16. Thematic Calegory	28 No of Stories 12-1	
1717-19 Oak Stu	et Biuldina	030 050	29. Basement? Yes	Jac
	9	17 Date(s) or Period .	No 1.	Jackson
		1915 (alt. & add. 1926)	30. Foundation Material	on
7 City or Town If Au Kansas City, Miss	al, Township & Vicinity ouri	18 Style or Design	31. Wall Construction	
B. Site Plan with North A		19. Architect or Engineer other	masonry	
1.		30 40	32. Roof Type & Material F+ PC	
N		20. Contractor or Builder	flat; tar & gravel 99	_
19		George L. Brown & Son 21. Original Use, if apparent	Front 3 Side	11 .
1 7		commercial ODE	34. Wall Treatment	117
*		22. Present Use	brick 50	1717-19 Oak
1 4		commercial	35. Plan Shape rectangular	0
9		23 Ownership Public !   Private XX	36. Changes Addition X (Explain Altered X	0ak
		24. Owner's Name & Address,	in #42) Moved	1
		if known	37. Condition Interior	
9. Coordinates Lat.	UTM			
Long		25. Open to Yes XX	Exterior good	
10. Site ! .	Structure   1	Public? No 11	Underway? No X	
Building 1	Object	26. Local Contact Person or Organization	39. Endangered? Yes I	
11. On National Yes 1: Register? No 14	12 Is It Yes X Eligible? No 1:	Landmarks Commission	By What? No X	1
13 Part of Estab Yes	14. District Yes IX	27. Other Surveys in Which Included	40. Visible from Yes X	
Hist. Dist.? No 11	Potent'1? No :		Public Road? No 11	
15. Name of Established D	district		41. Distance from and Frontage on Road	
			50 feet on Oak	
42. Further Description of	Important Features The	e first story features rectangular	store fronts. The bays	-
of the second stor	y are articulated	d by means of brick piers that sepa	rate square windows.	(
possessing stone s	sills. Bands of h	orick laid in soldier course appear	over the windows on	Cuice Hainer
both the first and	second story, and	nd on the parapet wall. The parape	t wall is stepped and	-
torminator in ator	dening of Oak t	was constructed as a single story be he front was cut back and a 2nd sto	rv only 18 feet deep.	ig
cerminates in stor	dening of oak, c	HE TIONE Was car back and a time see	-1 -1	
accommodate the wi			A CONTRACTOR OF THE PARTY OF TH	
accommodate the was added to the was	vest end of the b	uilding.		5
accommodate the was added to the was add	west end of the b			ē
accommodate the was added to the was	west end of the b	uilding.		ę
accommodate the was added to the was add	west end of the b	uilding.		ç
accommodate the was added to the was add	west end of the b	uilding.		Š
accommodate the was added to the was add	west end of the book the earliest known the earliest known any.	uilding. nown tena <del>n</del> t of this building (1917)	was the W. H.	g
accommodate the was added to the was add	west end of the book of the earliest known and outbuildings	nown tenant of this building (1917)  A storage lot is south of this build	was the W. H.	Š
accommodate the will was added to the wa	west end of the book of the earliest known and outbuildings	uilding. nown tena <del>n</del> t of this building (1917)	was the W. H.	Š
accommodate the was added to the was add	west end of the book of the earliest known and outbuildings	nown tenant of this building (1917)  A storage lot is south of this build	was the W. H.	
accommodate the will was added to the wa	west end of the book of the earliest known o	nown tenant of this building (1917)  A storage lot is south of this build	was the W. H.  ding. To the east is a the north is a surface	Š
accommodate the will was added to the wa	west end of the book of the earliest known o	nown tenant of this building (1917)  A storage lot is south of this build	was the W. H.  ding. To the east is a the north is a surface  46 Prepared by Piland /Uquccioni	Ē
accommodate the was added to the was add	west end of the book of the earliest known o	nown tenant of this building (1917)  A storage lot is south of this build	was the W. H.  ding. To the east is a the north is a surface  46. Prepared by Piland /Uquccioni  47. Organization	Ē
accommodate the will was added to the wa	west end of the bite of the earliest known and outbuildings Another comments.	nown tenant of this building (1917)  A storage lot is south of this build	was the W. H.  ding. To the east is a the north is a surface  46 Prepared by Piland /Uquccioni	

Western Contractor, July 14, 1915, p. 29.



1 No 41-J	4 Presen	west Acoustics Inc.	
Jackson	5 Other		
3 toration of NegativeSMT #8-1 Landmarks Commissio	8 & 8- n 19		
Specific Location		6 Thematic Category	28. No of Stories \$-2-1
1722-724 Oak Stu	et Building T	7 Date(s) or Period	29. Basement? Yes !!
1722 24 Odk		c. 1919 (add. 1948)	30. Foundation Material
	ship & Vicinity 1	8 Style or Design	31. Wall Construction
Kansas City, Mo.		9. Architect or Engineer Other	masonry; block UD CB
Sile Flan with Hollin Hollin	.1	30 40	32. Roof Type & Material F+ PR
	N 2	O Contractor or Builder	flat; tar and gravel
	1 1	1. Original Use, if apparent	Front Side 99
16	1	commercial DDE	34. Wall Trealment brick; metal 50 30
5	1	commercial	35. Plan Shape irregular
N X	2	3 Ownership Public ( )	36. Changes Addition xx
6	1	Private M	(Explain Altered XX in #42) Moved
		if known	37. Condition
Coordinates UTM			Exterior good
Lat Lung		95. Open to Yes ⋈	38. Preservation Yes
0 Site	Structure 1	Public? No 11	Underway? No X
Building X  1 On National Yes 12 Is		6 Local Contact Person or Organization	39. Endangered? Yes III
	CONTRACTOR OF THE REAL PROPERTY.	andmarks Commission 7 Other Surveys in Which Included	
	istrict Yes X		40 Visible from Yes XX Public Road? No
5 Name of Established District	Alem III		41. Distance from and
**************************************			Frontage on Road
2 Further Description of Importan	t Feetwes The	north, two-story section of the	125 feet on Oak
uilding was erected c.	1919. The si	ingle story south section was an of both sections was altered in ing over the window areas.	Photo
969 by the addition of			
13 History and Significance The lotor Company. The addition roducts Company.  4 Description of Environment and north and west are other	earliest kno ion of 1948 w	own occupant of this building (19 as undertaken by the tenant at the surface parking lot is south of building. A storage lot is to the south of the building.	hat time, the Electric this building. To the
3 History and Significance The otor Company. The addition of company. The additional control of the control of	earliest kno ion of 1948 w	as undertaken by the tenant at t	this building. To the the east.
3 History and Significance The lotor Company. The additional roducts Company.	earliest kno ion of 1948 w	as undertaken by the tenant at t	this building. To the the east.  46. Prepared by Piland
3 History and Significance The lotor Company. The additional roducts Company.  4 Description of Environment and north and west are otherwise Sources of Information NP #5703; 93055	earliest kno ion of 1948 w	as undertaken by the tenant at t	this building. To the the east.  46. Prepared by Piland



MIDWEST ACOUSTICS, INC.



County

Present Name(s)

umci isame(5,

48. Date 49. Revision Date(s)

12/21/82



BP #84716

Kansas City Star, Arril 4, 1948, 7, 15D

48. Date

6/15/8

49. Revision Date(s)

GLASS FOR EVERY PURPOSE TOPS MIRRORS WINDOW GLASS GLAZING GLAS EVERY

A-A5008-1325

Present Namers

HISTORIC INVENTORY



d Yes	Street
Yes   Ng/X	
Yes XX No i i	
treet th he dows.	o Curco Hainette,
sed	

1. No.	4. Pres	seni Name(s)	JA-A50081326	
57-A 2 County -	180	01-05 Oak Street		57-
Jackson	5(Oth	er)Name(s)		A
3 Location of Negatives Landmarks Commissi	MT# 104-9	401-05 East 18th Street Bulding		
6 Specific Location	0.1 01 1.0	16. Thematic Category	28. No. of Stories 2	
		030 050	29. Basement? Yes	1
1801-05 Oak Str	eet Building	17 Date(s) or Period	30. Foundation Material	Ja
7 City or Town - If Rura	al. Township & Vicinity	18 Style or Device	50. Foundation Material	Jackson
Kansas City, M	Missouri	50 63	31. Wall Construction	on
B. Site Plan with North Arr		19 Architect or Engineer other McKecknie & Trask 30 70 90	22 Part Time & Material Cl. 00	
F. 18 %	57 N	McKecknie & Trask 30 70 40	32. Roof Type & Materia Ct PR flat; tar & gravel 99	
12			33. No. of Bays	
	1	21. Original Use, if apparent Commercial ODE	Front Side	1
NA C		22. Present Use	34. Wall Treatment 50 30 brick, metal, tile	1801
0	4	commercial	35. Plan Shape rectangular	1-05
		23 Ownership Public     Private	36. Changes Addition : (Explain Altered XX	
		24. Owner's Name & Address,	in #42) Moved	0ak
		if known	37. Condition	St
Coordinates I	MTM		Exterior good	ree
Long.		25. Open to Yes II	38. Preservation Yes	et
O Site ! :	Structure	Public? No !!	Underway? No XX	
Building I XX	Object ! !	26. Local Contact Person or Organization	39. Endangered? Yes I By What? Ng.\(\frac{1}{2}\)	
1. On National Yes    Register? No **	12 Is It YesXX Eligible? No 1	Landmarks Commission of KC  27. Other Surveys in Which Included	-	
3. Part of Estab. Yes II	14. District Yes XX Potent'l? No:		40. Visible from Yes XX	
Hist. Dist.? No XX	1.60		Public Road? No !:	1
J. Name of Established Di	Sinci		Frontage on Road	
	- mi	is corner building has frontage on	75 feet on Oak Street	L
Street. Narrow re windows is veneere	ctangular window d with ceramic t	s fenestrate the first floor. The ile. A band of corrugated metal ru covered with corrugated metal.	wall space below the	
43. History and Significance several busine		lt for Lexington, Missouri in	vestors and housed	
44. Description of Environm structure. To the		Commercial buildings are south, eas	et and north of this	
5 Sources of Information Kansas City Star, WP# 8141		actor September 8, 1920, pg.34	46. Prepared by PILAND 47. Organization	
BP# 12710			Landmarks Commission  48. Date 49. Revision Date(s)  1/6/84	



Columbia, Missouri 65201 STORIC INVENTORY JA-15008-1327 1. No 4. Present Name(s) 56-B Atlas Imported Parts 2 County 5 Other Name(s) Jackson entered 3 Location of Negatives MT #8-16 Landmarks Commission 1806 Oak Specific Location 16. Thernatic Category 28. No. of Stories 1808 Oak Jackson 29. Basement? Yes County 17. Date(s) or Period No I 1918 30. Foundation Material 7 City or Town Kansas City, If Rural, Township & Vicinity Missouri 18. Style or Design 31. Wall Construction B. Site Plan with North Arrow 19. Architect or Engineer masonry 32. Roof Type & Material flat; tar & gravel 20. Contractor or Builder 33. No. of Bays Front Side 21. Original Use, if apparent Present Name(s) 34. Wall Treatment 22. Present Use stucco 35. Plan Shape irregular commercial 0ak 36. Changes Public !! 23 Ownership Addition : PrivateXX (Explain Altered X in #42) Moved i 24. Owner's Name & Address, if known 37. Condition Interior 9. Coordinates UTM Lat. Exterior good Long 25. Open to YesXX 38. Preservation Yes . Public? No 11 Underway? NoXX 10 Site ! : Structure ! Building K Object 11 26. Local Contact Person or Organization 39. Endangered? Yes By What? Noxx Landmarks Commission 11. On National Yes ! Yes 12 Is It Eligible? No I Register? No IX 27. Other Surveys in Which Included 13. Part of Estab. Yes ! ! 14. District Yes Yes XX 40. Visible from Hist. Dist.? No X Potent'1? No : Public Road? No !! 41. Distance from and 15. Name of Established District Frontage on Road 42 Further Description of Important Features The building faces east onto Oak Street. The building has been considerably altered with the application of stucco panels to the facade. Theentrance, placed on the east facade, is recessed. 43. History and Significance The building permit indicates this structure was erected as a garage, although the City directories do not confirm this. 44. Description of Environment and Outbuildings A surface parking lot is north of this building. south, east and west are other commercial buildings. 45 Sources of Information 46. Prepared by WP #4138 Piland /Uguccioni BP #64376 47. Organization Landmarks Commission

48. Date

3/12/84

49. Revision Date(s)

State Historical Survey and Planning Office, 909 University Avenue, Suite 215,

ATLAS IMPORTED PARTS

Frontage on Road 25 feet on Oak

57-B 180	sent Name(s)  9 Oak Street Building  er Name(s)	JA-45008-1328	57-B
6 Specific Location 1809 Oak	16. Thematic Category 030 050  17. Date(s) or Period 1901 (add. 1926) 18. Style or Design	28. No. of Stories 2 29. Basement? Yes I No I	Jackson
7. City or Town II Aural, Township & Vicinity Kansas City, Missouri  8. Site Plan with North Arrow	19 Architect or Engineer  R L Falkenberg 6. 30 90  20 Contractor or Builder Fred Roux (1901)  21 Original Use, if apparent commercial 02 E AW  22 Present Use storage  23 Ownership Public 11	31. Wall Construction masonry LLD  32. Roof Type & Material F4 PE flat; tar & gravel 99  33. No. of Bays Front 2 Side  34. Wall Treatment brick: metal 30 SD  35. Plan Shaperectangular  36. Changes Addition x	1809 Oak
9. Coordinates UTM Lat. Long.	Private 21.  24. Owner's Name & Address, if known  25. Open to Yes II	(Explain Altered Noved in #42) Moved in #42)  37. Condition Interior Exterior — good ————————————————————————————————	AND DESCRIPTION OF THE PERSON
10. Site!: Structure!: Object!!  11. On National Yes!! 12 Is!t Yes!X	Public? No M  26. Local Contact Person or Organization Landmarks Commission	Underway? No x  39. Endangered? Yes! By What? No 1: x	
Register? No IX Eligible? No II  13 Part of Estab. Yes II 14. District Yes IX Potent'I? No I.  15 Name of Established District	27. Other Surveys in Which Included	40. Visible from Yes X Public Road? No 11	Total Control

42 Further Description of Important Features The main facade of this building faces west. Comparison with a c. 1940 photograph reveals that the display windows of the first floor have been replaced by an overhead garage door. Two rectangular windows with stone sills fenestrate the second floor. An addition in 1926 extended the building to the rear. The R. L. Falkenberg & Co. erected the addition.

43. History and Significance The history of this building is unknown. It appears to have originally been a commercial structure. A building permit issued in 1926 for an addition indicates it consisted of a store and 5 apartment units.

44. Description of Environment and Outbuildings A surface parking area is south of this building. the north, east and west are other commercial buildings.

45 Sources of Information

WP #18638 BP #84580 46. Prepared by Piland

47. Organization

Landmarks Commission 48. Date 49 Revision Date(s) 9/26/84



(
=
-
C
-
-
-
4
=
=
· CD
-
64
- 20

1. No.	4. Prese	ent Name(s)	5A-AS-008-1329
56-L		Seasonal Heating and Air Condition	oning; G. J. Flooring
County Jackson		r Name(s)	
Location of Negatives MT #8- Landmarks Commission			
Specific Location		16. Thematic Category	28. No. of Stories I
**************************************		950 990	29. Basement? Yes X
1814 Oak Street Bu	ulding	17. Date(s) or Period	partial No.
	-	1917	30. Foundation Material
City or Town II Rural, Town Kansas City, Missouri	snip & Vicinity	18. Style or Design	31. Wall Construction UA S+
Site Plan with North Arrow		19. Architect or Engineer	masonry; steel frame
	M	20. Contractor or Builder	32. Roof Type & Material
	14	Bert Elmer	33. No. of Bays
		21. Original Use, if apparent	Front 3 Side
15	1	garage 0⇒E 16D 22. Present Use	34. Wall Treatment brick
- 4	1	commercial	35. Plan Shaperectangular
90		23 Ownership Public   Private	36. Changes Addition :: (Explain Altered IX
		24. Owner's Name & Address,	in #42) Moved i
		if known	37. Condition Interior
Coordinates UTM			Exterior _good.
Long.		25. Open to Yes IX	38. Preservation Yes
Site!: Building XX	Structure I : 8	Public? No 11  26. Local Contact Person or Organization	Underway? NoXX  39. Endangered? Yes
On National Yes   12 Is I	VY-	Landmarks Commission	39. Endangered? Yes No.XX
	gible? No 1:	27. Other Surveys in Which Included	
Part of Estab. Yes 11 14 Di Hist. Dist.? No XX Po	strict Yes XX stent'l? No :		40. Visible from YesXX Public Road? No 11
Name of Established District			41. Distance from and
			Frontage on Road 50 feet on Oak
Further Description of Importan	t Features The	east facade has been altered by	the closing of two
rectangular storefrom	nt panes wit	h wood paneling. A garage bay is	
parapet wall is stepp	bed and term	inates in tile coping.	
History and Significance £ \$8,000.	This	was originally a garage and was	constructed at a cost
τ γο, σοσ.			
Description of Environment and		Surface parking lots are to the no	
st is a commercial buil	Lding. And	other surface parking lot is to th	le east.
Sources of Information			46. Prepared by
#12132			Piland / Uguccioni
estern Contractor, Apri	1 4, 1917, p	. 25.	47. Organization Landmarks Commission
			48. Date 49. Revision Date(s)
			40. Date 45. Hevision Date(s)



9/7/84



County

Present Name(s)

Landmarks Commission

49 Revision Date(s)

48. Date

9/21/81



State Historical Su sy and Planning Office, 909 University Avenue, Suite 215, columbia, Missouri 65201 HISTORIC INVENTORY JAM5-008-133 4. Present Name(s) 1. No. 76-M K & A Litho Process, Inc. 2 County 5. Other Name(s) not Jackson 3 Location of Negatives MT #8-14 entered Natkin & Company Landmarks Commission 6. Specific Location 16. Thematic Category 28. No. of Stories 2 ackson Courty 29. Basement? Yes I 1924 Oak 17. Date(s) or Period No I 1946 (add. 1954) 30. Foundation Material 7. City or Town . If Rural, Township & Vicinity Kansas City, Missouri 18. Style or Design 31. Wall Construction concrete block 8. Site Plan with North Arrow 19. Architect or Engineer 32. Roof Type & Material Kivett & Myers (1946) 20. Contractor or Builder flat; tar & gravel 33. No. of Bays Swenson Const. Co. (1946) Front Side 21. Original Use, if apparent 924 Present Name(s) commercial 34. Wall Treatment brick 22. Present Use commercial 35. Plan Shape rectangula 36. Changes 23 Ownership Public 11 Addition :X Private IX (Explain Altered | in #42) Moved i 24. Owner's Name & Address, if known 37. Condition Interior 9. Coordinates UTM Lat Exterior good Long 25. Open to Yes X 38. Preservation Yes i Public? No 1 Underway? No IX 10 Site!: Structure | Building XI Object | | 39. Endangered? 26. Local Contact Person or Organization Yes By What? No IX 11. On National Yes 12 Is It Yes Landmarks Commission Register? Eligible? No X No X 27. Other Surveys in Which Included 13 Part of Estab. Yes I 14. District Yes i 40. Visible from Yes !X Hist Dist ? NoxI Potent'l? Nox Public Road? No !! 41. Distance from and 15. Name of Established District Frontage on Road 60 feet on Oak 42. Further Description of Important Features The Oak Street Viaduct rises in front of this building. Natkin & causing it to appear as a single story from street level. The building faces east. The central entrance bay is angled and in addition to the door, contains a series of three glass windows. A metal canopy projects from this bay. In 1954 a 2 story addition was placed at the rear of the building. The Hiram Elliott Construction Company built the addition. Company This building was occupied by Natkin and Company from its time of 43. History and Significance construction until 1973. The firm, founded in Kansas City in 1909 by Benjamin Natkin, specialized in the installation of large boiler plants as well as heating, plumbing, and air conditioning. 44. Description of Environment and Outbuildings A surface parking lot is north of this building. To the south and east are surface parking lots. Commercial buildings are to the east. 45 Sources of Information WP #20871 46. Prepared by Piland BP #16309 47. Organization BP #38077A Landmarks Commission

48. Date 49. Revision Date(s)

1/27/83

Kansas City Star, Dec. 23, 1973.



HISTORIC INVENTORY JA-AS-008-1333 4. Present Name(s) 1 No 168-B 2727 Oak 2. County 168-B 5 Other Name(s) not Jackson 3 Location of Negatives MT #46-14 entered Landmarks Commission Bausch & Lomb Inc. 16. Thematic Category 6. Specific Location 28. No. of Stories 29. Basement? Yes ! 17. Date(s) or Period 2727 Oak No I 1958 30. Foundation Material 7. City or Town It Rural, Township & Vicinity Kansas City, Missouri 18. Style or Design 31. Wall Construction B. Site Plan with North Arrow 19. Architect or Engineer concrete block George Davidson 32. Roof Type & Material 20. Contractor or Builder flat; tar & gravel Bennett Const. Co. 33. No. of Bays Front Side 21. Original Use, if apparent 2727 commercial Wall Treatment 22. Present Use brick Oak vacant 35. Plan Shape rectangular 23 Ownership Public 11 36. Changes Addition : Private 1 1 Altered | (Explain in #42) Moved i 24. Owner's Name & Address, if known 37. Condition Interior 9. Coordinates UTM Exterior good Lal. Long 25. Open to Yes Preservation Yes Public? Underway? No x 10 Site ! : Structure | Building IX Object 11 39. Endangered? 26. Local Contact Person or Organization Yes k By What? No I Landmarks Commission Yes 11. On National Yesli 12 Is It Eligible? Register? No IX No IX 27. Other Surveys in Which Included poss. demolition Yes 13. Part of Estab. Yes ! ! District 40. Visible from Yes x Hist. Dist.? No 1x Potent'1? No X Public Road? No 41. Distance from and 15. Name of Established District 85 ft. Frontage on Road on Oak 42. Further Description of Important Features The building faces west onto Oak Street. The main entrance to the building is located at the south end of the west facade. A series of three windows placed equidistant along the west facade are enframed by horizontal stone bands above and below the windows. 43. History and Significance This building originally housed the Bausch & Lomb Optical Company. 44. Description of Environment and Outbuildings A surface parking lot is west of this building, north is a vacant lot. Other surface parking lots are to the south and east. 46. Prepared by 45 Sources of Information Piland / Uguccioni BP #18817 47. Organization WP #63797K Landmarks Commission 49. Revision Date(s) 48. Date

2/13/84

Jackson



C
=
ċ
_
â
Ξ
e
50
7

HISTORIC INVENTORY JX-15008-1330 1. No 4. Present Name(s) No. 190-U 190-U The Envelope Man Express Envelope; 2. County Jackson 5 Other Name(s) not entered 3 Location of Negatives MT #71-17 General Controls Co/American-LaFrance Corp. Landmarks Commission 6 Specific Location 16. Thematic Category 28. No. of Stories Jackson 2904-08 Oak 29. Basement? Yes I Count 17. Date(s) or Period No I 1955 30. Foundation Material Il Rural, Township & Vicinity 18. Style or Design 7. City or Town 31. Wall Construction Kansas City, Missouri 8. Site Plan with North Arrow 19. Architect or Engineer concrete block 32. Roof Type & Material Leon Maslan flat; tar & gravel 20. Contractor or Builder Bennett Construction Co. 33. No. of Bays Front Side 4 21. Original Use, if apparent 2904-08 Present Name(s. 34. Wall Treatment commercial 22. Present Use brick commercial 35. Plan Shape rectangular 36. Changes 23 Ownership Public 11 Addition : Private ly Altered I (Explain in #42) Moved i 24. Owner's Name & Address. il known 37. Condition Interior 9. Coordinates UTM Exterior good Lat Long 25. Open to Yes IX Preservation Yes Noix Public? Underway? Site ! : Structure | Building Object ! ! 39. Endangered? 26. Local Contact Person or Organization Yes I No Ix By What? Landmarks Commission 11. On National Yes 12 Is It Yes Eligible? Register? No x! No x 27. Other Surveys in Which Included Yes i 13 Part of Estab. Yes 11 District Yes IX 40. Visible from Hist. Dist.? No +! Potent'1? Nox Public Road? No 11 41. Distance from and 15. Name of Established District Frontage on Road 60 feet on Oak 42. Further Description of Important Features The building is sited on a grade, and faces east on Oak Street. The building's parts are defined by the juxtaposition of red and buff colored brick. The south end of the building veneered in contrasting red brick is slightly taller than the remainder of the building. The building extends northward on the lot and features red brick banding on the parapet wall. The entrance is placed slightly off center. 43. History and Significance The building was erected at a cost of \$32,000. It was originally leased to an auto parts firm (General Controls Co.) and a firm which dealt in fire fighting equipment (American-LaFrance Corporation). 44. Description of Environment and Outbuildings A surface parking lot is north of this building. To the west is Union Cemetery. The grade drops sharply to the east, where a service station is located. Another commercial building is to the south. 45 Sources of Information 46. Prepared by Kansas City Star, Nov. 6, 1955, p. 6D. Uguccioni WP #106597 47. Organization BP #18334 Landmarks Commission 48. Date 49. Revision Date(s) 2/3/82

State Historical Survey and Planning Office, 909 University Avenue, Suite 215.

Columbia, Missouri 65201



No. 190-T	INVENTORY  4. Present Name(s)  Myers Tire Supply	DAAS DUS 1335	190-T
Jackson Location of Negatives MT #71-16 Landmarks Commission	5 Other Name(s) Trafner Bearing Company	red	-13
Specific Location	16. Thematic Category	28. No of Stories 1	Ja
2910 Oak	17 Date(s) or Period .	29. Basement? Yes I No I.	Jackson
City or Town - If Rural, Township & Kansas City, Missouri	Vicinity 18. Style or Design  19. Architect or Engineer	31. Wall Construction concrete block	and the same of
N	Roger Frangkiser  20. Contractor or Builder  Century Const. Co.	flat; tar & gravel 33. No. of Bays	
- h	21 Original Use, if apparent commercial 22 Present Use	Front 7 Side  34. Wall Treatment brick	2910
l v l	commercial	35. Plan Shape rectangular	Oak
940 J	23 Ownership Public   Private \( \frac{1}{x} \)	36. Changes Addition : (Explain Altered I in #42) Moved i	*
Coordinates UTM	24. Owner's Name & Address, if known	37. Condition Interior Exterior good	
	25. Open to Yes III	38. Preservation Yes Underway? No X	
1. On National Yes   12 Is It	Yes: 26. Local Contact Person or Organization Landmarks Commission	39. Endangered? Yes I By What? No I <sub>X</sub>	
Register? No 1x Eligible?	No IX 27. Other Surveys in Which Included		

42. Further Description of Important Features The building faces east on Oak. A flat roof metal canopy extends across the east facade sheltering two pedestrian entrances and a garage bay at the north end. Brick laid in soldier course forms decorative banding above and below the windows and extends to the south facade.

Yes !

No x

14 District

Potent'1?

The original occupant of the building was the Trafner Bearing Company. 43. History and Significance

44. Description of Environment and Outbuildings The Union Cemetery is west of this building. Other commercial buildings are to the north and south. To the east, below grade, is vacant land.

45 Sources of Information

13 Part of Estab. Yes !!

No 1x

15. Name of Established District

Hist. Dist.?

WP #103819 BP #17907

46. Prepared by Uguccioni 47. Organization Landmarks Commission 48. Date 49. Revision Date(s)

3/5/82



HISTORIC	INVENTORY	A-A5008-1336	*
190-S 2 County	4. Present Name(s)  2916-18 Oak  Not entered  5 Other Name(s)		190-S
7 City or Town If Rural, Township & Kansas City, Missouri		30. Foundation Material  31. Wall Construction	on 2916-18 Oak
B. Site Plan with North Arrow	20. Contractor or Builder  Century Const. Co.  21. Original Use, if apparent		
ONK S	commercial 22 Present Use commercial		
	23 Ownership Public   Private		
9 Coordinates UTM Lat. Long.	25. Open to Yes I x		
The state of the s	bject   Public? No   No   No   No   No   No   No   No	Underway? No i x  39. Endangered? Yes i	

26. Local Contact Person or Organization

27. Other Surveys in Which Included

Landmarks Commission

42. Further Description of Important Features The main facade of this building faces east. Because of a grade change, the building has two elevations. Entrances are at the north and south ends of this facade. A flat canopy protects the entrance at the south end. A horizontal window band extends along the length of the facade. The window, openings are alternately filled with glass blocks or with a small fixed pane surrounded with glass blocks. String courses of red brick provide the sills and lintels.

Yes

No

Yes

No

12 Is It

Eligible?

District

Potent'1?

Yes I

No

No II

43. History and Significance The first tenant of this building was F. H. Wilson & Sons, manufacturer representatives.

44. Description of Environment and Outbuildings Union Cemeteary is west of this building. Commercial buildings are to the north, south, and east.

45 Sources of Information WP #103587

BP #18414

11. On National

Register?

Hist. Dist.?

Part of Estab. Yes II

15. Name of Established District

46. Prepared by Piland 47. Organization

By What?

40. Visible from

Public Road?

41. Distance from and Frontage on Road 100 feet on Oak

Landmarks Commission 48. Date 49. Revision Date(s) 12/14/84



42. Further Description of Important Features The subsequent additions to this building has created an canopy roofs. The building and its additions were built by the Century Construction Company.

43. History and Significance The earliest known tenant of this building (1955) was F.H. Wilson & Sons, manufacturing agents.

44. Description of Environment and Outbuildings An apartment building is north of this structure. To the west is Union Cemetery. Vacant land to the east drops in a steep grade. To the north is a commercial building.

## 45 Sources of Information

WP #102363

BP #17753

BP #41063A; 38584A

46. Prepared by Piland

47. Organization

Landmarks Commission 48. Date 49 Revision Date(s)

12/14/84





47. Organization

48. Date 7/15/83

Landmarks Commission

49. Revision Date(s)

BP #16738



8/30/83



9/6/83





_	
2	
5	
ē	
IIDI	
111	
mels,	
-	

12/19/84

1. No.	THE RESERVE OF THE PERSON NAMED IN		5A-A5008-1342	-
191-J		+	191	
2 County Jackson	294	1 (A) Oak Street House		L.
3 Location of Negatives M	Г#102-9	ior rame(s)		
Landmarks Commissio	on of KC	N.S. Thomatic Catagonia		
6. Specific Location		16. Thematic Category	28. No. of Stories 2  29. Basement? Yes I	
2941 (A) Oak		17. Date(s) or Period	29. Basement? Yes I	Jackson
		1916	30. Foundation Material	cso
7. City or Town If Rura Kansas City, M		18. Style or Design 49	31. Wall Construction	n
8. Site Plan with North Arr		19. Architect or Engineer	frame wu	
Oa	K		32. Roof Type & Material GB	
4.		20. Contractor or Builder	gable; comp.shingle 63	
ts		21. Original Use, if apparent	33. No. of Bays Front Side	29
30		residence OIA	34. Wall Treatment	41
	٨.	22. Present Use	clapboard 21	2
East	N	residence	35. Plan Shape rectangular	5
6	$\rightarrow$	23 Ownership Public □ Private ⋈  24. Owner's Name & Address,	36. Changes Addition 1: (Explain Altered III Moved III	2941 (A) Oak
		if known	37. Condition	
9. Coordinates L	JTM		Interior	
Lat. Long.			Exterior-good	
10. Site!:	Structure	25. Open to Yes II Public? No 🖂	38. Preservation Yes : Underway? No iX	
Building ki	Object ! !	26. Local Contact Person or Organization	39. Endangered? Yes III	
11. On National Yes     Register? No K!	12 Is It Yes 🗷 Eligible? No i !	Landmarks Commission of KC 27. Other Surveys in Which Included	By What? No Ix	
3. Part of Estab. Yes   1 Hist. Dist.? No k	14. District Yes K Potent'l? No :		40. Visible from Yes!X Public Road? No !!	
15. Name of Established Di	strict		41. Distance from and Frontage on Road	
		e main entrance is on the west faca ast and west roof slopes.	de of this residence.	of Chick Halliels,
43. History and Significance tage sits at the fr neer.	The house was cont of the lot.	constructed at the rear of a lot. A The first resident of this house wa	house of earlier vin- as Sam Jordon, an engi-	
14. Description of Environm to the east is a s	ent and Outbuildings R urface parking 1	desidences are west and south of the ot. The rear yards of adjacent pro	is house. Below grade, operties are to the north	
5 Sources of Information		4	46. Prepared by PILAND	
WP#2835			47. Organization	
			Landmarks Commission  48. Date 49. Revision Date(s)	



State Historical Sur y and Planning Office, 909 University Avenue, Suite 215,

)lumbia, Missouri 65201

2/28/82



olumbia, Missouri 65201

207-A 2 County	3001 Oak Street House ther Name(s)	5A-A5008-1344	207-A
6 Specific Location 3001 Oak	16. Thernatic Category  17. Date(s) or Period	28. No. of Stories 1½ 29. Basement? Yes X	Jackson
7 City or Town If Rural, Township & Vicinit Kansas City, Missouri	1897	30. Foundation Material stone 31. Wall Construction	son
8. Site Plan with North Arrow  L. 30 7 5 1	19. Architect or Engineer  20. Contractor or Builder	masonry LB  32. Roof Type & Material GB  gable; comp. shingle 3  33. No. of Bays  Front 3 Side	
ON CONTRACTOR OF THE CONTRACTO	21. Original Use, if apparent residence OIA Prod Fu  22. Present Use residence 23. Ownership Public II	34. Wall Treatment 30 99  35. Plan Shape rectangular  36. Changes Addition :	3001 Oak
9. Coordinates UTM	24. Owner's Name & Address, if known	(Explain Altered 1 Moved 1 Moved 1 Moved 1 Exterior good	
Long.  Site!: Structure!		38. Preservation Yes I Underway? No i	
Building   W Object    11. On National Yes   12 Is It Yes	Landmarks Commission	39. Endangered? Yes 11. By What? No 11. XX	
Register? No IX Eligible? No IX  13 Part of Estab. Yes II 14 District Yes II Hist. Dist.? No IX Potent'I? No IX	27. Other Surveys in which included	40. Visible from Yes XX Public Road? No ::	1
15. Name of Established District	This corner residence faces west. A	41. Distance from and Frontage on Road 26 feet on Oak	***

State Historical Sur 'y and Planning Office, 909 University Avenue, Suite 215,

across the front. The shed roof of the porch is supported by wood posts resting on stone bases. A large gabled dormer extends above the porch roof on the west roof slope.

43. History and Significance The original resident of this house is unknown.

44. Description of Environment and Outbuildings Other residences are south and west of this house. A storage/parking lot is below grade to the east. A residence is also to the north

45 Sources of Information

WP #4409

46. Prepared by Piland

47. Organization Landmarks Commission

48. Date 49. Revision Date(s)

8/20/81



1. No 4. Present Name(s) 206-Z 3002 Oak Street House 2. County 5 Other Name(s) Jackson MT #68-15 3 Location of Negatives Maria Wolf Residence Landmarks Commission 16. Thematic Category 6. Specific Location 28. No. of Stories 29. Basement? Yes XX 3002 Oak Date(s) or Period No 30. Foundation Material 1909 stone 40 7. City or Town II Rural, Township & Vicinity Kansas City, Missouri 18 Style or Design 18 31. Wall Construction 8. Site Plan with North Arrow 19. Architect or Engineer frame; masonry W other Walter Lovitt 20 32. Roof Type & Material 20. Contractor or Builder gable; comp. shingle 33. No. of Bays Wiedenmann and Deck Front Side 21. Original Use, if apparent Poch Present Namers 34. Wall Treatment 30 residence DIA brick; clapboard 22. Present Use 35. Plan Shape rectangular residence 23 Ownership Public 1 36. Changes Addition : Privatexx (Explain Altered I in #42) Moved i 24. Owner's Name & Address, if known 37. Condition Interior 9. Coordinates UTM Exterior excellent Lat Long 25. Open to YesX Yes I 38. Preservation Public? Underway? Noxx No i 10 Structure Site ! : Building X Object ! ! 39. Endangered? 26. Local Contact Person or Organization Yes By What? No XX Landmarks Commission 11. On National Yesli 12 Is It Yes X Eligible? Register? No 1 No IX 27. Other Surveys in Which Included 13. Part of Estab. District Yes X Yes II 40. Visible from Yes XX No X Hist. Dist.? Potent'1? No : Public Road? No I 41. Distance from and 15. Name of Established District Frontage on Road 25 feet on Oak 42. Further Description of Important Features A gable with returns is the dominant feature of the east facade, with the porch gable mirroring that of the house. Brick piers support the porch poof. The returns of the roof gable are bracketed. A double window fenestrates the sable wall area. An oriel window projects from the north facade. A second oriel window is on the sputh facade. A dormer is placed on the north and the south roof slope. 43. History and Significance This house was constructed for Maria Wolf, a widow. 44. Description of Environment and Outbuildings Other residences are to the north, south and east. A landscaped yard is across the alley to the west. 45 Sources of Information 46. Prepared by Piland /Uguccioni BP #24625 WP #40966 47. Organization Landmarks Commission Western Contractor August 18,1909,p.1 49. Revision Date(s) 48. Date 8/25/81

State Historical Survey and Planning Office, 909 University Avenue, Suite 215

Columbia, Missouri 65201



		VENTORY	y Avenue, Suite 215, Imbia, Missouri 65201 54-A5-008-1346	
1. No. 207-B	4. Pres	ent Name(s)  15 Oak Street House	DA-715-008-1594	207-
2. County		er Name(s)		10:1
Jackson 3 Location of Negatives	MT #26-1	sephine Hackl residence		
Landmarks Commission	on Jos		-	_
6. Specific Location		16. Thematic Category	28. No. of Stories 1½	J.
3005 Oak		17. Date(s) or Period	29. Basement? Yes X	ick
3003 Oak		1911	30. Foundation Material	Jackson
7. City or Town II Rural Kansas City, Misson	I, Township & Vicinity	18. Style or Design	stone 45	1
8. Site Plan with North Arro	ow	19. Architect or Engineer	masonry UD	
N L		20. Contractor or Builder	gable; comp. shingle/3	
1 2		21. Original Use, if apparent Puch	33. No. of Bays Front 2 Side 4	3005
3		residence DIA FU	34. Wall Treatment brick 30	-
0	,	22. Present Use	brick 30 35. Plan Shape rectangular	0ak
		residence 23 Ownership Public ! !	36. Changes Addition :	1
		Private   X	(Explain Altered I : Moved I	1
		24. Owner's Name & Address,. if known	37. Condition	1
9. Coordinates U	тм		Interior good	,
Long.		25. Open to Yes I i	38. Preservation Yes	1
10. Site!:	Structure I	Public? No X	Underway? No ix	1
Building IX	Object 11	26. Local Contact Person or Organization Landmarks Commission	39. Endangered? Yes II By What? No XX	
Register? No IX	Eligible? No / !	27. Other Surveys in Which Included	40. Visible from Yes XX	
Hist. Dist.? No IX	Potent'l? No !		Public Road? No 11	
15. Name of Established Dis	strict		41. Distance from and Frontage on Road	
			22 feet on Oak	╀
with brick piers so gable is steeply point the center of the have stone lugsills	upporting a gabl itched and a mod he gable wall su s.	west facade features a railed porce roof with return. The second striffied Palladian window motif is plantage. Windows of the north facade	orty acced	
of Adelaide Hackl,	widow of John Ha	ory of 1911 lists this as the resifirm. The 1912 city directory listckl. The building permit is issue ther residences are north, south, a percial building.	d to Mrs. A. Hackl.	
A. S.			Les Dominates	
45 Sources of Information BP #26763		2	46. Prepared by Piland /Uguccioni	
WP #45071			47. Organization	1
)			Landmarks Commission	
			48. Date   49 Revision Date(s)   8/5/81	



State Historical Surey and Planning Office, 909 University Avenue, Suite 215,

Columbia, Missouri 65201

6/19/82

Present Name(s)



-
-
=
11111
*
-
Ξ
à
=
=
e
0
5
7

2 County

1. No.	C INVENTORY  [4. Present Name(s)		1
207-C		The state of the s	
2 County	5 Other Name(s)		207-C
Jackson 3 Location of Negatives MT #46-1 Landmarks Commission			
6 Specific Location	16. Thematic Category	28. No. of Stories 2	1
3009 Oak	030	29. Basement? YesXX	ac
	17. Date(s) or Period 1899	30. Foundation Material	Jackson
City or Town If Aural, Township Kansas City, Missouri	& Vicinity 18 Style or Design	01	U.
Site Plan with North Arrow	19 Architect or Engineer	31. Wall Construction masonry UD	Steam
Site Flan with North Arrow	19 Architect of Engineer	32. Roof Type & Material HP	and and
N	20. Contractor or Builder	hip; comp. shingle 63	L
14 6	21. Original Use, if apparent Pnch	33. No. of Bays Front 2 Side	
	residence OIA Fu	34. Wall Treatment 30 64	3009
1	22 Present Use residence	brick; asbestos sidin	2
1 0	23 Ownership Public	35. Plan Shape Rectangular 36. Changes Addition	Oak
	Private 1x	(Explain Altered X' in #42) Moved	
	24. Owner's Name & Address, if known	37. Condition	
Coordinates UTM		Interior	THE REAL PROPERTY.
Lat. Long		Exteriorgood	
100 m	25. Open to Yes II	38. Preservation Yes Underway? No X	1
T 2 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1	Object   26. Local Contact Person or Organization	39. Endangered? Yes I	1
1. On National Yes   12 Is It  Register? No & Eligible'	Yes X Landmarks Commission	By What? No 1 X	
Register? No 1 Eligible'  3. Part of Estab. Yes 11 14. District	27. Other Surveys in Willer Included	40. Visible from Yes ! X	
Hist. Dist.? No V Potent's	? No.1.	Public Road? No 11	
5. Name of Established District		41. Distance from and Frontage on Road	
		27 feet on Oak	L
2. Further Description of Important Fea	itures		
A hip roofed porch extends	s across the facade, supported by wood pos dow, bayed projection is at the north end	of the west facade.	
slender columns. A 3-wind			
3. History and Significance The r	majority of houses on this block date from ouse to the immediate south.	the 1890's. This	
3. History and Significance The The Nouse is identical to the ho	Duildings Other residences are north, south,		
3. History and Significance The incluse is identical to the hold to the east, below grade is	Duildings Other residences are north, south,	and west of this house.	
3. History and Significance The Inhouse is identical to the hold to the east, below grade is Sources of Information	Duildings Other residences are north, south,	and west of this house.  46 Prepared by Piland	
3. History and Significance The Thouse is identical to the house is id	Duildings Other residences are north, south,	and west of this house.  46 Prepared by Piland 47. Organization	
3. History and Significance The Induse is identical to the hold to the east, below grade is Sources of Information	Duildings Other residences are north, south,	and west of this house.  46 Prepared by Piland	



8/30/81



State Historical Survey and Planning Office, 909 University Avenue, Suite 215,

olumbia, Missouri 65201

8/4/81



HISTORIC INVENTORY 5A-45-008-1 4. Present Name(s) I. No. 206-b 3014 Oak Street House 2 County 06-b 5 Other Name(s) Jackson Location of Negatives MT Landmarks Commission Location of Negatives #71-11 6. Specific Location 16. Thematic Category 28. No. of Stories 030 ackson 29. Basement? Yes XX 3014 Oak 17. Date(s) or Period No I 30. Foundation Material City or Town Kansas City, If Rural, Township & Vicinity Missouri stone 18. Style or Design 18 31. Wall Construction 19. Architect or Engineer ploties B. Site Plan with North Arrow frame; masonry 20 32. Roof Type & Material 6M 20. Contractor or Builder gambrel; comp. shingl 33. No. of Bays pnun Side Front 4 DR 21. Original Use, if apparent FU residence 34. Wall Treatment 30 brick; asbestos siding 22. Present Use 35. Plan Shape residence rectangular 23 Ownership 36. Changes Public 11 Addition : Private ly (Explain Altered | in #42) Moved I 24. Owner's Name & Address, if known 37. Condition Interior 9. Coordinates UTM Good Exterior Lat. Long 25. Open to 38. Preservation Yes I Yes No IX Underway? 10 No X Site ! : Structure | Building XX Object | 1 26. Local Contact Person or Organization 39. Endangered? Yes By What? NoIX Landmarks Commission Yes X 11. On National Yes 12 Is It Eligible? No I Register? No XX 27. Other Surveys in Which Included Yes X District 13. Part of Estab. Yes II 40. Visible from Yes! X No XX Hist. Dist.? Potent'1? No: Public Road? No Distance from and 15. Name of Established District Frontage on Road 15 feet on Oak 42. Further Description of Important Features A porch extends across the front. The hip roof of the porch is supported by paired wood posts. Both the north and south facades contain 2 dormers, each fenestrated by a single window. The dormer walls and the gable area are covered with asbestos siding. Photo 43. History and Significance The majority of houses on this block date from the 1890's. 44. Description of Environment and Outbuildings Other residences are north, south, east and west of this house. 46. Prepared by 45 Sources of Information WP #13711 Piland 47. Organization Landmarks Commission 48. Date 49. Revision Date(s)

State Historical Survey and Planning Office, 909 University Avenue, Suite 215,

olumbia, Missouri 65201

12/10/82



State Historical Sur / and Planning Office, 909 Univ

ity Avenue, Suite 215,

48. Date

6/1/84

49. Revision Date(s)



49. Revision Date(s)

48. Date 2/29/84

State Historical Sur my and Planning Office, 909 University Avenue, Suite 215,



1. No. 207-G	4. Present Name(s) 3017 Oak Street House	+
2 County		
Jackson MT #81 20	5 Other Name(s)	
3 Location of Negatives MT #81-20 Landmarks Commission	William D. Coe residence	
6. Specific Location	16. Thematic Category	28. No. of Stories 21/2
	030	29. Basement? YesXX
3017 Oak	17. Date(s) or Period.	No I.
7. City or Town - If Bural, Township	1896 & Vicinity 218: Style or Design	stone 40
7. City or Town II Rural, Township Kansas City, Missouri	18	31. Wall Construction
8. Site Plan with North Arrow	19. Architect or Engineer	frame wu
٨.	20. Contractor or Builder	32. Roof Type & Material 6m gambrel; comp. shingle
N		The state of the s
, v) -	21. Original Use, if apparent pnch	33. No. of Bays Front 2 Side SR
1	residence OIA RISL  22. Present Use	34. Wall Treatment 64 asbestos siding
3	residence	35. Plan Shape rectangular
1 0	23 Ownership Public □ Private Ŋ	36. Changes Addition 1: (Explain Altered 1:
	24. Owner's Name & Address, if known	in #42) Moved i
		37. Condition Interior
9 Coordinates UTM Lat.		Exterior good
Long.	25. Open to Yes I i	38. Preservation Yes
	Object   Public? No to	Underway? No 1 <sub>X</sub>
11. On National Yes   12 Is It	Yes XX Landmarks Commission	39. Endangered? Yes I No IX
Register? No XX Eligible		
Register? No XX Eligible  13. Part of Estab. Yes 11 14. District	? No 11 27. Other Surveys in Which Included	40. Visible from Yes !X Public Road? No i i
Register? No XX Eligible  13. Part of Estab. Yes 11 14. District	? No 11 27. Other Surveys in Which Included Yes XX	Public Road? No 11
Register? No XX Eligible  13. Part of Estab. Yes   1	? No 11 27. Other Surveys in Which Included Yes XX	Public Road? No 11  41. Distance from and Frontage on Road
Register? No XX Eligible  13. Part of Estab Yes   1	? No!! 27. Other Surveys in Which Included  Yes XX !? No!!  atures The main facade faces west. The sout	Public Road? No ii  41. Distance from and Frontage on Road approx. 25 ft. on Oak h Portion of this facade
Register? No XX Eligible  13. Part of Estab. Yes     14. District Hist. Dist.? No XX Potent  15. Name of Established District  42. Further Description of Important Fea advances, providing a small brick bases, is an enclosed windows fenestrate all three of the north portion of the area. A shallow dormer is	27. Other Surveys in Which Included  Yes XX 12. No:  atures The main facade faces west. The sout open 1st floor porch. Above, supported b area with a gamble roof repeating the hou e sides of the projection. Double windows west facade. A single semicircular windoplaced on the south roof slope.	Public Road? No 11  41. Distance from and Frontage on Road approx. 25 ft. on Oak hortion of this facade wood piers resting on se roof. Rows of fenestrate both floors we fenestrate the gable
Register? No XX Eligible  13. Part of Estab. Yes   1	27. Other Surveys in Which Included  Yes XX 12. No:  atures The main facade faces west. The sout open 1st floor porch. Above, supported be area with a gamble roof repeating the house sides of the projection. Double windows west facade. A single semicircular window placed on the south roof slope.  irst resident of this house was William D.	Public Road?  A1. Distance from and Frontage on Road approx. 25 ft. on Oak h portion of this facade wood piers resting on se roof. Rows of fenestrate both floors fenestrates the gable coe, for whom no
Register? No XX Eligible  13. Part of Estab. Yes   1	27. Other Surveys in Which Included  Yes XX 12. No:  atures The main facade faces west. The sout open 1st floor porch. Above, supported be area with a gamble roof repeating the house sides of the projection. Double windows west facade. A single semicircular window placed on the south roof slope.  irst resident of this house was William D. city directory.	Public Road?  Al. Distance from and Frontage on Road approx. 25 ft. on Oak hortion of this facade wood piers resting on se roof. Rows of fenestrate both floors fenestrates the gable  Coe, for whom no  and west of this
Register? No XX Eligible  13. Part of Estab. Yes   1	27. Other Surveys in Which Included  Yes XX 12. No:  atures The main facade faces west. The sout open 1st floor porch. Above, supported be area with a gamble roof repeating the house sides of the projection. Double windows west facade. A single semicircular window placed on the south roof slope.  irst resident of this house was William D. city directory.	Public Road? No 11  41. Distance from and Frontage on Road approx. 25 ft. on Oak hortion of this facade y wood piers resting on se roof. Rows of fenestrate both floors fenestrates the gable  Coe, for whom no  46. Prepared by
Register? No XX Eligible  13. Part of Estab. Yes   1	27. Other Surveys in Which Included  Yes XX 12. No:  atures The main facade faces west. The sout open 1st floor porch. Above, supported be area with a gamble roof repeating the house sides of the projection. Double windows west facade. A single semicircular window placed on the south roof slope.  irst resident of this house was William D. city directory.	Public Road?  Al. Distance from and Frontage on Road approx. 25 ft. on Oak hortion of this facade wood piers resting on se roof. Rows of fenestrate both floors fenestrates the gable  Coe, for whom no  and west of this
Register? No XX Eligible  13. Part of Estab. Yes   1	27. Other Surveys in Which Included  Yes XX 12. No:  atures The main facade faces west. The sout open 1st floor porch. Above, supported be area with a gamble roof repeating the house sides of the projection. Double windows west facade. A single semicircular window placed on the south roof slope.  irst resident of this house was William D. city directory.	Public Road? No 11  41. Distance from and Frontage on Road approx. 25 ft. on Oak hortion of this facade y wood piers resting on se roof. Rows of fenestrate both floors we fenestrate the gable coe, for whom no  Coe, for whom no  46. Prepared by Piland



Present Namers

47. Organization

48. Date

5/5/81

Landmarks Commission

49. Revision Date(s)



Piland / Uguccioni

Landmarks Commission

49. Revision Date(s)

47. Organization

48. Date 2/16/82

No. 206-d

Lat.

10

Long

WP #12035



1. No.	A Pro	NVENTORY Columbia, Missouri 65201  A-AS-006-135	
207-I		27 Oak Street House	*
2. County		Sheet House	
Jackson		er Name(s)	
3 Location of Negatives MT Landmarks Commission	#101-1		
Specific Location		16. Thematic Category	28. No. of Stories
3027 Oak		and the second second	
		17. Date(s) or Period	29. Basement? Yes IX
		c. 1890	30. Foundation Material
Kansas City, Missour:	Township & Vicinity	18. Style or Design	stone 46
Site Plan with North Arrow	1	49	31. Wall Construction frame WW
. Site Plan with North Arrow		19 Architect or Engineer	
N .		20. Contractor or Builder puch	32. Roof Type & Material P GB gabled hip; comp. shing
N		fu	33. No. of Bays 63
1		21. Original Use, if apparent	Front 3 Side
7	7	residence DIA	34. Wall Treatment 64
3		22. Present Use residence	asbestos siding
		23 Ownership Public 11	35. Plan Shape rectangular  36. Changes Addition ::
		Private  X	36. Changes Addition : (Explain Altered )
		24. Owner's Name & Address,	in #42) Moved
		if known	37. Condition
Coordinates UTM			Interior
Lat. Long.		25. Open to Yes I i	Exterior good
Site!:	Structure	25. Open to Yes II Public? No lx	38. Preservation Yes Underway? No x
Building XX	Object	26. Local Contact Person or Organization	39. Endangered? Yes I
	Is It Yes XX	Landmarks Commission	By What? No 1X
Register? No XX	Eligible? No 1 !	27. Other Surveys in Which Included	
	4. District Yes XX		40. Visible from Yes !X
			Public Road? No 11
Hist. Dist.? No XX	Potent'l? No :		7 CHO C 197 P. C.
Hist. Dist.? No XX			41. Distance from and Frontage on Road
Hist. Dist.? No XX  Name of Established District	ct	s house faces west. A shed roof a	41. Distance from and Frontage on Road 21 feet on Oak
Hist. Dist.? No XX  Name of Established District  Further Description of Impo	ortant Features Thi	s house faces west. A shed roof as support the porch roof. A gabled	41. Distance from and Frontage on Road 21 feet on Oak cross the facade creates
Hist. Dist.? No XX  Name of Established District  Further Description of Import n open porch. Turned he west roof slope.	ortant Features Thi d wood columns		41. Distance from and Frontage on Road 21 feet on Oak cross the facade creates projection is placed on
History and Significance O	ortant Features Thid wood columns One of several	support the porch roof. A gabled	41. Distance from and Frontage on Road 21 feet on Oak cross the facade creates projection is placed on n the 1890's.
Name of Established District  Further Description of Import open porch. Turner he west roof slope.  History and Significance Of Description of Environment	ortant Features Thid wood columns One of several	houses of this block constructed i	41. Distance from and Frontage on Road 21 feet on Oak cross the facade creates projection is placed on n the 1890's.
Name of Established District  Further Description of Import open porch. Turner he west roof slope.  History and Significance Of the Description of Environment elow grade, is a sur	ortant Features Thid wood columns One of several	houses of this block constructed i	41. Distance from and Frontage on Road 21 feet on Oak cross the facade creates projection is placed on n the 1890's.  his house. To the east, orth.
Name of Established District  Further Description of Import open porch. Turner the west roof slope.  History and Significance Of Description of Environment	ortant Features Thid wood columns One of several	houses of this block constructed i	41. Distance from and Frontage on Road 21 feet on Oak cross the facade creates projection is placed on n the 1890's.
Name of Established District  Further Description of Import open porch. Turner the west roof slope.  History and Significance Of Description of Environment elow grade, is a sur	ortant Features Thid wood columns One of several	houses of this block constructed i	41. Distance from and Frontage on Road 21 feet on Oak cross the facade creates projection is placed on  n the 1890's.  his house. To the east, orth.  46. Prepared by Piland 47. Organization
Name of Established District  Further Description of Import open porch. Turner the west roof slope.  History and Significance Of Description of Environment elow grade, is a sur	ortant Features Thid wood columns One of several	houses of this block constructed i	41. Distance from and Frontage on Road 21 feet on Oak cross the facade creates projection is placed on n the 1890's.  The transfer of the east, orth.  46. Prepared by Piland



Landmarks Commission

49 Revision Date(s)

48. Date

5/3/82



45 Sources of Information WP #21348

46. Prepared by
PILAND

47. Organization
Landmarks Commission

48. Date 49 Revision Date(s)
12/17/84





48. Date

2/28/84

49 Revision Date(s)

10

BP #83138

Western Contractor, April 18, 1917, p. 19.

Kansas City Star, April 28, 1966. Kansas City Star, December 16, 1940 ...... vicy viat, nov. 20, 1700, p. 41.







Yes XX

No I

Columbia, Missouri 65201

5A-AS-008-1362

030 050 2440 West Pennway 17. Date(s) or Period 1930 (add. 1956) 7 City or Town - If Rural, Township & Vicinity 18 Style or Design Kansas City, Missouri other B. Site Plan with North Arrow 19. Architect or Engineer Archer & Gloyd (1930) 20. Contractor or Builder Original Use, if apparent warehouse/offices 00 H OSA 22. Present Use warehouse/offices 23 Ownership Public 11 Private IX Pennway 24. Owner's Name & Address, if known Interior 9. Coordinates UTM Exterior good Lat. Long 25. Open to Yes I Preservation Yes Public? No Ix Underway? Noxx Site ! : Structure | Building XI Object 11 39. Endangered? 26. Local Contact Person or Organization Yes I By What? Yes X Landmarks Commission No xx 11. On National Yes 12 Is It Register? Eligible? No I No K 27. Other Surveys in Which Included

State Historical Sur , and Planning Office, 909 Univ ; ity Avenue, Suite 215,

The Carter-Waters Corporation

16. Thematic Category

HISTORIC INVENTORY

Yes X

No

14 District

Potent'1?

4. Present Name(s)

5 Other Name(s)

42 Further Description of Important Features The building follows a steep grade along West Pennway. Garage bays, which have been filled in with brick and cinder blocks as a result of a later alteration articulate the ground story. Patterned brickwork comprises the surrounds of the garage bays. The second story is fenestrated with narrow rectangular windows which feature vertically laid brick for the lintels. The building terminates in a parapet that consists of bricks laid in soldier course. In 1956 a single story reinforced concrete structure was extended approximately 360 feet south from the building. The lower level is used for storage, while the roof is used for parking. The building contains 24,000 square feet.

43 History and Significance The building was constructed for, and is still occupied by the Carter-Waters Corporation, a firm involved with building materials. The building was constructed to support an additional six stories. Architects of the 1956 addition were Bales & Schechter. A concrete block addition of unknown date is at the north end of the building.

44. Description of Environment and Outbuildings A commercial building and surface parking lot are east of this building. To the south is another commercial building. Commercial buildings and storage lots are to the west.

45 Sources of Information WP #90100

13. Part of Estab. Yes !!

No tel

15. Name of Established District

Hist. Dist ?

No 129½-D

2 County

Jack son

6. Specific Location

3 Location of Negatives MT #55-6 Landmarks Commission

BP #15553

BP #30408A

Midwest Contractor, Oct. 9, 1929, p. 30.

BP #18439

Kansas City Star, Nov. 26, 1950, p. 4F.

46. Prepared by Uguccioni

47. Organization

Visible from

Public Road?

41. Distance from and

Frontage on Road 100 feet on West Pennwa

Landmarks Commission 48. Date 49. Revision Date(s)

11/5/81



1. No. 130-D 2. County Jackson	4. Present Name(s) 2461 West Pennway; 5. Other Name(s)	U.S. Mail Bag Depository	130-D
3 Location of Negatives MT#10 -18 Landmarks Commission of KC	G. W. Van Keppel Con	npany entered	-D
6 Specific Location 2461 West Pennway	16. Thematic Category 17. Date(s) or Period	28. No. of Stories 1 29. Basement? Yes	Jac
7 City or Town If Rural, Township Kansas City, Missouri	1950 Vicinity 18. Style or Design	30. Foundation Material  concrete  31. Wall Construction	Jackson
3. Site Plan with North Arrow  3. W. 25th St	19. Architect or Engine Sigmund Sieber 20. Contractor or Build Universal Con: 21. Original Use, if approximate the commercial 22. Present Use government 23. Ownership	32. Roof Type & Material  flat; tar and gravel  33. No. of Bays Front Side  34. Wall Treatment brick  35. Plan Shape rectangul  Public! Private lx  36. Changes Addition (Explain Altered	est
9 Coordinates UTM Lat. Long.	24. Owner's Name & A if known	37. Condition Interior Exterior good	Pennway
	cture   Public? bject   26. Local Contact Pers	No ixi Underway? No	X
11. On National Yes   12 Is It Register? No ½! Eligible?	Yes: Landmarks Com No x 27. Other Surveys in W	mission of KC By What? No hich Included	Ιχ
3 Part of Estab. Yes   14. District Hist. Dist.? No x   Potent'l	No X	40. Visible from Yes Public Road? No	
15. Name of Established District		41. Distance from and Frontage on Road	£

- 12. Further Description of Important Features The main facade of this corner building faces west. An entrance door and garage entrance are placed near the center. A long window band extends across the facade.
- 43. History and Significance This building was constructed to house the G. W. Van Keppel Company, dealers in contractors' supplies. The building contains 12,000 square feet.
- 44 Description of Environment and Outbuildings Surface parking lots are north and east of this building. To the south is a commercial building. A storage/parking structure is to the west.
- 45 Sources of Information

WP #75415 BP #17390

Kansas City Star, Nov. 26, 1950, p. 4F.

46. Prepared by PILAND

47. Organization

Landmarks Commission

125 feet on W. Pennway

48. Date 49. Revision Date(s)

9/30/83



State Historical Survey and Planning Office, 909 University Avenue, Suite 215, Columbia, Missouri 65201 HISTORIC INVENTORY A-45-008-131 4. Present Name(s) inload A B Dick Company 138-E 5 Other Name(s) 3 Location of Negatives MT #55-5 E R Squibb & Sons Landmarks Commission 6 Specific Location 16. Thematic Category 28. No. of Stories ac 29. Basement? Yes kson 2500 West Pennway 17 Date(s) or Period No I 1953 30. Foundation Material stone 7 City or Town If Rural, Township & Vicinity 18. Style or Design 31. Wall Construction Kansas City, Missouri 8. Site Plan with North Arrow 19. Architect or Engineer concrete block WEST 25 th ST 32. Roof Type & Material Charles E. Keyser flat; composition 20. Contractor or Builder 33. No. of Bays Hoffman Construction Co. Front Side 21. Original Use, if apparent Present Name 2500 34. Wall Treatment commercial 22 Present Use brick West 35. Plan Shaperectangular commercial 23 Ownership Public II 36. Changes Addition Private I (Explain Altered I Pennw in #42) Moved i 24. Owner's Name & Address, il known 37. Condition Interior 9. Coordinates UTM Exterior pood 25. Open to Yes I 38. Preservation Yes Public? No Ix Underway? Noix Site Structure Building ki Object | 26. Local Contact Person or Organization 39. Endangered? Yes ! No Ix By What? Landmarks Commission Yes 11 On National Yes 12 Is It Register? Eligible? No x No M 27. Other Surveys in Which Included Yes ! 13 Part of Estab Yes !! 14 District Visible from Public Road? Hist. Dist.? No X Potent'1? No x No II 15. Name of Established District Distance from and Frontage on Road 145 feet on West Pennway 42. Further Description of Important Features The building is sited at the southwest corner of West 25th Street and West Pennway, with the main facade facing east onto West Pennway. Buff and red brick are used to face the building. Red brick extends around the perimeter of the parapet R Squibb wall, and is used to flank the doorway. The fenestration of multipaned rectangular windows is distinguished by the addition of brick sills. 20 The building, constructed as an office and warehouse was originally

43. listory and Significance occupied by the E R Squibb and Sons Company, manufacturing chemists. The building contains 20,000 square feet.

stion of Environment and Outbuildings A commercial building is east of this structure. To the west is a surface parking lot and a commercial building. Another commercial building is to the south. To the north is a storage lot and parking/storage structure.

Information 45, WP #73729 BP #17941 Kansas City Star, July 19, 1953, p. 8D

1. No

138-E

County

Jackson

Lat

Long

46. Prepared by Uguccioni 47. Organization Landmarks Commission 48. Date 5/6/82 49 Revision Date(s)



State Historical Survey and Planning Utfice, 909 University Avenue, Suite 215

Columbia, Missouri 65201

48. Date

8/26/83

49 Revision Date(s)





JRE COMPANY

CUSTOMER PARKING

.....

NATIONAL STORE FIXTURE COMPANY

_
o vinci
ridine(S,

1. No. 139-B	4. Pres	sent Name(s)	
County Jackson	Th	The Company Store	
		ner Name(s)	
Landmarks Commissi	on of KC		
Specific Location		16. Thematic Category	28. No. of Stories 1
2525 20 Hogt Bon	P. i.d.	030 050	29. Basement? Yes 🛚 X
2525-29 West Pen	nway building	17. Date(s) or Period	No 1.
7. City or Town If Rur	al Township & Vicinity	18 Style or Design	30. Foundation Material
Kansas City, 1		60 69	31. Wall Construction
Site Plan with North Ar		19. Architect or Engineer Other	masonry &A
11 -		20. Contractor or Builder	32. Roof Type & Material FR flat; tar and gravel 99
1 3		Morley Brothers	33. No. of Bays
3,		21. Original Use, if apparent	Front Side
1, 25		commercial OSE	34. Wall Treatment
19		22. Present Use commercial	brick 30
		23 Ownership Public II	35. Plan Shape rectangular 36. Changes Addition :
3		Private XI	(Explain Altered I
		24. Owner's Name & Address, if known	in #42) Moved i
Constitution	UTM	. I KNOWN	37. Condition Interior
Coordinates Lat.	шм		Exterior good
Long		25. Open to Yes I x	38. Preservation Yes
). Site!: Building lx	Structure I : Object I I	Public? No 11	Underway? No ix
	12 Is It Yes x	26. Local Contact Person or Organization	39. Endangered? Yes i No IX
1. On National Yes     Register? No   X	Eligible? No 11	Landmarks Commission of KC 27. Other Surveys in Which Included	
Part of Estab. Yes 11 Hist. Dist.? No IX	14. District Yes X: Potent'l? No :		40. Visible from Yes 🗓
5. Name of Established D	1,010111		41. Distance from and
J. Hame of Established D	ionici		Frontage on Road
		ne main facade of this building fac	98 ft. on West Pennway
is located beneat	h the triangular	two points by triangular projections projection at the south end of the re filled with glass blocks.	
3. History and Significanc		ginal tenants of this building was	an auto accessory firm,
Gilfillan Brothers  4. Description of Environm	, Inc.	ginal tenants of this building was a surface parking lots are north and ommercial buildings.	
Gilfillan Brothers  I. Description of Environm	, Inc.	Surface parking lots are north and	
Gilfillan Brothers  4. Description of Environment  To the south and	, Inc.	Surface parking lots are north and	east of this building.
Gilfillan Brothers  4. Description of Environment  To the south and	, Inc.	Surface parking lots are north and	east of this building.  46. Prepared by PILAND
4. Description of Environment To the south and the Sources of Information WP #69167 BP #13904	, Inc.	Surface parking lots are north and	east of this building.  46. Prepared by PILAND  47. Organization
Gilfillan Brothers  4. Description of Environment To the south and the Sources of Information WP #69167	, Inc.	Surface parking lots are north and	east of this building.  46. Prepared by PILAND



Landmarks Commission

49. Revision Date(s)

48. Date

4/12/84

BP #14361



43. History and Significance The building at the north end of this complex was constructed in 1912 as a warehouse for the Kansas City Brewing Company. A house to the south was incorporated into the complex at an unknown date. By the 1930's both structures were being utilized by a milling company. The General Mills Equipment Company expanded the complex further south in 1954 and 1959.

44 Description of Environment and Outbuildings Vacant land is north of this complex. Elevated to the west is a freeway. A residence is to the south. To the east is a commercial building and a surface parking lot.

45 Sources of Information WP#61414 BP#10542; 13581A BP#40175A; 59168 46. Prepared by
PILAND

47. Organization
Landmarks Commission

48. Date 49. Revision Date(s)
1/10/85





28. No. of Stories 11/2	LN
29. Basement? Yes I No I	Jackson
30. Foundation Material	son
31. Wall Construction frame	
32. Roof Type & Material gable: comp. shingle	
33. No. of Bays Front 2 Side	4 0
34. Wall Treatment brick; wood shingle	Present 2029
35. Plan Shape rectangular	
36. Changes Addition : (Explain Altered XX in #42) Moved :	Name(s) Pennsylvania
37. Condition Interior	lvani
Exterior good	а
28 Procesuation Vec	4

20 ft. on Pennsylvania

Columbia, Missouri 65201

TA-15008-1370

State Historical Survey and Planning Office, 909 University Avenue, Suite 215

HISTORIC INVEN

4. Present Name(s)

1. No.

The main facade faces west, with the entrance at the 42. Further Description of Important Features south end. A band of three rectangular windows fenestrates the first story. The lower wall surface is veneered with brick, while the remainder of the facade wall surface is covered with wood shingles. A single window fenestrates the attic story. A front porch was enclosed in a 1973 alteration.

43. History and Significance One of a very few remaining residences in this section of the midtown district.

44. Description of Environment and Outbuildings A surface parking lot is east of this building. To the south is another residence. A commercial building is to the north. Elevated to the west is Southwest Trafficway.

45 Sources of Information WP #7947 BP # 75975A

46. Prepared by Piland

47. Organization Landmarks Commission

48. Date 49. Revision Date(s) 2/27/84



5
Vinc.
italine(S.

84-C	Present Name(s)	
County Toolsoon	2031 Pennsylvania Street House Other Name(s)	
Location of Negatives MT#109-2 Landmarks Commission of KC	Other Name(s)	
Specific Location	16. Thematic Category	28. No. of Stories 2
	030	29. Basement? Yes X
2031 Pennsylvania	17. Date(s) or Period 1897	30. Foundation Material
City or Town - If Rural, Township & Vici	nity 18. Style or Design	01
Kansas City, Missouri	19. Architect or Engineer	11. Wall Construction frame WW
		32. Roof Type & Material GB
	20. Contractor or Builder	gable; comp. shingle 63
	21. Original Use, if apparent Pnoh	33. No. of Bays DR Side
	residence OIA Fu	34. Wall Treatment
	22. Present Use	clapboard 2/
	residence 23 Ownership Public !!	35. Plan Shape irregular  36. Changes Addition ::
	Private 1xl	(Explain Altered in M42) Moved
	24. Owner's Name & Address, if known	37. Condition
Coordinates UTM	_	Interior
Lal. Long		Exterior good
Site!: Structure	25. Open to Yes 11 Public? No 🔀	38. Preservation Yes Underway? No IX
Building 1 x Object		39. Endangered? Yes I
	Landmarks Commission of KC 27. Other Surveys in Which Included	By What? No IX
3 Part of Estab. Yes   1	S   X	40. Visible from Yes ! X Public Road? No ! :
Marie Diet 2 No. let 1 Dotont 12 No.		Public Road? No 11 41. Distance from and
Hist. Dist.? No 1 Potent'l? No		mai. Distance from and
		Frontage on Road 21 ft on Pennsylvania
5. Name of Established District  2. Further Description of Important Features the shed roof of a porch that ex	The main facade of this house faces we extends across the facade. A gablet at	Frontage on Road 21 ft on Pennsylvania rest. Wood columns support
2. Further Description of Important Features the shed roof of a porch that ex	xtends across the facade. A gablet at	Frontage on Road 21 ft on Pennsylvania rest. Wood columns support
2. Further Description of Important Features the shed roof of a porch that exporch roof marks the entrance based.  3. History and Significance One of the finance of the state	tends across the facade. A gablet at ay.	Frontage on Road 21 ft on Pennsylvania rest. Wood columns support the north end of the
2. Further Description of Important Features the shed roof of a porch that exporch roof marks the entrance based.  3. History and Significance One of the finance of the state	tends across the facade. A gablet at ay.	Frontage on Road 21 ft on Pennsylvania rest. Wood columns support the north end of the
2. Further Description of Important Features the shed roof of a porch that exporch roof marks the entrance based.  3. History and Significance One of the fonsists primarily of commercial	few residences remaining in this area buildings.	Frontage on Road 21 ft on Pennsylvania rest. Wood columns support the north end of the  of the midtown that now
Name of Established District  P. Further Description of Important Features the shed roof of a porch that exporch roof marks the entrance based on the state of th	few residences remaining in this area buildings.	est. Wood columns support the north end of the midtown that now this house. To the north
Name of Established District  P. Further Description of Important Features the shed roof of a porch that exporch roof marks the entrance become and Significance One of the fonsists primarily of commercial is another residence. A surface	few residences remaining in this area buildings.	est. Wood columns support the north end of the midtown that now this house. To the north
Name of Established District  2. Further Description of Important Features the shed roof of a porch that exporch roof marks the entrance based on the state of th	few residences remaining in this area buildings.	of the midtown that now  this house. To the north est, above grade, is an
2. Further Description of Important Features the shed roof of a porch that exporch roof marks the entrance because of the shed roof of a porch that exporch roof marks the entrance because of the shed roof of a porch that exports the entrance because of the shed roof of a porch that exports the entrance because of the shed roof of a porch that exports the entrance because of the shed roof of a porch that exports the entrance because of the shed roof of a porch that exports the entrance because of the shed roof of the	few residences remaining in this area buildings.	of the midtown that now  this house. To the north est, above grade, is an  46. Prepared by PILAND
5. Name of Established District  2. Further Description of Important Features the shed roof of a porch that exporch roof marks the entrance based.  3. History and Significance One of the footsists primarily of commercial	few residences remaining in this area buildings.	of the midtown that now  this house. To the north est, above grade, is an



A-AS-008-1373


4/6/84

HISTORIC INVENTORY

1. No.

118-C

4. Present Name(s)



Kansas City Star, Nov. 19, 1968.



44. Description of Environment and Outbuildings Below grade, to the west, is Crown Center Square. Across traffic islands and above grade to the east is the UMKC Dental School and Children's Mercy Hospital. To the south is a commercial building. To the north is the Hyatt Regency Hotel.

45 Sources of Information

WP #33934

WP #33181

Architectural Record, Oct. 1973, pp. 118-23

Kansas City Star, June 30, 1968.

Kansas City Star, Jan. 11, 1970

46. Prepared by Piland

47. Organization

Landmarks Commission

48. Date 49. Revision Date(s)

3/25/83



43. History and Significance Kansas City's Union Station is significant as: 1) a monumentally proportioned Beaux-Arts Classic style railroad terminal building; 2) the most prominent architectural contribution to the City Beautiful Movement in Kansas City; and 3) the facility serving the transportation and commercial needs of a growing major metropolitan area for 30-40 years from the time of its opening until the 1940s and 1950s.

44. Description of Environment and Outbuildings The area around the Union Station is predominantly commercial. To the south is the Liberty Memorial, a Kansas City monument to World War I Veterans. A small park, named Washington Park is located to the east of the station. And Crown Center, a major commercial development is to the southeast.

Sources of Information National Register Form

2. County

Lat. Long

Register?

Prepared November 11, 1971

46. Prepared by Linda F. Becker 47. Organization Kansas City Landmarks Commission 49. Revision Date(s) 12/2/76

JA-AS-008-1375

Union Station

No. 27 (cont.)

Survey, 1971, Missouri State Park Board

No. 42 (contt)

ing the multi-planar wall surface varying from thick, stone masonry to a broad expanse of pained glass in the round arched window. The entablature design is based on the Roman Doric Order with Beaux-Arts mannerisms.

The main block is flanked by side wings, three stories high, with pavilions at each end. The rear "T" extends north and bridges the through track system. This portion of the building joins the front block at the central third of the rear wall.

The station's unique solution to handling vast numbers of people was to place the waiting room concourse over and perpendicular to eight train tracks which passed beneath.

H	IIST	5	R	C	INI	/FN	JT	0	R	Y
					11 4 1	/	4 1	$\smile$		

A-AS-CO8-1375

1. No. 119-A 2. County Jackson	4. Present Name(s) Union Station	
3 Location of Negativesfile photo Landmarks Commission of KC	5. Other Name(s)	J-A
6 Specific Location	16. Thematic Category	28. No. of Stories
30 West Pershing Road	17. Date(s) or Period 1901–14	29. Basement? YesXX No I
7. City or Town If Rural, Township &	Vicinity 18. Style or Design	30. Foundation Material
Kansas City, Missouri  8. Site Plan with North Arrow	Beaux-Arts 19. Architect or Engineer	masonry
	Jarvis Hunt (Chicago)  20. Contractor or Builder	32. Rool Type & Malerial  Varied
	Fuller Const. Co. (Chicago) 21 Original Use, if apparent	Front Side
	railroad station  22 Present Use	34. Wall Treatment granite; limestone
	railroad station	35. Plan Shape irregular
	Priva	lic II 36. Changes Addition :
9 Coordinates UTM	24. Owner's Name & Address, if known	in #42)  Altered 1 Portion Moved 1 Portion Interior good
Long.	Public?	es IX 38. Preservation Yes : ON II Underway? No XX
Building 💆 O	restriction of Organization  Yes: Tandmarks Commission of	39. Endangered? Yes I
Register? No 11 Eligible?	No 1: 27. Other Surveys in Which Included	KC.
13 Part of Estab. Yes   1	Yes In	40. Visible from Yes XX Public Road? No i
15. Name of Established District		41. Distance from and Frontage on Road 510 feet on Pershing Ro
42. Further Description of Important Feat	res The building has an elevated cent	

arches, nearly 90 feet in height. Each arch is flanked by columns. The walls are granite at the base and limestone above. The side wings are three stories high. The rear "T" extends the building 450 feet north and bridges the through track systems. The central section of the building originally housed a 240 x 100 foot lobby/ticket office.

43. History and Significance This monumental railroad station, modeled after ancient Roman baths, opened in 1914. During the height of the rail passenger industry, this station housed the city's transportation needs, accomoding some 300 passenger trains daily. This structure also served as the most prominent architectural contribution to the City Beautiful movement in Kansas City The building was listed in the National Register on February 1, 1972.

44. Description of Environment and Outbuildings A parking area is south of this building. To the north are the Terminal Railroad tracks. Railroad express buildings are to the west. To the east is a commercial building.

## 45 Sources of Information

National Register Nomination Form

46. Prepared by PILAND 47. Organization Landmarks Commission 48. Date 49. Revision Date(s) 4/4/84



State Historical Sur and Planning Office, 909 University Avenue, Suite 215, Jumbia, Missouri 65201 HISTORIC INVENTORY A-AS-008-1 1. No 4. Present Name(s) 132-B Pershing Building County Jackson 5 Other Name(s) Location of Negatives Landmarks Commission Sweeney Automobile School; B.M.A. Building 16. Thematic Category 6. Specific Location 28. No. of Stories 10 030 050 29. Basement? Yes I Jackson 17. Date(s) or Period No I 215 W. Pershing 30. Foundation Material 1916-17 18 7. City or Town Style or Design . If Rural, Township & Vicinity 31. Wall Construction Kansas City, Missouri 8. Site Plan with North Arrow 19. Architect or Engineer WEST LEASHing KD 32. Roof Type & Material Keene & Simpson PR 20. Contractor or Builder 33. No. of Bays George E. Bliss Const. 21. Original Use, if apparent 4 Side Front Present Name(s) 215 commercial 34. Wall Treatment brick; terra cotta 22. Present Use 35. Plan Shape L-shaped commercial 36. Changes 23 Ownership Public 11 Addition i Pershing Private IX Altered to (Explain in #42) Moved I 24. Owner's Name & Address. if known 37. Condition Interior 9. Coordinates UTM Exterior excellent Lat. Long Yes IX 25. Open to Yes X 38. Preservation Public? Noil Underway? No i Site Structure | Building to Object | | 26. Local Contact Person or Organization 39. Endangered? Yes By What? No bo Landmarks Commission Yes X 11. On National 12 Is It Yesli Register? Eligible? No X 27. Other Surveys in Which Included Yes X 14 District Yes X 13. Part of Estab. Yes ! ! 40. Visible from Hist. Dist.? Potent'1? No : Public Road? No ! ! No to 15. Name of Established District 41. Distance from and Frontage on Road 200 feet on W. Pershing 42. Further Description of Important Features The building's 10-story mass, accommodating some 2,186,000 Cuici square feet of space, is articulated by the juxtaposition of terra cotta with red brick. the corners of the building are four towers created by the vertical extensions of the wall surface beyond the building's mass. The first, second and tenth stories are indine(5, constructed of terra cotta, as are the corner bays of the building. Classical detailing Automobile embellish the window areas. The building terminates in a pent roof with a denticulated molding. The building contains 2,186,000 square feet. For more than a decade this building housed the Sweeney Automotive and 43. History and Significance Electrical School. Head of the school, Emory J. Sweeney, had 4 architectural drawings published in the Kansas City Star in 1916 and asked the public to select the building to S be constructed. Over 3,000 people responded. This was the 1st building to be erected choo fronting Union Station. The building was designed for ultimate conversion to a hotel. 1;B 44. Description of Environment and Outbuildings Vacant and park land is south of this building. Z west is the Main Post Office. Penn Valley Park is to the east. To the north is the Union A Station Express Annex. W uildi 45 Sources of Information 46. Prepared by Piland /Uguccioni Kansas City Star, July 9, 1916, p. 13A. Kansas City Star, February 11 47. Organization 1917, p. 12A Kansas City Times, April 19, 1928. Landmarks Commission Kansas City Star, April 22, 1928. 49. Revision Date(s) 48. Date Kansas City Times, March 18, 1929. 12/30/81 WP #59425



State Historical Survey and Planning Office, 909 University Avenue, Suite 215, olumbia, Missouri 65201 HISTORIC INVENTORY 5A-AS-008-1377 No. 119-D 300-330 Pershing Road 2. County Jackson 5. Other Name(s) Union Station Express 3 Location of Negatives MT #86-12 Express Annex Bulder Landmarks Commission 6. Specific Location 16. Thematic Category 28. No. of Stories 29. Basement? LOURTY Yes 300-330 Pershing Road 17 Date(s) or Period 30. Foundation Material If Rural, Township & Vicinity 18. Style or Design concrete Kansas City, Missouri 31. Wall Construction 8. Site Plan with North Arrow 19. Architect or Engineer reinforced concrete 32. Roof Type & Material =+ selves 20. Contractor or Builder flat: tar and gravel 33. No. of Bays Front Side 21. Original Use, if apparent Present Name(s) 300-330 commercial 2 WA 34. Wall Treatment 22 Present Use concrete 35. Plan Shape irregular commercial PERSHING ROAD 36. Changes 23 Ownership Public 11 Addition Pershing Private | \* (Explain Altered I in #42) Moved 24. Owner's Name & Address, if known 37. Condition Interior 9. Coordinates UTM Rd Exterior Lat. Long 25. Open to Yes 1x 38. Preservation Yes i Public? No I Underway? No i 10. Site! Structure I Building M Object ! 26. Local Contact Person or Organization 39. Endangered? Yes IX By What? No I 11. On National Yes 12 Is It Yes Ix Landmarks Commission Eligible? No IX No I Register? 27. Other Surveys in Which Included possible demolition Yes X 13 Part of Estab. Yes 11 District 40. Visible from Yes ! x Hist. Dist.? No M Potent'l? No : Public Road? No 1 41. Distance from and Approx Frontage on Road 800 ft 15. Name of Established District on Pershing Road 42. Further Description of Important Features This building extends west from the Union Station and approximately 2/3's along its length, it angles slightly to accommodate the curve of Pershing Road. While the building is 53 feet in height, it is partially submerged in the ground, with Photo only 30 feet projecting above. The building sits below grade. Loading docks line the north and south facades. Above, the concrete walls are punctuated with a series of multipaned windows. 43. History and Significance This express building extends west from Union Station. When the Broadway Viaduct was constructed in 1913, it passed directly through the express offices, leaving a one-story passageway underneath that connected this building with the smaller portion of the express building (2414-18 Broadway). A tunnel running from this building carried express mail and to the track level 44. Description of Environment and Outbuildings Union Station is to the immediate east. At the west end of this building is the Broadway Viaduct. The Terminal railroad tracks are to the north. To the south is a commercial building and the Main Post Office. 45 Sources of Information 46. Prepared by Kansas City Times, Dec. 19, 1975, p. 18C. Piland 47. Organization Kansas City Times, May 28, 1913. Landmarks Commission Kansas City Star, Oct. 20, 1912 48. Date 49. Revision Date(s) Kansas City Star, Aug. 22, 1911 7/5/82



Present Name(s)

15

Jackson

Yes !

No I

4. Present Name(s) No 132-A 2. County

Main Post Office-Kansas City, Missouri entered


5 Other Name(s)

3 Location of Negatives MT #52-16 Landmarks Commission

Jack son

6. Specific Location

315 West Pershing Road 7 City or Town - If Rural, Township & Vicinity Kansas City, Missouri B. Site Plan with North Arrow



9 Coordinates Lat. Long

10	Site!. Buildingxx				cture   -
11.	On National Register?	Yes II No xx	12	Is It Eligible?	Yes XX
13	Part of Estab.	Yes II	14	District Potent'12	Yes XX

15. Name of Established District

16. Thematic Category 17 Date(s) or Period

18 Style or Design Classic Revival

1930-1933

19 Architect or Engineer

J. A. Wetmore (Washington D.C.) 20. Contractor or Builder

Ring Construction Co. 21. Original Use, if apparent

post office 22 Present Use

post office 23 Ownership

25. Open to

24. Owner's Name & Address, il known

Public? No I 26. Local Contact Person or Organization

Landmarks Commission 27. Other Surveys in Which Included 28. No of Stories

29. Basement? 30. Foundation Material

stone 31. Wall Construction Concret steel; reinforced

32. Roof Type & Material flat; tar & gravel

33. No. of Bays

Front 19 Side

34. Wall Treatment limestone 35. Plan Shape rectangular

36. Changes Addition I (Explain Altered I in #42) Moved i

37. Condition Interior Exterior

Underway?

Public K

Private | |

Yes k

excellent Preservation Yes No ix

No I

39. Endangered? Yes No 1x By What? 40. Visible from Yes !X

Public Road? 41. Distance from and Frontage on Road 280 feet on Broadway

42 Further Description of Important Features The building measures 265x280 feet in Size and is sited on a grade. Limestone is used as a facing material and its monumental appearance is derived not only from its enormous size, but in the juxtaposition of the severity of its non-ornamentation with classically inspired motifs. The fourth and fifth stories boast a two story colonnade on the primary facades, consisting of fluted Doric columns. Metal spandrels are placed between the columns and are ornamented with swags. The entablature above the colonnade consists of a series of rondels, and a denticulated molding. The main entrance, placed centrally on the north facade consists of three pedimented doorways. Placed above them (cont'd)

43. History and Significance Constructed at a cost of over \$3 million dollars, the Main Post Office encompasses a total of 5 acres of land surface. Built to replace the post office station at 9th and Grand which had become obsolete, the site was selected primarily because of its close proximity to Union Station and its rail facilities for dispatch of the mail. A tunnel and conveyor belt is located in the sub-basement and runs underground into the train (cont d)

44. Description of Environment and Outbuildings Vacant land is east of this building. To the north is a surface parking area. Commercial buildings and surface parking lots are to both the west and south.

## 45 Sources of Information

KC Star, July 17, 1931. KC Times, October 7, 1931. KC Star, May 11, 1930

KC Star, March 22, 1936. KC Journal-Post, July 17, 1932.

KC Star, December 9, 1930.

KC Star, March 27, 1929. KC Post, June 4, 1928. WP #3889

Midwest Contractor, July 15, 1931, p 48. Date 20.

Midwest Contractor, Dec. 17, 1930, p. 20.

46. Prepared by Uguccioni

47. Organization Landmarks Commission

49. Revision Date(s)

HISTORIC INVENTORY 315 West Pershing Road Page 2 JA-AS-008-1378

- 42. are carved relief panels in stone. The parapet wall is raised above the main wall surface on the center bays. It is ornamented with a bas-relief consisting of swags interspersed between roundels. Ornamentation at the corners of the building, and on the majority of the building's mass is highly restrained. Piers at the corners of the building terminate in carved, stylized eagles. Loading docks on the west facade are sheltered by a flat roofed canopy.
- 43. station. When the post office opened in 1933 it employed 1,000 workers. In 1936 the Kansas City Main Post Office was the third busiest in the nation exceeded in volume only by Chicago and New York. The interior of the building boasts ornamental plaster ceilings and a profusion of marble veneer Facilities in the building include a cafeteria, print shop, general offices, and lockers and shower rooms. The main post office is still the headquarters of the postmaster and executive officers of the postal service in Kansas City.



State Historical Survey and Planning Office, 909 University Avenue, Suite 215,

olumbia, Missouri 65201

47. Organization

12/16/81

Landmarks Commission 48. Date 49. Revision Date(s) County

Present Name(s)



5/6/82

State Historical Sur y and Planning Office, 909 University Avenue, Suite 215,



JA-45-008-1381

H	IST	OF	C	INI	VEN	IT	OR	Y
	101			11.4	V	4 1		

1. No. 70-F	4. Present Name(s)		Γ
Jackson  Jackson  Jackson  Jackson  Jackson  Jackson  Jackson  Jackson  Jackson  KC	George Will Company  5 Other Name(s)		70-F
6 Specific Location 110-116 Southwest Boulev	rard 16. Thematic Category  030 050 050  17. Date(s) or Period  1917	28. No. of Stories 1 29. Basement? Yes I Noxx 30. Foundation Material	Jacks
7 City or Town If Bural, Township & Kansas City, Missouri 8 Site Plan with North Arrow	Vicinity 18 Style or Design  19 Architect or Engineer  20 Contractor or Builder	31. Wall Construction masonry LLD  32. Roof Type & Material F+ flat; tar and gravel	on
Southwest Buro	21. Original Use, if apparent commercial OQE IUD  22. Present Use commercial	33. No. of Bays Front 4 Side  34. Wall Treatment brick 30  35. Plan Shape square	110-116
9 Coordinates UTM	23 Ownership Public   Private M  24. Owner's Name & Address, if known	36. Changes Addition : (Explain Altered I Moved I 37. Condition Interior	6 Southwest
Lat. Long.  10. Site!: Struc	25. Open to Yes & Public? No I	38. Preservation Yes Underway? No ix	Boule
11. On National Yes   12 Is It Register? No xx Eligible?	Yes XX No   27. Other Surveys in Which Included Yes XX	39. Endangered? Yes ! No !X  40. Visible from Yes !X	evard
Hist. Dist.? No.xx Potent'l?  15. Name of Established District		Public Road? No 11  41. Distance from and Frontage on Road	

42. Further Description of Important Features The main facade faces south. Brick piers divide the facade into four bays. Garage doors are at the east and west ends of the building. An entrance door is centrally located, flanked by display windows.

43. History and Significance This building originally served as the service department for the Gridley Motor Company, located at 1616 Grand.

44. Description of Environment and Outbuildings Other commercial buildings are north, south, east and west of this structure.

45 Sources of Information WP #60355; 60356 Western Contractor, March 21, 1917, p. 19 BP #12109

46. Prepared by PILAND 47. Organization Landmarks Commission 49. Revision Date(s) 48. Date

4/6/84



Columbia, Missouri 65201

o conce inamel	
Cinci itamet	
indine(	C
	iddine(s

HISTOR	IC IN	VENTORY	A-AS-008-1382	
1. No. 70-E 2. County Jackson	Ga	teway Chemical Company er Name(s)	•	70-E
3 Location of Negatives MT #55- Landmarks Commission	-18	ddies Products Company		
6. Specific Location		16. Thematic Category	28. No. of Stories 3	JE
118-20 Southwest Bouleva	ra Building	17. Date(s) or Period	29. Basement? Yes! No!.	Jackson
7 City or Town If Rural, Townsh Kansas City, Missouri	nip & Vicinity	1920 18 Style or Design 69	30. Foundation Material concrete 45 31. Wall Construction	1 4
8. Site Plan with North Arrow		19. Architect or Engineer C.M. Williams 20. Contractor or Builder	masonry 32. Roc Type & Material flat; tar & gravel ++	
		21. Original Use, if apparent commercial ODE	33. No. of Bays Front 3 Side  34. Wall Treatment	118-20
intes.	1	22 Present Use commercial	hrick: 30 35. Plan Shape rectangular	2
9. Coordinates UTM		23 Ownership Public   Private X	36. Changes Addition : (Explain Altered & Moved :	Southwest
		24. Owner's Name & Address, if known	37. Condition Interior good	
Long.	Structure 1	25. Open to Yes I i Public? No x	38. Preservation Yes Underway? No X	Boulevar
Building IX	Object 11	26. Local Contact Person or Organization Landmarks Commission	39. Endangered? Yes III	ard
13 Part of Estab Yes 11 14 Dist	rict Yes X ent'l? No	27. Other Surveys in Which Included	40. Visible from Yes X Public Road? No 11	
15. Name of Established District			41. Distance from and Frontage on Road 50 feet on Southwest Bl	rd.

42. Further Description of Important Features The first story of the building features a garage door on the east end and a pedestrian entrance on the west end of the south facade. The second and third stories are divided into three bays by the tripartite arrangement of the windows. A bracketed denticulated cornice extends across the parapet wall of the north facade.

- 43. History and Significance Originally the building was planned as only two stories in height, but a third story was added before the completion of construction. The original tenant of the building was the Buddies Products Company, a candy manufacturing firm.
- 44. Description of Environment and Outbuildings Other commercial buildings are to the north, south, east, and west of this building.
- 45 Sources of Information WP #5475 BP #12694 BP #70211 Western Contractor, July 21, 1920, p. 32.

- 46. Prepared by Uguccioni
- 47. Organization Landmarks Commission
- 48. Date 49. Revision Date(s) 12/31/81



4/11/83



State Historical Survey and Planning Office, 909 University Avenue, Suite 215

Columbia, Missouri 65201

8/30/82



8/30/82

State Historical Survey and Planning Office, 909 University Avenue, Suite 215



Frontage on Road approx. 00 ft. on Wyandotte

JA-AS-008-1386

No.

vinci itamels

noteed

4. Present Name(s)

5. Other Name(s)

Spector's Merchandise Mart

Landmarks Commission of KC	1930-34 Wyandotte		
6 Specific Location	16. Thematic Category	28. No. of Stories 1	2
200 Southwest Boulevard	17. Date(s) or Period .	29. Basement? Yes I No I .	Jackso
	1951	30. Foundation Material	108
7 City or Town If Rural, Township & Vicinity Kansas City, Missouri	18. Style or Design	31. Wall Construction	
8. Site Plan with North Arrow	19. Architect or Engineer	concrete block	
. (3)	Louis Geis 20. Contractor or Builder	32. Roof Type & Material flat; tar & gravel	
Wy andothe	Messina Brothers	33. No. of Bays Front Side	
IV!	21. Original Use, if apparent commercial	34. Wall Treatment	200
3	22. Present Use	brick	So
Southwest Boulevard	commercial	35. Plan Shape irregular	Ĕ
Southwest poulevard	23 Ownership Public     Private	36. Changes Addition : : (Explain Altered : :	uthwest
	24. Owner's Name & Address,	in #42) Moved	3 ts
9. Coordinates UTM	if known	37. Condition Interior good	Boulevard
Long.  10. Site!: Structure!	25. Open to Yes 😾 Public? No 🗆	38. Preservation Yes I Underway? No IX	var
Building (x Object ! )	26. Local Contact Person or Organization	39. Endangered? Yes I	
11. On National Yes   12 Is It Yes   Register? No   14 Eligible? No   15 K	Landmarks Commission of KC 27. Other Surveys in Which Included	By What? No IX	
13 Part of Estab Yes   1 14 District Yes	The time and the second state of the second	40 Visible from Yes IX	

42. Further Description of Important Features The main facade of this corner store faces south. An entrance door is at the east end of the south facade, protected by an canopy roof that extends across this facade.

43. History and Significance The original tenants of this building were a restaurant operated by Walter Ross and the paint manufacturing firm, Devoe of Kansas City, Inc.

44. Description of Environment and Outbuildings Commercial buildings are north of this structure. A surface parking lot is to the west. A commercial building is also to the north. Another surface parking lot is to the east.

45 Sources of Information

69-F

Jackson

2 County

WP#96393 BP#17414

Hist. Dist.?

No 14

15. Name of Established District

Potent'l? No X

46. Prepared by PILAND 47. Organization Landmarks Commission 48. Date 49. Revision Date(s) 2/26/85



- Hallips

7/7/83



JA-AS-008-1388

ne(s)	Boulevard	hwest
		ne(s)

1 No. 69-E	4. Present Name(s)  Johnstone Supply		69-
Jackson	5. Other Name(s)		E
3 Location of NegativesMT#100-22 Landmarks Commission of KC	The White Company Garage		
6 Specific Location	16. Thematic Category	28. No. of Stories 1	Ja
216 Southwest Boulevard	17. Date(s) or Period 1927	29. Basement? Yes I No I X	Jackson
7 City or Town II Rural, Township & Kansas City, Missouri	Vicinity 18. Style or Design	30. Foundation Material	n
B. Site Plan with North Arrow	19. Architect or Engineer Other Archer & Gloyd 30 40	concrete block CB	
T N	20. Contractor or Builder C.A. Kelly	flat; tar & graveI+RC	
1	21. Original Use, if apparent commercial OSH 14D	Front -3 Side	216
1311	22. Present Use	brick 30	
Southwest Blud	commercial	35. Plan Shape rectangular	no
Sour	23 Ownership Public     Private   X	36. Changes Addition : : (Explain Altered !	Southwest
9 Coordinates UTM	24. Owner's Name & Address,, if known	37. Condition Interior good	St
Long.	25. Open to Yes IX Public? No II	38. Preservation Yes Underway? No X	Boulevard
	Yes: Landmarks Commission of KC No X 27. Other Surveys in Which Included	39. Endangered? Yes I No K	
3 Part of Estab. Yes   1	Yes IX No :	40. Visible from Yes 🕱 Public Road? No 🗆	
5. Name of Established District		41. Distance from and Frontage on Road 50 feet on Southwest Bl	vd.

42. Further Description of Important Features The main facade of this building faces south. An overhead garage door is centrally located, flanked by display windows divided into three, vertical segments. An entrance door replaces one of the vertical segments of the west window. The parapet is shaped and has stone coping.

43. History and Significance This building was originally used by the White Company as their used truck department.

44. Description of Environment and Outbuildings Surface parking areas are east and west of this building. To the north and south are commercial buildings.

45 Sources of Information WP#80501 BP#15028 Western Contractor, May 25, 1927, p.41. 46. Prepared by PILAND

47. Organization Landmarks Commission

48. Date 49. Revision Date(s) 3/6/85

## JOHNSTONE MOTORS \* HEATING \* AIR-COND. \* TOOLS MOTORS-HTG-AIR COND-APPL PARTS REFRIGERATION APPLIANCE PARTS OI CORN

BP #24514A; 66928

Western Contractor, Aug. 23, 1922.

Kansas City Star, April 29, 1984, p.1E

WP #71430

47. Organization

48. Date

4/4/84

Landmarks Commission

49. Revision Date(s)



1. No. 86-L	4. Pre	sent Name(s)	5A/AS-008-1390
S 70 77		dependent Electric Machinery Co.	
2 County			
Jackson  3 Location of Negatives Landmarks Commiss		06 Central; Hall-Truman Furniture	
	ion	- UNICA BUILDING	Buckerng
Specific Location		16. Thernalic Calegory	28. No. of Stories3
300 Southwest Bou	levard	17 Date(s) or Period	29. Basement? Yes K
		1904	30 Foundation Material
City or Town If Rur Kansas City, Miss	al, Township & Vicinity	18 Style or Design	stone 40
Site Plan with North Ar		19. Architect or Engineer	masonry / \( \)
		Frank A. Sherrill	32. Roof Type & Material
	70 N	20. Contractor or Builder	flat; tar & gravel
	BUIL	George Huggins 30 40	33. No. of Bays Front Side
/	4	commercial OPH 10A	34. Wall Treatment
1	263	22 Present Use	brick 30
1/1	7	commercial	35. Plan Shape irregular
Low	WEST BLUD N	23 Ownership Public     Private K	36. Changes Addition : : (Explain Altered !
2		24. Owner's Name & Address,	in #42) Moved
		if known	37. Condition
	UTM		Interior
Lat. Long		25. Open to Yes tx	Exterior good  38. Preservation Yes
Site ! :	Structure	Public? No 11	38. Preservation Yes Underway? No ix
Building Ix	Object 11	26. Local Contact Person or Organization	39. Endangered? Yes I
On National Yes II Register? No IX	12 Is It Yes X	Landmarks Commission	By What? No lx
	14 District YesX	27. Other Surveys in Which Included	40 Visible from Yes X
Part of Estab Yes			Public Road? No !!
Hist. Dist.? No 1x	Potent'l? No :	1	T donc riodd !
Hist. Dist.? No 1x			41. Distance from and
Hist. Dist.? No 13.  Name of Established D	listrict		41. Distance from and Frontage on Road 74 feet on Southwest Bl
Name of Established Description of Boulevard and Centereated by their joy a coursed stone placed on the sout	Important Features The ral. As the Boulunction is acute first story piet h facade, near the	he building is sited at the northwe levard runs diagonally and Central. The street facades mirror each orced by tripartite segmental arch whe junction of the two facades. Bring paired segmental arch window.	41. Distance from and Frontage on Road 74 feet on Southwest Bl st corner of Southwest vertically, the angle ther and are characterize indows. The entrance is
Hist Dist.? No 1x  Name of Established D  Property of Soulevard and Centerested by their juy a coursed stone of the south	Important Features The Tral. As the Boulunction is acute first story piet in facade, near the transfer of stories framing.  This building Company. It rep	levard runs diagonally and Central . The street facades mirror each o rced by tripartite segmental arch w he junction of the two facades. Br	41. Distance from and Frontage on Road 74 feet on Southwest Bl st corner of Southwest vertically, the angle ther and are characterize indows. The entrance is ick piers project on
History and Significance Truman Furniture was damaged by a	Important Features The ral. As the Boulunction is acuted first story piet in facade, near the rd stories framing.  This building Company. It repflood.	levard runs diagonally and Central  The street facades mirror each or red by tripartite segmental arch whe junction of the two facades. Bring paired segmental arch window.  g was erected as a warehouse and falaced their previous building in the A storage lot is north of this but	41. Distance from and Frontage on Road 74 feet on Southwest Bl st corner of Southwest vertically, the angle ther and are characterize indows. The entrance is ick piers project on actory for the Hall- ne West Bottoms that
History and Significance Truman Furniture was damaged by a	Important Features The Tral. As the Boulunction is acute first story piet in facade, near the transfer of the Transfer This building Company. It repetited for the transfer of	levard runs diagonally and Central  The street facades mirror each orced by tripartite segmental arch whe junction of the two facades. Bring paired segmental arch window.  g was erected as a warehouse and falaced their previous building in the	41. Distance from and Frontage on Road 74 feet on Southwest Bl st corner of Southwest vertically, the angle ther and are characterize indows. The entrance is ick piers project on actory for the Hall- ne West Bottoms that
Name of Established Description of coulevard and Centereated by their juy a coursed stone laced on the southe second and thin.  History and Significant Truman Furniture was damaged by a Description of Environment and east are surfaced.	Important Features The ral. As the Boulunction is acute first story piet he facade, near the rd stories framing. This building Company. It repetited food.	levard runs diagonally and Central  The street facades mirror each or red by tripartite segmental arch whe junction of the two facades. Bring paired segmental arch window.  g was erected as a warehouse and falaced their previous building in the A storage lot is north of this but	41. Distance from and Frontage on Road 74 feet on Southwest Bl st corner of Southwest vertically, the angle ther and are characterize indows. The entrance is ick piers project on actory for the Hall- ne West Bottoms that  dilding. To the south east.  46. Prepared by
Further Description of coulevard and Centrated by their jy a coursed stone laced on the southe second and thi  History and Significant Truman Furniture was damaged by a  Description of Environmand east are surf	Important Features The ral. As the Boulunction is acute first story piet he facade, near the rd stories framing. This building Company. It repetited food.	levard runs diagonally and Central  The street facades mirror each or red by tripartite segmental arch whe junction of the two facades. Bring paired segmental arch window.  g was erected as a warehouse and falaced their previous building in the A storage lot is north of this but	41. Distance from and Frontage on Road 74 feet on Southwest Bl st corner of Southwest vertically, the angle ther and are characterize indows. The entrance is ick piers project on actory for the Hall- me West Bottoms that  46. Prepared by Piland/Uguccioni
Hist. Dist.? No 1x  Name of Established Discussion of Soulevard and Centereated by their juy a coursed stone placed on the south he second and this truman Furniture was damaged by a Description of Environment.	Important Features The ral. As the Boulunction is acute first story piet he facade, near the rd stories framing.  This buildin Company. It repetions.  The repetition of the r	levard runs diagonally and Central  The street facades mirror each or ced by tripartite segmental arch whe junction of the two facades. Bring paired segmental arch window.  g was erected as a warehouse and falaced their previous building in the  A storage lot is north of this but.  A commercial building is to the	41. Distance from and Frontage on Road 74 feet on Southwest Bl st corner of Southwest vertically, the angle ther and are characterize indows. The entrance is ick piers project on actory for the Hall- ne West Bottoms that  dilding. To the south east.  46. Prepared by



47. Organization

48. Date

12/1/82

Landmarks Commission

49. Revision Date(s)

Courty



HISTORIC INVENTORY 1-AS-104-1397 4. Present Name(s) No. 86-G No. 86-G Bell Auto Electric 2 County 5 Other Name(s) Jackson Location of Negatives MT #55-15 Landmarks Commission 6 Specific Location 16. Thematic Category 28. No. of Stories ackson County 29. Basement? Yes 310-16 Southwest Boulevard 17. Date(s) or Period No I Bulding 1911 30. Foundation Material City or Town If Rural, Township & Vicinity Kansas City, Missouri 18. Style or Design 31. Wall Construction 64 masonry UD B. Site Plan with North Arrow 19 Architect or Engineer Clifton B. Sloan 32. Roof Type & Material F-20. Contractor or Builder flat; tar & gravel 9 Southwest Bivo 33. No. of Bays Charles E. Peterson 4 Front Side 21. Original Use, if apparent Present Name(s) 310-16 commercial A2E 34. Wall Treatment 22 Present Use metal 35. Plan Shape rectangular commercial Southwest 36. Changes 23 Ownership Public 11 Addition | Private 1x Altered k (Explain in #42) Moved 24. Owner's Name & Address, if known 37. Condition Interior UTM 9. Coordinates Exterior good Boulevard Lat Long 25. Open to Yes Ix 38. Preservation Yes Public? No Underway? Noxx 10. Site !: Structure | Building 1 Object | 26. Local Contact Person or Organization 39. Endangered? Yes By What? No XX Yes x 11. On National 12 Is It Landmarks Commission Yes Register? No to Eligible? No I 27. Other Surveys in Which Included Yes X 13 Part of Estab. Yes 11 14 District 40. Visible from Yes xx Potent'1? Hist. Dist ? No LI No: Public Road? No I 41. Distance from and 15. Name of Established District Frontage on Road 100 feet on Southwest Blvd 42. Further Description of Important Features The facade of this building was covered with corrugated metal in 1967. Several garage doors and rectangular windows provide fenestration. indine(5 43. History and Significance Numerous commercial firms have occupied the building over the years. 44. Description of Environment and Outbuildings Commercial buildings are east and west of this structure. Surface parking areas are north and south of this building. 46. Prepared by 45 Sources of Information WP #46578; 46580 Piland BP#10309 47. Organization BP#37061 Landmarks Commission 48. Date 49. Revision Date(s) 12/17/84

State Historical Survey and Planning Office, 909 University Avenue, Suite 215,

olumbia, Missouri 65201



1. No.	4. Pre	sent Name(s)	
86-F	Т,	ndependent Electric Machinery Co. W	Jarehouse
2 County Jackson		her Name(s)	archouse
Location of Negatives	MT #55-14	ndependent Electric Machinery Co.	
Landmarks Commissi  Specific Location	ion	16. Thematic Category	28. No. of Stories
Specific Location		03 0 050	28. No. of Stories 2 29. Basement? Yes xx No
320 Southwest Blvd	d	17. Date(s) or Period .	No I
		1903	Territoria in the control of the con
City or Town II Rura		1	stone 40
Kansas City, Misso Site Plan with North Arr		19. Architect or Engineer	masonry UD
		30	32. Roof Type & Material F PE
		20. Contractor or Builder	flat; tar & gravel 99
	5 N	21. Original Use, if apparent	33. No. of Bays Front4 Side
	BLUD N	commercial OPE	34. Wall Treatment
/ /	16.	22 Present Use	brick 30
45		commercial	35. Plan Shape rectangular
Southwest	r	23 Ownership Public II Private **	36. Changes Addition : (Explain Altered )
Low		24. Owner's Name & Address,	in #42) Moved
7		if known	37. Condition
	UTM		Interior good
Lat. Long.		25. Open to Yes II	Exterior good  38. Preservation Yes
Site!:	Structure I	Public? No 1	Underway? No x
Building L	Object	26. Local Contact Person or Organization	39. Endangered? Yes I
X			
On National Yes II	12 Is It Yes Ix	Landmarks Commission	By What? No 1
On National Yes III Register? No III	Eligible? No 13	Landmarks Commission  27. Other Surveys in Which Included	^
Register? No 1.1	The state of the s		By What? No 1/2:  40. Visible from Yes to Public Road? No 1:
On National Yes II Register? No IX Part of Estab Yes II Hist. Dist.? No II	Eligible? No !!  14. District Yes   X Potent'!? No !!		40. Visible from Yes & Public Road? No 11
On National Yes II Register? No IX Part of Estab Yes II Hist. Dist.? No II	Eligible? No !!  14. District Yes   X Potent'!? No !!		40. Visible from Yes & No 11  41. Distance from and Frontage on Road
Register? No L. Part of Estab. Yes I I Hist. Dist.? No I I Name of Established Di	Eligible? No ::  14. District Yes : Potent'!? No :: istrict  Important Features The	27. Other Surveys in Which Included	40. Visible from Yes & Public Road? No!:  41. Distance from and Frontage on Road 40 feet on Southwest B
Register? No 1.1 Register? No 1.1 Register? No 1.1 Register? No 1.1 Hist. Dist.? No 1.1 Name of Established Dist. Further Description of 1 at the west end and	Eligible? No !!  14. District Yes X Potent'!? No !!  istrict  Important Features The A garage bay at	27. Other Surveys in Which Included	40. Visible from Yes & No!:  41. Distance from and Frontage on Road 40 feet on Southwest Boup of storefront panes s fenestrated with multi-
11. On National Yes   Register? No   No   No   No   No   No   No   No	Eligible? No 11  14 District Yes X Potent'!? No 12  istrict  Important Features The d a garage bay at the definition of the desired windows. He	27. Other Surveys in Which Included e south facade is composed of a gro t the east end. The second story i prizontal brick banding enlivens th	40. Visible from Yes be Public Road? No is 41. Distance from and Frontage on Road 40 feet on Southwest out of storefront panes as fenestrated with multiple parapet wall.
Register? No 12 Register. No 1	Eligible? No 11  14 District Yes X Potent'!? No 11  Important Features The d a garage bay at the windows. However, the desired windows in the desired windows in the desired windows in the desired windows. However, the desired windows is the desired windows in the desired win	27. Other Surveys in Which Included e south facade is composed of a gro	40. Visible from Yes x Public Road? No!:  41. Distance from and Frontage on Road 40 feet on Southwest Boup of storerront panes as fenestrated with multiple parapet wall.
Register? No 12 Register? No 12 Register? No 12 Register? No 12 Hist. Dist.? No 11 X Name of Established Dist. Register? No 12 X N	Eligible? No ??  14. District Yes X Potent'!? No ??  istrict  Important Features The d a garage bay at the earliest kn who currently us the desired and Outbuildings	27 Other Surveys in Which Included a south facade is composed of a group the east end. The second story is prizontal brick banding enlivens the prizontal brick banding enlivens the second story is prizontal brick banding enlivens the building was to the building for warehouse space.	40. Visible from Yes k Public Road? No!:  41. Distance from and Frontage on Road 40 feet on Southwest B out of storefront panes is fenestrated with multiple parapet wall.
Part of Estab. Yes     Hist. Dist.? No     Name of Established Dist. Name of Established Dist.   Further Description of It the west end and aned segmental architect Conpany, Description of Environm	Eligible? No ??  14. District Yes X Potent'!? No ??  istrict  Important Features The d a garage bay at the earliest kn who currently us the desired and Outbuildings	27 Other Surveys in Which Included a south facade is composed of a group the east end. The second story is prizontal brick banding enlivens the prizontal brick banding enlivens the second story is prizontal brick banding enlivens the building was to the building for warehouse space.	40. Visible from Yes k Public Road? No!:  41. Distance from and Frontage on Road 40 feet on Southwest B out of storefront panes is fenestrated with multiple parapet wall.
Part of Estab. Yes	Eligible? No ??  14. District Yes X Potent'!? No ??  istrict  Important Features The d a garage bay at the earliest kn who currently us the desired and Outbuildings	27 Other Surveys in Which Included a south facade is composed of a group the east end. The second story is prizontal brick banding enlivens the prizontal brick banding enlivens the second story is prizontal brick banding enlivens the building was to the building for warehouse space.	40. Visible from Yes k Public Road? No!:  41. Distance from and Frontage on Road 40 feet on Southwest B out of storefront panes as fenestrated with multiple parapet wall.  The Independent Electric re.
Part of Estab. Yes     Hist. Dist.? No     Name of Established Dist. N	Eligible? No ??  14. District Yes X Potent'!? No ??  istrict  Important Features The d a garage bay at the earliest kn who currently us the desired and Outbuildings	27 Other Surveys in Which Included a south facade is composed of a group the east end. The second story is prizontal brick banding enlivens the prizontal brick banding enlivens the second story is prizontal brick banding enlivens the building was to the building for warehouse space.	40. Visible from Yes k Public Road? No!:  41. Distance from and Frontage on Road 40 feet on Southwest B rup of storefront panes is fenestrated with multiple parapet wall.  The Independent Electric re.  46. Prepared by Uguccioni
Register? No 12 Rist. Dist.? No 11 X  Name of Established Dist.  Part the West end and baned segmental architecture and Significance Machinery Conpany,  Description of Environmouth. A surface part of Sources of Information	Eligible? No ??  14. District Yes X Potent'!? No ??  istrict  Important Features The d a garage bay at the earliest kn who currently us the desired and Outbuildings	27 Other Surveys in Which Included a south facade is composed of a group the east end. The second story is prizontal brick banding enlivens the prizontal brick banding enlivens the second story is prizontal brick banding enlivens the building was to the building for warehouse space.	40. Visible from Yes k Public Road? No!:  41. Distance from and Frontage on Road 40 feet on Southwest B out of store front panes as fenestrated with multiple parapet wall.  The Independent Electric re.  46. Prepared by Uguccioni 47. Organization
Register? No 12 Rist. Dist.? No 13 Rist. Dist.	Eligible? No ??  14. District Yes X Potent'!? No ??  istrict  Important Features The d a garage bay at the earliest kn who currently us the desired and Outbuildings	27 Other Surveys in Which Included a south facade is composed of a group the east end. The second story is prizontal brick banding enlivens the prizontal brick banding enlivens the second story is prizontal brick banding enlivens the building was to the building for warehouse space.	40. Visible from Yes k Public Road? No!:  41. Distance from and Frontage on Road 40 feet on Southwest B rup of storefront panes is fenestrated with multiple parapet wall.  The Independent Electric re.  46. Prepared by Uguccioni



Columbia, Missouri 65201

Landmarks Commission

49. Revision Date(s)

48. Date

6/30/83

County



1. No.	4. Pre	sent Name(s)	TA-AS-008-1395	-
86-E		gel Bindery Co.		
2 County Jackson		er Name(s)		86-
3 Location of Negatives M	m //cc 10			H
Landmarks Commissi		1ben Enameling Works Building		
6. Specific Location		16. Thematic Category	28. No. of Stories 2	Jackson
322 Southwest Blvd		030 050	29. Basement? Yes   X	cks
		17 Date(s) or Period . 1921	30. Foundation Material	on
7 City or Town - If Rura	1 Township & Vicinity	18. Style or Design	30. Poundation Material	
Kansas City, Misson		64	31. Wall Construction	
B. Site Plan with North Arro		19. Architect or Engineer	masonry UD	
		20 0 1 1 2 2 2 2	32. Roof Type & Material + PR	
1	14	20. Contractor or Builder 30 40	flat; tar & gravel ag	
	N	21. Original Use, if apparent	Front 3 Side	w
	1	commercial ODE	34. Wall Treatment	322
Southwest BLUE		22. Present Use	brick; stone 30	
BL		commercial	35. Plan Shape rectangular	Southwes
MEST	1	23 Ownership Public   Private	36. Changes Addition 1:	hw
COUTHU		24. Owner's Name & Address,	in #42) Moved i	est
2.		if known	37. Condition	
9. Coordinates U	ITM		Interior	Blvd
Lat. Long.		20 Q	Exterior good	
10. Site ! :	Structure 1	25. Open to YesXX Public? No ! !	38. Preservation Yes Underway? No XX	
Building to	Object	26. Local Contact Person or Organization	39. Endangered? Yes I	
11. On National Yes	12 Is It Yes X	Landmarks Commission	By What? No XX	
Register? No ⊠	Eligible? No 11	27. Other Surveys in Which Included	XX	
Hist. Dist.? No k	Potent'l? No .		40. Visible from Yes XX Public Road? No 1	
15. Name of Established Dis	strict		41. Distance from and	
			Frontage on Road	
12 Fruit as Danasiation of to	Tho	primary (south) facade is composed	25 feet on Southwest Bl	va.
fenestrated with re-	ctangular window	storefront panes on the east end. s that feature stone lintels and bronament. The parapet wall is shaped	rick sills accented at the	de la contrata del la contrata de la
building plans were \$8,000. The original	altered and the al tenant was the ent and Outbuildings (	nal plans submitted called for only building was constructed as two stee Malben Enameling Works.  There commercial buildings are to the Another commercial building is	tories, at a cost of	
5 Sources of Information	iriace parking io	ot. Another commercial building is	46 Prepared by Uguccioni/Piland	
WP #66798		Ť		1
BP #12898 BP #73235			47. Organization Landmarks Commission	
Western Contractor,	Oct. 19, 1921	32.	48. Date 49. Revision Date(s)	
de la contractor,	221, 17, 1721,		9/28/81	



1. No. 87-D 2. County	Warren Appliance Service Other Name(s)	JA-AS-008-1396	87-D
329 Southwest Boulevard Bulle 7. City or Town If Rural, Township & Vice Kansas City, Missouri 8. Site Plan with North Arrow	1887	28. No of Stories 2  29. Basement? Yes I No I  30. Foundation Material  31. Wall Construction    Masonry B  32. Roof Type & Material Flat; tar & gravel 99  33. No. of Bays    Front Side  34. Wall Treatment	Jackson 329 Sou
9 Coordinates UTM Lat. Long.	Private Private     24. Owner's Name & Address, if known   25. Open to Yes   x	(Explain Altered   X in #42) Moved    37. Condition Interior Exterior Fair    38. Preservation Yes	thwest Bouleva
Register? No x! Eligible? No x! Strain No x! Register? No x! Strain No x! Register? No x! Regi		Underway?  39. Endangered? By What?  40. Visible from Yesx: Public Road?  41. Distance from and Frontage on Road 25 feet	rd

42. Further Description of Important Features The main facade faces north. At the west end of this facade is an entrance leading to the second floor. The first floor entrance is off center. A corrugated metal panel runs between the first and second floors. Cast iron posts divide the first floor into bays. Some alteration has occured to the first floor.

43. History and Significance One in a row of commercial structures of similar date, visually united by scale and use of cast iron columns.

44. Description of Environment and Outbuildings Vacant land is north of this building. To the east, west and south are other commercial buildings.

45 Sources of Information

WP #7453

46 Prepared by Piland 47. Organization Landmarks Commission 48. Date 49. Revision Date(s) 4/12/84



39. Endangered?

By What?

40 Visible from

Public Road?

41. Distance from and

Frontage on Road 25 f on Southwest Blvd

Structure |

12 Is It

Eligible?

District

Potent'1?

Object | |

Yesk

YesX

No :

No I

	- 01
ular	Southwe
ion ::	TT 3
red I '	W s
ved i	68
_	77
	ᄍ
	0
	E
Yes	10
No X	a
100	rd
Yes	
No K	
-	N.
Yes X	
Nott	
feet	

Ye:

Yes

4. Present Name(s) 1. No. 87-F 331 Southwest Boulevard 2 County 5. Other Name(s) Jackson 3 Location of Negatives Landmarks Commission 16. Thematic Category 6. Specific Location 030 050 17. Date(s) or Period 331 Southwest Boulevard 1887 7. City or Town II Rural, Township & Vicinity Kansas City, Missouri 18. Style or Design 69 00 Sources free B. Site Plan with North Arrow 19. Architect or Engineer 20. Contractor or Builder Jeffers & Love 21. Original Use, if apparent commercial/apartment 22. Present Use unknown 23 Ownership 24. Owner's Name & Address, if known 9. Coordinates UTM Fair Exterior Lat Long 25. Open to Yes 38. Preservation Yes Public? No X Underway?

42 Further Description of Important Features The main facade, facing north, is divided into four bays. bay at the east contains an entry door, leading to the second floor. The 2nd bay from the west contains a double door and is flanked by display window bays and cast iron columns. Four rectangular windows, now boarded over, fenestrate the 2nd floor. These windows feature stone sills and lintels.

Landmarks Commission

27. Other Surveys in Which Included

26. Local Contact Person or Organization

43. History and Significance One in a row of commercial structures of similar date, visually united by scale and use of cast iron columns.

44. Description of Environment and Outbuildings Commercial buildings are east, west and south of this structure. To the north is vacant land.

45 Sources of Information WP #7606

Site!

Yesli

No ly

Building M

15. Name of Established District

11 On National

Register?

Hist. Dist.?

13 Part of Estab Yes ! !

46. Prepared by Piland 47. Organization Landmarks Commission 49. Revision Date(s) 48. Date 4/23/84



42. Further Description of Important Features Cast iron columns divide the first floor into four unequal. bays. A double entrance door is located in one of the center bays. The window transoms have been covered over. Comparison with a c. 1940 photograph shows that an ornate cornice has been removed.

43. History and Significance One is a row of commercial structures of similar date, visually united by scale and use of cast iron columns. The building originally housed a grocery store operated by Anthony Artmaier.

44. Description of Environment and Outbuildings Vacant land is north of this building. To the east, west and south are other commercial buildings.

45 Sources of Information

1. No.

2. County Jackson

Lat.

10.

Long

Register?

WP #8597

46. Prepared by Piland

47. Organization Landmarks Commission

49. Revision Date(s) 48. Date

4/12/84



Present

Name(s)

Diller Hallietz

47. Organization

48. Date

7/7/83

Landmarks Commission

49. Revision Date(s)



HISTORIC INVENTORY JA-A5-008-1400 4. Present Name(s) . No. 85-D 85-D Sarann Auto Leasing 2. County 5 Other Name(s) Jackson MT #86-1 Location of Negatives Ray Cole Sixty-Six Service Landmarks Commission 6. Specific Location 16. Thematic Category 28. No. of Stories ackson County 29. Basement? Yes I 400 Southwest Boulevard 17 Date(s) or Period No I 1954; (add. 1979-80) 30. Foundation Material 7 City or Town If Rural, Township & Vicinity Kansas City, Missouri 18. Style or Design 31. Wall Construction 8. Site Plan with North Arrow 19. Architect or Engineer concrete block 32. Roof Type & Material 20. Contractor or Builder flat; tar & gravel 33. No. of Bays Side Front 21. Original Use, if apparent 400 Southwest service station 34. Wall Treatment Southwest 3WD 22. Present Use brick: concrete block 35. Plan Shape commercial irregular Public 11 36 Changes 23 Ownership Addition Altered X Private IX (Explain in #42) Moved i 24. Owner's Name & Address, il known 37. Condition Bouleva Interior 9 Coordinates UTM Exterior good Lat. Long Yes IX 25. Open to 38. Preservation Yes . Noil Public? Underway? Noix 10 Site ! : Structure Building & Object | 26. Local Contact Person or Organization 39. Endangered? Yes By What? Nolx Landmarks Commission Yes 11. On National Yes 12 Is It Eligible? No Register? No t 27. Other Surveys in Which Included Yes X Yes 13 Part of Estab. Yes 11 District Visible from Hist. Dist.? No I Potent'1? No Public Road? No : : Distance from and 15. Name of Established District Frontage on Road 70 ft on Southwest Blyd 42. Further Description of Important Features The main facade of this corner building faces south. The original portion of the building is the west section. At the east end is an addition of 1979-80. The main entrance is on the south facade of the addition. Four garage bays extend across the south facade of the original section. Cole indine(5, Sixty-Six 43. History and Significance This building was constructed as a Phillips Sixty-Six Service Station and was first operated by Ray Cole. 44. Description of Environment and Outbuildings Vacant lots are south and east of this building. To the west is a commercial building. A small surface parking lot is to the north. 46. Prepared by 45 Sources of Information BP #18078 Piland WP #64143 47. Organization Landmarks Commission BP#14373A 48. Date 49. Revision Date(s) 2/14/85

State Historical Survey and Planning Office, 909 University Avenue, Suite 215,

olumbia, Missouri 65201



State Historical Survey HISTORIC IN	NVENTORY	y Avenue, Suite 215, mbia, Missouri 65201 A-AS-008-140	1 15
101-4	resent Name(s) ayne's Motorcycle Sales & Service	×	101-
Jackson 5	Weber Gas and Gasoline Eng Lloyd Foundry and Machine Works Bulds	ine Company; -other name	À
6. Specific Location	16. Thernatic Category	28. No of Stories 2	
405 Southwest Boulevard	030 050 17. Date(s) or Period	29. Basement? Yes IXX	Jackson
	1885	30. Foundation Material	cson
7. City or Town If Rural, Township & Vicini Kansas City, Missouri 8. Site Plan with North Arrow		31. Wall Construction masonry	Total Section
B. Site Plan with North Arrow	20. Contractor or Builder	32. Roof Type & Material AE flat; tar and gravel 99	
Southwest Brus N	21. Original Use, if apparent	33. No. of Bays Front 7 Side	
1 stutes	Commercial Da E IDA	34. Wall Treatment	405
Journ	22. Present Use	brick 30	
	Commercial	35. Plan Shape rectangular	no
	23 Ownership Public     Private   XX	36 Changes Addition X: (Explain Altered I)	Southwes
	24. Owner's Name & Address, if known	in #42) Moved	185
9 Coordinates UTM	- I Allowii	37. Condition Interior	Boulevard
Lat. Long	25. Open to Yes IXX	Exterior good	lei
10. Site 1: Structure		38. Preservation Yes Underway? NoXX	/ar
Building XX Object   11. On National Yes   12 is it Yes	20. Local Contact reison of Organization	39. Endangered? Yes I No XX	1
Register? No XX Eligible? No	The state of the s		
Hist. Dist.? No XX Potent'1? No		40. Visible from YesXX Public Road? No 11	
15. Name of Established District		41. Distance from and Frontage on Road 50 feet on Southwest Bl	vd.

42 Further Description of Important Features A double entrance door is centrally located on the north facade. The facade is further divided into multipaned window fronts, a garage entrance, and another double door by cast iron piers. The second floor is fenestrated with 7 tall rectangular windows with shaped lintels. At the rear of the building is an addition, date unknown.

43. History and Significance This was originally the Lloyd Foundry and Machine Works. Under the direction of George Weber, the firm engaged in all types of metal work and manufactured the Corliss Engine. By 1898 the firm name had become the Weber Gas and Gasoline Engine Company. This was one of 4 adjacent buildings used by the firm. In 1898 the company was building the largest gasoline hoisting engine in the world, for use in a Mexican mine. The firm supplied engines to many foreign countries; "the sun never sets on Weber engines."

44. Description of Environment and Outbuildings Another commercial building is to the west of this building. Vacant land is to the east and south. A commercial building is also to the north.

WP# 4685 Kansas City Star, Sept. 2, 1898, p. 4. 46, Prepared by
Piland
47. Organization
Landmarks Commission
48. Date 49. Revision Date(s)
10/26/81





Reart

HISTORIC	INVENTORY 5	-AS-008-1402	*
101-B 2 County Lackson	4. Present Name(s) 411-13 Southwest Boulevard 5 Other Name(s)		101-в
6 Specific Location 411-13 Southwest Boulevard	16. Thematic Category  030 050 290  17. Date(s) or Period  18. C. 1900 (add. 1926)	28. No of Stories 1—/ 29. Basement? Yes! No:	Jac
7 City or Town II Aural, Township & Vi Kansas City, Missouri 8 Site Plan with North Arrow Southwest Blud		31. Wall Construction masonry UD 32. Roof Type & Material F+ PQ	Jackson
Southwest N1	21. Original Use, if apparent commercial ODE 160	flat: tar & gravel ag 33. No. of Bays Front-3 Side  34. Wall Treatment brick 30	411-13
	23 Ownership Public 1 Private M  24. Owner's Name & Address.	35. Plan Shaperectangular  36. Changes Addition X (Explain Altered IX in #42) Moved	Southwes
9 Coordinates UTM Lat.	if known	37. Condition Interior Exterior good	п
Long.  Site 1: Structu Building 1x Obje	25. Open to Yes King Public? No II	38. Preservation Yes Underway? No X 39. Endangered? Yes I	Boulevard
11. On National Yes II 12 Is It Y	es X. Landmarks Commission of KC. 27. Other Surveys in Which Included	By What? No IX	rd

42. Further Description of Important Features The main facade faces north. The entrance is located at the west end of this facade. An overhead garage door and display windows extend across the remainder of the facade. Metal spandrels are placed above these openings. The parapet peaks near the center. An addition was placed at the rear of the building in 1926.

43 History and Significance The earliest known firm to occupy this building (1901) was the Weber Wagon Company. By 1907 the name of the business had been changed to the Weber Buggy Company. By 1915 the name was changed again, to the L.S. Weber Auto Company.

44. Description of Environment and Outbuildings Vacant land is south of this building. To the north, east, and west are other commercial buildings.

45 Sources of Information WP#6129 BP#84514

13 Part of Estab. Yes ! !

No IX

15. Name of Established District

Hist. Dist.?

District

Potent'l?

Yesx

No :

46. Prepared by PILAND 47. Organization Landmarks Commission 48. Date 49. Revision Date(s)

5/1/85

40. Visible from

Public Road? 41. Distance from and



JA-AS-008-1403

49. Revision Date(s)

48. Date 5/1/85

HISTORIC INVENTORY

1 No

4. Present Name(s)





2/14/85



Distance from and

Frontage on Road

128 feet on Southwest H

lvd.

lumbia, Missouri 65201

HISTO	DRIC IM	VENTORY	TA-AS-008-1406	
1. No. 99-E 2. County		sent Name(s) chifman Printing Company		99-
		her Name(s)		E
6. Specific Location		16. Thematic Category	28. No of Stories 2 29. Basement? Yes lx	Jac
500-10 Southwest Boulevard		17 Date(s) or Period . 1959-60 18 Style or Design	30. Foundation Material	Jackson
7 City or Town If Rural, Township & Vicinity Kansas City, Missouri  8. Site Plan with North Arrow		19. Architect or Engineer  Kivett & Myers 20. Contractor or Builder	31. Wall Construction  prob. steel frame  32. Roof Type & Material flat; tar & gravel	OUTCOMPRISED IN
Bourn west B	wo \	Universal Const. Co. 21. Original Use, if apparent	33. No. of Bays Front Side  34. Wall Treatment	500-
I vest		22 Present Use commercial	glass; concrete block 35. Plan Shape rectangular	4 4
South		23 Ownership Public ! Private **	36. Changes Addition : (Explain Altered I' Moved I	Sout
9 Coordinates UTM		24. Owner's Name & Address, if known	37. Condition Interior good	Southwest B
Long.	Structure I	25. Open to Yes 1x Public? No 11	38. Preservation Yes Underway? No XX	Bouleva
Building ki	Object ! !	26. Local Contact Person or Organization Landmarks Commission	39. Endangered? Yes   No XX	vard
	District Yes	27. Other Surveys in Which Included	40. Visible from Yes XX	

42. Further Description of Important Features Decorative concrete block work forms a screen over the rsised basement level of this building. The upper floor is veneered with glass. The entrance is at the east end of the south facade. At the west end is a garage entrance.

43. History and Significance This building was first occupied by the Gerson Company, wholesale jewelers.

44. Description of Environment and Outbuildings A surface parking lot is north of this building. Other commercial buildings are to the south and west. A small traffic island is to the west.

45 Sources of Information

15. Name of Established District

WP #55933

BP #19015

46. Prepared by Piland 47. Organization Landmarks Commission 48. Date 49 Revision Date(s)

9/23/82



48. Date

2/6/84

49. Revision Date(s)





Landmarks Commission

49. Revision Date(s)

48. Date

10/21/81



48. Date

9/28/81

49. Revision Date(s)



WP #11231

BP #12689

Piland

48. Date 7/7/83

47. Organization

Landmarks Commission

49. Revision Date(s)



Brick corbelling marks the parapet wall.

43. History and Significance The original occupant of this commercial building was the Littick Brothers Grocery. In 1906 it was occupied by James V. Lasson and Company, a grocery firm.

44. Description of Environment and Outbuildings Other commercial buildings are to the north, south, east and west of this structure.

45 Sources of Information WP #24832

46. Prepared by Piland 47. Organization Landmarks Commission

49. Revision Date(s) 48. Date 11/28/83



00 p	4. Pres	sent Name(s)		
99-B 2 County Cro		own Tire and Alignment Co.		
Jackson		er Name(s)		
3 Location of Neuraliune MT #55-7		uthwest Texaco Filling Station		
Specific Location		16. Thematic Category	28. No. of Stories 1	
520 Southwest Boulevard			29. Basement? Yes	
J20 Bouthwest Bou	revaru	17. Date(s) or Period	No IX	
		1949 18 Style or Design	30. Foundation Material	
7 City or Town If Rural, Township & Vicinity Kansas City, Missouri		18. Style or Design	concrete 31. Wall Construction	
8. Site Plan with North Arrow		19. Architect or Engineer	concrete block	
			32. Roof Type & Material	
	- 19	20. Contractor or Builder Park Construction Co.	flat; tar & gravel 33. No. of Bays	
	2102	21. Original Use, if apparent	Front 5 Side 3	
Southwest	- Du	_service station	34. Wall Treatment	
TWES.		22. Present Use	metal	
South	1	service station  23 Ownership Public	35. Plan Shape rectangular 36. Changes Addition:	
		Private IX	(Explain Altered I	
		24. Owner's Name & Address,	in #42) Moved	
		if known	37. Condition Interior	
Coordinates	ИТМ		Exterior good	
Long		25. Open to Yes IX	38. Preservation Yes	
Site!;	Structure 1	Public? No 11	Underway? Noxix	
Building XI	Object	26. Local Contact Person or Organization	39. Endangered? Yes III	
On National Yes 11	12 Is It Yes	Landmarks Commission	- Dy Hinai.	
	Eligible? No X	27 Other Surveys in Which Included		
Register? No X:	14 District Yes	27. Other Surveys in Which Included	40. Visible from YesXX	
Register? No X:		27. Other Surveys in Which Included	Public Road? No 11	
Register? No X:  Part of Estab. Yes     Hist. Dist.? No X	14 District Yes   Potent'l? No x	27. Other Surveys in Which Included	Public Road? No 11	
Register? No X!  Part of Estab. Yes      Hist. Dist.? No X!  Name of Established D	14 District Yes   Potent'l? No ½		Public Road? No i i  41. Distance from and Frontage on Road  58 feet on Southwest I	
Part of Estab. Yes     Hist. Dist.? No x   Name of Established D  Further Description of the west end of	14 District Yes   Potent'1? No 1/2. District	27. Other Surveys in Which Included  ne main facade faces south. A glas To the east are two garage bays. M	Public Road? No ii  41. Distance from and Frontage on Road  58 feet on Southwest I walled office area is	
Part of Estab. Yes     Hist. Dist.? No x    Name of Established D  Further Description of the west end of building.  History and Significance erected in 1917.	District Yes Potent'1? No X District  Important Features The the building. This service This building of the buildings	ne main facade faces south. A glass to the east are two garage bays. Me station replaced an earlier one on riginally housed the Southwest Texas	Public Road? No::  41. Distance from and Frontage on Road  58 feet on Southwest It is walled office area is letal panels veneer the letal panels veneer the letal station.	
Part of Estab. Yes     Hist. Dist.? No x    Name of Established D  Further Description of the west end of building.  History and Significance erected in 1917.  Description of Environment aructure. To the	Important Features The building. This building of the buildings west is an inter-	ne main facade faces south. A glass to the east are two garage bays. Me station replaced an earlier one on riginally housed the Southwest Texas	Public Road? No::  41. Distance from and Frontage on Road  58 feet on Southwest I is walled office area is letal panels veneer the item that had been area Station.	
Part of Estab. Yes     Hist. Dist.? No x    Name of Established D  Further Description of the west end of building.  History and Significance erected in 1917.  Description of Environment ructure. To the	Important Features The building. This building of the buildings west is an inter-	ne main facade faces south. A glass to the east are two garage bays. Me station replaced an earlier one on riginally housed the Southwest Texas	Public Road? No::  41. Distance from and Frontage on Road  58 feet on Southwest I is walled office area is letal panels veneer the interest of the site that had been accompanied by the station.  46. Prepared by	
Part of Estab. Yes     Hist. Dist.? No x    Name of Established D  Further Description of the west end of building.  History and Significance erected in 1917.  Description of Environment aructure. To the Sources of Information P #59134	Important Features The building. This building of the buildings west is an inter-	ne main facade faces south. A glass to the east are two garage bays. Me station replaced an earlier one on riginally housed the Southwest Texas	Public Road? No::  41. Distance from and Frontage on Road  58 feet on Southwest I is walled office area is letal panels veneer the item that had been area Station.	
Part of Estab. Yes     Hist. Dist.? No x   Name of Established D  Further Description of the west end of building.  History and Significance erected in 1917.  Description of Environmentation.	Important Features The building. This building of the buildings west is an inter-	ne main facade faces south. A glass to the east are two garage bays. Me station replaced an earlier one on riginally housed the Southwest Texas	Public Road? No:  41. Distance from and Frontage on Road  58 feet on Southwest I is walled office area is letal panels veneer the letal panels veneer the letal panels veneer the letal panels that had been letal panels of this station is to the north.  46. Prepared by Piland	



49. Revision Date(s)

48. Date 4 11/17/82



47. Organization

12/17/8

Landmarks Commission
48. Date 49. Revision Date(s)

Kansas City Architect and Builder,

Nov.1902, p.24



49. Revision Date(s)

48. Date 10/27/82



Landmarks Commission

49. Revision Date(s)

48. Date

10/28/82



HISTORIC INVENTORY 1. No. 4. Present Name(s) 48-A 48-A Husar Industries Inc. 2 County 5 Other Name(s) Jackson Location of Negatives MT #25-16 Landmarks Commission 6 Specific Location 16. Thematic Category 28. No. of Stories ackson 1620 Troost 29. Basement? Yes County 17 Date(s) or Period No 1978 30. Foundation Material 7. City or Town - II Rural, Township & Vicinity Kansas City, Missouri 18. Style or Design 31. Wall Construction B. Site Plan with North Arrow 19 Architect or Engineer steel frame 32. Roof Type & Material Manuel Morris flat; tar & gravel 20. Contractor or Builder 33. No. of Bays A.L. Huber, Jr. 4 Front Side 21. Original Use, if apparent Present 1620 34. Wall Treatment commercial concrete 22 Present Use 35. Plan Shape Name(s) commercial rectangular Troost 23 Ownership Public 1 36. Changes Addition : Private 1x (Explain Altered I in #42) Moved I 24. Owner's Name & Address, if known 37. Condition Interior 9 Coordinates UTM Exterior Lat. excellent. Long Yes X 25. Open to 38. Preservation Yes Public? Noxx Noil Underway? Site! Structure | Building ! Object | | 26. Local Contact Person or Organization Endangered? Yes No XX By What? Landmarks Commission 11. On National Yes 12 Is It Yes ! Eligible? NoXX Register? No I 27. Other Surveys in Which Included District Yes 13. Part of Estab. Yes !! Visible from Yes XX No X Hist. Dist ? No to Potent'1? Public Road? No I Distance from and 15. Name of Established District Frontage on Road 42 Further Description of Important Features The building is constructed of precast concrete "T's". south facade contains an entrance and a loading dock. The building contains 30,000 square feet. 43. History and Significance This \$325,000 building is part of the Downtown East Industrial Park. It was constructed by Husar Industries, Inc. as a truck and bus transmission reconditioning plant. Surface parking lots are north and south of this 44. Description of Environment and Outbuildings building. A commercial building is to the east. Vacant land is to the west. 46. Prepared by 45 Sources of Information WP #24515 Piland BP #86799 47. Organization Kansas City Star, Feb. 12, 1978. Landmarks Commission 48. Date 49. Revision Date(s) 3/24/82

State Historical Survey and Planning Office, 909 University Avenue, Suite 215,

lumbia, Missouri 65201



State Historical Survey and Planning Office, 909 University Avenue, Suite 215,

lumbia, Missouri 65201



Columbia, Missouri 65201

2/16/82



State Historical Survey and Planning Office, 303 University Avenue, Survey

County

Landmarks Commission

49. Revision Date(s)

48. Date

9/11/81



State Historical Su y	and Planning Office,	909 Uni	
LUCTODIC IN	VENITODY		-Columbia, Missouri (
HISTORIC IN	VENTORI		TA-AS-008-

4. Present Name(s)	320 Troost ner Name(s)	
5 Other Name(s) Kraft Laundry Company		
16. Thematic Category 17. Date(s) or Period 1915 Vicinity 18. Style or Design  19. Architect or Engineer 20. Contractor or Builder N. S. Weeks (K.C. Kan) 21. Original Use, if apparent 22. Present Use vacant 23. Ownership Public 11 PrivateXX  24. Owner's Name & Address,	36. Changes (Explain Altered XX in #42) Moved i  37. Condition Interior Exterior good  38. Preservation Yes i	oost
25. Open to Yes 11		
ject 11 26. Local Contact Person or Organization YesXX Landmarks Commission	39. Endangered? Yes I No IXX	
Yes XX No 1:	40. Visible from Public Road? No ::  41. Distance from and Frontage on Road  50. feet on Troost	1
֡֡֜֜֜֜֜֜֜֜֜֜֜֜֜֜֜֜֜֜֜֜֜֜֜֜֜֜֜֜֜֜֜֜֜֜֜	5 Other Name(s) Kraft Laundry Company  16. Thematic Category 17. Date(s) or Period 1915  Vicinity 18. Style or Design  20. Contractor or Builder N. S. Weeks (K.C. Kan)  21. Original Use, if apparent Commercial 22 Present Use vacant 23 Ownership Public   PrivateXX  24. Owner's Name & Address, if known  25. Open to Public? VesXX No   PesXX Pes	1820 Troost   1   18   19   19   19   19   19   19

two bay elevation contains storefront windows flanking a central entrance door. The store front at the south end of the building has been filled with concrete blocks. The parapet wall is stepped and terminates in stone coping.

43. History and Significance A laundry company was the original tenant of this building. The building was constructed at a cost of \$5,000.

44. Description of Environment and Outbuildings Other commercial buildings are north, east, and west of this structure. To the south is a small surface parking area.

45 Sources of Information

WP# 55885 BP #11423

Western Contractor, March 17, 1915, p. 27.

46, Prepared by Piland / Uguccioni

47. Organization

Landmarks Commission

1/5/82

48. Date 49. Revision Date(s)



extending across the facade. A doorway, and window areas have been bricked in. Some of the windows still possess stone sills. A decorative cornice projects and features "Gothic-inspire bracketes at the corners. The cornice extends in a semicircular sunburst motif and is inscribed "1886."

43. History and Significance The building, originally a residence, was constructed for August Koehler at a cost of \$7,000. Although the building permit was issued for a "residence", the size and configuration of the building indicates that perhaps it was a multifamily residence.

44. Description of Environment and Outbuildings A storage lot is south and west of this building. A commercial building is to the north. To the east is another storage lot.

45 Sources of Information WP #7847 Kansas City Star, April 9, 1888, p. 1.

1. No.

2 County Jackson

> Lat. Long

Register?

10

46. Prepared by Uguccioni

47. Organization Landmarks Commission

48. Date 49. Revision Date(s) 2/9/84



BP #47435

BP #55074

Kansas City, Its Resources and Their Development

47. Organization

2/14/84

Landmarks Commission

48. Date 49. Revision Date(s)



ming diffice, 303 onitectates

HISTORIC

Columbia, Missouri 65201

2/24/82

vince indine(5.



24 Troost	*	115-
r Name(s) entered		Đ
16. Thernatic Category	28. No. of Stories 1	J.
17. Date(s) or Period	29. Basement? Yes I	County
1948	30. Foundation Material	SOI
18. Style or Design		- 1
	31. Wall Construction	
19. Architect or Engineer	concrete block	
20. Contractor or Builder	32. Roof Type & Material flat; tar & gravel	
	33. No. of Bays Front 5 Side	4
21. Original Use, if apparent	34. Wall Treatment	Prese 2224
commercial 22 Present Use	brick	4 sen
vacant	35. Plan Shape rectangular	Troos
23 Ownership Public 11 Private 😾	36. Changes Addition : (Explain Altered )	Present Name(s) 224 Troost
24. Owner's Name & Address,	in #42) Moved	
if known	37. Condition Interior Exterior good	
25. Open to Yes II No I x	38. Preservation Yes ( Underway? No iX	
26. Local Contact Person or Organization Landmarks Commission	39. Endangered? Yes III No IX	
27. Other Surveys in Which Included	40. Visible from Yes!X Public Road? No!	

Columbia, Missouri 65201

TA-AS-008-

41. Distance from and 15. Name of Established District Frontage on Road 31 feet on Troost 42. Further Description of Important Features Brick veneer is applied to the east facade which fronts on Troost. A central entrance door is flanked by paired windows on either side. Brick laid in soldier course runs across the tops of the windows. The building terminates in stone

State Historical Survey and Planning Office, 909 University Avenue, Suite 215

4. Present Name(s)

5. Other Name(s)

2224 Troost

Structure !

Potent'l? No XX

Object | |

Yes!

Yes

Noxx

HISTORIC

City or Town If Aural, Township & Vicinity Kansas City, Missouri

UTM

12 Is It

Eligible?

14. District

MT #66-14

115-D

6. Specific Location

2224 Troost

3 Location of Negatives A Landmarks Commission

B. Site Plan with North Arrow

TROOST

Site ! :

Yes

Noxx

Noxx

Building |

2 County

Jackson

9. Coordinates

11. On National

Register?

coping.

Hist. Dist.?

13. Part of Estab. Yes 11

Lat. Long

43. History and Significance This building appears to have been erected in 1948 as an addition to a building that set further back on the lot. Only the addition still exists. The building was erected for the Ever-Ready Plumbing and Heating Co.

44. Description of Environment and Outbuildings To the west, at the rear of the property, is a detached, 2-car, concrete block garage. Vacant land is to the north and south. A vacant lot is to the east.

45 Sources of Information

WP #7306 BP #24950A

46. Prepared by Piland /Uguccioni

47. Organization Landmarks Commission

49. Revision Date(s) 48. Date

7/18/84



columbia, Missouri 65201 HISTORIC INVENTORY A-AS-008-1. No. 4. Present Name(s) 126-B 2300 Troost A venue House 2. County 5 Other Name(s) Jackson 3 Location of Negatives MT #76-1 Nathaniel J. Powell Residence; 2302 Troost Landmarks Commission 16. Themalic Category 6. Specific Location 030 2300 Troost Au 17. Date(s) or Period 1913 c. 1883 7 City or Town - If Rural, Township & Vicinity 18. Style or Design Kansas City, Missouri B. Site Plan with North Arrow 19. Architect or Engineer 20. Contractor or Builder N. J. Powell (attrib) 21. Original Use, if apparent residence DIA 22. Present Use residence 23 Ownership 24. Owner's Name & Address, if known 37. Condition Interior 9. Coordinates UTM Exterior Lat. fair. Long 25. Open to Yes Preservation Yes No L Public? Noix Underway? 10. Site!: Structure Building 1 Object 11 26. Local Contact Person or Organization 39. Endangered? Yes Nolx Landmarks Commission By What? Yes 11. On National 12 Is It Yes X Eligible? No !! Register? No to! 27. Other Surveys in Which Included Yes x 13. Part of Estab. Yes ! ! 14. District 40. Visible from Yes! X Potent'l? Hist. Dist.? No LI No : Public Road? No ! 41. Distance from andapprox. 15. Name of Established District Frontage on Road 40 feet on Troost 42. Further Description of Important Features A porch resting on a brick base wraps around the east and north facades. Brick piers support the shed roof of the porch. The building's mass projects forward on the east end. Segmental arch windows with radiating brick voussoirs fenestrate the second story. A bracketed cornice supports a gable roof. The north and south ends of the building's mass bisect and extend beyond the east/west axis, creating the Greek cross plan. A kitchen and sleeeping porch were added in 1913.

State Historical Su y and Planning Office, 909 Univ sity Avenue, Suite 215,

In 1884 the city directories list a Nathaniel J. Powell living at 43. History and Significance 2302 Troost. The year prior to this Powell's occupation was listed as a brick mason, and he may have constructed this residence. The Powell's continue to be listed at 2302 Troost through 1888.

44. Description of Environment and Outbuildings Vacant land is north of this building. To the south is an apartment building. A commercial building is to the west. A commercial building is also to the east.

## 45 Sources of Information

WP #7046

BP #88740

BP #5530

46. Prepared by Uguccioni

47. Organization

Landmarks Commission 49. Revision Date(s) 48. Date

3/1/82



torical survey and Flamming Office, 303 oniversity

Columbia, Missouri 65201



BP #3729

COURTY

Present Namers)

Chirci Halliele

Landmarks Commission

49 Revision Date(s)

48. Date

6/5/84



1. No.	4. Pres	ent Name(s)	TA-A5-008-1	
126-I		2326 Troost enterel		
2 County Jackson	5 Oth	er Name(s)		
Location of Negatives Landmarks Commissi	MT #66-16 on	Cascade Apartments; 2324-28 Troo	st	
Specific Location	-	16. Thematic Category	28. No. of Stories	1
2326 Troost		17. Date(s) or Period	29. Basement?	Yes k
		1904 (alt. 1975)	30. Foundation Material	NO I
City or Town II Aura Kansas City, Misso	I, Township & Vicinity	18. Style or Design	So. 1 oundation material	1
			31. Wall Construction	
3. Site Plan with North Arre	ow	19. Architect or Engineer	masonry  32. Roof Type & Material	
*		20. Contractor or Builder	flat; tar & gray	
342St			33. No. of Bays Front 5 Side	
18	$\stackrel{>}{\longrightarrow}$	21. Original Use, if apparent apartments	Front 5 Side  34. Wall Treatment	
ts t	$\rightarrow$	22 Present Use	brick	- 1
TROOST	+	vacant	35. Plan Shaperectangu	ılar
		23 Ownership Public   Private   12		ular
		24. Owner's Name & Address,	The state of the s	loved i
		if known	37. Condition	
Coordinates U	TM		Exterior good	
Long		25. Open to Yes Li	38. Preservation	Yes
O. Site !:	Structure	Public? , No 1/x	Underway?	Noxx
Building k	Object	26. Local Contact Person or Organization	39. Endangered? By What?	Yes III
1. On National Yes   Register? No K!	12 Is It Yes Ik	Landmarks Commission 27. Other Surveys in Which Included	- by what?	NOT
3. Part of Estab. Yes II	14. District Yes!. Potent'l? No x	27. Other Surveys in Which included	40. Visible from	Yes XX
Hist. Dist.? No x			Public Road?	No
is. Name of Established Dis	Strict		Frontage on Road	
			53 feet on Troost	
	r two floors. The	s building was substantially alter e remaining openings have been boa ade.		
3. History and Significance	This was origina	ally a three-story apartment build	ing.	
o. motory one organism				3
				1
				resi-
		Vacant land is north and south of and is to the west.	this structure. A	resi-
	,			00
5 Sources of Information			46. Prepared by	
WP #24603 BP#16784A			Piland	
22 / 20 / 07/1			47. Organization Landmarks Commiss:	ion
			48. Date 49. Revision D	
			1/28/85	



43. History and Significance Lipsey's Grocery was the first tenant of this building and was still operating in 1957.

44. Description of Environment and Outbuildings Residences are west of this building. To the south is a commercial building. Vacant land is north of this building. To the east is a residence.

45 Sources of Information BP #15978; 17277A

WP #6404

1. No.

2. County

Long

10.

Jackson

46. Prepared by Piland /Uguccioni

47. Organization

Landmarks Commission 48. Date 49. Revision Date(s)

4/13/84



1. No. 137-R	4. Pres	sent Name(s)	SA-AS-008-1431	
3 County	2450	Troost		_ 3
Jackson 5. Othe		er Name(s)		37-R
3 Location of Negatives Mi Landmarks Commissio	n of KC	Spruce Garage; Jones Auto Serv	ice Company Buddens	-R
6 Specific Location		16. Thematic Category	28. No. of Stories 1	J
2450 Troost		030 050 240 17 Date(s) or Period .	29. Basement? Yes I	Jackson
7.00		1926	30. Foundation Material	on
7 City or Town If Rural Kansas City, M		Spanish Colonial 55 69	31. Wall Construction	
8. Site Plan with North Arro		19. Architect or Engineer	masonry UD	
	M	20. Contractor or Builder	32. Roof Type & Malerial varied & PR	
	11	Barney Tanhoff	33. No. of Bays	
	b	21. Original Use, if apparent	Front 3 Side	24
	500	commercial DDE 16A  22. Present Use	34. Wall Treatment	50
	2	storage	brick 30 35. Plan Shape rectangular	2450 Troost
	*	23 Ownership Public !!	36. Changes Addition :	Troost
	1-	Private xx  24. Owner's Name & Address.	(Explain Altered I I in #42) Moved I	t s
		if known	37. Condition	
9 Coordinates U'	тм		Interior good	
Long.	Structure	25. Open to Yes	38. Preservation Yes : Underway? No x	
Building X	Object	26. Local Contact Person or Organization	39. Endangered? Yes !	
1. On National Yes 1: Register? No IX	12 Is It Yes X Eligible? No	Landmarks Commission of KC 27. Other Surveys in Which Included	By What? No 😿	
3 Part of Estab Yes     Hist. Dist.? No bd	14. District Yes X Potent'l? No		40. Visible from Yes X Public Road? No 1:	
15. Name of Established Dis	trict		41. Distance from and	
			Frontage on Road 50 Feet on Troost Ave.	
door is centrally lo	cated. The flank	main facade of this building faces king window areas have been covered jects above the garage door.	east. An overhead garage over. A curvilinear	Spruce Garage;
13. History and Significance	The first tenant	of this building was the Jones Au	to Service Company.	Jo
		the building was occupied by the Sp		Jones
				100
				Auto
14. Description of Environme	nt and Outbuildings	A commercial building is north of t	his structure. To the	Sei
south is a storage service station.	lot. Residence	es are to the west. To the east is	the surfaced lot of a	Service
5 Sources of Information			46. Prepared by	Co.
BP #14793	0	1026 - 26	PILAND  47. Organization	
Western Contractor	, september 8,	1920, p. 30	Landmarks Commission	
			48. Date 49. Revision Date(s)	



	0
ALC: UNKNOWN	- dalle
-	6

137-N	10,007	sent Name(s)	
2. County	2454	2454-56 Troost (& 1010-22 East 25th Street)	
Jackson Location of Negatives MT Landmarks Commission	#96-13	er Name(s) other nance	-
Specific Location		16. Thematic Category	28. No. of Stories 1
2454-56 Troost		17. Date(s) or Period	29. Basement? Yes I
(& 1010-22 East 25t)	h Street)	1923	30. Foundation Material
City or Town If Rural, T Kansas City, Missour	ownship & Vicinity	18. Style or Design	0
Site Plan with North Arrow	-	19. Architect or Engineer	31. Wall Construction masonry
_	W	OD Control of Building	32. Roof Type & Material +
1	News The	20. Contractor or Builder	flat; gar and gravel
	3	21. Original Use, if apparent Porch	Front Side
	8	commercial OSE e1	34. Wall Treatment brick 30 .
		commercial	35. Plan Shape L
E. 25 7 51	-	23 Ownership Public   Private k	36. Changes Addition 1: (Explain Altered &
		24. Owner's Name & Address,	in #42) Moved i
Coordinates UTM		ii known	37. Condition Interior
Lat.			Exterior poor
Long Site !:	Structure 1	25. Open to Yes Xi Public? No	38. Preservation Yes Underway? No x
Building Ix	Object	26. Local Contact Person or Organization	39. Endangered? Yes ⊠
1 On National Yes 1 12 Register? No IX	2 Is It Yes :X Eligible? No ::	Landmarks Commission	By What? No!: poss. demolition
Control of the second s	4. District Yes ix	27. Other Surveys in Which Included	40. Visible from Yes !X
Hist. Dist.? No IX	Potent'l? No :		Public Road? No 11
5. Name of Established Distric	ct		41. Distance from and Frontage on Road
		main facades of this corner build	42 feet on Troost
	oors along the	south facade have been closed. T	ne primary entrance is at
he southeast corner o	f the building	. A display window extends along t	
he southeast corner of the sou	This commercial and Outbuildings al structure.	A storage lot is north of this but A vacant service station is to the for commercial purposes.	e store rooms.
A. Description of Environment is another commercia an apartment building	This commercial and Outbuildings al structure.	A storage lot is north of this bu	e store rooms.  dilding. To the south e east. To the west is
4. Description of Environment is another commercia an apartment buildin WP #71478	This commercial and Outbuildings al structure.	A storage lot is north of this bu A vacant service station is to the	e store rooms.  Alliding. To the south e east. To the west is  46. Prepared by Piland
A. Description of Environment is another commercia an apartment building.  Sources of Information	This commercial and Outbuildings al structure.	A storage lot is north of this bu A vacant service station is to the	e store rooms.  dilding. To the south e east. To the west is



0
5
ē
*
2
2
ē
5

12/26/84

1. No. 151-J		and the second s	. Present Name(s)	
25		2500-02 Troost Avenu Building		
Jackson	5. Off	ner Name(s)		
3 Location of Negatives MT Landmarks Commission	#108-20 n of KC			
6. Specific Location		16. Thematic Calegory	28. No. of Stories 1	
2500-02 Troost		030 050	29. Basement? Yes !	
2500-02 1100SL		17. Date(s) or Period .	No i	
City or Town - If Rural,	Township & Vicinity	1910 18. Style or Design	30. Foundation Material	
Kansas City, Mi		50 63	31. Wall Construction	
. Site Plan with North Arro		19. Architect or Engineer	masonry Ltb	
1 £ 25th	Sr	20. Contractor or Builder	32. Roof Type & Material T	
A I	-11	Fred Roux	33. No. of Bays 99	
11	15,	21. Original Use, if apparent	From Side	
1	Koost	commercial ODE DD RIEL  22. Present Use	34. Wall Treatment brick 30	
	1	vacant	35. Plan Shape rectangular	
7		23 Ownership Public !!	36. Changes Addition i:	
		Private 1x	(Explain Altered 1: in #42) Moved i	
		if known	37. Condition	
Coordinates UT	М		Interior	
Lat. Long.			Exterior-fair	
Site ! :	Structure 1	25. Open to Yes 1: No   Yes 1:	38. Preservation Yes : No i X	
Building &	Object ! !	26. Local Contact Person or Organization	39. Endangered? Yes 1 ½	
On National Yes	12 Is It Yes !: Eligible? No !!	Landmarks Commission of KC	By What? No :	
	14. District Yes	27. Other Surveys in Which Included	40. Visible from Yes! X	
	Potent'l? No :		Public Road? No 11	
Hist. Dist.? No ½1		4		
Hist. Dist.? No ½1			41. Distance from and	
Hist. Dist.? No ½1			41. Distance from and Frontage on Road	
Hist. Dist.? No ½1  5. Name of Established Dist	rict	main facade of this corner building	41. Distance from and Frontage on Road 50 feet on Troost	
Hist. Dist.? No ½!  5. Name of Established Dist  6. Further Description of Im-  1. Invided into two sto	portant Features The	cessed entrance is placed centrally	41. Distance from and Frontage on Road  50 feet on Troost  ng faces east and is in the south store	
Hist. Dist.? No ½!  5. Name of Established Dist  7. Further Description of Im-  ivided into two sto  ront. The north sto	portant Features The re fronts. A re re front has a		41. Distance from and Frontage on Road  50 feet on Troost  ng faces east and is in the south store	
Hist. Dist.? No ½!  5. Name of Established Dist  7. Further Description of Im-  ivided into two sto  ront. The north sto	portant Features The re fronts. A re re front has a	cessed entrance is placed centrally	41. Distance from and Frontage on Road  50 feet on Troost  ng faces east and is in the south store	
Hist. Dist.? No ½!  5. Name of Established Dist  7. Further Description of Im-  ivided into two sto  ront. The north sto	portant Features The re fronts. A re re front has a	cessed entrance is placed centrally	41. Distance from and Frontage on Road  50 feet on Troost  ng faces east and is in the south store	
Hist. Dist.? No ½!  5. Name of Established Dist  2. Further Description of Im  Livided into two sto	portant Features The re fronts. A re re front has a	cessed entrance is placed centrally	41. Distance from and Frontage on Road  50 feet on Troost  ng faces east and is in the south store	
Hist. Dist.? No ½!  5. Name of Established Dist  2. Further Description of Im  Livided into two sto  ront. The north sto  ave been boarded ov	portant Features The re fronts. A re re front has a er.	cessed entrance is placed centrally canted entrance at the northeast co	41. Distance from and Frontage on Road 50 feet on Troost ag faces east and is in the south store orner. The window areas	
Hist. Dist.? No ½!  Name of Established Dist  Further Description of Imivided into two storont. The north storont been boarded ov	portant Features The re fronts. A re re front has a er.	cessed entrance is placed centrally	41. Distance from and Frontage on Road 50 feet on Troost ag faces east and is in the south store orner. The window areas	
History and Significance	portant Features The re fronts. A re re front has a er.	cessed entrance is placed centrally canted entrance at the northeast co	41. Distance from and Frontage on Road 50 feet on Troost ag faces east and is in the south store orner. The window areas	
History and Significance	portant Features The re fronts. A re re front has a er.	cessed entrance is placed centrally canted entrance at the northeast co	41. Distance from and Frontage on Road 50 feet on Troost ag faces east and is in the south store orner. The window areas	
Hist. Dist.? No ½!  5. Name of Established Dist  6. Further Description of Im- divided into two sto front. The north sto ave been boarded ov  6. History and Significance Tore operated by Ca	portant Features The re fronts. A re re front has a er.  his building or roline Hirsch.	cessed entrance is placed centrally canted entrance at the northeast co	41. Distance from and Frontage on Road 50 feet on Troost ag faces east and is in the south store orner. The window areas store and a grocery	
Hist. Dist.? No ½!  Name of Established Dist  Further Description of Imivided into two storont. The north storont ave been boarded ov  History and Significance to the operated by Ca	portant Features The re fronts. A re re front has a er.  his building or roline Hirsch.	cessed entrance is placed centrally canted entrance at the northeast continuation of the continuation of t	41. Distance from and Frontage on Road 50 feet on Troost ag faces east and is in the south store orner. The window areas store and a grocery	
History and Significance Tore operated by Ca	portant Features The re fronts. A re re front has a er.  his building or roline Hirsch.	cessed entrance is placed centrally canted entrance at the northeast co	41. Distance from and Frontage on Road 50 feet on Troost ag faces east and is in the south store orner. The window areas store and a grocery	
Name of Established Dist  Further Description of Imivided into two storont. The north storave been boarded ov  History and Significance tore operated by Ca	portant Features The re fronts. A re re front has a er.  his building or roline Hirsch.	cessed entrance is placed centrally canted entrance at the northeast continuation of the continuation of t	41. Distance from and Frontage on Road 50 feet on Troost ag faces east and is in the south store orner. The window areas store and a grocery	
History and Significance Tore operated by Ca	portant Features The re fronts. A re re front has a er.  his building or roline Hirsch.	cessed entrance is placed centrally canted entrance at the northeast continuation of the continuation of t	41. Distance from and Frontage on Road 50 feet on Troost ag faces east and is in the south store orner. The window areas store and a grocery	
Name of Established Dist  Further Description of Imivided into two storont. The north storont been boarded over the store operated by Carter opera	portant Features The re fronts. A re re front has a er.  his building or roline Hirsch.	cessed entrance is placed centrally canted entrance at the northeast continuation of the continuation of t	41. Distance from and Frontage on Road 50 feet on Troost  Ing faces east and is in the south store orner. The window areas  store and a grocery  ding. Commercial build-  46. Prepared by PILAND	
History and Significance Torre operated by Ca	portant Features The re fronts. A re re front has a er.  his building or roline Hirsch.	cessed entrance is placed centrally canted entrance at the northeast continuation of the continuation of t	41. Distance from and Frontage on Road 50 feet on Troost ag faces east and is in the south store orner. The window areas  store and a grocery  ding. Commercial build-	



INVENTORY HISTORIC No 4. Present Name(s) 163-F not 2. County 2618 Troost Jack son 5 Other Name(s) 3 Location of Negatives MT #75-16 Norman Paint & Supply Co./Community Plumbing Co. Landmarks Commission 6. Specific Location 16. Thematic Category lackson 2618 Troost 17. Date(s) or Period 1959 7 City or Town If Rural, Township & Vicinity 18. Style or Design 31. Wall Construction Kansas City, Missouri 8. Site Plan with North Arrow 19. Architect or Engineer concrete block 32. Roof Type & Material Sam Price 20. Contractor or Builder flat; tar & gravel A.I. Morris Construction Co. 33. No. of Bays Front Side 21. Original Use, if apparent 34. Wall Treatment commercial 22. Present Use brick 35. Plan Shape storage rectangular 23 Ownership Public 11 36. Changes Addition 1 Private I Altered I (Explain in #42) Moved I 24. Owner's Name & Address. il known 37. Condition Interior 9. Coordinates UTM Exterior good Lat Long 25. Open to Yes ! Preservation Yes Public? No I Underway? Noix 10 Site ! : Structure | Building 1 Object ! ! 26. Local Contact Person or Organization 39. Endangered? Yes By What? Landmarks Commission Nolx 11. On National Yes! 12 Is It Yes Eligible? Register? No k! No x 27. Other Surveys in Which Included 13. Part of Estab. Yes !! Yes Yes | X District 40. Visible from Potent'l? Hist. Dist.? No to No x Public Road? No II 41. Distance from and 15. Name of Established District Frontage on Road 40 feet on Troost

State Historical Sur / and Planning Office, 909 Univ sity Avenue, Suite 215,

on the east facade. The building terminates in tile coping.

42. Further Description of Important Features Plate glass storefronts comprise the majority of wall surface

43. History and Significance The building was constructed for the Yarco Realty Company at a cost of \$11,000.

44. Description of Environment and Outbuildings A storage lot is south of this building. To the north is a surface parking lot. Vacant land is to the west. A commercial building is to the east.

45 Sources of Information WP #7311 BP #19017

46. Prepared by Uguccioni 47. Organization

Landmarks Commission 49. Revision Date(s) 48. Date

5/27/82



1. No. 163-E	4. Pres	ent Name(s)		16
2. County		2628 Troost		163-I
Jackson  3 Location of Negatives MT Landmarks Commission	#14-8	er Name(s)  e Chicken Inn		[4]
6. Specific Location	511	16. Thematic Category	28. No. of Stories 1	4
2628 Troost			29. Basement? Yes I	Jackson
2020 1100SL		17. Date(s) or Period	No I	ckson
7. City or Town - If Rural	Township & Vicinity	1951 18. Style or Design	30. Foundation Material	
Kansas City, Misson	ıri		31. Wall Construction	
I. Site Plan with North Arro	w ( )	19. Architect or Engineer	concrete block	
		20. Contractor or Builder	32. Roof Type & Material flat; tar & grave1	
	N		33. No. of Bays Front Side	
- S	1	21. Original Use, if apparent commercial	34. Wall Treatment	2628
6		22. Present Use	brick	2628
1		unknown	35. Plan Shape rectangula	Troos
		23 Ownership Public   Private x	36. Changes Addition 1: (Explain Altered 1:	Soc
		24. Owner's Name & Address,	in #42) Moved i	4
		if known	37. Condition Interior	
Coordinates U Lat.	тм		Exterior good	
Long.  Site!:	Structure	25. Open to Yes 1: Public? No ½	38. Preservation Yes : Underway? No k	
Building ly	Object 11	26. Local Contact Person or Organization	39. Endangered? Yes I	1
1. On National Yes     Register? No	12 Is It Yes I	Landmarks Commission	By What? No 🗽	1
Part of Estab. Yes 11 Hist. Dist.? No 12	14. District Yes Potent'l? No x	27. Other Surveys in Which Included	40. Visible from Yes X: Public Road? No iii	
5. Name of Established Dis	strict		41. Distance from and approx	1
4			Frontage on Road approx.  20 feet on Troost	1
2. Further Description of In	nportant Features The	east facade is veneered with bric		1
		ourse brick surround fenestrates t icked in) are placed at the north		
3. History and Significance	The building or	iginally housed a restaurant facil	ity.	1
43. History and Significance	The building or	iginally housed a restaurant facil	ity.	
. Description of Environmenthe east is a commen		Vacant land is north, south and we	st of this building. To	
and to a comme	vaaadangi			
5 Sources of Information WP #12112			46. Prepared by Uguccioni	
BP #17444			47. Organization	
			Landmarks Commission  48. Date 49. Revision Date(s)	
			10/2/81	



State Historical Survey and Flamming Unite, 303 University

MICHIGE



BP #14944

Kansas City Star, October 24, 1926, p. 1D

Western Contractor, March 2, 1927, p. 34

174-

Jackso

2700-06

Troost

(and

10

15

H

th

Street

47. Organization

6/4/84

Landmarks Commission

49 Revision Date(s)



		VENTORY	y Avenue, Suite 215, imbia, Missouri 65201	
1. No.	AND RESIDENCE OF THE PARTY OF T	sent Name(s)	17/3 000 1100	-
174-U 2 County	Ac	e Moving and Storage		174-
Jackson		er Name(s)		D-
3 Location of Negatives Landmarks Commiss	MT #75-15 BC	A Cleaners		
6 Specific Location	1011	16. Thematic Category	28. No of Stories 1-	J. 2
A page of the same			29. Basement? Yes I	Coack
2708 Troost Ane	nie Beilding	17 Date(s) or Period	No I .	2 County Jackson
	ral, Township & Vicinity	18 Style or Design	01	The state of the s
Kansas City, Miss B. Site Plan with North A		19. Architect or Engineer	31. Wall Construction	
	1		32. Roof Type & Material Ff	
	N	20. Contractor or Builder Pench	flat; tar & gravel 99	_
	N	21. Original Use, if apparent	Front Side	A P
		commercial DDE	34. Wall Treatment	2708 Tro
4		22 Present Use	brick 50	708
8		commercial 23 Ownership Public !	35. Plan Shape irregular 36. Changes Addition X	Nam S T
18		Private k	(Explain Altered I	Troos
15		24. Owner's Name & Address, if known	in #42) Moved i	st
9. Coordinates Lat.	UTM		Interior good	
Long.		25. Open to Yes II	Exterior good 38. Preservation Yes	
10. Site!:	Structure ! . Object ! !	Public? No 🎮	Underway? No ix	
11. On National Yes	12 Is It Yes	26. Local Contact Person or Organization Landmarks Commission	39. Endangered? Yes I No Ix	
Register? No x:	Eligible? No x:	27. Other Surveys in Which Included	40. Visible from Yes X	
Hist. Dist.? No 1	Potent'l? No x		Public Road? No 11	
15. Name of Established C	District		41. Distance from and Frontage on Road approx. 40 feet on Troost	
dows flank a centra A building permit	al entrance door. issued in 1964 in	e main facade of this building face In 1965 an addition was placed on dicates a 2nd floor was removed, al single story building.	the rear of the building.	BCA Cleaners
44. Description of Environment dences are to the state of	ment and Outbuildings west. Vacant lar	A commercial building is north of and is to the south. To the west is	this structure. Resi- a commercial building.	
WP #7172 BP #16724			Uguccioni 47. Organization	
BP #13996			Landmarks Commission	
BP#11808			48. Date 49. Revision Date(s)	
			3/26/84	

PACKING CRATING SHIPPING

DONOT

ACE MOVING STORAGE

483-5760 421-1676 STANCE

OFFICE HOUSEHOLD COMPUTERS

18

PILAND

48. Date

3/5/85

47. Organization

Landmarks Commission

49. Revision Date(s)

HISTORIC INVENTORY

Kansas City Star, November 4, 1923, p.2F

Western Contractor, July 18, 1923, p.36

BP#13702



BP #13724

Western Contractor, July 18, 1923, p. 36

Landmarks Commission

49. Revision Date(s)

48. Date

9/1/82



## HISTORIC INVENTORY JA-A5-008-1441 4. Present Name(s) 174-0 2 County Jackson 2734 Troost 5. Other Name(s) 3 Location of Negatives MT#109-8 Landmarks Commission of KC Jack Apartment - name 16. Thematic Category 6 Specific Location 28. No. of Stories 030 29. Basement? Yes IX 2734 Troost 17. Date(s) or Period 30. Foundation Material · If Rural, Township & Vicinity 18. Style or Design stone Kansas City, Missouri 31. Wall Construction Tapestry Brick 8. Site Plan with North Arrow 19. Architect or Engineer masonry LD 32. Roof Type & Material Nelle Peters 20. Contractor or Builder Other flat; tar & gravel 30 40 33. No. of Bays Ouality Builders Pnon Front-3 21. Original Use, if apparent apartment OIR 34. Wall Treatment brick 22. Present Use apartment 35. Plan Shape 36. Changes 23 Ownership Public ! ! Private k (Explain in #42) 24. Owner's Name & Address, if known 37. Condition 9. Coordinates UTM Long 25. Open to Yes II 38. Preservation Public? Underway? Nox Sile ! : Structure Building IX Object 11 26. Local Contact Person or Organization 39. Endangered? Yes By What? No to 11. On National Yes X Yesli 12 Is It Landmarks Commission of KC Eligible? Register? No IX No !! 27. Other Surveys in Which Included 14 District Yes IX 13 Part of Estab. Yes ! ! 40. Visible from Yes K No 1st Potent'l? No : Hist Dist ? Public Road? No ! : 41. Distance from and 15. Name of Established District Frontage on Road 39 ft. on Troost 42. Further Description of Important Features A hip roof porch supported by brick piers resting on an elevated base extends across the east facade. Stone banding enframes the windows of the second and third stories, and continues around to the secondary facades. Above a projecting cornice, the parapet wall is shaped and terminates in stone coping.

43. History and Significance One of 3 identical apartments in a row, constructed in 1923 by Quality Builders. Each structure was erected at a cost of \$70,000.

44. Description of Environment and Outbuildings A commercial building is south of this apartment. To the north is an identical apartment. A residence is to the west. A surface parking lot is to the east.

45 Sources of Information Kansas City Star, November 4, 1923, p.2F. BP#13725

46. Prepared by PILAND

47. Organization Landmarks Commission

49. Revision Date(s) 48. Date



	28. No. of Stories 1	Ja
	29. Basement? Yes X	2. Courty Jackson
	30. Foundation Material stone 40	n ty
l.a	31. Wall Construction masonry	
5	32. Roof Type & Material + PR flat; composition	
inch	33. No. of Bays Front Side 99	4
eı	34. Wall Treatment 30 hrick: stone 35. Plan Shaperectangular	Present Namers 2738-42 Ti
Public I ! Private XIX	36. Changes Addition : (Explain Altered I in #42) Moved I	ame(s)
	37. Condition Interior	
Yes XX	Exterior good  38. Preservation Yes	Aven

39. Endangered?

By What?

40. Visible from

Public Road?

Distance from and

Frontage on Road 45 feet on E. 28th St

Yes

No IX

Yes !X

No 11

Columbia, Missouri 65201

A-AG-(08-144)

4. Present Name(s) 174-V Big Hank's Liquors 2. County Jackson 5 Other Name(s) 3 Location of Negatives MT #14-7 Landmarks Commission 6 Specific Location 16. Thematic Category 050 030 2738-42 Troost Avenue Bulding 17. Date(s) or Period 1921 7 City or Town . If Rural, Township & Vicinity 18. Style or Design 50 Kansas City, Missouri B. Site Plan with North Arrow 19. Architect or Engineer 20. Contractor or Builder J. R. Van Sant Const. 21. Original Use, if apparent commercial ODF 22. Present Use commercial 23 Ownership 24. Owner's Name & Address, if known 9. Coordinates UTM Long 25. Open to Public? Underway? No No X 10. Site ! : Structure |

26. Local Contact Person or Organization

Landmarks Commission

27. Other Surveys in Which Included

State Historical Survey and Flaming Office, 303 oniversity Avenue, Suite 21.

42. Further Description of Important Features The building which fronts on both Troost Avenue and East 28th Street, has its main entrance placed at the corner. The facade has been altered with the addition of wood paneling over the store fronts. The building's east facade contains another entrance. The parapet wall is decorated with inset diamond shaped stone and the building terminates in stone coping.

- 43. History and Significance Built at a cost of \$10,000, the building was one of the extensive holdings of Porter T. Hall. Hall, in his career was director of the Emery, Bird, Thayer Company, and president of the Real Estate Board from 1927-1928. The building originally housed a cleaning establishment, a grocery and a drugstore.
- 44. Description of Environment and Outbuildings The building is located at the northwest corner of East 28th Street and Troost. To the north is an apartment building. To the east and south are commercial buildings. A surface parking area is to the west.

			970	Int	ormation				
В	P	#12	946						
K	an	sas	Cit	у	Star,	November	14,	1947.	

Building XX

15. Name of Established District

Yes

No XX

Noxx

11. On National

Register?

Hist. Dist.?

13 Part of Estab. Yes ! !

Object 11

12 Is It

Eligible?

District

Potent'l?

Yes XX

No I!

Yes XX

No !

HISTORIC

1. No

46. Prepared by Uguccioni 47. Organization Landmarks Commission 48. Date 49. Revision Date(s) 9/11/81



Columbia, Missouri 65201

8/30/84



5+-AS-008-1444

9/4/84

HISTORIC I VENTORY

4. Present Name(s)



	٠.	
	н	
-	ю	
-	э.	

Present Name(s)

ISTORIC INVENT 4. Present Name(s) 1. No. 186-N Nazarene Publishing House 2 County 5 Other Name(s) Jackson not 3 Location of Negatives MT #14-3 Landmarks Commission enterel Safeway Stores, Inc. 6 Specific Location 16. Thematic Category 28. No. of Stories Jackson 2832 Troost 29. Basement? Yes I 17. Date(s) or Period No I 1950 30. Foundation Material City or Town If Rural, Township & Vicinity Kansas City, Missouri 18. Style or Design 31. Wall Construction B. Site Plan with North Arrow 19. Architect or Engineer masonry 32. Roof Type & Material 20. Contractor or Builder truss; comp. 33. No. of Bays Front Side 21. Original Use, if apparent 28 34. Wall Treatment 22. Present Use brick Troost commercial 35. Plan Shape rectangular 36. Changes 23 Ownership Public 11 Addition : Private x (Explain Altered I Moved i in #42) 24. Owner's Name & Address, il known 37. Condition Interior 9. Coordinates UTM Lat. Exterior good Long 25. Open to Yes 38. Preservation Yes No IX Public? Underway? No ix 10. Structure I Sile ! : Building 1x Object 11 26. Local Contact Person or Organization 39. Endangered? Yes By What? No lx Landmarks Commission 11. On National Yes II 12 Is It Yes ! Eligible? Register? No Ix Nox 27. Other Surveys in Which Included 13 Part of Estab. Yes 11 14. District Yes 40. Visible from Yes X No 1x Nox Hist. Dist.? Potent'1? Public Road? No 11 41. Distance from and 15. Name of Established District Frontage on Road 100 feet on Troost 42. Further Description of Important Features A flat canopy supported by metal tie rods extends across the facade. Early reports noted a virtual absence of glass show windows, with the building featuring instead small "jewel case" display windows. Those windows have now been covered and the only fenestration of the east facade is a door. A forty foot high, flat towerline projection is at the south end of the building to accommodate highly visible signage. 43. History and Significance This building was one of 7 stores erected by Safeway Stores, Inc. during a building program in 1951. It is now part of a complex of buildings owned by the Nazarene Publishing House, publishers of magazines, Sunday school literature, books, and forms for the Church of the Nazarene. Vacant lots are north and west of this building. To 44. Description of Environment and Outbuildings the south is a surface parking lot. Vacant land is also to the east. 45 Sources of Information 46. Prepared by Piland / Uguccioni WP #15894 47. Organization Kansas City Star, Aug. 26, 1951, p. 2D. Landmarks Commission Kansas City Star, March 20, 1966. 48. Date 49. Revision Date(s) 3/10/82

State Historical Survey and Planning Office, 909 University Avenue, Suite 215,

olumbia, Missouri 65201




47. Organization

48. Date

3/26/84

Landmarks Commission

49 Revision Date(s)



Jackson

4 Present Name(s) 2916-44 Troost

1. No.	4. Present	ENIURY Name(s)		JA-A5-008-144
198-D		rene Publishing House		
Jackson	5 Other N			
3 Location of Negatives MT#70-2 Landmarks Commission of 1		not entered		
Specific Location	16	. Thematic Category		28. No. of Stories 1
2916-44 Troost	17	Date(s) or Period		29. Basement? Yes !
		1922 (add. betw. 1	964-66)	30. Foundation Material
City or Town If Rural, Towns Kansas City, Missou		Style or Design		31. Wall Construction
Site Plan with North Arrow		Architect or Engineer		masonry
	N L			32. Roof Type & Material
	14 20	Contractor or Builder		flat; tar and gravel 33. No. of Bays
	21	Original Use, if apparent		Front Side
1 - 4	1	commercial		34. Wall Treatment
20	1 22	Present Use commercial		brick; concrete block 35. Plan Shape II
la se	23		Public	36 Changes Addition 2
	24	Owner's Name & Address,	Private 1x	(Explain Altered I in #42) Moved I
	24	if known		37. Condition
Coordinates UTM				Interior
Lal. Long.	26	. Open to	Yes 1x	Exterior good  38. Preservation Yes
). Site!;	Structure	Public?	No II	38. Preservation Yes in Underway? No in
Building X	Object 11 26	Local Contact Person or Organiza	ation	39. Endangered? Yes I
1. On National Yes   12 Is It Register? No X: Elig	LI-0 11	andmarks Commission Other Surveys in Which Included	of KC	By What? No I
Part of Estab. Yes II 14. Dis	trict Yes	Other Surveys in winch included		40. Visible from Yes!
	ent'l? No 🗴		-	Public Road? No l 41. Distance from and
5. Name of Established District	1			Frontage on Road
2. Further Description of Important			- Annual Control	384 Feet on Troost
ists of a series of addit f the wall plane is reces enestration varies with o	ssed from the overhead gara north end of	street to provide parkinge doors, entrances, and this building was constr	ng and lo multipan ucted as	ading dock areas. The ed windows.  the American Garage #2
n 1922. The remaining postate azarene Publishing Comparation of Environment and are surface parking lots.	ny. Outbuildings Resi	dences are west of this	building.	
WP #15934; 69793				PILAND
WP #117063				47. Organization
BP#24882;26853				Landmarks Commission 48. Date 49. Revision Date(s)
BP#7541;9884				12/18/84

BP#13220 Western Contractor, August 9, 1922, p. 36





No. otto	4. Present	ENTORY Name(s)	JA-AS-008-1448
213-M County Jackson 5. Other		ted States Uniform Company	\$
		ame(s)	-
Location of Negatives MT #70 Landmarks Commission of	KC Saf	eway Stores Inc. No. 517	20
Specific Location	Commence of the last	. Theinatic Category	28. No. of Stories 1
3000 Troost			29. Basement? Yes I
	17	Date(s) or Period 1938	No i
City or Town If Rural, Town	ship & Vicinity 18	Style or Design	30. Foundation Material
Kansas City, Misso	AND AND AND ASSESSMENT OF THE PARTY OF THE P	rt Deco Elements	31. Wall Construction
Site Plan with North Arrow		Architect or Engineer	concrete block
	11		32. Roof Type & Material
	20	Contractor or Builder	flat; tar and gravel
	21	Morris Hoffman Const. Co. Original Use, if apparent	33. No. of Bays Front Side
1 4	1	commercial	34. Wall Treatment
20	22	Present Use	brick
2	4	commercial	35. Plan Shape rectangular
1	23	Ownership Public	11 36 Changes Addition :
	-	Private	in #42) Altered I
	24	Owner's Name & Address, if known	37. Condition
Coordinates UTM			Interior
Lat.			Exterior good
Long.	Structure	Open to Yes Public? No	
Site ! : Building ki		Local Contact Person or Organization	39. Endangered? Yes
On National Yes   12 Is		andmarks Commission of I	By What? No LX
		Other Surveys in Which Included	
	istrict Yes		40. Visible from Yes ! X Public Road? No ! :
Name of Established District			41. Distance from and
Maria an established Street			Frontage on Road
			50 feet on Troost
entrance canted at the	northeast corn	in facade of this corner bui er of the building. Plate g e is veneered with buff bric	lass display windows domin-
		-1 • Cof C	
History and Significance This	was construct	ed as a Safeway Grocery Store	e.
Description of Environment and	Outhuildings Vac	ant land is south and west o	f this building. To the
orth is a surface parki	ng lot. A vac	ant lot is to the east.	i this barraing. To the
Sources of Information			46. Prepared by
BP #15863		9	PILAND
WP #17840			47. Organization
WI 1/1/040			Landmarks Commission
WF #17040			Landmarks Commission 48. Date 49. Revision Date(s)



_
2
0
C .
16
ne(S

3030-36 Troost  17 Date(s) or Period 1965  1965  21 OF Foundation Material 1985  31 Wall Construction 22 Prosent Use 23 Nortical 24 Owner's Name & Address.  18 Site   Structure	No.	4. Pre	sent Name(s)	5 A-AS-008-1449
Source of Investigate MT 670-22 andmarks Commission of KC	County		Midas Muffler Shops	
Location of Negatives MT #70-22 andmarks Commission of KC Specific Location  3030-36 Troost  17 Date(s) or Period 1965  18 Style or Design  31. Wall Construction concrete block(metal fr 32. Roof Style & Malerial for Blasty to Structure	lackson		ner Name(s)	
Specific tocation  3030-36 Troost  17 Date(s) or Period 1965 197 Date(s) or Period 197 Date(s) or Period 198 Style or Design 198 Architect or Engineer 199 Architect or Engineer 200 Contractor or Builder 200 Contractor or Build	Location of Negatives M	r #70-22 on of KC		
3030–36 Troost  17. Date(s) or Period 1965  1965  197. Date(s) or Period 1965  198. Separed 197. Date(s) or Period 198. Site or Design  31. Wall Construction 31. Wall Construction 32. Roof Type & Material 15. Step Plan with North Arrow  199. Architect or Engineer 200. Contractor or Builder 150. Contractor or Builder 151. Roof Type & Material 152. Prost Type & Material 152. Roof Type & Material 152. Roof Type & Material 153. No of Bays 154. Spring & Material 155. Spring & Material 155. Spring & Material 156. Spring & Material 157. Spring & Material 157. Spring & Material 157. Spring & Material 157. Spring & Material 158. Spring & Material 159. Spring & Material 159. Spring & Material 150. Condition of Builder 150. Spring & Material 150. Spring & Mat	Specific Location	7	16. Thematic Category	28. No. of Stories 1
Coordinates UTM Let Coordinates UTM Let Coordinates Building XX Object   25 Open to Public Public Public   12 Is II Yes Engister No XX Engister No XX Part of Estab Nes II 14 District Yes Hole No XX Part of Estab Nes II 14 District Yes Hole II 15 District Yes Hole II 15 District Yes The north facade. An enclosed office area is located at the east end.  Description of Environment and Outbuildings A parking area is north of this building. To the south is commercial building. An apartment building is to the west. A surface parking lot is to easts with #20 Public II Appared by PILAND / Uguccioni 47 Organization Landburg Marks Commission La	***************************************			
Coordinates  UTM  Lat.  Commercial  Suite:  Su	3030-36 Troos	st		
Size Plan with North Arrow    19 Architect or Engineer   32. Roof Type & Material from Concrete block; metal from Size from Siz				30. Foundation Material
Site Plan with North Arrow  19. Architect or Engineer 20. Contractor or Builder Hoffman Const. Co. 21. Original Use, if apparent commercial 22. Present Use Commercial 23. Wail Treatment brick 24. Owner's Name & Address, if known 25. Open to Public I 26. Open to Public I 27. Open to Public I 28. Open to Public I 29. Open to Public I 20. Open to Public I 20. Open to Public I 21. On National Yes I 22. Open to Public I 23. Open to Public I 24. Owner's Name & Address, if known 25. Open to Public I 26. Open to Public I 27. Open to Public I 28. Open to Public I 29. Open to Public I 20. Open to Public I 20. Open to Public I 21. Open to Public I 22. Open to Public I 23. Open to Public I 24. Owner's Name & Address, if known Interior Extenior good Indeway? No IX Public Road? No IX 27. Other Surveys in Which included  28. Preservation Ves IX 29. Endangered I 39. Preservation Interior Extenior good Indeway? No IX Public Road? No IX 40. Visited Yes IX 40. Visited Yes IX 40. Visited Yes IX 40. Visited Road? No IX 40. Visite Irom Public Road? No IX 40. Visite Irom Public Road? No IX 41. Distance Irom and Promise on Road Arronal Road			18. Style or Design	31. Wall Construction
20. Contractor or Builder Hoffman Const. Co. 21. Original Use, if apparent Commercial 22 Present Use Commercial 23 Ownership Public 1 Private by 24. Owner's Name & Address, if known  25. Open to Public?  26. Local Contact Person or Organization Public? 27. Other Surveys in Which included  28. Preservation Public Rodar?  29. Preservation Public Provided Public Preservation Public Pres	Site Plan with North Arre	ow 1	19. Architect or Engineer	
Hoffman Const. Co. 21. Criginal Use, if apparent commercial 22. Present Use commercial 23. Ownership Public! 24. Owners Name & Address. if known  Site: Surfacture: Building XX Object: An Astonal Yes: Building XX Object: An Astonal Yes: Building XX Object: Constitution of Eligible No XX Filipible No XX		1		
21. Original Use, if apparent commercial  22. Present Use		M		
Commercial  22 Present Use  commercial  23 Ownership  Private by  24 Owner's Name & Address,  if known  25 Open to public?  District  Suite No XX  Public?  No XX  Potenti? No XX  Suite No XX  Potenti? No XX  Potenti? No XX  Name of Established District  Private by  Suite No XX  Name of Established District  Private by  Suite No XX  Name of Established District  Commercial  32 Ownership  Private by  Public?  24 Owner's Name & Address,  If known  36 Changes Addition:  Esterior good.  Esterior good.  Public?  26 Local Contact Person or Organization  Landmarks Commission of KC  27 Other Surveys in Which included  40 Visible from Yes: X  Public Road?  40 Visible from and Frontage on Road  45 feet on Troost  Further Description of Important Features The building faces east on to Troost. Four garage bays extend to set the north facade. An enclosed office area is located at the east end.  Public Road?  A parking area is north of this building. To the south is commercial building. An apartment building is to the west. A surface parking lot is to east.  Commercial building. An apartment building is to the west. A surface parking lot is to east.  Sources of information  WP #6542  BP #21105	1	1		
23 Ownership   Public	1			34. Wall Treatment
23 Ownership Public   GExplain   Addition   (Explain   Addition   Moved   Addition   Move	00			
Private  x   (Explain   Mired   in #42)   Altered   in #42   Altered		1		rectangular
Conditional standard a Address and a Address				
Site				in #42) Moved i
Exterior good   Sterior good   Ste			if known	
Site: Structure   Dipolic   Structure   Dipolic   Suiding XX	MOTOR CONTRACTOR OF THE PROPERTY OF THE PROPER	ITM		
Site: Suiding XX Structure: Object: 26. Local Contact Person or Organization On National Yes   12 Isil Yes   Eligible? No XX Part of Established Potenti? No XX Potenti? No XX Part of Established District  Suiding XX Potenti? No XX			25. Open to Yes IX	
Description of Environment and Outbuildings   A parking area is north of this building. To the south is commercial building. An apartment building is to the west. A surface parking lot is to sources of information   Public Post   Public P			Public? No 11	
Register? No XX Eligible? No XX Potent'!? No X			26. Local Contact Person or Organization	
Part of Estab. Yes   14. District Yes   Potenti? Yes   No xx   40. Visible from Public Road? No   14. Distance from and Frontage on Road   45 feet on Troost   41. Distance from and Frontage on Road   45 feet on Troost   45 feet on Troost   46 feet on Troost   47 feet on Troost   47 feet on Troost   48 feet on Troost   48 feet on Troost   49 feet on Troost   49 feet on Troost   49 feet on Troost   49 feet on Troost   40 feet on Troost   41 Distance from and Frontage on Road   45 feet on Troost   45 feet on Troost   45 feet on Troost   46 feet on Troost   47 feet on Troost   48 fee				By What? NO 1X
Name of Established District  41. Distance from and Frontage on Road 45 feet on Troost  Further Description of Important Features The building faces east on to Troost. Four garage bays extend coss the north facade. An enclosed office area is located at the east end.  History and Significance One of a chain of muffler shops featuring a standard design.  Description of Environment and Outbuildings A parking area is north of this building. To the south is commercial building. An apartment building is to the west. A surface parking lot is to east.  Sources of Information  WP #6542  BP #21105  46. Prepared by PILAND /Uguccioni 47. Organization Landmarks Commission		14. District Yes	27. Other Surveys in Which included	40. Visible from Yes !X
Frontage on Road 45 feet on Troost  Further Description of Important Features The building faces east on to Troost. Four garage bays extend cross the north facade. An enclosed office area is located at the east end.  History and Significance One of a chain of muffler shops featuring a standard design.  Description of Environment and Outbuildings A parking area is north of this building. To the south is commercial building. An apartment building is to the west. A surface parking lot is to east.  Sources of Information  WP #6542  BP #21105  46. Prepared by PILAND /Uguccioni 47. Organization Landmarks Commission	Hist. Dist.? No XX	Potent'l? No XX		1. 1. 1. 1. 1. 1. 1. 1. 1. 1. 1. 1. 1. 1
Further Description of Important Features The building faces east on to Troost. Four garage bays extend coss the north facade. An enclosed office area is located at the east end.  History and Significance One of a chain of muffler shops featuring a standard design.  Description of Environment and Outbuildings A parking area is north of this building. To the south is commercial building. An apartment building is to the west. A surface parking lot is to east.  Sources of Information  WP #6542  BP #21105  46. Prepared by PILAND/Uguccioni 47. Organization Landmarks Commission	Name of Established Dis	strict		
Description of Environment and Outbuildings A parking area is north of this building. To the south is commercial building. An apartment building is to the west. A surface parking lot is to east.  Sources of Information  WP #6542  BP #21105  An enclosed office area is located at the east end.  History and Significance One of a chain of muffler shops featuring a standard design.  A parking area is north of this building. To the south is commercial building. An apartment building is to the west. A surface parking lot is to east.  46. Prepared by PILAND/Uguccioni  47. Organization Landmarks Commission				
Description of Environment and Outbuildings A parking area is north of this building. To the south is commercial building. An apartment building is to the west. A surface parking lot is to e east.  Sources of Information  WP #6542  BP #21105  46. Prepared by PILAND / Uguccioni  47. Organization Landmarks Commission				
A parking area is north of this building. To the south is commercial building. An apartment building is to the west. A surface parking lot is to east.  Sources of Information  WP #6542  BP #21105  46. Prepared by PILAND / Uguccioni  47. Organization Landmarks Commission	History and Significance	One of a chain	of muffler shops featuring a stand	ard design.
A parking area is north of this building. To the south is commercial building. An apartment building is to the west. A surface parking lot is to east.  Sources of Information  WP #6542  BP #21105  46. Prepared by PILAND / Uguccioni  47. Organization Landmarks Commission				1
A parking area is north of this building. To the south is commercial building. An apartment building is to the west. A surface parking lot is to east.  Sources of Information  WP #6542  BP #21105  46. Prepared by PILAND / Uguccioni  47. Organization Landmarks Commission			w	
WP #6542 BP #21105 PILAND/Uguccioni 47. Organization Landmarks Commission	commercial buildi			
BP #21105 Landmarks Commission				
Landmarks Commission				
	WP #6542		+	PILAND / Uguccioni
	WP #6542			PILAND / Uguccioni 47. Organization



- 43. History and Significance This was built as the first outlying department store in Kansas City for the Jones Store Company. It was built at a cost of \$12 million.
- 44. Description of Environment and Outbuildings Other commercial buildings are located to the north, south, and east of this building. A commercial building is also to the west.

45 Sources of Information WP #24168 BP #16759 Kansas City Star, Oct. 19, 1947, p. 16A. Kansas City Star, March 22, 1949, p. 3.

1. No 213-H

2 County

Jackson

9 Coordinates

11. On National

Register?

Hist. Dist.?

Lal. Long

10

46. Prepared by Piland 47. Organization Landmarks Commission 48. Date 49. Revision Date(s) 8/5/82



48. Date

9/2/82

49. Revision Date(s)



11-A	1. 7.10	seni Name(s)	,
County Jackson	St	erling Bearing, Inc.	
		ner Name(s)	
ndmarks Commissio	n of KC Mi	dwest Motors and Auto Sales Company	
Specific Location		16. Thematic Category	28. No. of Stories 1
			29. Basement? Yes!
601 Truman Road		17. Date(s) or Period	No 1.
City or Town If Rural	, Township & Vicinity	18. Style or Design	30. Poundation Material
Kansas City, Miss	souri		31. Wall Construction
Site Plan with North Arro	w	19. Architect or Engineer Leon Maslan	concrete block
	7.	20. Contractor or Builder	32. Roof Type & Material  flat; tar and gravel
TRUMAN	KOND		33. No. of Bays
N		21. Original Use, if apparent	Front Side
1		commercial 22 Present Use	34. Wall Treatment brick; glass
		commercial	35. Plan Shape irregular
		23 Ownership Public 11	36. Changes Addition
		Private Ki	(Explain Altered ) in #42) Moved
		24. Owner's Name & Address, if known	37. Condition
oordinates U'	тм		Interior
at. ong.			Exterior good
Site!:	Structure	25. Open to Yes Xi Public? No I I	38. Preservation Yes Underway? No X
Building Ix	Object	26. Local Contact Person or Organization	39. Endangered? Yes I
On National Yes II	12 Is It Yes :	Landmarks Commission	By What? No to
legister? No kt	Eligible? No X	27. Other Surveys in Which Included	
Part of Estab. Yes	Potent'l? No x		40. Visible from Yes 🔀 Public Road? No 🗆
Name of Established Dis	trict		41. Distance from and
			Frontage on Road 132 feet on Truman Road
Further Description of Im	portant Features	The main facade of this building fa	
	tion projects for	The main facade of this building fa orward, with an entrance centrally he north facade, and on the west fac	
walled, lower sec entrance is at th entrances.  History and Significance	tion projects for e east end of the thing the things of th	orward, with an entrance centrally	ade are other garage
walled, lower sec entrance is at th entrances.  History and Significance and retail used  Description of Environme	tion projects for the east end of the third large but cars, the Midwest and Outbuildings	orward, with an entrance centrally he north facade, and on the west fac	ade are other garage  hat dealt in wholesale  west of this building.
walled, lower sec entrance is at the entrances.  History and Significance and retail used  Description of Environme To the north is va	tion projects for the east end of the third large but cars, the Midwest and Outbuildings	orward, with an entrance centrally he north facade, and on the west facultiding was constructed for a firm to st Motors and Auto Sales Company.  Surface parking lots are east and	hat dealt in wholesale west of this building.
walled, lower sec entrance is at th entrances.  History and Significance and retail used  Description of Environme	tion projects for the east end of the third large but cars, the Midwest and Outbuildings	orward, with an entrance centrally he north facade, and on the west facultiding was constructed for a firm to st Motors and Auto Sales Company.  Surface parking lots are east and	hat dealt in wholesale west of this building.



I. No.	4. Pres	seni Name(s)	
12-I		Autorama Inc. entered	
Jackson 5 Oine		er Name(s)	
Location of Negatives N Landmarks Commission	AT #95-1 on of KC	George Welsh Motors, Inc.	
Specific Location		16. Theinatic Category	28. No. of Stories 1
711 Truman Road		17. Date(s) or Period	29. Basement? Yes I
/II Iruman koac		1948	30. Foundation Material
City or Town - Il Rura		18 Style or Design	
Kansas City, M		19. Architect or Engineer	31. Wall Construction
. Site Plan with North Am	\	19 Architect or Engineer	concrete block  32. Roof Type & Material
12000		20. Contractor or Builder	flat; tar and gravel
TRUMAN	KD !	Fogel Construction Company	33. No. of Bays Front Side
		21. Original Use, if apparent commercial	34. Wall Treatment
		22. Present Use	concrete block
		commercial	35. Plan Shape irregular
		23 Ownership Public   Private K	36. Changes Addition : : (Explain Altered :
		24. Owner's Name & Address,	in #42) Moved i
		H KNOWN	37. Condition Interior
Coordinates U	ITM		Exterior good
Long.		25. Open to Yes Ki Public? No I	38. Preservation Yes
Site!: Building XX	Structure I -	Public? No 11 26. Local Contact Person or Organization	Underway? No X  39. Endangered? Yes I
On National Yes II	12 Is It Yes :	Landmarks Commission of KC	By What? No 1x
Register? No XX	Eligible? No XX	27. Other Surveys in Which Included	
Part of Estab. Yes II Hist. Dist.? No xx	14. District Yes Potent'l? No xx		40. Visible from Yes !X Public Road? No !:
Name of Established Dis			41. Distance from and
			Frontage on Road
Further Description of In	poortant Features The	main facade of this simple buildi	no food north The west
		glass entry door, flanked by windo	
		le, also flanked by windows.	
	m		·
. History and Significance	This was erecte	d as a used car lot office for Geo	rge Welsh Motors, Inc.
			*
		The building is placed back from t	
provide parking s	pace to the nort	h, east and west. A commercial bui	lding is to the south.
Sources of Information			46. Prepared by
5 Sources of Information WP #2331			PILAND
VP #2331			
P #16881			47. Organization Landmarks Commission



## HISTORIC INVENTORY

1. No. 13-A	N. Present Name(s)  Clark Oil Company Service Sta	ition	13-A		
	other Name(s) not enteral				
6 Specific Location 805 Truman Road	16. Thematic Category  17. Date(s) or Period	28. No. of Stories 1 29. Basement? Yes   No.	Jackson		
7 City or Town If Rural, Township & Vic Kansas City, Missouri 8 Site Plan with North Arrow	1955-56 cimity 18 Style or Design 19. Architect or Engineer	30. Foundation Material  31. Wall Construction concrete block	on		
NTRUMAN RO	20 Contractor or Builder  A. I. Morris 21 Original Use, if apparent  service station 22 Present Use service station	32. Roof Type & Material flat; tar & gravel 33. No. of Bays Front Side 34. Wall Treatment glass 35. Plan Shape rectangular			
9 Coordinates UTM	23 Ownership Public   Private   Priv	36. Changes Addition : (Explain Altered   1 Moved   1 Mo	Truman Road		
Long  10 Site 1: Structu Building 1: Obje	4 ( ) ( ) ( ) ( ) ( ) ( ) ( ) ( ) ( ) (	38 Preservation Yes Underway? No k			
11 On National Yes 11 12 Is It Yes	26. Local Contact Person or Organization Landmarks Commission  27. Other Surveys in Which Included	39. Endangered? Yes I By What? No 😿			
Hist. Dist.? No 11 Potent'1? Name of Established District	es   	40. Visible from Yes X Public Road? No 1:  41. Distance from and Frontage on Road  120 feet from Truman Road			

42. Further Description of Important Features This building sits at an angle, near the rear of the lot, thus providing ample space for gas pumps and automobile traffic. The main facade faces northwest. The majority of the wall surface is comprised of plate glass windows.

- 43. History and Significance This building was constructed as a service station for the Clark Oil Company.
- 44. Description of Environment and Outbuildings The corner building sits at an angle, facing the northwest and 120 feet from both Truman Road and Charlotte. A school building is east of this structure. To the west and south are commercial buildings. Vacant land is to the north.
- 45 Sources of Information

WP #8028

BP #18519

46. Prepared by Piland 47. Organization Landmarks Commission 48. Date 49. Revision Date(s) 7/5/83

JA-AS-008-1454



49. Revision Date(s)

48. Date 1/18/85



Piland

48. Date

2/1/83

47. Organization

Landmarks Commission

49. Revision Date(s)

WP #4764

BP #27546A

BP #22943A; 68123

County

Present Name(s)





46. Prepared by

47. Organization

48. Date 2/2/83

Piland /Uguccioni

Landmarks Commission

49. Revision Date(s)

45 Sources of Information

WP #9979



2 County

4 Present Name(s)

15-A Re	esent Name(s) esenhouse Electric Supply Co.		
Jackson  3 Location of Negatives MT #23-19 Landmarks Commission	her Name(s)		15-A
6. Specific Location 1011 Truman Road	16. Thematic Category  17. Date(s) or Period 1909	28. No. of Stories 2  29. Basement?  Yes   <sub>X</sub> No    30. Foundation Material	Jackser
7 City or Town II Rural, Township & Vicinity Kansas City, Missouri  8. Site Plan with North Arrow	18. Style or Design  19. Architect or Engineer  20. Contractor or Builder	31. Wall Construction masonry  32. Roof Type & Material + Pp flat; tar & gravel	
TRUMAN RD. N	George Huggins  21. Original Use, if apparent commercial  22. Present Use commercial  23. Ownership Public   Private   Private	33. No. of Bays Front Side  34. Wall Treatment brick; concrete block 35. Plan Shape rectangular  36. Changes Addition; (Explain Altered IX in #42) Moved;	1011 Truman
9 Coordinates UTM Lat. Long.  10. Site!: Structure!	25. Open to Yes No !!	37. Condition Interior Exterior good  38. Preservation Yes   Underway? No ix	Road
Building IX Object   1  11. On National Yes   12 Is It Yes X Register? No   Eligible? No   1  13. Part of Estab Yes   14. District Yes X Hist. Dist.? No   1 Potent   17. No   1.  15. Name of Established District	26. Local Contact Person or Organization Landmarks Commission 27. Other Surveys in Which Included	39. Endangered? By What?  40. Visible from Yes !X Public Road?  No   1	
the 1st and 2nd floor have been i	The main facade faces north. The willied. An overhanging cornice was the building permit, this building to A surface parking lot is west of	removed in 1962.	

#5 Sources of Information

WP #5622

BP #79160

BP #68809

BP #9548


#6 Prepared by Piland

#7. Organization

Landmarks Commission

#8. Date #9. Revision Date(s)

6/23/81



_	
R	
	,

THE PARK COLUMN 2	4. Pr	esent Name(s)	
1. No. 15-B	st	eel Sales and Equipment Company	
County	5.0	her Name(s)	
Jackson Location of Negatives N		enterel	
Location of Negatives N Landmarks Commissi	on "23 10		
Specific Location		16. Thematic Calegory	28. No. of Stories 1
1013 Truman Road		17. Date(s) or Period	29. Basement? Yes I
		1964	30. Foundation Material
City or Town II Rura Kansas City, Misso	I, Township & Vicinity	18. Style or Design	
			31. Wall Construction concrete block
Site Plan with North Arre	ow	19 Architect or Engineer	32. Roof Type & Material
		20. Contractor or Builder	flat; tar and gravel
N			33. No. of Bays
N TRUMAN 1	2	21. Original Use, if apparent	Front Side
1 RUMAN	)0AD	22. Present Use	34. Wall Treatment concrete block
		commercial	35. Plan Shape irregular
		23 Ownership Public   1	36. Changes Addition
		Private M 24. Owner's Name & Address.	(Explain Altered I in #42) Moved I
		il known	37. Condition
Coordinates U	тм		Interior
Lat. Long			Exterior good
Site!:	Structure	25. Open to Yes II Public? No 29	38. Preservation Yes ( Underway? No is
Building 1x	Object	26. Local Contact Person or Organization	39. Endangered? Yes I
On National Yes 1	12 Is It Yes	Landmarks Commission	By What? No 13
Register? No IX	Eligible? No X	27. Other Surveys in Which Included	
Part of Estab Yes   1 Hist. Dist.? No   Z	14 District Yes Potent'l? No X		40. Visible from Yes !? Public Road? No
	et wint	1	41. Distance from and
Name of Established Dis	STRICT	E .	
Name of Established Dis	strict		Frontage on Road
Further Description of Ir	mportant Features Th	ne main facade faces north. Only a	Frontage on Road
enestrates this co	mportant Features Th oncrete block fa	acade.	Frontage on Road
Further Description of Interestrates this constructs.  History and Significance ince its constructs.	This building ion in 1964.		es and Equipment Company s structure. Other
Further Description of Ir enestrates this co History and Significance nce its construct:  Description of Environme commercial building	This building ion in 1964.	has been occupied by the Steel Sale  A church building is north of this	central entrance door es and Equipment Company s structure. Other urface parking lot.
Further Description of Ir enestrates this co enestrates this co enestrates this co enestrates this co enestrates this co	This building ion in 1964.	has been occupied by the Steel Sale  A church building is north of this	es and Equipment Company s structure. Other urface parking lot.  46 Prepared by Piland
Further Description of Ir enestrates this co History and Significance nce its construct:  Description of Environme commercial building	This building ion in 1964.	has been occupied by the Steel Sale  A church building is north of this	central entrance door es and Equipment Company s structure. Other urface parking lot.



43. History and Significance This building was constructed as a warehouse for the Grand Avenue Storage Company at a cost of \$30,000.

44. Description of Environment and Outbuildings Surface parking lots are north and south of this structure. To the east is a commercial building. A commercial building and surface parking lot are to the west.

45 Sources of Information American Architect and Building News, May 24, Kansas City Architect and Builder, June 1902, p. 11. 1902, p. XI. Kansas City Architect and Builder, Sept. 1902, p. 23. BP #57150A

1. No

6-A

2. County

Lat. Long

Register?

brick.

10

Jackson

46. Prepared by Piland /Uguccioni 47. Organization Landmarks Commission 49 Revision Date(s) 48. Date 3/17/82



HISTORIC INVENTORY TA-AS-008-146 I No 4. Present Name(s) 5-G 1512-16 Walnut County Jackson 5 Other Name(s) 3 Location of Negatives MT #107-16 Landmarks Commission of KC 6 Specific Location 16. Theinatic Category 28. No. of Stories 030 050 29. Basement? Yes Date(s) or Period 1512-16 Walnut 21+ 1927 30. Foundation Material 0 18 Style or Design If Rural, Township & Vicinity 31. Wall Construction Kansas City, Missouri Tapestry Brick masonry LID 19 Architect or Engineer 8. Site Plan with North Arrow 32. Roof Type & Material F+ Other flat; tar and gravel 20. Contractor or Builder 30 33. No. of Bays Orlando O. Concannon Front 4 21. Original Use, if apparent commercial O > 1+ 34. Wall Treatment brick 30 22 Present Use commercial 35. Plan Shape rectangular 36 Changes 23 Ownership Public | Addition Private x (Explain Altered X in #42) Moved I 24. Owner's Name & Address. if known 37. Condition Interior UTM Coordinates good Exterior Lat. Long 25. Open to 38. Preservation Yes Yes Public? No to Underway? No X Site! Structure Object Building IX 39 Endangered? 26. Local Contact Person or Organization Yes By What? No bo Yes X 11 On National 12 Is It Yes Landmarks Commission of KC Register? No IX Eligible? No 27. Other Surveys in Which Included District Yes X 40. Visible from Yes X 13 Part of Estab Yes II Public Road? Potent'1? Hist. Dist.? No x 41. Distance from and 15. Name of Established District Frontage on Road 75 feet on Walnut 42 Further Description of Important Features The main facade of this building faces east. The facade has been altered with the addition, probably in 1956, of an overhead garage door. Entrance doors are at the north and south ends of the east facade. Large display windows on the first floor have multipaned transoms. Rectangular sash windows, grouped in threes, provide the 2nd floor fenestration. A running brick soldier course is placed above these windows. 43. History and Significance The early use of this building is unknown. It appears to have remained vacant several years after its construction. 44. Description of Environment and Outbuildings Surface parking areas are north and east of this building. Commercial buildings are also to the east, south and west. 46. Prepared by 45 Sources of Information PILAND BP #15120 47. Organization Western Contractor, November 9, 1927, p. 38 Landmarks Commission 48. Date 49. Revision Date(s) BP #48054 6/22/84



State Historical Survey and Planning Office, 909 University Avenue, Suite 215

Columbia, Missouri 65201

12/16/82



43. History and Significance This was constructed for the General Testing Laboratories, a firm headed by Ben Poisner.

44. Description of Environment and Outbuildings Other commercial buildings are south, east, and west of this structure. A surface parking lot is to the north.

45 Sources of Information WP #8034 BP #16179 BP #24465A

1. No.

6-B 2 County

> Lat. Long

Register?

15. Name of Established District

10

Jackson

46. Prepared by Piland 47. Organization

41. Distance from and Frontage on Road

Landmarks Commission 48. Date 49. Revision Date(s)

4/7/82



State Historical Survey and Flamming Office, 303 Oniversity

UACTION

3/16/82

Columbia, Missouri 65201



Columbia, Missouri 65201



State Historical Survey and Planning Office, 909 University Avenue, Suite 215 olumbia, Missouri 65201 STORIC INVENT No. 4. Present Name(s) 6-D Parmelee Industries, Inc.; Parmelee Plastics Company 2. County Jackson Location of Negatives MT #77-1 Landmarks Commission #76-21 Campbell Paint and Glass Company 6 Specific Location 16. Thematic Category 28. No. of Stories 7 050 County 1529-35 Walnut ackson 29. Basement? Yes | x 17 Date(s) or Period No I at 1974 1915-16 30. Foundation Material (add. 1939) City or Town If Aural, Township & Vicinity Kansas City, Missouri 18. Style or Design 31. Wall Construction PC 62 B. Site Plan with North Arrow 19. Architect or Engineer reinforced concrete 32. Roof Type & Material C+ Sunderland 20. Contractor or Builder Other flat; tar & gravel9 62 40 33. No. of Bays 15 Front Side 21. Original Use, if apparent Present Name(s) 29-35 commercial 02 A 34. Wall Treatment 22. Present Use brick : terra cotta 35. Plan Shape commercial Walnut 23 Ownership 36. Changes Public 1 Addition Private X Altered K (Explain in #42) Moved 24. Owner's Name & Address. il known 37. Condition Interior 9 Coordinates Exterior good Lat. Long 25. Open to Yes Ix 38. Preservation Yes Public? No II Underway? No X Site! Structure Building to Object ! 26. Local Contact Person or Organization Endangered? Yes By What? No X Yes X Landmarks Commission 11. On National Yesli 12 Is It Register? No IX Eligible? No 27. Other Surveys in Which Included Yes X Yes X 13 Part of Estab. Yes !! 14. District 40. Visible from Potent'1? No : Hist. Dist.? No bd Public Road? No ! 15. Name of Established District 41. Distance from and Frontage on Road 150 feet on Walnut 42. Further Description of Important Features The main facade faces west. The first and second floors Campbell have been substantially altered. Brick piers divide the west facade into four bays. Each bay of the top five floors is fenestrated with a row of four one-over-one, double-hung A one-story addition extended the building to the north in 1939. The first floor window areas were covered with a new stone front in 1974. Paint 43. History and Significance The Campbell Paint and Glass Company, original occupant of this building, was established in 1879. By the time this building was constructed, the Kansas City firm had branches Glass in 5 other cities. 4. Description of Environment and Outbuildings An elevated walk-way, at about the third floor level, connects this building with the commercial building to the south. Another commercial 44. Description of Environment and Outbuildings building is to the north. To the west is a commercial building and a surface parking lot. Commercial buildings and a surface parking lot are also th the east. 45 Sources of Information 46. Prepared by KC Star, Feb. 19, 1939, p. 6D. Piland WP #15080 47. Organization BP #11527 Landmarks Commission Kansas City Journal, June 13, 1915 48. Date 49 Revision Date(s) Kansas City Star, Feb. 6, 1916.

6/28/83

10

Western Contractor, July 21, 1915.

BP #15881 BP #11063





1. No. 23-G	4. Present Name(s)		Т
2 County	Parmalee Industries Inc.		23-
Jackson	5 Other Name(s)		9-0
Location of Negatives MT #69-22 Landmarks Commission	Emery, Bird, & Thayer Company Warehou	e name	
Specific Location	16. Thematic Category	00 11 10:	٠
1601-15 Walnut	030 050	29. Basement? Yes   <sub>X</sub>	Jackson
1001-13 Walnut	17 Date(s) or Period .	No i	· KS
	1899-1900 (add. 1905)	30. Foundation Material	on
City or Town If Aural, Township & Kansas City, Missouri	Vicinity 18 Style or Design	stone 40	
Site Plan with North Arrow	19 Architect or Engineer	31. Wall Construction masonry (L)	
. She rian with north Artow	Van Brunt & Howe (1899-1900) 30	32. Roof Type & Material F	1
J. 19mst	20. Contractor or Builder	flat; tar & gravel 99	1
1	Hollinger & Mitchell (1899-1900)	33. No. of Bays	
N ,	21. Original Use, if apparent warehouse 🙉 H	Front 10 Side	16
1 5	22 Present Use	34. Wall Treatment brick 30	601-
Joena	warehouse	35. Plan Shape rectangular	15
2	23 Ownership Public I !	36. Changes Addition IX	Wa
1 3	Private 😾	(Explain Altered I I in #42) Moved I	alr
2	24. Owner's Name & Address, if known	37. Condition	Tut.
Coordinates UTM		Interior	1
Lat.		Exterior good	1
Long.	25. Open to Yes kd	38. Preservation Yes	
	cture	Underway? No iX	1
	Yes xx Landmarks Commission	39. Endangered? Yes !: By What? No !;	
1. On National Yes   12 Is It Register? No ** Eligible?	No : 27. Other Surveys in Which Included	*	
	Yes XX	40. Visible from Yes IX	4
3 Part of Estab. Yes   14. District Hist. Dist.? No   1 Potent'1?	No :	Public Road? No 11	
		Public Road? No 11	
Hist. Dist.? No.   Potent'l?  5. Name of Established District	No : -	Public Road? No 11 41. Distance from and approx Frontage on Road approx 200 ft. on Walnut	
Hist. Dist.? No   Potent'!?  5. Name of Established District  2. Further Description of Important Feature The 10 bay elevation is created facade. The first story feature to the story of t	No:  The primary facade of the building in the distance of the building in the second of	Public Road? No 11 41. Distance from and approx 200 ft. on Walnut faces west onto Walnut. arch windows across the cinguishes it from the between the fourth and	Emery, Bird
Hist. Dist.? No   Potent'!?  Name of Established District  The 10 bay elevation is created facade. The first story featupper stories. Brick quoinififth bays. A decorative stoplaced below the parapet wall below the parapet wall below the parapet wall first two floors of this busied for storage. The build	The primary facade of the building is sted by the regular spacing of segmental actures horizontal brick banding which disting marks the corners of the building and is cringcourse divides the fifth and sixth state.  Chitects for this warehouse for the Emery ned the store at 11th and Grand (demolish ilding were originally used for stables. ding was constructed at a cost of \$40,000	Public Road? No 11  41. Distance from and approx 200 ft. on Walnut  Faces west onto Walnut. Arch windows across the cinguishes it from the between the fourth and cories, and another is  7. Bird, and Thayer and in 1972). The  The upper floors were	Emery, Bird & Thayer
Hist. Dist.? No XX Potent'!?  Name of Established District  Property of Important Feature  The 10 bay elevation is created acade. The first story feature to the story of this but of the story of this but of the story of the story of this but of the story of the story of this but of the story of the stor	The primary facade of the building is sted by the regular spacing of segmental actures horizontal brick banding which disting marks the corners of the building and is cringcourse divides the fifth and sixth state.  Chitects for this warehouse for the Emery ned the store at 11th and Grand (demolish ilding were originally used for stables. ding was constructed at a cost of \$40,000	Public Road? No 11  41. Distance from and approx 200 ft. on Walnut  Faces west onto Walnut. Arch windows across the cinguishes it from the between the fourth and cories, and another is  7. Bird, and Thayer and in 1972). The  The upper floors were	Emery, Bird & Thayer
Name of Established District  Further Description of Important Feature The 10 bay elevation is created acade. The first story feature upper stories. Brick quoinities fifth bays. A decorative steplaced below the parapet wall.  History and Significance The are Department Store also design first two floors of this but used for storage. The built to Parmalee Industries for Stores.	The primary facade of the building in the day the regular spacing of segmental actures horizontal brick banding which disting marks the corners of the building and is tringcourse divides the fifth and sixth state.  Chitects for this warehouse for the Emery ned the store at 11th and Grand (demolish ilding were originally used for stables. ding was constructed at a cost of \$40,000 \$145,000.	Public Road? No 11 41. Distance from and approx 200 ft. on Walnut faces west onto Walnut. Arch windows across the ringuishes it from the between the fourth and cories, and another is  7. Bird, and Thayer and in 1972). The The upper floors were and was sold in 1970	Emery, Bird & Thayer
Name of Established District  Further Description of Important Feature The 10 bay elevation is created facade. The first story feature upper stories. Brick quoinities fifth bays. A decorative star placed below the parapet wall.  History and Significance The arc Department Store also design first two floors of this but used for storage. The build to Parmalee Industries for storage in the parapet wall orth is a commercial building orth is a commercial building.	The primary facade of the building is sted by the regular spacing of segmental attures horizontal brick banding which disting marks the corners of the building and is tringcourse divides the fifth and sixth state.  Chitects for this warehouse for the Emery ned the store at 11th and Grand (demolish ilding were originally used for stables. ding was constructed at a cost of \$40,000 \$145,000.	Public Road? No 11  41. Distance from and approx 200 ft. On Walnut  Frontage on Road approx 200 ft. On Walnut  Faces west onto Walnut. Arch windows across the cinquishes it from the between the fourth and cories, and another is  7. Bird, and Thayer and in 1972). The The upper floors were and was sold in 1970  This building. To the	Emery, Bird & Thayer
Name of Established District  Purther Description of Important Feature The 10 bay elevation is created facade. The first story feature to story and Significance of the parapet wall of the parameter of the parameter of the bused for storage. The build to Parmalee Industries for storage.  Description of Environment and Outbusters is a commercial building east.	The primary facade of the building is sted by the regular spacing of segmental actures horizontal brick banding which disting marks the corners of the building and is tringcourse divides the fifth and sixth stal.  Chitects for this warehouse for the Emery med the store at 11th and Grand (demolish ilding were originally used for stables. ding was constructed at a cost of \$40,000 \$145,000.	Public Road? No 11  41. Distance from and approx 200 ft. On Walnut  Frontage on Road approx 200 ft. On Walnut  Faces west onto Walnut. Arch windows across the cinquishes it from the between the fourth and cories, and another is  7. Bird, and Thayer and in 1972). The The upper floors were and was sold in 1970  This building. To the	Emery, Bird & Thayer
History and Significance The arc Department Store also design first two floors of this but used for storage. The build to Parmalee Industries for Sources of Information	The primary facade of the building in the day the regular spacing of segmental actures horizontal brick banding which disting marks the corners of the building and is tringcourse divides the fifth and sixth state.  Chitects for this warehouse for the Emery need the store at 11th and Grand (demolish ilding were originally used for stables. ding was constructed at a cost of \$40,000 \$145,000.	Public Road?  41. Distance from and approx 200 ft. on Walnut  Faces west onto Walnut. Arch windows across the cinguishes it from the between the fourth and cories, and another is  43. Bird, and Thayer and in 1972). The The upper floors were and was sold in 1970  This building. To the parking lot are to the	Emery, Bird &
History and Significance The arc Department Store also design first two floors of this but used for storage. The build to Parmalee Industries for Sources of Information IP #16663  P. Further Description of Important Feature 2. Further Description of Environment and Outbut east.  Potential Potent	The primary facade of the building is sted by the regular spacing of segmental actures horizontal brick banding which disting marks the corners of the building and is ringcourse divides the fifth and sixth state.  Chitects for this warehouse for the Emery need the store at 11th and Grand (demolish ilding were originally used for stables. ding was constructed at a cost of \$40,000 \$145,000.  Iddings A surface parking lot is west of the ing. A commercial building and a surface parking and a surface parking lot is west of the ing. A commercial building and a surface parking lot is west of the ing. A commercial building and a surface parking lot is west of the ing. A commercial building and a surface parking lot is west of the ing. A commercial building and a surface parking lot is west of the ing.	Public Road?  41. Distance from and approx 200 ft. on Walnut Frontage on Road approx 200 ft. on Walnut Faces west onto Walnut.	Emery, Bird & Thayer
History and Significance The are Department Store also design first two floors of this but used for storage. The built of Parmalee Industries for St.	The primary facade of the building in the ted by the regular spacing of segmental actures horizontal brick banding which disting marks the corners of the building and is tringcourse divides the fifth and sixth state.  Chitects for this warehouse for the Emery need the store at 11th and Grand (demolish ilding were originally used for stables. ding was constructed at a cost of \$40,000 \$145,000.  Iddings A surface parking lot is west of the ing. A commercial building and a surface parking and a surface parking lot. The ing. A commercial building and a surface parking lot. The ing. A commercial building and a surface parking lot. The ing. A commercial building and a surface parking lot.	Public Road?  41. Distance from and approx 200 ft. On Walnut  Frontage on Road approx 200 ft. On Walnut  Faces west onto Walnut. In the strong windows across the strong windows across the strong wishes it from the between the fourth and cories, and another is  7. Bird, and Thayer and was sold in 1970  The upper floors were and was sold in 1970  his building. To the parking lot are to the  46. Prepared by Piland /Uguccioni	Emery, Bird & Indyer



1. No.	4. Pres	sent Name(s)	
23-A		1619-21 Walnut	
2. County	5 Oth	er Name(s)	
Jackson  3 Location of Negatives Landmarks Commiss	MT #69-21		ulding
6 Specific Location		16. Thematic Category	28. No. of Stories 1
1619-21 Walnut		030 050 290	29. Basement? Yes I
		17 Date(s) or Period .	No L.
		1917	30. Foundation Material
City or Town II Ru Kansas City, Miss	ral, Township & Vicinity	18 Style or Design	31. Wall Construction
Site Plan with North A		19. Architect or Engineer	masonry Lub
. One rium min month is	,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,	Herman Stroeh	32. Roof Type & Material +
11		20. Contractor or Builder	steel truss; tar & grav
1		Alex Kinghorn	33. No. of Bays 99
1 31		21. Original Use, if apparent	17.61
7		commercial COE 16D	34. Wall Treatment brick 3 ○
3 1		commercial	35. Plan Shape rectangular
3		23. Ownership Public !!	36 Changes Addition 1
		Private IX	(Explain Altered I I Moved I
		24. Owner's Name & Address, if known	
		ii kiiowii	37. Condition Interior
Coordinates Lat.	<b>UTM</b>		Exterior
Long.		25. Open to Yes IX	38 Preservation Yes
O. Site ! ;	Structure	Public? No 11	Underway? No ix
Building	Object ! !	26. Local Contact Person or Organization	39. Endangered? Yes I
X		The first of the control of the cont	
1. On National Yes I i	12 Is It Yes X	Landmarks Commission	By What? No IX
1. On National Yes   i Register? No X!	Eligible? No 11	Landmarks Commission 27. Other Surveys in Which Included	By What? No 1x
1. On National Yes   i Register? No X!		ELIPTIC REPART AND AND REPART OF THE PROPERTY	
1. On National Yes   i Register? No X! 3. Part of Estab. Yes   i Hist. Dist.? No X!	Eligible? No ::  14. District Yes x Potent'!? No ::	ELIPTIC REPART AND AND REPART OF THE PROPERTY	40. Visible from Public Road? Yes!X No!!
1. On National Yes   i Register? No X: 3. Part of Estab. Yes   i Hist. Dist.? No X	Eligible? No ::  14. District Yes x Potent'!? No ::	ELIPTIC REPART AND AND REPART OF THE PROPERTY	40. Visible from Yes!X Public Road? No!!  41. Distance from and Frontage on Road approx.
1. On National Yes   i Register? No X: 3. Part of Estab. Yes   i Hist. Dist.? No X! 5. Name of Established I	Eligible? No 11  14. District Yes X Potent'1? No 11  District	27. Other Surveys in Which Included	40. Visible from Yes!X Public Road? No!!  41. Distance from and Frontage on Road approx. 65 feet on Walnut
Register? No X:  3 Part of Estab. Yes     Hist. Dist.? No X:  5 Name of Established I  12 Further Description of on the small sect months work began an overhead garage except at the nor	Eligible? No ::  14 District Yes X Potent'!? No ::  District  Important Features Bu ion at the north on the larger side door. Glass di	27. Other Surveys in Which Included  ilding permits indicate that construend of this building, as an office ection to the south, the garage are splay windows run across the reaminubeen filled in with glass blocks.	By What?  40. Visible from Public Road?  41. Distance from and Frontage on Road approx. 65 feet on Walnut  ruction was started first area. Within two ea. Each section has nder of the facade,
1. On National Yes   1 Register? No X!  3. Part of Estab. Yes   1 Hist. Dist.? No X!  5. Name of Established ( 12. Further Description of on the small sect months work began an overhead garage except at the nor rises in a gentle	Eligible? No ::  14 District Yes x Potent'!? No ::  District  Important Features But ion at the north on the larger see door. Glass ditth end which has curve and has st	27. Other Surveys in Which Included  ilding permits indicate that construend of this building, as an office ection to the south, the garage are splay windows run across the reaminubeen filled in with glass blocks.	40. Visible from Yes!X Public Road? No!!  41. Distance from and Frontage on Road approx. 65 feet on Walnut ruction was started first area. Within two ea. Each section has nder of the facade, The parapet wall
Register? No X!  3. Part of Estab. Yes     Hist. Dist.? No X!  5. Name of Established (  42. Further Description of on the small sect months work began an overhead garage except at the nor rises in a gentle  43. History and Significant	Eligible? No ::  14. District Yes x Potent'!? No ::  District  Important Features Bu ion at the north on the larger see door. Glass dith end which has curve and has st  Ce The building o	ilding permits indicate that constrend of this building, as an office ection to the south, the garage are splay windows run across the reaminate been filled in with glass blocks. one coping.	40. Visible from Public Road? No!:  41. Distance from and Frontage on Road approx. 65 feet on Walnut  ruction was started first area. Within two ea. Each section has nder of the facade, The parapet wall  Sales Company.
Register? No X:  3. Part of Estab. Yes     Hist. Dist.? No X:  5. Name of Established ( 12. Further Description of on the small sect months work began an overhead garage except at the nor rises in a gentle  13. History and Significant ( 14. Description of Environche north, south, and s	Eligible? No ::  14 District Yes X Potent'!? No ::  Important Features Bu ion at the north on the larger size door. Glass ditth end which has curve and has store The building of the building of the buildings and east are other.	ilding permits indicate that constrend of this building, as an office ection to the south, the garage are splay windows run across the reaminate been filled in with glass blocks. one coping.  riginally housed the NS Automobile	40. Visible from Public Road? No!:  41. Distance from and Frontage on Road approx. 65 feet on Walnut  ruction was started first area. Within two ea. Each section has nder of the facade, The parapet wall  Sales Company.
Register? No X!  3. Part of Estab. Yes     Hist. Dist.? No X!  5. Name of Established I  12. Further Description of on the small sect months work began an overhead garage except at the nor rises in a gentle  13. History and Significant the north, south, and the north south	Eligible? No ::  14 District Yes x Potent'!? No ::  District  Important Features Bu ion at the north on the larger see door. Glass dith end which has curve and has store The building of the building of the buildings and east are other the second control of the buildings.	ilding permits indicate that construend of this building, as an office ection to the south, the garage are splay windows run across the reamin been filled in with glass blocks. one coping.  riginally housed the NS Automobile  A surface parking lot is west of the commercial buildings.	40. Visible from Public Road? No!:  41. Distance from and Frontage on Road approx. 65 feet on Walnut  ruction was started first area. Within two ea. Each section has nder of the facade, The parapet wall  Sales Company.
Register? No X:  Register? No X:  Part of Estab Yes II Hist. Dist.? No k!  Name of Established II  Further Description of on the small sect months work began an overhead garage except at the nor rises in a gentle  History and Significant A. Description of Environ he north, south, and the south of the south, and the south of the	Eligible? No ::  14 District Yes x Potent'!? No ::  District  Important Features Bu ion at the north on the larger see door. Glass dith end which has curve and has store The building of the building of the buildings and east are other the second control of the buildings.	ilding permits indicate that construend of this building, as an office ection to the south, the garage are splay windows run across the reamin been filled in with glass blocks. one coping.  riginally housed the NS Automobile  A surface parking lot is west of the commercial buildings.	A0. Visible from Yes!X Public Road? No!:  41. Distance from and Frontage on Road approx. 65 feet on Walnut  ruction was started first area. Within two ea. Each section has nder of the facade, The parapet wall  Sales Company.  46. Prepared by
Register? No X:  3 Part of Estab. Yes     Hist. Dist.? No X:  5 Name of Established (  2 Further Description of on the small sect months work began an overhead garage except at the nor rises in a gentle  3. History and Significant (  4. Description of Environment of the south, and the south and th	Eligible? No ::  14 District Yes x Potent'!? No ::  District  Important Features Bu ion at the north on the larger see door. Glass dith end which has curve and has store The building of the building of the buildings and east are other the second control of the buildings.	ilding permits indicate that construend of this building, as an office ection to the south, the garage are splay windows run across the reamin been filled in with glass blocks. one coping.  riginally housed the NS Automobile  A surface parking lot is west of the commercial buildings.	A0. Visible from Public Road? No!:  40. Visible from Public Road? No!:  41. Distance from and Frontage on Road approx. 65 feet on Walnut  ruction was started first area. Within two ea. Each section has nder of the facade, The parapet wall  Sales Company.  46. Prepared by Piland



Landmarks Commission

49 Revision Date(s)

48. Date 4/13/82 4. Present Name(s)

1. No.	A CONTRACTOR OF THE PARTY OF	VENTORY ent Name(s)	10000
23-B		23-27 Walnut	-
2 County			
Jackson		er Name(s)	
Landmarks Commissi	MT #69-19 Ex:	ide Battery Depot	
6 Specific Location	The state of the s	16. Thematic Category	28. No. of Stories 2
1623-27 Walnut 56			29. Basement? Yes IX
8	sulding	17. Date(s) or Period .	Noi
	U	1916	30. Foundation Material
Kansas City, Misso	d, Township & Vicinity	18 Style or Design	31. Wall Construction
3. Site Plan with North Arr		19. Architect or Engineer	masonry UD
NI.		Herman Stroeh	32. Roof Type & Material
A		20. Contractor or Builder	flat; tar & gravel qq
11		Fogel Const. Co.; Alex Kinghorn	33. No. of Bays Front E Side
3		21. Original Use, if apparent commercial OSE	Front 5 Side
DALNU		22. Present Use	brick 30
1 4		commercial	35. Plan Shape rectangular
EAST	17TH ST	23 Ownership Public   Private	36. Changes Addition : (Explain Altered ! in #42) Moved :
		24. Owner's Name & Address, if known	37. Condition Interior
	DTM		Exterior
Lat. Long.		25. Open to Yes↓	38. Preservation Yes
10. Site!:	Structure	25. Open to Yes x Public? No 11	Underway? No :X
Building Ix	Object	26. Local Contact Person or Organization	39. Endangered? Yes I
11. On National Yes I i	12 Is II Yes xx	Landmarks Commission	By What? No IX
Register? No 1x	Eligible? No 11	27. Other Surveys in Which Included	- X
Hist. Dist.? No 14	14. District Yes AA Potent'l? No		40. Visible from Yes!X Public Road? No !
15. Name of Established Di	strict		41. Distance from and
			Frontage on Road
Particular Section 1		ile the building's primary facade	70 feet on Walnut
story pilasters that	t terminate in st	the south facade. Bays are definence. Fenestration of the building ectangular windows. The building to	on the first and
43. History and Significance	This building	was erected at a cost of \$20,000.	The first tenant was the
Exide Battery Depot		210 2002223 300 0 3220 22 (22,122	the read to latter the late.
44. Description of Environm	ent and Outbuildings	surface parking lot is west of th	is building. To the
north, south, and ea	ast are other com	mercial buildings.	13 bullaring. To the
45 Sources of Information			46. Prepared by
WP #57731		A	Piland /Uguccioni
Western Contractor	, Feb. 2, 1916, p	. 16.	47. Organization



48. Date 8/2/83

49. Revision Date(s)

2 County

1. No. 39-A		VENTORY  ent Name(s)		
2. County	N	ickols Store Fixture		39
Jackson	#60 17	er Name(s)		A
Landmarks Commission	"05 2.	Caylor Building-nane		
6. Specific Location		16. Thematic Category	28. No. of Stories 5	Jac
1701-03 Walnut		030 050 17. Date(s) or Period	29. Basement? Yes   No   No	Jackson
7 City or Town If Rural, Tow	nship & Vicinity	18. Style or Design	31. Wall Construction	The state of the s
Kansas City, Missouri  B. Site Plan with North Arrow		19. Architect or Engineer Olhes	masonry (1)	
F. 17 Th J	-	Root & Siemens (attrib) 3040	32. Roof Type & Material The flat; tar & gravel 90	
1		21. Original Use, if apparent parch	33. No. of Bays Front 3 Side	
2		warehouse DAH St	34. Wall Treatment brick; stone 30	1701
14.		Commercial	35. Plan Shape rectangular	1-0
3		23 Ownership Public !! Private lx	36. Changes Addition : (Explain Altered ! : Moved !	-03 Walnut
		24. Owner's Name & Address, if known	37. Condition	alnu
9. Coordinates UTM Lat.			Interior good	14
Long.  Site !:	Structure I	25. Open to Yes XX Public? No 1	38. Preservation Yes : No :X	
Building X 1	Object	26. Local Contact Person or Organization Landmarks Commission	39. Endangered? Yes II By What? No IX	
3. Part of Estab. Yes II 14.	District Yes XX	27. Other Surveys in Which Included	40. Visible from Yes !*	
Hist. Dist.? No XX  5. Name of Established District	Potent'l? No ! .		Public Road? No 1:	
			Frontage on Road 50 feet on Walnut	
for its surface ornames rectangular windows, wi band course separates third and fourth storie three Palladian windows projecting dentiled six parapet wall and is supparapet wall and is supported by Goods Company. The retailing companies to for this building becausely.  14. Description of Environment and	ith multipand the second from	building relies heavily on Classic ree compound brick arches rise two red flanking sidelights and transoms rom third stories. Tiered rectanged by decorative brick bands. The fare intricate moldings. The base of by acanthus brackets. A stone stronsoles that are deeply undercut with as erected as a warehouse facility or Dry Goods firm was one of the ear Kansas City. Root & Siemens are a same time as the construction of the cont for the Taylor Dry Goods Store Surface parking lots are easial buildings are to the north	stories and contain  a. A projecting stone  alar windows on the  fourth story features  of the windows rest on a  ring course defines the  ith involved (cont'  for the John Taylor  rliest and largest  ttributed as architects  is building they were in-  at 11th and Main.  t and west of this	
5 Sources of Information	L Commercia	ar burrurngs are to the north	46. Prepared by	
WP #20853	n n 1111	1002 - 27	Uguccioni	
Kansas City Architect Kansas City Star, Febr			47. Organization Landmarks Commission	

HISTORIC INVENTORY SHEETS 1701-03 Walnut Page 2 JA-AS-008-1470

42. (cont'd) Sullivanesque ornament. The brick arches, framed tiered windows, and Palladian windows are repeated on the north facade. A square tower with the raised relief spelling "Taylor" is placed at the east end of the north facade.



-	
0	
-	

G & G Engine Rebuilders - Inc.  G & G Engine Rebuilders - Inc.  5 Other Name(s)  Grant-Reo-Elgin Service Station  1705-07 Walnut  17 Date(s) or Period 1917  30 Foundation Material  7 City or Town II Rural Township & Vicinity  8 Site Plan with North Arrow  19 Architect or Engineer  20 Contractor or Builder George L. Brown & Son  21 Original Use, if apparent COMMERCIAL OF  22 Present Use Commercial 23 Ownership Public II Private Li  13 Owner's Name & Address, if known  37 Condition Interior Exterior — Good Altered I In On National Yes II 12 Ist II Yes XX Register? No IX Register? No IX Site Plan With District  14 District Yes XX Register? No IX Potential? No IX Site Plan Rebuilders - Inc.  5 Other Name(s) Grant-Reo-Elgin Service Station Private 19 Architect or Engineer  20 Contractor or Builder George L. Brown & Son 21 Original Use, if apparent COMMERCIAL OF 22 Present Use Commercial 23 Owner's Name & Address, if known  36 Condition Interior Exterior — Good Ves XI Public? No IX Potential? Yes XX Register? No IX Potential? No IX Potential? No IX Potential? No IX District Yes XX Register? No IX Potential? No IX District Yes XX Register? No IX Potential? No IX Potential? No IX District Yes XX Public Road? No IX District Form and Frontage on Road Frontage on Road Footage on Road Frontage on Road Footage
Jackson   Location of Negatives MT #69-18   Grant-Reo-Elgin Service Station   Marchitect   Commission
Continued   Communication   Continued
29. Basement?   Yest   No   17. Date(s) or Period   1917   30. Foundation Material   30. Foundation Material   30. Foundation Material   31. Wall Construction   31. Wall Construction   32. Rool Type & Material   7. Oater   7. Oat
17. Date(s) or Period 1917  30. Foundation Material 31. Wall Construction masonry 32. Roof Type & Material Plat; tar & gravel 33. No. of Bays Front 3 Side 34. Wall Treatment COMMERCIAL 22. Present Use commercial 23. Ownership Public 1 Private 2  24. Owner's Name & Address. if known  25. Open to Public?  26. Local Contact Person or Organization Landmarks Commission Date of Established District  Part of Established District  17. Date(s) or Period 19. To Pate (so Date(so Date(so Date)) 19. Architect or Engineer 20. Contractor or Builder George L. Brown & Son 21. Original Use, if apparent COMMERCIAL OF 22. Present Use 23. Roof Type & MaterialCype 14. Wall Treatment 24. Wall Treatment 25. Changes (Explain 16. Changes 17. Original Use, if apparent COMMERCIAL OF 25. Open to Public or Engineer 26. Changes 27. Condition 18. Style or Design 28. Roof Type & MaterialCype 18. Wall Construction 19. Architect or Engineer 29. Roof Type & MaterialCype 14. Wall Treatment 20. Contractor or Builder 21. Explain 22. Roof Type & MaterialCype 14. Wall Treatment 22. Roof Type & MaterialCype 14. Wall Treatment 29. Roof Type & Mate
City or Town Kansas City, Missouri  Site Plan with North Arrow  19. Architect or Engineer  20. Contractor or Builder George L. Brown & Son 21. Original Use, if apparent COMMERCIAL 22. Present Use commercial 23. Ownership  24. Owner's Name & Address, if known  25. Open to Public?  26. Local Contact Person or Organization Dollect   Doll
Site Plan with North Arrow  19. Architect or Engineer  20. Contractor or Builder George L. Brown & Son  21. Original Use, if apparent COMMERCIAL COMMERCIAL 22. Present Use commercial  23. No. of Bays Front 3. Side  34. Wall Treatment stucco 35. Plan Shape rectangular 36. Changes (Explain Altered in #42)  40. Owner's Name & Address. if known  37. Condition Interior Exterior good  25. Open to Public?  Altered in #42)  And Wall Treatment Stucco  37. Condition Interior Exterior good  25. Open to Public?  And Wall Treatment Stucco  37. Condition Interior Exterior good  26. Local Contact Person or Organization Danational Yes   12 is it Public?  26. Local Contact Person or Organization Landmarks Commission  27. Other Surveys in Which Included  40. Visible from Public Road?  41. Distance from and Frontage on Road
20. Contractor or Builder George L. Brown & Son 21. Original Use, if apparent COMMERCIAL  22. Present Use commercial 23. Ownership Public   Private Li  Long.  Coordinates Lat. Long.  Site   Structure   Building L Object   Building L Object   Commarks Commission  Con National Yes   Building L Commarks Commission  Con National Yes   Commarks Commission  Commarks Commission  Con National Yes   Commarks Commission  Commission  Commarks Commission  Commarks Commission  Commarks Commission  Commission  Commarks Commission  Commarks Commission  Commarks Commission  Commarks Commission  Commarks Commission  Commission  Commarks Commission  Commarks Commission  Commarks Commission  Commission  Commarks Commission  Commarks Commission  Commission  Commarks Commission  Commarks Commission  Commissi
20. Contractor or Builder George L. Brown & Son 31. No. of Bays Front 3 Side 32. Wall Treatment Stucco 35. Plan Shape rectangular 36. Changes Stucco 37. Condition Street in May 1  24. Owner's Name & Address, if known  Site: Building Ix  Condition Interior Exterior good  25. Open to Public?  Structure: Building Ix  Object:  On National Yes: Structure: Building Ix  On National Yes: It is it Yes XX Eligible? No:  Part of Established District  Name of Established District  Page 16 Established District  Page 27. Other Surveys in Which Included  18. Tar & grave!  33. No. of Bays Front 3 Side  34. Wall Treatment Stucco  35. Plan Shape rectangular  36. Changes (Explain in #42) Moved  Altered In #42  26. Condition Interior Exterior good  17. Condition Interior Exterior good  26. Local Contact Person or Organization Public?  27. Other Surveys in Which Included  40. Visible from Yes Stablished Public Road?  41. Distance from and Frontage on Road
George L. Brown & Son  21. Original Use, if apparent COMMERCIAL  22. Present Use commercial  23. Ownership  Public   Private   Private   Public   Public   Private   Public   Pub
21. Original Use, if apparent COMMERCIAL OF  22. Present Use commercial 23. Ownership Public   Private   24. Owner's Name & Address, if known  25. Open to Public?  Site   Building   On National Yes   Do National Yes   Register? No   No   No   No   No   No   No   No
23 Ownership Public   Private   36. Changes (Explain in #42) Moved   24. Owner's Name & Address,   if known   27. Open to   Public   Public   Private   Public   Private   Public   Private   Privat
23 Ownership   Public
23 Ownership Public   Private   36. Changes (Explain in #42) Altered   in #42) Alter
Coordinates   UTM   24. Owner's Name & Address, if known   37. Condition   Interior   Exterior   Good   G
Coordinates   UTM   25. Open to   Yes xi   No i   Structure   Object   Ob
Coordinates Lat. Long.  Site!: Structure!: Public?  Building!: Object!!  On National Yes!: 12 is!! YesXX Eligible? No!!  Part of Estab. Yes!! 14. District Yes XX Potent'!? No!: X  Name of Established District  Name of Established District  Structure!: 25. Open to Public? No!! 25. Open to Public?  Landmarks Commission  27. Other Surveys in Which Included  Exteriorgood
Site !: Structure !: Object !! 25. Open to Public? No !! 38. Preservation Underway? No !! 26. Local Contact Person or Organization 27. Other Surveys in Which Included 27. Other Surveys in Which Included 28. Visible from Public Road? No !! 27. Other Surveys in Which Included 29. Visible from Public Road? No !! 27. Other Surveys in Which Included 29. Visible from Public Road? No !! 27. Other Surveys in Which Included 29. Visible from Public Road? No !! 27. Other Surveys in Which Included 29. Visible from Public Road? No !! 27. Other Surveys in Which Included 29. Visible from Public Road? No !! 27. Other Surveys in Which Included 29. Visible from Public Road? No !! 28. Preservation Ves !! 38. Preservation Underway? No !! 39. Endangered? By What? Surveys !! 39. Endangered? By What? No !! 39. Endange
Site !: Structure   Public? No ! Underway? No !  Building   Object !
Building   No   26. Local Contact Person or Organization   39. Endangered? Yes   By What?   No   No   No   No   No   No   No   N
Register? No 1.1 Eligible? No 1.1 27. Other Surveys in Which Included  Part of Estab. Yes 1.1 14. District Yes XX Potent'1? No 1.1 Potent'1? No 1.1 No 1.2 Name of Established District  Name of Established District  27. Other Surveys in Which Included  40. Visible from Yes to Public Road? No 1.2
Part of Estab. Yes 11 Hist. Dist.? No 11 Name of Established District  Yes XX Public Road? Yes 5 Public Road? No 1  11. Distance from and Frontage on Road
Name of Established District  Public Road? No !  All Distance from and Frontage on Road
Frontage on Road
JO TEEL OIL WAITIGE
torefront bays. An entrance is placed at the north end of the building. The stucco wall surface of the parapet wall terminates in stone coping framing a wooden band that defines he shaped parapet.

State Historical Survey and Planning Office, 909 University Avenue, Suite 215,



· N	Commence of the Commence of th	VENTORY	A-AS-008-1472	_
1. No. 39-C		sent Name(s)	*	w
2. County	1	709 Walnut		9-(
Jackson		ner Name(s)		1
3 Location of Negatives MT Landmarks Commission	#69-16 Sa	alvation Army Industrial Home and S	tore name	
6. Specific Location	4	16. Thematic Category	28. No. of Stories 2	
1709 Walnut		030 050	29. Basement? Yes 1	Jac
		17. Date(s) or Period	No I	Jackson
7 City or Town II Burst T	awashin 9 Visiantu	1909 18. Style or Design	30. Foundation Material	nc
7. City or Town II Rural, T Kansas City, Missouri	ownship & vicinity	50 64	31. Wall Construction	
8. Site Plan with North Arrow		19. Architect or Engineer Oches	masonry UD	
		Shepard and Farrar 30 40	12. Roof Type & Material Ft Pe flat; tar & gravel go	
M		20. Contractor or Builder James T. Patterson	33. No. of Bays	
N 1 -		21. Original Use, if apparent	Front 3 Side	3
1 5		commercial/apartmentONE 0/B	34. Wall Treatment	709 Walnut
3		22. Present Use	brick 30	Wa
3		unknown	35. Plan Shaperectangular	Waln
1 3		23 Ownership Public     Private	36. Changes Addition : (Explain Altered :X	ut
4		24. Owner's Name & Address,	in #42) Moved i	
		if known	37. Condition	
9 Coordinates UTM			Interior	
Lat. Long.		25. Open to Yes II	Exterior good  38 Preservation Yes	
10. Site ! :	Structure 1	Public? No x	Underway? No ix	
Building x:	Object	26. Local Contact Person or Organization	39. Endangered? Yes I	1
	Is It Yes X	Landmarks Commission	By What? No 1 x	
Register? No X!	Eligible? No !!	27. Other Surveys in Which Included		
3 Part of Estab. Tes 11 14	Potent'l? No:		40. Visible from Yes!X Public Road? No!!	
Hist. Dist.? No x1				
Hist. Dist.? No x1	t		41. Distance from and	
Hist. Dist.? No x1	1		Frontage on Road	
Hist. Dist.? No ½1			Frontage on Road 50 feet on Walnut	
Hist. Dist.? No x1  15. Name of Established District  12. Further Description of Impo	rtant Features Th	me first floor of the west facade is	Frontage on Road 50 feet on Walnut s composed of three	
Hist. Dist.? No x1  15. Name of Established District  42. Further Description of Impostorefront, panels with	rtant Features Th	placed at the north end. A stone	Frontage on Road 50 feet on Walnut s composed of three sills runs below	
42. Further Description of Impostrated with three	rtant Features Th	e placed at the north end. A stone burse is placed above them. The se- de windows. A stone string course	Frontage on Road 50 feet on Walnut s composed of three sills runs below cond story is runs below the windows.	
Hist Dist? No x1  15. Name of Established District  12. Further Description of Impostorefront panels with the windows, and a st fenestrated with three A shaped parapet term	rtant Features Th	placed at the north end. A stone	Frontage on Road 50 feet on Walnut s composed of three sills runs below cond story is runs below the windows.	
42. Further Description of Impostrated with three	rtant Features Th	e placed at the north end. A stone burse is placed above them. The se- de windows. A stone string course	Frontage on Road 50 feet on Walnut s composed of three sills runs below cond story is runs below the windows.	
42. Further Description of Impostorefront panels with the windows, and a st fenestrated with three A shaped parapet term	rtant Features Th	e placed at the north end. A stone burse is placed above them. The se- de windows. A stone string course	Frontage on Road 50 feet on Walnut s composed of three sills runs below cond story is runs below the windows.	
Hist Dist.? No x1  15. Name of Established District  42. Further Description of Impostorefront panels with the windows, and a st fenestrated with three A shaped parapet term five story building.	rtant Features The ch an entrance cone string co se Chicago-sty minates in sto	e placed at the north end. A stone burse is placed above them. The se- de windows. A stone string course	Frontage on Road 50 feet on Walnut s composed of three sills runs below cond story is runs below the windows. structed to support a	
Hist. Dist.? No x1  15. Name of Established District  42. Further Description of Impostore front panels with the windows, and a statement of the story building.  43. History and Significance T.	rtant Features The chan entrance cone string cone e Chicago-styninates in stockers.	e placed at the north end. A stone burse is placed above them. The service windows. A stone string course one coping. The foundation was cons	Frontage on Road 50 feet on Walnut s composed of three sills runs below cond story is runs below the windows. structed to support a	
Hist. Dist.? No x1  15. Name of Established District  42. Further Description of Impostore front panels with the windows, and a statement of the story building.  43. History and Significance T.	rtant Features The chan entrance cone string cone e Chicago-styninates in stockers.	e placed at the north end. A stone curse is placed above them. The service windows. A stone string course one coping. The foundation was constructed by the Salvation Ar	Frontage on Road 50 feet on Walnut s composed of three sills runs below cond story is runs below the windows. structed to support a	
Hist. Dist.? No x1  15. Name of Established District  12. Further Description of Impostore front panels with the windows, and a statement of the story building.  13. History and Significance T.	rtant Features The chan entrance cone string cone e Chicago-styninates in stockers.	e placed at the north end. A stone curse is placed above them. The service windows. A stone string course one coping. The foundation was constructed by the Salvation Ar	Frontage on Road 50 feet on Walnut s composed of three sills runs below cond story is runs below the windows. structed to support a	
Hist. Dist.? No x1  15. Name of Established District  42. Further Description of Impostore front panels with the windows, and a st fenestrated with three A shaped parapet term five story building.  43. History and Significance Ton the 2nd floor with	ch an entrance cone string cone e Chicago-sty minates in sto	e placed at the north end. A stone curse is placed above them. The service windows. A stone string course one coping. The foundation was consumasted by the Salvation Arel outlet on the 1st floor.	Frontage on Road 50 feet on Walnut s composed of three sills runs below cond story is runs below the windows. structed to support a	
Hist. Dist.? No x1  15. Name of Established District  42. Further Description of Impostorefront panels with the windows, and a st fenestrated with three A shaped parapet term five story building.  43. History and Significance Ton the 2nd floor with the 2nd flo	rtant Features The chan entrance cone string cone e Chicago-sty minates in stock this building what a commercial and Outbuildings	e placed at the north end. A stone burse is placed above them. The service windows. A stone string course one coping. The foundation was constructed by the Salvation Arel outlet on the 1st floor.  A surface parking lot is east of the string course of the string	Frontage on Road 50 feet on Walnut s composed of three sills runs below cond story is runs below the windows. structed to support a my and used for housing this building. To the	
Hist. Dist.? No x1  15. Name of Established District  12. Further Description of Impostorefront panels with the windows, and a st fenestrated with three A shaped parapet term five story building.  13. History and Significance Ton the 2nd floor with the 2nd flo	rtant Features The chan entrance cone string cone e Chicago-sty minates in stock this building what a commercial and Outbuildings	e placed at the north end. A stone curse is placed above them. The service windows. A stone string course one coping. The foundation was consumasted by the Salvation Arel outlet on the 1st floor.	Frontage on Road 50 feet on Walnut s composed of three sills runs below cond story is runs below the windows. structed to support a my and used for housing this building. To the	
Hist. Dist.? No x1  15. Name of Established District  12. Further Description of Impostorefront panels with the windows, and a st fenestrated with three A shaped parapet term five story building.  13. History and Significance Ton the 2nd floor with the 2nd flo	rtant Features The chan entrance cone string cone e Chicago-sty minates in stock this building what a commercial and Outbuildings	e placed at the north end. A stone burse is placed above them. The service windows. A stone string course one coping. The foundation was constructed by the Salvation Arel outlet on the 1st floor.  A surface parking lot is east of the string course of the string	Frontage on Road 50 feet on Walnut s composed of three sills runs below cond story is runs below the windows. structed to support a my and used for housing this building. To the	
Hist. Dist.? No x1  15. Name of Established District  12. Further Description of Impostorefront panels with the windows, and a st fenestrated with three A shaped parapet term five story building.  13. History and Significance Ton the 2nd floor with the 2nd flo	rtant Features The chan entrance cone string cone e Chicago-sty minates in stock this building what a commercial and Outbuildings	e placed at the north end. A stone burse is placed above them. The service windows. A stone string course one coping. The foundation was constructed by the Salvation Arel outlet on the 1st floor.  A surface parking lot is east of the string course of the string	Frontage on Road 50 feet on Walnut s composed of three sills runs below cond story is runs below the windows. structed to support a  may and used for housing his building. To the is to the south.	
Hist. Dist.? No x1  15. Name of Established District  12. Further Description of Impostore front panels with the windows, and a state fenestrated with three A shaped parapet term five story building.  13. History and Significance on the 2nd floor with the 2nd floor with the 2nd floor with the 2nd floor with the 2nd west are otherworth and west are otherworth and west are otherworth.	rtant Features The chan entrance cone string cone e Chicago-sty minates in stock this building what a commercial and Outbuildings	e placed at the north end. A stone burse is placed above them. The service windows. A stone string course one coping. The foundation was constructed by the Salvation Arel outlet on the 1st floor.  A surface parking lot is east of the string course of the string	Frontage on Road 50 feet on Walnut s composed of three sills runs below cond story is runs below the windows. structed to support a my and used for housing this building. To the	
Hist. Dist.? No x1  15. Name of Established District  12. Further Description of Imposes storefront panels with the windows, and a state of the windows, and a state of the story building.  13. History and Significance on the 2nd floor with the 2nd floor with the 2nd floor with the 2nd west are otherwise of Information wp #39686  15. Sources of Information wp #39686  16. P #9278	ch an entrance cone string cone string cone control cone control contr	e placed at the north end. A stone burse is placed above them. The service windows. A stone string course one coping. The foundation was consumed as a surface parking lot is east of the buildings. A surface parking lot	Frontage on Road 50 feet on Walnut s composed of three sills runs below cond story is runs below the windows. structed to support a  may and used for housing this building. To the is to the south.  46. Prepared by Piland/Uguccioni 47. Organization	
Hist. Dist.? No x1  15. Name of Established District  12. Further Description of Imposes storefront panels with the windows, and a state of fenestrated with three A shaped parapet term five story building.  13. History and Significance on the 2nd floor with th	ch an entrance cone string cone string cone control cont	e placed at the north end. A stone burse is placed above them. The service windows. A stone string course one coping. The foundation was consumed to the service of the ser	Frontage on Road 50 feet on Walnut s composed of three sills runs below cond story is runs below the windows. structed to support a  may and used for housing this building. To the is to the south.  46. Prepared by Piland/Uguccioni	



County   Jackson   1704-06 Walnut; 1708 Walnut   1704-06 Walnut; 1708 Walnu	. <b>No</b> . 38-н		sent Name(s)	
Some state   Som	10.00		1710 Walnut	
Location of Negatives MT #29-16   Landmarks Commission	Jackson	5 011	er Name(s)	
16. Themstic Category   17. Dates) or Period   19. Dates or Period   19. D		MT #29-16 17		
17. Date(s) or Period 1900 30. Foundation Material 1900 31. Wall Construction 1900 32. Roof Type & Material 1900 32. Roof Type & Material 1900 33. No of Bays 1900 1900 1900 1900 1900 1900 1900 190	THE RESERVE OF THE PERSON NAMED IN		16. Thematic Category	28. No. of Stories 2
Coordinates Lat. Long  Coordinates Lung  Site 1 2 Structure   Building   X  On National Yes   X  Part of Established District  Part of Established District  Part of Established District  Further Description of Important Features The primary facade faces east and is characterized by a pertends across the west facade.  18 Style or Design  18 Style or Design  18 Style or Design  19 Architect or Engineer  20 Contractor or Builder Matt O'Connell  21 Original Use, if apparent Commercial  22 Present Use Commercial  23 Ownership  Public   Private  24 Owner's Name & Address, if known  25 Open to Public Proving Style Preservation Underway?  26 Local Contact Person or Organization Symbols  27 Other Surveys in Which Included  28 Part of Established District  Purther Description of Important Features  Primary facade faces east and is characterized by a preservation of the public Proving Contact Person of Organization of Frontage on Road So feet on Walnut  Purther Description of Important Features  Purther Description of Important Features The primary facade faces east and is characterized by a preservation of the purpher with segmental arch sash windows. The parapet wall is shaped and terminates in stone coping. Decorative brick work consisting of horizontal banding extends across the west facade.		10 11		
Cordinates Lut. Long.  Site: Structure: No I Structure: No I Suite: No I Structure: No I Suite: No I Structure: No I Structure	1710 Walnut Scre		· ·	
19 Architect or Engineer   30 40   32. Roof Type & Math mat   19 Architect or Builder   33. No. of Bays   12 former   14 former   15 for	City or Town . If Au		18. Style or Design	
20. Contractor or Builder Matt O'Connell 21. Original Use, if apparent commercial 22. Present Use commercial 23. No. of Bays Front 3. Side 34. Wall Treatment brick 35. Plan Shape rectangular 36. Changes Addition: Private L Explain in #42) 36. Changes Addition: Private L Explain in #42) 37. Condition interior Exterior good 38. Preservation Underway? No. ix 10. National Yes   12 Is It Yes   X Register? No. ix 11. District Yes   X Potentral Yes   Y No. ix 12. Other Surveys in Which Included 37. Condition Interior Exterior good 38. Preservation Underway? No. ix 10. National Yes   12 Is It Yes   X Register? No. ix 11. District Yes   Y No. ix 12. Other Surveys in Which Included 37. Condition Interior Exterior good 18. Order Surveys in Which Included 40. Visible from Yes   Y Public Road? No. it 19. Part of Established District 41. District Yes   Y Public Road? No. it No.				
20. Contractor or Builder Matt O'Connell 21. Original Use, if apparent commercial 22. Present Use commercial 23. No. of Bays Front 3 Side 34. Wall Treatment brick Coordinates Commercial 24. Owner's Name & Address, if known  Coordinates Let. Long.  Site   Structure   Building   Dublic   Public   Public   Public   No   Site   Structure   Building   Dublic   Public   No   Building   Contact Person or Organization Landmarks Commission 27. Other Surveys in Which Included  28. Perservation Yes   Part of Estab Yes   1	Site Plan with North A	rrow		
Matt O'Connell   21. Original Use, if apparent   33. No. of Bays   Front   3   Side		N		
Commercial   22 Present Use   23 Ownership   Public   Private   24 Owner's Name & Address,   16 Known   25 Open to   Public   Public   Moved   16 Changes   Addition   (Explain   Altered   In #42)   Moved   17 Condition   Interior   Exterior   Good   25 Open to   Public   Public   Ves   No   1	1	N		33. No. of Bays
22 Present Use   23 Ownership   Public   24 Owner's Name & Address,   1 known   24 Owner's Name & Address,   1 known   25 Open to   Public?   25 Open to   Public?   26 Local Contact Person or Organization   27 Other Surveys in Which Included   27 Other Surveys in Which Included   28 Endangered?   No   1				
Coordinates Lat. Long.    Site   Structure   Public   Private   Structure   Public   Structure   Public	3	2		77.
23 Ownership   Public     36. Changes   Addition   Altered   Moved		2		35. Plan Shape rectangular
Coordinates UTM Lat. Lony  Site: Structure: Object:		3		36. Changes Addition :
Coordinates Lal. Long  Site: Structure: Object: 1  On National Yes: 12 Is! Yes: X Register? No x  Fart of Established District  Name of Established District  Further Description of Important Features The Primary facade faces east and is characterized by a pentrally placed entrance door, flanked by rectangular multipaned windows on the first story. The second story is fenestrated with segmental arch sash windows. The parapet wall is shaped and terminates in stone coping. Decorative brick work consisting of horizontal banding extends across the west facade.		3		
Coordinates Lat. Long    Site   Structure   Object   Object   Object   Object   Object   On National Yes   12 is it Eligible? No   Eligible? No   Eligible? No   Other Surveys in Which Included   On National Yes   Object   Object				
Lat. Long  Site 1: Structure 1: Object 1: Object 1: Object 1: Object 1: On National Yes 1: Eligible? No 1: Eligible? No 1: Eligible? No 1: Eligible? No 1: District Yes 1: No 1: Part of Estab Yes 1: No 1: Potent'!? No 1: Name of Established District  Further Description of Important Features The primary facade faces east and is characterized by a netertally placed entrance door, flanked by rectangular multipaned windows on the first story. The second story is fenestrated with segmental arch sash windows. The parapet wall is shaped and terminates in stone coping. Decorative brick work consisting of horizontal banding extends across the west facade.	Coordinates	UTM		Interior
Site: Building ix Object: On National Yes: Register? No ix Eligible? No i: Hist. Dist.? No ix Name of Established District  Further Description of Important Features Entrally placed entrance door, flanked by rectangular multipaned windows on the first story. The second story is fenestrated with segmental arch sash windows. The parapet wall is shaped and terminates in stone coping.  Decorative brick work consisting of horizontal banding extends across the west facade.				
Building   x		Structure		
Register? No ix Eligible? No i:  Part of Estab. Yes	one i		26 Local Contact Person or Organization	39 Endangered? Ves I
Part of Estab. Yes   14. District Yes   X Potent'1? No   2. Name of Established District	Building Ix		20. Local Contact Person of Organization	35. Eliobilgered: les i
Name of Established District    Public Road? No	On National Yes II	12 Is It Yes :X	Landmarks Commission	
Further Description of Important Features The primary facade faces east and is characterized by a mentrally placed entrance door, flanked by rectangular multipaned windows on the first story. The second story is fenestrated with segmental arch sash windows. The parapet wall is shaped and terminates in stone coping. Decorative brick work consisting of horizontal banding extends across the west facade.	On National Yes     Register? No   x	12 Is It Yes :X Eligible? No : !	Landmarks Commission	By What? No b
Further Description of Important Features The primary facade faces east and is characterized by a contrally placed entrance door, flanked by rectangular multipaned windows on the first story. The second story is fenestrated with segmental arch sash windows. The parapet wall is shaped and terminates in stone coping. Decorative brick work consisting of horizontal banding extends across the west facade.	Register? No 1x	12 Is It Yes :X Eligible? No ::	Landmarks Commission	By What? No b
centrally placed entrance door, flanked by rectangular multipaned windows on the first story. The second story is fenestrated with segmental arch sash windows. The parapet wall is shaped and terminates in stone coping. Decorative brick work consisting of horizontal banding extends across the west facade.	Register? No 1x Part of Estab. Yes   1 Hist. Dist.? No 1x	12 Is It Yes IX Eligible? No II  14. District Yes IX Potent'!? No I	Landmarks Commission	40. Visible from Public Road? No l
History and Significance The early use of this commercial building is undocumented.	Part of Established D. Name of Established D. Further Description of	12 Is It Yes IX Eligible? No I:  14. District Yes IX Potent'!? No I.  District  Important Features The	Landmarks Commission  27. Other Surveys in Which Included  e primary facade faces east and is	By What?  40. Visible from Public Road?  41. Distance from and Frontage on Road 50 feet on Walnut  Characterized by a 200
	Register? No 1x Register? No 1x Part of Estab. Yes   1 Hist. Dist.? No 1x Name of Established Controlly placed of the second story is and terminates in	12 Is It Yes IX Eligible? No II  14. District Yes IX Potent'I? No II  District  Important Features The entrance door, fla is fenestrated will stone coping. De	Landmarks Commission  27. Other Surveys in Which Included  e primary facade faces east and is anked by rectangular multipaned win th segmental arch sash windows. The	By What?  40. Visible from Public Road?  41. Distance from and Frontage on Road 50 feet on Walnut  Characterized by a mandadows on the first story are parapet wall is shaped
	Register? No 1x  Second Story in the second story	12 Is It Yes:X Eligible? No::  14. District Yes:X Potent'!? No::  District  Important Features The entrance door, flais fenestrated wirstone coping. De west facade.	Landmarks Commission  27. Other Surveys in Which Included  * e primary facade faces east and is anked by rectangular multipaned win th segmental arch sash windows. The ecorative brick work consisting of	By What?  40. Visible from Public Road?  41. Distance from and Frontage on Road 50 feet on Walnut characterized by a mandows on the first story me parapet wall is shaped horizontal banding
	Part of Estab. Yes     History and Significance  On National Yes     Register? No     No     No     Name of Established Controlly placed of the second story in the se	12 Is It Yes :X Eligible? No ::  14. District Yes :X Potent'!? No ::  District  Important Features The entrance door, flais fenestrated will stone coping. Do west facade.  Ce The early use	Landmarks Commission  27. Other Surveys in Which Included  e primary facade faces east and is anked by rectangular multipaned win th segmental arch sash windows. The ecorative brick work consisting of of this commercial building is under	By What?  40. Visible from Public Road?  41. Distance from and Frontage on Road 50 feet on Walnut characterized by a midows on the first story me parapet wall is shaped horizontal banding
	On National Yes   Register? No   X  Part of Estab. Yes   Hist. Dist.? No   X  Name of Established Control Placed entrally plac	12 Is It Yes :X Eligible? No ::  14. District Yes :X Potent'!? No ::  District  Important Features The entrance door, flais fenestrated wires stone coping. Do west facade.  The early use	Landmarks Commission  27. Other Surveys in Which Included  e primary facade faces east and is anked by rectangular multipaned win th segmental arch sash windows. The ecorative brick work consisting of of this commercial building is under the commercial building is	By What?  40. Visible from Public Road?  41. Distance from and Frontage on Road 50 feet on Walnut  characterized by a mandadows on the first story are parapet wall is shaped horizontal banding  documented.
	On National Yes   Register? No   X  Part of Estab. Yes   Hist. Dist.? No   X  Name of Established Control of Partner Description of Pentrally placed of the second story in terminates in extends across the extends across th	12 Is It Yes :X Eligible? No ::  14. District Yes :X Potent'!? No ::  District  Important Features The entrance door, flais fenestrated wires stone coping. Do west facade.  The early use	Landmarks Commission  27. Other Surveys in Which Included  e primary facade faces east and is anked by rectangular multipaned win th segmental arch sash windows. The ecorative brick work consisting of of this commercial building is under the commercial building is	By What?  40. Visible from Public Road?  41. Distance from and Frontage on Road 50 feet on Walnut  characterized by a mandadows on the first story are parapet wall is shaped horizontal banding  documented.
Sources of Information  A surface parking lot is also to the west.	On National Yes   Register? No   x  Part of Estab. Yes   I Hist. Dist.? No   x  Name of Established Control Placed entrally placed entrally placed entrally placed entrally placed entrally entrally indicates in extends across the extends across the entrally and Significant entrally entra	12 Is It Yes:X Eligible? No::  14. District Yes:X Potent'!? No::  District  Important Features The entrance door, flais fenestrated wirstone coping. Do west facade.  The early use ment and Outbuildings commercial buildings.	Landmarks Commission  27. Other Surveys in Which Included  e primary facade faces east and is anked by rectangular multipaned win th segmental arch sash windows. The ecorative brick work consisting of of this commercial building is under the commercial building is	By What?  40. Visible from Public Road?  41. Distance from and Frontage on Road 50 feet on Walnut  characterized by a mandadows on the first story are parapet wall is shaped horizontal banding  documented.  d south of this building to the west.
Sources of Information P #17151  A surface parking lot is also to the west.  46 Prepared by Piland/Uguccioni	On National Yes   Register? No   X  Part of Estab. Yes   I Hist. Dist.? No   X  Name of Established Control of Part ally placed of Phe second story in extends across the Extends across	12 Is It Yes:X Eligible? No::  14. District Yes:X Potent'!? No::  District  Important Features The entrance door, flais fenestrated wirstone coping. Do west facade.  The early use ment and Outbuildings commercial buildings.	Landmarks Commission  27. Other Surveys in Which Included  e primary facade faces east and is anked by rectangular multipaned win th segmental arch sash windows. The ecorative brick work consisting of of this commercial building is under the commercial building is	By What?  40. Visible from Public Road?  41. Distance from and Frontage on Road 50 feet on Walnut characterized by a mandows on the first story me parapet wall is shaped horizontal banding  documented.  46. Prepared by Piland/Uquccioni
o the east is a commercial building. A surface parking lot is also to the west.  Sources of Information  46. Prepared by	On National Yes   Register? No   X  Part of Estab. Yes   Hist. Dist.? No   X  Name of Established Control of Part ally placed of Phe second story in the second story	12 Is It Yes:X Eligible? No:  14. District Yes:X Potent'!? No:  District  Important Features The entrance door, flais fenestrated wires stone coping. Doe west facade.  The early use ment and Outbuildings commercial buildings.	Landmarks Commission  27 Other Surveys in Which Included  e primary facade faces east and is anked by rectangular multipaned win the segmental arch sash windows. The ecorative brick work consisting of this commercial building is under the segmental arch sash windows.  Surface parking lots are north and ag. A surface parking lot is also	By What?  40. Visible from Public Road?  41. Distance from and Frontage on Road 50 feet on Walnut characterized by a mandows on the first story are parapet wall is shaped horizontal banding.  documented.  46. Prepared by Piland/Uquccioni  47. Organization

State Historical Survey and Planning Office, 909 University Avenue, Suite 215,



1. No.	The second second second	VENTORY esent Name(s)		100
39-D	7	& B Sales Company; Eichenberg Equi	pment Sales Company	39-D
			pmene bares conf mi	Ď.º
Jackson Jackson Landmarks Commission	MT #69-14	19 Walnut; Street Building		
6. Specific Location		16. Thematic Category	28. No. of Stories 4	
1717 Walnut Shurt	Bulding		29. Basement? Yes IX	Jac
1717 Walnut Stud		17. Date(s) or Period . 1912 (alt. 1963)	No 1.	Jackson
7 City or Town If Rural, Kansas City, Missou	Township & Vicinity	18. Style or Design	31. Wall Construction	acath-sus
8. Site Plan with North Arro	w	19 Architect or Engineer Wilder & Wight	masonry UD	
	N	20. Contractor or Builder	32. Roof Type & Material Ft Pe flat; tar & gravel 99	
1	1/1	Swenson Const. Co.	33. No. of Bays	-
72	9 1	21. Original Use, if apparent	Front Side	17
3		commercial ODE AW	34. Wall Treatment 30 62	1717 Walnut
4		commercial	brick: terra cotta 35. Plan Shape rectangular	Wa
3		23 Ownership Public   Private lxt	36. Changes Addition 1: (Explain Altered XX	Lnu
		24. Owner's Name & Address,	in #42) Moved	43
		if known	37. Condition	
	гм		Interior good	
Lat. Long.		25. Open to Yes Ki	38. Preservation Yes	
Site!; Building	Structure   :	Public? No 11  26. Local Contact Person or Organization	Underway? No xx  39. Endangered? Yes I	
11. On National Yes     Register? No L!	12 Is It Yes & Eligible? No 1	Landmarks Commission	By What? No xx	
13. Part of Estab. Yes 11 14. District Yes X Hist. Dist.? No 11 Potent'1? No 11		27. Other Surveys in Which Included	40. Visible from Yes XX Public Road? No !!	
15. Name of Established Dis			41. Distance from and Frontage on Road	
			33 feet on Walnut	
horizontal bands ac	ross the facade by terra cotta	ne building faces west on Walnut. In the result of a 1962 remodeling of vertical panels that terminate in a shaped and is clad in terra cottage.	effort. The four story a segmental arch on the	Cinc. Hainels,
43. History and Significance Mortgage Company.	This building	was constructed for the Groves Bro	thers Real Estate and	
44. Description of Environme To the west and so		Surface parking lots are north and commercial buildings.	l east of this building.	
45 Sources of Information WP #36073			46. Prepared by	
WP #36073 BP #52608			Piland /Uguccioni 47. Organization	
BP #10653			Landmarks Commission	
BP #19693	20.00		48. Date 49. Revision Date(s)	
Western Contractor, 10, 1912, p. 15.	July		4/7/82	



47. Organization

48. Date

8/29/81

Landmarks Commission

49 Revision Date(s)

BP #64955A



BP #17013A

45 Sources of Information

WP #63883

BP #12656

Kansas City Star, Feb. 18, 1945.

Kansas City Star, July 8, 1945, p. P.

Western Contractor, April 21, 1920.

46 Prepared by

47. Organization

Landmarks Commission

49 Revision Date(s)

Piland

48. Date

3/13/84





Columbia, Missouri 65201

1/5/82



47. Organization

48. Date 6/1/84

Landmarks Commission

49. Revision Date(s)

WP #29497



1. No. 39-K		4. Present Name(s) Feigenbaum Pottery Company		39
Jackson Jackson Jackson Jackson Jackson Jackson Jackson	#69-10	ner Name(s)		39-K
6 Specific Location		16. Thematic Category	28. No. of Stories 3	1
		030 050	29. Basement? Yes !	
1737 Walnut Street Building		17. Date(s) or Period	No i	Jackson
7 City or Town II Rural, Township & Vicinity Kansas City, Missouri		18 Style or Design	31. Wall Construction	son
B. Site Plan with North Arro	)w	19. Architect or Engineer	masonry UD	
N		30 65 90	32. Roof Type & Material PC	
N		20. Contractor or Builder	flat: tar & gravel 99 33. No. of Bays Front 2 Side	
1		21. Original Use, if apparent		1737 1
3		commercial ODE	34. Wall Treatment 30 65	37
3		commercial	brick; concrete block	E
0		23 Ownership Public !!	35. Plan Shape rectangular	Walnut
3		Private X	36. Changes Addition : : (Explain Altered xx	Int
		24. Owner's Name & Address.	in #42) Moved	-
9 Coordinates UTM		if known	37. Condition Interior Exterior good	
Long.		25. Open to Yes IX	38. Preservation Yes	1
10. Site!:	Structure	Public? No 11	Underway? Nox	
Building IX	Object	26. Local Contact Person or Organization	39. Endangered? Yes !	1
11. On National Yes     Register? No  X	12 Is It Yes X. Eligible? No 11	Landmarks Commission of KC 27. Other Surveys in Which Included	By What? No bo	
13. Part of Estab. Yes     Hist. Dist.? No Id	14. District Yes X Potent'l? No !	es X 40. Visible from		
15. Name of Established District			41. Distance from and Frontage on Road 25 feet on Walnut	
Register? No IX  13 Part of Estab. Yes     Hist. Dist.? No IX  15. Name of Established Dis  42. Further Description of Ir placed on the firs	Eligible? No ::  14. District Yes X Potent'!? No ::  strict  nportant Features The floor. The wire	27. Other Surveys in Which Included  ne main facade faces west. An over adow areas in the second and third with decorative concrete block.	Public Road? No 11  41. Distance from and Frontage on Road 25 feet on Walnut  head garage door is	the statement of the supplemental framework the statement of the statement

44. Description of Environment and Outbuildings A service station is east of this building. To the west is a surface parking lot. Other commercial buildings are to the north and south.

45 Sources of Information WP#35033 BP#4829

46. Prepared by PILAND 47. Organization Landmarks Commission 48. Date 49. Revision Date(s) 12/26/84



1. No. 39-H	4. Present Name(s)	
2 County	Feigenbaum Pottery Company	
Jackson	5. Other Name(s)	
Location of Negatives MT #69- Landmarks Commission	-9	
Specific Location	16. Thematic Category	28. No. of Stories 2
1739 Walnut Street Bull	030 050	29. Basement? Yes I
or the real	17. Date(s) or Period	No 1.
City or Town If Rural, Townshi Kansas City, Missouri	ip & Vicinity 218. Style or Design	O/
		31. Wall Construction
Site Plan with North Arrow	19. Architect or Engineer 20065 40	masonry UD  32. Roof Type & Material + PP
	20. Contractor or Builder	flat; tar & gravel 94
	N	33. No. of Bays Front 3 Side
2 a	21. Original Use, if apparent commercial ODE	34. Wall Treatment 20 65
3	22. Present Use	brick; concrete block
74	commercial	35. Plan Shape rectangular
A	23 Ownership Public 日 Private 1本	36. Changes Addition i : (Explain Altered XX
	24. Owner's Name & Address,	in #42) Moved i
	if known	37. Condition Interior
Coordinates UTM		Exterior good
Long.	25. Open to Yes Ix	38. Preservation Yes
Site ! : Building ki	Structure 1: Public? No 11 Object 11 26 Local Contact Person or Organization	Underway? No XX
On National Yes   12 Is It	Yes X Landmarks Commission	39. Endangered? Yes I By What? No 1/1X
Register? No M Eligib	ole? No 11 27. Other Surveys in Which Included	
	rict Yes X	40. Visible from Yes XX
		Public Road? No.1.1
Hist. Dist.? No kl Poter		Public Road? No 11 41. Distance from and
Hist. Dist.? No kl Poter		41. Distance from and Frontage on Road
Name of Established District	nt'i? No : .	41. Distance from and Frontage on Road 25 feet on Walnut
Name of Established District  Further Description of Important F	Features The building faces west onto Wa	41. Distance from and Frontage on Road 25 feet on Walnut  lnut. Considerable
Name of Established District  Further Description of Important Falterations have been	Features The building faces west onto Waln made to the first story which cons	41. Distance from and Frontage on Road 25 feet on Walnut  lnut. Considerable ists of storefronts.
Name of Established District  Further Description of Important Falterations have been The three windows of crete blocks. The windows.	Features The building faces west onto Wan made to the first story which constitue second story have been filled windows have stone lugsills and linter	41. Distance from and Frontage on Road 25 feet on Walnut  lnut. Considerable ists of storefronts. ith decorative con-
Name of Established District  Further Description of Important Falterations have been The three windows of crete blocks. The windows.	Features The building faces west onto Waln made to the first story which constitute second story have been filled with	41. Distance from and Frontage on Road 25 feet on Walnut  lnut. Considerable ists of storefronts. ith decorative con-
Name of Established District  Further Description of Important Falterations have been The three windows of crete blocks. The windows.	Features The building faces west onto Wan made to the first story which constitue second story have been filled windows have stone lugsills and linter	41. Distance from and Frontage on Road 25 feet on Walnut  lnut. Considerable ists of storefronts. ith decorative con-
Name of Established District  Further Description of Important Falterations have been The three windows of crete blocks. The wis corbelled forming	Features The building faces west onto Wan made to the first story which constate second story have been filled windows have stone lugsills and linter triangular patterns.	41. Distance from and Frontage on Road 25 feet on Walnut lnut. Considerable ists of storefronts. ith decorative conls. The parapet wall
Name of Established District  Further Description of Important Falterations have been The three windows of crete blocks. The wis corbelled forming  History and Significance The ea	Features The building faces west onto Wan made to the first story which constitue second story have been filled windows have stone lugsills and linter	41. Distance from and Frontage on Road 25 feet on Walnut lnut. Considerable ists of storefronts. ith decorative conls. The parapet wall
Name of Established District  Further Description of Important Falterations have been The three windows of crete blocks. The wis corbelled forming  History and Significance The ea	Features The building faces west onto Wan made to the first story which constate second story have been filled windows have stone lugsills and linter triangular patterns.	41. Distance from and Frontage on Road 25 feet on Walnut lnut. Considerable ists of storefronts. ith decorative conls. The parapet wall
Name of Established District  Further Description of Important Falterations have been The three windows of crete blocks. The wis corbelled forming  History and Significance The ea	Features The building faces west onto Wan made to the first story which constate second story have been filled windows have stone lugsills and linter triangular patterns.	41. Distance from and Frontage on Road 25 feet on Walnut lnut. Considerable ists of storefronts. ith decorative conls. The parapet wall
Name of Established District  Further Description of Important Falterations have been The three windows of crete blocks. The wis corbelled forming  History and Significance The ea	Features The building faces west onto Wan made to the first story which constate second story have been filled windows have stone lugsills and linter triangular patterns.	41. Distance from and Frontage on Road 25 feet on Walnut lnut. Considerable ists of storefronts. ith decorative conls. The parapet wall
Name of Established District  Further Description of Important Falterations have been The three windows of crete blocks. The wis corbelled forming  History and Significance The eathers.	Features The building faces west onto Wan made to the first story which constitue second story have been filled windows have stone lugsills and linter triangular patterns.  The reliest known tenant of this building (1922)	41. Distance from and Frontage on Road 25 feet on Walnut  lnut. Considerable ists of storefronts. ith decorative conls. The parapet wall  was the Empire Rubber  th and east of this
Name of Established District  Further Description of Important Falterations have been The three windows of crete blocks. The wis corbelled forming  History and Significance The eathers.	Features The building faces west onto Wan made to the first story which constate second story have been filled windows have stone lugsills and linter triangular patterns.	41. Distance from and Frontage on Road 25 feet on Walnut  lnut. Considerable ists of storefronts. ith decorative conls. The parapet wall  was the Empire Rubber  th and east of this
Name of Established District  Further Description of Important Falterations have been The three windows of crete blocks. The wis corbelled forming  History and Significance The eathers.	Features The building faces west onto Wan made to the first story which constitue second story have been filled windows have stone lugsills and linter triangular patterns.  The reliest known tenant of this building (1922)	41. Distance from and Frontage on Road 25 feet on Walnut  lnut. Considerable ists of storefronts. ith decorative conls. The parapet wall  was the Empire Rubber  th and east of this
Name of Established District  Further Description of Important Falterations have been The three windows of crete blocks. The wis corbelled forming  History and Significance The eathers.  Description of Environment and On building. To the nother east.	Features The building faces west onto Wan made to the first story which constitue second story have been filled windows have stone lugsills and linter triangular patterns.  The reliest known tenant of this building (1922)	41. Distance from and Frontage on Road 25 feet on Walnut  lnut. Considerable ists of storefronts. ith decorative conls. The parapet wall  was the Empire Rubber the and east of this vice station is to
Name of Established District  Further Description of Important Falterations have been The three windows of crete blocks. The wis corbelled forming  History and Significance The early.  Description of Environment and Orbuilding. To the nother east.  Sources of Information	Features The building faces west onto Wan made to the first story which constitue second story have been filled windows have stone lugsills and linter triangular patterns.  The reliest known tenant of this building (1922)	41. Distance from and Frontage on Road 25 feet on Walnut  lnut. Considerable ists of storefronts. ith decorative conls. The parapet wall  was the Empire Rubber  th and east of this
Name of Established District  Further Description of Important Falterations have been The three windows of crete blocks. The wis corbelled forming  History and Significance The early.  Description of Environment and On building. To the nother east.  Sources of Information #8649	Features The building faces west onto Wan made to the first story which constitue second story have been filled windows have stone lugsills and linter triangular patterns.  The reliest known tenant of this building (1922)	41. Distance from and Frontage on Road 25 feet on Walnut  lnut. Considerable ists of storefronts. ith decorative conls. The parapet wall  was the Empire Rubber  th and east of this vice station is to  46. Prepared by Piland/Uguccioni  47. Organization
Name of Established District  Further Description of Important Falterations have been The three windows of crete blocks. The wis corbelled forming  History and Significance The early.  Description of Environment and On building. To the no	Features The building faces west onto Wan made to the first story which constitue second story have been filled windows have stone lugsills and linter triangular patterns.  The reliest known tenant of this building (1922)	41. Distance from and Frontage on Road 25 feet on Walnut lnut. Considerable ists of storefronts. ith decorative conls. The parapet wall was the Empire Rubber the and east of this vice station is to

State Historical Survey and Planning Office, 909 University Avenue, Suite 215,



46. Prepared by

47. Organization

48. Date

6/28/83

Piland /Uguccioni

Landmarks Commission

49. Revision Date(s)

45 Sources of Information WP #93224

BP #16854

Kansas City Star, Oct. 23, 1955, p. 7D.



State Historical Sur / and Planning Office, 909 Univ hity Avenue, Suite 215 columbia, Missouri 65201 No 4. Present Name(s) 53-D Superior Supply Company 2 County Jack son 5 Other Name(s) 3 Location of Negatives Sunshine Safety Lamps Company Bulding Landmarks Commission 6. Specific Location 16. Thematic Category Jackson 28. No. of Stories 030 050 29. Basement? Yes XX 1816 Walnut 17. Date(s) or Period No I 1920 (add. 1964) 30. Foundation Material 7. City or Town Il Rural, Township & Vicinity 18 Style or Design stone 64 31. Wall Construction Kansas City, Missouri masonry ather B. Site Plan with North Arrow 19. Architect or Engineer 40 2. Roo! Type & Material T+Pe flat; composition Ruel A. Curtis 20. Contractor or Builder 33. No. of Bays John Gosling Front pnoh 21 Original Use, if apparent commercial R1 34. Wall Treatment brick; metal 22 Present Use commercial 35. Plan Shape 23 Ownership Public 11 36. Changes Private K (Explain in #42) 24. Owner's Name & Address, WAlnut il known 37. Condition Interior Coordinates UTM Exterior Long 25. Open to 38. Preservation Yes Yes Public? No to Underway? No X Site Structure | Building Object 11 26. Local Contact Person or Organization 39. Endangered? Yes By What? No lx Landmarks Commission 11. On National Yes ! Yes 12 Is It Register? Eligible? Nox Nox! 27. Other Surveys in Which Included Yes Yes X 13 Part of Estab. Yes ! ! 14 District 40. Visible Irom Nox Hist. Dist.? Not Potent'1? Public Road? No i 41. Distance from and 15. Name of Established District Frontage on Road 100 feet on Walnut 42. Further Description of Important Features The primary facade faces east on Walnut. The first floor storefronts were altered considerably in 1951 and are now filled in with brick. The second story was also altered and is filled in with metal panels. The parapet wall features a stone band course punctuated with interspersed square stone blocks. Brick laid in soldier course defines the first from second story. In 1964 a 10 x 50 foot concrete block addition was extended from the southwest corner of the building. 43. History and Significance The building was constructed for William H. Hoffstot who was president of the Sunshine Safety Lamp Company. 44. Description of Environment and Outbuildings Surface parking lots are located to the north and south of this building. To the east is another commercial building and a surface parking lot. To the west is a surface parking lot.

46. Prepared by 45 Sources of Information WP #12353 Uguccioni BP #12746 47. Organization BP #31012A Landmarks Commission BP #14537 48. Date 49. Revision Date(s) 11/3/81

SUPERIOR
SUPPLIES
TING SUPPLIES
ESALE ONLY

SUPERIOR SUPPLY COMPANY

45 Sources of Information

Western Contractor, April 30, 1919, p. 22.

WP #62310

BP #66121

46. Prepared by

47. Organization

48. Date 4/30/82

Piland/ Uguccioni

Landmarks Commission

49 Revision Date(s)



42 Further Description of Important Features The building is sited at the northwest corner of 19th and Walnut Streets, and boasts twin facades. The building's mass is articulated by means of brick piers enriched with vertical terra cotta bands. The east facade is three bays wide and each bay contains three multipaned square windows. A terra cotta band course separates the third from fourth stories. The parapet wall at the tenth story displays vertical terra cotta banding. A tower projection above the tenth story of the northern bay is decorated with terra cotta panels.

43 History and Significance The first major tenant of this office building was the Post Office. The Gateway Substation, one of the largest in the midwest, occupied the first 4 floors and basemen when the building opened. From 1947-1958 the Veterans Administration occupied the building.

44. Description of Environment and Outbuildings Surface parking lots are east and west of this building. the north and south are other commercial buildings.

45 Sources of Information Western Contractor, Oct. 15, 1919, p. 26. Kansas City Star, Aug. 19, BP #12632 1924.

Kansas City Star, March 5, 1920, p. 2.

Western Contractor, March 24, 1920, p. 30. Kansas City Star, Oct. 21, 1981, p. 9C.

WP #1953 Kansas City Star Oct. 18, 1959.

1. No

53-B

2 County

Lat.

Long

Register?

Jackson

46. Prepared by Piland /Uguccioni 47. Organization Landmarks Commission 48. Date 49 Revision Date(s)

6/7/82



-
C1111C1
itame(5,
31

1. No.	4. Pres	VENTORY	5X-AS-008-1485
_73-I	Fee	deral Letter Co.	2
2. County		ther Name(s)	
		ex Welder & Engineering Company Building	
6. Specific Location		16. Thematic Category	28. No. of Stories I
1910 Walnut S			29. Basement? Yes I
		17. Date(s) or Period 1944-45 (add. 1946)	30. Foundation Material
7 City or Town II Rus	ral. Township & Vicinity	18. Style or Design	concrete 65
Kansas City, Miss	ouri		31. Wall Construction
8. Site Plan with North A		19 Architect or Engineer	masonry UD
FAST 19TH	57 11	C. A. Smith 20. Contractor or Builder	32. Roof Type & Material FPE flat; tar & gravel 99
	N	Flett Construction Company	33. No. of Bays
	14	21. Original Use, if apparent	Front 15 Side
	1	commercial OSE	34. Wall Treatment
	13	22 Present Use commercial	brick 30
	2		35. Plan Shaperectangular
	VALVUT	23 Ownership Public     Private	36. Changes Addition X (Explain Altered XX
-	2	24. Owner's Name & Address,	in #42) Moved XX
	4	if known	37. Condition
Coordinates	UTM		Interior
Lat. Long.		× 6	Exterior -good
0. Site ! :	Structure	25. Open to Yes II Public? No II	38. Preservation Yes Underway?
Building k	Object	26. Local Contact Person or Organization	39. Endangered? Yes I
		Landmarks Commission	By What? No 1:
1. On National Yes II	12 Is It Yes	Deviandrite Committee	XX
1. On National Yes     Register? No K!	Eligible? No K	27. Other Surveys in Which Included	
Register? No K!  3. Part of Estab. Yes ! !	Eligible? No x:		40. Visible from Yes **
Register? No x:  3. Part of Estab, Yes 11 Hist. Dist.? No x!	Eligible? No x:  14. District Yes   Potent'1? No x:		40. Visible from Yes ? Public Road? No 1:
Register? No k!  3. Part of Estab, Yes   1 Hist. Dist.? No k!	Eligible? No x:  14. District Yes   Potent'1? No x:		40. Visible from Yes ** Public Road? No !:  41. Distance from and Frontage on Road
Register? No x:  3. Part of Estab, Yes 11 Hist. Dist.? No x!  5. Name of Established E	Eligible? No x:  14. District Yes   Potent'1? No x:  District	27. Other Surveys in Which Included	40. Visible from Yes XX No 11  41. Distance from and Frontage on Road  100 feet on E, 19th St
Aegister? No x:  3. Part of Estab. Yes   1 Hist. Dist.? No x!  15. Name of Established Control  42. Further Description of paired rectangular are placed at the	Eligible? No x:  14. District Yes   Potent'1? No x:  District  Important Features The windows which exercise north end of the enclosed in 1958.	27. Other Surveys in Which Included  e west facade fronting on Walnut S  xtend along the facade. An entran  building. Stone coping terminate  The south portion of the building	40. Visible from Yes XX Public Road? No ::  41. Distance from and Frontage on Road 100 feet on E. 19th St treet, is fenestrated with ce and loading dock area, s the building. The
Register? No x:  3. Part of Estab. Yes   1 Hist. Dist.? No x!  15. Name of Established District Paired rectangular are placed at the loading dock was which brought the which brought the landing mats."	Important Features The windows which end of the enclosed in 1958. total square footone The Rex Welder de multi-welding	27. Other Surveys in Which Included  e west facade fronting on Walnut S  xtend along the facade. An entran  building. Stone coping terminate  The south portion of the building	40. Visible from Public Road? No!:  41. Distance from and Frontage on Road  100 feet on E. 19th St treet, is fenestrated with ce and loading dock area, s the building. The g is an addition of 1946,  ginal occupant of duct that produced  this building. To
Register? No x:  3 Part of Estab. Yes !! Hist. Dist.? No x!  5. Name of Established Control of paired rectangular are placed at the loading dock was which brought the which brought the loading mats."  4. Description of Environment the north and east the loading mats."	Important Features The windows which enclosed in 1958. total square footone ment and Outbuildings that are commercial is strong to the commercial in the commercial in the commercial is square footone to the multi-welding	e west facade fronting on Walnut Statend along the facade. An entrandoulding. Stone coping terminate The south portion of the building age to 25,000.  The and Engineering Company, the original machines, "a war-developed production of the south of th	40. Visible from Public Road? No!:  41. Dislance from and Frontage on Road  100 feet on E. 19th St treet, is fenestrated with ce and loading dock area, s the building. The g is an addition of 1946,  ginal occupant of duct that produced  this building. To is also to the west.
Register? No x:  3 Part of Estab. Yes !! Hist. Dist.? No x!  5. Name of Established Control of paired rectangular are placed at the loading dock was which brought the which brought the standing mats."  4. Description of Environment the north and east the north and east the sources of Information WP #406	Important Features The windows which enclosed in 1958. total square footone ment and Outbuildings that are commercial is strong to the commercial in the commercial in the commercial is square footone to the multi-welding	e west facade fronting on Walnut Statend along the facade. An entrandoulding. Stone coping terminate The south portion of the building age to 25,000.  The and Engineering Company, the original machines, "a war-developed production of the south of th	40. Visible from Public Road? No!:  41. Distance from and Frontage on Road  100 feet on E. 19th St treet, is fenestrated with ce and loading dock area, s the building. The g is an addition of 1946,  ginal occupant of duct that produced  this building. To is also to the west.
Register? No x:  3 Part of Estab. Yes   1 Hist. Dist.? No x!  5. Name of Established Dist.  12. Further Description of paired rectangular are placed at the loading dock was which brought the which brought the landing mats."  14. Description of Environment the north and east the north and east the loading mats.	Important Features The windows which enclosed in 1958. total square footone ment and Outbuildings that are commercial is strong to the commercial in the commercial in the commercial is square footone to the multi-welding	e west facade fronting on Walnut Statend along the facade. An entrandoulding. Stone coping terminate The south portion of the building age to 25,000.  The and Engineering Company, the original machines, "a war-developed production of the south of th	40. Visible from Public Road? No!:  41. Dislance from and Frontage on Road  100 feet on E. 19th St treet, is fenestrated with ce and loading dock area, s the building. The g is an addition of 1946,  ginal occupant of duct that produced  this building. To is also to the west.



5A-A5008-1486

1/23/85

HISTORIC INVENTORY



State Historical Survey and Planning Utfice, 909 University Avenue, Suite 213

Columbia, Missouri 65201



## 5A-A5008-1488 HISTORIC INVENTORY I. No. 93-A 2 County Pureweld Industrial Products Jackson 5. Other Name(s) 3 Location of Negatives MT #105-17 Puritan Compressed Gas Corporation Landmarks Commission of KC 6. Specific Location 16. Thematic Category 28. No. of Stories Jackson 29. Basement? Yes Ix 2001-13 Walnut 17. Date(s) or Period No I . 1955 (add. 1963; 1965) 30. Foundation Material 7. City or Town If Rural, Township & Vicinity 18. Style or Design Kansas City, Missouri 31. Wall Construction B. Site Plan with North Arrow 19. Architect or Engineer concrete block Samuel Bihr (1955) 32. Roof Type & Material (1955, 63,& 20. Contractor or Builder flat; tar and gravel Miller-Stauch Const. Co. 1965) 33. No. of Bays Front Side 21. Original Use, if apparent 2001-13 Wal commercial 34. Wall Treatment 22. Present Use brick 35. Plan Shape "T." commercial 36. Changes 23 Ownership Public 11 Addition & Private xx (Explain Altered I in #421 Moved i 24. Owner's Name & Address, if known 37. Condition Interior 9. Coordinates UTM Exterior good Lat. Long 25. Open to Yes XX 38. Preservation Yes i Public? No II Underway? No x 10 Site ! : Structure I Building IX Object ! I 39. Endangered? 26. Local Contact Person or Organization Yes By What? No to 11. On National Yes !! 12 Is It Yes: Landmarks Commission of KC Eligible? No IX Register? No IX 27. Other Surveys in Which Included 13 Part of Estab. District Yes I Yes ! ! 40. Visible from Yes K Hist. Dist.? Potent'1? No IX Public Road? No ! 41. Distance from and 15. Name of Established District Frontage on Road 62 ft on E. 20th St.

42. Further Description of Important Features The entrance is canted at the northwest corner of this corner building. Display windows flank the entrance. Metal coping terminates the plain brick walls. In 1963 and 1965 the building was expanded to the south.

- 43. History and Significance This building was constructed as a welding supply center for the Puritan Compressed Gas Corporation. The 7,600 square feet of the original structure encompassed a sales office, display rooms, welding supplies, and equipment and truck docks. The Puritan Corporation, established in 1913, was the first Kansas City manufacturer of oxygen.
- 44. Description of Environment and Outbuildings Commercial buildings are north, east and west of this structure. A surface parking lot is to the south.

## 45 Sources of Information BP #18268

BP #5822; 18923

Kansas City Star, May 15, 1955, p. 6E

46. Prepared by PILAND

47. Organization

Landmarks Commission
48. Date 49 Revision Date(s)

12/17/8



HISTO	RIC IN	VENTORY	mbia, Missouri 65201 5A-AS-008-1486	1
1. No. 92-H	4. Pres	sent Name(s)		
2 County Bel		elger Cartage Service Inc.		
Jackson 5 Othe		lger Cartage Service Inc.		
3 Location of Negatives MT #2 Landmarks Commission	9-5 Wes	stern Storage and Warehouse Company		H
6 Specific Location		16. Thematic Category	28. No. of Stories 3 -/	L
2100 Walnut		030 050	29. Basement? Yes !-	Jackson
		17. Date(s) or Period .	No I .	SSO
7 City or Town If Bural To	washin & Vicinity	1892	30. Foundation Material	n
7 City or Town If Rural, To Kansas City, Missouri	mining a vicinity	Romanesque Revival 40 69	31. Wall Construction	
8. Site Plan with North Arrow		19 Architect or Engineer Obtes	masonry LB UD	
M		30	32. Roof Type & Material + PL	H
0		20. Contractor or Builder	flat; tar & gravelqq	
1		21. Original Use, if apparent	Front 5 Side	21
1	11	commercial OOH	34. Wall Treatment	00
	12	22 Present Use	brick 30 50	W
	טאואטיי	commercial	35. Plan Shape rectangular	2100 Walnut
	1 X	23 Ownership Public ( ) Private 1/2	36. Changes Addition : X (Explain Altered)	lut
	3	24. Owner's Name & Address.	in #42) Moved	1
	3	il Known	37. Condition	
9 Coordinates UTM			Interior	
Lal. Long.			Exterior good	
10. Site ! :	Structure (	25. Open to Yes x Public? No 1	38. Preservation Yes Underway? No XX	
Building I i	Object ! I	26. Local Contact Person or Organization	39. Endangered? Yes I By What? No KX	
11. On National Yes   12 Register? No !!	Is It Yes XX Eligible? No	Landmarks Commission	by What?	
X	District YesXX	27. Other Surveys in Which Included	40. Visible from Yes xx	
Hist. Dist.? No lx	Potent'l? No		Public Road? No 11	
15. Name of Established District		1	41. Distance from and	
			Frontage on Road Approx 150 feet on Walnut	
				1
		he first story of this warehouse bu cess to vehicular traffic and penet		ad
		s a triple window. Bays between th		We
		a doorway with segmental transom.		Western
		ory. A decorative brick string cou		tern
parapet wall. A sing	gle story m	etal garage building has been	n placed on the south	1
facade of this buil	laing.			to
43. History and Significance				Storage
	st occupied b	by the Western Storage and Warehous	se Company	100
				and
				1000
				lar
44. Description of Environment a	and Outbuildings	Other commercial buildings are to	the north and west.	eh
		to the south. A surface parking are		Warehouse
		white Committee .	Activities and the second of	
				Cor
15 Sources of Information			46. Prepared by	Company
WP #3634			Piland/Uguccioni	ny
			47. Organization	1
			Landmarks Commission  48. Date 49 Revision Date(s)	



Citic
-
=
-
-
-
-
0.
=
•
$z_i$
i
10
27
-

Present

HISTORIC INVENTORY JA-AS-008-199 1. No 4. Present Name(s) 92-J Superior Moving and Storage 97 2 County 5 Other Name(s) Jackson 3 Location of Negatives MT #29-8 Kellogg-Mackay Company Bulding Landmarks Commission #29-9 16. Thematic Category 6. Specific Location 28. No. of Stories 030 ackson 29. Basement? Yes IX 17 Date(s) or Period 2020-24 Walnut No I 1926 (add. 1943) 30. Foundation Material 7 City or Town If Rural, Township & Vicinity Kansas City, Missouri concrete 65 18. Style or Design 31. Wall Construction 69 60 reinf. concrete B. Site Plan with North Arrow 19. Architect or Engineer other Walter Besecke 32. Roof Type & Material AP 20. Contractor or Builder flat; tar and gravel 33. No. of Bays Harvey Stiver 2020-24 Side Front PUICE 21. Original Use, if apparent AW commercial DeH 34. Wall Treatment 22. Present Use brick 35. Plan Shape commercial irregular Walnut 23 Ownership Public 11 36. Changes Addition X Private 1 (Explain Altered | in #42) Moved i 24. Owner's Name & Address, if known 37. Condition Interior 9. Coordinates UTM Exterior Lat. Long 25. Open to Yes IX 38. Preservation Yes . Public? Noil Underway? No ix 10 Site ! : Structure I Building tx Object | | 39. Endangered? 26. Local Contact Person or Organization Yes No IX By What? Landmarks Commission 11. On National Yes XX Yes ! 12 Is It Register? No XX Eligible? No !! 27. Other Surveys in Which Included 13. Part of Estab. Yes XX Yes !! District Yes !X Visible from Hist. Dist.? No L Potent'l? No ! Public Road? No 11 Distance from and 15. Name of Established District Frontage on Road 5 feet on Walnut 42. Further Description of Important Features The ground story of the east facade features a garage bay sheltered by a flat roof supported by tie rods. The main entrance is placed at the north end of the facade. The entrance door is flanked by multipaned sidelights and capped by a splayed lintel. The second through fifth stories are articulated into three bays by means of brick pilasters, and a tripartite window grouping. The parapet wall is shaped and is terminated with cut stone coping. A concrete block loading dock was added to the north facade in 1943. The dock contains 5 garage doors protecte by a shed roof. 43. History and Significance
This building was constructed for the Kellogg-Mackay Company, a firm handling heating, ventilating, and plumbing supplies. Plans for the building were made in 1923, but the actual construction was delayed three years. The building was constructed at a cost of \$150,000. Other commercial buildings are to the south and west. 44. Description of Environment and Outbuildings To the east is a surface parking lot. 46. Prepared by 45 Sources of Information KC Journal-Post, June 6, 1926, p. 1c. Piland | 47. Organization BP# 14748 Landmarks Commission BP #14401A 48. Date 49. Revision Date(s) 8/26/81

State Historical Survey and Planning Office, 909 University Avenue, Suite 215,

Columbia, Missouri 65201





1. No. 92-I		eni Name(s) 6-30 Walnut	
2 County			
Jackson		er Name(s) ch and Musser Manufacturing Compan	. Rividia
Landmarks Commission	29-6 Roa	ch and Musser Manufacturing Compan	y cuitaing
6 Specific Location		16. Thematic Category	28. No. of Stories 3
		030 050	29. Basement? Yes
2026-30 Walnut		17 Date(s) or Period .	No I
	Township & Vicinity	c. 1890 18 Style or Design	30. Foundation Material
Kansas City, Missouri	i vicinity	69	31. Wall Construction
. Site Plan with North Arrow		19. Architect or Engineer other	masonry LB
	1	30	32. Roof Type & Material flat
		20. Contractor or Builder	tar and gravel F+
	4	21. Original Use, if apparent	Front 3 Side
	12 1	COMMERCIAL OJH	34. Wall Treatment
	VAlnu	22. Present Use	brick 30
	3	unknown 23 Ownership Public !	35. Plan Shape rectangular 36. Changes Addition ::
		Private 1x	(Explain Altered I
		24. Owner's Name & Address,	in #42) Moved
		if known	37. Condition Interior
Coordinates UTM			Exterior good
Long		25. Open to Yes II	38. Preservation Yes
O. Site!:	Structure 1	Public? No X	Underway? No :X
Building 1 i	Object 11	26. Local Contact Person or Organization	39. Endangered? Yes   Yes   No   X
	2 Is It Yes X Eligible? No	Landmarks Commission 27 Other Surveys in Which Included	- No.
Register? No 13	4. District Yes x		40. Visible from Yes IX
Register? No 13			Public Road? No 11
Register? No 1 14  3 Part of Estab Yes   1 14  Hist. Dist.? No 12	4. District Yes x Potent'l? No		Public Road? No 11 41. Distance from and
Register? No 1 14  3 Part of Estab Yes   1 14  Hist. Dist.? No 12	4. District Yes x Potent'l? No		Public Road? No 11
Register? No 1/x   14  3. Part of Estab Yes   1   14  Hist. Dist.? No 1/x   15  5. Name of Established District  2. Further Description of Impo	District Yes X Potent'1? No :	e main facade faces east. A loadi	Public Road? No!!  41. Distance from and Frontage on Road  75 ft. on Walnut  ang dock comprises the
Register? No 1/x 3 Part of Estab Yes 11 14 Hist. Dist.? No 1/x 5 Name of Established District 12. Further Description of Important floor, protect by the window fenest	Potent'l? No:		Public Road? No!!  41. Distance from and Frontage on Road 75 ft. on Walnut  ang dock comprises the divided into three bays on the 2nd floor. Each
Register? No 1/x 3. Part of Estab Yes 11 14 Hist. Dist.? No 1/x 5. Name of Established District.  2. Further Description of Important floor, protect by the window fenest bay of the 3rd floor.  3. History and Significance.	District Yes x Potent'1? No:  ct  criant Features The down a flat contains three  This building	e main facade faces east. A loadi anopy roof. The upper floors are ied Chicago-style windows are used	Public Road? No!!  41. Distance from and Frontage on Road 75 ft. on Walnut  ang dock comprises the divided into three bays on the 2nd floor. Each erched lintels.  Musser Manufacturing
Register? No 1/x 14  3 Part of Estab Yes   1 14  Hist. Dist.? No 1/x 14  5 Name of Established District  2 Further Description of Important floor, protect by the window fenest bay of the 3rd floor  3. History and Significance	District Yes x Potent'1? No:  ct  criant Features The down a flat contains three  This building	e main facade faces east. A loadi anopy roof. The upper floors are ied Chicago-style windows are used e double-hung, sash windows with a	Public Road? No!!  41. Distance from and Frontage on Road 75 ft. on Walnut  ang dock comprises the divided into three bays on the 2nd floor. Each erched lintels.  Musser Manufacturing
Register? No x 14  3 Part of Estab Yes   14  Hist. Dist.? No x 14  5 Name of Established District  2 Further Description of Important floor, protect by the window fenest bay of the 3rd floor  3 History and Significance	District Yes x Potent'1? No:  ct  criant Features The down a flat contains three  This building	e main facade faces east. A loadi anopy roof. The upper floors are ied Chicago-style windows are used e double-hung, sash windows with a	Public Road? No!!  41. Distance from and Frontage on Road 75 ft. on Walnut  ang dock comprises the divided into three bays on the 2nd floor. Each erched lintels.  Musser Manufacturing
Register? No x 14  3 Part of Estab Yes   14  Hist. Dist.? No x 14  5 Name of Established District  2 Further Description of Important floor, protect by the window fenest bay of the 3rd floor  3. History and Significance	District Yes x Potent'1? No:  ct  criant Features The ded by a flat corration. Modification three contains thre	e main facade faces east. A loadi anopy roof. The upper floors are ied Chicago-style windows are used e double-hung, sash windows with a	Public Road? No!!  41. Distance from and Frontage on Road 75 ft. on Walnut  ang dock comprises the divided into three bays on the 2nd floor. Each erched lintels.  Musser Manufacturing
Register? No x  Part of Estab Yes   14  Hist. Dist.? No x  Name of Established District  Further Description of Important floor, protect by the window fenest bay of the 3rd floor  History and Significance Company. This firm,	Orlant Features The day a flat contains three This building headquartered	e main facade faces east. A loadi anopy roof. The upper floors are ied Chicago-style windows are used e double-hung, sash windows with a goriginally housed the Roach and in Muscatine, Iowa, made sash documents of the commercial buildings are nor	Public Road? No!!  41. Distance from and Frontage on Road 75 ft. on Walnut  ang dock comprises the divided into three bays on the 2nd floor. Each orched lintels.  Musser Manufacturing ors and blinds.  structure.  th and south of this
Register? No 12 Part of Estab Yes 11 Hist. Dist.? No 12 Name of Established District Parther Description of Important floor, protect by the window fenest bay of the 3rd floor History and Significance Company. This firm,	Orlant Features The day a flat contains three This building headquartered	e main facade faces east. A loadi anopy roof. The upper floors are ied Chicago-style windows are used e double-hung, sash windows with a ng originally housed the Roach and in Muscatine, Iowa, made sash doo	Public Road? No!!  41. Distance from and Frontage on Road 75 ft. on Walnut  ang dock comprises the divided into three bays on the 2nd floor. Each orched lintels.  Musser Manufacturing ors and blinds.  structure.  th and south of this
Register? No x  Part of Estab Yes   14  Hist. Dist.? No x  Name of Established District  Further Description of Important floor, protect by the window fenest bay of the 3rd floor  History and Significance Company. This firm,	Orlant Features The day a flat contains three This building headquartered	e main facade faces east. A loadi anopy roof. The upper floors are ied Chicago-style windows are used e double-hung, sash windows with a goriginally housed the Roach and in Muscatine, Iowa, made sash documents of the commercial buildings are nor	Public Road? No!!  41. Distance from and Frontage on Road 75 ft. on Walnut  and dock comprises the divided into three bays on the 2nd floor. Each arched lintels.  Musser Manufacturing ors and blinds.  structure. th and south of this is to the west.
Register? No 12  Part of Estab Yes 11 Hist. Dist.? No 12  Name of Established District  Further Description of Important floor, protect by the window fenest bay of the 3rd floor  History and Significance Company. This firm,  Description of Environment A surface parking lo	Orlant Features The day a flat contains three This building headquartered	e main facade faces east. A loadi anopy roof. The upper floors are ied Chicago-style windows are used e double-hung, sash windows with a goriginally housed the Roach and in Muscatine, Iowa, made sash documents of the commercial buildings are nor	Public Road? No!!  41. Distance from and Frontage on Road 75 ft. on Walnut  ang dock comprises the divided into three bays on the 2nd floor. Each arched lintels.  Musser Manufacturing ors and blinds.  structure. th and south of this list to the west.
Part of Estab Yes   14 Hist. Dist.? No   14 Name of Established District  Part floor, protect by the window fenest bay of the 3rd floor  Company. This firm,  Description of Environment A surface parking lo	Ortant Features The ded by a flat contains three This building headquartered and Outbuildings of is to the ear	e main facade faces east. A loadi anopy roof. The upper floors are ied Chicago-style windows are used to double-hung, sash windows with a goriginally housed the Roach and in Muscatine, Iowa, made sash documents. Another commercial buildings are nor ast. Another commercial building in	Public Road? No!!  41. Distance from and Frontage on Road 75 ft. on Walnut  ang dock comprises the divided into three bays on the 2nd floor. Each right right right right repairs and blinds.  Musser Manufacturing ors and blinds.  structure. th and south of this sto the west.  46. Prepared by Piland 47. Organization
Part of Estab Yes   14 Hist. Dist.? No   14  5. Name of Established District  7. Further Description of Important floor, protect by the window fenest bay of the 3rd floor  8. History and Significance Company. This firm,  1. Description of Environment A surface parking looks of the Sources of Information	Ortant Features The ded by a flat contains three This building headquartered and Outbuildings of is to the ear	e main facade faces east. A loadi anopy roof. The upper floors are ied Chicago-style windows are used to double-hung, sash windows with a goriginally housed the Roach and in Muscatine, Iowa, made sash documents. Another commercial buildings are nor ast. Another commercial building in	Public Road? No!!  41. Distance from and Frontage on Road 75 ft. on Walnut  ang dock comprises the divided into three bays on the 2nd floor. Each arched lintels.  Musser Manufacturing ors and blinds.  structure. th and south of this list to the west.



1. No.	4. Present Name(s)		
	2601-05 Walnut		4
2 County Jackson	5 Other Name(s)		155
3 Location of Negatives MT #3 Landmarks Commission			A
6 Specific Location	16. Thematic Category	28. No. of Stories 5	
	030 D50	28. No. of Stories 5 29. Basement? YesXX	Ja
2601-05 Walnut	17. Date(s) or Period	No L.	Jackson
	1923	30. Foundation Material	on
7 City or Town If Rural, Towns Kansas City, Missouri	hip & Vicinity 18. Style or Design	31. Wall Construction RC	
B. Site Plan with North Arrow	0.0	Dayton reinforced concrete	
E. 2671 ST		OH) 32. Roof Type & Material	
M 20111 01		thes flat; tar & gravel 99	
N	21 Original Use, if apparent	O 4D 33. No. of Bays Front 4 Side 4	
1 6	commercial por	34. Wall Treatment	2601-
3	22. Present Use	brick 30	01-
σενησι	commercial	35. Plan Shape irregular	-05 Walnut
3		ublic   1 36 Changes Addition :   ivate   X (Explain Altered   1	Wa
2	24. Owner's Name & Address,	in #42) Moved	ln
	if known	37. Condition Interior	ut
9 Coordinates UTM		Exterior good.	
Long	25. Open to	Yes   38. Preservation Yes	
Site!:	Structure   Public?	No ix Underway? No XX	
Building 1x	Object 1 26. Local Contact Person or Organizati	on 39. Endangered? Yes ! By What? No ! :	
11. On National Yes 1 12 Is It Register? No 12 Elig	ible? No 1: Landmarks Commission 27. Other Surveys in Which Included	by What:	
13 Part of Estab Yes II 14 Dis		40. Visible from Yes XX	
Hist. Dist.? No X Por	ent'l? No :	Public Road? No 11	
15. Name of Established District		41. Distance from and Frontage on Road	
		115 feet on Walnut	
42. Further Description of Important	Features The building occupies a corner	115 feet on Walnut	
it to the irregularities	Features The building occupies a corner of the plot plan. The building consi	115 feet on Walnut siting and its shape adapts sts of three sections composed	Hal
it to the irregularities of two identical section	of the plot plan. The building consist radiating from a center section that	115 feet on Walnut siting and its shape adapts sts of three sections composed is canted at the corner. The	33.4
it to the irregularities of two identical section first story is composed	of the plot plan. The building consist radiating from a center section that of garage and store front bays. Above	115 feet on Walnut siting and its shape adapts sts of three sections composed is canted at the corner. The it is a decorative string	33.4
it to the irregularities of two identical section first story is composed course composed of stone	of the plot plan. The building consist radiating from a center section that of garage and store front bays. Above banding and interspersed stone blocks	115 feet on Walnut siting and its shape adapts sts of three sections composed is canted at the corner. The it is a decorative string . The second through fifth	33.4
it to the irregularities of two identical section first story is composed course composed of stone stories are divided by b The building terminates	of the plot plan. The building consist radiating from a center section that of garage and store front bays. Above banding and interspersed stone blocks rick piers into bays containing three in terra cotta coping. The central se	115 feet on Walnut siting and its shape adapts sts of three sections composed is canted at the corner. The it is a decorative string The second through fifth rectangular windows each. ction between the third and	Hall Brothers
it to the irregularities of two identical section first story is composed course composed of stone stories are divided by b The building terminates fourth stories contains	of the plot plan. The building consist radiating from a center section that of garage and store front bays. Above banding and interspersed stone blocks rick piers into bays containing three in terra cotta coping. The central sea relief panel inscribed with the word	115 feet on Walnut siting and its shape adapts sts of three sections composed is canted at the corner. The it is a decorative string The second through fifth rectangular windows each. ction between the third and s "HALL BROTHERS."	
it to the irregularities of two identical section first story is composed course composed of stone stories are divided by both building terminates fourth stories contains.  43. History and Significance This	of the plot plan. The building consist radiating from a center section that of garage and store front bays. Above banding and interspersed stone blocks rick piers into bays containing three in terra cotta coping. The central searelief panel inscribed with the words building was designed and erected by	siting and its shape adapts sts of three sections composed is canted at the corner. The it is a decorative string. The second through fifth rectangular windows each. ction between the third and s "HALL BROTHERS."	33.4
it to the irregularities of two identical section first story is composed course composed of stone stories are divided by b The building terminates fourth stories contains.  43. History and Significance This Frank Hill Smith, Inc. sites. This site was se	of the plot plan. The building consist radiating from a center section that of garage and store front bays. Above banding and interspersed stone blocks rick piers into bays containing three in terra cotta coping. The central searclief panel inscribed with the words building was designed and erected by The site was chosen after 120 employees elected because of its proximity to Pen	siting and its shape adapts sts of three sections composed is canted at the corner. The it is a decorative string. The second through fifth rectangular windows each. ction between the third and s "HALL BROTHERS."  the Dayton, Ohio firm of s balloted on several proposed in Valley Park. Hall Brothers	33.4
it to the irregularities of two identical section first story is composed course composed of stone stories are divided by b The building terminates fourth stories contains.  43. History and Significance This Frank Hill Smith, Inc. sites. This site was se	of the plot plan. The building consist radiating from a center section that of garage and store front bays. Above banding and interspersed stone blocks rick piers into bays containing three in terra cotta coping. The central searchief panel inscribed with the words building was designed and erected by The site was chosen after 120 employees.	siting and its shape adapts sts of three sections composed is canted at the corner. The it is a decorative string. The second through fifth rectangular windows each. ction between the third and s "HALL BROTHERS."  the Dayton, Ohio firm of s balloted on several proposed in Valley Park. Hall Brothers	33.0
it to the irregularities of two identical section first story is composed course composed of stone stories are divided by b The building terminates fourth stories contains.  43. History and Significance This Frank Hill Smith, Inc. sites. This site was se	of the plot plan. The building consist radiating from a center section that of garage and store front bays. Above banding and interspersed stone blocks rick piers into bays containing three in terra cotta coping. The central searclief panel inscribed with the words building was designed and erected by The site was chosen after 120 employees elected because of its proximity to Pen	siting and its shape adapts sts of three sections composed is canted at the corner. The it is a decorative string. The second through fifth rectangular windows each. ction between the third and s "HALL BROTHERS."  the Dayton, Ohio firm of s balloted on several proposed in Valley Park. Hall Brothers	33.0
it to the irregularities of two identical section first story is composed course composed of stone stories are divided by both the building terminates fourth stories contains.  43. History and Significance This Frank Hill Smith, Inc. sites. This site was seeventually became one of	of the plot plan. The building consist radiating from a center section that of garage and store front bays. Above banding and interspersed stone blocks rick piers into bays containing three in terra cotta coping. The central searclief panel inscribed with the words building was designed and erected by The site was chosen after 120 employees elected because of its proximity to Pen	siting and its shape adapts sts of three sections composed is canted at the corner. The it is a decorative string. The second through fifth rectangular windows each. ction between the third and s "HALL BROTHERS." the Dayton, Ohio firm of the balloted on several proposed in Valley Park. Hall Brothers lmark Cards, Incorporated.	33.0
of two identical section first story is composed course composed of stone stories are divided by both building terminates fourth stories contains.  43. History and Significance This Frank Hill Smith, Inc. sites. This site was seeventually became one of	of the plot plan. The building consist radiating from a center section that of garage and store front bays. Above banding and interspersed stone blocks rick piers into bays containing three in terra cotta coping. The central searelief panel inscribed with the words building was designed and erected by The site was chosen after 120 employeed elected because of its proximity to Pener Kansas City's largest businesses, Hal	siting and its shape adapts sts of three sections composed is canted at the corner. The it is a decorative string. The second through fifth rectangular windows each. Cotion between the third and s "HALL BROTHERS."  the Dayton, Ohio firm of the balloted on several proposed in Valley Park. Hall Brothers lmark Cards, Incorporated.	33.0
of two identical section first story is composed course composed of stone stories are divided by both building terminates fourth stories contains.  43. History and Significance This Frank Hill Smith, Inc. sites. This site was seeventually became one of	of the plot plan. The building consist radiating from a center section that of garage and store front bays. Above banding and interspersed stone blocks rick piers into bays containing three in terra cotta coping. The central searchief panel inscribed with the words building was designed and erected by The site was chosen after 120 employee elected because of its proximity to Pener Kansas City's largest businesses, Hall	siting and its shape adapts sts of three sections composed is canted at the corner. The it is a decorative string. The second through fifth rectangular windows each. Cotion between the third and s "HALL BROTHERS."  the Dayton, Ohio firm of the balloted on several proposed in Valley Park. Hall Brothers lmark Cards, Incorporated.	33.0
of two identical section first story is composed course composed of stone stories are divided by both the building terminates fourth stories contains.  43. History and Significance This Frank Hill Smith, Inc. sites. This site was seeventually became one of parking lot. Vacant lar vacant land.	of the plot plan. The building consist radiating from a center section that of garage and store front bays. Above banding and interspersed stone blocks rick piers into bays containing three in terra cotta coping. The central searchief panel inscribed with the words building was designed and erected by The site was chosen after 120 employee elected because of its proximity to Pener Kansas City's largest businesses, Hall	siting and its shape adapts sts of three sections composed is canted at the corner. The it is a decorative string. The second through fifth rectangular windows each. Cotion between the third and s "HALL BROTHERS."  the Dayton, Ohio firm of s balloted on several proposed in Valley Park. Hall Brothers lmark Cards, Incorporated.  st. To the east is a surface surface parking lot and	33.0
of two identical section first story is composed course composed of stone stories are divided by both building terminates fourth stories contains.  43. History and Significance This Frank Hill Smith, Inc. sites. This site was seeventually became one of parking lot. Vacant lar vacant land.	of the plot plan. The building consist radiating from a center section that of garage and store front bays. Above banding and interspersed stone blocks rick piers into bays containing three in terra cotta coping. The central searchief panel inscribed with the words building was designed and erected by The site was chosen after 120 employee elected because of its proximity to Pener Kansas City's largest businesses, Hall	siting and its shape adapts sts of three sections composed is canted at the corner. The it is a decorative string. The second through fifth rectangular windows each. Cotion between the third and s "HALL BROTHERS."  the Dayton, Ohio firm of shalloted on several proposed in Valley Park. Hall Brothers lmark Cards, Incorporated.  St. To the east is a surface surface parking lot and	33.4
of two identical section first story is composed course composed of stone stories are divided by both building terminates fourth stories contains.  43. History and Significance This Frank Hill Smith, Inc. sites. This site was seeventually became one of parking lot. Vacant lar vacant land.  44. Description of Environment and parking lot. Vacant lar vacant land.  45. Sources of Information WP #71192  Western Contractor, Feb.	of the plot plan. The building consist radiating from a center section that of garage and store front bays. Above banding and interspersed stone blocks rick piers into bays containing three in terra cotta coping. The central searelief panel inscribed with the words building was designed and erected by The site was chosen after 120 employeed blected because of its proximity to Pener Kansas City's largest businesses, Hall Outbuildings Penn Valley Park is to the wend is to the south. To the north is a	siting and its shape adapts sts of three sections composed is canted at the corner. The it is a decorative string. The second through fifth rectangular windows each. Cotion between the third and s "HALL BROTHERS."  the Dayton, Ohio firm of s balloted on several proposed in Valley Park. Hall Brothers lmark Cards, Incorporated.  st. To the east is a surface surface parking lot and	33.0
of two identical section first story is composed course composed of stone stories are divided by be the building terminates fourth stories contains.  43. History and Significance This Frank Hill Smith, Inc. sites. This site was seeventually became one of parking lot. Vacant lar vacant land.  44. Description of Environment and parking lot. Vacant lar vacant land.  45. Sources of Information WP #71192  Western Contractor, Feb. Western Contractor, July	of the plot plan. The building consist radiating from a center section that of garage and store front bays. Above banding and interspersed stone blocks rick piers into bays containing three in terra cotta coping. The central searelief panel inscribed with the words building was designed and erected by The site was chosen after 120 employee elected because of its proximity to Per Kansas City's largest businesses, Hall Outbuildings Penn Valley Park is to the wend is to the south. To the north is a 14, 1923, p. 36. 19, 1922, p. 38.	siting and its shape adapts sts of three sections composed is canted at the corner. The it is a decorative string. The second through fifth rectangular windows each. ction between the third and s "HALL BROTHERS."  the Dayton, Ohio firm of shalloted on several proposed in Valley Park. Hall Brothers lmark Cards, Incorporated.  st. To the east is a surface surface parking lot and  46 Prepared by Piland /Uguccioni 47. Organization Landmarks Commission	33.4
of two identical section first story is composed course composed of stone stories are divided by both building terminates fourth stories contains.  43. History and Significance This Frank Hill Smith, Inc. sites. This site was seeventually became one of parking lot. Vacant lar vacant land.  44. Description of Environment and parking lot. Vacant lar vacant land.  45. Sources of Information WP #71192  Western Contractor, Feb.	of the plot plan. The building consist radiating from a center section that of garage and store front bays. Above banding and interspersed stone blocks rick piers into bays containing three in terra cotta coping. The central searelief panel inscribed with the words building was designed and erected by The site was chosen after 120 employeed lected because of its proximity to Pener Kansas City's largest businesses, Hall Outbuildings Penn Valley Park is to the weard is to the south. To the north is a 14, 1923, p. 36. 19, 1922, p. 38. 12, 1922, p. 1F	siting and its shape adapts sts of three sections composed is canted at the corner. The it is a decorative string. The second through fifth rectangular windows each. ction between the third and s "HALL BROTHERS."  the Dayton, Ohio firm of s balloted on several proposed in Valley Park. Hall Brothers lmark Cards, Incorporated.  st. To the east is a surface surface parking lot and  46 Prepared by Piland /Uguccioni  47. Organization	333



HISTORIC INVENTORY 4. Present Name(s) No. 189-B 189-2903 Walnut Street House 2 County 5 Other Name(s) Jackson MT #1/-14 3 Location of Negatives Landmarks Commission 16. Themalic Calegory 28. No. of Stories 6 Specific Location 030 Jackson 29. Basement? 2903 Walnut 17. Date(s) or Period No I 1898 30. Foundation Material 7 City or Town If Rural, Township & Vicinity Kansas City, Missouri 18. Style or Design stone 40 49 31. Wall Construction masonry US WW B. Site Plan with North Arrow 19. Architect or Engineer 32. Roof Type & Material hip; comp. shingle 63 20. Contractor or Builder 33. No. of Bays DR Side Front prich 21. Original Use, if apparent Present Name(s) 34. Wall Treatment residence 22 Present Use brick 35. Plan Shaperectangula residence 23 Ownership Public 1 36. Changes Addition Private k (Explain Altered I in #42) Moved i 24. Owner's Name & Address, if known 37. Condition Interior 9. Coordinates UTM good Exterior Lal Long 25. Open to Yes 38. Preservation Yes I No X Public? No X Underway? 10 Site ! : Structure Building Object 11 39. Endangered? Yes IX 26. Local Contact Person or Organization By What? Yes XX Landmarks Commission 11. On National Yes 12 Is It Noxx Eligible? No Register? 27. Other Surveys in Which Included Yes XX 13. Part of Estab. Yes ! ! District 40 Visible from Yes !X NoXX Potent'1? Hist. Dist.? No ! Public Road? No ! 15. Name of Established District 41. Distance from and Frontage on Road 24 feet on Walnut 42 Further Description of Important Features This residence features an unusual hipped roof slope that extends out on the west facade to form a gable roof dormer. A bay window projects on the north facade. The porch on the main facade has been enclosed in a later alteration. Photo 43. History and Significance One of a pair of identical houses, side-by-side. 44. Description of Environment and Outbuildings Vacant lots are to the north and south of this residence. An apartment building is the west. To the east is another residence Sources of Information WP #15012 46. Prepared by Piland / Uguccioni 47. Organization Landmarks Commission 48. Date 49. Revision Date(s)

State Historical Survey and Planning Office, 909 University Avenue, Suite 215,

Columbia, Missouri 65201



Columbia, Missouri 65201 HISTORIC INVENTORY No. 4. Present Name(s) 189-D 2925 Walnut Street House 2 County 5 Other Name(s) Jackson 3 Location of Negatives MT #17-16 Landmarks Commission Henry J. Blauw residence 6 Specific Location 16. Thematic Category 28. No. of Stories Jackson 030 29. Basement? Yes I 2925 Walnut 17 Date(s) or Period No I 30. Foundation Material c. 1895 7 City or Town If Rural, Township & Vicinity Kansas City, Missouri 18 Style or Design 14 cottage 31. Wall Construction frame wu B. Site Plan with North Arrow 19 Architect or Engineer 32. Roof Type & Material GB 20. Contractor or Builder pinch gable; comp. shingle FL 33. No. of Bays 2925 Front Side 21 Original Use, if apparent Present Namers residence 34. Wall Treatment asbestos shingle Walnut 22 Present Use 35. Plan Shape rectangular residence 23 Ownership Public 1 36. Changes Addition : Private X (Explain Altered | in #42) Moved i 24. Owner's Name & Address, if known 37. Condition Interior 9 Coordinates UTM good Exterior Lat. Long 25. Open to 38 Preservation Yes Yes Public? No X No IX Underway? Sile 1: Structure | Building XI Object ! 26. Local Contact Person or Organization 39. Endangered? Yes No IX By What? Landmarks Commission 11. On National Yes X Yesli 12 Is It Register? No X Eligible? No 27. Other Surveys in Which Included 13 Part of Estab Yes I I District Yes X Yes !X 40. Visible from Potent'l? No Hist. Dist.? No XI Public Road? No 1 41. Distance from and 15. Name of Established District Frontage on Road 15 feet on Walnut 42. Further Description of Important Features This small cottage faces west, with a rectangular window and entrance on the main facade. Slender wood posts support a hip roofed from porch. window fenestrates the gable area. Photo 43. History and Significance The 1st known resident of this house, Henry Blauw, was a marble cutter. 44. Description of Environment and Outbuildings An apartment building is north of this house. To the south is another residence. A surface parking lot is to the west and vacant land is to the east. 45 Sources of Information WP #28267 46. Prepared by Piland 47. Organization Landmarks Commission 48. Date 49. Revision Date(s) 4/10/81

State Historical St ey and Planning Office, 909 Unimorsity Avenue, Suite 215,



-
•
-
•
-
-
-
-
-
C
-
6-
-

	JINIO IIV	VENTORY	mbia, Missouri 65201 A-AS-008-1495
I. No. 189-E	4, Pres	ent Name(s)	
2. County	2	927 Walnut Street House	o shed
Jackson		er Name(s)	mis 1495
Location of Negatives MT Landmarks Commission	#17-17		140-
Specific Location		16. Thematic Category	28. No. of Stories 1½
			29. Basement? Yes XX
2927 Walnut		17 Date(s) or Period	No I.
City or Town II Burn T	awashin & Visinity	1911 18 Style or Design	30. Foundation Material stone 40
City or Town II Rural, To Kansas City, Missouri	L Vicinity	at Style of Design	31. Wall Construction
Site Plan with North Arrow		19. Architect or Engineer	masonry UD
	M	20. Contractor or Builder	32. Roof Type & Material GB gable; comp. shingle 3
	N		33. No. of Bays
	- 1	21. Original Use, if apparent	Front 3 Side
3	T	residence DIA + L	34. Wall Treatment brick 30
3		residence	35. Plan Shape rectangular
1/4	1	23 Ownership Public !!	36. Changes Addition ::
12		PrivateXX  24. Owner's Name & Address.	(Explain Altered I ' in #42) Moved I
		if known	37. Condition
Coordinates UTM			Interior
Lat. Long		25. Open to Yes II	Exterior good
Site!:	Structure	Public?	38. Preservation Yes : Underway? No XX
Building 1 <sub>X</sub>	Object 11	26. Local Contact Person or Organization	39. Endangered? Yes XX
		Tandanala Camatantan	By What? No !:
**************************************	Is It Yes X	Landmarks Commission	
Register? No lx	Eligible? No ::	27. Other Surveys in Which Included	possible demolition
Register? No 1x	Eligible? No 1!		possible demolition  40 Visible from Yes XX Public Road? No 11
Register? No lx  Part of Estab. Yes II 14 Hist. Dist.? No lx	Eligible? No :: District Yes X Potent'!? No ::		possible demolition  40. Visible from Public Road? Yes XX No ::  41. Distance from and
Register? No 1/2  Part of Estab. Yes     14  Hist. Dist.? No 1/2  Name of Established District	Eligible? No :: District Yes  X Potent'l? No ::	27. Other Surveys in Which Included	possible demolition  40. Visible from Yes XX Public Road? No      41. Distance from and Frontage on Road  25 feet on Walnut
Register? No 1x 14  3 Part of Estab. Yes 11 14  Hist. Dist.? No 1x 14  5. Name of Established District  2. Further Description of Importance of Columns resting of Sable area above is storn the north and south	District Yes X Potent'l? No :-  ortant Features A on stone bases tuccoed and ha an facade are s		possible demolition  40 Visible from Yes XX Public Road? No!!  41 Distance from and Frontage on Road 25 feet on Walnut  a facade, supported by ishes the porch. The w fenestrates the gable. walls. The dormers
Register? No 1x  No 1x  Register? No 1x  No 1x  No 1x  Register? No 1x  Register. No 1x  Re	District Yes X Potent'l? No:	27. Other Surveys in Which Included  hip roofed porch extends across the A wood railing further distinguis bracketed eaves. A double window hed roofed dormers with clapboard w	possible demolition  40 Visible from Yes XX Public Road? No!!  41 Distance from and Frontage on Road 25 feet on Walnut  25 feet on Walnut  26 facade, supported by ishes the porch. The walls. The dormers ade.  40 walls. The dormers are house to the north
Part of Estab. Yes 11 Hist. Dist.? No 12 Name of Established District Part her Description of Importance of Columns resting of Cable area above is stored in the north and south contain Palladian—motion of Part of Cable area above is stored to the north and south contain Palladian—motion of Environment house. To the expression of Environment house. To the expression of Part of Par	District Yes X Potent'l? No:	hip roofed porch extends across the A wood railing further distinguis bracketed eaves. A double window hed roofed dormers with clapboard win oriel window is on the south face lent of this house is unknown, although the control of t	possible demolition  40 Visible from Yes XX Public Road? No!!  41 Distance from and Frontage on Road 25 feet on Walnut  25 feet on Walnut  26 facade, supported by ishes the porch. The walls. The dormers ade.  40 walls. The dormers are house to the north  41 Distance from and Frontage on Road  42 feet on Walnut  43 feet on Walnut  44 south of this for the west.  45 Prepared by Piland  46 Prepared by Piland  47 Organization
Register? No 1x 14  Part of Estab. Yes 11 14  Hist. Dist.? No 1x 15  Name of Established District  Perther Description of Importance of Columns resting of Sable area above is storn the north and south contain Palladian-motification Palladian-motification (2925 Walnut)  Description of Environment house. To the experience of Information	District Yes X Potent'l? No:	hip roofed porch extends across the A wood railing further distinguis bracketed eaves. A double window hed roofed dormers with clapboard win oriel window is on the south face lent of this house is unknown, although the control of t	possible demolition  40 Visible from Yes XX Public Road? No!!  41 Distance from and Frontage on Road 25 feet on Walnut  25 feet on Walnut  26 facade, supported by ishes the porch. The walls. The dormers ade.  46 Prepared by Piland



olumbia, Missouri 65201 HISTORIC INVENTORY JA-AS-008-4. Present Name(s) No 189-G 2937 Walnut Street House 2 County 189-G 5 Other Name(s) Jackson 3 Location of Negatives MT #102-16 Landmarks Commission J.W. Axtell residence 6. Specific Location 16. Thematic Category 28. No. of Stories Jackson Jackson 030 29. Basement? Yes 2937 Walnut 17 Date(s) or Period No I 30. Foundation Material 1897; (add. 1983) stone 90 7 City or Town II Rural, Township & Vicinity Kansas City, Missouri 18 Style or Design 40 31. Wall Construction LB WU B. Site Plan with North Arrow 19. Architect or Engineer olher masonry 32. Roof Type & Material Devine Architects (1983) 20. Contractor or Builder flat; tar and gravel Alpert Company (1983) 33. No. of Bays 2937 Walnut 21. Original Use, if apparent proch Front Side residence OIA 34. Wall Treatment 22. Present Use brick 35. Plan Shape residence irregular 36. Changes 23 Ownership Public 11 Addition ix Private IX (Explain Altered | in #42) Moved i 24. Owner's Name & Address, if known 37. Condition Interior 9. Coordinates UTM Exterior good Lat Long 25. Open to Yes ! : Preservation Yes X Public? NOIX Underway? No I 10 Site!: Structure 1 Building X Object ! ! 26. Local Contact Person or Organization 39. Endangered? Yes ! By What? Nox Yes X 11. On National Landmarks Commission Yes 12 Is It Eligible? Register? No X No 1 27. Other Surveys in Which Included Yes X 13. Part of Estab. Yes !! 14. District Visible from Yes X Hist. Dist.? No XI Potent'1? No: Public Road? No II Distance from and 15. Name of Established District Frontage on Road 30 feet on Walnut 42. Further Description of Important Features This residence is currently being restored. The main facade faces west. A flat roofed porch extends across the main facade and partially along the south facade. The porch features ornate turned spindlework. The original windows on the west facade have been replaced Photo with single-pane, fixed windows. A denticulated cornice with modillions Axtell runs across the west facade and partially along the south facade. In 1983 an attached garage was placed at the rear of the house, featuring a wood shingle mansard roof. residence 43 History and Significance This house was 1st occupied by J. W. Axtell, a railroad brakeman. 44. Description of Environment and Outbuildings Vacant lots are to the south and east. To the north is a residence. A surface parking lot is to the west. 45 Sources of Information 46. Prepared by WP #13230 Piland BP #A57573 47. Organization Landmarks Commission 49. Revision Date(s) 48. Date 4/2/81

State Historical Survey and Planning Office, 909 University Avenue, Suite 215,



47. Organization

3/31/82

Landmarks Commission 48. Date 49. Revision Date(s)

WP #28352



C
2
-
-
-
0
=
e
=
5

	TORIC IN		TA-AS-008-1498
1. No. 203-b		sent Name(s)	*
2. County	30	14 Walnut Street Floot	
Jackson		ner Name(s)	
Location of Negatives Landmarks Commiss:	MT #19-18		
Specific Location	***************************************	16. Thematic Category	28. No. of Stories 2
3014 Walnut		030	29. Basement? Yes IX
		17. Date(s) or Period	No I
		c. 1890	30. Foundation Material
City or Town Kansas City, Misso	al, Township & Vicinity	18. Style or Design 52	stone 90
Site Plan with North Ar		19. Architect or Engineer	31. Wall Construction frame
One Flan with Hollin An	M	70. Alcimed of Engineer	32. Roof Type & Material
	N	20. Contractor or Builder Pnch	hip; comp. shingle
	17	ms	33. No. of Bays Front 2 Side
1 3		21. Original Use, if apparent residence	Front 2 Side  34. Wall Treatment
5		22. Present Use	asbestos siding 64
. 1	ſ	residence	35. Plan Shape rectangular
3		23 Ownership Public 11	36. Changes Addition ::
1		Private IX	(Explain Altered I in #42) Moved I
		24. Owner's Name & Address, if known	37. Condition
Coordinates	UTM		Interior
Lat.	-,,,,,,		Exterior good
Long		25. Open to Yes IX Public? No II	38. Preservation Yes
Site ! :	Structure     Object		Underway? No XX
On National Yes []	12 Is It Yes X	26. Local Contact Person or Organization Landmarks Commission	39. Endangered? Yes XX By What? No 1
Register? No X	Eligible? No	27. Other Surveys in Which Included	possible demolition
Part of Estab. Yes !!	14. District Yes X		40. Visible from Yes XX
Hist. Dist.? No V	Potent'1? No : .		Public Road? No 11
X	1000000		41 Distance from and
Name of Established D	istrict		41. Distance from and Frontage on Road approx 22 feet on Walnut
Further Description of characterizes story porch; entrance is a is a door open	istrict  Important Features A p  the east facade the 2nd story has t the north end oning onto the por		41. Distance from and Frontage on Road approx 22 feet on Walnut ugh second stories and piers of the first he perimeter. The ove, on the 2nd floor,
Name of Established D  Further Description of characterizes story porch; entrance is a is a door open.  History and Significance shipping clerk.	Important Features A parties the east facade the 2nd story has to the north end on the posterior of the earliest known and outbuildings	Coursed stone provides the base wood piers and a railing around to the east facade. Immediately about	41. Distance from and Frontage on Road approx 22 feet on Walnut ugh second stories and piers of the first he perimeter. The ove, on the 2nd floor, was Harry P. Hovey, a building. To the
Name of Established D  Further Description of characterizes story porch; entrance is a is a door open  History and Significance thipping clerk.  Description of Environm south and east	Important Features A parties the east facade the 2nd story has to the north end on the posterior of the earliest known and outbuildings	Coursed stone provides the base is wood piers and a railing around to f the east facade. Immediately about area.  nown resident of this house (1892)  Vacant land is north of this	41. Distance from and Frontage on Road approx 22 feet on Walnut ugh second stories and piers of the first he perimeter. The ove, on the 2nd floor, was Harry P. Hovey, a building. To the
Name of Established D  Further Description of characterizes story porch; entrance is a is a door open in the story and Significance thipping clerk.  Description of Environm south and east  Sources of Information	Important Features A parties the east facade the 2nd story has to the north end on the posterior of the earliest known and outbuildings	Coursed stone provides the base is wood piers and a railing around to f the east facade. Immediately about area.  nown resident of this house (1892)  Vacant land is north of this	41. Distance from and Frontage on Road approx 22 feet on Walnut ugh second stories and piers of the first he perimeter. The ove, on the 2nd floor, was Harry P. Hovey, a building. To the ommercial building.
Name of Established D  Further Description of characterizes story porch; entrance is a is a door open in the story and Significance shipping clerk.  Description of Environm south and east  Sources of Information	Important Features A parties the east facade the 2nd story has to the north end on the posterior of the earliest known and outbuildings	Coursed stone provides the base is wood piers and a railing around to f the east facade. Immediately about area.  nown resident of this house (1892)  Vacant land is north of this	41. Distance from and Frontage on Road approx 22 feet on Walnut ugh second stories and piers of the first he perimeter. The ove, on the 2nd floor, was Harry P. Hovey, a building. To the ommercial building.  46. Prepared by Piland 47. Organization
Name of Established D  Further Description of characterizes story porch; entrance is a is a door open.  History and Significance thipping clerk.	Important Features A parties the east facade the 2nd story has to the north end on the posterior of the earliest known and outbuildings	Coursed stone provides the base is wood piers and a railing around to f the east facade. Immediately about area.  nown resident of this house (1892)  Vacant land is north of this	41. Distance from and Frontage on Road approx 22 feet on Walnut ugh second stories and piers of the first he perimeter. The ove, on the 2nd floor, was Harry P. Hovey, a building. To the ommercial building.  46. Prepared by Piland



		VENTORY	ity Avenue, Suite 215, lumbia, Missouri 65201	
1. No. 204-R 2 County	4. Pres	sent Name(s) 3015 WalnutStreet House ser Name(s)	275000 - 1-11 1	204-
Jackson  3 Location of Negatives M. Landmarks Commission	T #84-14	mer E. Freeman residence		R
6. Specific Location 3015 Walnut	,	16. Thematic Category  30  17. Date(s) or Period	28. No. of Stories $1\frac{1}{2}$ 29. Basement? Yes $ X $	Jackson
7 City or Town If Rural Kansas City, Misson B. Site Plan with North Arrow B. Site Plan with Nort	Structure I Object I I  12 Is It Yes X Eligible? No II  14 District Yes X Potent'!? No X	1909  18. Style or Design  19. Architect or Engineer Sidney R. Frink  20. Contractor or Builder  21. Original Use, if apparent residence 22. Present Use residence 23. Ownership  24. Owner's Name & Address, if known  25. Open to Public?  26. Local Contact Person or Organization Landmarks Commission  27. Other Surveys in Which Included	(Explain in #42) Altered   Moved    37. Condition Interior Exterior good  38. Preservation Yes	
porch base which ext of three windows who decorative brackets	tends across the ich possess a br support the mai This house wall Marshall.	oursed stone provides the material west facade. The gable area is tacketed sill, and are sheltered in roof gable. The south facade is built for Elmer E. Freeman, a partment building is east of sidences.	fenestrated with a series by a shed roof. Larger features a stone chimney.	Elmer E. Freeman residence



HISTORIC INVENTORY 5A-AS-008-1500 4. Present Name(s) 1. No. 203-a 3016 Walnut Street Flat 2. County 203-a 5 Other Name(s) Jackson 3 Location of Negatives MT #19-19 Landmarks Commission 6. Specific Location 16. Thematic Category 28. No. of Stories Jackson 030 29. Basement? Yes I 3016 Walnut 17. Date(s) or Period No I 1896 30. Foundation Material City or Town II Rural, Township & Vicinity Kansas City, Missouri 18. Style or Design 31. Wall Construction frame WW B. Site Plan with North Arrow 19. Architect or Engineer prob 32. Roof Type & Material GB FU gable; comp. shingle 20. Contractor or Builder John C. Bonham 33. No. of Bays Front Side 21. Original Use, if apparent Present Name(s) residence 018 34. Wall Treatment 22. Present Use asbestos siding residence 35. Plan Shape rectangular 23 Ownership Public 11 36. Changes Addition : Private to (Explain Altered I in #42) Moved i 24. Owner's Name & Address, if known 37. Condition 3016 Interior 9. Coordinates UTM Exterior Lat. good Long 25. Open to Yes I 38. Preservation Yes . Underway? No XX 10 No XX Site!: Structure I Building Ix Object ! ! Yes XX 39. Endangered? 26. Local Contact Person or Organization By What? No I Landmarks Commission 11. On National YesX Yesli 12 Is It Eligible? Register? No 1 No I 27. Other Surveys in Which Included possible demolition Yes Yes XX 13 Part of Estab. Yes 11 14 District 40. Visible from Hist. Dist.? No IX Potent'1? No: Public Road? No 11 41. Distance from and 15. Name of Established District Frontage on Road 20 feet on Walnut 42. Further Description of Important Features A flat roofed porch extends across the 1st floor of the east facade. The porch roof is supported by wood piers. An entrance door is located at the south end of the east facade. At the south end on the 2nd floor is a door leading onto the porch roof. This door is protected by a small shed roof. A gabled projection shelters the 2nd floor windows, north of this door. 43. History and Significance The earliest known resident of this house (1902), was a laborer, George Toyne. 44. Description of Environment and Outbuildings A commercial building is west of this To the north, south, and east are other residences. 46. Prepared by 45 Sources of Information Piland / Uguccioni WP #12800 47. Organization Landmarks Commission 48. Date 49. Revision Date(s)

State Historical Survey and Planning Office, 909 University Avenue, Suite 215,

plumbia, Missouri 65201

9/2/81



1. No. 203-Z	ORIC IN	sent Name(s)	5A-AS-008-1501
2. County	301	8 Walnut Street House	
Jackson	Control of the Contro	ner Name(s)	
3 Location of Negatives Landmarks Commissi	MT #19-20		
6. Specific Location		16. Thematic Category	28. No. of Stories 1
3018 Walnut		030	29. Basement? Yes IX
		17. Date(s) or Period	No I
City or Town II Rura Kansas City, Misso	I, Township & Vicinity		brick 30
			31. Wall Construction
B. Site Plan with North Arrow		19. Architect or Engineer	frame WW 32. Roof Type & Material ♥ B
		20. Contractor or Builder puch	gable/shed; comp. shing
	17	21. Original Use, if apparent	33. No. of Bays Front 2 Side
	k	residence OIA	34. Wall Treatment 99
	2	22. Present Use residence	clapboard
	70	23 Ownership Public !	35. Plan Shape irregular 36. Changes Addition:
	7	Private IX	(Explain Altered XX in #42) Moved
	4	24. Owner's Name & Address, if known	37. Condition
Coordinates	TM		Interior
Lat. Long.		** O	Exterior good
O Site!:	Structure	25. Open to Yes   Public? No lx	38. Preservation Yes Underway? No i
Building X	Object 11	26. Local Contact Person or Organization	39. Endangered? Yes XX
1. On National Yes 11 Register? No let	12 Is It Yes X Eligible? No	Landmarks Commission 27. Other Surveys in Which Included	By What? No 1:
3. Part of Estab. Yes II	14. District Yes	27. Other Surveys in Which included	40. Visible from Yes XX
Hist. Dist.? No V	Potent'l? No :		Public Road? No 11
5. Name of Established Di	strict		41. Distance from and Frontage on Road
			23 feet on Walnut
coofed porch extend	s across the fac picture window f	ais building was repaired in 1980 for ade. Three wood columns resting of lanked by sash windows fenestrates gable area. A shed roof extends fr	n stone bases support the facade. A modified
Palladian window is gable roof.  3. History and Significance a watchmaker. A f Machinery Co.	The earliest kn ew years later C	own resident of this house (1892) was secretary/trasurer of Caps  Vacant land is south of this	Brothers Special Printers building, To the
Palladian window is gable roof.  3. History and Significance a watchmaker. A f Machinery Co.	The earliest kn ew years later C	own resident of this house (1892) vaps was secretary/trasurer of Caps	Brothers Special Printers building, To the
Palladian window is gable roof.  3. History and Significance a watchmaker. A formation of Environment east and north	The earliest kn ew years later C	own resident of this house (1892) was secretary/trasurer of Caps  Vacant land is south of this	Brothers Special Printers  building, To the  t is to the west.
Palladian window is gable roof.  3. History and Significance a watchmaker. A f Machinery Co.  4. Description of Environm east and north  5. Sources of Information WP #16546	The earliest kn ew years later C	own resident of this house (1892) was secretary/trasurer of Caps  Vacant land is south of this	Brothers Special Printers building, To the
Palladian window is gable roof.  3. History and Significance a watchmaker. A f Machinery Co.	The earliest kn ew years later C	own resident of this house (1892) was secretary/trasurer of Caps  Vacant land is south of this	building. To the t is to the west.  46. Prepared by Piland 47. Organization
Palladian window is gable roof.  3. History and Significance a watchmaker. A f Machinery Co.  4. Description of Environm east and north	The earliest kn ew years later C	own resident of this house (1892) was secretary/trasurer of Caps  Vacant land is south of this	Brothers Special Printers building. To the t is to the west.  46 Prepared by Piland



1. No.		ent Name(s)	5A-AS-008-1502
204-Q 2 County	302	21 Walnut Street House	
Jackson	the support of the state of the	r Name(s)	
3 Location of Negatives MT # Landmarks Commission	19-22 Wil	liam F. Mayer residence	
6 Specific Location		16. Thematic Category	28. No. of Stories 2½ -
		036	29. Basement? Yes XX
3021 Walnut		17. Date(s) or Period 1899 (add. 1965)	No I.
City or Town If Rural, Tow Kansas City, Missouri	inship & Vicinity	18 Style or Design	stone 40
		49	31. Wall Construction masonry LB LLD
Site Plan with North Arrow		19. Architect or Engineer	32. Roof Type & Material
N		20. Contractor or Builder	hip; comp. shingle 63
14		21. Original Use, if apparent	33. No. of Bays Front 2 Side 4
a war		residence OIA FLL	34. Wall Treatment
2		22. Present Use	brick 30 69
1 8		residence	35. Plan Shape rectangular
. 3		23 Ownership Public   Private 1/2x	(Explain Addition x:
		24. Owner's Name & Address,	in #42) Moved
		if known	37. Condition Interior
Coordinates UTM Lat.			Exterior good
Long		25. Open to Yes 11	38. Preservation Yes
Site ! :	Structure I - 2 Object I I	Public? No 1x	Underway? No XX
Building XX		26. Local Contact Person or Organization Landmarks Commission	39. Endangered? Yes I No XX
	ligible? No	27. Other Surveys in Which Included	
	District Yes XX		40. Visible from Yes XX Public Road? No 1:
Hist Dist ? Novy	Polentii No		- rubiic noau: No i
	Potent'l? No :		41. Distance from and
Name of Established District			Frontage on Road 23 feet on Walnut
2. Further Description of Importa extends across the from double windows fenestra dormer with slate walls large double hung sash	ant Features The nt, with the ate the 2nd f s is placed o windows. Tw	main facade of this house faces we porch roof supported by modern wro loor. All the windows feature stown the west roof slope. It is fend to identical dormers are on the nor slope. In 1965 a 21x32 foot a	Frontage on Road 23 feet on Walnut  est. A hip roofed porch  ought iron posts. Two  one sills. A hip roofed  estrated with two  th roof slope and an
2. Further Description of Importa extends across the from double windows fenestra dormer with slate walls large double hung sash additional one is on the south facade	ant Features The nt, with the ate the 2nd f s is placed o windows. Twhe south roofe, at the e	porch roof supported by modern wro loor. All the windows feature sto n the west roof slope. It is fene to identical dormers are on the nor slope. In 1965 a 21x32 foot a ast end. Asbestos siding ver	Frontage on Road 23 feet on Walnut  rest. A hip roofed porch ought iron posts. Two one sills. A hip roofed estrated with two th roof slope and an addition was placed neers the addition.
2. Further Description of Importa extends across the from double windows fenestra dormer with slate walls large double hung sash additional one is on the south facade	ant Features The nt, with the ate the 2nd f s is placed o windows. Tw he south roofe, at the exist was original	porch roof supported by modern wro loor. All the windows feature sto in the west roof slope. It is fene to identical dormers are on the nor slope. In 1965 a 21x32 foot a ast end. Asbestos siding ver ally the home of William F. Mayer,	Frontage on Road 23 feet on Walnut  rest. A hip roofed porch ought iron posts. Two one sills. A hip roofed estrated with two th roof slope and an addition was placed neers the addition.
2. Further Description of Importate extends across the front double windows fenestrated dormer with slate walls large double hung sash additional one is on the south facade.  3. History and Significance This confectionary firm of the confectionary firm of the confectionary firm of the confection of the south facade.	ant Features The nt, with the ate the 2nd f s is placed o windows. Tw he south roof e, at the element of Brown and add Outbuildings	porch roof supported by modern wro loor. All the windows feature sto in the west roof slope. It is fene to identical dormers are on the nor slope. In 1965 a 21x32 foot a ast end. Asbestos siding ver ally the home of William F. Mayer,	Frontage on Road 23 feet on Walnut  rest. A hip roofed porch ought iron posts. Two one sills. A hip roofed estrated with two th roof slope and an addition was placed neers the addition.  a member of the
Purther Description of Importance extends across the from double windows fenestrated dormer with slate walls large double hung sash additional one is on the north facade.  History and Significance This confectionary firm of the south facade to the confectionary firm of the south facade.	ant Features The nt, with the ate the 2nd f s is placed o windows. Tw he south roof e, at the element of Brown and add Outbuildings	porch roof supported by modern wro loor. All the windows feature sto in the west roof slope. It is fene to identical dormers are on the nor slope. In 1965 a 21x32 foot a ast end. Asbestos siding ver ally the home of William F. Mayer, Mayer.	Frontage on Road 23 feet on Walnut  rest. A hip roofed porch ought iron posts. Two one sills. A hip roofed estrated with two th roof slope and an addition was placed neers the addition.  a member of the
Name of Established District  Perther Description of Importance extends across the from double windows fenestrated former with slate walls large double hung sash additional one is on the south facade.  History and Significance This confectionary firm of the normal house. To the normal sources of Information	ant Features The nt, with the ate the 2nd f s is placed o windows. Tw he south roof e, at the element of Brown and add Outbuildings	porch roof supported by modern wro loor. All the windows feature sto in the west roof slope. It is fene to identical dormers are on the nor slope. In 1965 a 21x32 foot a ast end. Asbestos siding ver ally the home of William F. Mayer, Mayer.	Frontage on Road 23 feet on Walnut  rest. A hip roofed porch ought iron posts. Two one sills. A hip roofed estrated with two th roof slope and an addition was placed neers the addition.  a member of the  def. Prepared by Piland
2. Further Description of Importate extends across the front double windows fenestrated dormer with slate walls large double hung sash additional one is on the south facade.  3. History and Significance This confectionary firm of the confectionary firm of the confectionary firm of the confection of the south facade.	ant Features The nt, with the ate the 2nd f s is placed o windows. Tw he south roof e, at the element of Brown and add Outbuildings	porch roof supported by modern wro loor. All the windows feature sto in the west roof slope. It is fene to identical dormers are on the nor slope. In 1965 a 21x32 foot a ast end. Asbestos siding ver ally the home of William F. Mayer, Mayer.	Frontage on Road 23 feet on Walnut  rest. A hip roofed porch right iron posts. Two one sills. A hip roofed estrated with two th roof slope and an addition was placed neers the addition.  a member of the  de. Prepared by Piland 47. Organization
Name of Established District  2. Further Description of Importate extends across the front double windows fenestrated former with slate walls large double hung sash additional one is on the south facade.  3. History and Significance This confectionary firm of the normal former. To the normal former with the south facade.  4. Description of Environment and house. To the normal former we will be sources of Information with the sources of Inform	ant Features The nt, with the ate the 2nd f s is placed o windows. Tw he south roof e, at the element of Brown and add Outbuildings	porch roof supported by modern wro loor. All the windows feature sto in the west roof slope. It is fene to identical dormers are on the nor slope. In 1965 a 21x32 foot a ast end. Asbestos siding ver ally the home of William F. Mayer, Mayer.	Frontage on Road 23 feet on Walnut  rest. A hip roofed porch ought iron posts. Two one sills. A hip roofed estrated with two th roof slope and an addition was placed neers the addition.  a member of the  def. Prepared by Piland



Columbia, Missouri 65201

HISTORIC INVENTORY JA-AS-608-1503 1. No. 4. Present Name(s) 204-P Veterans of Foreign Wars, Louis A. Craig Post 18 2 County 5 Other Name(s) Jackson 3 Location of Negatives MT #19-21 Third Presbyterian Church Landmarks Commission 16. Thematic Category 6 Specific Location 3027 Walnut 17. Date(s) or Period c. 1888 (add. 1898 and 1929) 7 City or Town If Rural, Township & Vicinity Kansas City, Missouri 18 Style or Design 19 Architect or Engineer B. Site Plan with North Arrow C. P. Schmidt (1898) 20. Contractor or Builder 21 Original Use, if apparent church 22 Present Use social organization 23 Ownership 24. Owner's Name & Address. if known 9 Coordinates UTM Lat Long 25. Open to Public? Site 1: Structure | Building ! Object | | 26. Local Contact Person or Organization Yes X Landmarks Commission 11. On National Yes 12 Is It Register? No IX Eligible? 27. Other Surveys in Which Included Yes XX 13 Part of Estab. Yes 11 Yes X District 40. Visible from Hist. Dist ? No 1x Potent'1? No : Public Road? No I 41. Distance from and 15 Name of Established District Frontage on Road

42 Further Description of Important Features The back portion of the building, with a north-south axis was probably the original structure. The front portion, with an east-wes axis, is probably an addition of 1898. The main, west facade, has been considerably altered. A concrete block addition on the rear of the north facade was undertaken in 1929. Charles C. Vanderberg was the architect for the 1929 addition.

- 43. History and Significance This structure was built to house the Third Presbyterian Church. City Directory first lists the church at this address in 1889. Previously it had been in a West Bottoms location. The building continued to house the church until the 1950's, when it became a VFW Post.
- 44. Description of Environment and Outbuildings A surface parking lot is south of this building, Vacant land used for parking is to the west. To the east are residences.

## 45 Sources of Information

WP #14945

Kansas City Star, Feb. 9, 1925.

K.C. Architect and Builder, Sept. 1898, p. 262.

46. Prepared by Piland

47. Organization

Landmarks Commission

48. Date 49. Revision Date(s) 4/16/84



4/6/84

203-Y	4. Pre	seni Name(s)	
County Jackson		3030-32 Walnut Street Flat	
		ner Name(s)	
Location of Negatives Landmarks Commissi	MT #54-14 on of KC		
Specific Location		16. Thematic Category	28. No. of Stories 2
		_ 030	29. Basement? Yes x
3030-32 Walnut		17 Date(s) or Period .	No I.
City or Town If Rur	al. Township & Vicinity	1904 18. Style or Design	50. Foundation Material
Kansas City, Mis	ssouri	50 52	31. Wall Construction
Site Plan with North Ar	row	19. Architect or Engineer	masonry LLD
	<b>M</b>	20. Contractor or Builder	32. Roof Type & Material PC flat; tar & grave
	10	Frank Timmerman 30 20	33. No. of Bays 99
E .		21. Original Use, if apparent pnch duplex OIR ms	Front 2 Side
3		22 Present Use	34. Wall Treatment brick 30
0		duplex	35. Plan Shaperectangular
	3	23 Ownership Public 11	36. Changes Addition :
		Private 🔯	(Explain Altered I ! in #42) Moved i
		if known	37. Condition
THE PERSON NAMED IN COLUMN TWO IS NOT THE PERSON NAMED IN COLUMN TWO IS NAMED IN COLUMN TW	UTM		Interior
Lal. Long.		25. Open to Yes 11	Exterior good
Site!;	Structure 1	Public? Yes!	38. Preservation Yes : Underway? No X
Building XI	Object	26. Local Contact Person or Organization	39. Endangered? Yes I
On National Yes     Register? No Ki	12 Is It Yes X Eligible? No 1	Landmarks Commission	By What? No X:
	14 District Yes X	27. Other Surveys in Which Included	40. Visible from Yes X
Part of Estab Yes	1.1- 6-10-10-10-10-10-10-10-10-10-10-10-10-10-		Public Road? No !!
Part of Estab. Yes 11 Hist. Dist.? No ki	Potent'l? No ! .		110 110
Hist. Dist.? No ki	77.900.00		41. Distance from and
Hist. Dist.? No ki	77.900.00		
Name of Established D	Important Features	A flat roofed porch on both th	41. Distance from and Frontage on Road 16 feet on Walnut ne first and second
Purther Description of stories extend on the first s roof is suppor	Important Features As across the etory are quointed by wooden h segmental ar	A flat roofed porch on both the east facade. The supporting paned with (buff) brick. The sepiers. Fenestration of the each windows. A projecting bay	141. Distance from and Frontage on Road 16 feet on Walnut ne first and second piers of the porch econd story porch
Hist. Dist.? No xi Name of Established D  Further Description of stories extend on the first s roof is suppor facades is wit on the south f	Important Features As across the estory are quoin ted by wooden h segmental aracade.	east facade. The supporting placed with (buff) brick. The se piers. Fenestration of the e	41. Distance from and Frontage on Road 16 feet on Walnut ne first and second oiers of the porch econd story porch east and south window is placed
Name of Established D  Further Description of stories extend on the first s roof is suppor facades is wit on the south f  History and Significance year earlier (30)	Important Features As across the extory are quoing ted by wooden the segmental aracade.  This duplex is 134-36 Walnut).	east facade. The supporting paid with (buff) brick. The sepiers. Fenestration of the each windows. A projecting bay	141. Distance from and Frontage on Road 16 feet on Walnut the first and second oiers of the porch econd story porch east and south window is placed  to the south, erected a
Name of Established D  Property of Established D	Important Features As a cross the estory are quointed by wooden h segmental anacade.  This duplex is 134-36 Walnut).	east facade. The supporting pred with (buff) brick. The sepiers. Fenestration of the each windows. A projecting bay virtually identical to the duplex	41. Distance from and Frontage on Road 16 feet on Walnut the first and second officers of the porch east and south window is placed  to the south, erected a  this structure. A similast is a surface parking
History and Significance year earlier (30)  Description of Environmental duplex is to lot.	Important Features As a cross the estory are quointed by wooden h segmental anacade.  This duplex is 134-36 Walnut).	east facade. The supporting pred with (buff) brick. The sepiers. Fenestration of the each windows. A projecting bay virtually identical to the duplex	41 Distance from and Frontage on Road 16 feet on Walnut ne first and second piers of the porch econd story porch east and south window is placed  to the south, erected a  this structure. A simi- ast is a surface parking



State Historical Survey and Planning Office, 909 University Avenue, Suite 215

Columbia, Missouri 65201

11-15-83



25 feet on Walnut

Columbia, Missouri 65201

4. Present Name(s) 1. No. 203-W 3038-40 Walnut Street Float 2 County 5. Other Name(s) Jackson 3 Location of Negatives Landmarks Commission 6. Specific Location 16. Thematic Category 030 3038-40 Walnut 17 Date(s) or Period 1901 7 City or Town II Rural, Township & Vicinity Kansas City, Missouri 18 Style or Design 50 B. Site Plan with North Arrow 19. Architect or Engineer 20. Contractor or Builder J. A. Rose 21. Original Use, if apparent duplex 22. Present Use duplex 23 Ownership 24. Owner's Name & Address, if known 9 Coordinates UTM Lat. Long 25. Open to Site !: Structure \ Object | | Building ! 26. Local Contact Person or Organization Landmarks Commission 11. On National Yes X Yes 12 Is II Register? No I Eligible? No I 27. Other Surveys in Which Included Yes x 13. Part of Estab. Yes II District Hist. Dist ? No 11 Potent'1? No ! 15. Name of Established District

42. Further Description of Important Features The "L" shape of the east facade accommodates a two-story porch at the north end. Brick piers support the flat porch roofs. The projecting southern bay is fenestrated with segmental arch windows. The parapet wall features patterned brick detailing. The parapet steps down as the building recedes eastward on the lot.

43. History and Significance One of a pair of duplexes erected for realtor J. A. Rose.

44. Description of Environment and Outbuildings An identical duplex is south of this structure. To the east is a surface parking lot. A commercial building is to the west. Another duplex is to the north

45 Sources of Information WP #38243 WP#19830

46. Prepared by Piland/Uguccioni 47. Organization Landmarks Commission 48. Date 49. Revision Date(s) 12/17/84



203-V	4. Pres	ent Name(s)		T
2 Caustu	3	042-44 Walnut		203-
Jackson		er Name(s)		<
3 Location of Negatives MT #54-17 Landmarks Commission of KC				
Specific Location		16. Thematic Category	28. No. of Stories 2	
3042-44 Walnut		17. Date(s) or Period	29. Basement? Yes I	x Ja
		1901	30. Foundation Material	Jackson
City or Town - If Rural, Township	& Vicinity	18 Style or Design	stone 40	on
Kansas City, Missouri Site Plan with North Arrow	-	50 52 19. Architect or Engineer Oblus	31. Wall Construction masonryUD	
. Site Flan Will North Allow		30 20	32. Roof Type & Material F P	2
1		20. Contractor or Builder Purch	flat; tar and grave	-
		J.A. Rose (realtor)	33. No. of Bays Front Side 99	
3		duplex OIB	34. Wall Treatment	3042
arsa O		22. Present Use	brick 30	-
		23 Ownership Public ! !	35. Plan Shaperectangular 36. Changes Addition:	Walnut
3		Private   x	(Explain Altered i	nu
		24. Owner's Name & Address, if known	in #42) Moved	
Coordinates UTM		n known	37. Condition Interior	
Lat.			Exterior good	-
Long.		25 Open to Yes I i Public? No id	38. Preservation Yes in Underway? No it	100
D. Site!: S Building to	Object : 1	26. Local Contact Person or Organization	39. Endangered? Yes i	
1. On National Yes   12 Is It Register? No ⊠ Eligible	Yes x		By What? No I:	X
3. Part of Estab. Yes   1 14. District	ct Yes X	27. Other Surveys in Which Included	40. Visible from Yes !:	
Hist. Dist.? No XI Potent	1'1? No : .		Public Road? No I	
5. Name of Established District			Frontage on Road	1
			25 ft. on Walnut	1
2. Further Description of Important Fe	eatures The	main racade of this building race		
of the east facade accomd flat porch roofs. The pr The parapet wall features receds eastward on the lo	lates a two cojecting s patterne ot. At un	wo-story porch at the north end. Be southern bay is fenestrated with sed brick detailing. The parapet staknown dates an additional entrance och and a basement garage was place	rick piers support the segmental arch windows. eps down as the buildin door was added on the	
of the east facade accomd flat porch roofs. The pr The parapet wall features receds eastward on the lo north wall of the first i main facade.	lates a two rojecting s patterne ot. At un floor por	wo-story porch at the north end. Be southern bay is fenestrated with sed brick detailing. The parapet staknown dates an additional entrance	erick piers support the segmental arch windows. seps down as the buildin door was added on the d at the south end of the	
flat porch roofs. The pr The parapet wall features receds eastward on the lo north wall of the first i main facade.	lates a two rojecting s patterne ot. At un floor por	wo-story porch at the north end. Be southern bay is fenestrated with sed brick detailing. The parapet st known dates an additional entrance och and a basement garage was place	erick piers support the segmental arch windows. seps down as the buildin door was added on the d at the south end of the	
of the east facade accomd flat porch roofs. The pr The parapet wall features receds eastward on the lo north wall of the first in main facade.	lates a two rojecting s patterne ot. At un floor por	wo-story porch at the north end. Be southern bay is fenestrated with sed brick detailing. The parapet st known dates an additional entrance och and a basement garage was place	erick piers support the segmental arch windows. seps down as the buildin door was added on the d at the south end of the	
of the east facade accomd flat porch roofs. The pr The parapet wall features receds eastward on the lo north wall of the first main facade.  3. History and Significance ne of a	dates a two rojecting spatterned to the spattern	wo-story porch at the north end. Be southern bay is fenestrated with seed brick detailing. The parapet staknown dates an additional entrance och and a basement garage was place duplexes erected by realtor J. A. commercial building is south of the	rick piers support the segmental arch windows. eps down as the buildin door was added on the d at the south end of the Rose.	he
of the east facade accomd flat porch roofs. The pr The parapet wall features receds eastward on the lo north wall of the first main facade.  3. History and Significanc@ne of a surface parking lot. As	dates a two rojecting spatterned to the spattern	wo-story porch at the north end. Be southern bay is fenestrated with seed brick detailing. The parapet staknown dates an additional entrance och and a basement garage was place duplexes erected by realtor J. A.	rick piers support the segmental arch windows. eps down as the buildin door was added on the d at the south end of the Rose.	he
of the east facade accomd flat porch roofs. The pr The parapet wall features receds eastward on the lo north wall of the first main facade.  3. History and Significanc@ne of a surface parking lot. And he west.  5. Sources of Information	dates a two rojecting spatterned to the spattern	wo-story porch at the north end. Be southern bay is fenestrated with seed brick detailing. The parapet staknown dates an additional entrance och and a basement garage was place duplexes erected by realtor J. A. commercial building is south of the	rick piers support the segmental arch windows. eps down as the buildin door was added on the d at the south end of the Rose.  Rose.  46 Prepared by	he
of the east facade accomd flat porch roofs. The pr The parapet wall features receds eastward on the lo north wall of the first imain facade.  3. History and Significancene of a	dates a two rojecting spatterned to the spattern	wo-story porch at the north end. Be southern bay is fenestrated with seed brick detailing. The parapet staknown dates an additional entrance och and a basement garage was place duplexes erected by realtor J. A. commercial building is south of the	rick piers support the segmental arch windows. eps down as the buildin door was added on the d at the south end of the Rose.  Rose.  is building. To the eas ercial building is to	he
of the east facade accomd flat porch roofs. The pr The parapet wall features receds eastward on the lo north wall of the first main facade.  3. History and Significanc@ne of a surface parking lot. An he west.	dates a two rojecting spatterned to the spattern	wo-story porch at the north end. Be southern bay is fenestrated with seed brick detailing. The parapet staknown dates an additional entrance och and a basement garage was place duplexes erected by realtor J. A. commercial building is south of the	rick piers support the segmental arch windows. Seps down as the building door was added on the dat the south end of the Rose.  Rose.  46. Prepared by PILAND / Uguccioni	ne



HISTORIC INVENTORY 1. No. 165-C Reeves-Wiedeman Company (Toolside and Parts) 165 2. County 5. Other Name(s) not entered Jackson 3 Location of Negatives MT #52-21 Landmarks Commission Trans-American Freight Lines 6 Specific Location 16. Thematic Calegory 28. No. of Stories Jackson 29. Basement? Yes 2710-16 Warwick Trafficway 17. Date(s) or Period 1938 (add. 1964) 30. Foundation Material City or Town II Rural, Township & Vicinity Kansas City, Missouri 18 Style or Design 31. Wall Construction 8. Site Plan with North Arrow concrete block 19. Architect or Engineer 32. Roof Type & Material 20. Contractor or Builder flat; tar & gravel 33. No. of Bays Miller-Stauch Const. Co. (1938) 2710-16 Front Side 21. Original Use, if apparent 34. Wall Treatment commercial brick; concrete block 22. Present Use 35. Plan Shape Warwick commercial Public | | 23 Ownership 36. Changes Addition ix Private W (Explain Altered I in #42) Moved i 24. Owner's Name & Address, if known WARWICK 37. Condition Trafficway Interior 9. Coordinates Exterior good Lat. Long 25. Open to Yes IX 38. Preservation Yes Public? No II Underway? No k 10. Site ! : Structure | Building X Object | | 26. Local Contact Person or Organization 39. Endangered? Yes By What? No IX 11. On National Yes Landmarks Commission Yes 12 Is It No XX Register? No t! Eligible? 27. Other Surveys in Which Included Yes 13 Part of Estab. Yes II District Visible from Yes !X Hist. Dist ? No XI Potent'l? No XX Public Road? No 1 41. Distance from and 15. Name of Established District Frontage on Road 100 feet on Warwick Tr 42. Further Description of Important Features This building is sited on a corner, with its main facade faci south. The western most position of the building is veneered with brick and contains a single entrance door protected by a flat canopy. A 42x60 foot addition to the building extends it to the east. Inside the L formed by these two wings is a loading dock area. The Photo 1964 addition was erected by the Schweiger Construction Company. 43. History and Significance This building first housed the Trans-America Freight Lines. 44. Description of Environment and Outbuildings Another commercial building is to the south. To the north and west are surface parking lots. A vacant lot, to the east, has a gravel surface. 45 Sources of Information 46. Prepared by WP #45806 Piland BP #6193A; 7207 47. Organization Landmarks Commission 48. Date 49. Revision Date(s)

State Historical Survey and Planning Office, 909 University Avenue, Suite 215,

olumbia, Missouri 65201

12/9/81



State Historical Surv and Planning Office, 909 University Avenue, Suite 215, umbia, Missouri 65201 HISTORIC INVENTORY A-45-008-1509 4. Present Name(s) 1. No. 190-C Reeves Wiedeman Company 2. County 5 Other Name(s) Jackson not 3 Location of Negatives entered #52-20 Landmarks Commission 6. Specific Location 16. Themalic Category 28. No. of Stories 29. Basement? Yes I Jackson County 17. Date(s) or Period 2711-25 Warwick Trafficway No I 30. Foundation Material 1948 (1957, rebuilding) 7. City or Town . If Rural, Township & Vicinity 18. Style or Design 31. Wall Construction Kansas City, Missouri WARWICKTRUY masonry 8. Site Plan with North Arrow 19. Architect or Engineer A. Benberg (1957) 32. Roof Type & Material 20. Contractor or Builder flat: tar & gravel 33. No. of Bays Schweiger Const. Co. (1957) Side Front 21. Original Use, if apparent 2711-15 Present Name(s) office/warehouse 34. Wall Treatment 22. Present Use brick office/warehouse 35. Plan Shape rectangular 23 Ownership Public 11 36. Changes Addition 1 Warwick Private IX Altered I (Explain in #42) Moved i 24. Owner's Name & Address. if known 37. Condition Interior UTM 9. Coordinates good Exterior Lat. Long Yes X 25. Open to 38. Preservation Yes . Public? Noll No IX Underway? Site!: Structure I Building XX Object | | 26. Local Contact Person or Organization 39. Endangered? Yes I No IX By What? Landmarks Commission 11. On National Yes ! 12 Is It Yes 11 Register? No XX Eligible? No X 27. Other Surveys in Which Included Yes Yes !X 13 Part of Estab. Yes ! ! 14. District 40. Visible from No XX Hist. Dist.? No XX Potent'l? Public Road? No !! 41. Distance from and 15. Name of Established District 200 ft Frontage on Road on Warwick Trafficway 42. Further Description of Important Features Two large garage bays are at the east end of the north facade In the center of this facade is a row of windows, flanked by recessed entrance doors. CHIC The building contains 4,000 square feet of office and showroom space. The waxehouse area, with 20 foot ceilings, contains 35,000 square feet. isame(5, Photo 43. History and Significance A fire in October, 1956 destroyed most of the original 1948 building. exterior walls were reused in the 1957 reconstruction of this warehouse for the Reeves Wiedeman Company. The company is a wholesale distributor of plumbing and heating equipment. 44. Description of Environment and Outbuildings Union Cemetery is south, east, and west of this building. Another commercial building and a surface parking area are to the north. 45 Sources of Information 46. Prepared by Piland WP #76661 47. Organization BP #48787 Landmarks Commission Kansas City Star, May 19, 1957, p. 7D. 49. Revision Date(s) 48. Date 10/27/8



Piland

47. Organization

48. Date

4/19/82

Landmarks Commission

49. Revision Date(s)

WP #90467

BP #15592

WP #73572

BP #55385



48. Date

12/2/82

49. Revision Date(s)

Kansas City Star, Dec. 15, 1946, p. 9D.



11/24/81





-	
Cinci	
iddine(5,	

Landmarks Commission

48. Date 1/14/82 49 Revision Date(s)

Present Name(s)

State Historical Su y and Planning Office, 909 Uni sity Avenue, Suite 215, Columbia, Missouri 65201 HISTORIC INVENTORY TA-AS-008-1. No. 4. Present Name(s) 17-E 1651 Washington Street House 2. County Jackson 5 Other Name(s) 3 Location of Negatives Carrie P. Whitney Residence Landmarks Commission 6. Specific Location 16. Thematic Category Jackson 28. No. of Stories 29. Basement? Yes x 1651 Washington 17. Date(s) or Period No I c. 1887 alt 30. Foundation Material 18 Style or Design - If Rural, Township & Vicinity Kansas City, Missouri 31. Wall Construction B. Site Plan with North Arrow 19. Architect or Engineer masonry; frame 32. Roof Type & Material 68 20. Contractor or Builder gable; comp. shingle 3 33. No. of Bays TW DR pnch Front Side 21. Original Use, if apparent SL residence OIA 34. Wall Treatment 30 22. Present Use brick; asbestos siding Washing 35. Plan Shape rectangular residence 23 Ownership Public 11 36. Changes Addition Altered XX Private . (Explain in #42) Moved i 24. Owner's Name & Address, if known 37. Condition Interior 9. Coordinates UTM good Exterior Lat. Long 25. Open to Yes II Preservation Yes Public? No X NoIX Underway? 10. Site! Structure | Building Ix Object ! 26. Local Contact Person or Organization Endangered? Yes By What? No IX Yes X Landmarks Commission 11. On National Yesli 12 Is It Register? Eligible? No No IX 27. Other Surveys in Which Included Yes X 13. Part of Estab. Yes 11 14. District 40. Visible from Yes ! Hist. Dist.? No 1x Potent'1? No : Public Road? No i 41. Distance from and 15. Name of Established District Frontage on Road 42. Further Description of Important Features In 1963 the two story porch on the west facade was enclosed, severely altering the architectural features of the building. The attic story of the west facade terminates in a fenestrated gable. A brick tower pierced with segmental arch windows appears at the north end of the west facade. A gable roof dormer pierces the north roof slope. The earliest resident of the house was Carrie P. Whitney (1888). 43. History and Significance The house appears to have been built for Peter Rosenlof, a tailor who lived at 1840 Washington in 1888. Mrs. Whitney was a widow. 44. Description of Environment and Outbuildings Surface parking lots are north and south of this building. To the west is vacant land. A commercial building is to the east. 45 Sources of Information 46. Prepared by WP #11955 Uguccioni BP #78376 47. Organization



1. No.	4. Present Name(s)	JA-A5-008-1515
16-F	Mid-Central-Sysco Food Service	st
2 County	The production of the contract	
Jackson Location of Negatives MT #34-1	0	entered
Landmarks Commission #34-1	8 Carr-Heckert Fish and Oyster Co.	
Specific Location	16. Thematic Category	28. No. of Stories 2-3
1656-58 Washington (and		29. Basement? Yes I
506 West 17th Street)	17. Date(s) or Period 1913 (adds. 1949, 1952, 1961)	No 1
City of Town . If Bural Townshi		30. Foundation Material
City or Town II Aural, Townshi Kansas City, Missouri	p a vicinity 110. Style of besign	31. Wall Construction
. Site Plan with North Arrow	19. Architect or Engineer	masonry
	Jackson & McIlvain (1913) 20. Contractor or Builder	32. Roof Type & Material
	20. Contractor or Builder	flat; tar & gravel
	21. Original Use, if apparent	Front Side
	commercial	34. Wall Treatment
	22. Present Use commercial	brick
	20. Contractor or Builder  21. Original Use, if apparent  commercial  22. Present Use commercial  23. Ownership  Public 11	35. Plan Shape irregular 36. Changes Addition XX
W. 17Th ST	Private IX	(Explain Altered XX
	24. Owner's Name & Address,	in #42) Moved
	if known	37. Condition Interior
Coordinates UTM		Exterior good
Long	25. Open to Yes IX	38. Preservation Yes
	Structure   Public? No	Underway? No xx
Building X	Object     26 Local Contact Person or Organization	39. Endangered? Yes (
Register? No K! Eligib	Ves Landmarks Commission ole? No x 27. Other Surveys in Which Included	By What? No xx
Part of Estab. Yes 11 14. Distri	ict Yes	40. Visible from Yes XX
Hist. Dist.? No k! Poter		Public Road? No 11
Annual Control of the		41. Distance from and
5. Name of Established District		
	Features The Procest Structure	Frontage on Road approx 150 ft on Washington
placed on the east f a two-story addition is utilized. A load	Features The present structure was ach to the original three-story building acade. A three-story addition is not is to the south. A variety of winding dock is placed on the south factorner of the building is a garage a	Frontage on Road approx 150 ft on Washington ieved through a ng, centrally orth of this and dow fenestration ade. Projecting
2. Further Description of Important F variety of additions placed on the east f a two-story addition is utilized. A load from the southwest c	to the original three-story buildifacade. A three-story addition is not is to the south. A variety of winding dock is placed on the south factorner of the building is a garage attention of the structure facing Wassentral portion of the structure facing Wassentral	Frontage on Road approx 150 ft on Washington ieved through a ng, centrally orth of this and dow fenestration ade. Projecting ddition.
2. Further Description of Important F variety of additions placed on the east f a two-story addition is utilized. A load from the southwest c  3. History and Significance The c 1913 for the Carr-Heckert	s to the original three-story buildicacade. A three-story addition is not is to the south. A variety of winding dock is placed on the south factorner of the building is a garage at central portion of the structure facing Was Fish and Oyster Company.	Frontage on Road approx 150 ft on Washington ieved through a ng, centrally orth of this and dow fenestration ade. Projecting ddition.
2. Further Description of Important F variety of additions placed on the east f a two-story addition is utilized. A load from the southwest c  3. History and Significance The c 1913 for the Carr-Heckert  4. Description of Environment and Ocuilding. To the south are	to the original three-story buildifacade. A three-story addition is not is to the south. A variety of winding dock is placed on the south factorner of the building is a garage attention of the structure facing Wassentral portion of the structure facing Wassentral	Frontage on Road approx 150 ft on Washington ieved through a ng, centrally orth of this and dow fenestration ade. Projecting ddition.  Thington was built in est and east of this
P. Further Description of Important F variety of additions placed on the east f a two-story addition is utilized. A load from the southwest c  D. History and Significance The color of the Carr-Heckert  D. Description of Environment and October 1913. To the south are east.	s to the original three-story buildicade. A three-story addition is not is to the south. A variety of winding dock is placed on the south factorner of the building is a garage at central portion of the structure facing Was Fish and Oyster Company.	Frontage on Road approx 150 ft on Washington ieved through a ng, centrally orth of this and dow fenestration ade. Projecting ddition.  Thington was built in est and east of this
2. Further Description of Important F variety of additions placed on the east f a two-story addition is utilized. A load from the southwest c  3. History and Significance The c 1913 for the Carr-Heckert	s to the original three-story buildicade. A three-story addition is not is to the south. A variety of winding dock is placed on the south factorner of the building is a garage at central portion of the structure facing Was Fish and Oyster Company.	Frontage on Road approx 150 ft on Washington ieved through a ng, centrally orth of this and dow fenestration ade. Projecting ddition.  Thington was built in est and east of this building is also to the 46. Prepared by Piland
2. Further Description of Important F variety of additions placed on the east f a two-story addition is utilized. A load from the southwest c  3. History and Significance The c 1913 for the Carr-Heckert  4. Description of Environment and Ocuilding. To the south are east.	s to the original three-story buildicade. A three-story addition is not is to the south. A variety of winding dock is placed on the south factorner of the building is a garage at central portion of the structure facing Was Fish and Oyster Company.	Frontage on Road approx 150 ft on Washington ieved through a ng, centrally orth of this and dow fenestration ade. Projecting ddition.  Thington was built in est and east of this building is also to the 46. Prepared by Piland 47. Organization
P. Further Description of Important F variety of additions placed on the east f a two-story addition is utilized. A load from the southwest compared to the southwest of the control of the Carr-Heckert of the Carr-Heckert of the South are sast.  Sources of Information P #51041; 93872	s to the original three-story buildicade. A three-story addition is not is to the south. A variety of winding dock is placed on the south factorner of the building is a garage at central portion of the structure facing Was Fish and Oyster Company.	Frontage on Road approx 150 ft on Washington ieved through a ng, centrally orth of this and dow fenestration ade. Projecting ddition.  Thington was built in est and east of this building is also to the 46. Prepared by Piland



State Historical Sur y and Planning Office, 909 Univ -sity Avenue, Suite 215,

olumbia, Missouri 65201

4/6/84



1. No.	4. Present Name(s)		
33-Q	170	1705-15 Washington	
2. County	5 00	ner Name(s)	
Jackson 3 Location of NegativesMT #	72-6		
Landmarks Commission	Ti	riumph Manufacturing Company Bull	ling
5. Specific Location		16. Thematic Category	28. No. of Stories 1-2-/-/
1705-15 Washington		030 050	29. Basement? Yes !
		17. Date(s) or Period .	No X
City or Town - II Rural	Township & Vicinity		O)
7 City or Town II Rural, Township & Vicinity Kansas City, Missouri		50 69	31. Wall Construction
8. Site Plan with North Arrow		19. Architect or Engineer allen	masonry (LD)
		20. Contractor or Builder	32. Roof Type & Material Free flat; tar & gravel Pe
		20. Commactor or builder	33. No. of Bays 99
	1	21. Original Use, if apparent	Front 7 Side
		commercial OSE OSA AW	34. Wall Treatment brick
		22 Present Use commercial	35. Plan Shape rectangular
in the Last	•	23 Ownership Public !!	36. Changes Addition :
Washington		Private 1x	(Explain Altered I : Moved I
		24. Owner's Name & Address, if known	37. Condition
Coordinates UTM			Interior
Lal.	•		Exterior good
Long.		25. Open to Yes II	38. Preservation Yes
Site!: Building k	Structure     Object	Public? No XI	Underway? No x
	2 Is II Yes X	26. Local Contact Person or Organization Landmarks Commission	39. Endangered? Yes I By What? No ½:
Register? No K	Eligible? No	27. Other Surveys in Which Included	
	4. District Yes X		40. Visible from Yes X:
Hist. Dist.? No k	Potent'l? No i.		Public Road? No 11
15. Name of Established District			41. Distance from and
Name of Established Distri			Frontage on Road
	octant Englishes Mi	huilding is command of a toront	120 feet on Washington
2. Further Description of Imp flanked by a one sto	ry, two bay el	ne building is composed of a two stolevation on either side. Brick pies. Windows on the first story posses a stone coping.	120 feet on Washington ory three bay elevation rs with square stone
2. Further Description of Imp flanked by a one sto decorative motifs di parapet wall termina 3. History and Significance Manufacturing Compan- part of the Smith-Gri	ry, two bay elvide the bays. tes in a rough This building y. The firm seves Company of	levation on either side. Brick pies Windows on the first story posses stone coping.  was constructed for George Brinkman specialized in metal products. The	120 feet on Washington ory three bay elevation rs with square stone ss stone sills. The  to house his Triumph building is currently
P. Further Description of Imp flanked by a one sto decorative motifs di parapet wall termina Description of Environment west of this buildi Sources of Information P #64263	ry, two bay elvide the bays. Ites in a rough the building the firm state of the company of the c	Newation on either side. Brick pies  Windows on the first story posses  stone coping.  was constructed for George Brinkman  pecialized in metal products. The  complex  Other commercial buildings are not	120 feet on Washington ory three bay elevation rs with square stone ss stone sills. The  to house his Triumph building is currently  rth, south, east and  46. Prepared by Piland /Uguccioni
Further Description of Imp flanked by a one sto decorative motifs di parapet wall termina  History and Significance Manufacturing Compani art of the Smith-Gri  Description of Environment west of this buildi  Sources of Information #64263 estern Contractor, Se	ry, two bay elvide the bays. Ites in a rough the building the firm state of the company of the c	Newation on either side. Brick pies  Windows on the first story posses  stone coping.  was constructed for George Brinkman  pecialized in metal products. The  complex  Other commercial buildings are not	120 feet on Washington ory three bay elevation rs with square stone ss stone sills. The  1 to house his Triumph building is currently  1 to house his Triumph building is currently  1 to house his Triumph building is currently  1 to house his Triumph building is currently
P. Further Description of Imp flanked by a one sto decorative motifs di parapet wall termina Description of Environment	ry, two bay elvide the bays. Ites in a rough the building the firm state of the company of the c	Newation on either side. Brick pies  Windows on the first story posses  stone coping.  was constructed for George Brinkman  pecialized in metal products. The  complex  Other commercial buildings are not	120 feet on Washington ory three bay elevation rs with square stone ss stone sills. The  to house his Triumph building is currently  rth, south, east and  46. Prepared by Piland /Uguccioni



State Historical Survey and Planning Office, 909 University Avenue, Suite 215,

olumbia, Missouri 65201





HISTORIC INVENTORY 5-008-1519 4 Present Name(s) No 33-C Western Envelope; Smith-Grieves Company 2 County 33-C Jackson 3 Lucation of Negatives MT #72-7 Smith-Grieus Company Building Landmarks Commission 16 Thematic Category 28. No of Stories 6 Specific Location Jackson Courty 29. Basement? Yes 17 Date(s) or Period No 1717-19 Washington 1948 30. Foundation Material 18 Style or Design Il Rural. Township & Vicinity 7 City or Town 69 31. Wall Construction Kansas City, Mo. UD 19. Architect or Engineer 8 Site Plan with North Arrow 32. Roof Type & Material 20 Contractor or Builder flat; tar and gravel Universal Cosntruction Co. 33. No. of Bays 1717-19 Washington Side 21 Original Use, if apparent Wall Treatment commercial brick 22 Present Use 35. Plan Shaperectangular commercial 23 Ownership Public I 36 Changes Addition Private xx Altered (Explain Noved I in #42) 24 Owner's Name & Address, if known 37 Condition Interior 9 Coordinates UTM Exterior good Lung Open to Yes XX Preservation Yes Public? Underway? No I No X Structure ! . Sile: Building X Object | | 26 Local Contact Person or Organization 39. Endangered? Yes II By What? No X Yes 11 On National Yes 12 15 11 landmarks Commission Eliqible? Noxx Register? No X 27. Other Surveys in Which Included Yes 14 District Visible from 13 Part of Estab Yes Yes X Potent'1? Noxx Public Road? HIST DIST ? No X No . 41. Distance from and 15 Name of Established District Frontage on Road 103 ft on Washington 22 Further Description of Important Features The main facade of this building faces west. An entrance is recessed near the south end of this Other Name(s facade. A row of pivoted windows extends along the west facade. Each window is divided into four horizontal panes. Photo 43 History and Significance This building was constructed to serve as the offices of the Smith-Grieves Company, adjacent to the production areas of the company. de Description of Environment and Outbuildings Surface parking lots are south and east of this building. To the north and west are commercial buildings. 45 Sources of Information 46. Prepared by WP #92958 Piland BP#23987A 47. Organization Landmarks Commission 48. Date 49 Revision Date(s) 1/11/85

Office of Historic Pr servation, P.O. Box 176, Jefferson City, Missouri 65101



Columbia, Missouri 65201

47. Organization

48. Date

11/2/81

Landmarks Commission

49. Revision Date(s)

AS-008-1520

HISTORIC 'IVENTORY

BP #46135

Kansas City Star, Aug. 17, 1930, p. 1D.





t
Circi
isame(s,

1. No. 33-D	4. Present Name(s)	
2. County	1733 Washington Street Flat	
Jackson  3 Location of Negatives MT #72-	5 Other Name(s)	
Landmarks Commission	'0	
Specific Location	16. Thematic Category	28. No. of Stories 2
1733 Washington	030	29. Basement? Yes K
	17. Date(s) or Period 1899	No 1.
City or Town II Rural, Townshi Kansas City, Missouri	ip & Vicinity 218. Style or Design	O/
	24	31. Wall Construction
Site Plan with North Arrow	19. Architect or Engineer	masonry -6
11 3	20. Contractor or Builder	32. Roof Type & Material of Pe
1 3		33. No. of Bays Front 2 Side 99
1 3	21. Original Use, if apparent residence OIB	
18	22. Present Use	brick 30
1 3	residence	35. Plan Shape rectangular
	23 Ownership Public   Private   X	36. Changes Addition : : (Explain Altered !
	24. Owner's Name & Address,	in #42) Moved
	if known	37. Condition
Coordinates UTM Lat.		Exterior fair
Long	25. Open to Yes 11	38. Preservation Yes
	Structure   Public? No	Underway? No X
Building to	Object   1 26. Local Contact Person or Organization	39. Endangered? Yes i By What? No k
On National Yes   12 Is It Register? No IX Eligib	Ves X Landmarks Commission  Die? No 1: 27. Other Surveys in Which Included	- Cymai.
Part of Estab. Yes ! 1 14. Distr	rict Yes X	40. Visible from Yes X
Hist. Dist.? No 났 Poter	nt'1? No : .	Public Road? No 11
. Name of Established District		41. Distance from and Frontage on Road
		22 feet on Washington
symmetrical arrangement o	Features The west facade of the building is of features on its rectangular mass. A sheet corted by slender wooden piers. Rectangular me window transoms feature colored glass.	d roof porch, railed on windows possess stone
lugsills and lintels. Th	parapet wall.  of a pair of brick residences, side-by-side,	, in an area that has be-
lugsills and lintels. The mark the corners of the position of Environment and O	parapet wall.  of a pair of brick residences, side-by-side,	this residence. Commerci
lugsills and lintels. The mark the corners of the park the park the corners of the park the park the corners of the corn	of a pair of brick residences, side-by-side, tal.	this residence. Commerci
lugsills and lintels. The mark the corners of the posterior and Significance One of the predominantly commerciate.  Description of Environment and One of the predominantly commerciate.	of a pair of brick residences, side-by-side, tal.	this residence. Commerci th.  46 Prepared by Piland/Uguccioni
lugsills and lintels. The mark the corners of the park the park the corners of the park the park the corners of the corn	of a pair of brick residences, side-by-side, tal.	this residence. Commerci th.  46. Prepared by Piland/Uguccioni 47. Organization
History and Significance One of the predominantly commercial Description of Environment and Occurred are to the east	of a pair of brick residences, side-by-side, tal.	this residence. Commerci th.  46 Prepared by Piland/Uguccioni

State Historical Survey and Planning Office, 909 University Avenue, Suite 215,



2/9/84

1. No. 33-E	4. Pre	sent Name(s) 735 Washington Street House	-	1
2 County	Lance 1			33
Jackson	and the second s	ner Name(s)		H
3 Location of Negatives Landmarks Commissi	on			
6. Specific Location		16. Thematic Category	28. No. of Stories 2	
1735 Washington		030	29. Basement? Yes I	Jackson
		17. Date(s) or Period c. 1899	No I .	ackso
7 City or Town . Il Bura	I Township & Vicinity	18 Style or Devian	30. Foundation Material	'n
City or Town II Rura Kansas City, Misso	uri	4		
8. Site Plan with North Arrow		19. Architect or Engineer	masonry LB	
destinees)		20 0 11 1 2 11	32. Roof Type & Material PP flat; tar & gravel	
		20. Contractor or Builder		
		21. Original Use, if apparent	33. No. of Bays Front 3 Side 99	
3 -	-1	residence O/A	34. Wall Treatment	1735 Washi
1 5 6		22. Present Use	brick 30	5 W
14		residence 23 Ownership Public	35. Plan Shape rectangular	Was
My		23 Ownership Public Private	xx (Explain Altered k	hi
		24. Owner's Name & Address,	in #42) Moved i	shington
		if known	37. Condition Interior	non
9. Coordinates U	JTM		Exterior fair	
Long.		25. Open to Yes		
10. Site ! :	Structure 1	Public? No		
Building L	Object 11	26. Local Contact Person or Organization	39. Endangered? Yes III	
11. On National Yes   1	12 Is It Yes IX Eligible? No !!	Landmarks Commission	By What? No 🔀	
Register? No L Eligible? No 11  13. Part of Estab. Yes 11  14. District Yes 18		27. Other Surveys in Which Included	40. Visible from Yes ⋉	
Hist. Dist.? No 11	Potent'l? No 1.		Public Road? No 11	
15. Name of Established Dis	strict		41. Distance from and Frontage on Road	
			18 feet on Washington	
42. Further Description of Ir	mportant Features m	he west facade which has been al	tered considerably features	-
a porch which has h The flat roof of th second story is fer	peen closed on to the porch is supposestrated with respondents.	he north end and contains an ent orted by a Tuscan column resting ectangular windows that possess th corbelled brickwork and brick	rance at the south end g on a brick plinth. The stone lugsills and lintels.	Chici Halliets,
43. History and Significance come predominantly c		of brick residences, side-by-si	de, in an area that has be-	
44. Description of Environment building is to the	ent and Outbuildings east. To the n	Vacant Land is south and west orth is another residence.	of this house. A commercial	
45 Sources of Information			46. Prepared by	
WP #96330			Piland/Uguccioni	
			47. Organization Landmarks Commission 48. Date 49. Revision Date(s)	

State Historical Su y and Planning Office, 909 Unit sity Avenue, Suite 215,



1. No.		VENTORY sent Name(s)	TA-AS-008-1523
33-F	D	R.'s Place	
2. County		ner Name(s)	
Jackson 3 Location of Negatives		. A. Fletcher Grocery	
Landmarks Commission	n #/2-10 R	. A. Fletcher Glocery	
Specific Location	1 - 1	16. Thematic Category	28. No. of Stories 1-1
1741 Washington 5t	ect Building	030	29. Basement? Yes bx
	-	17. Date(s) or Period	No I.
60	*	1925 (add. 1974)	30. Foundation Material
Kansas City, Missou	ri	18. Style or Design	
B. Site Plan with North Arrow		19. Architect or Engineer	masonry; concrete bloc
. ~		40 20	32. Roof Type & Material + F+
1 3		20. Contractor or Builder	flat: tar & gravel
N R			33. No. of Bays
N Es L		21. Original Use, if apparent profit commercial ODE AW	
3		commercial ODE AW	34. Wall Treatment stucco; brick 30 61
1. W		commercial	35. Plan Shape rectangular
1/4		23 Ownership Public   1	36 Changes Addition X
13		Private XX	(Explain Altered 11 in #42) Moved 1
		24. Owner's Name & Address,	
		. Allowin	37. Condition Interior
Coordinates U'	гм		Exterior _ good
Long.		25. Open to Yes ki	38. Preservation Yes
Site!;	Structure 1	Public? No 11	Underway? No i <sub>X</sub>
Building IX	Object	26. Local Contact Person or Organization	39. Endangered? Yes I
On National Yes II	12 is it Yes :: Eligible? No is	Landmarks Commission	By What? No 1x
Register? No IX	Eligible? No 🗴	27. Other Surveys in Which Included	AN ANALYSIA COMMISSION OF THE PROPERTY OF THE
Part of Estab. Yes     Hist. Dist.? No	Potent'l? No x		40. Visible from Yes X Public Road? No 1
Name of Established Dis		1	41. Distance from and
and the second second			Frontage on Road approx.
			40 feet on Washington
		e original, 1925 structure is at the	
		74 addition. The stepped parapet of	
pent roof.	The entire west	facade has a stucco veneer. Wood	brackets support a tire
pent roor.			81 -
	mt 1 - 1 - 1 - 2 1	• 1 5 D T W-1	
		was constructed for R.J. Hader, a	realtor and originally
B. History and Significance occupied by the R.A.			realtor and originally
			realtor and originally
			realtor and originally
occupied by the R.A	. Fletcher Groc	ery.	
Description of Environme	. Fletcher Groce		
Description of Environme	. Fletcher Groce	ery.	
Description of Environme	. Fletcher Groce	ery.	
Description of Environme	. Fletcher Groce	ery.	his structure. To the
Description of Environme buth and east are re	. Fletcher Groce	ery.	his structure. To the
Description of Environment and east are respectively.  Sources of Information PR #82387	. Fletcher Groce	ery.	his structure. To the
Description of Environme buth and east are respectively.  Sources of Information IP #82387 P #14436	. Fletcher Groce	ery.	his structure. To the  46. Prepared by Piland
Description of Environme	. Fletcher Groce	ery.	46. Prepared by Piland 47. Organization



2 County Jackson  3 Location of Negatives MT #72-17 Landmarks Commission  6 Specific Location 1811 Washington Street Hor  7 City or Town If Rural, Township Kansas City, Missouri  8 Site Plan with North Arrow	16. Thematic Category  (30)  17. Date(s) or Period  1888  8 Vicinity  18. Style or Design  Queen Anne  19. Architect or Engineer	28. No. of Stories 2 29. Basement? Yes XX No 1. 30. Foundation Material
Jackson  3 Location of Negatives MT #72-17 Landmarks Commission  6 Specific Location  1811 Washington Street Hon  7 City or Town If Rural, Township Kansas City, Missouri  8 Site Plan with North Arrow	1809 Washington; Ellwood S. Hutchin  16. Themalic Category  () 30  17. Date(s) or Period  1888  8 Vicinity 18. Style or Design Queen Anne 45  19. Architect or Engineer	28. No. of Stories 2 29. Basement? Yes XX No 1. 30. Foundation Material
Landmarks Commission  6. Specific Location  1811 Washington Street Hon  7. City or Town  18 Rural, Township  Kansas City, Missouri  8. Site Plan with North Arrow	1809 Washington; Ellwood S. Hutchin  16. Themalic Category  () 30  17. Date(s) or Period  1888  8 Vicinity 18. Style or Design Queen Anne 45  19. Architect or Engineer	28. No. of Stories 2 29. Basement? Yes XX No 1. 30. Foundation Material
7 City or Town If Rural, Township Kansas City, Missouri 8 Site Plan with North Arrow	16. Thematic Category  030  17. Date(s) or Period  1888  8 Vicinity  18. Style or Design  Queen Anne  19. Architect or Engineer	28. No. of Stories 2 29. Basement? Yes XX No 1. 30. Foundation Material
7 City or Town If Rural, Township Kansas City, Missouri I. Site Plan with North Arrow	17. Date(s) or Period 1888  8 Vicinity 18. Style or Design Queen Anne 45  19. Architect or Engineer	29. Basement? Yes XX No 1.
City or Town If Rural, Township Kansas City, Missouri Site Plan with North Arrow	17. Date(s) or Period 1888  8 Vicinity 18. Style or Design Queen Anne 45  19. Architect or Engineer	30. Foundation Material
Kansas City, Missouri Site Plan with North Arrow	8 Vicinity 18. Style or Design Queen Anne 95  19. Architect or Engineer	0
Kansas City, Missouri Site Plan with North Arrow	Queen Anne 95	31. Wall Construction
Site Plan with North Arrow	19. Architect or Engineer	31. Wall Construction
\ \ \ \		masonry LB
Not :	90 30 2	32. Roof Type & Material 68
1	20. Contractor or Builder	gable/comp. shingles
	4.21	33. No. of Bays
7	residence OIA WA	Front Side Two DR
145	residence OIA WA	brick; stone 30
A.	residence	35. Plan Shape irregular
3	23 Ownership Public I !	36. Changes Addition i:
	Private L	(Explain Altered 1 Moved 1
	24. Owner's Name & Address, if known	37. Condition
Coordinates UTM		Interior
Lal.		Exterior - good-
Long	25. Open to Yes II Public? No II	38. Preservation Yes Underway? No L.
Site ! : Si	tructure 1 X	Δ.
On National Yes   12 Is It	Yes <sup>X</sup> Landmarks Commission	39. Endangered? Yes III By What? No III
Register? No IX Eligible		x
Part of Estab. Yes   14 Distric	1 YesX	40. Visible from Yes 😾
	1? No 1.	Public Road? No 11
. Name of Established District		41. Distance from and Frontage on Roadapprox.
		22 feet on Washington
he Queen Ann style. A rai he porch wraps around the outhwest corner. Rusticat he corners of the building geometric molding appears roof line at the west end		mns that support a shed roomical roof projects at the surrounds, the quoining at the second story. A sped roof gable pierces the
. History and SignificanceThis was	originally the home of realtor, Ellwood	S. Hutchin.



Landmarks Commission

48. Date 49 Revision Date(s)
1/20/82

1. No. 66-A	4. Present Name(s)	,	6
Jackson  Jocation of Negatives MT# 5-7 Landmarks Commission	1812 Washington Street House  5 Other Name(s)		66-A
6 Specific Location 1812 Washington	16. Thematic Category  17. Date(s) or Period  1889	28. No. of Stories 2½  29. Basement?  Yes X No I	Jacks
7 City or Town If Rural, Township & Vinansas City, Missouri  8. Site Plan with North Arrow  9. Coordinates UTM Lat. Long.	Queen Anne  19. Architect or Engineer  20. Contractor or Builder  21. Original Use, if apparent residence  22. Present Use residence  23. Ownership Public 11 Private XI  24. Owner's Name & Address, if known	30. Foundation Material stone 31. Wall Construction masonry 1 8 32. Roof Type & Material HP hipped gable; comp. shin 33. No. of Bays Front 2 Side D 2 34. Wall Treatment brick 30 35. Plan Shape irregular 36. Changes Addition : (Explain Altered I: Moved I) 37. Condition Interior Exterior fair	1812 Washington
10. Site!: Struct	25. Open to Yes III    Public? No X     26. Local Contact Person or Organization	38. Preservation Yes Inderway? Noxix  39. Endangered? Yes Index	
Register? No IXX Eligible?	YesX: Landmarks Commission  27. Other Surveys in Which Included  YesX No:	40. Visible from Yes WX Public Road? No 11  41. Distance from andapprox. Frontage on Road 26 feet on Washington	
southern bay recedes and fear roof shelters the porch which the main gable of the east for the main gable of the east for the east for the main gable of the east for the east fo	Queen Anne style. A northern bay projectures on the second story a multi-sided the extends across the east facade. Fish	ts forward while a bay window. A hipped scale shingles embellish was George Springer,	



42 Further Description of Important Features A shed roofed porch extends across the west facade of this residence. Wood posts, resting on brick piers, support the porch roof. At the north end of this facade is the entrance door.

43. History and Significance The first resident of this house, Carl Magnuson, was a tailor.

44 Description of Environment and Outbuildings Other residences are north, south, and west of this house. To the east is a commercial building.

45 Sources of Information WP #16387 46. Prepared by Piland

47. Organization
Landmarks Commission
48. Date 49. Revision Date(s)

8/6/82



3/15/82

49. Revision Date(s)

State Historical Survey and Planning Office, 909 University Avenue, Suite 215,



1/13/83



46. Prepared by

47. Organization

48. Date 3/15/82

Piland/Uguccioni

Landmarks Commission

49. Revision Date(s)

45 Sources of Information

Kansas City Times, July 4, 1889, p. 5.

WP #9732



-
9
-
144
ii.e
57

Jackson  3 Location of Negatives MT #72-16 Landmarks Commission  6 Specific Location 1819 Washington  7 City or Town If Rural, Township & Vici Kansas City, Missouri  8 Site Plan with North Arrow	Other Name(s)  Margaret Matteson Residence  16. Thematic Category  17. Date(s) or Period 1900  nity 18 Style or Design  19. Architect or Engineer  20. Contractor or Builder  21. Original Use, if apparent residence OLB	28. No. of Stories 2  29. Basement? Yes xx No 1  30. Foundation Material  31. Wall Construction  masonry 32. Roof Type & Material + Pe flat; tar & gravel
J Location of Negatives MT #72-16 Landmarks Commission  6 Specific Location 1819 Washington  7 City or Town If Rural, Township & Vici Kansas City, Missouri  8 Site Plan with North Arrow	Margaret Matteson Residence  16. Thematic Category  17. Date(s) or Period 1900  Inity 18 Style or Design  19. Architect or Engineer  20. Contractor or Builder  21. Original Use, if apparent	29. Basement? Yes xx No   30. Foundation Material  31. Wall Construction  masonry 32. Roof Type & Material F+ Da
Landmarks Commission  6 Specific Location  1819 Washington  7 City or Town If Rural, Township & Vicion Kansas City, Missouri  8 Site Plan with North Arrow	16. Thematic Category  17. Date(s) or Period 1900  18. Style or Design  19. Architect or Engineer 20. Contractor or Builder  21. Original Use, if apparent	29. Basement? Yes xx No   30. Foundation Material  31. Wall Construction  masonry 32. Roof Type & Material F+ Da
6 Specific Location 1819 Washington 7 City or Town If Rural, Township & Vici Kansas City, Missouri 8 Site Plan with North Arrow	17. Date(s) or Period 1900  Inity 18. Style or Design  19. Architect or Engineer 20. Contractor or Builder  21. Original Use, if apparent	29. Basement? Yes xx No   30. Foundation Material  31. Wall Construction  masonry 32. Roof Type & Material F+ Da
7 City or Town If Rural, Township & Vici Kansas City, Missouri 8. Site Plan with North Arrow	1900  18 Style or Design  19 Architect or Engineer  20. Contractor or Builder  21. Original Use, if apparent	29. Basement? Yes xx No 1.  30. Foundation Material  31. Wall Construction  masonry 32. Roof Type & Material
7 City or Town If Rural, Township & Vici Kansas City, Missouri 8. Site Plan with North Arrow	1900  18 Style or Design  19 Architect or Engineer  20. Contractor or Builder  21. Original Use, if apparent	31. Wall Construction  masonry 32. Roof Type & Material
Kansas City, Missouri  8. Site Plan with North Arrow	19 Architect or Engineer 20. Contractor or Builder 21. Original Use, if apparent	31. Wall Construction  masonry 32. Roof Type & Material F+ Da
Kansas City, Missouri  8. Site Plan with North Arrow	19 Architect or Engineer  20. Contractor or Builder  21. Original Use, if apparent	masonry 32. Roof Type & Material F+ Da
N 3	20. Contractor or Builder  21. Original Use, if apparent	32. Roof Type & Material F+ Da
Selveron)	20. Contractor or Builder  21. Original Use, if apparent Proces	flat; tar & gravel
45thin65770	21. Original Use, if apparent Price	
Bulmerr		33. No. of Bays 99
1 Sulmo	ranidanaa OIB	Front 2 Side
Sellin		34. Wall Treatment
1 %	22 Present Use residence	brick 35. Plan Shape rectangular
3.	23 Ownership Public   1	36. Changes Addition :
3	Privatexx	(Explain Altered I
,	24. Owner's Name & Address, . if known	in #42) Moved i
9. Coordinates UTM		37. Condition Interior
9. Coordinates UTM Lat.		Exterior good
Long	25. Open to Yes II	38. Preservation Yes
10. Site!: Structure Building Ki Objec		Underway? No i
	26. Local Contact Person or Organization Landmarks Commission	39. Endangered? Yes I By What? No XX
NO 10 TANGE AND RESIDENCE TO A RESIDENCE OF THE SECOND SECURITION OF THE SECOND	27. Other Surveys in Which Included	**
	5 1 <sub>X</sub>	40. Visible from Yes XX
		Public Road? No 1:
15. Name of Established District		Frontage on Road
		22 feet on Washington
42. Further Description of Important Features	A shed roof shelters a concrete slab p	proch area that extends
across the west facade. Two en	trance doors are placed at the north	end. A narrow rectan-
	h end of the second story. A broader	
coping.	lintels and sills. The parapet wall	terminates in stone
coping.		
43 History and Significance miss would be	ce was constructed for Lorenzo G. Mat	togon la vidou Margaret
its original occupant.	ice was constructed for Lorenzo G. Mac	teson's widow, Margaret,
its original occupant.		
44. Description of Environment and Outbuildin	gs Vacant land is south of this house	e. Other residences are
to the north, east, and west.		
45 Sources of Information		46. Prepared by Uguccioni
WP #17440		47. Organization
		Landmarks Commission
		48. Date 49. Revision Date(s)

State Historical Sur and Planning Office, 909 University Avenue, Suite 215, Columbia, Missouri 65201



4. Present Name(s)

2 County	1820-26 Washington Street Duplex		6
Jackson  3 Location of Negatives MT #5-4 Landmarks Commission	5 Other Name(s)		6-D
6 Specific Location 1820-26 Washington	16. Thematic Category 030  17. Date(s) or Period	28. No. of Stories 2  29. Basement?  Yes   X No   .  30. Foundation Material	Jackson
7 City or Town If Rural, Township & Kansas City, Missouri 8. Site Plan with North Arrow		stone 10 31. Wall Construction masonry UP 32. Roof Type & Material PP flat; tar & gravel 99	
WASHINGTO	Moore Brothers  21. Original Use, if apparent duplex OIB  22. Present Use apartment  23. Ownership Public   Private x	33. No. of Bays Front Side  34. Wall Treatment brick 35. Plan Shape rectangular  36. Changes Addition: (Explain Altered: in #42) Moved:	1820-26
9. Coordinates UTM Lat. Long.	24. Owner's Name & Address, if known  25. Open to Yes II	37. Condition Interior Exterior good	Washington
4.7	Public? No x    Sture   Public? No x    26. Local Contact Person or Organization  Yes   X    Landmarks Commission	38. Preservation Yes   Volume Y	
Register? No 1x Eligible?  13. Part of Estab. Yes   1	No ( ! 27, Other Surveys in Which Included Yes   x	40. Visible from Yes X. Public Road? No 11	
15. Name of Established District  42. Further Description of Important Feature	wes A coursed stone elevated basement le	41. Distance from and Frontage on Road approx. 40 feet on Washington	n

for the duplex. A porch extends on the east facade and features paired wooden columns with decorative capitals supporting a flat roof. Windows possess stone lugsills and lintels. Decorative brickwork forms the quoining at the corners, and the corbelling of the parapet wall. The building terminates in stone coping.

43. History and Significance The building was constructed by the Moore Brothers firm, who were contractor-builders.

44. Description of Environment and Outbuildings Residences are north and south of this building. To the east is vacant land. An interstate connector is to the west.

45 Sources of Information Kansas City Architect & Builder, April 1902, pp.12& WP #20364 23.

46. Prepared by Uguccioni

47. Organization Landmarks Commission 48. Date 49. Revision Date(s)

8/6/82



3/29/83



Kansas City Post, Jan. 28, 1938.

Western Contractor, Nov. 9, 1910, p. 7.

48. Date

1/7/82

49. Revision Date(s)

State historical survey and righning utilice, 909 university Avenue, suite 215



Uguccioni

47. Organization

48. Date

10/28/81

Landmarks Commission

49. Revision Date(s)

WP #13022



6/30/83

49. Revision Date(s)



20 feet on Washington

vinci irainels,

ity Avenue, Suite 215, columbia, Missouri 65201

1A-AS-008-1536

HISTORIC INVENTORY

4. Present Name(s)

Jackson	5 Other Name(s)	
3 Location of Negatives MT #72-20 Landmarks Commission		
6. Specific Location	16. Thematic Category	28. No. of Stories 23
1833 Washington	17. Date(s) or Period	28. No. of Stories 2½  29. Basement?  Yes XX  No 1.
	1903	30. Foundation Material
7 City or Town If Rural, Township & Kansas City, Missouri	52	31. Wall Construction
8. Site Plan with North Arrow	19 Architect or Engineer	masonry 32. Roof Type & Material HP
1 3 -	20. Contractor or Builder Prich William Hardacre Fu D	hip; comp. shingles63
aspulses	21. Original Use, if apparent duplex 018	Front 2 Side
	22. Present Use	brick 3D
25	duplex	35. Plan Shape rectangular
1 1/3	23 Ownership Public   Private   2	K (Explain Altered 1:
	24. Owner's Name & Address.	in #42) Moved i in
9. Coordinates UTM	if known	37. Condition Interior Exterior good
Long.	25. Open to Yes I	
	cture   Public? No 15	
Building k	yes x Landmarks Commission	39. Endangered? Yes I :  By What? No k:
Register? No k Eligible?	No 11 27. Other Surveys in Which Included	
13. Part of Estab. Yes   1	Yes ix	40. Visible from Yes X. Public Road? No 11
15. Name of Established District		41. Distance from and Frontage on Road approx.

1833 Washington Street flat

42 Further Description of Important Features A flat roof porch extends across the west facade. Two entrance doors with glass transoms are placed at the north end. The second story features a doorway with stone lintel that leads onto the wrought iron railed porch. A single rectangular window with stone lugsill and lintel fenestrates the south end of the second story. Hipped roof dormers pierce the west and north roof slopes.

One of a pair of residences (1833 and 1835 Washington) built by 43. History and Significance contractor William Hardacre.

44. Description of Environment and Outbuildings Vacant land is east of this building. Residences are north, south, and west of this building.

45 Sources of Information WP #23289

67-G

2. County

46. Prepared by Uguccioni 47. Organization Landmarks Commission 48. Date 49. Revision Date(s) 4/20/82



2/5/82

49. Revision Date(s)



SA-AK-108-1538

HISTORIC INVENTORY

1. No. 66-G	4. Present Name(s)		
a Caustu	1836-38 Washington Street flat		-99
Jackson  Jackson	5. Other Name(s)		G
6 Specific Location 1836-38 Washington	16. Thematic Category  030  17. Date(s) or Period 1905	28. No. of Stories 2  29. Basement?  Yes X No I  30. Foundation Material	Jackson
7 City or Town II Rural, Township & V Kansas City, Missouri B. Site Plan with North Arrow	19. Architect or Engineer 30 40	31. Wall Construction masonry  32. Roof Type & Material Fr. flat; tar & gravel	
Nashington	H. Madorie & Son  21. Original Use, if apparent  apartment  22. Present Use  apartment  23 Ownership  Public II  Private IX  24. Owner's Name & Address,  if known	33. No. of Bays Front = 0 Side  34. Wall Treatment brick 30  35. Plan Shape "U"  36. Changes Addition: (Explain Altered: in #42) Moved:  37. Condition	1836-38 Washington
9. Coordinates UTM Lat. Long.	25. Open to Yes II	Exterior good  38. Preservation Yes	on
Building 1 k Ob	yes: X No:: 27. Other Surveys in Which Included	39. Endangered? Yes! By What? No X:	
13 Part of Estab. Yes   1	Yes   X No : -	40. Visible from Yes X: Public Road? No 1:  41. Distance from and Frontage on Road 45 ft. on Washington	

stone sills. The parapet wall steps up in the center, on the east facade.

43. History and Significance This building was constructed with four apartment units.

44. Description of Environment and Outbuildings Residences are north and south of this building. To the east is a surface parking lot. Vacant land is to the west.

45 Sources of Information WP#28724

46. Prepared by PILAND

47. Organization Landmarks Commission

48. Date 49. Revision Date(s) 1/29/85



	ORICIA	VENTORY	olumbia, Missouri 65201
1. No. 66-H 2. County	4. Pres	sent Name(s) name 340 Washington Street House	JA-48-000 12 21
Jackson Location of Negatives Landmarks Commiss:		er Name(s) the name 936 Washington Street House	
Specific Location		16. Thematic Category	28. No. of Stories 1
		030	29. Basement? Yes I
1840 Washington		17. Date(s) or Period	No L
City or Town If Aur Kansas City, Misso	al, Township & Vicinity	c. 1890 18 Style or Design	30. Foundation Material
Site Plan with North Ar		19 Architect or Engineer	frame Lulu
Site Flan Willi North Ar	iow.	13 Architect of Engineer	32. Roof Type & Material Cm
1		20. Contractor or Builder	varied; comp.shingle
N	4	21. Original Use, if apparent pnch	Front 2 Side
1 //	Washington	residence DIA WA	34. Wall Treatment 64 asbestos siding
2	, w	residence	35. Plan Shape rectangula:
	- 2 ×	23 Ownership Public	11 36 Changes Addition
	2	Private	(Explain Altered   Moved
		24. Owner's Name & Address, if known	37. Condition Interior
Coordinates Lat.	итм		Exterior good
Long		25. Open to Yes	
	Structure	Public? No	√x Underway? No ½
Site!: Building  X	Object ( )	26. Local Contact Person or Organization	39. Endangered? Yes I
Building IX On National Yes II	Object 1 1	Landmarks Commission	39. Endangered? Yes I
Building  X  On National Yes     Register? No  X	Object   )  12 is it Yes :XX Eligible? No ::	Landmarks Commission 27. Other Surveys in Which Included	39. Endangered? Yes I By What? No ½
Building  X  On National Yes     Register? No  X	Object 1 1	Landmarks Commission 27. Other Surveys in Which Included	39. Endangered? Yes I By What? No ½ 40. Visible from Yes ½
Building  X  On National Yes     Register? No  X  Part of Estab Yes     Hist. Dist.? No  X	Object   )  12 Is It Yes :XX Eligible? No ::  14 District Yes :XX Potent'1? No :	Landmarks Commission 27. Other Surveys in Which Included	39. Endangered? Yes I By What? No ½  40. Visible from Yes ¾ Public Road? No i  41. Distance from and Frontage on Road
Building  X On National Yes	Object   1  12 Is It Yes (X) Eligible? No   1  14. District Yes (X) Potent'I? No   1  District  Important Features Th	Landmarks Commission 27. Other Surveys in Which Included e primary facade faces east on the	39. Endangered? By What?  40. Visible from Yes X Public Road?  41. Distance from and Frontage on Road 16 feet on Washington Washington. The north
Building  X   1. On National   Yes   1   Register?   No  X   3. Part of Estab. Yes   1   Hist. Dist.?   No  X   5. Name of Established Disection of the research of the resear	Object   12 Is It Yes   XXX Eligible? No   14 District Yes   XXX Potent' ? No   15 District   14 District   15 District   16 District   17 District   17 District   18 District   18 District   18 District   19 Dis	Landmarks Commission  27. Other Surveys in Which Included  e primary facade faces east on the south to east facades. A six	39. Endangered? By What?  40. Visible from Yes X Public Road?  41. Distance from and Frontage on Road 16 feet on Washington Washington. The north e south end is recessed.  ngle rectangular window
Building  X  On National Yes     Register? No  X  Part of Estab Yes     Hist Dist ? No  X  Name of Established D  Printer Description of Section of the research of the residence of the res	Object   12 Is It Yes   XX Eligible? No   14 District Yes   XX Potent'!? No   20 District   20 Distr	Landmarks Commission  27. Other Surveys in Which Included  e primary facade faces east on the south the entrance bay at the he south to east facades. A six he attic story.  f cottages of similar design and vacant land is east and west of e north is an apartment building	39. Endangered? By What?  40. Visible from Yes X Public Road?  41. Distance from and Frontage on Road 16 feet on Washington Washington. The north e south end is recessed. Ingle rectangular window  40. Visible from Yes X No in the Second Public Road?  41. Distance from and Frontage on Road 16 feet on Washington e south end is recessed.  42. To the south is a  43. A coursed rubble  44. Prepared by Piland /Uguccioni 44. Organization
Building  X   1. On National   Yes   1   Register?   No  X   3. Part of Estab. Yes   1   Hist. Dist.?   No  X   5. Name of Established D   2. Further Description of section of the rest A flat roofed pore fenestrates the gamma of the similar residence   1. Description of Environmental Procession of Environmental Procession   1. Description	Object   12 Is It Yes   XX Eligible? No   14 District Yes   XX Potent'!? No   20 District   20 Distr	Landmarks Commission  27. Other Surveys in Which Included  e primary facade faces east on the south the entrance bay at the he south to east facades. A six he attic story.  f cottages of similar design and vacant land is east and west of e north is an apartment building	39. Endangered? By What?  40. Visible from Yes X Public Road?  41. Distance from and Frontage on Road 16 feet on Washington  Washington. The north e south end is recessed.  Ingle rectangular window  41. Distance from and Frontage on Road 16 feet on Washington  Washington. The north e south end is recessed.  The south is a south is a south is a south end is recessed.  The south is a south is a south is a south end is residence. Another south is a south end is residence. Another south is a so



1/5/82

State Historical Survey and Planning Office, 909 University Avenue, Suite 215,



State Historical Sur by and Planning Office, 909 University Avenue, Suite 215,

olumbia, Missouri 65201



Yes

No K

Yes X

No 11

Courty

## HISTORIC INVENTORY

Object | |

Yes !

Yes

No x

No X

12 Is It

Eligible?

District

Potent'l?

A-AS-008-1542 I. No. 4. Present Name(s) 84-E Refrigeration Equipment Company 2 County Jackson 3 Location of Negatives MT #52-19 entered Landmarks Commission of KC 6. Specific Location 16. Thematic Category 28. No. of Stories 29. Basement? Yes 17. Date(s) or Period No I 2018 Washington 1942 & 1948 (adds, 1955, 1962) 30. Foundation Material 7. City or Town - If Rural, Township & Vicinity 18. Style or Design 31. Wall Construction Kansas City, Missouri B. Site Plan with North Arrow 19. Architect or Engineer concrete block A.B. Fuller (1948) 32. Roof Type & Material 20. Contractor or Builder flat; tar and gravel 33. No. of Bays Bellanti & Welsh Const. Co (1955) 2018 Front 21. Original Use, if apparent 34. Wall Treatment commercial 22. Present Use brick; concrete block Washington 35. Plan Shape irregular commercial Addition X 23 Ownership Public | | 36. Changes Private xx (Explain Altered 1 in #42) Moved i 24. Owner's Name & Address. if known 37. Condition Interior 9 Coordinates UTM Exterior good Lal. Long. 25. Open to Yes XX Preservation Yes : Public? No II Underway? No X Site ! Structure |

42 Further Description of Important Features This structure evolved from several construction projects. Loading dock areas are located at the north and south ends of the building. Joined in the center are two commercial buildings - a single story section on the south, constructed in 1948, and a two story, 1962 structure. These center structures are veneered with brick and contain the primary entrances. The 1962 addition was built by the Jenkins Blaine Construction Company. The architects were Monroe & Lefebvre. John Gosling was the builder for the 1948 section. Folger & Pearson were architects of the 1955 addition.

26. Local Contact Person or Organization

27. Other Surveys in Which Included

Landmarks Commission of KC

- 43. History and Significance This building was erected for various concerns. The single story section in the center was erected in 1948 for the Kansas City Envelope Company. The loading dock that extends on the south was erected in 1955 for the Darling Envelope Company. The 2-story section near the center was erected in 1962, also for the Darling Envelope Company.
- 44 Description of Environment and Outbuildings A residence is north of this building. To the west is vacant land and a commercial building. A surface parking lot is to the south. To the east is a commercial building and another surface parking area.

## 45 Sources of Information

Building by

15. Name of Established District

No DE

No X

11. On National

Register?

Hist. Dist.?

13 Part of Estab. Yes 11

WP #9030; 73337

BP #36520A

BP #44322; 79087

Midwest Contractor, February 18, 1948, p.11. Midwest Contractor, November 2, 1955, p.11.

46. Prepared by PILAND

39. Endangered?

By What?

40 Visible from

Public Road?

Distance from and

Frontage on Road approx. 280 ft. on Washington

4/20/84

47. Organization Landmarks Commission 48. Date 49. Revision Date(s)



11/18/82

49. Revision Date(s)



Present Namers

## HISTORIC INVENTORY A-AS-008- 1544 1. No. 4. Present Name(s) 85-L 2 County Jackson The Gas Service Company 5. Other Name(s) 3 Location of Negatives MT#97-20 entered Landmarks Commission of KC 6 Specific Location 16. Thematic Category 28. No. of Stories 29. Basement? Yes I 2023 Washington 17. Date(s) or Period No I 1959 30. Foundation Material 7. City or Town If Rural, Township & Vicinity 18 Style or Design concrete Kansas City, Mo. 31. Wall Construction 19. Architect or Engineer masonry B. Site Plan with North Arrow 32. Roof Type & Material 20. Contractor or Builder flat; tar and gravel Wesley Elders Const. Co. 33. No. of Bays Side Front 21. Original Use, if apparent commercial 34. Wall Treatment 22. Present Use brick 35. Plan Shape L-shape commercial 23 Ownership Public 1 36. Changes Addition | Private IX (Explain Altered | in #42) Moved I ngton 24. Owner's Name & Address, if known 37. Condition Interior UTM 9. Coordinates Lat. Exterior good Long 25. Open to Yes lx Preservation Yes . Public? No ix Underway? Site ! : Structure | Building 1 x Object | | 26. Local Contact Person or Organization 39. Endangered? Yes By What? Nolx Landmarks Commission 11. On National Yes 12 Is It Yes ! No X Eligible? Register? NOIX 27. Other Surveys in Which Included 13 Part of Estab. Yes 11 Yes District 40. Visible from Yes ! x Public Road? Hist. Dist.? No IX Potent'l? No x No 11 Distance from and 15. Name of Established District Frontage on Road approx. 35 feet on Washington 42 Further Description of Important Features The main facade faces west. The entrance is at the south end of the facade. A row of square windows fenestrates the south facade and a similar window is placed by the entrance. 43. History and Significance This building was constructed for the Bruce McDonald Company as an adjunct to the building to the north. 44. Description of Environment and Outbuildings A surface parking area is south of this building. To the north, east, and west are other commercial buildings. A surface parking area is also to the west.

45 Sources of Information
BP #60253

46. Prepared by PILAND

47. Organization
Landmarks Commission

48. Date 3/21/85



48. Date 49. Revision Date(s)

4/12/84

Kansas City Star, December 5, 1954, p. 6D

BP #38468A; 61384



washingtons



Southwest Boulevard 1

1. No. 101-E	4. Present Name(s)	171		
County Jackson	2101-07 Washington			
Location of Negatives MT#102-	5. Other Name(s)	1477		
Landmarks Commission of I	KC			
Specific Location	16. Thematic Category	28. No. of Stories 1		
2101-07 Washington	17. Date(s) or Period	29. Basement? Yes K		
	1914	30. Foundation Material		
City or Town If Rural, Towns		concrete 65		
Kansas City, Missou Site Plan with North Arrow	19. Architect or Engineer	masonry UD		
Ja.	Charles C. Vandenberg	32. Roof Type & Material P		
8	20. Contractor or Builder Frank Rohe	flat; tar & gravel		
3.1	21. Original Use, if apparent	33. No. of Bays Front 5 Side 94		
3	commercial DSE	34. Wall Treatment		
6 -	22 Present Use commercial	brick 35. Plan Shape irregular		
18	23 Ownership Public	36. Changes Addition :		
A	Private	(Explain Altered lx in #42) Moved		
	24. Owner's Name & Address, . if known	37. Condition		
Coordinates UTM		Interior		
Lat. Long.	25. Open to Yes	Exterior good		
Site ! ;	Structure 1: Public? No			
Building IX	Object !   26. Local Contact Person or Organization	39. Endangered? Yes I		
Register? No IX Elig	yes K Landmarks Commission of 1  No 1: 27. Other Surveys in Which Included	KC By What?		
Part of Estab. Yes I 1 14. Dis	itrict Yes X	40. Visible from Yes !X		
	tent'l? No 1.	Public Road? No 11		
5. Name of Established District		41. Distance from and Frontage on Road		
	Features The main facade faces west. The	100 feet on Washington		
tains an overhead garage paneling. Some of the w	ndows. The southern bay has been enclosed door. The transom areas have been filled window areas are filled with glass block.  The southern bay has been enclosed by the door. The transom areas have been filled with glass block.	ed in with a diagonal wood		
and the Arnold Motor Ca		, an oldinary		
	Outbuildings Other commercial buildings are the east is vacant land and surface parking			
of this structure. To t		ag areas.  46. Prepared by		
Sources of Information BP #11188		46. Prepared by PILAND		
of this structure. To t		46. Prepared by PILAND 47. Organization		
Sources of Information BP #11188		46. Prepared by PILAND		



1. No. 101-G	4. Present Name(s)	JA-AS008-1547
2 County Jackson	Mack-Lang Printers, Inc.	
3 Location of Negatives MT #102-6 Landmarks Commission of KC	5 Other Name(s) Acme Furnace and Sheet Metal Compa	my Building
6. Specific Location	16. Thematic Category	28. No. of Stories 1 - /
2119-21 Washington	030 050 17. Date(s) or Period	29. Basement? Yes I No I .
	1930 (add. 1946)	30. Foundation Material
Kansas City, Missour		31. Wall Construction
3. Site Plan with North Arrow	19 Architect or Engineer	masonry up
1) 3	20. Contractor or Builder	32. Roof Type & Material + PR
N %	21. Original Use, if apparent	33. No. of Bays Front Side 99
73.5	commercial CO	34. Wall Treatment brick 30
19	commercial	35. Plan Shape rectangular
4	23 Ownership Public [ ] Private ix	36. Changes Addition XX (Explain Altered   1
	24. Owner's Name & Address, if known	in #42) Moved i
Coordinates UTM		Interior
Lat. Long.	25. Open to Yes IX	Sa Preservation Yes
	Structure I : Public? No I !	Underway? No 🛭
Building 12	Object     26. Local Contact Person or Organization  Yes   X   Landmarks Commission of VC	39. Endangered? Yes I No K
Register? No M Eligib	ole? No 11 27. Other Surveys in Which Included	
3. Part of Estab. Yes   14. Distri		40. Visible from Yes 😿 Public Road? No 🖂
		41. Distance from and
ACRES TO A STATE OF THE STATE O		Frontage on Road
5. Name of Established District	eatures The main facade faces west. The f	Frontage on Road 50 feet on Washington acade is fenestrated
5. Name of Established District  2. Further Description of Important F with multipaned windows, in soldier course forms	features The main facade faces west. The f , an entrance door, and an overhead garage window surrounds and a string level. The coping. An addition was placed on the re-	50 feet on Washington acade is fenestrated entrance. Brick set parapet well is shaped
5. Name of Established District  2. Further Description of Important F with multipaned windows, in soldier course forms and terminates in stone	, an entrance door, and an overhead garage window surrounds and a string level. The	50 feet on Washington acade is fenestrated entrance. Brick set parapet well is shaped ar of the building in 1946.
5. Name of Established District  2. Further Description of Important F with multipaned windows, in soldier course forms and terminates in stone  3. History and Significance This	, an entrance door, and an overhead garage window surrounds and a string level. The coping. An addition was placed on the re-	50 feet on Washington acade is fenestrated entrance. Brick set parapet well is shaped ar of the building in 1946.
5. Name of Established District  2. Further Description of Important F with multipaned windows, in soldier course forms and terminates in stone  3. History and Significance This	, an entrance door, and an overhead garage window surrounds and a string level. The coping. An addition was placed on the restricted to house the Act	50 feet on Washington acade is fenestrated entrance. Brick set parapet well is shaped ar of the building in 1946.
5. Name of Established District  2. Further Description of Important F with multipaned windows, in soldier course forms and terminates in stone  3. History and Significance This	, an entrance door, and an overhead garage window surrounds and a string level. The coping. An addition was placed on the restricted to house the Act	50 feet on Washington acade is fenestrated entrance. Brick set parapet well is shaped ar of the building in 1946.
2. Further Description of Important F with multipaned windows, in soldier course forms and terminates in stone  3. History and Significance This Metal Company. Anton An	, an entrance door, and an overhead garage window surrounds and a string level. The coping. An addition was placed on the restricted to house the Activation was President of the firm.	50 feet on Washington acade is fenestrated entrance. Brick set parapet well is shaped ar of the building in 1946.
5. Name of Established District  2. Further Description of Important F with multipaned windows, in soldier course forms and terminates in stone  3. History and Significance This Metal Company. Anton An building. To the east in the seast in	, an entrance door, and an overhead garage window surrounds and a string level. The coping. An addition was placed on the restricted to house the Activation was President of the firm.	50 feet on Washington acade is fenestrated entrance. Brick set parapet well is shaped ar of the building in 1946.  The Furnace and Sheet  and south of this  46. Prepared by
5. Name of Established District  2. Further Description of Important F with multipaned windows, in soldier course forms and terminates in stone  3. History and Significance This Metal Company. Anton An building. To the east in Sources of Information WP #90677	, an entrance door, and an overhead garage window surrounds and a string level. The coping. An addition was placed on the restricted to house the Activation was President of the firm.	50 feet on Washington acade is fenestrated entrance. Brick set parapet well is shaped ar of the building in 1946.  The Furnace and Sheet  46. Prepared by PILAND
5. Name of Established District  2. Further Description of Important F with multipaned windows in soldier course forms and terminates in stone  3. History and Significance This Metal Company. Anton An building. To the east in the sources of Information	, an entrance door, and an overhead garage window surrounds and a string level. The coping. An addition was placed on the restricted to house the Activation was President of the firm.	50 feet on Washington acade is fenestrated entrance. Brick set parapet well is shaped ar of the building in 1946.  The Furnace and Sheet  and south of this  46. Prepared by



49 Revision Date(s)

48. Date 11/17/82





County Jackson		sent Name(s)	
Jackson	101-H 2125-29 Washington Street Bur		lding
Jackson 5. Othe		ner Name(s)	-
Location of Negatives andmarks Commissi	MT#102-4 ion of KC		
Specific Location	The same of the sa	16. Thematic Category	28. No. of Stories 1
			29. Basement? Yes I
2125-29 Washingt	ion	17. Date(s) or Period	No I
City or Town If Rur	ral, Township & Vicinity	18 Style or Degrap = 5	O)
Kansas City,	Missouri	Tapestry Brick	31. Wall Construction
Site Plan with North A	rrow	19. Architect or Engineer	masonry UD
3		20. Contractor or Builder	32. Roof Type & Material + P flat; tar and gravel
1 9		30 90	33. No. of Bays
/ 6		21. Original Use, if apparent	Front 3 Side
1 3		commercial ODE	34. Wall Treatment brick 30 50
1 8		commercial	35. Plan Shape rectangula
1		23 Ownership Public   1	36. Changes Addition :
3		Private ½	(Explain Altered I in #42) Moved i
1		24. Owner's Name & Address, if known	37. Condition
oordinates	UTM		Interior
at.			Exterior good
ong.		25. Open to Yes x: Public? No i	38. Preservation Yes Underway? Nox
Site ! : Building ly	Structure 1 :	26. Local Contact Person or Organization	Underway? Nox 39. Endangered? Yes I
On National Yes II	12 Is It Yes k	Landmarks Commission of KC	By What? No
legister? No ix	Eligible? No 1 !	27. Other Surveys in Which Included	
	14 District Yes k		40. Visible from Yes
Part of Estab. Yes II			TOTAL DESCRIPTION OF THE PARTY
Part of Estab. Yes III	Potent'l? No :		VATAL BATHTITAL TRANSL.
Part of Estab. Yes II Hist. Dist.? No bd	Potent'l? No :		Public Road? No I
Part of Estab. Yes     Hist. Dist.? No bd  Name of Established D  Further Description of	Potent'l? No :.  District  Important Features The	e main facade of this building face with a stepped parapet. The parap	Public Road? No land  41. Distance from and Frontage on Road  100 feet on Washington es west. The facade con
Part of Estab. Yes     Hist. Dist.? No bd  Name of Established D  Further Description of sists of identical distinguished by corner. The wind centrally located	Important Features That sections, each a soldier course low areas of the	with a stepped parapet. The parapet forming a rectangular pattern, with north section have been bricked in our is centrally located in the sou	Public Road? No.  41. Distance from and Frontage on Road  100 feet on Washingtones west. The facade contest wall of each half is the stone inserts at each and a garage door is
Part of Estab. Yes II Hist. Dist.? No by Name of Established D  Further Description of sists of identical distinguished by corner. The wind centrally located corrugated metal.  History and Significant tenants was the Description of Environmentaling. To the new Sources of Information.	Potent'l? No interior in portant Features The all sections, each a soldier course low areas of the runs above the wind above the wind a soldier course down areas of the runs above the wind a soldier course down areas of the runs above the wind above the wind a soldier course of the runs above the wind a soldier course of the runs above the wind a soldier course of the runs and outbuildings orth, south, and	with a stepped parapet. The parapet forming a rectangular pattern, with north section have been bricked in our is centrally located in the sou	Public Road? No is 41. Distance from and Frontage on Road 100 feet on Washington as west. The facade concet wall of each half is the stone inserts at each and a garage door is the section and a band of the original rich. One of the original lot is east of this section.
Part of Estab. Yes II Hist. Dist.? No M  Name of Established D  Further Description of ists of identical istinguished by orner. The windentrally located orrugated metal  History and Significant tenants was the Description of Environmental in the new contraction.	Potent'l? No interior in portant Features The all sections, each a soldier course low areas of the runs above the wind above the wind a soldier course down areas of the runs above the wind a soldier course down areas of the runs above the wind above the wind a soldier course of the runs above the wind a soldier course of the runs above the wind a soldier course of the runs and outbuildings orth, south, and	with a stepped parapet. The paraper forming a rectangular pattern, with north section have been bricked in por is centrally located in the south indows.  The paraperage statement of the south formula in the south for realter and the south for realter a	Public Road? No land 1. Distance from and Frontage on Road 100 feet on Washington es west. The facade con eet wall of each half is the stone inserts at each and a garage door is eth section and a band of erich. One of the origin lot is east of this s.  46. Prepared by PILAND
Part of Estab. Yes     Hist. Dist.? No M  Name of Established D  Further Description of dists of identical distinguished by corner. The wind dentrally located orrugated metal  History and Significant tenants was the Description of Environmental ding. To the new MP #61223  BP #12261	Potent'l? No interior in portant Features The all sections, each a soldier course low areas of the runs above the wind above the wind a soldier course down areas of the runs above the wind a soldier course down areas of the runs above the wind above the wind a soldier course of the runs above the wind a soldier course of the runs above the wind a soldier course of the runs and outbuildings orth, south, and	with a stepped parapet. The paraper forming a rectangular pattern, with north section have been bricked in por is centrally located in the south indows.  The paraperage of the section have been bricked in the south indows.  The paraperage of the paraperage of the section have been bricked in the south indows.  The paraperage of the paraperage of the paraperage of the section have been bricked in the south indows.  The paraperage of the para	Public Road? No is 41. Distance from and Frontage on Road 100 feet on Washington as west. The facade concet wall of each half is the stone inserts at each and a garage door is the section and a band of the section and a band of the original factors. One of the original factors are as a section and a band of the section and a band of the original factors. One of the original factors are as a section and a band of the original factors are as a section and a band of the original factors. One of the original factors are as a section and a band of the original factors are as a section and a band of the original factors are as a section and a band of the original factors are as a section and a band of the original factors are as a section and a band of the original factors are as a section and a band of the original factors are as a section and a band of the original factors are as a section and a band of the original factors are as a section and a band of the original factors are as a section and a band of the original factors are as a section and a band of the original factors are as a section and a band of the original factors are as a section and a band of the original factors are as a section and a band of the original factors are as a section and a section are as a section are as a section are as a section and a section are as a section are as a section are as a section are as a section and a section are as a section are a



	" Gotter Pront	Washington	II Name(S)	
ı				

Preser 2131

Yes I

No i

## HISTORIC INVENTORY 1. No. 4. Present Name(s) 101-J 2131 Washington Street Builder 2 County Jackson 5. Other Name(s)

3 Location of Negatives MT #102-2 Landmarks Commission of KC 6. Specific Location

2131 Washington

7 City or Town If Rural, Township & Vicinity Kansas City, Missouri

B. Site Plan with North Arrow

9 Coordinates UTM Lat. Long. 10. Sile! BuildingXX

11. On National Yes 11 12 Is It Eligible? Register? Noxx 13. Part of Estab. Yes ! ! District Hist. Dist.? Noxx Potent'1?

the doors. The parapet wall is stepped.

Structure |

Object 11

Yesxx

Yesxx

No

No

15. Name of Established District

16. Thematic Category 030 050 17. Date(s) or Period 1922

18. Style or Design Tapestry Brick 50 19. Architect or Engineer

20. Contractor or Builder 21. Original Use, if apparent

commercial OJE 22. Present Use commercial

23 Ownership

24. Owner's Name & Address. if known

25. Open to Yes Public? No 11

69

ather

30

90

Public 11

Private IX

26. Local Contact Person or Organization Landmarks Commission of KC 27. Other Surveys in Which Included

K-13008-1550

28. No. of Stories

30. Foundation Material

01

32. Roof Type & Material F+ PR

flat; tar and gravel

35. Plan Shaperectangular

good

Side

Addition

Altered |

Moved i

Yes

No ix

Yes No IX

Yes !X

No 1

31. Wall Construction

masonry UD

33. No. of Bays Front 5

34. Wall Treatment

brick 50

36 Changes

(Explain in #42)

37. Condition Interior

Exterior

Preservation

Underway?

39. Endangered?

By What?

40. Visible from

Public Road?

41. Distance from and

Frontage on Road

29. Basement?

50 ft on Washington 42. Further Description of Important Features The main facade of this building faces west. Entrance doors are ar the north and south ends of the west facade. Three display windows are placed between

43. History and Significance This building was constructed for realtor Eugene Dietrich. The first tenant was the Front Drive Motor Company.

44. Description of Environment and Outbuildings A surface parking lot is south of this building. north and west are other commercial buildings. To the east is a storage lot.

45 Sources of Information

Western Contractor, July 26, 1922, p. 38 BP #13218

WP #61223

46. Prepared by PILAND

47. Organization

Landmarks Commission 48. Date 49. Revision Date(s)

13/2/84



46. Prepared by PILAND

47. Organization

2/9/84

Landmarks Commission

48. Date 49. Revision Date(s)

Jackson  Location of Negatives MT#102-1 Landmarks Commission of KC  Specific Location  2139 Washington Street Building  City or Town If Rural, Township & Vicinity I8. Kansas City, Missouri  Site Plan with North Arrow  19.  Coordinates  Lat. Long.  Site!  Structure!  Object!  Pobject!  Potent'i? No!  Potent'i? No!  Further Description of Important Features  entrance is centrally located. Flank windows with metal panels in the trant the south facade have been filled in	Inernatic Category Date(s) or Period 1915 Style or Design Architect or Engineer John G. Thurtle Contractor or Builder Driginal Use, if apparent commercial Present Use commercial Dwnership Public   Private Xi Dwner's Name & Address, if known	28. No. of Stories 2  29. Basement? Yes! No!  30. Foundation Material stone 4  31. Wall Construction masonry CD  32. Roof Type & Material + Peflat; tar and gravel  33. No. of Bays Front 3 Side  34. Wall Treatment brick 3 99  35. Plan Shape rectangular  36. Changes Addition: (Explain Altered: in #42) Moved:  37. Condition interior
Location of Negatives MT#102-1 Andmarks Commission of KC  Specific Location  2139 Washington Street Building  17.  City or Town If Rural, Township & Vicinity Kansas City, Missouri  Site Plan with North Arrow  19.  20.  21.  22.  23.  Coordinates UTM  Lat. Long.  Site!: Structure!: Object!! 26.  On National Yes!! 12 is it Yes!x Eligible? No!! 27.  Part of Estab Yes!! 14. District Yes ix Potent!? No!.  Name of Established District  Further Description of Important Features The mentrance is centrally located. Flank windows with metal panels in the trantine south facade have been filled in	Thematic Category  Date(s) or Period  1915 Style or Design  Architect or Engineer  John G. Thurtle Contractor or Builder  Original Use, if apparent commercial DE Design  Present Use commercial Ownership Public     Private XI	29. Basement?  Yes I No i  30. Foundation Material stone 40  31. Wall Construction masonry  32. Roof Type & Material F+ P& flat: tar and gravel 33. No of Bays Front 3 Side  34. Wall Treatment brick 30 35. Plan Shape rectangular 36. Changes Addition 12 (Explain Altered 1) in #42) Moved 1
Specific Location  2139 Washington Street Building 17  City or Town If Rural, Township & Vicinity 18.  Kansas City, Missouri  Site Plan with North Arrow 19.  20.  21.  22.  23.  Coordinates UTM  Lat. Long.  Site! Structure! Object!!  Building IX Object!!  On National Yes!! 12 is!t Yes!x Eligible? No!!  Part of Estab. Yes!! 14. District Yes!x Potent!? No!.  Part of Established District  Part of Established District  Further Description of Important Features The mentrance is centrally located. Flank windows with metal panels in the tranthe south facade have been filled in	Date(s) or Period  1915 Style or Design Architect or Engineer  John G. Thurtle Contractor or Builder  Driginal Use, if apparent commercial DE DE Present Use commercial Dwnership Public     Private X   Dwner's Name & Address,	29. Basement?  Yes I No i  30. Foundation Material stone 40  31. Wall Construction masonry  32. Roof Type & Material F+ P& flat: tar and gravel 33. No of Bays Front 3 Side  34. Wall Treatment brick 30 35. Plan Shape rectangular 36. Changes Addition 12 (Explain Altered 1) in #42) Moved 1
Coordinates Lat. Long.  Site!: Structure! Building IX Object!!  Con National Yes!: 12 Is! Yes: Xegister? No IX Eligible? No!! Part of Estab Yes!! 14. District Yes IX Hist. Dist.? No IX Potent'!? No!.  Name of Established District  Purther Description of Important Features The mentrance is centrally located. Flank windows with metal panels in the tranthe south facade have been filled in	Date(s) or Period  1915 Style or Design Architect or Engineer  John G. Thurtle Contractor or Builder  Driginal Use, if apparent commercial DE DE Present Use commercial Dwnership Public     Private X   Dwner's Name & Address,	29. Basement?  Yes I No i  30. Foundation Material stone 40  31. Wall Construction masonry  32. Roof Type & Material F+ P& flat: tar and gravel 33. No of Bays Front 3 Side  34. Wall Treatment brick 30 35. Plan Shape rectangular 36. Changes Addition 12 (Explain Altered 1) in #42) Moved 1
Coordinates Lat. Long.  Site! Building M Part of Established District  Part her Description of Important Features entrance is centrally located. Flank windows with metal panels in the tranthe south facade have been filled in 18 18 18 18 18 18 18 18 18 18 18 18 18	Date(s) or Period  1915  Style or Design  Architect or Engineer  John G. Thurtle  Contractor or Builder  Driginal Use, if apparent  commercial DE DE  Present Use  commercial  Dwnership Public      Private XI	30. Foundation Material stone 40 31. Wall Construction masonry CD 32. Roof Type & Material F+ P& flat; tar and gravel 33. No. of Bays Front 3 Side 34. Wall Treatment brick 30 99 35. Plan Shape rectangular 36. Changes Addition: (Explain Altered in #42) Moved in #42)
City or Town If Rural, Township & Vicinity Kansas City, Missouri  Site Plan with North Arrow  19.  20.  21.  22.  23.  Coordinates  Lat.  Long.  Site!  Building M  Object!  Part of Estab. Yes!  Hist. Dist.?  No IX  Potent'!?  No IX  Potent'!?  No IX  Potent'!?  No IX  Potent'!?  Part of Established District  Part of Established District  Purther Description of Important Features  entrance is centrally located. Flank windows with metal panels in the tranthe south facade have been filled in	Architect or Engineer  John G. Thurtle Contractor or Builder  Original Use, if apparent commercial DDE DH Present Use commercial Ownership Public     Private XI	stone 40  31. Wall Construction masonry CD  32. Roof Type & Material F+ Pe flat: tar and gravel  33. No. of Bays Front 3 Side  34. Wall Treatment brick 30 99  35. Plan Shape rectangular  36. Changes Addition: (Explain Altered 1) in #42) Moved 1
Coordinates Lat. Long.  Site !: Structure !: Object !: 26.  On National Yes !: Eligible? No !: 27.  Part of Estab Yes !! 14. District Yes !x Hist. Dist.? No !x Potent !!? No !.  Part of Estab Yes !! 14. District Yes !x Potent !!? No !.  Name of Established District  Further Description of Important Features The mentrance is centrally located. Flank windows with metal panels in the tranthe south facade have been filled in	Architect or Engineer  John G. Thurtle Contractor or Builder  Original Use, if apparent commercial DDE DA  Present Use commercial Ownership Public     Private XI	31. Wall Construction masonry CD  32. Roof Type & Material F+ P& flat; tar and gravel  33. No. of Bays Front 3 Side  34. Wall Treatment brick 30 99  35. Plan Shape rectangular  36. Changes Addition: (Explain Altered: in #42) Moved:  37. Condition
Coordinates  Lat. Long.  Site!: Structure!: 25.4  Don National Yes!: 12 Islt Yes!x Eligible? No!!  Part of Estab Yes!! 14. District Yes!x Hist. Dist.? No!x Potent!!? No!.  Name of Established District  Further Description of Important Features The mentrance is centrally located. Flank windows with metal panels in the tranthe south facade have been filled in	Architect or Engineer  John G. Thurtle Contractor or Builder  Original Use, if apparent commercial DDE DA  Present Use commercial Ownership Public     Private X   Owner's Name & Address,	masonry CD  32. Roof Type & Material + P& flat; tar and gravel  33. No. of Bays Front 3 Side  34. Wall Treatment brick 3 9 9  35. Plan Shape rectangular  36. Changes Addition 1: (Explain Altered 1: in #42) Moved 1
Coordinates  Lat. Long.  Site!: Structure!: Object!!  On National Yes!! 12 Is!t Yes: X Register? No!X Eligible? No!!  Part of Estab. Yes!! 14. District Yes ix Potent!!? No!.  Name of Established District  Further Description of Important Features The mentrance is centrally located. Flank windows with metal panels in the tranthe south facade have been filled in	John G. Thurtle Contractor or Builder  Original Use, if apparent commercial DDE DDH  Present Use commercial Ownership Public     Private XI	32. Roof Type & Material F+ P& flat: tar and gravel 33. No. of Bays Front 3 Side  34. Wall Treatment brick 3 99  35. Plan Shape rectangular 36. Changes Addition 12 (Explain Altered 1) in #42) Moved 1
Coordinates Lat. Lony.  Site!: Structure! Building N Object!!  On National Yes!! 12 Is!t Yes!x Register? No!x Eligible? No!!  Part of Estab. Yes!! 14. District Yes ix Hist. Dist.? No!X Potent!? No!.  Name of Established District  Further Description of Important Features The mentrance is centrally located. Flank windows with metal panels in the transthe south facade have been filled in	Contractor or Builder  Original Use, if apparent  commercial DDE DDH  Present Use  commercial  Ownership Public      Private XI	flat; tar and gravel  33. No. of Bays Front 3 Side  34. Wall Treatment brick 30 99  35. Plan Shape rectangular  36. Changes Addition : (Explain Altered : in #42) Moved :  37. Condition
Coordinates Lat. Lony.  Site!: Structure! Building N Object!!  On National Yes!! 12 Is!t Yes!x Register? No!x Eligible? No!!  Part of Estab. Yes!! 14. District Yes ix Hist. Dist.? No!X Potent!? No!.  Name of Established District  Further Description of Important Features The mentrance is centrally located. Flank windows with metal panels in the transthe south facade have been filled in	Original Use, if apparent commercial DDE DDH Present Use commercial Ownership Public     Private X  Owner's Name & Address,	33. No. of Bays Front 3 Side  34. Wall Treatment brick 30 99  35. Plan Shape rectangular  36. Changes Addition : (Explain Altered : in #42) Moved :  37. Condition
Coordinates  Lat. Long.  Site!: Structure!: Object!!  Building M Object!!  On National Yes!: 12 Is!t Yes!x Eligible? No!!  Part of Estab. Yes!! 14. District Yes ix Potent'!? No!.  Name of Established District  Purther Description of Important Features The mentrance is centrally located. Flank windows with metal panels in the tranthe south facade have been filled in	Commercial DDE DDH  Present Use  Commercial  Ownership Public      Private X   Owner's Name & Address,	34. Wall Treatment brick 30 99 35. Plan Shape rectangular 36. Changes Addition 12 (Explain Altered 11 in #42) Moved 1
Coordinates  Lat. Long.  Site!: Structure!: Object!!  Building M Object!!  On National Yes!: 12 Is!t Yes!x Eligible? No!!  Part of Estab. Yes!! 14. District Yes ix Potent'!? No!.  Name of Established District  Purther Description of Important Features The mentrance is centrally located. Flank windows with metal panels in the tranthe south facade have been filled in	Present Use commercial Ownership Public     Private X  Owner's Name & Address,	brick 3.5 9.9  35. Plan Shape rectangular  36. Changes Addition : (Explain Altered : Moved : M
Coordinates  Lat. Long.  Site!: Structure!: Object!!  Building M Object!!  On National Yes!: 12 Is!t Yes!x Eligible? No!!  Part of Estab. Yes!! 14. District Yes ix Potent'!? No!.  Name of Established District  Purther Description of Important Features The mentrance is centrally located. Flank windows with metal panels in the tranthe south facade have been filled in	commercial Ownership Public     Private X  Owner's Name & Address,	35. Plan Shape rectangular 36. Changes Addition (a) (Explain Altered (b) in #42) Moved (a) 37. Condition
Coordinates UTM Lal. Long.  Site!: Structure!: Object!! 26. On National Yes!: 12 Is It Yes!x Eligible? No!! Part of Estab. Yes!! 14. District Yes!x Potent!? No!. Name of Established District  Further Description of Important Features The mentrance is centrally located. Flank windows with metal panels in the tranthe south facade have been filled in	Ownership Public 11 Private XI Owner's Name & Address,	36. Changes Addition : (Explain Altered : Moved : 37. Condition
Coordinates UTM Lal. Long.  Site!: Structure!: Object!! Building M Object!! Con National Yes!: 12 Is It Yes!X Register? No!X Eligible? No!! Part of Estab. Yes!! 14. District Yes!X Hist. Dist.? No!M Potent!!? No!. Name of Established District  Purther Description of Important Features The mentrance is centrally located. Flank windows with metal panels in the tranthe south facade have been filled in	Private XI  Owner's Name & Address,	(Explain Altered III Moved
Coordinates UTM Lat. Long.  Site!: Structure!: Object!! 26.  On National Yes!: 12 Is It Yes IX Eligible? No!!  Part of Estab Yes!! 14. District Yes IX Potent!? No!.  Name of Established District  Further Description of Important Features The mentrance is centrally located. Flank windows with metal panels in the tranthe south facade have been filled in		37. Condition
Site!: Structure!: Object!! 26.  On National Yes!: 12 is it Yes ix Eligible? No!! 27.  Part of Estab Yes!! 14. District Yes ix Potent'!? No!.  Name of Established District  Further Description of Important Features The mentrance is centrally located. Flank windows with metal panels in the tranche south facade have been filled in	it known	1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1
Site!: Structure!: Object!! 26.  On National Yes!: 12 is it Yes ix Eligible? No!! 27.  Part of Estab Yes!! 14. District Yes ix Potent'!? No!.  Name of Established District  Further Description of Important Features The mentrance is centrally located. Flank windows with metal panels in the tranche south facade have been filled in		
Site!: Structure   26.  Building M Object!   26.  On National Yes!: 12 Is!t Yes:X Register? No!X Eligible? No!!  Part of Estab. Yes!! 14. District Yes:X Potent'!? No!.  Name of Established District  Further Description of Important Features The mentrance is centrally located. Flank windows with metal panels in the trantithe south facade have been filled in		Exterior good
Building M Object   26.  On National Yes   12 Is It Yes   X Eligible? No   27.  Part of Estab Yes   14. District Yes   X Potent   17. No   1.  Name of Established District  Purther Description of Important Features The mentrance is centrally located. Flank windows with metal panels in the transthe south facade have been filled in	Open to Yes IX	
On National Yes   12 Is It Yes   X Eligible? No   27.  Part of Estab Yes   14. District Yes   X Potent'!? No   .  Name of Established District  Further Description of Important Features The mentrance is centrally located. Flank windows with metal panels in the trantine south facade have been filled in	Public? No 11	Underway? No X
Part of Estab. Yes   14. District Yes   X Potent'   No   27.  Name of Established District  Purther Description of Important Features The mentrance is centrally located. Flank windows with metal panels in the transthe south facade have been filled in	ocal Contact Person or Organization	39. Endangered? Yes !
Part of Estab. Yes   14. District Yes   X Potent' ? No   Name of Established District  Purther Description of Important Features The mentrance is centrally located. Flank windows with metal panels in the transthe south facade have been filled in	ndmarks Commission of KC	By What? No 🔯
Mist. Dist.? No M Potent'!? No : .  Name of Established District  Purther Description of Important Features The mentrance is centrally located. Flank windows with metal panels in the transthe south facade have been filled in	Other Surveys in Which Included	40. Visible from Yes 🗵
entrance is centrally located. Flank windows with metal panels in the tranthe south facade have been filled in		Public Road? No 11
entrance is centrally located. Flank windows with metal panels in the tranthe south facade have been filled in		41. Distance from and
entrance is centrally located. Flank windows with metal panels in the tranthe south facade have been filled in		Frontage on Road
entrance is centrally located. Flank windows with metal panels in the tranthe the south facade have been filled in		50 feet on Washington
windows with metal panels in the tran the south facade have been filled in	ain facade of this corner bui ing the entrance, on the firs	
the south facade have been filled in		
		Y
3. History and Significance The earliest known	tenant of this building (191	8) was the Victor Confec-
ion Company. While originally planned		
two stories prior to its completion.		
I. Description of Environment and Outbuildings Sur	÷	and south of this building.

45 Sources of Information BP #11559

Western Contractor, Aug. 4, 1915, p. 28.

WP #57259

BP #59475



2 County Tagleson	Present Name(s)  2451 Washington Street House Other Name(s)		T-1CT
6 Specific Location 2451 Washington  7 City or Town II Rural, Township & Vici Kansas City, Missouri 8 Site Plan with North Arrow	16. Themalic Category  17. Date(s) or Period  c. 1897  18. Style or Design  19. Architect or Engineer  20. Contractor or Builder  21. Original Use, if apparent  residence  22. Present Use  residence  23. Ownership  Public II  Private Ix  24. Owner's Name & Address,  if known	28. No. of Stories 1½  29. Basement?  30. Foundation Material  31. Wall Construction frame UUU  32. Roof Type & Material   G  cross gable; comp.shine 33. No. of Bays Front Side  34. Wall Treatment asbestos siding 64  35. Plan Shape irregular  36. Changes Addition: (Explain Altered   Moved   in #42) Moved    37. Condition Interior	Jackson w 2451 Washington
13 Part of Estab. Yes   1	26. Local Contact Person or Organization  Landmarks Commission of KC 27. Other Surveys in Which Included	Exterior-good  38. Preservation Yes   No   X  39. Endangered? Yes   X By What? No      possible demolition  40. Visible from Yes   X Public Road? No      41. Distance from and Frontage on Road  20 feet on Washington	

42. Further Description of Important Features The main facade of this house faces west. A hip roofed porch extends across this facade. Wood columns support the porch roof. The entrance is recessed at the south end of the main facade.

43. History and Significance The earliest known resident of this house (1898) was Clemens Koch, a harness maker.

44 Description of Environment and Outbuildings A surface parking lot is west of this house. A Surface parking lots are to the north, south, and also, east.

45 Sources of Information WP #45332

46. Prepared by PILAND

47. Organization

Landmarks Commission
48. Date 49. Revision Date(s)

1/3/85



County

Present Name(s)



1. No.	4. Present Name(s)	5A-AS-008-1554	7
3-A	McDowell Tire Company not entired		ı
2 County	5 Other Name(s)		-
Jackson Location of Negatives MT #21- Landmarks Commission			ı
			1
Specific Location	16. Thernatic Category	28. No. of Stories 1	1
1501 Wyandotte	17. Date(s) or Period	29. Basement? Yes ! No !	-
	1951	30. Foundation Material	-
City or Town If Rural, Township Kansas City, Missouri	p & Vicinity 18 Style or Design		
		31. Wall Construction	I
Site Plan with North Arrow	19 Architect or Engineer	concrete block	-
TRUMAN.	Neville, Sharp & Simon 20. Contractor or Builder	32. Roof Type & Material flat; tar & gravel	ı
N " L	Hiram Elliott Const. Co.	33. No. of Bays	t
19 7	21. Original Use, if apparent	Front Side	ı
o l	commercial 22. Present Use	34. Wall Treatment	
0000	commercial	brick 35. Plan Shape rectangular	1
8	23 Ownership Public !!	35. Plan Shape rectangular 36. Changes Addition :	1
3	Private 🐰	(Explain Altered I:	1
9	24. Owner's Name & Address, if known	in #42) Moved i	4.
0		37. Condition Interior	
Coordinates UTM Lat.		Exterior good	
Long.	25. Open to Yes 😾	38. Preservation Yes	
Site ! : S Building xx	Structure   Public? No   No   Object   Person or Organization	Underway? NoXX	
	Object :   26. Local Contact Person or Organization  Yes :   Landmarks Commission	39. Endangered? Yes !! By What? NoXX	H
On National Yes   12 Is It  Register? No xx Eligibl			ı
Part of Estab. Yes II 14. Distri	ict Yes	40. Visible from YesXX	1
Hist. Dist.? No	nt'l? No xx	Public Road? No 11	1
Name of Established District		41. Distance from and	
		Frontage on Road	ı
	and the same of th	Frontage on Road 80 feet on Wyandotte	
Further Description of Important For this facade is recess	realures The main facade faces west. To sed and protected by a flat, projection north end of this facade.	Frontage on Road 80 feet on Wyandotte The south half of	
Further Description of Important For this facade is recess entrances are at the	sed and protected by a flat, projecti	Frontage on Road  80 feet on Wyandotte The south half of Ing roof. Garage	The state of the s
Further Description of Important For this facade is recess entrances are at the	sed and protected by a flat, projection north end of this facade.	Frontage on Road  80 feet on Wyandotte The south half of Ing roof. Garage	THE CONTRACT OF THE PARTY OF TH
Further Description of Important For this facade is recess entrances are at the	sed and protected by a flat, projection north end of this facade.	Frontage on Road  80 feet on Wyandotte The south half of Ing roof. Garage	
Further Description of Important For this facade is recess entrances are at the History and Significance This but	sed and protected by a flat, projection north end of this facade.	Frontage on Road 80 feet on Wyandotte The south half of ing roof. Garage	
Further Description of Important For this facade is recess entrances are at the History and Significance This but Description of Environment and Out a surface parking area.	sed and protected by a flat, projection north end of this facade.  Tilding is still used by the firm for which a commercial building is to the east	Frontage on Road 80 feet on Wyandotte The south half of ing roof. Garage it was built.	
Further Description of Important For this facade is recess entrances are at the History and Significance This but Description of Environment and Out a surface parking area. cant land is to the works	sed and protected by a flat, projection north end of this facade.  Tilding is still used by the firm for which a commercial building is to the east	Frontage on Road 80 feet on Wyandotte The south half of ing roof. Garage  it was built.  north. To the south , at a lower grade.	
Further Description of Important For this facade is recess entrances are at the History and Significance This but Description of Environment and Out a surface parking area. cant land is to the way. Sources of Information P #17537	sed and protected by a flat, projection north end of this facade.  Tilding is still used by the firm for which a commercial building is to the east	Frontage on Road 80 feet on Wvandotte The south half of Ing roof. Garage  it was built.  north. To the south , at a lower grade.  46. Prepared by Piland	
Further Description of Important For this facade is recess entrances are at the History and Significance This but.	sed and protected by a flat, projection north end of this facade.  Tilding is still used by the firm for which a commercial building is to the east	Frontage on Road 80 feet on Wyandotte The south half of ing roof. Garage  it was built.  north. To the south , at a lower grade.	



Landmarks Commission

49. Revision Date(s)

48. Date

1/21/85



Landmarks Commission

27. Other Surveys in Which Included

- 43. History and Significance This building is still used by the firm for which it was built.
- 44. Description of Environment and Outbuildings A vacant school building is north of this structure. Other commercial buildings are to the east and south. A surface parking lot is to the west.

## 45 Sources of Information WP #66132 BP #18064

No. 35-I

2. County

Jackson

9. Coordinates

11. On National

Register?

Hist. Dist.?

13 Part of Estab. Yes 11

Yesli

No L

No II

15. Name of Established District

12 Is It

Eligible?

Potent'l?

14. District

Yes!

Yes

Noxx

Noxx

Lat.

10

Long

6. Specific Location

Midwest Contractor, March 3, 1954, p. 13

46. Prepared by Piland / Uguccioni 47. Organization Landmarks Commission 48. Date 49. Revision Date(s)

5/29/84

No X

Yes X

No 11

Ville Haine(S.

By What?

40. Visible from

Public Road?

41. Distance from and

Frontage on Road 73 feet on Wyandotte



No. 36-A		sent Name(s) 701-03 Wyandotte		*
Jackson  Jackson  Location of Negatives MT #21-13 Landmarks Commission		er Name(s) rner Brothers Building		
6 Specific Location 1701-03 Wyandotte		16. Thernatic Category 120 17. Date(s) or Period 1930		28. No. of Stories 4 29. Basement? Yes XX No
City or Town II Rural, Kansas City, Missour Site Plan with North Arrow WEST 17TH ST		18 Style or Design Art Moderne  19 Architect or Engineer Zimmerr Zimmerman (Chicago)  20 Contractor or Builder John T. Neil & Son  21 Original Use, if apparent commercial  22 Present Use commercial  23 Ownership	Public II	31. Wall Construction masonry  32. Roof Type & Material flat; tar & grave1  33. No of Bays Front 5 Side 6  34. Wall Trealment brick  35. Plan Shape rectangular  36. Changes (Explain Altered in Mayed) in #42) Moved
Coordinates UTM Lat. Long.  Site !: Building   1	Structure   Object   1	24. Owner's Name & Address, if known  25. Open to Public?  26. Local Contact Person or Organ Landmarks Commission	Yes lx No ill	37. Condition Interior good  Sterior good  38. Preservation Yes   No XX  39. Endangered? Yes   No XX
Part of Estab Yes 11 1 Hist. Dist.? No 11  Name of Established Distri	Eligible? No 1:  4 District YesXX Potent'1? No 1:	27. Other Surveys in Which Includ	led	40. Visible from Yes XX Public Road? No 11  41. Distance from and Frontage on Road 96 feet on Wyandotte
cojecting brick pier econd through fourth s placed at the summ anels of the first s laborate fire proofi	s that frame a stories and to it of the four tory. An entro ng measures we	tripartite window arrang erminate in Art Deco inspeth story. Another band cance door is located at the undertaken including song also included a project	ement. Sto ired capita ourse is pl he south en storage are	one piers extend from the als. A stone band course Laced above the storefrom nd of the west facade.

Other commercial buildings are to the north, east, and

State Historical Survey and Planning Office, 909 University Avenue, Suite 215,

45 Sources of Information 46. Prepared by Piland /Uguccioni plans at UMKC WP #90036 47. Organization BP #15535 Landmarks Commission Kansas City Star, Sept. 15, 1929, p. 1D. 48. Date 2/5/82 49. Revision Date(s) Kansas City Star, Aug. 31, 1930, p. 1D. Kansas City Star, March 31, 1930. Kansas City Star, Dec. 15, 1929, p. 1D.

44. Description of Environment and Outbuildings

west. To the south is a surface parking lot.



49. Revision Date(s)

48. Date

1/7/82

County

Present

State Historical Sur and Planning Office, 909 University Avenue, Suite 215, Jumbia, Missouri 65201 HISTORIC INVENTORY 74-45-008-155 X 4. Present Name(s) 1. No 35-G Creative Color; Business Systems, Inc. 2. County 5 Other Name(s) Jackson 3 Location of Negatives Landmarks Commission & 83-19 6 Specific Location 16. Thematic Category 28. No. of Stories 1-2 Jackson 20 29. Basement? Yes I 1706-10 Wyandotte 17. Date(s) or Period No I 1921 (add. 1937 and 1982) 30. Foundation Material 7. City or Town If Rural, Township & Vicinity Kansas City, Missouri 01 18. Style or Design 31. Wall Construction masonry LID B. Site Plan with North Arrow 19. Architect or Engineer 3) James Stevens (3) Dick Matheurs 32. Roof Type & Material FT PR flat; tar & gravel 20. Contractor or Builder George L. Brown 33. No. of Bays TOOUR Front Side 21. Original Use, if apparent DZE commercial 34. Wall Treatment 22. Present Use brick 30 commercial/residence 35. Plan Shape rectangular 36. Changes Public 11 Addition X 23 Ownership Private 1x (Explain Altered & Moved I in #42) 24. Owner's Name & Address, il known 37. Condition Interior 9 Coordinates UTM Lat Exterior good Long 25. Open to Yes IX Preservation Yes . Public? No 11 Underway? Noix 10 Sile!: Structure 1 Building ki Object 11 26. Local Contact Person or Organization 39. Endangered? Yes Nolx By What? 11. On National Yes X Landmarks Commission Yes Is It Eligible? No 1 Register? No k 27. Other Surveys in Which Included Yes X 13. Part of Estab. Yes 11 District 40. Visible from Yes ! X Potent'1? Hist. Dist.? No X Public Road? No 11 41. Distance from and 15. Name of Established District Frontage on Road 115 feet on Wyandotte 42 Further Description of Important Features The 2nd floor of the north end of this building was an addition of 1937. Two entrances are recessed at the center of the east facade. of the 2nd floor have been boarded over. Brick relief panels decorate the parapet wall above the 2nd floor. In 1982 a 1,000 square foot residence was erected on the roof of the south portion of the building (architect: James Stevens; builder: Dick Mathews, Gladstone). 43. History and Significance This building was first\*leased to the Metro Picture Corporation. 1937 the building was remodeled and the 2nd floor was added to adapt the building for use by the National Screen Service, a branch distributing agency and manufacturer of film previews. 44. Description of Environment and Outbuildings A surface parking lot is south of this building. A commercial building is to the north. To the east is a surface parking lot. 45 Sources of Information 46. Prepared by Piland WP #65837; 65838 47. Organization BP #12832 Landmarks Commission

BP #3404A

Kansas City Star, March 21, 1937, p. 7D.

Kansas City Star, Aug. 29, 1982, p. 5H.

Kansas City Journal Post, Sept. 9, 1928, p. 1c.





-	
3	
(	
:	
Ē	
-	
2	
-	
9111	
ine(s	

1. No. 36-B		esent Name(s)	*	w
2 County Jackson 5 Oth		715-17 Wyandotte		36-B
		her Name(s) name alter united Sta	tes army motion	w
3 Location of Negatives M Landmarks Commissi	on #21-14 Z	oglin Building Picture Seri	in Building	
6. Specific Location		16. Thematic Category	28. No. of Stories 2	_
1715-17 Wyandotte		030 120	29. Basement? Yes	Jackson
		17. Date(s) or Period 1925	Nox:	cso
7. City or Town If Rura Kansas City, Misso	, Township & Vicinit	18. Style or Design	01	n
B. Site Plan with North Arro		19. Architect or Engineer	31. Wall Construction masonry	
b. Sile Flan with North Am	J.W.	Charles C. Vandenberg 40 30	32. Roof Type & Material FF PP	
N		20. Contractor or Builder	flat; tar & gravel	
1 4 -		B.L. Hoffman Const. Co.	33. No. of Bays 99	
2		commercial OPA	34. Wall Treatment	1715
3		22. Present Use	brick 30	15-
Troansh	-	23 Ownership Public I	35. Plan Shape rectangular 36. Changes Addition :	17
3		Private **	(Explain Altered 1.1	Wy
		24. Owner's Name & Address, it known	in #42) Moved i	Wyando
9 Coordinates 11	TM	-4	37. Condition Interior	ott
9. Coordinates UTM Lat.			Exterior good	0
Long.	Structure	25. Open to Yes IX Public? No 11	38. Preservation Yes   Underway? No X	
Building ⋈	Object 11	26. Local Contact Person or Organization Landmarks Commission	39. Endangered? Yes I By What? No K	
Register? No 🖂	12 Is It Yes X Eligible? No	27. Other Surveys in Which Included		
13. Part of Estab. Yes   14. District Yes   X   Hist. Dist.? No M   Potent'1? No :			40. Visible from Yes X Public Road? No i	
15. Name of Established Dis	strict		41. Distance from and Frontage on Road	
			48 feet on Wyandotte	
42. Further Description of Ir	mportant Features Th	e building faces west onto Wyandotte		
the corners, and subanding is applied.	rmounting the b The second sto ing is applied	are embellished with brick soldier rick piers separating the windows, say windows possess stone lugsills at the brick of the parapet. An eleof the west facade.	stone rectilinear nd soldier course lintels.	
America, Inc., and	the United Star	g was originally occupied by the Filtes Army Motion Picture Service. The principal developer in the "film di	ne building was con-	
	THE RESERVE OF PERSONS ASSESSMENT OF THE PERSON ASSESSMENT OF THE PERSO			
		Other commercial buildings are sou	ith, east, and west	
		Other commercial buildings are sou king lot is to the north.	ith, east, and west	
			46. Prepared by	
of this structure.  45 Sources of Information BP #14531	A surface par	ring lot is to the north.	46. Prepared by Piland /Uquccioni	
of this structure.	A surface par	ring lot is to the north.	46. Prepared by	

State Historical Survey and Planning Office, 909 University Avenue, Suite 215,



42. Further Description of Important Features which is flanked by square windows that extend across the facade. The parapet wall which peaks at the corners of the building carries an elaborate "Deco inspired" terra cotta relief pattern. Horizontal brick banding extends across both the south and east facades.

43. History and Significance The first tenant of this building was the Fox Film Corporation. It is currently occupied by the Concession Division of the Mid-Continent Theatre Supply Corporation.

44. Description of Environment and Outbuildings Commercial buildings are north, south, and east of this A surface parking lot is to the west. structure.

## 45 Sources of Information

WP #78787 BP #15591

Kansas City Star, Aug. 31, 1930, p. 1D.

46. Prepared by

Piland /Uguccioni

47. Organization

Landmarks Commission

49. Revision Date(s) 48. Date 11/1/82

CHIC indine(5

Film

Corporation



		Present Name(s)  Commonwealth Theatres - Data Processi	na
2 County			.ng
Jackson		Other Name(s)	enthell
3 Location of Negatives Landmarks Commiss	MT #83-13	Paramount Building; Paramount Publix	Corp.
6 Specific Location		16. Thematic Category	28. No of Stories 2
1800-02 Wyandotte			29. Basement? Yes K
1000 02 Wydndocte		17. Date(s) or Period .	No i
		1929	30. Foundation Material
Kansas City, Miss	ral, Township & Vic ouri	inity 18. Style or Design	31. Wall Construction
Site Plan with North Ar		19. Architect or Engineer	masonry
			32. Roof Type & Material
		20. Contractor or Builder	flat; tar & gravel
West 18	7 Street	Wilbur F. Coen (realtor)	33. No. of Bays
DV2-21	1.1	21. Original Use, if apparent	Front 3 Side
	12	commercial	34. Wall Treatment
	8	22 Present Use	brick; stone
*	2	commercial	35. Plan Shape rectangular
	Wyandotte	23 Ownership Public   Private   X	36 Changes Addition XX
		Private   X	(Explain Altered I in #42) Moved I
		if known	37. Condition
Coordinates	UTM		Interior
Lat.	UIM		Exterior good
Long.		25. Open to Yes IX	38. Preservation Yes
Site !;	Structur	Public?	Underway? No i x
Building Ki	Object	26. Local Contact Person or Organization	39. Endangered? Yes I
On National Yes 11		s X Landmarks Commission	By What? No I X
Register? No K		27. Other Surveys in Which Included	
Register? No Ki	14. District Ye	s X	40. Visible from Yes !
Register? No 83  3. Part of Estab. Yes I I Hist. Dist.? No kl	14. District Ye Potent'l? No	s X	40. Visible from Yes! Public Road? No!!
Register? No M 3. Part of Estab. Yes I I Hist. Dist.? No kl	14. District Ye Potent'l? No	s X	Public Road? No 11  41. Distance from and Frontage on Road
Register? No M  3. Part of Estab. Yes I I Hist. Dist.? No M  5. Name of Established D  2. Further Description of	14. District Ye Potent'1? No District  Important Features	The building faces east onto Wyandot	Public Road? No ::  41. Distance from and Frontage on Road 58 feet on Wyandotte
Register? No Market Part of Established Date of Established Date of Established Date of the with a stone Tudor features vertical panels featuring ethe second story for the second story from the seco	Important Features e street. Smoor arched surro stone banding	S X Other Surveys in Which included	Public Road? No::  41. Distance from and Frontage on Road 58 feet on Wyandotte  tte, and follows a rather st story, and a doorway ag. The central bay wall. Rectangular band course divides
Register? No M  3. Part of Estab Yes II Hist Dist.? No M  5. Name of Established D  2. Further Description of steep grade of the with a stone Tudor features vertical panels featuring ethe second story f	Important Features e street. Smoor arched surrous tone banding elaborate reliferom the parapaced on the re	The building faces east onto Wyandot oth stone facing is applied to the fir und is at the south end of the building that extends through to the parapet wef carving articulate the parapet. A et wall which terminates in stone band ar of the building.	Public Road? No::  41. Distance from and Frontage on Road 58 feet on Wyandotte  tte, and follows a rather st story, and a doorway ng. The central bay vall. Rectangular band course divides ding. At an unknown date,
Register? No Model  Part of Established Down to the Model	Important Features e street. Smoor arched surrous tone banding elaborate reliferom the parapaced on the re	The building faces east onto Wyandot oth stone facing is applied to the fir und is at the south end of the building that extends through to the parapet wef carving articulate the parapet. A et wall which terminates in stone band ar of the building.	Public Road? No::  41. Distance from and Frontage on Road 58 feet on Wyandotte  tte, and follows a rather st story, and a doorway ng. The central bay vall. Rectangular band course divides ding. At an unknown date,
Register? No Mark  Part of Estab Yes II Hist Dist.? No Mark  Name of Established Distered parade of the with a stone Tudor features vertical panels featuring ethe second story fanaddition was planed to the second story fanaddition was plane	Important Features e street. Smoor arched surrous tone banding elaborate reliferom the parapaced on the rester operators.  The originater operators are the originater operators.	The building faces east onto Wyandot oth stone facing is applied to the fir und is at the south end of the building that extends through to the parapet wef carving articulate the parapet. A et wall which terminates in stone band ar of the building.	Public Road? No::  41. Distance from and Frontage on Road 58 feet on Wyandotte  te, and follows a rather st story, and a doorway and. The central bay vall. Rectangular band course divides ding. At an unknown date,  Paramount Publix  th, south and east of
Register? No March 19 Part of Established Date 19 No March 2 Further Description of Steep grade of the with a stone Tudor features vertical panels featuring ethe second story fanaddition was planed to the second story fanaddition to the second story fanaddition was planed to the second story fanaddition was planed to the second story fanaddition of the second story fanaddition was planed to the second story fanaddition of the second story fanaddition	Important Features e street. Smoor arched surrous tone banding elaborate reliferom the parapaced on the rester operators. The originate repeater of the originate repeater operators.	The building faces east onto Wyandot oth stone facing is applied to the fir und is at the south end of the building that extends through to the parapet we for carving articulate the parapet. A et wall which terminates in stone band ar of the building.  Inal tenant of this building was the Possible of the building of the building was the Possible of the building are norted to see the sale walkway bridges the alley behing the sale walkway bridges the alley behing the sale walkway bridges the sale walkway behing the sale walkway bridges the sale was a sale walkway bridges the sale was a sale was a sale was a sale walkway bridges the sale was a	Public Road? No::  41 Distance from and Frontage on Road 58 feet on Wyandotte  te, and follows a rather st story, and a doorway and. The central bay wall. Rectangular band course divides ding. At an unknown date,  Paramount Publix  46 Prepared by
Register? No March 1981 Part of Established Date of Established Date of Established Date of Established Date of the With a stone Tudor features vertical panels featuring established State of the second story fanaddition was placed. History and Significant Corporation, thea connect it with the Sources of Information P #15351	Important Features e street. Smoor arched surrous tone banding elaborate reliferom the parapaced on the rester operators.  The originater operators are building to be building to	The building faces east onto Wyandot oth stone facing is applied to the fir und is at the south end of the building that extends through to the parapet we for carving articulate the parapet. A set wall which terminates in stone band ar of the building.  Inal tenant of this building was the Post of the building was the Post of the building was the Post of the west (213-15 West 18th Street).	Public Road? No::  41 Distance from and Frontage on Road 58 feet on Wyandotte  te, and follows a rather st story, and a doorway and. Rectangular band course divides ding. At an unknown date,  Paramount Publix  46 Prepared by Piland/Uguccioni
Register? No Mark  Part of Estab Yes II Hist Dist.? No Mark  Name of Established Distered parade of the with a stone Tudor features vertical panels featuring ethe second story fanaddition was planed to the second story fanaddition was plane	Important Features e street. Smoor arched surrous tone banding elaborate reliferom the parapaced on the rester operators.  The originater operators are building to be building to	The building faces east onto Wyandot oth stone facing is applied to the fir und is at the south end of the building that extends through to the parapet we for carving articulate the parapet. A set wall which terminates in stone band ar of the building.  Inal tenant of this building was the Post of the building was the Post of the building was the Post of the west (213-15 West 18th Street).	Public Road? No::  41 Distance from and Frontage on Road 58 feet on Wyandotte  tte, and follows a rather st story, and a doorway and a doorway all. Rectangular band course divides ding. At an unknown date,  Paramount Publix  46 Prepared by Piland/Uguccioni  47 Organization
Register? No March 1981 Part of Established Date of Established Date of Established Date of Established Date of the With a stone Tudor features vertical panels featuring established State of the second story fanaddition was placed. History and Significant Corporation, thea connect it with the Sources of Information P #15351	Important Features e street. Smoor arched surrous tone banding elaborate reliferom the parapaced on the rester operators.  The originater operators are building to be building to	The building faces east onto Wyandot oth stone facing is applied to the fir und is at the south end of the building that extends through to the parapet we for carving articulate the parapet. A set wall which terminates in stone band ar of the building.  Inal tenant of this building was the Post of the building was the Post of the building was the Post of the west (213-15 West 18th Street).	Public Road? No::  41 Distance from and Frontage on Road 58 feet on Wyandotte  te, and follows a rather st story, and a doorway and. Rectangular band course divides ding. At an unknown date,  Paramount Publix  46 Prepared by Piland/Uguccioni



		3
		4
		i

1	1. No. 51-A	4. Pres	ent Name(s)	*
Sources of Information   Size   Structure   Building xx   Structure	Country		1801 Wyandotte	
Specific Location  Specific Location  1801 Wyandotte  City or Yow If Rural, Township & Vicinity Kansas City, Missouri  Site Plan with North Arrow  Next 182 Street  Coomercial Decomercial  23 Owner's Name & Address, If Annual Caronic Provider Ix House It Street Private Ix	Jackson		er Name(s)	
1801 Wyandotte	Location of Negatives M	T #105-13 n of KC	Whitcomb Cabinet Company	
17 Date(s) or Period 1904  City or Town II Rural, Township & Vicinity Kansas City, Missouri Site Plan with North Arrow  Wist 18 2 Street  20 Contractor or Builder  21 Original Use, if apparent commercial ODE 21 Original Use, if apparent commercial 22 Present Use commercial 23 Ownership Private ix Building Xx  UTM Left Long  Coordinates UTM Left Long  Contractor Name & Address, if known  Site I: Building Xx  UTM Left Long  Contractor Name & Address, if known  Site I: Building Xx  Open to Public I' 76 Condition Interior Exterior good.  25 Open to Public Private Notinic Ves I' 8 Lightler No. XX  Register? No. XX  Further Description of Important Features  Further Description of Important Features This corner building has a canted entrance at the north corner of the building. Plate glass windows flank the entrance. Most of the window ar on the first floor have been bricked in. The window openings on the second and third f have stone sills. Some of these windows have been covered. Corbelling marks the parape  Description of Environment and Outbuildings  Commercial buildings are north, east and west of this  rer. A surface parking area is to the south.  46 Prepared by PILIAND  Programszation PILIAND  46 Prepared by PILIAND  Programszation PILIAND  Programszation Prog	THE RESIDENCE OF THE PARTY OF T	and the same of the same of		28. No. of Stories 3
Coordinates  UTM  Lat. Long  Coordinates Lut.  Site 1: Building xx  Register?  No xx  Register.  Reg	2220 200 200 200			
Coordinates Long  Site: Structure: On National Yes: 12 is! Yes X Register? Nox X History No XX History No XX Part of Established District  Further Description of Environment and Outbuildings Commercial buildings are north, east and west of this rep. 42, 226, 226, 226, 227, 227, 227, 227, 22	1801 Wyandotte		The second secon	No I
Site Plan with North Arrow    Declipical Contractor or Builder   Prophosis   P	City of Town . If Bural	Township & Vicinity		
19 Architect of Engineer   14   15   16   16   17   17   18   18   18   18   18   18			1 -	31. Wall Construction
20 Contractor or Builder   21   23 No. of Bays   33 No. of Bays   34   Wail Treatment   22   Present Use   23   24   25   25   25   26   26   26   26   26			puller.	
21 Original Use, if apparent commercial OPH 31. No. of Bays Front Side Commercial OPH 34. Wall Treatment brick 30. No. of Bays Front Side Commercial 23 Ownership Public 1 Private 1x 24. Owner's Name & Address, if known 37. Condition Interior Exterior good    Site   Structure   Object   25. Open to Public 2 Present Use Commercial Structure   Object   26. Local Contact Person or Organization Register? No. xx Eligible? No. xx Potenti? No. xx Potenti. Xx Pot	West 18	R Street		32. Roof Type & Material F+
21 Original Use, if apparent commercial 34 Wall Treatment brick 35 Plan Shaperectan 35. Plan Shaperectan 37. Condition Interior Extenor good.  22 Present Use			Prince)	
Coordinates  UTM  Lat.  Lony  Site: Structure:   Structure:   25. Open to   Public?   Yes X   Public?   No.   Yes   Xet   Yes X   Public?   No.   Yes   Xet   Yes X   Potenti?   No.   Yes   Xet   Yes X   No.   Yes   Yes X   Yes	10		21. Original Use, if apparent	
Coordinates  UTM  Lat.  Long  Site! Structure!  Building xx Object!  Building xx Object!  Building xx Object!  Con National Yes   12   Is   Il Yes X Eligible? No.   12   Other Surveys in Which included  Landmarks Commission of KC 27 Other Surveys in Which included  The public Road?  Name of Established District  Further Description of Important Features This corner building has a canted entrance at the north corner of the building. Plate glass windows flank the entrance. Most of the window are on the first floor have been bricked in. The window openings on the second and third flave stone sills. Some of these windows have been covered. Corbelling marks the parape  History and Significance This building was constructed for the Whitcomb Cabinet Company, a st xture firm.  Description of Environment and Outbuildings Commercial buildings are north, east and west of this re. A surface parking area is to the south.  46. Prepared by PILAND  P#24206  Andress Address.  37. Condition Interior Exterior good.  38. Preservation Underway?  39. Endangere?  By What?  40. Visible from Public Road?  40. Visible from Public Road?  41. Distance from and Frontage on Road  45. Prepared by PILAND  Ansas City Star. September 19, 1926, p. 2D  46. Prepared by PILAND  47. Organization	8			
Coordinates  UTM  Lat.  Long  Site! Structure!  Building xx Object!  Building xx Object!  Building xx Object!  Con National Yes   12   Is   Il Yes X Eligible? No.   12   Other Surveys in Which included  Landmarks Commission of KC 27 Other Surveys in Which included  The public Road?  Name of Established District  Further Description of Important Features This corner building has a canted entrance at the north corner of the building. Plate glass windows flank the entrance. Most of the window are on the first floor have been bricked in. The window openings on the second and third flave stone sills. Some of these windows have been covered. Corbelling marks the parape  History and Significance This building was constructed for the Whitcomb Cabinet Company, a st xture firm.  Description of Environment and Outbuildings Commercial buildings are north, east and west of this re. A surface parking area is to the south.  46. Prepared by PILAND  P#24206  Andress Address.  37. Condition Interior Exterior good.  38. Preservation Underway?  39. Endangere?  By What?  40. Visible from Public Road?  40. Visible from Public Road?  41. Distance from and Frontage on Road  45. Prepared by PILAND  Ansas City Star. September 19, 1926, p. 2D  46. Prepared by PILAND  47. Organization	3		The state of the s	
Coordinates  UTM Lett. Long  Site: Structure: Building xx  Object: Object: Object: This contact Person or Organization  And Significance This building xx  Potential Past place glass windows flank the entrance. Most of the window are on the first floor have been bricked in. The window openings on the second and third finate stone stills. Some of these windows have been covered. Corbelling marks the parape  Private ix  (Explain in #42)  37. Condition Interior Exterior good.  25. Open to Public?  26. Local Contact Person or Organization District  27. Other Surveys in Which Included  48. Wisible Irom Public Road?  49. Wisible Irom Public Road?  40. Usible Irom Public Road?  41. Distance from and Frontage on Road  Further Description of Important Features on the first floor have been bricked in. The window openings on the second and third finate stone stills. Some of these windows have been covered. Corbelling marks the parape  History and Significance This building was constructed for the Whitcomb Cabinet Company, a st xture firm.  Description of Environment and Outbuildings  Commercial buildings are north, east and west of this re. A surface parking area is to the south.  46. Prepared by PILAND  PILAND  47. Organization	8			36. Changes Addition
Coordinates UTM Lai. Long  Site: Structure: Object: Depending XX  On National Yes: No XX  Register? No XX  Register		1		(Explain Altered :
Coordinates Lai. Long  Site: Building xx  Structure: Building xx  Object:  Object:  No xx  Register?  No xx  Register?  No xx  Potenti?  Potenti.  Potenti?  Potenti.  Potenti.  Potenti.  Potenti.  Potenti.  Potenti.  Poten		NI		
Lait Long  Site: Structure: Building xx  Object: Objec			ii known	
Site: Building xx  Structure: Building xx  Object: On National Yes: Register? No xx  Register? No xx  Eligible? No: Part of Estab. Yes: It District Yes x Potent!? No: Part of Estab. Yes: It District Yes x Potent!? No: Part of Estab. Yes: It District Yes x Potent!? No: Part of Estab. Yes: It District Yes x Potent!? No: Part of Estab. Yes: It District Yes x Potent!? No: Part of Estab. Yes: It District Yes x Potent!? No: Potent!? No: Part of Estab. Yes: Part of Est		М		Exterior good
Building xx  Object  O	Long			38. Preservation Yes
On National Yes   12   12   18   12   18   12   18   14   18   18   18   18   18   18				
Part of Estab. Yes   14. District Yes x Hist. Dist.? No xx Potent'!? No xx Pot	On National Yes II	12 is it Yes X	Landmarks Commission of KC	
Name of Established District  41. Distance from and Frontage on Road  Further Description of Important Features This corner building has a canted entrance at the north corner of the building. Plate glass windows flank the entrance. Most of the window are on the first floor have been bricked in. The window openings on the second and third flavor stone sills. Some of these windows have been covered. Corbelling marks the parapetature firm.  History and Significance This building was constructed for the Whitcomb Cabinet Company, a stature firm.  Description of Environment and Outbuildings Commercial buildings are north, east and west of this re. A surface parking area is to the south.  Sources of Information  P #24206  ansas City Star, September 19, 1926, p. 20	Part of Estab. Yes ! !		27. Other Surveys in Which included	
Further Description of Important Features This corner building has a canted entrance at the north corner of the building. Plate glass windows flank the entrance. Most of the window are on the first floor have been bricked in. The window openings on the second and third for have stone sills. Some of these windows have been covered. Corbelling marks the parape History and Significance This building was constructed for the Whitcomb Cabinet Company, a stature firm.  Description of Environment and Outbuildings Commercial buildings are north, east and west of this are. A surface parking area is to the south.  Sources of Information  P #24206 Cansas City Star, September 19, 1926, p. 2D	AA			41. Distance from and
corner of the building. Plate glass windows flank the entrance. Most of the window are on the first floor have been bricked in. The window openings on the second and third f. have stone sills. Some of these windows have been covered. Corbelling marks the parape  History and Significance This building was constructed for the Whitcomb Cabinet Company, a staxture firm.  Description of Environment and Outbuildings Commercial buildings are north, east and west of this are. A surface parking area is to the south.  Sources of Information  P #24206 Cansas City Star. September 19, 1926, p. 2D				Frontage on Road
Description of Environment and Outbuildings Commercial buildings are north, east and west of this are. A surface parking area is to the south.  Sources of Information  Pr #24206  Cansas City Star, September 19, 1926, p. 20  47. Organization	on the first floor have stone sills.	have been brick Some of these wi	ted in. The window openings on the indows have been covered. Corbellin	second and third floors ng marks the parapet wal
PILAND  Ansas City Star, September 19, 1926, p. 2D  47. Organization	ixture firm.  Description of Environment	nt and Outbuildings	Commercial buildings are north, ea	
Kansas City Star, September 19, 1926, p. 2D	The state of the s			
		eptember 19, 19	26, p. 2D	Landmarks Commission
48. Date 49 Revision 4/12/84				48. Date 49 Revision Date(s)



I	804	esent	
of transferred and the name	804 Wyandotte	esent Name(s)	
TRACE LA			
and a special party			
To be desired to			
1			
100000			
n			

Landmarks Commission

49 Hevision Date(s)

40. Date

8/13/82

1. No.	4. Pre	sent Name(s)		
50-G 2 County	Mi	d-Continent Theatre Supply Corporat	tion	50-
Jackson		ner Name(s)		)-G
3 Location of Negatives Landmarks Commiss:		ebbins Theater Equipment Company	Sulding	
6 Specific Location		16. Thematic Category	28. No. of Stories	Ja
		190	29. Basement? Yes	Jackson
1804 Wyandotte		17 Date(s) or Period .	No I	SOI
		1929 (alt)	30. Foundation Material	2
7 City or Town II Aur. Kansas City, Misso		18 Style or Design	31. Wall Construction	N COL
Site Plan with North Ar		19 Architect or Engineer	masonry UD	
	1.1		32. Roof Type & Material ++	
Los	N	20. Contractor or Builder	flat; composition 99	
4	1/2		33. No. of Bays Front Side	
90		21. Original Use, if apparent commercial DE	34. Wall Treatment	TA
Obuch		22 Present Use	brick; metal 50	1804
10		commercial	35. Plan Shape rectangular	
13	,	23 Ownership Public ! !	36. Changes Addition :	wyando
		Private 🐰	(Explain Altered   X in #42) Moved	00
		24. Owner's Name & Address, if known	37. Condition	CCE
Coordinates	UTM		Interior	
Lat.	UTM		Exterior good	
Long.		25. Open to Yes II	38. Preservation Yes	200.00
O. Site ! :	Structure	Public? No ⊠	Underway? No iX	
Building ( x	Object 11	26. Local Contact Person or Organization Landmarks Commission	39. Endangered? Yes I By What? No IX	
Register? No IX	Eligible? No 11	27. Other Surveys in Which Included	40. Visible from Yes!X	
Hist. Dist.? No 1 k	Potent'l? No : .		Public Road? No 11	
5. Name of Established D	istrict		41. Distance from and Frontage on Road	
			25 feet on Wyandotte	1
2. Further Description of	Important Features Th	e building faces east onto Wyandot	NAME AND ADDRESS OF THE OWNER, WHEN PERSON	a
		panes. The corners of the buildi	ng feature buff brick	1
piers. The parape	et wall consists	of a series of metal panels. Com	parison of a c. 1940	1
		been altered, with the original te	rra cotta wall surface	
removed or obscure	ed. Date of this	alteration is unknown.		
				•
I. Vistory and Significance	e This building	was originally occupied by the St	ebbins Theater	
Equipment Company.	Property of the first of the			
tion of Environm	nent and Outbuildings	Other commercial buildings are nor	th and west of this	
structure A surf	ace parking lot	is to the south. To the east is an		
building.	are francis		Arran Carlotte Comment	
And the state of t				
Information			46. Prepared by	
WP #89487			Uguccioni /Piland	
DD #15/30			47. Organization	4

BP #15439



12/23/82



J. Vinc. framets		
Cinc. fadic		
Cinc. fadic		
Cinc. fadic		
Cinc. fadic	_	-
ILL THE		-
iadine(S.		ישווני
11:0(5		144
67		100
		5

Landmarks Commission
48. Date 49. Revision Date(s)

10/18/82

. No. 50-F	4. Pre	sent Name(s)	+	
?. County	18	318-22 Wyandotte		50
Jackson Location of Negatives Landmarks Commission	MT#91-3	ner Name(s) not entered		0-F
Specific Location		16. Thematic Category	28. No. of Stories 2	
1818-22 Wyandotte		17. Date(s) or Period	29. Basement? Yes ! No ! .	Jackson
City or Town Kansas City, Misson	, Township & Vicinity	1922 18. Style or Design	30. Foundation Material	on
Site Plan with North Arro		19. Architect or Engineer	31. Wall Construction masonry	
one rial with room site		John G. Braecklein	32. Roof Type & Material	
	# N	20. Contractor or Builder George Bowling & Son	flat; tar & gravel	-
	0	21. Original Use, if apparent	Front Side	18
	9	commercial	34. Wall Treatment	1818-2
	8	22. Present Use commercial	concrete block/stone 35. Plan Shape rectangular	-22
W. 19 Th 57	- 2	23 Ownership Public I !	36. Changes Addition i:	
		Private   x	(Explain Altered X: in #42) Moved	Wyandotte
Coordinates U	TM -	il known	37. Condition Interior	
Lat. Long.		25. Open to Yes Ix	Exterior good Yes	
Site ! :	Structure 1	Public? No 11	Underway? No ix	
Building lx On National Yes II Register? No lx	Object     12 Is II Yes   X Eligible? No   !	26. Local Contact Person or Organization Landmarks Commission	39. Endangered? Yes I I No x I	
Part of Estab Yes I I Hist. Dist.? No 🖂	14. District Yes IX Potent'1? No	27. Other Surveys in Which Included	40. Visible from Yes x Public Road? No i	
Name of Established Dis	trict		41. Distance from and Frontage on Road 50 feet on Wyandotte	
dramatically alte	red. Decorative s been used to s	e building which faces east onto Wy blocks face the first story of the urface the remainder of the building is unknown.	e east facade. A rock	
. History and Significance The first tenants Company.		g originally housed firms involved in Service, Keystone Press, and Mid		
1				
Description of Environme the east and west		A surface parking lot is north of buildings. A commercial building i		

Western Contractor, Feb. 22, 1922, p. 38 Kansas City Star, Feb. 19, 1922, p. 8D.



BP #20236A

Piland

48. Date 1/21/83

47. Organization

Landmarks Commission

49. Revision Date(s)



BP #12986

Kansas City Star, Jan. 1, 1922, p. 9C.

47. Organization

9/28/82

Landmarks Commission

48. Date 49. Revision Date(s)



AS-008-15/n

49. Revision Date(s)

48. Date 4

HISTORIC INVENTORY

1 No

4. Present Name(s)



Landmarks Commission

49. Revision Date(s)

48. Date

1/26/82

`olumbia, Missouri 65201 ISTORIC INVEN 4. Present Name(s) 1. No. 70-B 1905-07 Wyandotte 2. County 5. Other Name(s) Jackson 3 Location of Negatives MT #21-16 Landmarks Commission & 77-4 MT #21-16 A. B. Stephens and Company Watchnice 6. Specific Location 16. Thematic Calegory 28. No. of Stories 050 ackson Yes K 29. Basement? 1905-07 Wyandotte 17. Date(s) or Period No I 30. Foundation Material 1915 (add. 1945) 7 City or Town II Rural, Township & Vicinity Kansas City, Missouri 18 Style or Design 50 31. Wall Construction 19. Architect or Engineer masonry; concrete block B. Site Plan with North Arrow 32. Roof Type & Material PR Swanson & Terney (1945) 20. Contractor or Builder varied; tar & 33. No. of Bays Gardner Brothers (1915) Front Side 21. Original Use, if apparent commercial () -34. Wall Treatment 22. Present Use brick 35. Plan Shape commercial rregular 36. Changes Addition ix 23 Ownership Public 11 Private xx (Explain Altered | in #42) Moved i 24. Owner's Name & Address, if known 37. Condition Interior 9 Coordinates MTU Exterior good Lat. Long 25. Open to Yes M Preservation Yes I Public? Noil Underway? No K 10 Site ! : Structure Building 12 Object | | 26. Local Contact Person or Organization Endangered? Yes By What? No k Landmarks Commission 11. On National 12 Is It Yes X Yes Register? No 1x Eligible? No 27. Other Surveys in Which Included Yes X 13 Part of Estab Yes ! ! 14. District 40. Visible from Yes X Hist. Dist ? No L Potent'1? Public Road? No ! 41. Distance from and 15. Name of Established District Frontage on Road 50 feet on Wyandotte 42 Further Description of Important Features The first story of the west facade contains entrances at the north and south ends. Above the doors and storefronts are placed bands of brick laid in soldier course. A stone string course separates the first from second story and also defines the parapet wall. Stone quoining occurs at the corners of the building. parapet wall is stepped and is embellished with decorative brick rectangular panels. An addition extended the building 50 feet to the south in 1945. Brick piers divide this addition into bays. The addition has a truss roof. The building contains 23,000 square feet of space. 43. History and Significance This building was constructed as a warehouse for A.B. Stephens and Company, fur merchants. The company was headed by Albert Stephens. The addition to the building was to accommodate the expansion of the Fox Product Company, syrup manufacturers. 44. Description of Environment and Outbuildings Other commercial buildings are north, south, east, and west of this structure. 45 Sources of Information 46. Prepared by Piland /Uguccioni BP #11535 47. Organization BP #17874A

WP #6654

Kansas City Star, Nov. 22, 1981, p. 3H.

Western Contractor, July 7, 1915, p. 30.

State Historical Survey and Planning Office, 909 University Avenue, Suite 215



Add V



1. No.	4. Present Name(s)	
65-E 2 County Jackson	1914-16 Wyandotte Street Ware  5 Other Name(s)	house
3 Location of Negatives Landmarks Commission MT #83-20		
6. Specific Location	16. Thematic Category	28 No. of Stories 1=/
1914-16 Wyandotte	17 Date(s) or Period .	29. Basement? Yes   No   700
7 City or Town If Rural, Township & Kansas City, Missouri	Vicinity 18 Style or Design	31. Wall Construction
B. Site Plan with North Arrow	19 Architect or Engineer 30 40	masonry UD  32. Roof Type & Material FR  flat; tar & gravel
The back	James W. Hood  21 Original Use, if apparent  commercial  22 Present Use  unknown	33. No. of Bays Front 3 Side  34. Wall Treatment  30 brick  35. Plan Shape rectangular
3	23 Ownership Public     Private     24. Owner's Name & Address, If known	(Explain Altered   Wy n m #42) Moved   D
9. Coordinates UTM Lat.		37. Condition Interior Exterior good
	25. Open to Yes 1 ; Public? No lx	38. Preservation Yes Underway? No x
11. On National Yes 11 12 Is II	Yes: x Landmarks Commission	39. Endangered? Yes   By What? No   X
Register? No Z: Eligible?  13 Part of Estab. Yes   14 District Hist. Dist.? No x  Potent' ?	Yes x No :-	40. Visible from Yes x Public Road? No
15. Name of Established District		41. Distance from and Frontage on Road 50 ft. on Wyandotte

in elevation. Storfront bays flank a central garage bay. The parapet wall steps up intermittantly and terminates in stone coping. A small addition of unknown date has been placed on the south wall of the structure.

43. History and Significance This building was first used as a warehouse for the Bunting Hardware and Machinery Company.

44. Description of Environment and Outbuildings Commercial buildings are north and east of this structure A surface parking area is to the south. To the west is another commercial building.

## 45 Sources of Information

WP #83037K BP #14502

Western Contractor, October 28, 1925, p. 38

46. Prepared by Piland /Uguccioni

47. Organization

Landmarks Commission

48. Date 49 Revision Date(s)

1/31/84



No 4. Present Name(s) 70-K Squadron Press 70-K 2. County 5. Other Name(s) Jackson 3 Location of Negatives MT #77-3 Landmarks Commission 1915 Wyandotte Street Budding 6. Specific Location 16. Thematic Category 28. No. of Stories ackson 29. Basement? Yes xx 1919 Wyandotte 17 Date(s) or Period No I 1906 30. Foundation Material City or Town If Rural, Township & Vicinity Kansas City, Missouri Style or Design 50 31. Wall Construction B. Site Plan with North Arrow ables 19. Architect or Engineer masonry LLD 30 32. Roof Type & Material - PP 20. Contractor or Builder flat; tar & gravel 33. No. of Bays Side Front 21. Original Use, if apparent Present Commercial ODE 34. Wall Treatment 1919 22. Present Use brick ; wood commercial 35. Plan Shape irregular Wyandotte 23. Ownership Public !! 36. Changes Addition : Private 13 (Explain Altered X in #42) Moved 24. Owner's Name & Address, if known 37. Condition Interior 9 Coordinates good Exterior Lat. Long 25. Open to Yes X 38. Preservation Yes Public? No Underway? Noix Site ! Structure ! Building | Object | | 26. Local Contact Person or Organization 39. Endangered? Yes By What? Nolx Yes XX Landmarks Commission 11. On National 12 Is It Yesii Register? No XX Eligible? No 27. Other Surveys in Which Included Yes XX Yes !X 13 Part of Estab. Yes !! District Visible from Potent'l? Hist. Dist.? Noxx No: Public Road? Noil 41. Distance from and approx. 15. Name of Established District Frontage on Road 60 feet on Wyandotte 42. Further Description of Important Features The West facade contains a garage bay at the north end. Storefront panels comprise the remainder of the first story. The second story is fenestrated 1915 Wyandotte with 3 paired rectangular windows, flanked by single rectangular windows, that posses stone lugsills and lintels. The parapet wall is distinguished by a string course of corbelled brick. The building terminates in tile coping. The building contains 10,000 square feet. 43. History and Significance The water permits indicate this building was to be used for "manufacturing ladies and gents suits." This has not been confirmed by City Directories and the early use of the building is unknown. The Decorator's Wallpaper Company began occupying the building in 1939 and in 1953 purchased the building. 44. Description of Environment and Outbuildings Commercial buildings are north, south, east, and west of this structure. 45 Sources of Information 46. Prepared by Piland /Uguccioni WP #32091 47. Organization Kansas City Star, July 12, 1953, p. 12D Landmarks Commission 48. Date 49. Revision Date(s)

State Historical Survey and Planning Office, 909 University Avenue, Suite 215,

lumbia, Missouri 65201

12/6/83



structure. A small surfaced parking area is to the north. To the east is another

Kansas City Architect and Builder, August

1900, p. 243

46. Prepared by

47. Organization

Landmarks Commission

49. Revision Date(s)

Uguccioni

48. Date

5/3/82

commercial building.

Kansas City Times, November 10, 1943.

45 Sources of Information

WP #30953

1920 Wyandotte

43 cont.

JA-AS-008-1572

The Kansas City Architect and Builder indicates that in 1900 a building permit was issued to the Berkowitz Envelope Company for an \$8000.00 business building on Wyandotte between 19th and 20th Streets. The city directory of 1901 locates their building at 1918-20 Wyandotte. The water permit however was not issued until 1906.



48. Date

3/30/83

49. Revision Date(s)



11/17/82

BP #69190



45 Sources of Information

Western Contractor, Feb. 20, 1918, p. 20

BP #12334; 12368

WP #17416

State Historical Surry and Planning Office, 909 University Avenue, Suite 215,

Courty

Present Name(s)

46. Prepared by

47. Organization

48. Date

6/28/82

Piland /Uguccioni

Landmarks Commission

49. Revision Date(s)

JA-AS-008-1575

Historic Inventory 2014-20 Wyandotte

#42 Continued

detached  $24 \times 36$  foot brick storage building was constructed at the rear of the property. At some more recent time a metal garage building was placed between the two brick structures.





REAR 1

olumbia, Missouri 65201 HISTORIC INVENTORY 1. No. 4. Present Name(s) 90-A Lee Warehouse 2 County Warehouse 5 Other Name(s) H. D. Lee Mercantile Co.; (117 West 20th Street Warhous Jackson Location of Negatives MT Landmarks Commission MT #75-11 6 Specific Location 16. Thematic Category 28. No. of Stories lackson County 2019 Wyandotte 29. Basement? Yes IX 17. Date(s) or Period No I 1916-17 30. Foundation Material 7. City or Town II Rural, Township & Vicinity Kansas City, Missouri concrete 65 18. Style or Design 63 31. Wall Construction 8. Site Plan with North Arrow 19. Architect or Engineer reinforced concrete Other 32. Roof Type & Material West 20 - Street Sunderland flat; tar & grave + 10 20. Contractor or Builder 33. No. of Bays 99 Gray Const. Co. Front Side 21. Original Use, if apparent 8 Present commercial OPH 34. Wall Treatment 19 22. Present Use brick ; stone 3 35. Plan Shape irregular warehouse 23 Ownership Public 11 36. Changes Addition Private bd (Explain Altered | in #42) Moved I 24. Owner's Name & Address, if known 37. Condition Interior 9 Coordinates UTM good Exterior Lat. Long 25. Open to Yes II 38. Preservation Yes Public? No X Underway? No X Site!: Structure 1 Object 11 Building !! 26. Local Contact Person or Organization Endangered? Yes By What? No K Landmarks Commission 11. On National Yes ! 12 Is It Yes x Eligible? Register? No No I 27. Other Surveys in Which Included Yes x 13. Part of Estab. Yes I Yes X District Visible from Hist. Dist ? No ly Potent'1? Public Road? No ! Distance from and 15. Name of Established District Frontage on Road 138 feet on Wyandotte 42. Further Description of Important Features The main facade faces north. The building is characterized by regularly spaced rectangular windows that are separated by brick piers. The west facade features stone facing on the first two stories. A terra cotta band course separates the eighth from ninth stories. A tower is placed at the south end of the building. Garage bays pierce the first story of the south facade. A one-story addition extends on the south facade. Terra cotta banding decorates the tower and terminates the parapet wall. 43. History and Significance The H. D. Lee Mercantile Company was established in Saline, Kansas in 1889 The company opened a clothing manufacturing plant in Kansas City in 1915. This building housed factories and the wholesale grocery business of the Lee firm. The building contains 230,000 square feet. 44. Description of Environment and Outbuildings A surface parking lot and loading dock area are south of this building. To the east and west are other commercial buildings. To the north is a commercial building and a surface parking lot. Wes 45 Sources of Information 46. Prepared by Piland /Uguccioni WP #20612 47. Organization Kansas City Star, March 18, 1917, p. 15A. Landmarks Commission S Kansas City Times, March 16, 1928. 48. Date 49. Revision Date(s) Kansas City Star, May 7, 1916, p. 13A. 7/28/83 Western Architect, June 1917, p. v.

Kansas City Star, March 4, 1957, p. 3A.

State Historical Surry and Planning Office, 909 University Avenue, Suite 215,



47. Organization

48. Date

1/14/82

Landmarks Commission

49. Revision Date(s)

Present Name(s)

State Historical Sur / and Planning Office, 909 Univ ity Avenue, Suite 215, columbia, Missouri 65201 HISTORIC INVENTORY No 90-B K-G Sales Company; Rail Sales 2. County Jack son 5 Other Name(s) Safeway Stores (Regional Offices) 3 Location of Negatives MT #75-10 Landmarks Commission Suilding 6. Specific Location 16. Thematic Category 28. No. of Stories 050 030 29. Basement? Yes IX Date(s) or Period No I. 2029-43 Wyandotte 1929 (add. 1949 & 1976) 30. Foundation, Material concrete 65 Style or Design · If Rural, Township & Vicinity 31. Wall Construction PC Kansas City, Missouri other B. Site Plan with North Arrow 19. Architect or Engineer reinforced concrete Archer & Gloyd 40 30 32. Roof Type & Material flat; tar & gravel F+PE 20 Contractor or Builder (3) Charles E. J.H. Thompson Const. Co. Keyser 33. No. of Bays Front 5 Side 21. Original Use, if apparent warehouse/offices OPA OPH 34. Wall Treatment 22. Present Use brick; stone 35. Plan Shape rectangular commercial 36. Changes 23 Ownership Addition X Public I Private L (Explain Altered IX in #42) Moved i 24. Owner's Name & Address, it known 37. Condition Interior 9. Coordinates UTM Exterior Lat pood Long 25. Open to Yes M Preservation Yes . No ix Public? Underway? Site !: Structure | Object | | Building Ix 39. Endangered? 26. Local Contact Person or Organization Yes By What? No I Yes X Landmarks Commission 11. On National Yes II 12 Is It Eligible? No !! Register? No IX 27. Other Surveys in Which Included 13 Part of Estab. Yes II District Yes X 40. Visible from Yes !x Potent'l? No : Hist. Dist.? No 1x Public Road? No :: 15. Name of Established District Distance from and Frontage on Road 100 feet on Wyandotte 42. Further Description of Important Features The end bays of the west facade contain arched openings on the first story. The end bays are defined by stone piers that extend from the second story beyond the shaped parapet. The central three bays are distinguished on the parapet level by a stone panel inscribed in raised relief with the legend: "SAFEWAY STORES INCORPORATED." Stone strin courses divide the building horizontally into individual segments. A major remodeling was accomplished in 1934; and a loading dock added in 1949. Architect for these projects was In 1976 an addition was placed on the north facade of the Charles E. Keyser. building. The building contains 84,000 square feet. 43. History and Significance The building was construced for the Safeway chain of grocery stores, as their regional office, main warehouse and bakery. The company was founded and originally name after M. B. Skaggs. In 1929 the Safeway chain had 640 retail stores, 44 warehouses and 15 bakeries. During the late thirties, the Safeway Company engaged in an extensive building program and constructed this warehouse building to serve its rapidly expanding facilities. 44. Description of Environment and Outbuildings Other commercial buildings are east and west of this structure. A surface parking lot is to the north. To the south is another commercial building. 45 Sources of Information 46. Prepared by BP #98411; 26093A Uguccioni/Piland

Midwestern Contractor, Oct 16, 1929, p. 28.

Kansas City Star, Nov. 27, 1983, p.6E.

BP#A2989

BP #91035

BP #415484

KC Star, June 12, 1932

KC Star, February 21, 1940

KC Star, December 1, 1940 KC Star, August 26, 1951



## HISTORIC INVENTORY 1. No 4. Present Name(s) 90-J Garage 2049 Wyandotte Street 2. County 5. Other Name(s) Jackson 2117 Wyandotte Street Garage - other name 3 Location of Negatives MT #43-6 Landmarks Commission 6. Specific Location Thematic Category 28. No of Stories Jackson 030 05 29. Basement? Yes 2049 Wyandotte Date(s) or Period 1934 No I 30. Foundation Material City or Town If Rural, Township & Vicinity Kansas City, Missouri 18 Style or Design 69 31. Wall Construction B. Site Plan with North Arrow 19. Architect or Engineer masonry LLD alter 32. Roof Type & Material + PR 20. Contractor or Builder flat; tar and gravel 33. No. of Bays John H. Thompson Front Side 21. Original Use, if apparent 2049 garage 160 34. Wall Treatment Wat 22 mstreet 22. Present Use bric Wyandotte 35. Plan Shape garage rregular 23 Ownership Public | Changes Addition Private k (Explain Altered in #42) Moved 24. Owner's Name & Address, if known 37. Condition Interior 9. Coordinates UTM Exterior Lat Long 25. Open to Yes !! Preservation Yes Public? No ix Underway? No ix Site ! : Structure Building 1x Object 11 26. Local Contact Person or Organization Endangered? Yes By What? No IX Landmarks Commission 11. On National Yesli 12 Is It Yes x Register? Eligible? No I No I 27. Other Surveys in Which Included 13 Part of Estab. Yes ! ! District Yes ! Yes X Visible from X Hist. Dist.? No 1+ Potent'1? No ! Public Road? No I Distance from and 15. Name of Established District Frontage on Road 70 ft on Wyandotte 42 Further Description of Important Features The main facade of this building faces north and consists of a series of garage door openings. A secondary garage door opening is at the southwest corner of the building. Concrete coping terminates the brick walls. Wyandotte

43. History and Significance This garage building was constructed for Safeway Stores, Inc., whose regional offices and main headquarters were to the immediate north (2029-43 Wyandotte).

44. Description of Environment and Outbuildings Commercial buildings are north, south, east and west of this structure.

45 Sources of Information BP#15754

46. Prepared by Piland 47. Organization Landmarks Commission 49. Revision Date(s) 48. Date 5/13/85



No !

State Historical Sur 'y and Planning Office, 909 University Avenue, Suite 215, olumbia, Missouri 65201 HISTORIC INVENTORY 1. No 4. Present Name(s) 89-D 2100 Wyandotte 2 County 5 Other Name(s) Jackson 3 Location of Negatives Landmarks Commission MT#43-7 J. W. Jenkins's Sons Music Company Warehouse hand 6. Specific Location 16. Thematic Category 030 050 2100 Wyandotte 17. Date(s) or Period 1920 City or Town II Rural, Township & Vicinity Kansas City, Missouri 18 Style or Design B. Site Plan with North Arrow 19. Architect or Engineer 2/5151 20. Contractor or Builder Bliss Building Co. 21. Original Use, if apparent Commercial APH 22. Present Use 35. Plan Shaperectangular commercial 23 Ownership Public 11 36. Changes Addition : Private lx Alteredxx (Explain in #42) Moved i 24. Owner's Name & Address, if known 37. Condition Interior 9 Coordinates UTM Exterior Lat. good. Long 25. Open to Yes x 38. Preservation Yes Public? No II Underway? No IX Site!: Structure | Building X Object ! I 26. Local Contact Person or Organization 39. Endangered? Yes ! By What? Nolx Landmarks Commission 11 On National Yes 12 Is It Yes X Eligible? Register? No 12! No !! 27. Other Surveys in Which Included Yes X 13 Part of Estab. 14 District YesX Yes II 40. Visible from

42 Further Description of Important Features The primary entrance to this building is at the east end of the north facade. Brick piers mark the corner bays of the building. Windows on the first floor have been filled in with decorative concrete block. A string course runs between the 1st and 2nd floor. Loading dock/garage entrances are on the east facade.

- 43. History and Significance This served as a warehouse for the J. W. Jenkins's Sons Music Company, a Kansas City firm founded in 1878. The retail store was at 1217-23 Walnut. The building is now used by several firms including Graphix Associated, Inc. and Rosse Lithographing.
- 44. Description of Environment and Outbuildings Other commercial buildings are to the north, east, and wes of this building. A surface parking lot is to the south.
- 45 Sources of Information WP# 64499 BP #12685

No V

15. Name of Established District

Potent'1?

No :

Hist. Dist.?

46. Prepared by Piland/Uguccioni

Public Road?

41. Distance from and

Frontage on Road

148 feet on Wyandotte

47. Organization

Landmarks Commission 48. Date 49. Revision Date(s) 9/23/81



1. No.	4. Present Name(s)	JA-AS-008- 158C
2 County Jackson 3 Location of Negatives MT #91-8 8 Landmarks Commission #91-10	Western Extralite Company  5 Other Name(s)	
6 Specific Location 2124 Wyandotte Street  7 City or Town Missouri  8 Site Plan with North Arrow	16. Thematic Category  17. Date(s) or Period  1923  8 Vicinity  18 Style or Design  Paul H. Anthony  20. Contractor or Builder  Miller Stauch Const. Co.  21. Original Use, if apparent  commercial  22. Present Use  commercial  23. Ownership  Public      Private	28. No. of Stories 3-1 and 3  29. Basement? Yes! No!  30. Foundation Material stone  31. Wall Construction reinf. conc.; conc.blk. 32. Roof Type & Material flat; tar and gravel  33. No. of Bays Front Side  34. Wall Treatment brick; metal 35. Plan Shape irregular  36. Changes (Explain Addition: X (Explain H42) Moved:
9 Coordinates UTM Lat. Long.  10. Site!. Si Building   x  11. On National Yes!! 12 Is It Register? No x! Eligible  13 Part of Estab Yes!! 14 District	27. Other Surveys in William included	37. Condition Interior ExteriorGood  38. PreservationYes   Underway?
structure has become the an entrance and one gara irregular in plan as it. A stone stringcourse define the parapet surface. I filled in.  43. History and Significance This	e. A one story addition on the north side primary facade. The addition is windowles ge bay. The older three story section of this canted to conform to its site. Windows ines the parapet, and shield medallions are Many of the entrances and windows on the find building was constructed as a warehouse for Company. The date of the addition is undoc	thwest corner of East of the original as and contains the building is are multipaned. e placed centrally irst story have been or Westinghouse Elec-

45 Sources of Information

Kansas City Star, March 14, 1948, p. 12D

WP #74943

BP #13839

Kansas City Star, March 14, 1948, p. 12D

Western Contractor, Nov. 7, 1923, p. 40.

46. Prepared by Piland / Uguccioni
47. Organization
Landmarks Commission
48. Date 49. Revision Date(s)
7/28/83





48. Date 49. Revision Date(s)

2/15/82

4 Present Name(s)

1. No. 201-B	4. Pre	4. Present Name(s)		
	An	Annex Building		
2 County			tered	
Jackson  3 Location of Negatives MT	#70-3	5 Other Name(s) Trinity Lutheran Nursing School Dormitory		
Landmarks Commission	n Tr			
6 Specific Location 2943 Wyandotte		16. Thernatic Category	28. No. of Stories 4	
			29. Basement? Yes	
		17 Date(s) or Period	No I	
7 City or Town . If Bural Township & Vicinity		18 Style or Design	30. Foundation Material stone; concrete	
7 City or Town If Aural, Township & Vicinity Kansas City, Missouri		To Style of Design	31. Wall Construction	
B. Site Plan with North Arrow		19. Architect or Engineer		
		Emil O Bayerl	32. Roof Type & Material	
Wyandothe		20. Contractor or Builder Brunn Const. Co.	flat; tar & gravel	
		21. Original Use, if apparent	Front Side	
		nurse's dormitory	34. Wall Treatment	
		22. Present Use	brick: metal	
		hospital	35. Plan Shape T  36. Changes Addition : Section Altered : Section Altered : Section Moved : Section S	
		23 Ownership Public   Private	36. Changes Addition : 2	
		24. Owner's Name & Address,	in #42) Moved	
		if known	37. Condition	
9. Coordinates UTM Lat. Long.			Interior	
			Exterior good	
	Charatura	25. Open to Yes II Public? No II	38. Preservation Yes Underway? No X	
10. Site!: Building L	Structure   Object	26. Local Contact Person or Organization	39. Endangered? Yes	
11. On National Yes   12 Is It Yes		Landmarks Commission	By What? No 🕮	
Register? No 11 Eligible? No 11		27. Other Surveys in Which Included		
Hist. Dist.? No [1]	14 District Yes i Potent'1? No :		40. Visible from Yes xx Public Road? No 11	
15. Name of Established District			41. Distance from and	
			Frontage on Road 105 feet on Wyandotte	
		he main entrance to this building		
The wing that project the rows of windows.  43. History and Significance	ts to the west  Work was star	ick walls, with metal canopies pro- features a metal grid with metal sp ted on this 100 capacity nurses don construction strikes, finally beir	pandrels running below	
The building is current administrative office	ces.	Trinity Lutheran Hospital for clini  Trinity Lutheran Hospital is to the state of the trinity to the east is the state of the state of the east is the	ics, laboratories, and ne south. To the west	
45 Sources of Information		-	46. Prepared by	
WP #123612	8	Piland		
BP #18993 Kansas City Star, A	ug 20 1960		47. Organization	
Mulious CILY Stal, P	Landmarks Commission			

State Historical Sur v and Planning Office, 909 University Avenue, Suite 215,



Kansas City Star, Jan 15, 1911; Aug. 10, 1969; Jan. 9, 1966.

Kansas City Star, Oct. 25, 1931; Jan. 11, 1970, p.12I; March 15, 1981

Kansas City Star, March 20, 1965; Aug. 8, 1971; May 7, 1973

Kansas City Star, March 30, 1968

Kansas City Star, March 24, 1968

JA-AS-008-1582

Historic Inventory 3009-11 Wyandotte

#42 continued.


The \$18 million addition of 90,000 square feet was completed in 1983. The 1954 entrance was demolished to accommodate this latest expansion. The exterior walls of this latest addition consist of precast, textured concrete panels. Red tile forms a string course beneath the horizontal windows bands.

#43 continued.

Radotinsky, Deardorff & Associates were architects for the 1966-68 east wing; the Swenson Construction Company was the contractor. Howard-Needles-Tammen & Bergendoff were architects for the 1969-73 north wing; contractor was the Bennett Construction Company. The same architecture and construction firms were responsible for the 1981-83 addition.



1 West 3151 Street facade



1 Bultimore Facade