KNASOQI-OOI KNOX COUNTY Edina

Site Data Form 170A-1

Rec. 3-4-70

Date of Inspection 2-22-1970

Please type or print in ink: 1. Site Name Old Edina Sentinel Building + Methodist church 2. Site Location a. County Knox______,Section______,Township______,Range b. Town Edina ,Street & Number corner of Main + Morgan 3. Present Owner F. E. Schoffeld Estate - Methodist Church Address Edina Mo 4. Present Use of Site Storage church Building Historic Use of Site 5. Approximate Date of Construction Before 1868 9-20-1898 6. Identification Photograph: Number enclosed Date exposed 2-22-70 Please label reverse side with site name, location, the compass point of view, the photographer's name and date photograph was taken. Photographer's name Junior Wilkerson Address Novelty MO 63460 7. Construction: a) Wall material stone _____brick _____ wood frame_____ other (specify) b) Present condition very good state of repair X fair poor much altered ruins_ 8. References: a) Local Histories b) County Historical Atlas 1916 ATLas -1916 ATLas c) Local libraries and librarians (give name and address) 9. Site is Important Because 10. Site Inspector's Name Junion Wilherson



MISSOURI STATE PARK BOARD MISSOURI STATE HISTORICAL SURVEY

Number - 4 - KNASOOI-COZKNOX County Edina Rec. 3-4-70

Site Data Form 170A-1

Plea	ise type or print in ink:
1.	Site Name Edins Austren
2.	Site Location HNOX a. County ,Section ,Township ,Range,
	b. Town Edina ,Street & Number Main
3.	Present Owner Edina Auction Co
	Address Edina Mo
4.	Present Use of Site Sale Barn.
	Historic Use of Site
5.	Approximate Date of Construction After 1897 Before 1916
6.	Identification Photograph: Number enclosed
	Please label reverse side with site name, location, the compass point of view, the photograph rapher's name and date photograph was taken.
	Photographer's name tunior Wilkerson
	Address Novelty Mo
7.	Construction: a) Wall material stone brick X wood frame X other (specify)
	b) Present condition very good state of repair fair X
	poor much altered ruins
8.	References: a) Local Histories
	b) County Historical Atlas
	c) Local libraries and librarians (give name and address)
9.	Site is Important Because they made boths of wagons and Buggies
	Sere,
10.	Site Inspector's Name (J. Willerson)



Site Data Form 170A-1

KNOX COUNTY Ru. 3.4-70

Date of Inspection 2-22-70

Please type or print in ink: a catholic church 2. Site Location a. County h may ,Section ,Township ,Range b. Town Edina ,Street & Number corner of Main ISmallwood 3. Present Owner <u>Catholie church</u> Address 4. Present Use of Site church Building Historic Use of Site 5. Approximate Date of Construction 18 7.3 6. Identification Photograph: Number enclosed / Date exposed 2-22-70 Please label reverse side with site name, location, the compass point of view, the photographer's name and date photograph was taken. Photographer's name Junior Wilkerson Address Novelty Mo 7. Construction: a) Wall material stone brick X wood frame other (specify) b) Present condition very good state of repair X fair poor____much altered___ruins____ 8. References: a) Local Histories______ b) County Historical Atlas 1876 - 1897 - 1916 c) Local libraries and librarians (give name and address)_____ 9. Site is Important Because 10. Site Inspector's Name with Wilberson



KNOW COUNTY Edina Rec. 3-4-70

Site Data Form 170A-1

P1e	ase type or print in ink:
1.	site Name The old winter bottom woolen Mills Building
2.	Site Location
	a. County Knox ,Section ,Township ,Range
	b. Town Edina , Street & Number corner of Main + Front
3.	Present Owner Hirner
	Address Edina, MO
4.	Present Use of Site Storage up Stairs - Auto parts store Bebw
	Historic Use of Site
5.	Approximate Date of Construction BeFore. 1879 -
6.	Identification Photograph: Number enclosed / Date exposed 2-22-70
	Please label reverse side with site name, location, the compass point of view, the photographer's name and date photograph was taken.
	Photographer's name funior Wilherson Address Novelty, mo
	Address Norelty, mo
7.	Construction: a) Wall material stone brick X wood frame
	other (specify)
	b) Present condition very good state of repair X fair
	poormuch alteredruins
8.	References: a) Local Histories
	b) County Historical Atlas
	c) Local libraries and librarians (give name and address)
9.	Site is Important Because It was and has been the only woolen mill
	site is Important Because It was and has been the only woolen mill in Knoy county - the Brishs were made in Southwest part of
	Edving at the parker Brick plant-
10	Edving at the packer Brich plant. Site Inspector's Name Junior Wilberry



b. Town Edina ,Street & Number public Square 3. Present Owner	Ple	ase type or print in ink:
2. Site Location a. County knox ,Section ,Township ,Range b. Town Edina ,Street & Number public Square 3. Present Owner	1.	site Name Knox county court House
b. Town Edina		,
Address 4. Present Use of Site		a. County Knox ,Section ,Township ,Range
Address 4. Present Use of Site		b. Town Edin's ,Street & Number public Square
Address 4. Present Use of Site	3.	·
Historic Use of Site Knex county Historical Society Museum in one Noom- 5. Approximate Date of Construction /934 6. Identification Photograph: Number enclosed / Date exposed 2-22-70 Please label reverse side with site name, location, the compass point of view, the photographer's name and date photograph was taken. Photographer's name Junior Wilkerson Address Novelty Mo 7. Construction: a) Wall material stone brick X wood frame other (specify) b) Present condition very good state of repair X fair poor much altered ruins 8. References: a) Local Histories b) County Historical Atlas c) Local libraries and librarians (give name and address) 9. Site is Important Because		,
5. Approximate Date of Construction 1934 6. Identification Photograph: Number enclosed / Date exposed 2-22-70 Please label reverse side with site name, location, the compass point of view, the photographer's name and date photograph was taken. Photographer's name / Junior Wilherson Address / Novelty / Mo 7. Construction: a) Wall material stone brick X wood frame	4.	
5. Approximate Date of Construction 1934 6. Identification Photograph: Number enclosed / Date exposed 2-22-70 Please label reverse side with site name, location, the compass point of view, the photographer's name and date photograph was taken. Photographer's name / Junior Wilherson Address / Novelty / Mo 7. Construction: a) Wall material stone brick X wood frame		Historic Use of Site Knox county Historical Society Museum in
6. Identification Photograph: Number enclosed / Date exposed 2-22-70 Please label reverse side with site name, location, the compass point of view, the photographer's name and date photograph was taken. Photographer's name	5.	Approximate Date of Construction 1934
rapher's name and date photograph was taken. Photographer's name		
Address Novelty Mo 7. Construction: a) Wall material stone brick X wood frame other (specify) b) Present condition very good state of repair Xfair poor much altered ruins 8. References: a) Local Histories b) County Historical Atlas c) Local libraries and librarians (give name and address) 9. Site is Important Because		Please label reverse side with site name, location, the compass point of view, the photographer's name and date photograph was taken.
7. Construction: a) Wall material stone brick wood frame other (specify) b) Present condition very good state of repair fair poor much altered ruins		Photographer's name Junior Wilherson
b) Present condition very good state of repair X fair poormuch alteredruins 8. References: a) Local Histories b) County Historical Atlas c) Local libraries and librarians (give name and address) 9. Site is Important Because		Address Novelty Mo
b) Present condition very good state of repair X fair poormuch alteredruins 8. References: a) Local Histories b) County Historical Atlas c) Local libraries and librarians (give name and address) 9. Site is Important Because	7.	Construction: a) Wall material stone brick X wood frame
poormuch alteredrwins		other (specify)
8. References: a) Local Histories b) County Historical Atlas c) Local libraries and librarians (give name and address) 9. Site is Important Because		b) Present condition very good state of repair $oldsymbol{\mathcal{X}}$ fair
b) County Historical Atlas_ c) Local libraries and librarians (give name and address) 9. Site is Important Because		poor much altered ruins
b) County Historical Atlas c) Local libraries and librarians (give name and address) 9. Site is Important Because	8.	References: a) Local Histories
c) Local libraries and librarians (give name and address) 9. Site is Important Because		
9. Site is Important Because		b) County Historical Atlas
		c) Local libraries and librarians (give name and address)
10. Site Inspector's Name Junior Wilherson	ġ.	Site is Important Because
10. Site Inspector's Name Junior Wilherson		
10. Site Inspector's Name Junior Wilherson		
	10	. Site Inspector's Name Junior Wilherson

KNAS001-005

Research: Glen Hartley

April, 1972

Knox County
Edina, Mo.

Courthouse of 1935


This brick building has two floors with a recessed entrance area. This area is divided by pilasters into five bays, the second floor with round topped windows and the door in the center bay on the ground floor has a pediment. The roof is flat with a closed balustrade over the entrance area.

DATE: 1935 ARCHITECT: BUILDER: COST: SIZE:

MATERIAL: Brick

Style: Beaux Arts Classicism





MISSOURI STATE PARK BOARD MISSOURI STATE HISTORICAL SURVEY

Site Data Form 170A-1

Number - 3 KNASCCI-COL KNOX COUNTY

NOVELTY

Rec. 3-4-70

Ple	ase type or print in ink:
1.	site Name Novelty christian church
	Site Location
	a. County Knox ,Section ,Township ,Range_
	b. Town Novelty ,Street & Number State St.
3.	Present Owner
	Address
4.	Present Use of Site church Building
	Historic Use of Site
5.	Approximate Date of Construction 1898
6.	Identification Photograph: Number enclosed / Date exposed 1-22-70
	Please label reverse side with site name, location, the compass point of view, the photographer apher and date photograph was taken.
	Photographer's name Junion Wilkerson
	Address Novelty MO
7.	Construction: a) Wall material stone brick wood frame X
	other (specify)
	b) Present condition very good state of repair χ fair
	poor much altered ruins
8.	References: a) Local Histories
	b) County Historical Atlas
	c) Local libraries and librarians (give name and address)
9.	Site is Important Because
10	. Site Inspector's Name Junior Wilherson.



MISSOURI STATE PARK BOARD
MISSOURI STATE HISTORICAL SURVEY Number-1-

Site Data Form 170A-1

KNASOCI-COT KNOX COUNTY
NOUGLTY

Rec. 3-4-70

Date of Inspection 2-22-70

Please type or print in ink: 1. Site Name Rinehart House 2. Site Location a. County Knox ,Section 29 ,Township 60 ,Range 12 W b. Town_______,Street & Number_____ 3. Present Owner W. F. Augutt Address Novelty 4. Present Use of Site Home Historic Use of Site 5. Approximate Date of Construction about 1845 6. Identification Photograph: Number enclosed / Date exposed 2-21-70 Please label reverse side with site name, location, the compass point of view, the photographer's name and date photograph was taken. Photographer's name B Junior Wilkerson Address Novelty Mo 7. Construction: a) Wall material stone _____brick _____ wood frame_____ other (specify) b) Present condition very good state of repair X fair poor much altered ruins 8. References: a) Local Histories None b) County Historical Atlas None c) Local libraries and librarians (give name and address) None 9. Site is Important Because The time it was Built and has Bean in The Rinehart Family Senee 1852 - Now owned By The Fifth Generation, the House and 1200 Acres of Land Was Bought in 1852 For 5000.00 By Abraham Rinehart - The Cover)
10. Site Inspector's Name Junior Wieberson



MISSOURI STATE PARK BOARD
MISSOURI STATE HISTORICAL SURVEY

Number - 2 - KICHCCOL-COE KNOX COUNTY
Rec. 3-4-70

Site Data Form 170A-1

	Date of Inspection 2-12-70
Ple	ase type or print in ink:
1.	Site Name Eucebis church
2.	Site Location
	a. County Knox ,Section 29 ,Township 60 ,Range 12 W
	b. Town,Street & Number
3.	Present Owner
	Address
4.	Present Use of Site church Building
	Historic Use of Site
5.	Approximate Date of Construction 1875
6.	Identification Photograph: Number enclosed / Date exposed 2-22-70
	Please label reverse side with site name, location, the compass point of view, the photographer's name and date photograph was taken.
	Photographer's name Junio- Wilkerson
	Address Novelty Mo
7.	Construction: a) Wall material stone brick wood frame
	other (specify)
	b) Present condition very good state of repair X fair
	poor much altered ruins
8.	References: a) Local Histories None
	b) County Historical Atlas None
	c) Local libraries and librarians (give name and address) worke
9.	Site is Important Because Land Donaled for site By Abraham Rivehau
	Site is Important Because Land Donaled for site By Abraham Rinsham and church built just Like The Eucebia church in
	Virginia -
10	. Site Inspector's Name Jurior Wilherson -

