SLCA5013-001

1.	No. 011	3. Location of Negatives: Landmarks Association of St. Louis, Inc., 917 Locust, St. Louis, MO 63101	
2.	City/County: City of St. Louis, MO	4. Prepared by: Cynthia Longwisch & Mary M. Stiritz, Landmarks Association of St. Louis, Inc.	
5.	Date: 11/90	6. Sources of information: St. Louis Public Records,	
7.	Building? Yes	City Hall; St. Louis Public Library; MO Historical Soc.	
9.	Ownership:	8. On National Register or part of estab. district? No	
<i>J</i> .	Private	10. Visible from public road? Yes 11. Endangered? No	
12.	Street address:	2217 N. First 13. Style: commercial/industrial	
14.	Date(s): 10/18/1888; 1908; 1916		
15.	. Architect: 16. Builder:		
17.	Original Use: foundry 18. Present Use: warehouse		
19.	Owner's name/address if known: Krane-Garrick Manufacturing Co., 2224 2nd		
20.	No. of stories: 2 21. Basement? unk. 22. Wall construction: masonry		
23.	23. Foundation material: limestone 24. Roof type/material: fl		
25.	No. Bays: Front 17 Side 25 25. Wall treatment: red brick		
26.	Plan shape: L	27. Changes: Addition? yes Altered? yes	
28.	Exterior condit	ion: fair 29: Open to public? no	
30.		n which included: St. Louis Harbor Historic Properties 1987, U.S. Army Corps of Engineers survey (partially incl.	

- 31. Further description of important features: Double-rowlock segmentally arched windows with stone sills are infilled; recessed panels topped with dentilling divide them into pairs on the east elevation. A concrete loading dock with a frame and iron overhang extends both lengths of the building. The western part of the L is flat-roofed.
- 32. History and Significance: The Ranken & Fritsch Foundry Company took out a building permit in 1888 for \$3,000 for a one-story foundry building. The building was later bought by the Foundry Inv. Co. who took out permits to alter the building in 1908 (for \$350 and \$1800) and in 1916 (for \$2600). The original building probably was gabled, with the flat-roofed portion coming at one of the later dates, along with the upper story.



5LCA5013-002

1.	No. 147	3. Location of Negatives: Landmarks Association of St. Louis, Inc., 917 Locust, St. Louis, MO 63101	
2.	City/County: City of St. Louis, MO	4. Prepared by: Cynthia Longwisch & Mary M. Stiritz, Landmarks Association of St. Louis, Inc.	
5.	Date: 11/90	6. Sources of information: St. Louis Public Records,	
7.	Building? Yes	City Hall; St. Louis Public Library; MO Historical Soc. 8. On National Register or part of estab. district? No	
9.	Ownership: Private	8. On National Register or part of estab. district? No 10. Visible from public road? Yes 11. Endangered? No	
12.	Street address:	4023 N. First 13. Style: vernacular	
14.	Date(s): 7/3/1937		
15.	Architect: 16. Builder:		
17.	Original Use: commercial 18. Present Use: commercial		
19.	Owner's name/address if known:		
20.	. No. of stories: 1 21. Basement? yes 22. Wall construction: frame		
23.	. Foundation material: concrete 24. Roof type/material: end gable		
25.	No. Bays: Front 2 Side 3 25. Wall treatment: asphalt siding		
26.	Plan shape: rectangular 27. Changes: Addition? yes Altered?		
28.	Exterior condit	ion: poor 29: Open to public? no	
30.	_	n which included: St. Louis Harbor Historic Properties 1987, U.S. Army Corps of Engineers survey (partially incl.)	

31. Further description of important features: Very modest frame building has an asphalt-shingled roof and rectangular wood-framed windows. A frame rear addition is sheeted with corrugated iron.

^{32.} History and Significance: This building was built by the Terminal Rail-road Association in 1937. It is located a few feet away from a railroad siding.



NORTH BEOADWAY INDUSTRIAL SURVEY II 4023 N. FIRST FACING SW

ST. LOUIS, MO

1.	No. 146	3. Location of Negatives: Landmarks Association of St. Louis, Inc., 917 Locust, St. Louis, MO 63101		
2.	City/County: City of St. Louis, MO	4. Prepared by: Cynthia Longwisch & Mary M. Stiritz, Landmarks Association of St. Louis, Inc.		
5.	Date: 11/90	6. Sources of information: St. Louis Public Records, City Hall; St. Louis Public Library; MO Historical Soc.		
7.	Building? Yes			
9.	Ownership: Private	8. On National Register or part of estab. district? No 10. Visible from public road? Yes 11. Endangered? No		
12.	Street address:	4028-30 N. First 13. Style: industrial		
14.	Date(s): 10/2/1918			
15.	Architect: 16. Builder: J. Charles Mueller			
17.	Original Use: industrial 18. Present Use: industrial			
19.	Owner's name/address if known: Herman Oak Leather Co.			
20.	No. of stories: 2 21. Basement? unk. 22. Wall construction: masonry			
23.	Foundation material: concrete 24. Roof type/material: flat			
25.	No. Bays: Front 3 Side 2 25. Wall treatment: red brick			
26.	Plan shape: rectangular 27. Changes: Addition? Altered? yes			
28.	Exterior condition: good 29: Open to public? no			
30.		which included: St. Louis Harbor Historic Properties 1987, U.S. Army Corps of Engineers survey (partially incl.)		

Further description of important features: Openings have double-rowlock segmental arches, many of which are infilled with brick. North roofline is slightly stepped.

History and Significance: The Herman Oak Leather Co. took out the permit for \$3,500 to build this building in 1918 as part of his tannery complex. company had been operating in this city block since 1888; a frame tannery building was in use across the street by Herman 1886. The complex is still in use as a tannery today.



NORTH BROADWAY INDUSTRIAL SURVEY IL FACING

SLCA5013-004

1.	No. 145	 Location of Negatives: Landmarks Association of St. Louis, Inc., 917 Locust, St. Louis, MO 63101 		
2.	City/County: City of St. Louis, MO	4. Prepared by: Cynthia Longwisch & Mary M. Stiritz, Landmarks Association of St. Louis, Inc.		
5.	Date: 11/90	6. Sources of information: St. Louis Public Records, City Hall; St. Louis Public Library; MO Historical Soc.		
7.	Building? Yes			
9.	Ownership:	8. On National Register or part of estab. district? No		
	Private	10. Visible from public road? Yes 11. Endangered? No		
12.	Street address:	4044 N. First 13. Style: commercial		
14.	Date(s): 5/9/1901			
15.	Architect: Otto J. Wilhelmi 16. Builder: J. Charles Mueller & Co.			
17.	Original Use: warehouse 18. Present Use: warehouse			
19.	Owner's name/address if known: Herman Oak Leather Co.			
20.	No. of stories: 2 21. Basement? yes 22. Wall construction: masonry			
23.	Foundation material: limestone 24. Roof type/material: flat			
25.	No. Bays: Front 6 Side 25. Wall treatment: red brick			
26.	Plan shape: rectangular 27. Changes: Addition? yes Altered? yes			
28.	Exterior condit	ion: good 29: Open to public? no		
30.	_	n which included: St. Louis Harbor Historic Properties 1987, U.S. Army Corps of Engineers survey (partially incl.		

- 31. Further description of important features: A series of small vents with tiny stone hoods runs across the building at the attic; a corbelled cornice extends below. Original arches of second-story windows appear to have been altered; they now have flat arches and brick sills, with the same one-over-two-over-one horizontally hinged panes as are found in the building (cont'd. below)
- 32. History and Significance: to the north. First-story openings have been infilled with brick; double-rowlock segmental arches are still visible. A loading dock bay is located in the south end. The building is attached to a one-story building on the north and a newer brick building on the south. The permit for this building was taken out by Herman Koenitzer in 1901 for \$4,000 for a warehouse for his Herman Oak Leather tannery, a concern still operating on this site.



ARCHITECTURAL/HISTORIC INVENTORY SURVEY FORM SLCASO/3-005

1.	No. 144	3. Location of Negatives: Landmarks Association of St. Louis, Inc., 917 Locust, St. Louis, MO 63101	
2.	City/County: City of St. Louis, MO	4. Prepared by: Cynthia Longwisch & Mary M. Stiritz, Landmarks Association of St. Louis, Inc.	
5.	Date: 11/90	6. Sources of information: St. Louis Public Records,	
7.	Building? Yes	City Hall; St. Louis Public Library; MO Historical Soc. 8. On National Register or part of estab. district? No	
9.	Ownership: Private	10. Visible from public road? Yes 11. Endangered? No	
12.	Street address:	4054 N. First 13. Style: industrial	
14.	Date(s): 7/26/1888		
15.	Architect: 16. Builder:		
17.	Original Use: tannery 18. Present Use: tannery		
19.	Owner's name/address if known: Herman Oak Leather Co.		
20.	No. of stories: 3 21. Basement? yes 22. Wall construction: masonry		
23.	Foundation material: limestone 24. Roof type/material: flat		
25.	No. Bays: Front 10 Side 25. Wall treatment: red brick		
26.	Plan shape: rectangular 27. Changes: Addition? yes Altered? yes		
28.	Exterior condit	ion: good 29: Open to public? no	
30.		which included: St. Louis Harbor Historic Properties 1987, U.S. Army Corps of Engineers survey (partially incl.)	

31. Further description of important features: A deeply corbelled cornice is interrupted by pilasters dividing the facade. Triple-rowlock segmental arches top brick-silled windows. One-over-two-over-one windows are horizontally hinged (see photo). Openings at the first story have been infilled with brick to fit smaller panes. Two-story brick addition attached to south side.

History and Significance: Herman Koenitzer took out the permit in 1888 to build a \$5,000 tannery. The company became known as the Herman Oak Leather Co. and operates in this building today. No other information could be found on Koenitzer.



54CAS013-006

1.	No. 010	3. Location of Negatives: Landmarks Association of St. Louis, Inc., 917 Locust, St. Louis, MO 63101	
2.	City/County: City of St. Louis, MO	4. Prepared by: Cynthia Longwisch & Mary M. Stiritz, Landmarks Association of St. Louis, Inc.	
5.	Date: 11/90	6. Sources of information: St. Louis Public Records,	
7.	Building? Yes	City Hall; St. Louis Public Library; MO Historical So	
9.	Ownership: Private	8. On National Register or part of estab. district? 10. Visible from public road? Yes 11. Endangered?	
12.	Street address:	2224 N. Second 13. Style: commercial	
14.	Date(s): 5/3/1881		
15.	Architect: 16. Builder:		
17.	Original Use: storehouse 18. Present Use: warehouse		
19.	Owner's name/address if known: Krane-Garrick Manufacturing Co.		
20.	No. of stories: 2 21. Basement? no 22. Wall construction: masonry		
23.	Foundation material: stone 24. Roof type/material: end gable/aspl		
25.	No. Bays: Front 8 Side 11 25. Wall treatment: red brick		
26.	Plan shape: rec	angular 27. Changes: Addition? Altered? y	
28.	Exterior condition: fair 29: Open to public? no		
30.	_	which included: St. Louis Harbor Historic Properties 1987, U.S. Army Corps of Engineers survey (partially in	
31.	Further descrip	on of important features: Parapeted gable end is step	

- with a slant on the north side and straight on the south; center and south sections have corbelled brick cornices. Double rowlock segmentally arched windows with stone sills are mostly infilled with brick or concrete block. Round arches top the two outside bays in the primary elevation. Loading dock on north side.
- 32. History and Significance: Smith, Beggs & Ranken were given a building permit for a \$4,000 storehouse in 1881. No firm by this name could be located, although the foundry of Ranken & Fritsch was located adjoining this building after 1888. C. H. Beggs and David Ranken were two St. Louisans of money and position about this time and possibly funded the undertaking for speculation.



FACING SE

SLCAS013-007

1.	No. 056	3. Location of Negatives: Landmarks Association of St. Louis, Inc., 917 Locust, St. Louis, MO 63101	
2.	City/County: City of St. Louis, MO	4. Prepared by: Cynthia Longwisch & Mary M. Stiritz, Landmarks Association of St. Louis, Inc.	
5.	Date: 11/90	6. Sources of information: St. Louis Public Records,	
7.	Building? Yes	City Hall; St. Louis Public Library; MO Historical Soc.	
α	Ouronahin	8. On National Register or part of estab. district? No	
9.	Ownership: Private	10. Visible from public road? Yes 11. Endangered? No	
12.	Street address:	3014 N. Second 13. Style: commercial	
14.	Date(s): c. 1900		
15.	Architect: 16. Builder:		
17.	Original Use: commercial 18. Present Use: commercial		
19.	Owner's name/address if known: Diversified Foam Products		
20.	No. of stories: 3 21. Basement? yes 22. Wall construction: masonry		
23.	Foundation material: stone 24. Roof type/material: flat		
25.	No. Bays: Front 8 Side 17 25. Wall treatment: brown brick		
26.	Plan shape: L 27. Changes: Addition? yes Altered? yes		
28.	Exterior condit	ion: fair 29: Open to public? limited	
30.		n which included: St. Louis Harbor Historic Properties 1987, U.S. Army Corps of Engineers survey (partially incl.)	

31. Further description of important features: Building has a corbeled cornice and a small parapet on the north elevation. Double rowlock segmental arches and brick sills; almost all windows have been infilled in the western half of this building. Small pedimented entry of buff terra cotta at the n.w. corner has acanthus leaf-consoles and reads, "BILT WELL MILL WORK."

^{32.} History and Significance: All inactive building permits and active permits before 1963 are missing for this city block. No information could be found on Bilt Well.



Location of Negatives: Landmarks Association of

3.

1.

No. 079



1.	NO. 0/3	St. Louis, Inc., 917 Locust, St.			
2.	City/County: City of St.	4. Prepared by: Cynthia Longwisch &	Mary M. Stiritz,		
	Louis, MO	Landmarks Association of St. Loui	ls, inc.		
5.	Date: 11/90		6. Sources of information: St. Louis Public Records, City Hall; St. Louis Public Library; MO Historical Soc.		
7.	Building? Yes				
9.	Ownership: Private	8. On National Register or part of estab. district? No 10. Visible from public road? Yes 11. Endangered? No			
12.	Street address:	3201-03 N. Second 13. Style: comm	nercial		
14.	Date(s): 7/18/	1910			
15.	Architect: 16. Builder:				
17.	Original Use: commercial 18. Present Use: warehouse				
19.	Owner's name/address if known:				
20.	No. of stories: 2 21. Basement? yes 22. Wall construction: masonry				
23.	Foundation material: stone 24. Roof type/material: low-hipped		rial: low-hipped		
25.	No. Bays: Front 4 Side 8 25. Wall treatment: red brick		: red brick		
26.	Plan shape: rec	tangular 27. Changes: Addition?	yes Altered? yes		
28.	Exterior condit	ion: fair 29: Open to public	c? no		
30.	-	n which included: St. Louis Harbor Hist 1987, U.S. Army Corps of Engineers surv	_		
rema gina (s.	in at the southed windows of the & e. elevations)	tion of important features: A cast-iron ast corner; concrete block infill has observed and a cast-iron sill and first-salso remain. The other entrances and will be a cast-iron sill and silved with wood or CMU. A garage bay is	bliterated the ori- story lintel course indows have flat		

^{32.} History and Significance: located at the north end of the front elevation. A corbelled cornice beneath the wide overhanging eaves is the main ornament left on the building. The permit for this "store & dwelling" was taken out by William A. Meinhart in 1910. It appears that the original plan housed two residential units, judging from the two rear doors and the reference to the building being a "double" in the building permit.



SCC45013-009

1.	No. 156	i		egatives: Landmark c., 917 Locust, St	
2.	City/County: City of St. Louis, MO	· ·	4. Prepared by: Cynthia Longwisch & Mary M. Stiritz, Landmarks Association of St. Louis, Inc.		
5.	Date: 11/90	6. Sources of information: St. Louis Public Records, City Hall; St. Louis Public Library; MO Historical Soc.			
7.	Building? Yes				
9.	Ownership:	8. On Nat	ional Re	egister or part of	estab. district? No
<i>J</i> .	Private	10. Visible	e from p	public road? Yes	11. Endangered? No
12.	Street address:	4138 N. Sec	ond	13. Style: co	mmercial
14.	Date(s):				
15.	Architect: 16. Builder:				
17.	Original Use: commercial 18. Present Use: commercial				
19.	Owner's name/address if known: OK Trucking Co.				
20.	No. of stories: 1 21. Basement? unk. 22. Wall construction: masonr		construction: masonry		
23.	Foundation material: limestone 24. Roof type/material: flat		erial: flat		
25.	No. Bays: Front 4 Side 3 25. Wall treatment: painted brick		t: painted brick		
26.	Plan shape: rectangular 27. Changes: Addition? yes Altered?		yes Altered?		
28.	Exterior condit	ion: fair		29: Open to publ	ic? limited
30.	Other Surveys is Reconnaissance,			t. Louis Harbor Hi ps of Engineers su	storic Properties rvey (partially incl.)

31. Further description of important features: A round-arched, recessed entrance draws the visual interest of this facade. Double-rowlock segmentally-arched windows have been infiled with glass brick and small windows; brick sills. A one-story CMU addition is located at the rear. The building is connected to a larger, newer commercial building.


32. History and Significance:



150

NORTH BROADWAY INDUSTRIAL SURVEY II. 4138 N. SECOND FACING SE

97, LOUIS, MO 9/90



(cont'd. below)

1.	No. 162	3. Location of Negatives: Landmarks Association of St. Louis, Inc., 917 Locust, St. Louis, MO 63101	
2.	City/County: City of St. Louis, MO	4. Prepared by: Cynthia Longwisch & Mary M. Stiritz, Landmarks Association of St. Louis, Inc.	
5.	Date: 11/90	6. Sources of information: St. Louis Public Records, City Hall; St. Louis Public Library; MO Historical Soc.	
7.	Building? Yes		
9.	Ownership: Private	8. On National Register or part of estab. district? No 10. Visible from public road? Yes 11. Endangered? No	
12.	Street address:	4205 N. Second 13. Style: commercial	
14.	Date(s): 4/19/	1907	
15.	Architect:	16. Builder: Charles Gescheidt	
17.	Original Use: factory 18. Present Use: warehouse/for sale		
19.	Owner's name/address if known:		
20.	No. of stories:	2 21. Basement? yes 22. Wall construction: masonry	
23.	Foundation material: concrete 24. Roof type/material: flat		
25.	No. Bays: Front 1 Side 8 25. Wall treatment: painted brick		
26.	Plan shape: irregular L 27. Changes: Addition? Altered? yes		
28.	Exterior condition: good 29: Open to public? no		
30.	_	n which included: St. Louis Harbor Historic Properties 1987, U.S. Army Corps of Engineers survey (partially incl.)	
	roofline of this	tion of important features: Terra cotta coping rims the s functional building. Windows have flat arches, the larger t story have been enframed with concrete and sized down with	

probable that the other windows were originally segmentally

brick infill.

Some bricked-in segmentally-arched openings are visible; it is

^{32.} History and Significance: arched as well. Several sliding loading dock doors. The permit for this building was taken out in 1907 by the Union Cooperage Co. for \$5,000. The company was established in 1862 and incorporated in 1886. Their frame factory stood on this site at least as early as 1883 (see Hopkins map). They built kegs, half barrels and barrels, well buckets, harvest kegs, and "patented all wood and porcelain enameled water coolers," according to their city directory listing. Here in 1930, they were gone by 1940.



162

4205 N. SECOND

57. LEUIS, MO 9/90

SLC 45013-011

1.	No. 161	 Location of Negatives: Landmarks Association of St. Louis, Inc., 917 Locust, St. Louis, MO 63101 		
2.	City/County: City of St. Louis, MO	4. Prepared by: Cynthia Longwisch & Mary M. Stiritz, Landmarks Association of St. Louis, Inc.		
5.	Date: 11/90	6. Sources of information: St. Louis Public Records, City Hall; St. Louis Public Library; MO Historical Soc.		
7.	Building? Yes			
9.	Ownership:	8. On National Register or part of estab. district? No		
Э.	Private	10. Visible from public road? Yes 11. Endangered? No		
12.	Street address:	4209-11 N. Second 13. Style: vernacular		
14.	Date(s): c. 1875			
15.	Architect: 16. Builder:			
17.	Original Use: residential 18. Present Use: residential			
19.	Owner's name/address if known:			
20.	No. of stories: 1-1/2 21. Basement? yes 22. Wall construction: masonry			
23.	Foundation material: limestone 24. Roof type/material: side gable			
25.	No. Bays: Front 4 Side 4 25. Wall treatment: painted brick			
26.	Plan shape: rectangular 27. Changes: Addition? Altered? yes			
28.	Exterior condit	ion: good 29: Open to public? no		
30.	-	n which included: St. Louis Harbor Historic Properties 1987, U.S. Army Corps of Engineers survey (partially incl.)		

31. Further description of important features: North and south walls have parapeted chimneys. Windows have segmental soldier arches and stone sills. Two-over-two window panes. Two dormers. Two centered, transomed entrance doors, one of which is missing stone steps. Denticulated brick cornice. Rear wood porch.

^{32.} History and Significance: The permits for this city block go back as early as 1876, and no permit was recorded for this house. It is fairly clearly not on the 1875 Compton & Dry map, however; hence the c. date of 1875. (It does appear on the 1883 Hopkins map.) The building seems to have always been a residence.



|6| NORTH BROADWAY INDUSTRIAL SURVEY IN 4207-11 N. SECOND FACING SW

9/90

MISSOURI OFFICE OF HISTORIC PRESERVATION SLC ASO13-012

City/County: City of St. Louis, MO	St. Louis, Inc., 917 Locust, St. Louis, MO 63101 4. Prepared by: Cynthia Longwisch & Mary M. Stiritz, Landmarks Association of St. Louis, Inc.		
Date: 11/90	6. Sources of information: St. Louis Public Records,		
Building? Yes	City Hall; St. Louis Public Library; MO Historical Soc.		
Ownership: Private	8. On National Register or part of estab. district? No 10. Visible from public road? Yes 11. Endangered? No		
Street address:	2214-24 N. Ninth 13. Style: commercial		
Date(s): c. 1890s; 1903			
Architect: unknown 16. Builder: Ewald Becker			
Original Use: factory 18. Present Use: commercial			
Owner's name/address if known: Missouri Equipment Co., 2214-24 N. Ninth			
No. of stories: 1 21. Basement? unk. 22. Wall construction: masonry			
Foundation material: stone 24. Roof type/material: flat			
No. Bays: Front 14 Side 25. Wall treatment: painted brick			
Plan shape: rectangle 27. Changes: Addition? yes Altered? yes			
Exterior condit	ion: good 29: Open to public? limited		
	which included: St. Louis Harbor Historic Properties 1987, U.S. Army Corps of Engineers survey (partially incl.)		
	City of St. Louis, MO Date: 11/90 Building? Yes Ownership: Private Street address: Date(s): c. 189 Architect: unkr Original Use: f Owner's name/add No. of stories: Foundation mater No. Bays: Front Plan shape: rect Exterior condition Other Surveys in		

Terra cotta coping. May have originally been a two-story building (see below).

^{32.} History and Significance: An 1889 building permit for a \$2,500, 2-story warehouse was taken out by Charles Wunderlich for a location on the east side of Ninth. A permit dated 5/16/1903 was taken out by the St. Louis Enamel Works for \$3,240 to "alter enameling works," no story height specified. No other permit appears on file that could be for this building. Wunderlich operated a cooperage works at the south end of the block that possibly extended as far as 2214-24.



5LCAS013-013

MISSOURI OFFICE OF HISTORIC PRESERVATION ARCHITECTURAL/HISTORIC INVENTORY SURVEY FORM

1.	No. 002	3. Location of Negatives: Landmarks Association of St. Louis, Inc., 917 Locust, St. Louis, MO 63101					
2.	City/County: City of St. Louis, MO	4. Prepared by: Cynthia Longwisch & Mary M. Stiritz, Landmarks Association of St. Louis, Inc.					
5.	Date: 11/90	6. Sources of information: St. Louis Public Records,					
7.	Building? Yes	City Hall; St. Louis Public Library; MO Historical Soc.					
9.	Ownershin	8. On National Register or part of estab. district? No					
9.	Ownership: Private	10. Visible from public road? Yes 11. Endangered? No					
12.	Street address:	2307-11 N. Ninth 13. Style: commercial					
14.	Date(s): 11/5/1877						
15.	Architect: unk	nown 16. Builder: unknown					
17.	Original Use:	stable 18. Present Use: storage					
19.	Owner's name/address if known: Modern Screw Products, Inc., 2307-11 9th						
20.	No. of stories:	2 21. Basement? yes 22. Wall construction: masonry					
23.	Foundation mate	rial: limestone 24. Roof type/material: flat					
25.	No. Bays: Fron	t 12 Side 25. Wall treatment: red brick					
26.	Plan shape: rec	tangular 27. Changes: Addition? yes Altered? yes					
28.	Exterior condit	ion: fair 29: Open to public? no					
30.		n which included: St. Louis Harbor Historic Properties 1987, U.S. Army Corps of Engineers survey (partially incl.					

- 31. Further description of important features: This building appears to have been built in two or three sections, although only one permit was found. The north section features arched stone lintels and stone sills above; brick segmental arches and stone sills can be found below and in the remaining part of the building. Extensive brick infill has changed former stable door openings.
- 32. History and Significance: A \$600 building permit was taken out in 1877 by William Paschedag to build a two-story stable. The building was owned during the 1920s early 1940s by W. Doane of the Doane Carton Co. Doane used the building as a factory for his carton-manufacturing business. Later alteration permits indicate that the upper floor was also used as a residence during the early 20th century.



SLCA5013-014

1.	No. 019 3. Location of Negatives: Landmarks Association of St. Louis, Inc., 917 Locust, St. Louis, MO 63101						
2.	City/County: City of St. Louis, MO	4. Prepared by: Cynthia Longwisch & Mary M. Stiritz, Landmarks Association of St. Louis, Inc.					
5.	Date: 11/90	6. Sources of information: St. Louis Public Records,					
7.	Building? Yes	City Hall; St. Louis Public Library; MO Historical Soc.					
9.	Ownership: Private	8. On National Register or part of estab. district? No 10. Visible from public road? Yes 11. Endangered? No					
12.	Street address: 2500-08 N. Ninth 13. Style: industrial						
14.	Date(s): 11/16/1915						
15.	Architect: A. W. Albrecht 16. Builder:						
17.	Original Use: warehouse 18. Present Use: commercial						
19.	Owner's name/address if known: National Auto Supply						
20.	No. of stories:	2 21. Baseme	ent? no 22. Wall construction: masonry				
23.	Foundation mate	rial: brick	24. Roof type/material: flat				
25.	No. Bays: Fron	t 4 Side 9	25. Wall treatment: painted brick				
26.	Plan shape: rec	tangular 27.	Changes: Addition? Altered? yes				
28.	Exterior condit	ion: good	29: Open to public? limited				
30.	Other Surveys in which included: St. Louis Harbor Historic Properties Reconnaissance, 1987, U.S. Army Corps of Engineers survey (partially incl						
31. uppe			features: Windows have brick sills; all been infilled with plywood or corrugated				

fiberglas. Stepped parapet has terra cotta coping.

^{32.} History and Significance: Schoellhorn & Albrecht, "manufacturers in general machinery & supplies," took out the building permit for this warehouse in 1915 for \$6,000. H. S. Albrecht was president of the firm, A. W. Albrecht was vice president, and A. Schoellhorn was the secretary. The "St. Louis M. Co." owned the building in 1917, and International Harvester altered it for \$3,850, according to a permit dated 10/18/1923. The building was briefly a store in the early 1930s before becoming a warehouse again.



1.	No. 028	3. Location of Negatives: Landmarks Association of St. Louis, Inc., 917 Locust, St. Louis, MO 63101						
2.	City/County: City of St. Louis, MO	4. Prepared by: Cynthia Longwisch & Mary M. Stiritz, Landmarks Association of St. Louis, Inc.						
5.	Date: 11/90	6. Sources of information: St. Louis Public Records, City Hall; St. Louis Public Library; MO Historical Soc.						
7.	Building? Yes							
9.	Ownership:	8. On National Register or part of estab. district? No						
	Private	10. Visible from public road? Yes 11. Endangered? No						
12.	Street address: 2601-05 N. Ninth 13. Style: Classical Revival							
14.	Date(s): 4/19/1876; 6/8/1880							
15.	Architect: 16. Builder:							
17.	Original Use: residential 18. Present Use: residential							
19.	Owner's name/address if known:							
20.	No. of stories: 2-1/2 21. Basement? yes 22. Wall construction: masonry							
23.	Foundation mate	rial: stone 24. Roof type/material: side gabled						
25.	No. Bays: Fron	t 6 Side 3 25. Wall treatment: red brick						
26.	Plan shape: modif. rectang. 27. Changes: Addition? yes Altered? yes							
28.	Exterior condit	ion: fair/poor 29: Open to public? no						
30.	Other Surveys in which included: St. Louis Harbor Historic Properties Reconnaissance, 1987, U.S. Army Corps of Engineers survey (partially incl.							

Further description of important features: Projecting wood cornice returns at the south corner. It is highlighted by modillion blocks and dentils of wood. Second-story windows originally had segmental arches; several have been altered. First-story windows on the primary elevation originally had round arches. Three dormers. South wall has parapeted chimnies. North portion (cont'd below)

History and Significance: (2 bays) is vacant (burned?) and an additional portion on the north side has been demolished, leaving a jagged facade wall where it was attached. Stoops feature curved stone sidewalls. A. Hedekamp built this residence for \$2,400 in 1876. A. Wippern added the two-story rear kitchen addition for \$200 in 1880.



1.	No. 030	 Location of Negatives: Landmarks Association of St. Louis, Inc., 917 Locust, St. Louis, MO 63101 					
2.	City/County: City of St. Louis, MO	4. Prepared by: Cynthia Longwisch & Mary M. Stiritz, Landmarks Association of St. Louis, Inc.					
5.	Date: 11/90	6. Sources of information: St. Louis Public Records,					
7.	Building? Yes	City Hall; St. Louis Public Library; MO Historical Soc.					
9.	Ownership: Private	8. On National Register or part of estab. district? No 10. Visible from public road? Yes 11. Endangered? No					
12.	Street address: 2600-06 N. Ninth 13. Style: commercial/Moderne						
14.	Date(s): 10/1/1942						
15.	Architect: J. E. Tarling 16. Builder: Kloster Co.						
17.	Original Use: factory 18. Present Use: manufacturing warehouse						
19.	Owner's name/address if known: Porbeck Manufacturing Co.						
20.	No. of stories: 1 21. Basement? no 22. Wall construction: masonry						
23.	Foundation material: concrete 24. Roof type/material: flat						
25.	No. Bays: Front 6 Side 12 25. Wall treatment: buff brick						
26.	. Plan shape: rectangular 27. Changes: Addition? Altered?						
28.	Exterior condition: good 29: Open to public? limited						
30.	Other Surveys in which included: St. Louis Harbor Historic Properties Reconnaissance, 1987, U.S. Army Corps of Engineers survey (partially incl.						

- 31. Further description of important features: A stepped parapet above the center garage bay defines the height of a raised clerestory running the length of the building. A soldier lintel course, raised brick banding and recessed panels provide the visual interest for this building. Trim is terra cotta of an unusual pale salmon color. Windows in the southwest corner (cont'd. below)
- 32. History and Significance: of the building have been reduced in size to reflect their use in an office. The Porbeck Manufacturing Company took out a permit to build this factory/warehouse building for \$15,000 in 1942. The company has occupied the building ever since.



NORTH BROADWAY INDUSTRUE BURURY IN 2600-06 N. NINTH FACING NE # 30

7/90

1.	No. 048	3. Location of Negatives: Landmarks Association of St. Louis, Inc., 917 Locust, St. Louis, MO 63101					
2.	City/County: City of St. Louis, MO	4. Prepared by: Cynthia Longwisch & Mary M. Stiritz, Landmarks Association of St. Louis, Inc.					
5.	Date: 11/90	6. Sources of information: St. Louis Public Records, City Hall; St. Louis Public Library; MO Historical Soc.					
7.	Building? Yes						
9.	Ownership: Private	8. On National Register or part of estab. district? No 10. Visible from public road? Yes 11. Endangered? No					
12.	Street address: 2800 N. Ninth 13. Style: industrial						
14.	Date(s): 11/19	/1900					
15.	Architect: August Beinke 16. Builder:						
17.	Original Use: cabinet fact. 18. Present Use: commercial						
19.	Owner's name/address if known: Flower City, Inc. Distribution Center						
20.	No. of stories:	1 21. Basement? yes 22. Wall construction: masonry					
23.	Foundation mate	rial: limestone 24. Roof type/material: flat					
25.	. No. Bays: Front 10 Side 9 25. Wall treatment: painted bri						
26.	Plan shape: rec	tangular 27. Changes: Addition? yes Altered? yes					
28.	Exterior condit	ion: fair 29: Open to public? limited					
30.	Other Surveys in which included: St. Louis Harbor Historic Properties Reconnaissance, 1987, U.S. Army Corps of Engineers survey (partially incl.						
	infilled with b	tion of important features: Original large window bays have rick and glass block. Those on the west elevation have tical arches; those on the south have flat arches. Rubble-					

stone foundation. Building adjoins 2820 N. Ninth (#49).

^{32.} History and Significance: Herman J. Benderschied built this building in 1900 for \$4,000 as a cabinet factory for the Benderschied Manufacturing Co. By 1924, he had moved his residence to Los Angeles, still retaining his presidency in the company. By the 1930s, the company had begun to specialize in drugstore fixtures. The Great Western Box Co. occupied the building in 1943, followed by a succession of light manufacturing concerns.



	ARCH	ITECTURAL/HI	STURIC	INAI	ENTURY SU	RVEY FO	RM 52	-CADIS VI	10
1.	No. 049	 Location of Negatives: Landmarks Association of St. Louis, Inc., 917 Locust, St. Louis, MO 63101 Prepared by: Cynthia Longwisch & Mary M. Stiritz, Landmarks Association of St. Louis, Inc. Sources of information: St. Louis Public Records, City Hall; St. Louis Public Library; MO Historical Soc. 							
2.	City/County: City of St. Louis, MO								,
5.	Date: 11/90								
7.	Building? Yes								
9.	Ownership: Private	8. On National Register or part of estab. district? No							
		10. Visib	le from	n pul	olic road	? Yes	11.	Endangered?	? No
12.	Street address:	2820 N. Ni	nth	PLO VELOCENSIÓN DE PORTE NA	13. Style: commercial				
14.	Date(s): 2/20/1906								
15.	Architect: 1			6. Builder:					
17.	Original Use: factory 18.			Present Use: warehouse					
19.	Owner's name/address if known: Flower City, Inc. Distribution Center								
20.	No. of stories: 2 21. Basemer				yes 22	. Wall	constr	uction: mass	onry
23.	Foundation material: limestone			24. Roof type/material: flat					
25.	No. Bays: Front 3 Side 9			25. Wall treatment: painted brick					
26.	Plan shape: rectangular 27.			Changes: Addition? Altered? yes					
28.	Exterior condition: fair`			29: Open to public? no					

30. Other Surveys in which included: St. Louis Harbor Historic Properties Reconnaissance, 1987, U.S. Army Corps of Engineers survey (partially incl

31. Further description of important features: This building was built as an annex to the cabinet factory directly to the south. All openings have been infilled with wood and/or corrugated fiberglas. Metal sills and soldier-course lintels. Terra cotta coping.

32. History and Significance: Herman J. Benderschied applied for the permit to build this \$18,000 addition to his factory in 1906. Benderschied specializin fixtures for drugstores. He had moved his place of residence to Los Angele by 1924, still retaining his presidency in the company. The company remained



#4

NOTE DESCRIPT INDUSTRIAL SURVEY IT 2020 N. NINTH FACING SE

ST. LOUD, MO

MISSOURI OFFICE OF HISTORIC PRESERVATION ARCHITECTURAL/HISTORIC INVENTORY SURVEY FORM

SLCA5013-019	7
--------------	---

1.	No. 052	3. Location of Negatives: Landmarks Association of St. Louis, Inc., 917 Locust, St. Louis, MO 63101
2.	City/County: City of St. Louis, MO	4. Prepared by: Cynthia Longwisch & Mary M. Stiritz, Landmarks Association of St. Louis, Inc.
5.	Date: 11/90	6. Sources of information: St. Louis Public Records,
7.	Building? Yes	City Hall; St. Louis Public Library; MO Historical Soc.
9.	Ownership: Private	8. On National Register or part of estab. district? No. Visible from public road? Yes 11. Endangered? No.
12.	Street address:	2923-25 N. Ninth 13. Style: Tudor Revival
14.	Date(s): 9/4/19	930
15.	Architect: una	vailable 16. Builder: unavailable
17.	Original Use:	filling sta. 18. Present Use: storage
19.	Owner's name/address if known:	
20.	No. of stories:	1 21. Basement? no 22. Wall construction: masonr
23.	Foundation mate	rial: concrete 24. Roof type/material: cross gabled
25.	No. Bays: Fron	t 6 Side 3 25. Wall treatment: painted brick
26.	Plan shape: mod	ified L 27. Changes: Addition? yes Altered? yes
28.	Exterior condit	ion: fair/poor 29: Open to public? no
30.		n which included: St. Louis Harbor Historic Properties 1987, U.S. Army Corps of Engineers survey (partially incl
31.	Further descrip	tion of important features: The picturesquely-gabled roof

the east chimney base have raised brick roundels. Openings have soldier course


lintels, multipane windows. Elliptically-arched main (east) entrance.

block addition on the south side. Gas pumps remain on east side.

^{32.} History and Significance: O. K. Wing took out the permit to build this \$3,000 filling station in 1930. It appears to have remained a filling station/garage for most of its history. Daily Record microfilm records for this year are currently unavailable.



MISSOURI OFFICE OF HISTORIC PRESERVATION ARCHITECTURAL/HISTORIC INVENTORY SURVEY FORM



1.	No. 067	 Location of Negatives: Landmarks Association of St. Louis, Inc., 917 Locust, St. Louis, MO 63101 	
2.	City/County: , City of St. Louis, MO	4. Prepared by: Cynthia Longwisch & Mary M. Stiritz, Landmarks Association of St. Louis, Inc.	
5.	Date: 11/90	6. Sources of information: St. Louis Public Records, City Hall; St. Louis Public Library; MO Historical Soc.	
7.	Building? Yes		
9.	Ownership:	8. On National Register or part of estab. district? No	
٠.	Private	10. Visible from public road? Yes 11. Endangered? No	
12.	Street address:	3105-07 N. Ninth 13. Style: commercial	
14.	Date(s): 11/10/1911		
15.	Architect: 16. Builder: Tom Kennitt		
17.	Original Use: factory 18. Present Use: warehouse		
19.	Owner's name/address if known:		
20.	No. of stories: 3 21. Basement? yes 22. Wall construction: masonry		
23.	Foundation material: stone 24. Roof type/material: flat		
25.	No. Bays: Fron	t 5 Side 3 25. Wall treatment: stucco washed brick	
26.	Plan shape: rec	tangular 27. Changes: Addition? Altered? yes	
28.	Exterior condit	ion: fair 29: Open to public? no	
30.	_	n which included: St. Louis Harbor Historic Properties 1987, U.S. Army Corps of Engineers survey (partially incl.)	
	k sills and repl	tion of important features: Segmentally arched windows have acement one-over-one panes. Centered parapet. Corbelled a cotta coping. First-story openings include a garage bay,	

32. History and Significance: The Bennett-Dryer-Buss Belting Co. took out the permit for this building in 1911 for \$1,000. The company later became the Bennett-McGuire Belting Co.

apparently original, with a rosette-studded iron lintel. Center first-story

window infilled. A stucco wash covers the building.



WG7 SIOS-OT N. NINTH FACING W-SW 97, 20415, MO

73

MISSOURI OFFICE OF HISTORIC PRESERVATION ARCHITECTURAL/HISTORIC INVENTORY SURVEY FORM

	ARCH	TECTURAL/HISTORIC INVENTORY SURVEY FORM SLCASSI3-021
1.	No. 075	3. Location of Negatives: Landmarks Association of St. Louis, Inc., 917 Locust, St. Louis, MO 63101
2.	City/County: City of St. Louis, MO	4. Prepared by: Cynthia Longwisch & Mary M. Stiritz, Landmarks Association of St. Louis, Inc.
5.	Date: 11/90	6. Sources of information: St. Louis Public Records, City Hall; St. Louis Public Library; MO Historical Soc.
7.	Building? Yes	
9.	Ownership:	8. On National Register or part of estab. district? No
<i>.</i>	Private	10. Visible from public road? Yes 11. Endangered? No
12.	Street address:	3116-18 N. Ninth 13. Style: commercial
14.	Date(s): 6/12/	891
15.	Architect:	16. Builder:
17.	Original Use: warehouse 18. Present Use: warehouse	
19.	Owner's name/add	lress if known:
20.	No. of stories:	1 21. Basement? yes 22. Wall construction: masonry
23.	Foundation mate	rial: unknown 24. Roof type/material: flat
25.	No. Bays: From	25. Wall treatment: brown brick
26.	Plan shape: irre	egular 27. Changes: Addition? Altered? yes
28.	Exterior condit	ion: fair/poor 29: Open to public? no

- 30. Other Surveys in which included: St. Louis Harbor Historic Properties Reconnaissance, 1987, U.S. Army Corps of Engineers survey (partially incl.)
- 31. Further description of important features: A corbeled brick cornice bands the building. Terra cotta coping. Garage bay is round-arched. Building appears to have been damaged by fire.
- 32. History and Significance: A. Kessler took out the permit for this building for use as a warehouse in 1891. The cost was \$3,400.



MISSOURI OFFICE OF HISTORIC PRESERVATION ARCHITECTURAL/HISTORIC INVENTORY SURVEY FORM SLLASO/3-022

)=:,\dir	
1.	No. 068	 Location of Negatives: Landmarks Association of St. Louis, Inc., 917 Locust, St. Louis, MO 63101 	
2.	City/County: City of St. Louis, MO	4. Prepared by: Cynthia Longwisch & Mary M. Stiritz, Landmarks Association of St. Louis, Inc.	
5.	Date: 11/90	6. Sources of information: St. Louis Public Records, City Hall; St. Louis Public Library; MO Historical Soc.	
7.	Building? Yes		
9.	Ownership:	8. On National Register or part of estab. district? No	
	Private	10. Visible from public road? Yes 11. Endangered? No	
12.	Street address:	3133-37 N. Ninth 13. Style: industrial	
14.	Date(s): c. 19	10	
15.	Architect: 16. Builder:		
17.	Original Use: industrial 18. Present Use: industrial		
19.	Owner's name/address if known:		
20.	No. of stories: 3 21. Basement? yes 22. Wall construction: masonry		
23.	Foundation mate	rial: stone 24. Roof type/material: flat	
25.	No. Bays: Fron	t 6 Side 9 25. Wall treatment: red brick	
26.	Plan shape: rec	tangular 27. Changes: Addition? yes Altered? yes	
28.	Exterior condit	ion: fair 29: Open to public? no	
30.	-	n which included: St. Louis Harbor Historic Properties 1987, U.S. Army Corps of Engineers survey (partially incl.	
31. with	Further descrip	1987, U.S. Army Corps of Engineers survey (partially in tion of important features: Two upper stories have wind trial metal sash and no arches; first-story windows in t	

32. History and Significance: the front elevation. Simple corbelled brick cornice. Terra cotta coping. No building permit could be found for this building.

front elevation. Dark headers distinguish the brickwork on

front elevation have double-rowlock segmental arches; all have brick sills. A loading dock with double wood doors is located at the southeast corner of the

(cont'd below)



MISSOURI OFFICE OF HISTORIC PRESERVATION ARCHITECTURAL/HISTORIC INVENTORY SURVEY FORM

6LC ASO13-023

1.	No. 070	3. Location of Negatives: Landmarks Association of
2.	City/County: City of St. Louis, MO	St. Louis, Inc., 917 Locust, St. Louis, MO 63101 4. Prepared by: Cynthia Longwisch & Mary M. Stiritz, Landmarks Association of St. Louis, Inc.
5.	Date: 11/90	6. Sources of information: St. Louis Public Records, City Hall; St. Louis Public Library; MO Historical Soc.
7.	Building? Yes	
9.	Ownership: Private	8. On National Register or part of estab. district? No 10. Visible from public road? Yes 11. Endangered? No
12.	Street address:	3145-51 N. Ninth 13. Style: industrial
14.	Date(s): 9/5/1890; 8/2/1948	
15.	Architect: 16. Builder:	
17.	Original Use: factory 18. Present Use: warehouse	
19.	Owner's name/address if known:	
20.	No. of stories: 2 21. Basement? yes 22. Wall construction: masonr	
23.	Foundation material: limestone 24. Roof type/material: flat	
25.	No. Bays: Fron	t 3 Side 11 25. Wall treatment: red brick
26.	Plan shape: rec	tangular 27. Changes: Addition? yes Altered? yes
28.	Exterior condition: fair 29: Open to public? no	
30.	-	n which included: St. Louis Harbor Historic Properties 1987, U.S. Army Corps of Engineers survey (partially incl.
	orbelled brick b	tion of important features: Two-story piers are connected anding at either end. Paired windows (some infilled with industrial double-hung sash, segmental soldier arches and

wood tympana incised with scrollwork (Ninth St. elevation). Parapet is stepped.

^{32.} History and Significance: The Yerkes & Finan Woodworking Machine Company took out the permit for this \$5,500 building in 1890. The Vitro Products Co. added a one-story brick addition to the south side of the building in 1948 for \$4,000.



NORTH BECADURY INDUSTRIAL SURVEY II. 3145-51 N. NIMTH PROLITS SN

ST LENY, MO

7

MISSOURI OFFICE OF HISTORIC PRESERVATION ARCHITECTURAL/HISTORIC INVENTORY SURVEY FORM

5LCA5013-024

(cont'd. below)

1.	No. 072	3. Location of Negatives: Landmarks Association of St. Louis, Inc., 917 Locust, St. Louis, MO 63101
2.	City/County: City of St. Louis, MO	4. Prepared by: Cynthia Longwisch & Mary M. Stiritz, Landmarks Association of St. Louis, Inc.
5.	Date: 11/90	6. Sources of information: St. Louis Public Records,
7.	Building? Yes	City Hall; St. Louis Public Library; MO Historical Soc.
9.	Ownership:	8. On National Register or part of estab. district? No
•	Ownership: Private	10. Visible from public road? Yes 11. Endangered? No
12.	Street address:	3203 N. Ninth 13. Style: Classical Revival
14.	Date(s): 5/2/1883	
15.	Architect: 16. Builder:	
17.	Original Use: res./commer. 18. Present Use: vacant	
19.	Owner's name/address if known:	
20.	No. of stories:	2-1/2 21. Basement? yes 22. Wall construction: masonry
23.	Foundation material: stone 24. Roof type/material: side gable	
25.	No. Bays: Fron	t 5 Side 5 25. Wall treatment: red brick
26.	Plan shape: rec	tangular 27. Changes: Addition? yes Altered? yes
28.	Exterior condition: fair 29: Open to public? no	
30.	_	n which included: St. Louis Harbor Historic Properties 1987, U.S. Army Corps of Engineers survey (partially incl.
	stopher & Simpso	tion of important features: A cast-iron storefront marked n occupies the southeast corner of this building. Corinth-although the original window configuration has been altered

32. History and Significance: openings infilled. Parapeted brick chimneys on north and south walls. Two dormers. Rear, one-story brick addition is much newer and connected by a transitional passageway. Henry Bauer took out the permit for this building in 1883 for \$4,700.

Windows have segmental soldier arches and stone lugsills; those on the primary

elevation have stone keystones. Corbelled brick cornice. All



MISSOURI OFFICE OF HISTORIC PRESERVATION ARCHITECTURAL/HISTORIC INVENTORY SURVEY FORM



1.	No. 073	 Location of Negatives: Landmarks Association of St. Louis, Inc., 917 Locust, St. Louis, MO 63101
2.	City/County: City of St. Louis, MO	4. Prepared by: Cynthia Longwisch & Mary M. Stiritz, Landmarks Association of St. Louis, Inc.
5.	Date: 11/90	6. Sources of information: St. Louis Public Records, City Hall; St. Louis Public Library; MO Historical Soc.
7.	Building? Yes	
9.	Ownership:	8. On National Register or part of estab. district? No
	Private	10. Visible from public road? Yes 11. Endangered? No
12.	Street address:	3221-27 N. Ninth 13. Style: industrial
14.	Date(s): 3/13/1890; 3/17/1891	
15.	Architect: 16. Builder:	
17.	Original Use: planing mill 18. Present Use: planing mill	
19.	Owner's name/address if known: Crescent Planing Mill Co.	
20.	No. of stories:	2 21. Basement? yes 22. Wall construction: masonry
23.	Foundation mate	rial: limestone 24. Roof type/material: flat
25.	No. Bays: Fron	t 21 Side 14 25. Wall treatment: red brick
26.	Plan shape: rectangular 27. Changes: Addition? yes Altered?	
28.	Exterior condit	ion: good 29: Open to public? limited
30.	=	n which included: St. Louis Harbor Historic Properties 1987, U.S. Army Corps of Engineers survey (partially incl.)
	- Afficial Antique de Contra , a majorque d'Arquis par l'aprimentation y l'Arquis de Laborator de Laborator (Antique Laborator	

- 31. Further description of important features: Pilasters divide the facade into sections. Windows have double-rowlock segmental arches. A round arch heads the entry at the south end of the primary elevation. Corbelled brick cornice on primary elevation. Decoratively-incised wood tympana survive on some windows. Several loading dock bays around the building.
- 2. History and Significance: The Crescent Planing Mill took out a permit to build a \$10,000 "factory" in 1890. They then got a permit in 1891 to build a \$5,000 warehouse and shop. The mill specializes in woodwork and has remained active in this location to the present day.



NORTH BROADWAY INQUATRIAL SURVEY II.
3221-27 N. NIKER
FACILLE NO.

97. LOUIS, MO

7/90

SLCA5013-026

(cont'd. below)

MISSOURI OFFICE OF HISTORIC PRESERVATION ARCHITECTURAL/HISTORIC INVENTORY SURVEY FORM

1.	No. 095	3. Location of Negatives: Landmarks Association of St. Louis, Inc., 917 Locust, St. Louis, MO 63101	
2.	City/County: City of St. Louis, MO	4. Prepared by: Cynthia Longwisch & Mary M. Stiritz, Landmarks Association of St. Louis, Inc.	
5.	Date: 11/90	6. Sources of information: St. Louis Public Records, City Hall; St. Louis Public Library; MO Historical Soc.	
7.	Building? Yes		
9.	Ownership: Private	8. On National Register or part of estab. district? No. 10. Visible from public road? Yes 11. Endangered? No.	
12.	Street address:	3300-02 rear N. 9th 13. Style: vernacular	
14.	Date(s): 7/27/	1885	
15.	Architect: 16. Builder:		
17.	Original Use: residential 18. Present Use: residential		
19.	Owner's name/address if known:		
20.	No. of stories: 2 21. Basement? yes 22. Wall construction: masonr		
23.	Foundation material: stone 24. Roof type/material: flat		
25.	No. Bays: Fron	t 5 Side 2 25. Wall treatment: painted brick	
26.	Plan shape: rec	tangular 27. Changes: Addition? Altered? yes	
28.	Exterior condit	ion: good 29: Open to public? no	
30.	 -	n which included: St. Louis Harbor Historic Properties 1987, U.S. Army Corps of Engineers survey (partially incl	
	arches and ston	tion of important features: Windows feature segmental sole sills. Wood tympana have incised scroll design. Corsthe front elevation. Doors flank center doorway; this	

32. History and Significance: surround. Metal and frame two-story rear porch is of much more recent vintage than the house. Paul Kempf took out the permit for this double residence for \$3,000 in 1885. The building appears to have always been used as a residence.

latter appears to be an opening to a passageway through the building that has

been Greek Revivalized (more recently?) with a pedimented door



95 NORTH BROADWAY INDUSTRIAL SURVEY.
33CO-02 REAR N. NINTH
FRAIG NW

ST. LOUIS, M.D



ARCHITECTURAL/HISTORIC INVENTORY SURVEY FORM SLCASO13-027



1.	No. 096	3. Location of Negatives: Landmarks Association of St. Louis, Inc., 917 Locust, St. Louis, MO 63101
2.	City/County: City of St. Louis, MO	4. Prepared by: Cynthia Longwisch & Mary M. Stiritz, Landmarks Association of St. Louis, Inc.
5.	Date: 11/90	6. Sources of information: St. Louis Public Records,
7.	Building? Yes	City Hall; St. Louis Public Library; MO Historical Soc.
9.	Ownership:	8. On National Register or part of estab. district? No
	Private	10. Visible from public road? Yes 11. Endangered? No
12.	Street address:	3314 N. Ninth 13. Style: Classical Revival
14.	Date(s): 3/16/	1877
15.	Architect:	16. Builder:
17.	Original Use: residential 18. Present Use: residential	
19.	Owner's name/add	dress if known:
20.	No. of stories: 2 21. Basement? yes 22. Wall construction: mason	
23.	Foundation mate	rial: stone 24. Roof type/material: side gable
25.	No. Bays: Fron	t 2 Side 2 25. Wall treatment: red brick
26.	Plan shape: L	27. Changes: Addition? Altered? yes
28.	Exterior condit	ion: good 29: Open to public? no
30.	*	n which included: St. Louis Harbor Historic Properties 1987, U.S. Army Corps of Engineers survey (partially incl.
stor bric	have segmental te keys. Two-ove ked in. Shared	tion of important features: Corbelled brick cornice. Open brick soldier arches, the ones on the front elevation with r-two, double-hung wood sash, stone sills. Attic window commonwall with 3316 N. Ninth (#97). Rear ell has flounder built directly on sidewalk line; stone steps.

32. History and Significance: S. Gang took out the permit for this house in 1877 for \$1,700. It has always been a residence.



MISSOURI OFFICE OF HISTORIC PRESERVATION ARCHITECTURAL/HISTORIC INVENTORY SURVEY FORM SLC ASO/3-028



1.	No. 090	3. Location of Negatives: Landmarks Association of St. Louis, Inc., 917 Locust, St. Louis, MO 63101
2.	City/County: City of St. Louis, MO	4. Prepared by: Cynthia Longwisch & Mary M. Stiritz, Landmarks Association of St. Louis, Inc.
5.	Date: 11/90	6. Sources of information: St. Louis Public Records, City Hall; St. Louis Public Library; MO Historical Soc.
7.	Building? Yes	
9.	Ownership:	8. On National Register or part of estab. district? No
	Private	10. Visible from public road? Yes 11. Endangered? No
12.	Street address:	3315 N. Ninth 13. Style: Second Empire
14.	Date(s): 3/13/1891	
15.	Architect: 16. Builder:	
17.	Original Use: residential 18. Present Use: vacant	
19.	Owner's name/ad	dress if known:
20.	No. of stories: 3 21. Basement? yes 22. Wall construction: masonr	
23.	Foundation material: stone 24. Roof type/material: mansard/slat	
25.	No. Bays: Front 2 Side 2 25. Wall treatment: red brick	
26.	Plan shape: rec	tangular 27. Changes: Addition? yes Altered? yes
28.	Exterior condit	ion: poor 29: Open to public? no
30.	-	n which included: St. Louis Harbor Historic Properties 1987, U.S. Army Corps of Engineers survey (partially incl.)
two	y is a mansard r dormers with car	tion of important features: The front elevation of the 3rd oofline covered with hexagonal slate tiles and inset with ved wood frames and cornices. Below, a corbelled cornice ntal pressed brick extend across the front. Front elevation

32. History and Significance: and stone lugsills. Doorway appears to have been recessed. No openings on the north elevation. Stone water table. House is built right on the sidewalk line with stone steps. A flat-roofed, two-story rear addition has a one-story frame addition on it.

openings are segmentally soldier arched with stone keystones (cont'd. below)



MISSOURI OFFICE OF HISTORIC PRESERVATION SLC ASSISTED

1.	No. 097	3. Location of Negatives: Landmarks Association of	
2.	City/County:	St. Louis, Inc., 917 Locust, St. Louis, MO 63101	
	City of St. Louis, MO	4. Prepared by: Cynthia Longwisch & Mary M. Stiritz. Landmarks Association of St. Louis, Inc.	
5.	Date: 11/90	6. Sources of information: St. Louis Public Records, City Hall; St. Louis Public Library; MO Historical Soc.	
7.	Building? Yes		
9.	Ownership:	8. On National Register or part of estab. district? No	
	Private	10. Visible from public road? Yes 11. Endangered? No	
12.	Street address:	3316 N. Ninth 13. Style: Second Empire	
14.	Date(s): 1888	(see #32 below)	
15.	Architect: 16. Builder:		
17.	Original Use: residential 18. Present Use: residential		
19.	Owner's name/address if known:		
20.	No. of stories: 2 21. Basement? yes 22. Wall construction: masonry		
23.	Foundation mate:	rial: limestone 24. Roof type/material: mansard/asph	
25.	No. Bays: Fron	t 4 Side 25. Wall treatment: red brick	
26.	Plan shape: rec	tangular 27. Changes: Addition? Altered? yes	
28.	Exterior condit	ion: good 29: Open to public? no	
30.	-	n which included: St. Louis Harbor Historic Properties 1987, U.S. Army Corps of Engineers survey (partially incl	
31.	Further descrip	tion of important features: The original mansard roof no	

32. History and Significance: the rear of the building has had its arch altered; it probably was originally similar to the arches of the other openings. House is built directly on the sidewalk with stone steps (wood inside entrance) and stone water table. Rear elevation can be seen at middle left in photo for #101. It features a wood and metal two-story porch. Only one permit for a mansard exists for this city block, and it is Joe Mettig's for \$3,400 (dated 7/3/1888), the usual cost of a double. It apparently included 3318 N. 9th (#98).

with ornamental pressed brick highlights the building. Segmentally-arched openings feature fanciful pressed brick made in a recessed pattern. Stone lugsills

(cont'd. below)

have brackets. Entrance is recessed. A passageway opening to

4 97


NORTH BROADWAY INDUSTRIAL SURVEY IT

55, LOUIS,MO

1/90



MISSOURI OFFICE OF HISTORIC PRESERVATION ARCHITECTURAL/HISTORIC INVENTORY SURVEY FORM



1.	No. 101	3. Location of Negatives: Landmarks Association of St. Louis, Inc., 917 Locust, St. Louis, MO 63101	
2.	City/County: City of St. Louis, MO	4. Prepared by:	Cynthia Longwisch & Mary M. Stiritz,
5.	Date: 11/90	6. Sources of information: St. Louis Public Records,	
7.	Building? Yes	City Hall; St. Louis Public Library; MO Historical Soc.	
9.	Ownership: Private	8. On National	Register or part of estab. district? No
		10. Visible from	n public road? Yes 11. Endangered? No
12.	Street address: 3316 Rear N. Ninth 13. Style: vernacular		
14.	Date(s): c. 1870		
15.	Architect: 16. Builder:		
17.	Original Use: residential 18. Present Use: residential		
19.	Owner's name/address if known:		
20.	No. of stories: 2-1/2 21. Basement? yes 22. Wall construction: masonry		
23.	Foundation material: stone 24. Roof type/material: side gable		
25.	No. Bays: Front 2 Side 1		25. Wall treatment: red brick
26.	Plan shape: rectangular 27. Changes: Addition? yes Altered?		
28.	Exterior condition: good		29: Open to public? no
30.	Other Surveys in which included: St. Louis Harbor Historic Properties Reconnaissance, 1987, U.S. Army Corps of Engineers survey (partially incl.		
Wind	vation that actua lows have double-	lly faces west, ric rowlock segmental a	features: This "alley house" has a front ght into the rear of 3316 N. Ninth (#97). arches, stone sills and six-over-six or tion 1 and 2 stories in height is covered

32. History and Significance: The building appears on the 1875 Compton & Dry map. No permit was found.

with brick-look ashpalt siding.



101

33/6 REAR NORTH NINTH FACING N-NW


MISSOURI OFFICE OF HISTORIC PRESERVATION ARCHITECTURAL/HISTORIC INVENTORY SURVEY FORM SLLASO13-03/

1.	No. 098	3. Location of Negatives: Landmarks Association of St. Louis, Inc., 917 Locust, St. Louis, MO 63101	
2.	City/County: City of St. Louis, MO	4. Prepared by: Cynthia Longwisch & Mary M. Stiritz, Landmarks Association of St. Louis, Inc.	
5.	Date: 11/90	6. Sources of information: St. Louis Public Records,	
7.	Building? Yes	City Hall; St. Louis Public Library; MO Historical Soc.	
9.	Ownership: Private	8. On National Register or part of estab. district? No	
		10. Visible from public road? Yes 11. Endangered? No	
12.	Street address:	3318 N. Ninth 13. Style: Second Empire	
14.	Date(s): 1888 (see #32 below)		
15.	Architect:	ect: 16. Builder:	
17.	Original Use: residential 18. Present Use: residential		
19.	Owner's name/address if known:		
20.	No. of stories: 2 21. Basement? yes 22. Wall construction: masonr		
23.	Foundation material: limestone 24. Roof type/material: mansard/asp		
25.	No. Bays: Front 4 Side 0 25. Wall treatment: red brick		
26.	Plan shape: rectangular 27. Changes: Addition? Altered? ye		
28.	Exterior condit	ion: good 29: Open to public? no	
30.	Other Surveys in which included: St. Louis Harbor Historic Properties Reconnaissance, 1987, U.S. Army Corps of Engineers survey (partially incl		
 ງ 1			

- 31. Further description of important features: The original mansard was probably slate-covered. Elaborately corbelled cornice. Segmental soldier arches have shaped stone keys; bracketed stone lugsills. Two-over-two double-hung wood sash. Recessed, wood-paneled entrance. Narrow passageway through to rear is transomed. Slight setback from sidewalk.
- 32. History and Significance: The only permit for a mansarded dwelling in this city block was taken out by Joe Mettig on 7/3/1888 for \$3,400. That sum is about double the standard single dwelling cost, and about equal to the usual cost of a double; based on this information, it appears that #97 and #98 were built from the same permit.



MISSOURI OFFICE OF HISTORIC PRESERVATION ARCHITECTURAL/HISTORIC INVENTORY SURVEY FORM SLC 18013-03C



(cont'd. below)

1.	No. 102		Negatives: Landmarks Association of
2.	City/County: City of St. Louis, MO	St. Louis, Inc., 917 Locust, St. Louis, MO 63101 4. Prepared by: Cynthia Longwisch & Mary M. Stiritz, Landmarks Association of St. Louis, Inc.	
5.	Date: 11/90	6. Sources of information: St. Louis Public Records,	
7.	Building? Yes	City Hall; St. Louis Public Library; MO Historical Soc.	
9.	Ownership: Private	8. On National Register or part of estab. district? No 10. Visible from public road? Yes 11. Endangered? No	
12.	Street address: 3320 rear N. Ninth 13. Style: vernacular		
14.	Date(s): c. 1870		
15.	Architect: 16. Builder:		
17.	Original Use: resid./? 18. Present Use: garage/storage		
19.	Owner's name/address if known:		
20.	No. of stories: 2 21. Basement? yes 22. Wall construction: masonry		
23.	Foundation mate	rial: stone	24. Roof type/material: side gable
25.	No. Bays: Fron	t 2 Side 2	25. Wall treatment: concrete wash
26.	Plan shape: rec	tangular 27.	Changes: Addition? Altered? yes
28.	Exterior condition: good		29: Open to public? no
30.	Other Surveys in which included: St. Louis Harbor Historic Properties Reconnaissance, 1987, U.S. Army Corps of Engineers survey (partially incl.		
	a special concr	ete wash mixture d	features: Owner says brick is covered one initially c. mid-1940s and periodic-ws have stone sills. Dentilled cornice.

indicates early use as a carriage house/stable/servant's

Some openings infilled with CMU. Garage bay dominates east elevation; possibly

^{32.} History and Significance: quarters, although the latter is somewhat unlikely in this German-Irish working class neighborhood. Building appears on the 1875 Compton & Dry map. No permit was found.



#102 NORTH BROADWRY INDUSTRIAL SURVEY IT FACING NW

ST. LOWIS, MO



MISSOURI OFFICE OF HISTORIC PRESERVATION ARCHITECTURAL/HISTORIC INVENTORY SURVEY FORM 5LCA5013-033


1.	No. 092	 Location of Negatives: Landmarks Association of St. Louis, Inc., 917 Locust, St. Louis, MO 63101 Prepared by: Cynthia Longwisch & Mary M. Stiritz, Landmarks Association of St. Louis, Inc. 	
2.	City/County: City of St. Louis, MO		
5.	Date: 11/90	6. Sources of information: St. Louis Public Records, City Hall; St. Louis Public Library; MO Historical Soc.	
7.	Building? Yes	8. On National Register or part of estab. district? No 10. Visible from public road? Yes 11. Endangered? No	
9.	Ownership: Private		
12.	Street address: 3323 N. Ninth 13. Style: vernacular		
14.	Date(s): 4/29/1875		
15.	Architect: 16. Builder:		
17.	Original Use: residential 18. Present Use: residential		
19.	Owner's name/address if known:		
20.	No. of stories: 2 21. Basement? yes 22. Wall construction: masonr		
23.	Foundation mate	rial: limestone 24. Roof type/material: side gable	
25.	No. Bays: Front 5 Side 25. Wall treatment: red brick		
26.	Plan shape: rectangular 27. Changes: Addition? Altered? yes		
28.	Exterior condition: fair 29: Open to public? no		
30.	Other Surveys in which included: St. Louis Harbor Historic Properties Reconnaissance, 1987, U.S. Army Corps of Engineers survey (partially incl		
	a commonwall; t	tion of important features: This is two separate buildings he round-arched center doorway opens into a passageway to ave flat stone lintels and stone sills (both painted green)	

Denticulated brick cornice. Single dormer. Parapeted chimney in commonwall. Stone water table. Built on sidewalk line with stone steps. (cont'd. below)

^{32.} History and Significance: Repair work to the primary facade, mostly at the second-story level, was done with an inappropriate variegated brick (the facade of the house adjoining to the north was completely redone with this brick, in the process rendering it totally without integrity - see photo, right). W. Wilhelmy took out the single permit for this double dwelling in 1876 for \$7,000.



MISSOURI OFFICE OF HISTORIC PRESERVATION ARCHITECTURAL/HISTORIC INVENTORY SURVEY FORM



	and the second s		
1.	No. 099	 Location of Negatives: Landmarks Association of St. Louis, Inc., 917 Locust, St. Louis, MO 63101 Prepared by: Cynthia Longwisch & Mary M. Stiritz, Landmarks Association of St. Louis, Inc. 	
2.	City/County: City of St. Louis, MO		
5.	Date: 11/90	6. Sources of information: St. Louis Public Records,	
7.	Building? Yes	City Hall; St. Louis Public Library; MO Historical Soc.	
9.	Ownership: Private	8. On National Register or part of estab. district? No	
		10. Visible from public road? Yes 11. Endangered? No	
12.	Street address:	: 3324 N. Ninth 13. Style: vernacular	
14.	Date(s): c. 1870		
15.	Architect: 16. Builder:		
17.	Original Use: residential 18. Present Use: residential		
19.	Owner's name/add	lress if known:	
20.	No. of stories:	2 21. Basement? yes 22. Wall construction: masonry	
23.	Foundation material: limestone 24. Roof type/material: side gable		
25.	No. Bays: Front 3 Side 1 25. Wall treatment: red brick		
26.	Plan shape: rectangular 27. Changes: Addition? Altered? ye		
28.	Exterior condit	ion: fair 29: Open to public? no	
30.	-	n which included: St. Louis Harbor Historic Properties 1987, U.S. Army Corps of Engineers survey (partially incl.	
the remn	ted atop the commorth. A profilmants of a corbel	tion of important features: A pair of parapeted chimneys imonwall between this building and the one adjoining it to ed (metal?) cornice is located above what appear to be the led cornice; much of the upper part of the primary facade brickwork done. Upper story front windows (cont'd. below	
วา	High and Cim		

32. History and Significance: have flat arches; lowers have shaped stone arches. Two-over-two double-hung wood sash; stone lugsills with brackets. Recessed entrance. Side windows have been bricked in. Building appears on the 1875 Compton & Dry map. No building permit found.



MISSOURI OFFICE OF HISTORIC PRESERVATION ARCHITECTURAL/HISTORIC INVENTORY SURVEY FORM 54-CA5013-035

1.	No. 103	 Location of Negatives: Landmarks Association of St. Louis, Inc., 917 Locust, St. Louis, MO 63101 Prepared by: Cynthia Longwisch & Mary M. Stiritz, Landmarks Association of St. Louis, Inc. 	
2.	City/County: City of St. Louis, MO		
5.	Date: 11/90	6. Sources of information: St. Louis Public Records,	
7.	Building? Yes	City Hall; St. Louis Public Library; MO Historical Soc.	
9.	Ownership:	8. On National Register or part of estab. district? No	
	Private	10. Visible from public road? Yes 11. Endangered? No	
12.	Street address: 3324 rear N. Ninth 13. Style: vernacular		
14.	Date(s): c. 1870		
15.	Architect: 16. Builder:		
17.	Original Use: residential 18. Present Use: storage		
19.	Owner's name/address if known:		
20.	No. of stories: 1 21. Basement? yes 22. Wall construction: masonr		
23.	Foundation mate	rial: stone 24. Roof type/material: side gable	
25.	No. Bays: Front 2 Side 3 25. Wall treatment: concrete wash		
26.	Plan shape: rectangular 27. Changes: Addition? Altered? yes		
28.	Exterior condition: good 29: Open to public? no		
30.	Other Surveys in which included: St. Louis Harbor Historic Properties Reconnaissance, 1987, U.S. Army Corps of Engineers survey (partially incl		
31.	Further descrip	tion of important features: This brick alley house was,	

like #102 next to it, covered with a "special" concrete wash mixture by the owner c. mid-1940s. Segmentally-arched windows have stone sills, two-over-two

panes. Dentilled brick cornice. Side entrance.

^{32.} History and Significance: This house is clearly on the 1875 Compton & Dry pictorial map of St. Louis. No permit could be found.



#103 WIRM BROADWY INDUSTRIAL SURVEY II.
324 REAR N. MINTH (COURSE)
FACING SW

ST. LOUIS, MO

1/20

MISSOURI OFFICE OF HISTORIC PRESERVATION ARCHITECTURAL/HISTORIC INVENTORY SURVEY FORM SLCASO13036

1.	No. 100	 Location of Negatives: Landmarks Association of St. Louis, Inc., 917 Locust, St. Louis, MO 63101 	
2.	City/County: City of St. Louis, MO	4. Prepared by: Cynthia Longwisch & Mary M. Stiritz, Landmarks Association of St. Louis, Inc.	
5.	Date: 11/90	6. Sources of information: St. Louis Public Records, City Hall; St. Louis Public Library; MO Historical Soc.	
7.	Building? Yes		
9.	Ownership: Private	8. On National Register or part of estab. district? No	
		10. Visible from public road? Yes 11. Endangered? No	
12.	Street address:	dress: 3328 N. Ninth 13. Style: vernacular	
14.	Date(s): c. 1870		
15.	Architect: 16. Builder:		
17.	Original Use: comm./resid. 18. Present Use: vacant		
19.	Owner's name/address if known:		
20.	No. of stories: 2 21. Basement? yes 22. Wall construction: masonry		
23.	Foundation material: stone 24. Roof type/material: side gable		
25.	No. Bays: Fron	t 3 Side 7 25. Wall treatment: permastoned	
26.	Plan shape: rectangular 27. Changes: Addition? yes Altered? yes		
28.	Exterior condit	ion: 29: Open to public? no	
30.	Other Surveys in which included: St. Louis Harbor Historic Properties Reconnaissance, 1987, U.S. Army Corps of Engineers survey (partially incl.)		
arch pair	rely encased in particular in the sectural elements of the sectural elements of the section in the section is a section in the section in the section in the section is a section in the s	tion of important features: Although the building has been permastone (c. 1946), attempts were made to retain the major ts; windows still have segmental arches and stone sills; ckets remain at the simple wood cornice. The side parapet. Large front openings may have been part (cont'd. below)	

^{32.} History and Significance: of a storefront. Rear two-story and one-story additions. This building appears on the 1875 Compton & Dry map. It was used as a saloon at least c. 1904 when M. Mummer took out a permit for a minor alteration.





1.	No. 093	 Location of Negatives: Landmarks Association of St. Louis, Inc., 917 Locust, St. Louis, MO 63101 				
2.	City/County: City of St. Louis, MO	4. Prepared by: Cynthia Longwisch & Mary M. Stiritz, Landmarks Association of St. Louis, Inc.				
5.	Date: 11/90	6. Sources of information: St. Louis Public Records,				
7.	Building? Yes	City Hall; St. Louis Public Library; MO Historical Soc.				
9.	Ownership:	8. On National Register or part of estab. district? No				
	Private	10. Visible from public road? Yes 11. Endangered? No				
12.	Street address:	3401 N. Ninth 13. Style: Second Empire				
14.	Date(s): 8/24/1881					
15.	Architect:	16. Builder:				
17.	Original Use: residential 18. Present Use: commercial					
19.	Owner's name/ad	dress if known:				
20.	No. of stories:	2 21. Basement? yes 22. Wall construction: masonry				
23.	Foundation mate	rial: limestone 24. Roof type/material: mansard/slate				
25.	No. Bays: Fron	t 3 Side 3 25. Wall treatment: red brick				
26.	Plan shape: rec	tangular 27. Changes: Addition? yes Altered? yes				
28.	Exterior condit	ion: good 29: Open to public? no				
30.	_	n which included: St. Louis Harbor Historic Properties 1987, U.S. Army Corps of Engineers survey (partially incl.)				
thei	ard roof with he r pediments. Be	tion of important features: The front elevation features a exagonal slates; two dormers have wooden sunburst designs in low, a corbelled cornice features ornamental pressed brick. al soldier arches, stone sills (with ornamented brackets in				

^{32.} History and Significance: the first-story windows have been infilled with glass brick & regular brick; the others have replacement panes. A one-story addition adjoins the building to the north. It in turn is attached to the south side of 3405 N. Ninth (#94). A rear ell addition of #94 extends across the rear of this property, directly connected to this building only by a passageway.

the case of the primary elevation). Recessed doorway. Four of (cont'd. below)





1.	No. 094	3. Location of Negatives: Landmarks Association of St. Louis, Inc., 917 Locust, St. Louis, MO 63101						
2.	City/County: City of St. Louis, MO	4. Prepared by: Cynthia Longwisch & Mary M. Stiritz, Landmarks Association of St. Louis, Inc.						
5.	Date: 11/90	6. Sources of information: St. Louis Public Records,						
7.	Building? Yes	City Hall; St. Louis Public Library; MO Historical Soc.						
9.	Ownershiw	8. On National Register or part of estab. district? No						
Э.	Ownership: Private	10. Visible from public road? Yes 11. Endangered? No						
12.	Street address:	3405 N. Ninth 13. Style: commercial						
14.	Date(s): c. 19	Date(s): c. 1900						
15.	Architect:	Architect: 16. Builder:						
17.	Original Use: commercial 18. Present Use: commercial							
19.	Owner's name/add	lress if known:						
20.	No. of stories:	2 21. Basement? yes 22. Wall construction: masonry						
23.	Foundation mate	rial: limestone 24. Roof type/material: flat						
25.	No. Bays: Fron	t 5 Side 25. Wall treatment: red brick						
26.	Plan shape: L	27. Changes: Addition? yes Altered?						
28.	Exterior condit	ion: good 29: Open to public? no						
30.		n which included: St. Louis Harbor Historic Properties 1987, U.S. Army Corps of Engineers survey (partially incl.)						
	have no arches,	tion of important features: Multipane industrial metal brick sills. Terra cotta coping. Building is attached between this building and 3401 N. Ninth (#93, center						

32. History and Significance: Piatt); parts of this rear addition (partially visible in photo) were apparently modernized c. late 1930s - early 1940s.

foreground in photo). A rear addition extends to the corner, behind 3401; it appears to be a wagon shed (permit date 2/18/1899 by H. L. (cont'd. below)



#94 NORTH GROADWAY INDUSTRIAL SURVEY II.
3405 N. NINTH (RIGHT)
FACING NW

7/90

 Location of Negatives: Landmarks Association of St. Louis, Inc., 917 Locust, St. Louis, MO 63101 						
4. Prepared by: Cynthia Longwisch & Mary M. Stiritz, Landmarks Association of St. Louis, Inc.						
6. Sources of information: St. Louis Public Records, City Hall; St. Louis Public Library; MO Historical Soc.						
f estab. district? No						
11. Endangered? No						
ommercial						
Date(s): 10/3/1899						
ehouse/possibly vacant						
construction: masonry						
terial: low end gable						
nt: corrugated iron						
? Altered? yes						
lic? no						
istoric Properties urvey (partially incl.)						
o :						

31. Further description of important features: Frame building is covered with

corrugated iron. Window infilled. Roof gable has very slight slope.

^{32.} History and Significance: The Thielling Moulding Co. took out the 1899 permit for this building to be used as a wagon shed. An early 20th century edition of the Sanborn maps says it was used for hay storage. More recently it has been used by a feed company for storage.



NORTH BROADWAY INDUSTRIEL SURVEY II

1.	No. 118	3. Location of Negatives: Landmarks Association of St. Louis, Inc., 917 Locust, St. Louis, MO 63101						
2.	City/County: City of St. Louis, MO	4. Prepared by: Cynthia Longwisch & Mary M. Stiritz, Landmarks Association of St. Louis, Inc.						
5.	Date: 11/90	6. Sources of information: St. Louis Public Records,						
7.	Building? Yes	City Hall; St. Louis Public Library; MO Historical Soc.						
9.	Ownership:	8. On National Register or part of estab. district? No						
J.	Private	10. Visible from public road? Yes 11. Endangered? No						
12.	Street address: 3810-14 N. Ninth 13. Style: commercial							
14.	Date(s): 8/19/	1894; 12/2/1898; 3/27/1907						
15.	Architect:	16. Builder:						
17.	Original Use:	noulding mill 18. Present Use: garage						
19.	Owner's name/ad	lress if known:						
20.	No. of stories:	2 21. Basement? unk. 22. Wall construction: masonry						
23.	Foundation mate	rial: stone 24. Roof type/material: flat						
25.	No. Bays: Fron	t 6 Side 25. Wall treatment: red brick						
26.	Plan shape: L	27. Changes: Addition? yes Altered? yes						
28.	Exterior condit	ion: fair 29: Open to public? limited						
30.	-	n which included: St. Louis Harbor Historic Properties 1987, U.S. Army Corps of Engineers survey (partially incl.)						


- 31. Further description of important features: A gabled parapet flanked by colonettes bears a corbelled cornice. Centered at the second story are two windows with round-arched pressed-brick hoods. Remaining windows feature triple rowlock segmental arches (mostly double rowlock on side elevations). Remnants of a corbeled cornice can be seen between the two stories on (cont'd. below)
- 32. History and Significance: the front elevation. Most openings have been infilled; original windows appear to have had multipane industrial sash. The Theiling Moulding Co. (later, Theiling-Lothmann) (see brief history attached) took out three major building permits relating to this building. The first was in 1894 for a one-story factory at \$3,600; the second was in 1898 for a \$2,500 moulding mill of unspecified height. The third was in 1907 for a "2-story addition to warehouse" for \$5,924, facing Bremen, clearly the n-s ell portion.



\$ 118 NORTH BROADWAY INDUSTRIAL SURVEY IN THOUSENED IN PROCESS OF THE PROCESS OF

St. Louis, MO

- /



1.	No. 124	 Location of Negatives: Landmarks Association of St. Louis, Inc., 917 Locust, St. Louis, MO 63101 					
2.	City/County: City of St. Louis, MO	4. Prepared by: Cynthia Longwisch & Mary M. Stiritz, Landmarks Association of St. Louis, Inc.					
5.	Date: 11/90	6. Sources of information: St. Louis Public Records, City Hall; St. Louis Public Library; MO Historical Soc.					
7.	Building? Yes						
9.	Ownership:	8. On National Register or part of estab. district? No					
	Private	10. Visible from public road? Yes 11. Endangered? No					
12.	Street address:	3906 N. Ninth 13. Style: commercial					
14.	Date(s): 4/22/1912						
15.	Architect:	16. Builder: William Hoffschwelle					
17.	Original Use:	stable 18. Present Use: vacant?					
19.	Owner's name/add	lress if known:					
20.	No. of stories:	1 21. Basement? no 22. Wall construction: masonry					
23.	Foundation mate	rial: concrete 24. Roof type/material: flat					
25.	No. Bays: Fron	t 3 Side 0 25. Wall treatment: red brick					
26.	Plan shape: L	27. Changes: Addition? Altered?					
28.	Exterior condit	ion: poor 29: Open to public? no					
30.	Other Surveys in which included: St. Louis Harbor Historic Properties Reconnaissance, 1987, U.S. Army Corps of Engineers survey (partially incl.)						

31. Further description of important features: A corbelled cornice extends across the front elevation. Terra cotta coping. Two wood garage doors.

^{32.} History and Significance: F. Bartchoer had this stable built in 1912 for \$1,000. It was intended to be used by residents of 827-29 and 831-33 Bremen. In later years it almost certainly served as an automobile garage.



CONDUMY INDUSTRIAL SURVEY IT FACINA SE



-								
1.	No. 125	3. Location of Negatives: Landmarks Association of St. Louis, Inc., 917 Locust, St. Louis, MO 63101						
2.	City/County: City of St. Louis, MO	4. Prepared by: Cynthia Longwisch & Mary M. Stiritz, Landmarks Association of St. Louis, Inc.						
5.	Date: 11/90	6. Sources of information: St. Louis Public Records,						
7.	Building? Yes	City Hall; St. Louis Public Library; MO Historical Soc.						
9.	Ownership:	8. On National Register or part of estab. district? No						
	Private	10. Visible from public road? Yes 11. Endangered? No						
12.	Street address:	3916-18 N. Ninth 13. Style: vernacular						
14.	Date(s): 4/3/18	393						
15.	Architect:	16. Builder:						
17.	Original Use:	residential 18. Present Use: residential						
19.	Owner's name/add	dress if known:						
20.	No. of stories:	2 21. Basement? yes 22. Wall construction: masonry						
23.	Foundation mate:	rial: limestone 24. Roof type/material: flat						
25.	No. Bays: Fron	t 4 Side 25. Wall treatment: red brick						
26.	Plan shape: rec	tangular 27. Changes: Addition? yes Altered? yes						
28.	Exterior condit	ion: good 29: Open to public? no						
30.	-	n which included: St. Louis Harbor Historic Properties 1987, U.S. Army Corps of Engineers survey (partially incl.						

31. Further description of important features: Corbelled cornice. Segmental soldier arches. Two-over-one panes appear not to be original. Wood sills. Entrance has a flat header arch; curved brick form its jambs. A stucco wash covers the south wall. Rear one-story frame addition.

^{32.} History and Significance: This building was one of a pair of adjoining flats listed on a permit taken out by Pauline McMillan in 1893 for \$5,500 for the both. The other building was attached to this one on the south side and has been demolished, which is the reason for the stucco coverup.



125

NORTH BROADWAY INDUSTRIES SURVEY IN 3916-18 IN NUMBE FACING NE

St. LOUIS, MO

7

5LCA5013-043

MISSOURI OFFICE OF HISTORIC PRESERVATION ARCHITECTURAL/HISTORIC INVENTORY SURVEY FORM

1.	No. 126	 Location of Negatives: Landmarks Association of St. Louis, Inc., 917 Locust, St. Louis, MO 63101 						
2.	City/County: City of St. Louis, MO	4. Prepared by: Cynthia Longwisch & Mary M. Stiritz, Landmarks Association of St. Louis, Inc.						
5.	Date: 11/90	6. Sources of information: St. Louis Public Records, City Hall; St. Louis Public Library; MO Historical Soc.						
7.	Building? Yes							
9.	Ownership: Private	8. On National Register or part of estab. district? No 10. Visible from public road? Yes 11. Endangered? No						
12.	Street address:	4000-02 N. Ninth 13. Style: Classical Revival						
14.	Date(s): 4/6/1	912						
15.	Architect:	16. Builder: owner						
17.	Original Use:	residential 18. Present Use: vacant						
19.	Owner's name/ad	dress if known:						
20.	No. of stories:	2 21. Basement? yes 22. Wall construction: masonry						
23.	Foundation mate	rial: limestone 24. Roof type/material: flat						
25.	No. Bays: Fron	t 4 Side 4 25. Wall treatment: red brick						
26.	Plan shape: rectangular 27. Changes: Addition? Altered? yes							
28.	Exterior condit	ion: fair/poor 29: Open to public? no						
30.	Other Surveys in which included: St. Louis Harbor Historic Properties Reconnaissance, 1987, U.S. Army Corps of Engineers survey (partially incl.)							

- 31. Further description of important features: A stepped parapet features a raised brick design in its pediment. A copper cornice across the building's front elevation surmounts brick corbelling that "drips" down at intervals into a brick soldier lintel course. First-story front windows have flat soldier arches; side windows have double-rowlock segmental arches. (cont'd. below)
- 32. History and Significance: Stone sills on the front elevation; wood on the side. Windows are replacements or boarded. Square brick pillars support a hipped porch roof with profiled brackets. Double entrances. Rear wood porch. P. J. Mays took out the permit for this \$5,500 tenement in 1912 and built it himself. No information could be found on Mays. The building appears to have always been used as a residence.



126

NORTH BROADWAY INDUSTRIAL SURVEY II 4000-02 N. NINTH FACING NE

87.40415, MO

SLCASO13 944

1.	No. 127	3.	3. Location of Negatives: Landmarks Association of St. Louis, Inc., 917 Locust, St. Louis, MO 63101						
2.	City/County: City of St. Louis, MO	4.							
5.	Date: 11/90	6.							
7.	Building? Yes		City Hall; St. Louis Public Library; MO Historical Soc.						
9.	Ownership:	8.	On Nationa	l Re	gister	or part of	estab. district? No		
, . 	Private	10.	Visible fr	om p	ublic	road? Yes	11. Endangered? No		
12.	Street address:	4006	N. Ninth	ngalow					
14.	Date(s): 5/24/	1926			***************************************				
15.	Architect:			16. Builder:					
17.	Original Use:	resider	ntial 18	. P	resent	Use: resid	dential		
19.	Owner's name/add	dress i	if known:						
20.	No. of stories:	1	21. Base	ment	? yes	22. Wall	construction: masonry		
23.	Foundation mate	rial:	concrete	2	4. Ro	of type/mate	erial: end gable		
25.	No. Bays: Fron	t 3	Side	2	5. Wa	ll treatmen	t: textured brick		
26.	Plan shape: rectangular 27				anges:	Addition?	Altered?		
28.	Exterior condit	ion: go	oog	Andreas and which are the same	29: O	pen to publ	ic? no		
30.	Other Surveys in which included: St. Louis Harbor Historic Properties								

Reconnaissance, 1987, U.S. Army Corps of Engineers survey (partially incl.)

31. Further description of important features: Flat soldier arches over openings. Brick pillars support porch roof with wood Craftsman detailing. Chimney in south wall. Well-maintained.

^{32.} History and Significance: This building and the three to its north (#128-130) were all listed on a single building permit taken out by E. Cantanne in 1926 for a total of \$12,000.



127 HORTH BROADWAY INDUSTRIAL SURVEY II

97. 40UIS, MO



1.	No. 128	[3. Location of Negatives: Landmarks Association of St. Louis, Inc., 917 Locust, St. Louis, MO 63101						
2.	City/County: City of St. Louis, MO	4. Prepared by: Cynthia Longwisch & Mary M. Stiritz, Landmarks Association of St. Louis, Inc.							
5.	Date: 11/90		· · · · · · · · · · · · · · · · · · ·						
7.	Building? Yes	_	City Hall; St. Louis Public Library; MO Historical Soc.						
9.	Ownership:	8. On Nat	cional Re	egister ———	or part of	estab. district? No			
	Private	10. Visib	le from p	public :	road? Yes	11. Endangered? No			
12.	2. Street address: 4008 N. Ninth 13. Style: Bungalow					ngalow			
14.	Date(s): 5/24/	1926							
15.	Architect:		16	16. Builder:					
17.	Original Use:	residential	18.	Present	Use: resid	dential			
19.	Owner's name/add	dress if know	wn:						
20.	No. of stories:	1 21.	Basemen	t? yes	22. Wall	construction: masonry			
23.	Foundation mate	rial: concre	ete .	24. Ro	of type/mate	erial: end gable			
25.	No. Bays: Fron	t 3 Side		25. Wa	ll treatmen	t: textured brick			
26.	Plan shape: rec	tangular	27. C	hanges:	Addition?	Altered?			
28.	Exterior condit	ion: good		29: 0	pen to publ	ic? no			
30.	-					storic Properties rvey (partially incl.)			

31. Further description of important features: Soldier arch lintel courses over openings. Brick pillars support gabled porch roof with Craftsman detail. Chimney in south wall. Brick sills. Virtually identical to #127, 129 & 130.

^{32.} History and Significance: Four nearly identical buildings were listed on a single permit for \$12,000 taken out in 1926 by E. Cantanne, who also built them. They are all excellently maintained.



NORTH BROADWAY INDUSTRIAL SURVEY II PACING NE

57,40415, MO 8/90

SLCA5013-046

1.	No. 129	 Location of Negatives: Landmarks Association of St. Louis, Inc., 917 Locust, St. Louis, MO 63101 						
2.	City/County: City of St. Louis, MO	4. Prepared by: Cynthia Longwisch & Mary M. Stiritz, Landmarks Association of St. Louis, Inc.						
5.	Date: 11/90	6. Sources of information: St. Louis Public Records,						
7.	Building? Yes	City Hall; St. Louis Public Library; MO Historic						
9.	Ownership: Private	8. On National Register or part of estab. district? No 10. Visible from public road? Yes 11. Endangered? No						
12.	Street address:	4012 N. Ninth 13. Style: Bungalow						
14.	Date(s): 5/24/	926						
15.	Architect:	16. Builder: owner						
17.	Original Use:	esidential 18. Present Use: residential						
19.	Owner's name/add	ress if known:						
20.	No. of stories:	1 21. Basement? yes 22. Wall construction:	masonry					
23.	Foundation mate	ial: concrete 24. Roof type/material: end g	able					
25.	No. Bays: Fron	3 Side 25. Wall treatment: textured b	rick					
26.	Plan shape: rec	angular 27. Changes: Addition? Alter	ed?					
28.	Exterior condit	on: good 29: Open to public? no						
30.		which included: St. Louis Harbor Historic Proper 1987, U.S. Army Corps of Engineers survey (partial						
31.	Further descrip	ion of important features: Square brick columns s	support					

a gabled wood porch roof with Craftsman detailing. Soldier lintel courses over

openings; brick sills. Chimney in south wall. Excellently maintained.

^{32.} History and Significance: E. Cantanne took out the permit for four nearly identical houses in 1926, which he built himself for a total of \$12,000. They are #127-130 of this survey, and they remain virtually unchanged.



4/29

NORTH BROKOWAY INDUSTRIAL SURVEYE PACING NE

SLCA5013-047

1.	No. 130	3. Location of Negatives: Landmarks Association of St. Louis, Inc., 917 Locust, St. Louis, MO 63101						
2.	City/County: City of St. Louis, MO	4. Prepared by: Cynthia Longwisch & Mary M. Stiritz, Landmarks Association of St. Louis, Inc.						
5.	Date: 11/90	6. Sources of information: St. Louis Public Records,						
7.	Building? Yes	City Hall; St. Louis Public Library; MO Historical Soc. 8. On National Register or part of estab. district? No 10. Visible from public road? Yes 11. Endangered? No						
9.	Ownership: Private							
12.	Street address:	idress: 4014 N. Ninth 13. Style: Bungalow						
14.	Date(s): 5/24/	1926						
15.	Architect:	16. Builder: owner						
17.	Original Use:	residential 18. Present Use: residential						
19.	Owner's name/add	dress if known:						
20.	No. of stories:	1 21. Basement? yes 22. Wall construction: masonry						
23.	Foundation mate	rial: concrete 24. Roof type/material: end gable						
25.	No. Bays: Fron	t 3 Side 25. Wall treatment: textured brick						
26.	Plan shape: rec	tangular 27. Changes: Addition? Altered? yes						
28.	Exterior condit	ion: good 29: Open to public? no						
30.		n which included: St. Louis Harbor Historic Properties 1987, U.S. Army Corps of Engineers survey (partially incl.)						
	has been altere	tion of important features: The gable end of the wood porch d from the original Craftsman detailing; otherwise, this dentical to the three houses to its south. Soldier lintel						

32. History and Significance: This house is one of four listed on a single building permit taken out in 1926 for \$12,000 by E. Cantanne, who also built the houses himself. The other three are #127-129 of this survey.

courses and brick sills. Square brick porch pillars. Chimney in south wall.

Excellently maintained.



4t 12

NORTH BROADWAY INDUSTRIAL SURVEY II. 4014 N. NINTH PACING NE 57. LOUIS, MO

ARCHITECTURAL/HISTORIC INVENTORY SURVEY FORM 5LCASO13-044

Brick jack arch-

(cont'd. below)

No. 131		ion of	Negatives	s: Landmark:	s Assoc	lation of	
	 Location of Negatives: Landmarks Association of St. Louis, Inc., 917 Locust, St. Louis, MO 63101 						
City/County: City of St. Louis, MO	4. Prepared by: Cynthia Longwisch & Mary M. Stiritz, Landmarks Association of St. Louis, Inc.						
Date: 11/90							
Building? Yes	_					7	
Ownership: Private							
Street address:	4018 N. Ni	4018 N. Ninth 13. Style: Classical Revival					
Date(s): 6/22/1908							
Architect: Geor	rge Schalthe	iss 1	6. Build	der:			
Original Use:	residential	18.	Present	Use: resi	dential		
Owner's name/add	dress if kno	wn:					
No. of stories:	2 21.	Baseme	nt? yes	22. Wall	constru	ction: masonry	
Foundation mater	rial: stone		24. Ro	of type/mat	erial:	flat	
No. Bays: Fron	t 3 Side	3	25. Wa	ll treatmen	t: red	brick	
Plan shape: L		27.	Changes:	Addition?		Altered? yes	
Exterior condition: good 29: Open to public? no					ı		
							
	City of St. Louis, MO Date: 11/90 Building? Yes Ownership: Private Street address: Date(s): 6/22/3 Architect: Georginal Use: Owner's name/add No. of stories: Foundation mate: No. Bays: From Plan shape: L Exterior condit Other Surveys in	City of St. Louis, MO Date: 11/90 Building? Yes 8. On Na Ownership: Private 10. Visib Street address: 4018 N. Ni Date(s): 6/22/1908 Architect: George Schalthe Original Use: residential Owner's name/address if kno No. of stories: 2 21. Foundation material: stone No. Bays: Front 3 Side Plan shape: L Exterior condition: good Other Surveys in which incl	City of St. Louis, MO Date: 11/90 Building? Yes Ownership: Private 10. Visible from Street address: 4018 N. Ninth Date(s): 6/22/1908 Architect: George Schaltheiss Original Use: residential Owner's name/address if known: No. of stories: 2 City Hall; St. L. 8. On National Ovisible from 10. Visible from 11. Visible from 12. Visible from 13. Visible from 14. Prepared by: Landmarks As 15. L. 16. Sources of in City Hall; St. L. 8. On National 16. Sources 16. Sources 6. Sour	City of St. Louis, MO Date: 11/90 6. Sources of informatic City Hall; St. Louis Pub Building? Yes 8. On National Register Ownership: Private 10. Visible from public Street address: 4018 N. Ninth Date(s): 6/22/1908 Architect: George Schaltheiss Original Use: residential Original Use: residential Owner's name/address if known: No. of stories: 2 21. Basement? yes Foundation material: stone 24. Ro No. Bays: Front 3 Side 3 25. Wa Plan shape: L Exterior condition: good Other Surveys in which included: St. Loui	City of St. Louis, MO Date: 11/90 6. Sources of information: St. Louis Public Library Building? Yes 8. On National Register or part of Ownership: Private 10. Visible from public road? Yes Street address: 4018 N. Ninth Date(s): 6/22/1908 Architect: George Schaltheiss Original Use: residential No. of stories: 2 21. Basement? yes 22. Wall Foundation material: stone Plan shape: L Exterior condition: good Other Surveys in which included: St. Louis Harbor Hi	City of St. Louis, MO Landmarks Association of St. Louis, In Date: 11/90 6. Sources of information: St. Louis Pub City Hall; St. Louis Public Library; MO Hi Building? Yes 8. On National Register or part of estab. Ownership: Private 10. Visible from public road? Yes 11. Street address: 4018 N. Ninth 13. Style: Classical Date(s): 6/22/1908 Architect: George Schaltheiss 16. Builder: Original Use: residential 18. Present Use: residential Owner's name/address if known: No. of stories: 2 21. Basement? yes 22. Wall constru Foundation material: stone 24. Roof type/material: No. Bays: Front 3 Side 3 25. Wall treatment: red Plan shape: L 27. Changes: Addition?	

History and Significance: on side elevation. Quarry-faced stone water table. Recessed entrance is obscured by a canvas awning. Replacement panes. A small wood and metal porch is located in the corner formed by the rear ell. Apparently original wrought iron fence. The permit for this building was taken out by Fred Kraft in 1908 for \$5,500. It has apparently always been a residence.

stringcourse of ornamental pressed brick crosses the building below the corbel-

Double-rowlock segmentally arched windows

ling; brick, corbelling and cornice all return at the corners.

es.

Stone sills.



2005, MO

5LCA5013-049

1.	No. 132	3.		_		s: Landmarks Association of Locust, St. Louis, MO 63101		
2.	City/County: City of St. Louis, MO	4. Prepared by: Cynthia Longwisch & Mary M. Stiritz, Landmarks Association of St. Louis, Inc.						
5.	Date: 11/90	6. Sources of information: St. Louis Public Records, City Hall; St. Louis Public Library; MO Historical Soc.						
7.	Building? Yes							
9.	Ormonahin	8.	8. On National Register or part of estab. district? No					
7.	Ownership: Private	10. Visible from public road? Yes 11. Endangered? No						
12.	Street address:	t address: 4040 N. Ninth			13.	Style: vernacular		
14.	Date(s): c. 1900							
15.	Architect:			16.	Buile	der:		
17.	Original Use: comm./resid. 18.			3. Pre	sent	Use: residential		
19.	Owner's name/address if known:							
20.	No. of stories: 2 21. Ba			ement?	yes	22. Wall construction: masonry		
23.	Foundation material: limestone			24.	Ro	of type/material: flat		
25.	No. Bays: Front 3 Side 5			25.	Wa	ll treatment: brick/permastone		
26.	Plan shape: rectangular 27.			Chan	iges:	Addition? yes Altered? yes		
28.	Exterior condition: fair			29): O	pen to public? no		
30.	-					s Harbor Historic Properties ngineers survey (partially incl.)		
21	77 13 1							

31. Further description of important features: Parapeted front elevation has had ye olde permastone treatment. A painted, corbelled brick cornice has the look of having been applied to the permastone. A sheet of corrugated metal has been attached to the front between stories. Segmentally arched windows on front and sides have been reduced with infill for replacement windows (cont'd. below)

^{32.} History and Significance: Modern openings at first story front. Rear two-story wood porch. Although no permit was recorded for this building, John Laskowitz took out a \$1,300 permit for an addition to a store and flat on 8/17/1908. He hired C. Gescheit for the construction. F. Laskowitz built the one-story workshop (visible at the rear of the property in the photo) with a permit dated 7/31/1905 for \$800. The Laskowitz family occupied the house at least through 1940, apparently using part of it as a store.



132 HORTH BECADULAY INDUSTRIAL SURVEY I

57. 40415, MO

5LCASN3-050

1.	No. 133	3. Location of Negatives: Landmarks Association of St. Louis, Inc., 917 Locust, St. Louis, MO 63101			
2.	City/County: City of St. Louis, MO	4. Prepared by: Cynthia Longwisch & Mary M. Stiritz, Landmarks Association of St. Louis, Inc.			
5.	Date: 11/90	6. Sources of information: St. Louis Public Records,			
7.	Building? Yes	City Hall; St. Louis Public Library; MO Historical Soc.			
9.	Ownership: Private	8. On National Register or part of estab. district? No			
		10. Visible from public road? Yes 11. Endangered? No			
12.	Street address: 4042 rear N. Ninth 13. Style: vernacular				
14.	Date(s): c. 1876				
15.	Architect: 16. Builder:				
17.	Original Use: residential 18. Present Use: residential				
19.	Owner's name/address if known:				
20.	No. of stories: 2-1/2 21. Basement? yes 22. Wall construction: masonr				
23.	Foundation material: limestone 24. Roof type/material: gable/flou				
25.	. No. Bays: Front 2 Side 1 25. Wall treatment: brown brick				
26.	Plan shape: rectangular 27. Changes: Addition? yes Altered? yes				
28.	Exterior condition: good 29: Open to public? no				
30.	Other Surveys in which included: St. Louis Harbor Historic Properties Reconnaissance, 1987, U.S. Army Corps of Engineers survey (partially incl.				

- Further description of important features: This alley house has two totally different elevations (see photo #133-34): the alley (east) elevation has side gables and parapeted chimneys while the west elevation is a flounder. Windows are segmentally soldier arched with stone sills. Dormer on e. elevation. A wood overhang on the south side shelters the modern wood deck. (cont'd. below)
- 32. History and Significance: A one-story frame addition with brick-look asphalt siding is attached to the west elevation. Permits for this block were issued as early as 1877, and no permit was found for this house. Close scrutiny fails to confirm its presence on the 1875 Compton & Dry map; hence, the c. 1876 date. The building is on the 1883 Hopkins map.

NORTH BROWNING WONSTRIAL SURVEY IT. 4042 REAR (COUTER) N. NINTH FACING SW

#133

8/90 87. LOUIS, MO

1.	No. 134	 Location of Negatives: Landmarks Association of St. Louis, Inc., 917 Locust, St. Louis, MO 63101 Prepared by: Cynthia Longwisch & Mary M. Stiritz, Landmarks Association of St. Louis, Inc. 						
2.	City/County: City of St. Louis, MO							
5.	Date: 11/90	6. Sources of information: St. Louis Public Records,						
7.	Building? Yes	City Hall; St. Louis Public Library; MO Historical Soc. 8. On National Register or part of estab. district? No						
9.	Ownership:	8. On Nat		Register	or part of	estab.	district:	No
	Private	10. Visib	le from	public 1	road? Yes	11.	Endangered?	No
12.	Street address:	4044 rear l	N. Nint	h 13.	Style: ve	rnacula	r	
14.	Date(s): c. 1860-70							
15.	Architect:			6. Build	ler:			
17.	7. Original Use: residential 18. Present Use: resident				dential			
19.	Owner's name/address if known:							
20.	No. of stories: 1-1/2 21. Base			ent? yes	22. Wall	constru	ction: mason	ary
23.	Foundation material: stone			24. Roo	of type/mate	erial:	gable/flou	ndei
25.	No. Bays: Front 2 Side 1			25. Wa	ll treatmen	t: perm	astone/stuc	20
26.	Plan shape: rectangular 27.			Changes:	Addition?	yes	Altered? ye	- s
28.	Exterior condition: good			29: O ₁	pen to publ	ic? no		***********
30.	Other Surveys in which included: St. Louis Harbor Historic Properties Reconnaissance, 1987, U.S. Army Corps of Engineers survey (partially incl.					c1.		

- 31. Further description of important features: This alley house has two completely different elevations (see photo #133-34): the east elevation that faces the alley is side-gabled with parapeted chimneys, while the west elevation is a flounder with a flounder addition. All but the north elevation have been covered with permastone; the north side has been stuccoed. Windows (cont'd. below)
- 32. History and Significance: in the east elevation are segmentally arched while those in the western addition have rectangular openings. A wood and metal overhang creates a porch/patio on the south side of the rear addition. This building is on the 1875 Compton & Dry pictorial map as well as the 1883 Hopkins map. It predates building permits for this block (1877). It has apparently always been used as a residence.





#134 NORTH ERONDWAY INDUSTRIAL SURVEY IT

8/90

5LCAS013-05Z

No. 017					
NO. 017	3. Location of Negatives: Landmarks Association of St. Louis, Inc., 917 Locust, St. Louis, MO 63101				
City/County: City of St. Louis, MO	4. Prepared by: Cynthia Longwisch & Mary M. Stiritz, Landmarks Association of St. Louis, Inc.				
Date: 11/90	6. Sources of information: St. Louis Public Records, City Hall; St. Louis Public Library; MO Historical Soc.				
Building? Yes					
Ownership: Private	8. On National Register or part of estab. district? No. 10. Visible from public road? Yes 11. Endangered? No.				
Street address:	2524 N. Tenth 13. Style: commercial				
Date(s): 8/11/1928; 1974					
Architect:		16. Builder:			
Original Use: store 18. Present Use: church					
Owner's name/address if known: Northside General Baptist					
No. of stories: 1 21. Basement? no 22. Wall construction: masonr					
Foundation material: concrete 24. Roof type/material: flat					
No. Bays: Front 3 Side 4 25. Wall treatment: red & brown br					
. Plan shape: rectangular 27. Changes: Addition? yes Altered					
Exterior condit:	ion: fair	29: Open to public? yes			
Other Surveys in which included: St. Louis Harbor Historic Properties Reconnaissance, 1987, U.S. Army Corps of Engineers survey (partially incl					
	City of St. Louis, MO Date: 11/90 Building? Yes Ownership: Private Street address: Date(s): 8/11/3 Architect: Original Use: s Owner's name/add No. of stories: Foundation mater No. Bays: From Plan shape: rect Exterior condit	City/County: City of St. Louis, MO Date: 11/90 Building? Yes 8. On Ownership: Private 10. Vis Street address: 2524 N. Date(s): 8/11/1928; 1974 Architect: Original Use: store Owner's name/address if k No. of stories: 1 Foundation material: con No. Bays: Front 3 Sid Plan shape: rectangular Exterior condition: fair Other Surveys in which in			

- apets top the front of this building. The original storefront has been infilled with brick. A terra cotta course echoes the parapet lines above the openings. Windows have brick sills. A small rear addition (1974) is attached to the east end of the building.
- 32. History and Significance: Gloria Lee Realty Company took out the \$2,500 building permit to build a store here in 1928. The building was used as a grocery store or vacant until 1952-3, when an occupancy permit was granted to the Church of God. The Old Time General Baptist Church took the building over in 1960, and the present occupants have been using the building as their church since the early 1970s.



#17

2524 N. PACING SE

54CA5013-053

1.	No. 025	3. Location of Negatives: Landmarks Association of St. Louis, Inc., 917 Locust, St. Louis, MO 63101				
2.	City/County: City of St. Louis, MO	4. Prepared by: Cynthia Longwisch & Mary M. Stiritz, Landmarks Association of St. Louis, Inc.				
5.	Date: 11/90	6. Sources of information: St. Louis Public Records,				
7.	Building? Yes	City Hall; St. Louis Public Library; MO Historical Soc.				
9.	Ownership: Private	8. On National Register or part of estab. district? No 10. Visible from public road? Yes 11. Endangered? No				
12.	Street address:	2600-06 N. Tenth 13. Style: commercial				
14.	Date(s): 4/6/1901					
15.	Architect: 16. Builder: Christopher Frieling					
17.	Original Use: flats 18. Present Use: flats					
19.	Owner's name/address if known:					
20.	No. of stories:	2 21. Basement? yes 22. Wall construction: masonry				
23.	Foundation mate	rial: stone 24. Roof type/material: flat				
25.	No. Bays: Fron	t 11 Side 5 25. Wall treatment: red brick				
26.	Plan shape: modif. rectang. 27. Changes: Addition? Altered? yes					
28.	Exterior condition: fair 29: Open to public? no					
30.	Other Surveys in which included: St. Louis Harbor Historic Properties Reconnaissance, 1987, U.S. Army Corps of Engineers survey (partially incl					

- 31. Further description of important features: Brick egg & dart and dentilled cornice above raised string course. Above cornice, concrete veneer replaces the former profiled cornice (see #26). One-over-one windows have no arches, stone sills; most first-story and several second-story are infilled. Corner cast-iron front is all enclosed except for the Globe Foundry column. Small rear shed.
- 32. History and Significance: H. Clark took out a permit in 1901 to build flats for \$7,000. He hired Christopher Frieling for the job. No information could be found on either. The building obviously housed a store at some early point, although the permit did not specify commercial use. The Gloria Lee Realty Co. obtained a \$2,500 permit in 1961 to make repairs to a "store and dwelling" and an occupancy permit was granted in 1963 to make the building a laundry. It appears to have been in use strictly as apartments for some time.



FACING NE

MISSOURI OFFICE OF HISTORIC PRESERVA	ATION (()
ARCHITECTURAL/HISTORIC INVENTORY SURV	EY FORM 7445013754

		•				
1.	No. 029	3. Location of Negatives: Landmarks Association of St. Louis, Inc., 917 Locust, St. Louis, MO 63101				
2.	City/County: City of St. Louis, MO	4. Prepared by: Cynthia Longwisch & Mary M. Stiritz, Landmarks Association of St. Louis, Inc.				
5.	Date: 11/90	6. Sources of information: St. Louis Public Records,				
7.	Building? Yes	City Hall; St. Louis Public Library; MO Historical Soc.				
9.	Ownership: Private	8. On National Register or part of estab. district? No: 10. Visible from public road? Yes 11. Endangered? No				
12.	Street address:					
14.	Date(s): 8/26/1897					
15.	Architect: G. Becker 16. Builder: Hemminghaus & Wollmer					
17.	Original Use: residential 18. Present Use: vacant					
19.	Owner's name/address if known:					
20.	No. of stories: 2 21. Basement? yes 22. Wall construction: masonr					
23.	Foundation material: limestone 24. Roof type/material: flat					
25.	No. Bays: Front 6 Side 6 25. Wall treatment: red brick					
26.	Plan shape: rectangular 27. Changes: Addition? Altered? yes					
28.	Exterior condition: poor 29: Open to public? no					
30.	Other Surveys in which included: St. Louis Harbor Historic Properties Reconnaissance, 1987, U.S. Army Corps of Engineers survey (partially incl.					
31.	Further description of important features: This building was recently					

- 31. Further description of important features: This building was recently gutted by fire. Second-story front elevation windows have gauged brick arches; first-story windows have flat arches with splayed sandstone. All front elevation openings have pressed-brick jambs. Side windows have double-rowlock segmental arches; all windows have stone sills. Centered peaked (con't. below)
- 32. History and Significance: parapet emphasizes the slightly projecting center bay; carved sandstone colonnettes further highlight this feature. Sandstone banding highlights the entrance pilasters. Limestone water table. The building permit for this residence was taken out in 1897 by H. Wedig for \$4,250.



1.	No. 039	1	tion of Negatives: Landmarks Association of Louis, Inc., 917 Locust, St. Louis, MO 63101
2.	City/County: City of St. Louis, MO	4. Prepa	ared by: Cynthia Longwisch & Mary M. Stiritz, marks Association of St. Louis, Inc.
5.	Date: 11/90	1	ces of information: St. Louis Public Records,
7.	Building? Yes	City Hall	1; St. Louis Public Library; MO Historical Soc.
9.	Ownership:	8. On Na	ational Register or part of estab. district? No
	Private	10. Visib	ble from public road? Yes 11. Endangered? No
12.	Street address:	2708-10 N.	. Tenth 13. Style: Second Empire
14.	Date(s): 8/17/	1892 & 8/30/	/1898
15.	Architect: owner 16. Builder: owner		
17.	Original Use: residential 18. Present Use: residential		
19.	Owner's name/add	dress if kno	own:
20.	No. of stories:	2-1/2 21.	Basement? yes 22. Wall construction: masonry
23.	Foundation mate	rial: stone	e 24. Roof type/material: mansard/slate
25.	No. Bays: Fron	t 6 Side	1/4 25. Wall treatment: red brick
26.	Plan shape: rec	tangular	27. Changes: Addition? Altered?
28.	Exterior condit	ion: good	29: Open to public? no
30.	Other Surveys in which included: St. Louis Harbor Historic Properties Reconnaissance, 1987, U.S. Army Corps of Engineers survey (partially incl.		

built, mirror-image halves. Both have flat roofs with front elevation mansards covered with hexagonal slate tiles; paired window dormers are gabled. 1st and 2nd story openings are segmentally soldier-arched. Bracketed stone lugsills have incised Eastlake designs. Recessed double entries have (cont'd. below)

32. History and Significance: stairs to upper units. Four-bay rear ell has a two-story wood porch.

The two parts of the building were designed and built by owner John Baumer. Mr. Baumer took out a \$3,200 permit in 1892 and one for \$2,000 in 1898. He also built a stable on this block in 1892 (an outbuilding was recently demolished; it was probably the stable).



SLCA-013-056

1.	No. 040	3. Location of Negatives: Landmarks Association of St. Louis, Inc., 917 Locust, St. Louis, MO 63101
2.	City/County: City of St. Louis, MO	4. Prepared by: Cynthia Longwisch & Mary M. Stiritz, Landmarks Association of St. Louis, Inc.
5.	Date: 11/90	6. Sources of information: St. Louis Public Records, City Hall; St. Louis Public Library; MO Historical Soc.
7.	Building? Yes	
9.	Ownership: Private	8. On National Register or part of estab. district? No 10. Visible from public road? Yes 11. Endangered? No
12.	Street address:	2712 N. Tenth 13. Style: vernacular
14.	Date(s): 2/26/	1892
15.	Architect: 16. Builder:	
17.	Original Use: stable 18. Present Use: residential	
19.	Owner's name/address if known:	
20.	No. of stories: 2 21. Basement? yes 22. Wall construction: masonry	
23.	Foundation material: stone 24. Roof type/material: flat	
25.	No. Bays: Front 3 Side 1 25. Wall treatment: red brick	
26.	Plan shape: rectangular 27. Changes: Addition? Altered? yes	
28.	Exterior condition: fair/good 29: Open to public? no	
30.	Other Surveys in which included: St. Louis Harbor Historic Properties Reconnaissance, 1987, U.S. Army Corps of Engineers survey (partially incl.)	

31. Further description of important features: The original stable door has been infilled to form a window. Other openings have segmental soldier arches. Corbelled brick cornice.

^{32.} History and Significance: This building was originally built as a stable in 1892, but has been used as a residence for most of the 20th century.

40

NORTH DROADWAY INDUSTRIAL SURVEY IT

57. LOUIS, MO

740

SLCA503-057

This

1.	No. 041	 Location of Negatives: Landmarks Association of St. Louis, Inc., 917 Locust, St. Louis, MO 63101 	
2.	City/County: City of St. Louis, MO	4. Prepared by: Cynthia Longwisch & Mary M. Stiritz, Landmarks Association of St. Louis, Inc.	
5.	Date: 11/90	6. Sources of information: St. Louis Public Records, City Hall; St. Louis Public Library; MO Historical Soc.	
7.	Building? Yes		
9.	Ownership: Private	8. On National Register or part of estab. district? No 10. Visible from public road? Yes 11. Endangered? No	
12.	Street address:	2716 N. Tenth 13. Style: industrial	
14.	Date(s): 11/19	/1940	
15.	Architect: 16. Builder:		
17.	Original Use: warehouse 18. Present Use: warehouse		
19.	Owner's name/address if known:		
20.	No. of stories:	1 21. Basement? no 22. Wall construction: masonry	
23.	Foundation mate	rial: concrete 24. Roof type/material: flat	
25.	No. Bays: Front 2 Side 1 25. Wall treatment: red brick		
26.	Plan shape: rec	tangular 27. Changes: Addition? Altered? yes	
28.	Exterior condition: fair 29: Open to public? no		
30.	Other Surveys in which included: St. Louis Harbor Historic Properties Reconnaissance, 1987, U.S. Army Corps of Engineers survey (partially incl.		
31.	Further descrip	tion of important features: The primary opening in the his building is an overhead garage door bay; a regular	

32. History and Significance: W. Schoenbeck took out a permit for this addition to a warehouse in 1940 for \$1,000. It was evidently part of the "A. Schoenbeck W. & S. Co.," who took out other permits in this city block. The company does not appear in City directories.

door is the only other opening. Neither have arches. Terra cotta coping.

flected by the non-stricken mortar joints on the south wall.

building was originally an addition to a warehouse now demolished; this is re-



NORTH BROADWAY INDUSTRIAL SURVEY ID FACING NE

\$7.65413,40

1.	No. 042	3. Location of Negatives: Landmarks Association of St. Louis, Inc., 917 Locust, St. Louis, MO 63101
2.	City/County: City of St. Louis, MO	4. Prepared by: Cynthia Longwisch & Mary M. Stiritz, Landmarks Association of St. Louis, Inc.
5.	Date: 11/90	6. Sources of information: St. Louis Public Records, City Hall; St. Louis Public Library; MO Historical Soc.
7.	Building? Yes	
9.	Ownership:	8. On National Register or part of estab. district? No
	Private	10. Visible from public road? Yes 11. Endangered? No
12.	Street address:	2718-20 N. Tenth 13. Style: Italianate
14.	Date(s): 7/29/	1880
15.	Architect: 16. Builder:	
17.	Original Use: residential 18. Present Use: residential	
19.	Owner's name/address if known:	
20.	No. of stories:	2 21. Basement? yes 22. Wall construction: masonry
23.	Foundation material: stone 24. Roof type/material: side gable	
25.	No. Bays: Front 4 Side 3 25. Wall treatment: brick	
26.	Plan shape: rec	tangular 27. Changes: Addition? Altered?
28.	Exterior condition: good 29: Open to public? no	
30.		n which included: St. Louis Harbor Historic Properties 1987, U.S. Army Corps of Engineers survey (partially incl.)

Further description of important features: Windows of the primary elevation have shaped stone lintels and stone lugsills. Two-over-two windows are probably replacements. Elaborately corbelled cornice. Parapeted chimneys. Building fronts directly on sidewalk; front stone steps have stone side walls.

^{32.} History and Significance: The building permit was taken out in 1880 by "C. Schoenbach," also known in the permits as C. Schawback and C. Schoenbeck, for \$3,500. The building has always been in residential use.

NORTH BROADWAY INDUSTRIAL SURVEY IT ATIB-20 N. TENTH ST. LOUIS, MO 7/90



SLCAS013-059

1.	No. 043	3. Location of Negatives: Landmarks Association of St. Louis, Inc., 917 Locust, St. Louis, MO 63101	
2.	City/County: City of St. Louis, MO	4. Prepared by: Cynthia Longwisch & Mary M. Stiritz, Landmarks Association of St. Louis, Inc.	
5.	Date: 11/90	6. Sources of information: St. Louis Public Records, City Hall; St. Louis Public Library; MO Historical Soc.	
7.	Building? Yes		
9.	Ownership:	8. On National Register or part of estab. district? No	
•	Private	10. Visible from public road? Yes 11. Endangered? No	
12.	Street address:	2722 N. Tenth 13. Style: Italianate	
14.	Date(s): 4/13/1879		
15.	Architect: 16. Builder:		
17.	Original Use: store/dwell. 18. Present Use: vacant		
19.	Owner's name/address if known:		
20.	No. of stories:	2-1/2 21. Basement? yes 22. Wall construction: masonry	
23.	Foundation material: stone 24. Roof type/material: side gable		
25.	No. Bays: Fron	t 3 Side 6 25. Wall treatment: brick	
26.	Plan shape: rec	tangular 27. Changes: Addition? Altered? yes	
28.	Exterior condition: poor 29: Open to public? no		
30.	Other Surveys in which included: St. Louis Harbor Historic Properties Reconnaissance, 1987, U.S. Army Corps of Engineers survey (partially incl.		

- 31. Further description of important features: Primary elevation features shaped stone lintels and stone lugsills, elaborately corbelled cornice and a cast-iron storefront headed with a wood cornice. The display windows of the storefront appear to be in their original configuration, although they have been boarded up. Side openings are segmentally arched with the (cont'd. below)
- 32. History and Significance: exception of a round-arched recessed entryway near the rear of the building, which probably provided access to upper units for residential use. Windows are two-over-two, double-hung wood sash. Parapeted chimneys. Building appears to have had fire damage. The permit for this building was taken out by C. Schawback/Schoenbach/Schoenbeck (there is great inconsistency in the recorded permits) for \$2,400 in 1879 to build a "store & dwelling." Its use was apparently consistent with this until its vacancy.



\$ 43

NOTTH BROWNING THURSTELL SHELLY 2722 N. TENTH FACANG SE 51-104B, 1

7/9

5LC A5013-060

1.	No. 058	3. Location of Negatives: Landmarks Association of St. Louis, Inc., 917 Locust, St. Louis, MO 63101	
2.	City/County: City of St. Louis, MO	4. Prepared by: Cynthia Longwisch & Mary M. Stiritz, Landmarks Association of St. Louis, Inc.	
5.	Date: 11/90	6. Sources of information: St. Louis Public Records,	
7.	Building? Yes	City Hall; St. Louis Public Library; MO Historical Soc.	
9.	Ownership:	8. On National Register or part of estab. district? No	
	Private	10. Visible from public road? Yes 11. Endangered? No	
12.	Street address:	3103 N. Eleventh 13. Style: commercial	
14.	Date(s): 1/4/1907		
15.	Architect: Aug	ust Schuerman 16. Builder: Bernhardt Wussler	
17.	Original Use: store/flats 18. Present Use: church		
19.	Owner's name/address if known: Faith Temple Assembly		
20.	No. of stories:	2 21. Basement? yes 22. Wall construction: masonry	
23.	Foundation mate	rial: stone 24. Roof type/material: hipped/asphal	
25.	No. Bays: Fron	t 2 Side 7 25. Wall treatment: red brick	
26.	Plan shape: irr	egular 27. Changes: Addition? yes Altered? yes	
28.	Exterior condition: fair 29: Open to public? limited		
30.	-	n which included: St. Louis Harbor Historic Properties 1987, U.S. Army Corps of Engineers survey (partially incl.	
31.	Further descrip	tion of important features: This building is located on a	

- 31. Further description of important features: This building is located on a peninsula, necessitating its odd shape. Windows are segmentally arched on the 11th St. elevation; gauged brick arches are on the corner & 9th St. elevations. First-story openings have been infilled, including the corner cast-iron storefront by St. Louis Architectural Iron. Stone sills have egg & (cont'd below)
- 32. History and Significance: dart ornamental brick directly beneath. One-story rear addition attaches the building to 1111-13 Branch. H. Bressler took out the permit for this building in 1907 for \$7,000. He hired General Contractor Bernhardt Wussler to do the construction. The pair teamed up on two other tenement buildings in this city block at the same time (#59 & 60). No information could be found on Bressler; he evidently built the buildings as speculation or investment. Wussler was active in many parts of the city c. 1900.



\$58 NORTH BROKEWAY INDURRUPL SURVEY III
\$103 N. ELEVENTH
FACING N

ST. LOUIS, MO

7

9LCA4013-06/

1.	No. 061	 Location of Negatives: Landmarks Association of St. Louis, Inc., 917 Locust, St. Louis, MO 63101 	
2.	City/County: City of St. Louis, MO	4. Prepared by: Cynthia Longwisch & Mary M. Stiritz, Landmarks Association of St. Louis, Inc.	
5.	Date: 11/90	6. Sources of information: St. Louis Public Records, City Hall; St. Louis Public Library; MO Historical Soc.	
7.	Building? Yes		
9.	Ownership:	8. On National Register or part of estab. district? No	
	Private	10. Visible from public road? Yes 11. Endangered? No	
12.	Street address:	3115 N. Eleventh 13. Style: vernacular	
14.	Date(s): c. 18	80; 11/23/1886	
15.	Architect: 16. Builder:		
17.	Original Use: residential 18. Present Use: residential		
19.	Owner's name/address if known:		
20.	No. of stories:	1 21. Basement? yes 22. Wall construction: frame	
23.	Foundation mate	rial: stone 24. Roof type/material: front gable	
25.	No. Bays: Fron	t 2 Side 25. Wall treatment: permastoned	
26.	Plan shape: L	27. Changes: Addition? yes Altered? yes	
28.	Exterior condit	ion: good 29: Open to public? no	
30.	_	n which included: St. Louis Harbor Historic Properties 1987, U.S. Army Corps of Engineers survey (partially incl.)	

31. Further description of important features: An open porch is located across the gable end of this house. A rear ell is attached to the rear. The exterior is covered with permastone.

^{32.} History and Significance: This house is shown on the 1883 Hopkins map; it is not possible to say with certainty whether it is on the 1875 Compton & Dry. A permit was taken out in 1886 for a "brick front" on a house owned by A. Hanschild in this approximate location, indicating a frame house. Catherine Woodlock took out a \$200 permit in 1906 to alter this building. The permastone treatment is mid-20th century, usually reserved for frame houses, so it is assumed that this house is frame, possibly making it even earlier than 1880.



ARCHITECTURAL/HISTORIC INVENTORY SURVEY FORM SLCASO13-062

1.	No. 062	3. Location of Negatives: Landmarks Association of St. Louis, Inc., 917 Locust, St. Louis, MO 63101		
2.	City/County: City of St. Louis, MO	4. Prepared by: Cynthia Longwisch & Mary M. Stiritz, Landmarks Association of St. Louis, Inc.		
5.	Date: 11/90	6. Sources of information: St. Louis Public Records,		
7.	Building? Yes	City Hall; St. Louis Public Library; MO Historical Soc.		
9.	Ownership:	8. On National Register or part of estab. district? No		
	Private	10. Visible from public road? Yes 11. Endangered? No		
12.	Street address:	3119 N. Eleventh 13. Style: vernacular		
14.	Date(s): 7/11/	1885		
15.	Architect:	Architect: 16. Builder:		
17.	Original Use: residential 18. Present Use: residential			
19.	Owner's name/address if known:			
20.	No. of stories: 2 21. Basement? yes 22. Wall construction: masonry			
23.	Foundation material: stone 24. Roof type/material: side gable			
25.	No. Bays: Front 2 Side 3 25. Wall treatment: painted brick			
26.	Plan shape: modif. rectang. 27. Changes: Addition? Altered? yes			
28.	Exterior condition: fair 29: Open to public? no			
30.		n which included: St. Louis Harbor Historic Properties 1987, U.S. Army Corps of Engineers survey (partially incl.)		
	windows have fl	tion of important features: Plain wood cornice. Replace- at wood lintels. First-story window heads obscured by metal lock porch with wood railing of late-20th century vintage.		

History and Significance: William Wermmet took out the permit for this house in 1885 for \$800. The building has always been used as a residence.



		/-	
1.	No. 063	 Location of Negatives: Landmarks Association of St. Louis, Inc., 917 Locust, St. Louis, MO 63101 	
2.	City/County: City of St. Louis, MO	4. Prepared by: Cynthia Longwisch & Mary M. Stiritz, Landmarks Association of St. Louis, Inc.	
5.	Date: 11/90	6. Sources of information: St. Louis Public Records,	
7.	Building? Yes	City Hall; St. Louis Public Library; MO Historical Soc.	
9.	Ownership:	8. On National Register or part of estab. district? No	
	Private	10. Visible from public road? Yes 11. Endangered? No	
12.	Street address:	3131 N. Eleventh 13. Style: Craftsman	
14.	Date(s): 4/27/	1925	
15.	Architect: own	er 16. Builder: owner	
17.	Original Use: residential 18. Present Use: residential		
19.	Owner's name/add	lress if known:	
20.	No. of stories:	1 21. Basement? yes 22. Wall construction: masonry	
23.	Foundation mate	rial: concrete 24. Roof type/material: flat/parapeted	
25.	No. Bays: Front 3 Side 3 25. Wall treatment: textured brick		
26.	Plan shape: rec	tangular 27. Changes: Addition? Altered?	
28.	Exterior condition: good 29: Open to public? no		
30.	Other Surveys in which included: St. Louis Harbor Historic Properties Reconnaissance, 1987, U.S. Army Corps of Engineers survey (partially incl.)		
31.		tion of important features: Variegated "tire track" tex- ick is trimmed with terra cotta coping. Shaped parapet.	

Gabled wooden front

Double-rowlock segmentally arched windows have brick sills.

porch.

^{32.} History and Significance: C. J. Melles took out a building permit in 1925 for this building and the two buildings to the north (#64 & 65) of it. Melles designed and built the residences himself. The permit originally specified eleven dwellings for \$33,000, seven on Branch St. and four on Eleventh; the remaining eight have since been demolished, the ones on Branch to make way for the Mark Twain Expressway (Hwy. 70). The building has always been a residence.



SLCA5013-064

1.	No. 064	 Location of Negatives: Landmarks Association of St. Louis, Inc., 917 Locust, St. Louis, MO 63101
2.	City/County: City of St. Louis, MO	4. Prepared by: Cynthia Longwisch & Mary M. Stiritz, Landmarks Association of St. Louis, Inc.
5.	Date: 11/90	6. Sources of information: St. Louis Public Records,
7.	Building? Yes	City Hall; St. Louis Public Library; MO Historical Soc.
9.	Ownership: Private	8. On National Register or part of estab. district? No. 10. Visible from public road? Yes 11. Endangered? No.
12.	Street address:	3137 N. Eleventh 13. Style: Craftsman
14.	Date(s): 4/27/	1925
15.	Architect: owner 16. Builder: owner	
17.	Original Use: residential 18. Present Use: residential	
19.	Owner's name/address if known:	
20.	No. of stories: 1 21. Basement? yes 22. Wall construction: masonry	
23.	Foundation material: concrete 24. Roof type/material: flat	
25.	No. Bays: Front 3 Side 3 25. Wall treatment: textured brick	
26.	Plan shape: rectangular 27. Changes: Addition? Altered?	
28.	Exterior condition: good 29: Open to public? no	
30.	Other Surveys in which included: St. Louis Harbor Historic Properties Reconnaissance, 1987, U.S. Army Corps of Engineers survey (partially incl.	


Double-rowlock segmentally arched windows have brick sills. Gabled wooden front

porch.

^{32.} History and Significance: C. J. Melles took out a building permit in 1925 for this building and the two buildings flanking it (#63 & 65). Melles designed and built the residences himself. The permit originally specified eleven dwellings for \$33,000, seven on Branch St. and four on Eleventh; the remaining eight have since been demolished, the ones on Branch to make way for the Mark Twain Expressway (Hwy. 70). This building has always been a residence.



TROADWAY INDUSTRIAL SURVEY IT #64 FACINE



		,
1.	No. 065	3. Location of Negatives: Landmarks Association of St. Louis, Inc., 917 Locust, St. Louis, MO 63101
2.	City/County: City of St. Louis, MO	4. Prepared by: Cynthia Longwisch & Mary M. Stiritz, Landmarks Association of St. Louis, Inc.
5.	Date: 11/90	6. Sources of information: St. Louis Public Records,
7.	Building? Yes	City Hall; St. Louis Public Library; MO Historical Soc.
9.	Ownership: Private	8. On National Register or part of estab. district? No 10. Visible from public road? Yes 11. Endangered? No
12.	Street address:	3139 N. Eleventh 13. Style: Craftsman
14.	Date(s): 4/27/	1925
15.	Architect: owner 16. Builder: owner	
17.	Original Use: residential 18. Present Use: residential	
19.	Owner's name/address if known:	
20.	No. of stories: 1 21. Basement? yes 22. Wall construction: masonry	
23.	Foundation material: concrete 24. Roof type/material: flat	
25.	No. Bays: Fron	t 3 Side 3 25. Wall treatment: textured brick
26.	Plan shape: rectangular 27. Changes: Addition? Altered?	
28.	Exterior condition: good 29: Open to public? no	
30.	Other Surveys in which included: St. Louis Harbor Historic Properties Reconnaissance, 1987, U.S. Army Corps of Engineers survey (partially incl.	

31. Further description of important features: Variegated "tire track" textured red & mixed brick is trimmed with terra cotta coping. Shaped parapet. Double-rowlock segmentally arched windows have brick sills. Gabled wooden front porch.

32. History and Significance: C. J. Melles took out a building permit in 1925 for this building and the two buildings to its south (#63 & 64). Melles designed and built the residences himself. The permit originally specified eleven dwellings for \$33,000, seven on Branch St. and four on Eleventh; the remaining eight have since been demolished, the ones on Branch to make way for the Mark Twain Expressway (Hwy. 70). The building has always been a residence.



SLEA5013-066

1.	No. 066	3. Location of Negatives: Landmarks Association of St. Louis, Inc., 917 Locust, St. Louis, MO 63101	
2.	City/County: City of St. Louis, MO	4. Prepared by: Cynthia Longwisch & Mary M. Stiritz, Landmarks Association of St. Louis, Inc.	
5.	Date: 11/90	6. Sources of information: St. Louis Public Records, City Hall; St. Louis Public Library; MO Historical Soc.	
7.	Building? Yes		
9.	Ownership:	8. On National Register or part of estab. district? No	
	Private	10. Visible from public road? Yes 11. Endangered? No	
12.	Street address:	3141 N. Eleventh 13. Style:	
14.	Date(s): c. 1890		
15.	Architect: 16. Builder:		
17.	Original Use: residential 18. Present Use: vacant		
19.	Owner's name/address if known:		
20.	No. of stories: 2 21. Basement? yes 22. Wall construction: masonry		
23.	Foundation material: limestone 24. Roof type/material: flat		
25.	No. Bays: Front 2 Side 3 25. Wall treatment: red & painted brick		
26.	Plan shape: rectangular 27. Changes: Addition? Altered? yes		
28.	Exterior condition: fair/poor 29: Open to public? no		
30.	-	n which included: St. Louis Harbor Historic Properties 1987, U.S. Army Corps of Engineers survey (partially incl.)	


Further description of important features: Windows have segmental soldier arches, rounded pressed-brick jambs and stone lugsills with brackets. Corbeled cornice. Quarry-faced foundation. Openings are all infilled with wood. unusual feature of this building is the side entrance.

History and Significance: No building permit was recorded for this dwelling. A permit for \$550 to alter the dwelling was taken out by John Schott in 1909. O. Fisher & Son completed the alteration.



BROADWAY INDUSTRUM SURVEY IT N. ELEVENTH (RIGHT)





1.	No. 069	3. Location of Negatives: Landmarks Association of	
		St. Louis, Inc., 917 Locust, St. Louis, MO 63101	
2.	City/County: City of St. Louis, MO	4. Prepared by: Cynthia Longwisch & Mary M. Stiritz, Landmarks Association of St. Louis, Inc.	
5.	Date: 11/90	6. Sources of information: St. Louis Public Records,	
7.	Building? Yes	City Hall; St. Louis Public Library; MO Historical Soc.	
9. Ownersh Private	Ownershin	8. On National Register or part of estab. district? No	
	-	10. Visible from public road? Yes 11. Endangered? No	
12.	Street address: 3142 N. Eleventh 13. Style: commercial		
14.	Date(s): 6/7/1900		
15.	Architect: 16. Builder: owner		
17.	Original Use: wagon shed 18. Present Use: industrial		
19.	Owner's name/address if known:		
20.	No. of stories: 1 21. Basement? 22. Wall construction: masonry		
23.	Foundation material: stone 24. Roof type/material: flat		
25.	No. Bays: Front 8 Side 25. Wall treatment: red brick		
26.	Plan shape: trapezoid 27. Changes: Addition? Altered?		
28.	Exterior condition: good 29: Open to public? no		
30.	Other Surveys in which included: St. Louis Harbor Historic Properties Reconnaissance, 1987, U.S. Army Corps of Engineers survey (partially incl.		

- 31. Further description of important features: This building is unusual in that the only part of it visible from the street appears basementlike. The interior height is actually the equivalent of about 1-1/2 stories due to the slope of the site. Double-rowlock segmentally arched windows are spaced at regular intervals just above the stone "foundation" (really a (cont'd. below)
- 32. History and Significance: retaining wall). A permit was taken out for a wagon shed and stone retaining wall in 1900 by the Yerkes & Finan Woodworking Machine Company for \$450. The company also owned the factory next door at 3145-51 N. Ninth (#70).



EACING

3. Location of Negatives: Landmarks Association of

1. No. 071



	NO. 071	J.		_	Locust, St. Louis, MO 63101
2.	City/County: City of St. Louis, MO	4.	Prepared by	y: Cynthia	Longwisch & Mary M. Stiritz, n of St. Louis, Inc.
5.	Date: 11/90	6.			on: St. Louis Public Records,
7.	Building? Yes				lic Library; MO Historical Soc.
9.	Ownership: Private	10.			or part of estab. district? No road? Yes 11. Endangered? No
12.	Street address:	3156	-58 N. E leve	enth 13.	Style: Italianate
14.	Date(s): 7/3/1884				
15.	Architect: 16. Builder:			der:	
17.	Original Use: residential 18. Present Use: vacant				
19.	Owner's name/ad	dress	if known:		
20.	No. of stories:	2	21. Basem	nent? yes	22. Wall construction: masonry
23.	Foundation mate	rial:	limestone	24. Ro	of type/material: flat
25.	No. Bays: Front 4 Side 1		25. Wa	ll treatment: red brick	
26.	Plan shape: trapezoid 27.			Changes:	Addition? Altered? yes
28.	Exterior condition: poor 29: Open to public? no			pen to public? no	
30.	=				s Harbor Historic Properties ngineers survey (partially incl.)
unus in.	t to accomdodate suallly tall. Se	the d gmenta sed-br	iagonal line lly arched s ick panels a	e of the so soldier-cou are inset l	This building was a duplex treet. Original openings were ursed openings had been bricked below second-story windows. rapet. This (cont'd. below)

^{32.} History and Significance: building had just been substantially burned in a fire the night before the photo was taken. W. C. Richardson took out the building permit for this duplex in 1884 for \$5,000. The building has always been a residence.



NORTH BRUATWAY INTUSTRUST SURVEY # 31%-58 N. ELEVENTH FACING NE

ST. LOUIS MO

1/90

SLCAS 013-169

1.	No. 152	3. Location of Negatives: Landmarks Association of St. Louis, Inc., 917 Locust, St. Louis, MO 63101	
2.	City/County: City of St. Louis, MO	4. Prepared by: Cynthia Longwisch & Mary M. Stiritz, Landmarks Association of St. Louis, Inc.	
5.	Date: 11/90	6. Sources of information: St. Louis Public Records,	
7.	Building? Yes	City Hall; St. Louis Public Library; MO Historical Soc. 8. On National Register or part of estab. district? No	
9.	Ownership: Private	8. On National Register or part of estab. district? No 10. Visible from public road? Yes 11. Endangered? No	
12.	Street address: 1-21 Angelica, rear 13. Style: industrial		
14.	Date(s): 12/6/1926; 5/4/1903 (see #32 below)		
15.	Architect: G. Becker (1903) 16. Builder: Barnard Stock (1903)		
17.	Original Use: planing mill 18. Present Use: commercial		
19.	Owner's name/address if known: Lange Stegmann Fertilizer Co.		
20.	No. of stories: n/a 21. Basement? unk. 22. Wall construction: frame?		
23.	Foundation material: concrete 24. Roof type/material: monitor/metal		
25.	No. Bays: Front 2 Side unk. 25. Wall treatment: corrugated iron		
26.	Plan shape: rectangular 27. Changes: Addition? Altered? yes		
28.	Exterior condition: good 29: Open to public? no		
30.	Other Surveys in which included: St. Louis Harbor Historic Properties Reconnaissance, 1987, U.S. Army Corps of Engineers survey (partially incl.		

31. Further description of important features: This building has a monitor roof with corrugated fiberglas clerestory. High concrete foundation gives way to complete sheathing with corrugated iron. Loading bay in gable end and west end of south elevation.

^{32.} History and Significance: Conflicting information is given in the building permits for this building. A 1903 permit for a \$10,000 architect-designed planing mill was taken out for this address by the Lothman Cypress Company; it seems that it was for a brick building. A 1926 permit for 21 Angelica was granted to the General Metal Refg. Co. for a \$15,000 alteration to a factory. Since no factory per se had been built on this site to our knowledge, it would seem that the permit was for sheathing the older building.



152 NORTH BROADLEY INDUSTRURE SURVEY IT
1 AND BELICA
FACING NE

ST. LOUIS, MO

1.			
	No. 151	 Location of Negatives: Landmarks Association of St. Louis, Inc., 917 Locust, St. Louis, MO 63101 	
2.	City/County: City of St. Louis, MO	4. Prepared by: Cynthia Longwisch & Mary M. Stiritz, Landmarks Association of St. Louis, Inc.	
5.	Date: 11/90	6. Sources of information: St. Louis Public Records,	
7.	Building? Yes	City Hall; St. Louis Public Library; MO Historical Soc.	
9.	Ownership:	8. On National Register or part of estab. district? No	
	Private	10. Visible from public road? Yes 11. Endangered? No	
12.	Street address:	1 Angelica 13. Style: industrial	
14.	Date(s): 1/8/1904		
15.	Architect: G. Becker 16. Builder: J. P. Reichers		
17.	Original Use: warehouse 18. Present Use: warehouse		
19.	Owner's name/address if known: Lange Stegmann Fertilizer Co.		
20.	No. of stories: 2 21. Basement? unk. 22. Wall construction: masonry		
23.	Foundation material: stone 24. Roof type/material: end gables		
25.	No. Bays: Front 2 Side 25. Wall treatment: painted brick		
26.	Plan shape: rectangular 27. Changes: Addition? yes Altered? yes		
28.	Exterior condit	ion: good 29: Open to public? no	
30.	-	which included: St. Louis Harbor Historic Properties 1987, U.S. Army Corps of Engineers survey (partially incl.)	

- 31. Further description of important features: Roofline has two end gables, each surmounted by a gable of the same pitch to provide a clerestory (sheathed with corrugated fiberglas see photo #150 for better view). Gable ends covered with corrugated iron. All original openings have been bricked in with the exception of two large garage bays.
- 32. History and Significance: The Lothman Cypress Co. hired architect G. Becker to design and J. P. Reichers to construct this warehouse for \$7,000 in 1904. The Lothman company operated a planing mill in this city block, specializing in "air-dried Louisiana red cypress." This building has been owned by the Lange Stegmann Fertilizer Company since 1927.



|5| NORTH BROADWHY INDUSTRIAL SURVEY III

55. LOUIS, MO

5LCA5013-078

1.	No. 149	3. Location of Negatives: Landmarks Association of St. Louis, Inc., 917 Locust, St. Louis, MO 63101		
2.	City/County: City of St. Louis, MO	4. Prepared by: Cynthia Longwisch & Mary M. Stiritz, Landmarks Association of St. Louis, Inc.		
5.	Date: 11/90	6. Sources of information: St. Louis Public Records,		
7.	Building? Yes	City Hall; St. Louis Public Library; MO Historical Soc.		
9.	. Ownership:	8. On National Register or part of estab. district? No		
	Private	10. Visible from public road? Yes 11. Endangered? No		
12.	Street address:	9 Angelica 13. Style: commercial		
14.	Date(s): 8/27/1940			
15.	Architect:	16. Builder:		
17.	Original Use:	commercial 18. Present Use: warehouse		
19.	Owner's name/address if known: Lange Stegmann Fertilizer Co.			
20.	No. of stories: 1 21. Basement? unk. 22. Wall construction: maso			
23.	Foundation mate	rial: stone 24. Roof type/material: flat		
25.	No. Bays: Fron	t 3 Side 2 25. Wall treatment: painted brick		
26.	Plan shape: L	27. Changes: Addition? Altered? yes		
28.	Exterior condit	ion: good 29: Open to public? no		
30.	-	n which included: St. Louis Harbor Historic Properties 1987. U.S. Army Corps of Engineers survey (partially incl.)		

- Reconnaissance, 1987, U.S. Army Corps of Engineers survey (partially incl.)
- Further description of important features: Side openings in this building are overhead garage-door bays. Original front elevation openings have been infilled with brick and wood. Terra cotta coping.

History and Significance: This building was built in 1940 by Carroll P. Poland for use as a warehouse. It cost \$1,500 to build. Poland operated the Poland Oil Company at 4070 North Main.



#149 NORTH BROADWAY MAUSTRUM SURVEY II
9 ANGELICA
FACILIA NUI

57. LOUB, MO

56CAS013-012

1.	No. 150	3. Location of Negatives: Landmarks Association of St. Louis, Inc., 917 Locust, St. Louis, MO 63101			
2.	City/County: City of St. Louis, MO	4. Prepared by: Cynthia Longwisch & Mary M. Stiritz, Landmarks Association of St. Louis, Inc.			
5.	Date: 11/90	6. Sources of information: St. Louis Public Records, City Hall; St. Louis Public Library; MO Historical Soc.			
7.	Building? Yes				
9.	Ownership:	8. On National Register or part of estab. district? No			
	Private	10. Visible from public road? Yes 11. Endangered? No			
12.	Street address:	21 Angelica 13. Style: commercial			
14.	Date(s): 11/24/1903				
15.	Architect: 16. Builder: Barnard Stock				
17.	Original Use:	office 18. Present Use: office			
19.	Owner's name/add	dress if known: Lange Stegmann Fertilizer Co.			
20.	No. of stories:	1 21. Basement? yes 22. Wall construction: masonry			
23.	Foundation mate	rial: limestone 24. Roof type/material: flat			
25.	No. Bays: Front 5 Side 7 25. Wall treatment: painted brick				
26.	Plan shape: rec	tangular 27. Changes: Addition? yes Altered?			
28.	Exterior condit	ion: good 29: Open to public? limited			
30.		n which included: St. Louis Harbor Historic Properties 1987, U.S. Army Corps of Engineers survey (partially incl.)			

stone lugsills. Part of each window is infilled. Wood door in center of front

elevation apparently no longer in use; entrance is now through a side door (under a new wood porch). Terra cotta coping. Storage (cont'd. below)

^{32.} History and Significance: building is attached to east side. The Lothman Cypress Company hired Barnard Stock to build this office for \$4,000 in 1903. The company operated a planing mill at this location, specializing in "air-dried Louisiana red cypress." The Lange Stegmann Fertilizer Co. has been in operation here since 1927.



SLCAKO13-673

1.	No. 143	3. Location of Negatives: Landmarks Association of St. Louis, Inc., 917 Locust, St. Louis, MO 63101			
2.	City/County: City of St. Louis, MO	4. Prepared by: Cynthia Longwisch & Mary M. Stiritz, Landmarks Association of St. Louis, Inc.			
5.	Date: 11/90	6. Sources of information: St. Louis Public Records,			
7.	Building? Yes	City Hall; St. Louis Public Library; MO Historical Soc.			
9.	Ownership: Private	8. On National Register or part of estab. district? N 10. Visible from public road? Yes 11. Endangered? N			
12.	Street address:	88 Angelica 13. Style: commercial			
14.	. Date(s): 8/16/1912				
15.	Architect:	16. Builder: Jacob Schenk			
17.	Original Use:	office 18. Present Use: office			
19.	Owner's name/ad	dress if known: Herman Oak Leather Co.			
20.	No. of stories:	2 21. Basement? yes 22. Wall construction: masonry			
23.	Foundation mate	rial: limestone 24. Roof type/material: flat			
25.	No. Bays: Fron	t 8 Side 7 & 7 25. Wall treatment: brown brick			
26.	5. Plan shape: irregular 27. Changes: Addition? A				
28.	Exterior condit	ion: good 29: Open to public? limited			
30.		n which included: St. Louis Harbor Historic Properties 1987, U.S. Army Corps of Engineers survey (partially incl.)			
31.	-	tion of important features: This building is set on a diagwith a projecting center entrance pavilion highlighted by a			

32. History and Significance: The Mississippi Glass Company took out the permit to build this \$15,500 office building in 1912. The Herman Oak Leather Company later moved into the building, which adjoined its tannery, and still owns the building.

reached by either of a pair of flanking steps.

panelled terra cotta cornice. Double brick string cornice courses extend across the wings. Flat arches, stone sills; one-over-one panes. Centered entrance is



143 NORTH BROADWAY INDUSTRIAL SURVEY IT
68 ANSELICA
FACING SE

9/90

SLC15-07

1.	No. 142	3. Location of Negatives: Landmarks Association of St. Louis, Inc., 917 Locust, St. Louis, MO 63101			
2.	City/County: City of St. Louis, MO	4. Prepared by: Cynthia Longwisch & Mary M. Stiritz, Landmarks Association of St. Louis, Inc.			
5.	Date: 11/90	6. Sources of information: St. Louis Public Records, City Hall; St. Louis Public Library; MO Historical Soc.			
7.	Building? Yes				
9.	Ownership:	8. On National Register or part of estab. district? No			
	Private	10. Visible from public road? Yes 11. Endangered? No			
12.	Street address:	106-10 Angelica 13. Style: commercial			
14.	Date(s): 7/8/19	21; 8/7/1925			
15.	Architect:	16. Builder: Gary Construction Co.			
17.	Original Use:	ffice 18. Present Use: office			
19.	Owner's name/add	ress if known: Subsurface Construction, Inc.			
20.	No. of stories:	1 21. Basement? yes 22. Wall construction: masonry			
23.	Foundation mate	ial: concrete 24. Roof type/material: flat			
25.	No. Bays: Fron	8 Side 4 25. Wall treatment: painted brick			
26.	Plan shape: L	27. Changes: Addition? yes Altered?			
28.	Exterior condit	on: good 29: Open to public? limited			
30.		which included: St. Louis Harbor Historic Properties 1987, U.S. Army Corps of Engineers survey (partially incl.)			

31. Further description of important features: Building has an awninglike roof on the north and west sides, covered in asphalt shingles and supported by heavy wood brackets. Window arches are obscured by this feature. Terra cotta coping. One-story brick rear ell addition.

^{32.} History and Significance: This building was constructed in 1921 for Gideon Anderson & Co. by Gary Construction Co. at a cost of \$4,000. Gideon Anderson had a \$2,500 addition to the office built in 1925, to make the building an L shape. They were a realty company.



SLCA5013-75

1.	No. 141	3. Location of Negatives: Landmarks Association of St. Louis, Inc., 917 Locust, St. Louis, MO 63101			
2.	City/County: City of St. Louis, MO	4. Prepared by: Cynthia Longwisch & Mary M. Stiritz, Landmarks Association of St. Louis, Inc.			
5.	Date: 11/90	6. Sources of information: St. Louis Public Records,			
7.	Structure: yes	City Hall; St. Louis Public Library; MO Historical Soc.			
	A 1.	8. On National Register or part of estab. district? No			
9.	Ownership: Private	10. Visible from public road? Yes 11. Endangered? No			
12.	Street address:	210 Angelica 13. Style: industrial			
14.	Date(s): c. 1920				
15.	Architect:	16. Builder:			
17.	Original Use:	shavings bin 18. Present Use: shavings bin			
19.	Owner's name/ad	dress if known: Harrison Lumber Co.			
20.	No. of stories:	n/a 21. Basement? no 22. Wall construction: frame			
23.	Foundation mate	rial: concrete 24. Roof type/material: n/a			
25.	No. Bays: Fron	t 2 Side 0 25. Wall treatment: corrugated iron			
26.	Plan shape: squ	are 27. Changes: Addition? yes Altered? yes			
28.	Exterior condit	ion: fair 29: Open to public? no			
30.		n which included: St. Louis Harbor Historic Properties 1987, U.S. Army Corps of Engineers survey (partially incl.)			

- 31. Further description of important features: This metal-covered shavings bin or vault is basically a metal-covered frame hopper to collect sawdust and wood shavings from the planing mill behind it. A newer cyclone collector is mounted on the top. Two loading bays covered in corrugated iron are located on the north elevation to provide access for unloading the bin.
- 32. History and Significance: The active building permits for this city block, which begin about 1918, are missing, so this building cannot be precisely dated; however, it has an old foundation and is found on older Sanborn maps.



#14

NORTH BROADBUY INDUSTRIAL SURVEY II 210 ABBEUCA FACING SE

9/90 MO

Location of Negatives: Landmarks Association of St. Louis, Inc., 917 Locust, St. Louis, MO 63101

Prepared by: Cynthia Longwisch & Mary M. Stiritz,

1.

2.

No.

135

City/County: City of St.

SLCA5013-076

	Louis, MO	ouis, MO Landmarks Association of St. Louis, Inc.					
5.	Date: 11/90	I .	· · · · · · · · · · · · · · · · · · ·				
7.	Building? Yes		City Hall; St. Louis Public Library; MO Historical Soc.				
9.	Ownership:	8. On Natio	cional Register or part of estab. district? No				
	Private	10. Visible	fro	om public	road? Yes	11. Endangered? No	
12.	Street address:	812 Angelica		13.	Style: co	mmercial	
14.	Date(s): c. 18	Date(s): c. 1883 - 1910					
15.	Architect:			16. Buil	der:		
17.	Original Use: stable?			Present	Use: vaca	nt	
19.	Owner's name/add	dress if known:	•				
20.	No. of stories: 1 21. Basem			ment? no	22. Wall	construction: masonry	
23.	Foundation material: brick			24. Ro	of type/mate	erial: flat	
25.	No. Bays: Front 3 Side 1			25. Wa	ll treatmen	t: painted brick	
26.	Plan shape: squ	are 2	27.	Changes:	Addition?	yes Altered? yes	
28.	Exterior condit	ion: fair/poor		29: 0	pen to publ	ic? no	
30.	Other Surveys in which included: St. Louis Harbor Historic Properties Reconnaissance, 1987, U.S. Army Corps of Engineers survey (partially incl.)						
sold the	ave begun as a s	mall shop or st ws that were or s slightly shor	tabl rigi rter	le (see 18 inally muc and cont	83 Hopkins) h longer. ains a flat	story building appears with segmentally A c. 1910 addition to -arched garage bay. (cont'd. below)	

History and Significance: The building is connected to 4051-57 N. Broadway

No permit could be found for this

(#136) by means of a small passageway.

building, which has apparently always been used commercially.



\$ 135 NORTH BROADWAY INDUSTRIAL SURVEY I.

ST. LOUIS, MO 8/90

(cont'd. below)

No. 154	3. Location of Negatives: Landmarks Association of St. Louis, Inc., 917 Locust, St. Louis, MO 63101			
City/County: City of St. Louis, MO	4. Prepared by: Cynthia Longwisch & Mary M. Stiritz, Landmarks Association of St. Louis, Inc.			
Date: 11/90	6. Sources of information: St. Louis Public Records,			
Building? Yes	City Hall; St. Louis Public Library; MO Historical Soc.			
Ownership: Private	8. On National Register or part of estab. district? No 10. Visible from public road? Yes 11. Endangered? No			
Street address:	815 Angelica 13. Style: (residential) vernacula			
Date(s): 3/16/2	1914			
Architect:	16. Builder: Frederick C. Aufderheide			
Original Use:	church 18. Present Use: junkyard storage			
Owner's name/address if known:				
No. of stories:	1 21. Basement? unk. 22. Wall construction: masonry			
Foundation mate	rial: unknown 24. Roof type/material: flat			
No. Bays: Fron	t 3 Side 4 25. Wall treatment: painted brick			
Plan shape: rectangular 27. Changes: Addition? Altered? ye				
Exterior condit	ion: poor 29: Open to public? no			
-	n which included: St. Louis Harbor Historic Properties 1987, U.S. Army Corps of Engineers survey (partially incl.			
	City/County: City of St. Louis, MO Date: 11/90 Building? Yes Ownership: Private Street address: Date(s): 3/16/2 Architect: Original Use: Owner's name/add No. of stories: Foundation mate: No. Bays: Front Plan shape: rec Exterior condit			

segmental arches top windows and doors, of which all visible from the street have been infilled. Metal used for coping on stepped parapet and profiled

Brick corbelling below cornice. Building now sits


cornice.

^{32.} History and Significance: behind a chainlink fence in the midst of a junkyard, sadly obscured. The Apostolic Christian Congregation of St. Louis took out a permit to build the church for \$1,900. The congregation remained in this building at least through 1940. Sometime later, the building was known as the Jesus' Name Mission. It has evidently been in its current plight for quite some time.



154 NORW BECADURY INDUSTRIAL SURVEY II.
815 ANGELICA
FACING NW

57. LOUIS, MO 9/90



1.					
2.	City/County: City of St. Louis, MO	St. Louis, Inc., 917 Locust, St. Louis, MO 63101 4. Prepared by: Cynthia Longwisch & Mary M. Stiritz, Landmarks Association of St. Louis, Inc.			
5.	Date: 11/90		information: St. Louis Public Records,		
7.	Building? Yes		Louis Public Library; MO Historical Soc.		
9.	Ownership:	8. On National	Register or part of estab. district? No		
	Private	10. Visible from public road? Yes 11. Endangered? No			
12.	Street address: 11-15 Angelrodt 13. Style: commercial				
14.	Date(s): 3/14/1903; 6/10/1919				
15.	Architect: Victor Klutho 16. Builder:				
17.	Original Use: office 18. Present Use: office				
19.	Owner's name/ad	dress if known: T	homas & Proetz Lumber Co.		
20.	No. of stories: 1 21. Basement? yes 22. Wall construction: masonry				
23.	Foundation material: stone 24. Roof type/material: flat				
25.	No. Bays: Front 5 Side 10 25. Wall treatment: brick veneer				
26.	Plan shape: rec	tangular 27.	Changes: Addition? yes Altered? yes		
28.	Exterior condit	ion: good	29: Open to public? limited		
30.			St. Louis Harbor Historic Properties orps of Engineers survey (partially incl		
at t From	ter entrance surr the corners. Sin nt windows have f	ound featuring raigled wood awning halar arches, stone	features: White terra cotta coping and sed ornamental patterning. Brick quoini as Craftsmanlike heavy wood brackets. sills, six-over-one paning. Side window r addition; one-story (cont'd. belo		

32. History and Significance: rear "log cabin" addition attached to the east elevation. The Thomas & Proetz Lumber Company took out the \$500 building permit in 1903 for their office; the permit allowed them to build either a brick veneer structure or one clad in metal; it is surmised that the final building probably exceeded the \$500 estimate. The Pelligreen Construction Co. built the \$7.000 rear addition, according to a permit Thomas & Proetz took out on 6/10/19.



y/County: y of St. is, MO e: 11/90 Iding? Yes ership: vate eet address: e(s): 4/15/ nitect: ginal Use:	1949 16. Builder:				
lding? Yes ership: vate eet address: e(s): 4/15/	City Hall; St. Louis Public Library; MO Historical Soc 8. On National Register or part of estab. district? 10. Visible from public road? Yes 11. Endangered? 200 Angelrodt 13. Style: industrial 1949 16. Builder:				
ership: vate eet address: e(s): 4/15/	8. On National Register or part of estab. district? 10. Visible from public road? Yes 11. Endangered? 1200 Angelrodt 13. Style: industrial 1949 16. Builder:				
vate eet address: e(s): 4/15/	10. Visible from public road? Yes 11. Endangered? 1 200 Angelrodt 13. Style: industrial (1949) 16. Builder:				
e(s): 4/15/	1949 16. Builder:				
nitect:	16. Builder:				
ginal Use:	warehouse 18. Present Use: warehouse				
e Periode in Proposition (Periode State St	Original Use: warehouse 18. Present Use: warehouse				
Owner's name/address if known: Donley Pipe & Supply Co.					
No. of stories: 1 21. Basement? unk. 22. Wall construction: masonry					
Foundation material: concrete 24. Roof type/material: flat					
No. Bays: Front 8 Side 25. Wall treatment: red brick					
n shape: L	27. Changes: Addition? Altered?				
Exterior condition: good 29: Open to public? no					
Other Surveys in which included: St. Louis Harbor Historic Properties Reconnaissance, 1987, U.S. Army Corps of Engineers survey (partially incl.					
	Bays: From shape: L erior condit				

^{32.} History and Significance: The Donley Pipe & Supply Co. built this warehouse in 1949 for \$10,000. Because of its ubiquitous industrial style, this building was included in the survey before its history was investigated.



108

NOON BOODWAY INDUSTRIAL SURVEY IL 200 AGELEOUT PKING SU

ST. 60415, MO

75

5LCA5013-08-1

MISSOURI OFFICE OF HISTORIC PRESERVATION ARCHITECTURAL/HISTORIC INVENTORY SURVEY FORM

1.					
2.	City/County: City of St. Louis, MO	St. Louis, Inc., 917 Locust, St. Louis, MO 63101 4. Prepared by: Cynthia Longwisch & Mary M. Stiritz, Landmarks Association of St. Louis, Inc.			
5.	Date: 11/90	6. Sources of information: St. Louis Public Records,			
7.	Building? Yes	City Hall; St. Louis Public Library; MO Historical Soc.			
9.	Ownership:	8. On National Register or part of estab. district? No			
_	Private	10. Visible from public road? Yes 11. Endangered? No			
12.	Street address: 816 Angelrodt 13. Style: cottage				
14.	Date(s): c. 1860 - 70				
15.	Architect: 16. Builder:				
17.	Original Use: residential 18. Present Use: residential				
19.	Owner's name/address if known:				
20.	No. of stories: 1-1/2 21. Basement? yes 22. Wall construction: frame				
23.	. Foundation material: stone? 24. Roof type/material: end gable				
25.	. No. Bays: Front 3 Side 2 25. Wall treatment: permastone				
26.	Plan shape: rectangular 27. Changes: Addition? yes Altered? yes				
28.	Exterior condit	ion: good 29: Open to public? no			
30.		n which included: St. Louis Harbor Historic Properties 1987, U.S. Army Corps of Engineers survey (partially incl.			
31.	Further description of important features: Simple frame cottage has been				

31. Further description of important features: Simple frame cottage has been altered by the use of permastone. A one-story, aluminum-sided frame addition extends to the west. Openings have been modernized.

32. History and Significance: Owner maintains that this house was here "before the sewers came in the 1840s." This has not been verified; however, it does appear on the 1875 Compton & Dry map, and frame has not been allowed in building construction almost since the institution of building permits. Owner maintains that this is the oldest house in the entire area, which is why it was included in this survey despite its alterations.




#104

NORTH BROADWAY INDUSTRIAL SURVEY II-816 ANGELRODT FACING SE

ST. LOUIS, MO

7/90



1.	No. 091	No. 091 3. Location of Negatives: Landmarks Association of St. Louis, Inc., 917 Locust, St. Louis, MO 63101			
2.	City/County: City of St. Louis, MO	4. Prepared by: Cynthia Longwisch & Mary M. Stiritz, Landmarks Association of St. Louis, Inc.			
5.	Date: 11/90	6. Sources of information: St. Louis Public Records,			
7.	Building? Yes	City Hall; St. Louis Public Library; MO Historical Soc.			
9.	Ownership:	8. On National Register or part of estab. district? No			
	Private	10. Visible from public road? Yes 11. Endangered? No			
12.	Street address: 910-12 Angelrodt 13. Style: vernacular				
14.	Date(s): c. 1870-5				
15.	Architect: 16. Builder:				
17.	Original Use: residential 18. Present Use: vacant				
19.	Owner's name/address if known:				
20.	No. of stories: 2 21. Basement? yes 22. Wall construction: masonry				
23.	Foundation material: limestone 24. Roof type/material: side gable				
25.	No. Bays: Front 5 Side 2 25. Wall treatment: red brick				
26.	Plan shape: rectangular 27. Changes: Addition? yes Altered? yes				
28.	Exterior condition: fair/good 29: Open to public? no				
30.	Other Surveys in which included: St. Louis Harbor Historic Properties Reconnaissance, 1987, U.S. Army Corps of Engineers survey (partially incl.)				
31.	Further descrip	tion of important features: Openings on the front elevation			
		ed soldier courses with stone sills. Single, centered door			
		All openings boarded. Corbelled brick cornice. West wall			
nas	barabered culmue	y. Stone water table. West side openings have no arches			

32. History and Significance: House appears on the 1875 Compton & Dry map. It appears to have always been used as a residence.

and brick sills - probably newer. Rear flounder addition.



1.	<u> i</u>			Negatives: Landmarks Association of Inc., 917 Locust, St. Louis, MO 63101				
2.	City/County: City of St. Louis, MO	4. Prepare	d by: (by: Cynthia Longwisch & Mary M. Stiritz, s Association of St. Louis, Inc.				
5.	Date: 11/90	<u> </u>				uis Public Records, ; MO Historical Soc		
7.	Building? Yes					estab. district?		
9.	Ownership: Private				or part of oad? Yes	11. Endangered?		
12.	Street address:	919 Benton		13.	Style: in	dustrial		
14.	Date(s): 6/8/1916; 5/8/1918							
15.	Architect:	16	. Build	ler:				
17.	Original Use: factory			Present	Use: indu	strial		
19.	Owner's name/ad	dress if known	•					
20.	No. of stories: 2 21. I		asemen	t? yes	22. Wall	construction: mason		
23.	Foundation material: stone			24. Roc	of type/mat	erial: flat		
25.	No. Bays: Front 5 Side 8			25. Wal	l treatmen	t: painted brick		
26.	Plan shape: modified L 27.		27. CI	hanges:	Addition?	yes Altered? ye		
28.	Exterior condit	ion: good	ART CALL IN THE SECTION	29: Or	en to publ	ic? no		
30.								

31. Further description of important features: Windows have multipane industrial metal sash with no arches and brick sills. Most first-floor openings are infilled. A tiny parapet coped with light terra cotta extends across the primary elevation. A one-story rear addition was build in 1918.

^{32.} History and Significance: W. C. Wahlers filed for a \$6,500 building permit for a factory in 1916; he installed a heating boiler in November of the same year. In May of 1918, Wahlers & Traher took out a permit for \$3,000 for the rear storeroom addition to the building. Neither Wahlers nor Wahlers & Traher are listed in city directories in pertinent years. The building was used primarily for auto repair during the 1950s.



SLCA5013-043


1.	No. 088	 Location of Negatives: Landmarks Association of St. Louis, Inc., 917 Locust, St. Louis, MO 63101 			
2.	City/County: City of St. Louis, MO	4. Prepared by: Cynthia Longwisch & Mary M. Stiritz, Landmarks Association of St. Louis, Inc.			
5.	Date: 11/90	6. Sources of information: St. Louis Public Records,			
7.	Building? Yes	City Hall; St. Louis Public Library; MO Historical Soc.			
9.	Ownership: Private	8. On National Register or part of estab. district? No 10. Visible from public road? Yes 11. Endangered? No			
12.	Street address: 15 Branch 13. Style: industrial				
14.	Date(s): 11/10/1897				
15.	Architect: 16. Builder:				
17.	Original Use: factory 18. Present Use: warehouse				
19.	Owner's name/address if known: Gaines Hardwood Lumber Co.				
20.	No. of stories: 1 & 2 21. Basement? no 22. Wall construction: masonry				
23.	Foundation material: concrete 24. Roof type/material: monitor				
25.	No. Bays: Fron	t 1 Side 25. Wall treatment: corrugated iron			
26.	Plan shape: rec	tangular 27. Changes: Addition? Altered? yes			
28.	Exterior condit	ion: good 29: Open to public? limited			
30.		n which included: St. Louis Harbor Historic Properties 1987, U.S. Army Corps of Engineers survey (partially incl.			
	ures double slid	tion of important features: The gable end of this building ing loading bay doors. The first-story sides are not erestory is covered with corrugated fiberglas to light the			

32. History and Significance: The Skaboura Dip Co. paid \$7,000 to build this building in 1897. The corrugated iron covering is in such good general condition that it seems likely that it is replacement material, as of course is the fiberglas covering the clerestory openings.

interior. Exposed wood rafter ends beneath wide overhanging eaves. Unusually

high concrete foundation.





1.	The state of the s				
2.	City/County: City of St. Louis, MO	St. Louis, Inc., 917 Locust, St. Louis, MO 63101 4. Prepared by: Cynthia Longwisch & Mary M. Stiritz, Landmarks Association of St. Louis, Inc.			
5.	Date: 11/90	÷	information: St. Louis Public Records,		
7.	Building? Yes	City nail; St. 1	Louis Public Library; MO Historical Soc.		
9.	Ownership:	8. On National	Register or part of estab. district? No		
	Ownership: Private	10. Visible from	m public road? Yes 11. Endangered? No		
12.	Street address: 19 Branch 13. Style: industrial				
14.	Date(s): c. 1920				
15.	Architect: 16. Builder:				
17.	Original Use: warehouse 18. Present Use: warehouse/office				
19.	Owner's name/ad	dress if known: G	aines Hardwoods		
20.	No. of stories: 1 21. Basement? no 22. Wall construction: masonr				
23.	Foundation material: concrete 24. Roof type/material: 2 side gable				
25.	No. Bays: Fron	t 5 Side 3	25. Wall treatment: corrugated iron		
26.	Plan shape: rec	tangular 27.	Changes: Addition? Altered? yes		
28.	Exterior condit	ion: good	29: Open to public? limited		
30.			St. Louis Harbor Historic Properties orps of Engineers survey (partially incl.		
is c	d be found that clearly old. The gable ends. The	describes the build roof and cornices configuration of	features: Although no building permit ding as it appears today, the foundation are new. Sliding loading dock doors in two gables conjoined lengthwise may belient, perhaps taller. (cont'd. below)		

32. History and Significance: If this were the case, it might be possible to locate a building permit. All the buildings in the Gaines Hardwood complex have been extremely well maintained — so well, in fact, that the ages of these frame buildings tend to be obscured as new roofs, siding and opening shapes are modernized. This is probably the greatest hazard of frame buildings; after a length of time, the sum of the new parts no longer equals the original total.



FLC ASOB-085

MISSOURI OFFICE OF HISTORIC PRESERVATION ARCHITECTURAL/HISTORIC INVENTORY SURVEY FORM

1.	No. 057	3. Location of Negatives: Landmarks Association of St. Louis, Inc., 917 Locust, St. Louis, MO 63101
2.	City/County: City of St. Louis, MO	4. Prepared by: Cynthia Longwisch & Mary M. Stiritz, Landmarks Association of St. Louis, Inc.
5.	Date: 11/90	6. Sources of information: St. Louis Public Records, City Hall; St. Louis Public Library; MO Historical Soc.
7.	Building? Yes	8. On National Register or part of estab. district? No
9.	Ownership:	6. On National Register or part of estab. district: No
	Private	10. Visible from public road? Yes 11. Endangered? No
12.	Street address: 24 Branch 13. Style: commercial	
14.	Date(s): 5/21/1897	
15.	Architect: 16. Builder:	
17.	Original Use: commercial 18. Present Use: commercial	
19.	Owner's name/address if known: Gaines Hardwood Lumber Co.	
20.	No. of stories: 1 21. Basement? unk. 22. Wall construction: fram	
23.	Foundation mate	rial: stone 24. Roof type/material: flat
25.	No. Bays: Front 3 Side 7 25. Wall treatment: wood shingles	
26.	Plan shape: rectangular 27. Changes: Addition? yes Altered?	
28.	Exterior condit	ion: good 29: Open to public? limited
30.	Other Surveys in which included: St. Louis Harbor Historic Properties Reconnaissance, 1987, U.S. Army Corps of Engineers survey (partially incl	

- 31. Further description of important features: Front elevation has a stepped parapet. Cornice is supported by profiled wood brackets and bears the name of the business. Rectangular openings are wood-framed, have 6-over-6 double-hung wood sash. Frame rear additions of several heights and sizes apparently built over a period of time.
- 32. History and Significance: H. G. Arndt took out the permit to build this frame office in 1897 for the handsome sum of \$150.00. Arndt had died by 1917 and T. E. Powe opened the Powehar Mill & Lumber Co. here. Harry D. Gaines was a clerk in the business at this time; it is apparently his name that the business carries today. The office is surrounded by a lumberyard and storage buildings.



5LC AS013-0918

1.	No. 083	3. Location of Negatives: Landmarks Association of St. Louis, Inc., 917 Locust, St. Louis, MO 63101
2.	City/County: City of St. Louis, MO	4. Prepared by: Cynthia Longwisch & Mary M. Stiritz, Landmarks Association of St. Louis, Inc.
5.	Date: 11/90	6. Sources of information: St. Louis Public Records, City Hall; St. Louis Public Library; MO Historical Soc.
7.	Building? Yes	
9.	Ownership: Private	8. On National Register or part of estab. district? No 10. Visible from public road? Yes 11. Endangered? No
12.	Street address: 47 Branch 13. Style: industrial	
14.	Date(s): 12/10/1900	
15.	Architect: 16. Builder: Anton Wind	
17.	Original Use: factory 18. Present Use: industrial	
19.	Owner's name/address if known: Alpha Plastics, Inc.	
20.	No. of stories: 3 21. Basement? yes 22. Wall construction: mason:	
23.	Foundation material: stone 24. Roof type/material: flat	
25.	No. Bays: Front 15 Side 12 25. Wall treatment: red brick	
26.	Plan shape: modif. rectang. 27. Changes: Addition? Altered? yes	
28.	Exterior condition: good 29: Open to public? no	
30.	Other Surveys in which included: St. Louis Harbor Historic Properties Reconnaissance, 1987, U.S. Army Corps of Engineers survey (partially incl.	
31. dows	Further description of important features: All first and second-story wing and the third-story windows on the Hall St. elevation have double-rowlock	

32. History and Significance: Fred Westerbeck hired general contractor Anton Wind to construct this \$12,000 "tin can factory" in 1900. German-born Wester-

beck was president of Columbia Can Co. (see attached).

segmentally-arched windows. Brick sills. All openings have been infilled or had modern replacements. Hall St. elevation has a plain parapet and brick cor-



-	The state of the s	
1.	No. 082	3. Location of Negatives: Landmarks Association of St. Louis, Inc., 917 Locust, St. Louis, MO 63101
2.	City/County: City of St. Louis, MO	4. Prepared by: Cynthia Longwisch & Mary M. Stiritz, Landmarks Association of St. Louis, Inc.
5.	Date: 11/90	6. Sources of information: St. Louis Public Records, City Hall; St. Louis Public Library; MO Historical Soc.
7.	Building? Yes	
9.	Ownership: Private	8. On National Register or part of estab. district? No
		10. Visible from public road? Yes 11. Endangered? No
12.	Street address: 59 Branch 13. Style: industrial	
14.	Date(s): 9/4/1909	
15.	Architect: 16. Builder:	
17.	Original Use: factory 18. Present Use: industrial	
19.	Owner's name/address if known: Alpha Plastics, Inc.	
20.	No. of stories: 3 21. Basement? unk. 22. Wall construction: mason:	
23.	Foundation material: unknown 24. Roof type/material: shallow gal	
25.	No. Bays: Front 8 Side 17 25. Wall treatment: red brick	
26.	Plan shape: modif. rectang. 27. Changes: Addition? Altered? yes	
28.	Exterior condition: good 29: Open to public? no	
30.	Other Surveys in which included: St. Louis Harbor Historic Properties Reconnaissance, 1987, U.S. Army Corps of Engineers survey (partially incl	
0.4	-	


- 31. Further description of important features: Windows have triple-rowlock segmental arches, stone sills, and three-over-three horizontally-hinged sash. Piers divide the building into recessed panels that are topped with corbelling. Some windows infilled with brick. Terra cotta coping. Southwest & souteast corners and small parapet rise above the roofline. Building is (cont'd. below)
- 32. History and Significance: attached to building on its east (#83) by a catwalk/passageway. The permit for this factory building was taken out in 1909 by Missouri Can Company for \$50,000.



#82 NORTH ERCHDURY INDUSTRIAL SURVEY II

55- LOUS, MO

7/90



(cont'd below)

1.	No. 059	3. Location of Negatives: Landmarks Association of St. Louis, Inc., 917 Locust, St. Louis, MO 63101
2.	City/County: City of St. Louis, MO	4. Prepared by: Cynthia Longwisch & Mary M. Stiritz, Landmarks Association of St. Louis, Inc.
5.	Date: 11/90	6. Sources of information: St. Louis Public Records,
7.	Building? Yes	City Hall; St. Louis Public Library; MO Historical Soc.
9.	Ownership: Private	8. On National Register or part of estab. district? No 10. Visible from public road? Yes 11. Endangered? No
12.	Street address:	1111-13 Branch 13. Style:
14.	Date(s): 1/4/1907	
15.	Architect: August Schuerman 16. Builder: Bernhardt Wussler	
17.	Original Use: residential 18. Present Use: residential	
19.	Owner's name/address if known:	
20.	No. of stories: 3 21. Basement? yes 22. Wall construction: mason:	
23.	Foundation material: limestone 24. Roof type/material: flat	
25.	No. Bays: Front 5 ea.Side 3 25. Wall treatment: red brick	
26.	Plan shape: rectangular 27. Changes: Addition? Altered? yes	
28.	Exterior condition: good 29: Open to public? no	
30.	Other Surveys in which included: St. Louis Harbor Historic Properties Reconnaissance, 1987, U.S. Army Corps of Engineers survey (partially incl	
31.	Further descrip	tion of important features: This is actually two separate being counted as one unit. Gauged brick arches and stone

sills with egg & dart molding beneath highlight the 6-over-6 double-hung wood sash windows. Inset wood panels with diamonds throughout are new additions.

Stone water table; quarry-faced

Elaborately corbeled cornice.

^{32.} History and Significance: foundation. Entries are recessed at the top of steps. New metal balconies were installed across the fronts c. late 1980s. Like #58 and #60, this pair of buildings was built by H. Bressler in 1907; his cost was \$8,000. Bressler hired General Contractor Bernhardt Wussler for the job; Wussler was quite active in St. Louis around the turn of the century. No information was available on Bressler, who evidently built the buildings as an investment. The buildings have always been used as residences.



SLC A5013-044

1.	No. 060	2 Togetier of Negatives, Independs Aggoriation of
1.	NO. 000	 Location of Negatives: Landmarks Association of St. Louis, Inc., 917 Locust, St. Louis, MO 63101
2.	City/County: City of St. Louis, MO	4. Prepared by: Cynthia Longwisch & Mary M. Stiritz, Landmarks Association of St. Louis, Inc.
5.	Date: 11/90	6. Sources of information: St. Louis Public Records,
7.	Building? Yes	City Hall; St. Louis Public Library; MO Historical Soc.
9	9. Ownership: Private	8. On National Register or part of estab. district? No
		10. Visible from public road? Yes 11. Endangered? No
12.	Street address: 1115-19 Branch 13. Style:	
14.	Date(s): 1/4/1907	
15.	Architect: August Schuerman 16. Builder: Bernhardt Wuss'ler	
17.	Original Use: residential 18. Present Use: residential	
19.	Owner's name/address if known:	
20.	No. of stories: 3 21. Basement? yes 22. Wall construction: mason	
23.	Foundation material: limestone 24. Roof type/material: flat	
25.	No. Bays: Front 10 Side 3 25. Wall treatment: red brick	
26.	Plan shape: modif. rectang. 27. Changes: Addition? Altered? yes	
28.	Exterior condition: good 29: Open to public? no	
30.	Other Surveys in which included: St. Louis Harbor Historic Properties Reconnaissance, 1987, U.S. Army Corps of Engineers survey (partially incl.	


- 31. Further description of important features: This triple tenement building is of the same design as #59. Gauged brick arches and stone sills with egg & dart molding beneath highlight 6-over-6 double-hung wood sash. Inset wood panels with diamonds are recent additions. Elaborately corbeled cornice. Stone water table. Quarry-faced foundation. Recessed doorways. New metal balcony.
- 32. History and Significance: H. Bressler took out the building permit for this building in 1907 for \$12,000. Bressler hired General Contractor Bernhardt Wussler to build the tenement; Bressler and Wussler also worked together on two other projects in this city block in 1907. No information could be found on Bressler; however, Wussler was an active contractor in St. Louis around the turn of the century.



1.	No. 148	3. Location of Negatives: Landmarks Association of St. Louis, Inc., 917 Locust, St. Louis, MO 63101
2.	City/County: City of St. Louis, MO	4. Prepared by: Cynthia Longwisch & Mary M. Stiritz, Landmarks Association of St. Louis, Inc.
5.	Date: 11/90	6. Sources of information: St. Louis Public Records, City Hall; St. Louis Public Library; MO Historical Soc.
7.	Building? Yes	
9.	O	8. On National Register or part of estab. district? No
J.	Ownership: Private	10. Visible from public road? Yes 11. Endangered? No
12.	Street address:	37 Bremen 13. Style: commercial
14.	Date(s): 8/6/1941	
15.	Architect: 16. Builder:	
17.	Original Use:	commercial 18. Present Use: vacant?
19.	Owner's name/address if known:	
20.	No. of stories:	n/a 21. Basement? yes 22. Wall construction: masonry
23.	Foundation mate	rial: concrete 24. Roof type/material: flat & gabled
25.	No. Bays: Fron	t 5 Side 10+ 25. Wall treatment: red & multi brick
26.	Plan shape: L	27. Changes: Addition? Altered? yes
28.	Exterior condit	ion: fair 29: Open to public? no
30.	Other Surveys in which included: St. Louis Harbor Historic Properties Reconnaissance, 1987, U.S. Army Corps of Engineers survey (partially incl	

- 31. Further description of important features: The long, north part of this bldg. is severely functional, with only brick corbelling between piers to provide architectural interest. West end is 2 large bays with RR tracks to allow diesel engines to enter for repair. This end was damaged and poorly repaired with CMU. Windows are infilled with glass brick, probably orig- (cont'd. below)
- 32. History and Significance: inal. Extending from the south wall is a side-gabled ell done in multi-colored brick. The roofline and two dormers give it a residential look. It, too, has two garage bays with railroad tracks. The Sanborn map distinguishes the two parts by function: the first is a diesel engine house; the second, a shop. Both parts were built from one \$10,000 permit by the St. Louis M.B.T. Railway in 1941. Behind this structure (unfortunately inaccessable) is a 1918 one-story brick Terminal RR Association "service" building.





1.	No. 139	3. Location of Negatives: Landmarks Association of St. Louis, Inc., 917 Locust, St. Louis, MO 63101			
2.	City/County: City of St. Louis, MO	4. Prepared by: Cynthia Longwisch & Mary M. Stiritz, Landmarks Association of St. Louis, Inc.			
5.	Date: 11/90	6. Sources of information: St. Louis Public Records,			
7.	Building? Yes	City Hall; St. Louis Public Library; MO Historical Soc.			
9.	Ownership:	8. On National Register or part of estab. district? No			
· .	Private	10. Visible from public road? Yes 11. Endangered? No			
12.	Street address:	201-15 Bremen 13. Style: commercial			
14.	Date(s): 8/5/1	900			
15.	Architect:	16. Builder:			
17.	Original Use:	factory 18. Present Use: warehouse			
19.	Owner's name/ad	lress if known:			
20.	No. of stories:	1 21. Basement? unk. 22. Wall construction: masonry			
23.	Foundation mate	rial: limestone 24. Roof type/material: flat			
25.	No. Bays: Fron	t 11 Side 9 25. Wall treatment: painted brick			
26.	Plan shape: rectangular 27. Changes: Addition? Altered? ye				
28.	Exterior condition: fair 29: Open to public? limited				
30.		n which included: St. Louis Harbor Historic Properties 1987, U.S. Army Corps of Engineers survey (partially incl.)			

31. Further description of important features: A concrete loading dock with a wood and metal fixed awning spans the Bremen St. elevation of this building. All windows are boarded; they have double-rowlock segmental arches and brick sills.

^{32.} History and Significance: Leschen & Sons Rope Co. took out the permit for this building in 1900 for \$5,000. It was used as part of their factory, which manufactured rope, iron, steel and galvanized wire rope and aerial wire rope tramways. The company had moved west to Kennerly & Hamilton by 1917.



139 NORTH BROADWAY INDUSTRIAL SURVEY II
201-15 BREMEN
PACING NE

57. LOUIS, MO 9/90

SLCA5013-093

1.	No. 137	3.			_	s: Landmarks Locust, St.		
2.	City/County: City of St. Louis, MO	4.	_	_	_	Longwisch &		
5.	Date: 11/90	6.						lic Records,
7.	Building? Yes		City Hall; St. Louis Public Library; MO Historical Soc.					
9.	Ownership: Private	10.	8. On National Register or part of estab. district? No 10. Visible from public road? Yes 11. Endangered? No					
12.	Street address:	217-2	23 Bre	men	13.	Style: ver	nacular	
14.	Date(s): c. 18	80						
15.	Architect:	rchitect: 16. Builder:						
17.	Original Use:	nal Use: residential 18. Present Use: vacant						
19.	Owner's name/add	dress	if kno	wn:				
20.	No. of stories:	2	21.	Basem	ent? yes	22. Wall o	construc	ction: masonry
23.	Foundation mate	rial:	limes	tone	24. Ro	of type/mate	erial:	flat
25.	No. Bays: Fron	t 12	Side	2	25. Wa	ll treatment	: red l	orick
26.	Plan shape: rec	tangula	ar	27.	Changes:	Addition?	yes	Altered? yes
28.	Exterior condition: fair 29: Open to public? no							
30.	Other Surveys in Reconnaissance,							
31. bric	Further descrip		_				_	

one-story frame porches extend from the units.

32. History and Significance: The earliest permits for this city block are in the early 1890s, which this building predates. It appears on the 1883 Hopkins

map.

wood sills; all have been boarded. Two sets of paired, paneled wood doors have transoms. Building is built directly on brick sidewalk with no stoop. Rear,



#137 NORTH BROADWAY INDUSTRIAL SURVEY II
217-23 BREMEN
FACING NE

97 LOUIS, MO 9/90

9LCA4013093

MISSOURI OFFICE OF HISTORIC PRESERVATION ARCHITECTURAL/HISTORIC INVENTORY SURVEY FORM

1.	No. 123	1	3. Location of Negatives: Landmarks Association of St. Louis, Inc., 917 Locust, St. Louis, MO 63101				
2.	City/County: City of St. Louis, MO	4. Pre					
5.	Date: 11/90	1	6. Sources of information: St. Louis Public Records, City Hall; St. Louis Public Library; MO Historical Soc.				
7.	Building? Yes		-				
9.	Ownership: Private						
12.	Street address:	825 Breme	en	13.	Style: Cl	assical	Revival
14.	Date(s): 8/25/	1886					
15.	Architect:			16. Buile	der:		
17.	Original Use: residential 18			Present	Use: vaca	nt	
19.	Owner's name/ad	dress if k	nown:				
20.	No. of stories:	2 21	. Basem	nent? yes	22. Wall	constru	ction: mason
23.	Foundation mate	rial: sto	ne	24. Ro	of type/mat	erial:	side gable
25.	No. Bays: Fron	t 2 Sid	e 0	25. Wa	ll treatmen	t: red	brick
26.	Plan shape: rectangular 27.			Changes:	Addition?		Altered? ye
28.	Exterior condition: fair/poor			29: 0	pen to publ	ic? no	
30.	Other Surveys in which included: St. Louis Harbor Historic Properties Reconnaissance, 1987, U.S. Army Corps of Engineers survey (partially incl.)						

31. Further description of important features: Corbelled cornice. Segmental soldier arches have stone keys and bracketed lugsills. Parapeted chimneys. Openings have been boarded up. Building is built directly on sidewalk with only one stone step. Building appears to have burned.

^{32.} History and Significance: "Schnetze" is all that was recorded of the person who took out the building permit for this residence in 1886. It appears to have always been used as a residence.



1.	No. 122	 Location of Negatives: Landmarks Association of St. Louis, Inc., 917 Locust, St. Louis, MO 63101 				
2.	City/County: City of St. Louis, MO	4. Prepared by: Cynthia Longwisch & Mary M. Stiritz, Landmarks Association of St. Louis, Inc.				
5.	Date: 11/90	6. Sources of information: St. Louis Public Records, City Hall; St. Louis Public Library; MO Historical Soc. 8. On National Register or part of estab. district? No. 10. Visible from public road? Yes 11. Endangered? No.				
7.	Building? Yes					
9.	Ownership: Private					
12.	Street address:	827-29 Bremen 13. Style: Classical Revival				
14.	Date(s): c. 18	во				
15.	Architect:	16. Builder:				
17.	Original Use:	residential 18. Present Use: residential				
19.	Owner's name/add	me/address if known:				
20.	No. of stories:	2 21. Basement? yes 22. Wall construction: mason:				
23.	Foundation material: stone 24. Roof type/material: side gable					
25.	No. Bays: Fron	t 5 Side 25. Wall treatment: red brick				
26.	Plan shape: rec	tangular 27. Changes: Addition? Altered? yes				
28.	Exterior condition: fair 29: Open to public? no					
30.	Other Surveys in which included: St. Louis Harbor Historic Properties Reconnaissance, 1987, U.S. Army Corps of Engineers survey (partially incl.					
31. top	-	tion of important features: A corbelled cornice crosses to A round-arched center gangway provides the entrance to				

32. History and Significance: are infilled. Replacement windows have metal sash. Building has commonwall with 831-33 Bremen (#121). No permit was found for this building. It does not appear on the 1875 Compton & Dry map but seems to be on the Hopkins 1883 map.

Window arches

(cont'd. below)

open hall to the rear stairs. The other openings are segmentally arched with stone keys and bracketed lugsills. Building fronts directly on sidewalk. Some

rebuilding of the front facade is in evidence.



Location of Negatives: Landmarks Association of

1. No. 121

5LCAS013-095
d -

1.	NO. 121	St. Louis, Inc., 917 Locust, St. Louis, MO 63101						
2.	City/County: City of St.	4. Prepare	4. Prepared by: Cynthia Longwisch & Mary M. Stiritz,					
	Louis, MO	MO Landmarks Association				n of St. Louis, Inc.		
5.	Date: 11/90	1						
7.	Building? Yes		City Hall; St. Louis Public Library; MO Historical Soc.					
9.	Ownership:	8. On Nat	lonal ke	gister ———	or part or	estab. district? No		
	Private	10. Visible	e from p	ublic n	road? Yes	11. Endangered? No		
12.	Street address:	831-33 Brem	en	13.	Style: ve	rnacular		
14.	Date(s): c. 18	80						
15.	Architect:		16.	Buile	der:			
17.	Original Use:	res./commer. 18. Present Use: residential						
19.	Owner's name/add	name/address if known:						
20.	No. of stories:	o. of stories: 2 21. Basement? yes 22. Wall construction: mason				construction: masonry		
23.	Foundation material: stone 24. Roof type/material: side gable				erial: side gable			
25.	No. Bays: Front 5 Side 3			5. Wa.	ll treatmen	t: red brick		
26.	Plan shape: rec	tangular	27. Ch	anges:	Addition?	yes Altered? yes		
28.	Exterior condit	ion: fair/goo	d	29: O _l	pen to publ	ic? no		
30.	Other Surveys in which included: St. Louis Harbor Historic Properties Reconnaissance, 1987, U.S. Army Corps of Engineers survey (partially incl.					_		
brac evat	s highlight orig	inal openings; it returns original iro	. A pro at the s n balcon	filed vides. y with	wood cornic Parapeted iron brack	e lintels and stone e features carved chimneys on west el- ets. Southwest corner (cont'd. below)		

32. History and Significance: entrance for a business in the building. A brick corner pillar, punched-in window, and Queen Anne style wooden doors belie a later alteration. Residence shares commonwall with 827-29 Bremen (#122); the chimneys on that wall feature corbelling. No permit was evidently issued on this building due to its early date. It does not appear on the Compton & Dry 1875 map, although it is on the 1883 Hopkins. A rear frame addition of indeterminate age extends from the rear, obscured by foliage.



NORTH BROADWAY INSUSTRIAL SURVEY II 891-33 BARMEN #121 FACILIG NE

ST. LOUIS, MD

1.	No. 004	3. Location of Negatives: Landmarks Association of St. Louis, Inc., 917 Locust, St. Louis, MO 63101				
2.	City/County: City of St. Louis, MO	4. Prepared by: Cynthia Longwisch & Mary M. Stiritz, Landmarks Association of St. Louis, Inc.				
5.	Date: 11/90	6. Sources of information: St. Louis Public Records,				
7.	Building? Yes	City Hall; St. Louis Public Library; MO Historical Soc.				
9.	Ormonahin	8. On National Register or part of estab. district? No				
Э.	Ownership: Private	10. Visible from public road? Yes 11. Endangered? No				
12.	Street address:	2204-10 N. Broadway 13. Style: commercial				
14.	Date(s): 9/24/	.903				
15.	Architect: C.H	C.H. Pope, Moline 16. Builder: James Stewart & Co.				
17.	Original Use:	plow factory 18. Present Use: wholesale furniture				
19.	Owner's name/ado	dress if known: Wholesale Furniture, 2204-10 N. Broadway				
20.	No. of stories:	4 21. Basement? yes 22. Wall construction: masonry				
23.	Foundation mate	rial: brick 24. Roof type/material: flat				
25.	No. Bays: Fron	11 Side 22 25. Wall treatment: brown & ptd. brick				
26.	Plan shape: L	27. Changes: Addition? Altered? yes				
28.	Exterior condit	ion: good 29: Open to public? yes				
30.	Other Surveys in which included: St. Louis Harbor Historic Properties Reconnaissance, 1987, U.S. Army Corps of Engineers survey (partially incl.)					

- 31. Further description of important features: First-story facade extensively altered. "1847-1903" inscribed across centered stepped parapet. Triple-row-lock segmentally-arched windows have stone sills, are divided into pairs or triples by pilasters & brick corbelling. All openings on front elevation infilled to some degree. Rear & side windows have original industrial multipaning.
- 32. History and Significance: The John Deere Plow Co. of Moline, Ill. took out the \$60,000 permit for this building in 1903. Deer operated a factory here through the 1930s. The Harris Wool company used the building as a warehouse for about a dozen years; International Shoe used it as a warehouse for a short time, and the Wholesale Furniture Co. located in the building in 1953.



NORTH BROADNAY INDUSTRIAL SURVEY II.
2204-10 N. BROADWAY
FACING NE

770

SLCA5027097

MISSOURI OFFICE OF HISTORIC PRESERVATION ARCHITECTURAL/HISTORIC INVENTORY SURVEY FORM

1.	No. 005	3. Location of Negatives: Landmarks Association of St. Louis, Inc., 917 Locust, St. Louis, MO 63101				
2.	City/County: City of St. Louis, MO	4. Prepared by: Cynthia Longwisch & Mary M. Stiritz, Landmarks Association of St. Louis, Inc.				
5.	Date: 11/90	6. Sources of information: St. Louis Public Records,				
7.	Building? Yes	City Hall; St. Louis Public Library; MO Historical Soc.				
9.	Ownership:	8. On National Register or part of estab. district? No				
	Private	10. Visible from public road? Yes 11. Endangered? No				
12.	Street address:	2212-20 N. Broadway 13. Style: commercial				
14.	Date(s): 4/10/	1905; 1936				
15.	Architect: Osc	rchitect: Oscar Eckerman 16. Builder: Collins Bros., Rock Island				
17.	. Original Use: warehouse 18. Present Use: factory					
19.	Owner's name/ad	dress if known: Killark Electric Manufacturing Co.				
20.	No. of stories:	7 21. Basement? yes 22. Wall construction: masonry				
23.	Foundation mate	rial: concrete 24. Roof type/material: flat				
25.	No. Bays: Fron	t 12 Side 40 25. Wall treatment: red brick				
26.	Plan shape: rec	tangular 27. Changes: Addition? yes Altered?				
28.	Exterior condit	ion: good 29: Open to public? limited				
30.	Other Surveys in which included: St. Louis Harbor Historic Properties Reconnaissance, 1987, U.S. Army Corps of Engineers survey (partially incl.					

- 31. Further description of important features: Stone-capped pilasters divide the triple-rowlock segmentally-arched windows into pairs. Stone lintels above 1st & 2nd story windows; stone sills. Stone cornice across front above 2nd story. Paneled pilasters support stone entablature over entrance. Original windows in floors 3-7 have multiple industrial panes.
- 32. History and Significance: The John Deer Plow Co. of Moline, Ill. took out a \$2,500 permit to excavate this site in March, 1905 and a building permit for \$140,000 in April, 1905. They hired architect Oscar Eckerman of Moline for the job. The company altered the warehouse for \$10,000 in 1936, and then variously in 1940, 1941, 1942, 1958, 1959, 1960 and 1969. The Killark Electric Co. took a permit to occupy the building in 1973.



#5 NORTH BROADWAY INDUSTRIAL SURVEY II
2212-20 N. BROADWAY
FACILIES SE

ST, LOWS , MO

7/90

SLCA5013-096

1.	No. 013	 Location of Negatives: Landmarks Association of St. Louis, Inc., 917 Locust, St. Louis, MO 63101 			
2.	City/County: City of St. Louis, MO	4. Prepared by: Cynthia Longwisch & Mary M. Stiritz, Landmarks Association of St. Louis, Inc.			
5.	Date: 11/90	6. Sources of information: St. Louis Public Records, City Hall; St. Louis Public Library; MO Historical Soc.			
7.	Building? Yes				
	O	8. On National Register or part of estab. district? No			
9.	Ownership: Private	10. Visible from public road? Yes 11. Endangered? No			
12.	Street address:	2401 North Broadway 13. Style: commercial			
14.	Date(s): 4/1/18	389			
15.	Architect: 16. Builder:				
17.	Original Use: store/resid. 18. Present Use: restaurant/residence				
19.	Owner's name/address if known: Crystal Grill				
20.	No. of stories: 2 21. Basement? yes 22. Wall construction: masonry				
23.	Foundation mate	rial: stone 24. Roof type/material: flat			
25.	No. Bays: Front 6 Side 11 25. Wall treatment: painted brick				
26.	Plan shape: L 27. Changes: Addition? Altered? yes				
28.	Exterior condition: good 29: Open to public? yes				
30.	Other Surveys in which included: St. Louis Harbor Historic Properties Reconnaissance, 1987, U.S. Army Corps of Engineers survey (partially incl.)				

- 31. Further description of important features: Triple-rowlock segmentally arched windows have stone sills and modernized panes; many first-story openings are infilled. A deeply-corbelled cornice returns for the width of one bay. A cast-iron storefront by Globe Iron & Foundry Co. is mostly intact, distinguished by sunbursts, with rosettes across the lintel beam.
- 32. History and Significance: Joseph Syenberg took out a \$4,000 building permit in 1889 to build a "store and rooms." No information could be found on Syenberg. The building has been a restaurant since the late 1920s.



#13


1.	No. 014	3. Location of Negatives: Landmarks Association of St. Louis, Inc., 917 Locust, St. Louis, MO 63101				
2.	City/County: City of St. Louis, MO	4. Prepared by: Cynthia Longwisch & Mary M. Stiritz, Landmarks Association of St. Louis, Inc.				
5.	Date: 11/90	6. Sources of information: St. Louis Public Records,				
7.	Building? Yes	City Hall; St. Louis Public Library; MO Historical Soc.				
9.	Ownership:	8. On National Register or part of estab. district? No				
	Private	10. Visible from public road? Yes 11. Endangered? No				
12.	Street address:	2407 North Broadway 13. Style: commercial				
14.	Date(s): 2/9/1	885				
15.	Architect:	16. Builder:				
17.	Original Use:	commercial 18. Present Use: commercial				
19.	Owner's name/ad	dress if known: Lonnie Tettaton Signs				
20.	No. of stories: 2 21. Basement? unk. 22. Wall construction: masonry					
23.	Foundation material: unknown 24. Roof type/material: flat					
25.	No. Bays: Fron	t 3 Side 0 25. Wall treatment: painted brick				
26.	Plan shape: mod	if. rectang. 27. Changes: Addition? Altered? yes				
28.	Exterior condition: good 29: Open to public? yes					
30.	-	n which included: St. Louis Harbor Historic Properties 1987, U.S. Army Corps of Engineers survey (partially incl.)				
	facade have been e been modified,	tion of important features: Although the upper windows of infilled with glass brick and the windows of the storefront much remains of an elaborate cast-iron front by Christopher feature fluted bases and ball banding. A dentilled cornice				

^{32.} History and Significance: with Eastlake ornamentation that includes rosettes. Nine ornamental pressed bricks decorate the wall surface above the second-story windows; windows are set into recessed panels. Lewis Rosenbaum obtained a permit for a \$2,000 "store and photograph gallery" in 1885. Rosenbaum was a real estate and financial agent who operated his business at this location, specializing in north St. Louis property. Edward Hauschulte operated a real estate business here from at least the late teens through 1940.

below the second-story sill line is flanked by ornate brackets (cont'd. below)







1.	No. 016	3. Location of Negatives: Landmarks Association of				
2.	City/County: City of St. Louis, MO	St. Louis, Inc., 917 Locust, St. Louis, MO 63101 4. Prepared by: Cynthia Longwisch & Mary M. Stiritz, Landmarks Association of St. Louis, Inc.				
5.	Date: 11/90	6. Sources of information: St. Louis Public Records,				
7.	Building? Yes	City Hall; St. Louis Public Library; MO Historical Soc.				
	0 1:	8. On National Register or part of estab. district? No				
9.	Ownership: Private	10. Visible from public road? Yes 11. Endangered? No				
12.	Street address:	2422-26 N. Broadway 13. Style: commercial				
14.	Date(s): 3/7/1	903; 12/14/1920; 7/25/1941				
15.	Architect: J. W. Foster 16. Builder: A. J. Blondin					
17.	Original Use: cold storage 18. Present Use: storage					
19.	Owner's name/address if known: Schaffer Moving & Storage Specialist					
20.	No. of stories: 1 & 3 21. Basement? yes 22. Wall construction: masonry					
23.	Foundation material: stone 24. Roof type/material: flat					
25.	No. Bays: Fron	t 4 Side 12 25. Wall treatment: red brick				
26.	Plan shape: rectangular 27. Changes: Addition? yes Altered? yes					
28.	Exterior condition: good 29: Open to public? limited					
30.	Other Surveys in which included: St. Louis Harbor Historic Properties Reconnaissance, 1987, U.S. Army Corps of Engineers survey (partially incl.)					

- 31. Further description of important features: This building was originally only two stories; a third was added above the stone sillcourse with guttae, probably in 1920. Tooled stone extends midway up the first floor, returning at the sides. Stone forms the pilaster capitals and sills as well. Original windows are multipane industrial metal sash; some one-over-one (cont'd. below)
- 32. History and Significance: replacements have been made. The interior has millwork construction with iron/steel columns; interior walls are of vitreous brick. A one-story garage (1941) is attached to the south side of the building. The original permit for a cold storage building was taken out for \$27,000 in 1903 by J. Ogden Armour. Condie Bray Glass Co. apparently added the third floor for \$12,000 in 1920. The Pernoud Carpet Co. owned the building in the 1930s, followed by rug companies in the 1950s, a box company, and Schaffer Moving Co.



PACINA SE

SLC A5013-103

MISSOURI OFFICE OF HISTORIC PRESERVATION ARCHITECTURAL/HISTORIC INVENTORY SURVEY FORM

1.	No. 022	3. Location of Negatives: Landmarks Association of				
2.	City/County:	St. Louis, Inc., 917 Locust, St. Louis, MO 63101				
2.	City of St. Louis, MO	4. Prepared by: Cynthia Longwisch & Mary M. Stiritz, Landmarks Association of St. Louis, Inc.				
5.	Date: 11/90	6. Sources of information: St. Louis Public Records, City Hall; St. Louis Public Library; MO Historical Soc.				
7.	Building? Yes					
9.	Ownership:	8. On National Register or part of estab. district? No				
	Private	10. Visible from public road? Yes 11. Endangered? No				
12.	Street address:	2500 N. Broadway 13. Style: industrial				
14.	Date(s): 7/29/	1907				
15.	Architect: Mau	ran, Russell & Garden 16. Builder: Killermann Const. Co.				
17.	Original Use:	warehouse 18. Present Use: warehouse				
19.	Owner's name/add	dress if known: St. Louis Bag/AAA Bag				
20.	No. of stories:	6 21. Basement? yes 22. Wall construction: masonry				
23.	Foundation mate	rial: stone 24. Roof type/material: flat				
25.	No. Bays: Fron	t 5 Side 8 25. Wall treatment: speckled red brick				
26.	Plan shape: rectangular 27. Changes: Addition? Altered?					
28.	Exterior condition: good 29: Open to public? limited					
30.	Other Surveys in which included: St. Louis Harbor Historic Properties Reconnaissance, 1987, U.S. Army Corps of Engineers survey (partially incl.)					
31.	Further descrip	tion of important features: Chicago-style tripartite win-				

32. History and Significance: H. G. Condie took out a permit for this ware-house building in 1907 for \$96,000. Herbert Condie was president of the Condie-Neale Glass & Paint Co., which later became Condie-Bray and then dissolved in the 1930s; they specialized in building glass. The Renard Co. owned the bldg. in the 1940s, and paper box/bag manufacturers have occupied it since the mid-1950s. The noted architectural firm of Mauran, Russell & Garden, who designed the building, were guite active in St. Louis.

dows have continuous lintel and sill soldier courses for horizontal emphasis. Prominent, overhanging, bracketed copper cornice. Stylized classical piers at entry. Metal grillwork at base of first story windows. Pink granite entry

steps and foundation facing.



SLCASOB -102

1.	No. 020	3. Location of Negatives: Landmarks Association of St. Louis, Inc., 917 Locust, St. Louis, MO 63101
2.	City/County: City of St. Louis, MO	4. Prepared by: Cynthia Longwisch & Mary M. Stiritz, Landmarks Association of St. Louis, Inc.
5.	Date: 11/90	6. Sources of information: St. Louis Public Records,
7.	Building? Yes	City Hall; St. Louis Public Library; MO Historical Soc.
9.	Ownership: Private	8. On National Register or part of estab. district? No 10. Visible from public road? Yes 11. Endangered? No
12.	Street address: 2507-11 N. Broadway 13. Style: commercial	
14.	Date(s): 10/25/1902	
15.	Architect:	16. Builder:
17.	Original Use: factory 18. Present Use: warehouse	
19.	Owner's name/address if known: St. Louis Dyeing	
20.	No. of stories: 2 & 3 21. Basement? yes 22. Wall construction: mason:	
23.	Foundation material: concrete 24. Roof type/material: flat	
25.	No. Bays: Front 3 Side 25. Wall treatment: painted brick	
26.	Plan shape: L 27. Changes: Addition? Altered? yes	
28.	Exterior condit	ion: fair/good 29: Open to public? limited
30.	Other Surveys in which included: St. Louis Harbor Historic Properties Reconnaissance, 1987, U.S. Army Corps of Engineers survey (partially incl.	
31.	Further descrip	tion of important features: The three recessed bays of the

- 31. Further description of important features: The three recessed bays of the primary elevation are topped by a (concrete?) parapet of probably 1940s vintage. Utilitarian windows are horizontally hinged and have concrete sills. Center bay is a loading dock/garage door bay. The rear elevation is three stories, with all openings infilled save a garage bay. Rear windows have soldier arches.
- 32. History and Significance: H. C. Beckmann took out a \$15,000 permit for a factory in 1902. Beckmann ran the Henry C. Beckmann Realty & Investment Co. and was secretary of the Progress Press Brick & Machinery Co. It appears that he built the building for Charles F. Kraushaar, president of the Kraushaar Brass Manufacturing Co. Kraushaar (and, after 1936, the Kraushaar Estate) owned the building until 1946, when the Samour Realty Co. bought it. A series of companies owned the building until St. Louis Dyeing bought it in 1963.



SCCA5013-103

			· ·
1.	No. 021		f Negatives: Landmarks Association of Inc., 917 Locust, St. Louis, MO 63101
2.	City/County: City of St. Louis, MO	4. Prepared b	y: Cynthia Longwisch & Mary M. Stiritz, Association of St. Louis, Inc.
5.	Date: 11/90		information: St. Louis Public Records,
7.	Building? Yes		Louis Public Library; MO Historical Soc.
9.	Ownership: Private		Om public road? Yes 11. Endangered? No
12.	Street address:	2513 N. Broadwa	y 13. Style: flounder
14.	Date(s): c. 1875, 1886		
15.	Architect:		16. Builder:
17.	Original Use:	residence 18	. Present Use: commercial
19.	Owner's name/add	lress if known:	Angle Roofing & Sheet Metal
20.	No. of stories: 1 & 2 21. Basement? unk. 22. Wall construction: masonr		
23.	Foundation mate	rial: unknown	24. Roof type/material: flat& flounder
25.	No. Bays: Fron	t 2 Side c. 20	25. Wall treatment: painted brick
26.	Plan shape: rec	tangular 27.	Changes: Addition? Altered? yes
28.	Exterior condition: good 29: Open to public? limited		
30.	-		St. Louis Harbor Historic Properties Corps of Engineers survey (partially incl.)
31. pund	-	-	features: A single, stone-linteled window mary elevation; warehouse doors open in the

32. History and Significance: be found earlier than 1886, it is likely that this building is a remnant of the earlier era. A permit taken out by Louise Becker on 6/23/1886 for two adjoining tenements probably incorporated this building. No other permits could be found from 1886 to 1970, when a demolition permit was issued to wreck a "2 story factory & warehouse." The tenements had probably been turned into industrial buildings before their demise left the smaller building standing alone.

flat-roofed section. The 1875 Compton & Dry map shows a diverse group of buildings in the immediate area, including the mixed gabled-front-with-flounder-rear style found throughout the north side. Although no permit could (con't. below)



#21

2513 N. BROADWAY

7/90

1.	No. 023	 Location of Negatives: Landmarks Association of St. Louis, Inc., 917 Locust, St. Louis, MO 63101 	
2.	City/County: City of St. Louis, MO	4. Prepared by: Cynthia Longwisch & Mary M. Stiritz, Landmarks Association of St. Louis, Inc.	
5.	Date: 11/90	6. Sources of information: St. Louis Public Records, City Hall; St. Louis Public Library; MO Historical Soc.	
7.	Building? Yes		
9.	Ownership:	8. On National Register or part of estab. district? No	
٦.	Private	10. Visible from public road? Yes 11. Endangered? No	
12.	Street address:	2514 N. Broadway 13. Style: commercial	
14.	Date(s): 7/29/1910		
15.	Architect: A. B. Groves 16. Builder: E. A. Steininger Const. Co		
17.	Original Use: machine house 18. Present Use: warehouse		
19.	Owner's name/address if known: United Bags		
20.	No. of stories: 6 21. Basement? yes 22. Wall construction: masonry		
23.	Foundation material: stone 24. Roof type/material: flat		
25.	No. Bays: Fron	t 4 Side 25. Wall treatment: red & brown brick	
26.	Plan shape: rec	tangular 27. Changes: Addition? Altered? yes	
28.	Exterior condit	ion: good 29: Open to public? limited	
30.		n which included: St. Louis Harbor Historic Properties 1987, U.S. Army Corps of Engineers survey (partially incl.	

- 31. Further description of important features: 1st & 2nd story windows have been infilled; south bay is a modernized entrance. Windows above are tripartite Chicago-style with white terra cotta. The shaped parapet is trimmed with terra cotta; a centered insignia bears the initials "P O." Below, a sloped lintel of terra cotta extends across the four bays. Between these bays are (con't. below)
- 32. History and Significance: Craftsman panels of patterned brickwork. Profiled terra cotta sill courses at the second and sixth stories have dentilling (6th) and bead & reel molding (2nd) below, supported by brackets. The Parlin & Orendorff Plow Co. took out the \$90,000 permit for this "fireproof machinery house" in 1910. President William Parlin lived in Canton, Ill., as did his partner Ulysses Orendorff. The company was no longer in St. Louis by the early 1920s. The building has been a bag warehouse since the mid-1950s.



-			
1.	No. 024	3. Location of Negatives: Landmarks Association of St. Louis, Inc., 917 Locust, St. Louis, MO 63101	
2.	City/County: City of St. Louis, MO	4. Prepared by: Cynthia Longwisch & Mary M. Stiritz, Landmarks Association of St. Louis, Inc.	
5.	Date: 11/90	6. Sources of information: St. Louis Public Records, City Hall; St. Louis Public Library; MO Historical Soc.	
7.	Building? Yes	8. On National Register or part of estab. district? No	
9.	Ownership: Private	10. Visible from public road? Yes 11. Endangered? No	
12.	Street address: 2516 N. Broadway 13. Style: commercial		
14.	Date(s): 9/16/1911		
15.	Architect: Prask & Perrine 16. Builder: H. G. Cristmann Co.		
17.	Original Use: warehouse 18. Present Use: warehouse		
19.	Owner's name/address if known: United Bags Inc.		
20.	No. of stories:	5 21. Basement? yes 22. Wall construction: masonry	
23.	Foundation material: stone 24. Roof type/material: flat		
25.	No. Bays: Front 5 Side 10 25. Wall treatment: speckled rose brid		
26.	Plan shape: rectangular 27. Changes: Addition? Altered? yes		
28.	Exterior condit	ion: good 29: Open to public? limited	
30.	Other Surveys in which included: St. Louis Harbor Historic Properties Reconnaissance, 1987, U.S. Army Corps of Engineers survey (partially incl.		

- 31. Further description of important features: Extensive use of cream-colored terra cotta trim highlights the building's pier & spandrel system. Tripled windows of the primary elevation appear to have been modified in all but the 2nd story. A green terra cotta panel over the entry reads "OLIVER" and the shaped parapet features a center terra cotta insignia of a capital O (cont'd. below)
- 32. History and Significance: with a plow and shield motif. Mortar is rose-colored. First-story display windows have glass brick, wood or plate glass infill. The \$75,000 building permit for this warehouse was taken out by the Oliver Chilled Plow Co. in 1911, specifying that the building be "fireproof." The company became the Oliver Farm Equipment Co., makers of tractors and other farming implements sold nationwide. They used the building until its sale to United Bags in 1960. The architects were from Pittsburgh, builder from Indiana.



1.	No. 031	 Location of Negatives: Landmarks Association of St. Louis, Inc., 917 Locust, St. Louis, MO 63101
2.	City/County: City of St. Louis, MO	4. Prepared by: Cynthia Longwisch & Mary M. Stiritz, Landmarks Association of St. Louis, Inc.
5.	Date: 11/90	6. Sources of information: St. Louis Public Records, City Hall; St. Louis Public Library; MO Historical Soc.
7.	Building? Yes	
9.	Ownership: Private	8. On National Register or part of estab. district? No 10. Visible from public road? Yes 11. Endangered? No
12.	Street address:	2601 N. Broadway 13. Style: commercial
14.	Date(s): c. 1940	
15.	Architect:	16. Builder:
17.	Original Use: commercial 18. Present Use: filling station	
19.	Owner's name/address if known: Convent Gardens Sunoco	
20.	No. of stories: 2 21. Basement? no 22. Wall construction: masonr	
23.	Foundation mate	rial: concrete 24. Roof type/material: flat
25.	No. Bays: Front 3 Side 4 25. Wall treatment: painted brick	
26.	Plan shape: rectangular 27. Changes: Addition? yes Altered?	
28.	Exterior condit	ion: good 29: Open to public? yes
30.		n which included: St. Louis Harbor Historic Properties 1987, U.S. Army Corps of Engineers survey (partially incl.)

single panes. Terra cotta coping.

^{32.} History and Significance: Early building permits in "active" file are missing for this city block. Rear concrete block addition built in 1951.



FACING NW

SCLAS013 -107

(cont'd. below)

1.	No. 032	3. Location of Negatives: Landmarks Association of St. Louis, Inc., 917 Locust, St. Louis, MO 63101	
2.	City/County: City of St. Louis, MO	4. Prepared by: Cynthia Longwisch & Mary M. Stiritz, Landmarks Association of St. Louis, Inc.	
5.	Date: 11/90	6. Sources of information: St. Louis Public Records, City Hall; St. Louis Public Library; MO Historical Soc.	
7.	Building? Yes		
9.	Ownership: Private	8. On National Register or part of estab. district? No. Visible from public road? Yes 11. Endangered? No. Visible from public road?	
12.	Street address: 2604-06 N. Broadway 13. Style: commercial		
14.	Date(s): 7/24/1906; 2/7/1913		
15.	Architect: A. B. Groves 16. Builder: Wm. Sutherland Bldg. & Con		
17.	Original Use: warehouse 18. Present Use: warehouse		
19.	Owner's name/address if known: Ultra-Comp SAS Manufacturers & Importers		
20.	No. of stories: 6 21. Basement? yes 22. Wall construction: masonr		
23.	Foundation mate	rial: stone 24. Roof type/material: flat	
25.	No. Bays: Fron	t 5 Side 10 25. Wall treatment: red brick	
26.	Plan shape: rectangular 27. Changes: Addition? Altered? ye		
28.	Exterior condition: good 29: Open to public? limited		
30.	Other Surveys in which included: St. Louis Harbor Historic Properties Reconnaissance, 1987, U.S. Army Corps of Engineers survey (partially incl		

vertical terra cotta paneled brackets. Piers terminate below the cornice with

Craftsman raised brickwork panels. A stylized classical front

^{32.} History and Significance: entry features paneled pilasters supporting an elliptical arch. Raised letters of grey terra cotta above the entrance read, "KINGMAN." Four loading docks are located on the south elevation. Kingman took out an \$85,000 permit in 1906 for this warehouse; the permit mentions the St. Louis Implement Co. Leonard Hillis took out a \$10,000 permit to "repair fire damage to warehouse." Artophone occupied the building in 1947.



HOPH BROADWAY INDUSTRUAL SERVEY II 2604-06 N. BEDADWAY ST. LOUIS, MO #32 FACING NE

SLCA5013-108

1.	No. 033	3. Location of Negatives: Landmarks Association of St. Louis, Inc., 917 Locust, St. Louis, MO 63101
2.	City/County: City of St. Louis, MO	4. Prepared by: Cynthia Longwisch & Mary M. Stiritz, Landmarks Association of St. Louis, Inc.
5.	Date: 11/90	6. Sources of information: St. Louis Public Records, City Hall; St. Louis Public Library; MO Historical Soc.
7.	Building? Yes	
9.	Ownership: Private	8. On National Register or part of estab. district? No
Э.		10. Visible from public road? Yes 11. Endangered? No
12.	Street address:	2608 N. Broadway 13. Style: commercial
14.	Date(s): 11/8/1911	
15.	Architect: H.W. Beardsley & Co. 16. Builder: owner	
17.	Original Use: warehouse 18. Present Use: commercial	
19.	Owner's name/address if known: Learn Sign Painting/Midwest Schools	
20.	No. of stories: 4 21. Basement? yes 22. Wall construction: masonry	
23.	Foundation mate	rial: stone 24. Roof type/material: flat
25.	No. Bays: Fron	t 3 Side 25. Wall treatment: red brick
26.	Plan shape: rec	tangular 27. Changes: Addition? Altered? yes
28.	Exterior condition: fair 29: Open to public? limited	
30.	Other Surveys in which included: St. Louis Harbor Historic Properties Reconnaissance, 1987, U.S. Army Corps of Engineers survey (partially incl.	
	Funthan dan est	Line E important Entropy White Languages


31. Further description of important features: White terra cotta is used to highlight the facade, including coping on the stepped parapet, diamond insets in the spandrels, and profiled cornices at the first and fourth stories. Paired, transomed windows have soldier-course lintels. First-story facade has been altered with a north bay garage door and infilling of the center bay.

^{32.} History and Significance: The Tyler Estate had this warehouse built for \$16,000 in 1911.



NORTH BROADWAY INDUSTRIAL SURVEY II. 2608 N. BROADWAY (CENTER) FACING NE

ST. LOWIS, MO



8. Yes 8.	St. Louis, Prepared by Landmarks As Sources of ty Hall; St. 1	Inc., 917 : Cynthia ssociation information	s: Landmarks Association of Locust, St. Louis, MO 63101 Longwisch & Mary M. Stiritz, n of St. Louis, Inc. on: St. Louis Public Records, lic Library; MO Historical Soc.
St. 4.) /90 6. Cit ? Yes 8. p: 10.	Prepared by Landmarks As Sources of ty Hall; St. 1	: Cynthia ssociation information	Longwisch & Mary M. Stiritz, n of St. Louis, Inc. on: St. Louis Public Records, lic Library; MO Historical Soc.
Cit ? Yes 8.	On National	Louis Pub	lic Library; MO Historical Soc.
8. Yes 8.	On National		
10.		Register	
	Visible from		or part of estab. district? No
ldress: 2614	VIBIDIC IIO	m public	road? Yes 11. Endangered? No
	4 N. Broadway	13.	Style: commercial
3/6/1914			
Architect: C. F. Steitz 16. Builder: Federal Construction Co.			
Original Use: commercial 18. Present Use: warehouse			
Owner's name/address if known:			
No. of stories: 4 21. Basement? yes 22. Wall construction: masonry			22. Wall construction: masonry
Foundation material: stone 24. Roof type/material: flat			
: Front 3	Side 3	25. Wa	ll treatment: brown & rose brick
pe: rectangul	lar 27.	Changes:	Addition? Altered? yes
condition:	fair	29: 0	pen to public? no
-			-
rv	condition: reys in which sance, 1987	condition: fair reys in which included: sance, 1987, U.S. Army C	

appears to be original.

^{32.} History and Significance: The Tyler Estate took out the permit for this "mercantile" building for \$10,000 in 1914.



34 NORTH BREADWAY INDUSTRIAL
2014 N. BREADWAY (CENTER)
FACING ESE

		1001011		
1.	No. 047	3. Location of Negatives: Landmarks Association of St. Louis, Inc., 917 Locust, St. Louis, MO 63101		
2.	City/County: City of St. Louis, MO	4. Prepared by: Cynthia Longwisch & Mary M. Stiritz, Landmarks Association of St. Louis, Inc.		
5.	Date: 11/90 6. Sources of information: St. Louis Public Records, City Hall; St. Louis Public Library; MO Historical Soc			
7.	Building? Yes	? Yes		
9.	Ownership: Private 8. On National Register or part of estab. district? Notes that the stab is the st			
12.	Street address: 2700-04 N. Broadway 13. Style: commercial			
14.	Date(s): 9/1/1903; 9/19/1941			
15.	Architect: 16. Builder: C. E. Huntley			
17.	Original Use: meat market 18. Present Use: warehouse			
19.	Owner's name/address if known: Fortune Paper Co.			
20.	No. of stories:	2 & 3 21. Basement? yes 22. Wall construction: masonry		
23.	Foundation mate	rial: stone 24. Roof type/material: flat		
25.	No. Bays: Fron	t 5 Side 10 25. Wall treatment: red & painted brick		
26.	Plan shape: rec	tangular 27. Changes: Addition? yes Altered? yes		
28.	Exterior condit	ion: fair 29: Open to public? no		
30.	-	n which included: St. Louis Harbor Historic Properties 1987, U.S. Army Corps of Engineers survey (partially incl.)		
31.	Further descrip	tion of important features: All openings in the front por-		

- 31. Further description of important features: All openings in the front portion of the building have been infilled with wood or masonry. Rusticated brickwork defines the first-story storefront. 1st & 2nd story windows have segmental arches, stone sills. 3rd story windows have no arches. Modern CMU 1-story addition to the north; one-story brick addition connects the rear (cont'd. below)
- 32. History and Significance: 1941 addition to the front part. Rear addition has windows with no arches and brick sills, flat roof, terra cotta coping. The Schwarzschild & Switzberger Co., apparently a short-lived meat market, took out the \$25,000 building permit for this building in 1903; they were gone by 1917. The M. Holtzman Metal Co. occupied the building by 1924, owning it through the early 1950s. It has since been a textile waste warehouse, package liquor store confectionery and now is a warehouse for paper products.



NORTH BROADWAY INDUSTRIAL SURVEY II ST. LOUIS, MO 8700-04 N. GROADWAY FACINA NE

SLCASOB-111

1.	No. 045	 Location of Negatives: Landmarks Association of St. Louis, Inc., 917 Locust, St. Louis, MO 63101 	
2.			
5.	,		
7.	Building? Yes City Hall; St. Louis Public Library; MO Historical Soc.		
9.	Ownership:	8. On National Register or part of estab. district? No	
<i>J</i> .	Private 10. Visible from public road? Yes 11. Endanger		
12.	Street address: 2701-03 N. Broadway 13. Style: industrial		
14.	Date(s): 10/29/1908		
15.	Architect: Robert Osterhorn 16. Builder: owner		
17.	Original Use: shop 18. Present Use: machinery shop/office		
19.	Owner's name/address if known: Williams Patent Crusher & Pulverizer Co.		
20.	No. of stories: 1 & 2 21. Basement? no 22. Wall construction: masonry		
23.	Foundation mate	rial: brick 24. Roof type/material: flat	
25.	No. Bays: Front 5 Side 8 25. Wall treatment: red brick		
26.	Plan shape: rectangular 27. Changes: Addition? Altered? yes		
28.	Exterior condit	ion: good 29: Open to public? limited	
30.	_	n which included: St. Louis Harbor Historic Properties 1987, U.S. Army Corps of Engineers survey (partially incl.)	

31. Further description of important features: Windows have brick sills and multipane industrial metal sash; openings have no arches. White terra cotta coping. Primary elevation has several brick-in openings.

^{32.} History and Significance: The Williams Patent Crusher & Pulverizer Co. took out the \$20,000 permit to build this building in 1908. M. F. Williams and his relatives had operated the company in this city block since at least 1898; it has continued in the same location, today taking up the bulk of the block.



1.	No. 046	 Location of Negatives: Landmarks Association of St. Louis, Inc., 917 Locust, St. Louis, MO 63101 		
2.	City/County: City of St. Louis, MO	nty: St. 4. Prepared by: Cynthia Longwisch & Mary M. Stiritz,		
5.	Date: 11/90			
7.	City Hall; St. Louis Public Library; MO Historical Soc.			
9.	Ownership:	8. On National Register or part of estab. district? No		
	Private	10. Visible from public road? Yes 11. Endangered? No		
12.	Street address: 2713 N. Broadway 13. Style: industrial			
14.	Date(s): 6/24/1916			
15.	Architect: 16. Builder: Chas. B. McCormack & Son			
17.	Original Use: warehouse 18. Present Use: warehouse			
19.	Owner's name/address if known: Williams Patent Crusher & Pulverizer Co.			
20.	No. of stories: 3-1/2 21. Basement? unk. 22. Wall construction: masonry			
23.	Foundation material: concrete 24. Roof type/material: flat			
25.	No. Bays: Front 4 Side 6 25. Wall treatment: concrete			
26.	Plan shape: rec	tangular 27. Changes: Addition? Altered?		
28.	Exterior condit	ion: good 29: Open to public? no		
30.		n which included: St. Louis Harbor Historic Properties 1987, U.S. Army Corps of Engineers survey (partially incl.)		

head garage door bays. Simple profiled cornice. Row of narrow windows at attic story.

32. History and Significance: The Williams Patent Crusher & Pulverizer Co.

concrete grid; windows in primary facade infilled with glass brick. Two over-

Further description of important features: Facade is defined by reinforced

took out the permit for this warehouse in 1916 for \$26,000. M. F. Williams was installing a boiler in property on this city block as early as 1898. His company, still in operation in the same location, today takes up most of this city block.

NORTH BROADWAY INDUSTRIAL SURVEY IT
2713 N. BROADWAY
FACING SW

#

ST. LOUIS, MO

7/90

1.	No. 054	3. Location of Negatives: Landmarks Association of St. Louis, Inc., 917 Locust, St. Louis, MO 63101			
2.	City/County: City of St. Louis, MO	4. Prepared by: Cynthia Longwisch & Mary M. Stiritz, Landmarks Association of St. Louis, Inc.			
5.	,				
7.	Building? Yes	City Hall; St. Louis Public Library; MO Historical Soc.			
9.	Ownership: Private 8. On National Register or part of estab. district? No Ownership: 10. Visible from public road? Yes 11. Endangered? No				
12.	Street address: 2900 N. Broadway 13. Style: commercial/Roman. Reviv				
14.	Date(s): c. 1892-5				
15.	Architect: 16. Builder:				
17.	Original Use: commercial 18. Present Use: warehouse/office				
19.	Owner's name/address if known: McHenry Meat Co				
20.	No. of stories:	2 21. Basement? yes 22. Wall construction: masonry			
23.	Foundation mate	rial: limestone 24. Roof type/material: flat			
25.	No. Bays: Fron	t 5 Side 15 25. Wall treatment: painted brick			
26.	Plan shape: modified L 27. Changes: Addition? yes Altered? yes				
28.	Exterior condit	ion: good 29: Open to public? limited			
30.	-	n which included: St. Louis Harbor Historic Properties 1987, U.S. Army Corps of Engineers survey (partially incl.)			
31.	Further descrip	tion of important features: A stepped parapet is high-			

- 31. Further description of important features: A stepped parapet is high-lighted with rows of recessed square panels; below, a string course of quarry-faced stone tops brick corbelling divided by pilasters. Windows have quarry-faced flat stone lintels in the front part of the building. The original store-front has been infilled with masonry; an oval Moderne-style (cont'd below)
- 32. History and Significance: window has been punched into the west elevation. Quarry-faced stone banding remains on pilasters. First-story side windows have round, pressed-brick arches. A rear 1917 cooler addition has only a row of tiny segmentally arched windows near the roofline. A brick addition is located on the north side. The active and inactive building permits for this city block have been mixed together with the loss of some. An 1892 demo permit for this site is never followed by a building permit. Meat companies here since 1917.



SLCA5013-114

		•			
1.	No. 053	3. Location of Negatives: Landmarks Association of St. Louis, Inc., 917 Locust, St. Louis, MO 63101			
2.	City/County: City of St. Louis, MO	City/County: 4. Prepared by: Cynthia Longwisch & Mary M. Stiritz,			
5.	•				
7.	Building? Yes City Hall; St. Louis Public Library; MO Historical Soc.				
9.	Ownership:	8. On National Register or part of estab. district? No			
٠,٠	Private 10. Visible from public road? Yes 11. En				
12.	Street address: 2917-23 N. Broadway 13. Style: commercial				
14.	Date(s): 7/19/1880; 6/17/1904				
15.	Architect: 16. Builder:				
17.	Original Use: feed store 18. Present Use: commercial				
19.	Owner's name/address if known: Robsco Pipe & Supply Co.				
20.	No. of stories: 2 21. Basement? yes 22. Wall construction: masonry				
23.	Foundation material: stone 24. Roof type/material: flat				
25.	No. Bays: Fron	t 7 Side 9 25. Wall treatment: red brick			
26.	Plan shape: rectangular 27. Changes: Addition? yes Altered? yes				
28.	Exterior condit	ion: good 29: Open to public? limited			
30.	_	n which included: St. Louis Harbor Historic Properties 1987, U.S. Army Corps of Engineers survey (partially incl.			
	-				

- 31. Further description of important features: Windows have segmental soldier arches with stone sills; they have all been infilled with corrugated material or glass brick. Angled cast-iron storefront has a single column. Corbelled brick cornice. Stepped parapet at front is coped with white terra cotta. One-story 1904 warehouse addition to south; concrete block rear addition to west.
- 32. History and Significance: William Saeger took out the 1880 building permit for this \$1,150 feed store. He later took out a permit for \$4,000 in 1904 to alter and add to the feed store, which addition was made to the south side of the building. Saeger was out of the business in St. Louis by the teens. Arthur Morgan's hauling and express company bought the building before 1924. The company evolved into a trucking firm and remained in the building at least through the 1940s.



453 NOTH BEST INDUSTRIES SURVEY IN 2917-23 N. BELLEWIT BACKS ON

ST. 10415, MO

790

5LCA5013-115

1.	No. 055	3. Location of Negatives: Landmarks Association of St. Louis, Inc., 917 Locust, St. Louis, MO 63101	
2.	City/County: City of St. Louis, MO	4. Prepared by: Cynthia Longwisch & Mary M. Stiritz, Landmarks Association of St. Louis, Inc.	
5.	Date: 11/90	6. Sources of information: St. Louis Public Records,	
7.	Building? Yes City Hall; St. Louis Public Library; MO Historical Soc.		
9.	Ownership:	8. On National Register or part of estab. district? No	
	Private	10. Visible from public road? Yes 11. Endangered? No	
12.	Street address: 3001 N. Broadway 13. Style: commercial		
14.	Date(s): c. 1890		
15.	Architect: 16. Builder:		
17.	Original Use: commercial 18. Present Use: commercial		
19.	Owner's name/address if known: Antler Trucking Co.		
20.	No. of stories: 1 21. Basement? unk. 22. Wall construction: masonr		
23.	Foundation mate	rial: stone 24. Roof type/material: flat	
25.	No. Bays: Fron	t 6 Side 9 25. Wall treatment: painted brick	
26.	Plan shape: squ	are 27. Changes: Addition? Altered? yes	
28.	Exterior condit	ion: good 29: Open to public? limited	
30.	-	n which included: St. Louis Harbor Historic Properties 1987, U.S. Army Corps of Engineers survey (partially incl.)	
21	77		

^{31.} Further description of important features: Triple-rowlock segmental arches top openings on the east and south elevations. Corbelled brick cornice. Raised brick sill string course. Terra cotta coping. Windows have been infilled with brick.

^{32.} History and Significance: No building permit could be found for this building; however, the Howe Scale Co. moved into the building between 1917 and 1924, remaining there until 1950 when the building became a warehouse for the Missouri Pecan Co.



NOTH BROKENBY INDUSTRIAL SURVEY II. 3001 N. BROKENBY FACING NW

ST. LOWS, MO 7/90

1.	No. 077	3. Location of Negatives: Landmarks Association of St. Louis, Inc., 917 Locust, St. Louis, MO 63101	
2.	City/County: City of St. Louis, MO	4. Prepared by: Cynthia Longwisch & Mary M. Stiritz, Landmarks Association of St. Louis, Inc.	
5.	Date: 11/90	6. Sources of information: St. Louis Public Records, City Hall; St. Louis Public Library; MO Historical Soc.	
7.	Building? Yes		
9.	Ownership: Private	8. On National Register or part of estab. district? No 10. Visible from public road? Yes 11. Endangered? No	
12.	Street address:	3100 N. Broadway 13. Style: industrial	
14.	Date(s): 1922		
15.	Architect: 16. Builder:		
17.	Original Use: factory 18. Present Use: warehouse		
19.	Owner's name/address if known: Cash's Scrap Metal		
20.	No. of stories: 2 21. Basement? yes 22. Wall construction: masonr		
23.	Foundation mater	rial: concrete 24. Roof type/material: monitor/tile	
25.	No. Bays: Fron	t 7 Side 11 25. Wall treatment: red brick	
26.	Plan shape: rec	tangular 27. Changes: Addition? Altered? yes	
28.	Exterior condit	ion: good 29: Open to public? no	
30.	_	n which included: St. Louis Harbor Historic Properties 1987, U.S. Army Corps of Engineers survey (partially incl.)	
31.		tion of important features: The center of this building is neight with a monitor roofline. Terra cotta coping rims the	

32. History and Significance: The Sanborn Insurance maps date this building at 1922. The General Metals Refining Co. was the first occupant.

parapet. A double-rowlock segmental soldier arch dominates the upper center bay of this building, which was originally used as a foundry. Windows have all been

infilled. Stone sills on front elevation.



54CASUZ-117

1.	No. 078	3. Location of Negatives: Landmarks Association of St. Louis, Inc., 917 Locust, St. Louis, MO 63101	
2.	City/County: City of St. Louis, MO	4. Prepared by: Cynthia Longwisch & Mary M. Stiritz, Landmarks Association of St. Louis, Inc.	
5.	Date: 11/90	6. Sources of information: St. Louis Public Records,	
7.	Building? Yes	City Hall; St. Louis Public Library; MO Historical Soc.	
9.	Ownership:	8. On National Register or part of estab. district? No	
A service of the service of the	Private	10. Visible from public road? Yes 11. Endangered? No	
12.	Street address: 3130 N. Broadway 13. Style: commercial		
14.	Date(s): 5/24/1882		
15.	Architect: 16. Builder:		
17.	Original Use: wagon shop 18. Present Use: commercial		
19.	Owner's name/address if known: Ameri-Can/Cash's Scrap Metal		
20.	No. of stories: 2 21. Basement? no 22. Wall construction: masonry		
23.	Foundation material: unknown 24. Roof type/material: flat		
25.	No. Bays: Fron	t 9 Side 10 25. Wall treatment: painted brick	
26.	Plan shape: rectangular 27. Changes: Addition? yes Altered? yes		
28.	Exterior condit	ion: good 29: Open to public? limited	
30.		n which included: St. Louis Harbor Historic Properties 1987, U.S. Army Corps of Engineers survey (partially incl.)	
Larg	ered on the builder garage bay in	tion of important features: A corbelled brick cornice is ding. Flat and segmentally—arched windows are all infilled. south end of front elevation. Plain parapet with terra ddition adjoins building on the north.	

^{32.} History and Significance: Henry Becker took out the permit for this \$1,450 wagon shop in 1882. Becker was the superintendent of the More-Jones Brass & Metal Co.



MICCOURT OFFICE OF HICTORIC PRECERVATION

		ARCH	I TECTU	RAL/HISTORIC INVENTORY SURVEY FORM SLC ASO13-113
1.	No.	080	3.	Location of Negatives: Landmarks Association of St. Louis, Inc., 917 Locust, St. Louis, MO 63101

1.	No. 080	3. Location of Negatives: Landmarks Association of St. Louis, Inc., 917 Locust, St. Louis, MO 63101
2.	City/County: City of St. Louis, MO	4. Prepared by: Cynthia Longwisch & Mary M. Stiritz, Landmarks Association of St. Louis, Inc.
5.	Date: 11/90	6. Sources of information: St. Louis Public Records,
7.	Building? Yes	City Hall; St. Louis Public Library; MO Historical Soc.
9.	Ownership:	8. On National Register or part of estab. district? No
J.	Private	10. Visible from public road? Yes 11. Endangered? No
12.	Street address:	3228 N. Broadway 13. Style: industrial
14.	Date(s): 7/18/1929	
15.	Architect: 16. Builder:	
17.	Original Use: industrial 18. Present Use: industrial	
19.	Owner's name/ad	dress if known: Scienco, Inc.
20.	No. of stories:	4 21. Basement? yes 22. Wall construction: masonry
23.	Foundation mate	rial: CMU 24. Roof type/material: flat
25.	No. Bays: Fron	t 4 Side 9 25. Wall treatment: concrete & brick
26.	Plan shape: rec	tangular 27. Changes: Addition? Altered? yes

- 28. Exterior condition: fair Open to public? 29: limited
- 30. Other Surveys in which included: St. Louis Harbor Historic Properties Reconnaissance, 1987, U.S. Army Corps of Engineers survey (partially incl.)
- Further description of important features: Bays of multipane industrial metal sash windows make up the bulk of the walls of this building. A buff terra cotta Art Deco entrance in the southwest corner projects somewhat from the face of the building; it is surmounted by nine-over-six windows, one per story, and topped by a tiny inset shield at the roofline. Some of the (cont'd. below)

History and Significance: bays have been infilled with brick. The permit for this building was taken out by the Con Fero Paint Company in 1929. The building cost \$55,000.



SLCA5013-128


1.	No. 076	 Location of Negatives: Landmarks Association of St. Louis, Inc., 917 Locust, St. Louis, MO 63101 		
2.	City/County: City of St. Louis, MO	4. Prepared by: Cynthia Longwisch & Mary M. Stiritz, Landmarks Association of St. Louis, Inc.		
5.	Date: 11/90	6. Sources of information: St. Louis Public Records,		
7.	Building? Yes	City Hall; St. Louis Public Library; MO Historical Soc.		
9.	Ownership:	8. On National Register or part of estab. district? No		
Private		10. Visible from public road? Yes 11. Endangered? No		
12.	Street address: 3237 N. Broadway 13. Style: commercial			
14.	Date(s): c. 190	00		
15.	Architect: 16. Builder:			
17.	Original Use: commercial 18. Present Use: commercial			
19.	Owner's name/address if known: Norm's Precision Maintenance			
20.	No. of stories: 1 21. Basement? no 22. Wall construction: masonry			
23.	Foundation material: concrete 24. Roof type/material: flat			
25.	No. Bays: Fron	t 3 Side 3 25. Wall treatment: red brick		
26.	Plan shape: rec	tangular 27. Changes: Addition? Altered? yes		
28.	Exterior condit	ion: good 29: Open to public? limited		
30.	-	n which included: St. Louis Harbor Historic Properties 1987, U.S. Army Corps of Engineers survey (partially incl.		

a replacement of the original.

flanked by white terra cotta coping. The primary facade shows evidence of being

^{32.} History and Significance: No permit shows up for this building, although an 8/22/1903 permit was taken out by William Wilhelam for \$200 worth of alterations of a saloon at this address, to be done by Wohlbrink & Shade. In 1919, A. Mehilmy hired E. Oventrop to do \$100 worth of alterations to a "shop."





1.	No. 105	 Location of Negatives: Landmarks Association of St. Louis, Inc., 917 Locust, St. Louis, MO 63101 				
2.	City/County: City of St. Louis, MO	4. Prepared by: Cynthia Longwisch & Mary M. Stiritz, Landmarks Association of St. Louis, Inc.				
5.	Date: 11/90	6. Sources of information: St. Louis Public Records,				
7.	Building? Yes	City Hall; St. Louis Public Library; MO Historical Soc.				
9.	Ownership: Private	8. On National Register or part of estab. district? No				
		10. Visible from public road? Yes 11. Endangered? No				
12.	Street address: 3301-03 N. Broadway 13. Style: commercial					
14.	Date(s): 2/4/1892					
15.	Architect: 16. Builder:					
17.	Original Use: residential 18. Present Use: commercial					
19.	Owner's name/address if known: Richey & Sons Service					
20.	No. of stories: 1 21. Basement? yes 22. Wall construction: masonry					
23.	Foundation material: concrete 24. Roof type/material: flat					
25.	No. Bays: Fron	t 5 Side 7 25. Wall treatment: red brick				
26.	. Plan shape: U 27. Changes: Addition? yes Altered?					
28.	Exterior condition: fair 29: Open to public? limited					
30.	Other Surveys in which included: St. Louis Harbor Historic Properties Reconnaissance, 1987, U.S. Army Corps of Engineers survey (partially incl.					

mental arches, most infilled. Terra cotta coping.

^{32.} History and Significance: Paul Kempf took out the \$500 permit for a onestory dwelling on Buchanan in 1892; this is probably the west part of the building. A building of about the right size appears on the 1883 Hopkins map. The building was being used at least partially as a dwelling in 1918, when J. Schneider had a minor alteration done. The Schorr-Kolkschneider Co. took out a very minor alteration permit to a store at this address in 1912. The building has been used primarily as a commercial concern through most of this century.



FACILITY NIW

5LCA5013-121

1.	. No. 107 3. Location of Negatives: Landmarks Association of St. Louis, Inc., 917 Locust, St. Louis, MO 63101					
2.	City/County: City of St. Louis, MO	4. Prepared by: Cynthia Longwisch & Mary M. Stiritz, Landmarks Association of St. Louis, Inc.				
5.	Date: 11/90	6. Sources of information: St. Louis Public Records, City Hall; St. Louis Public Library; MO Historical Soc.				
7.	Building? Yes					
9.	Ownership: Private	8. On National Register or part of estab. district? No				
		10. Visible from public road? Yes 11. Endangered? No				
12.	Street address: 3310 N. Broadway 13. Style: industrial					
14.	Date(s): 3/25/1926; 7/10/1912					
15.	Architect: 16. Builder:					
17.	Original Use: factory 18. Present Use: warehouse					
19.	Owner's name/address if known: Donley Pipe & Supply Co.					
20.	No. of stories: 2 21. Basement? yes 22. Wall construction: masonry					
23.	Foundation material: concrete 24. Roof type/material: flat					
25.	No. Bays: Front 11 Side 10 25. Wall treatment: dark red brick					
26.	Plan shape: rectangular 27. Changes: Addition? yes Altered? yes					
28.	Exterior condition: fair 29: Open to public? no					
30.	Other Surveys in which included: St. Louis Harbor Historic Properties Reconnaissance, 1987, U.S. Army Corps of Engineers survey (partially incl.)					

- 31. Further description of important features: All openings on the west and south elevations have been infilled with wood. Brick sills, flat arches. White terra cotta coping along roofline that has parapeting at corners and center front. One-story, six-bay rear addition predates main building.
- 32. History and Significance: The Missouri Engine Company took out a permit to build a \$50,000 factory in 1926. Charles Olcutt had operated a box factory on the site and had built a \$1,200 addition to the building in 1912; this rear addition was evidently allowed to remain when Missouri Engine replaced the old factory with their 1926 building.



4CASO13-122

1.	No. 106				
2.	City/County: City of St. Louis, MO	y of St. 4. Prepared by: Cynthia Longwisch & Mary M. Stiritz,			
5.	Date: 11/90 6. Sources of information: St. Louis Public Records				
7.	Building? Yes	City Hall; St. Louis Public Library; MO Historical Soc.			
9.	Ownership: Private	8. On National Register or part of estab. district? No			
		10. Visible from public road? Yes 11. Endangered? No			
12.	Street address: 3319 N. Broadway 13. Style: commercial				
14.	Date(s): c. 1870				
15.	Architect: 16. Builder:				
17.	Original Use: store/res. 18. Present Use: commercial				
19.	Owner's name/address if known:				
20.	No. of stories: 2 21. Basement? unk. 22. Wall construction: masonry				
23.	Foundation material: brick 24. Roof type/material: flat				
25.	No. Bays: Front 2 Side 1 25. Wall treatment: red/multi brick				
26.	Plan shape: rec	tangular 27. Changes: Addition? Altered? yes			
28.	Exterior condition: good 29: Open to public? no				
30.	Other Surveys in which included: St. Louis Harbor Historic Properties Reconnaissance, 1987, U.S. Army Corps of Engineers survey (partially incl.				
arch	covered with a es, brick sills	tion of important features: The facade of this building has variegated brick veneer. Front elevation windows have no and have a three-over-one Craftsman double-hung wood sash Double wood doors are transomed. Side window is segment-			

32. History and Significance: This building appears in the 1875 Compton & Dry pictorial map, with what appear to be round- or segmentally-arched window heads. A \$100 permit was taken out for an open porch on a "store & dwelling" at this address by C. Jaeger.

ally arched; smaller, square window is punched in. Short stepped parapet.



NO BOW BROWNING INDUSTRIAL SHEVEY I FACING AN

ST. LOUIS, MO



(cont'd. below)

1.	No. 109	3. Location of Negatives: Landmarks Association of St. Louis, Inc., 917 Locust, St. Louis, MO 63101			
2.	City/County: City of St. Louis, MO	St. 4. Prepared by: Cynthia Longwisch & Mary M. Stiritz,			
5.	Date: 11/90	6. Sources of information: St. Louis Public Records, City Hall; St. Louis Public Library; MO Historical Soc.			
7.	Building? Yes	8. On National Register or part of estab. district? No			
9.	Ownership: Private 10. Visible from public road? Yes 11. Endangered?				
12.	Street address: 3440 N. Broadway 13. Style: commercial				
14.	Date(s): 11/19/1906				
15.	Architect: 16. Builder: Sutherland Building & C				
17.	Original Use: warehouse 18. Present Use: industrial				
19.	Owner's name/address if known: Mallinckrodt Chemical Works				
20.	No. of stories: 3 21. Basement? yes 22. Wall construction: masonry				
23.	Foundation material: concrete 24. Roof type/material: flat				
25.	. No. Bays: Front 6 Side 17 25. Wall treatment: red & cull				
26.	. Plan shape: L 27. Changes: Addition? Altere				
28.	Exterior conditi	on: good 29: Open to public? no			
30.	Other Surveys in which included: St. Louis Harbor Historic Properties Reconnaissance, 1987, U.S. Army Corps of Engineers survey (partially incl				
ling	ounted by a scrol	cion of important features: A white terra cotta cornice is a lack ball pediment. A second t.c. cornice features dentil—lack modillions in the center; t.c. shield ornaments mark the The facade is laid in a checkerboard pattern using dark			

32. History and Significance: those above have flat arches; side windows are segmentally arched. All front elev. windows have brick sills. Above the first-story center openings is a large t.c. panel: "ST. LOUIS SASH and DOOR WORKS." Below, amid t.c. swags and ornamentally-bricked round arches, is the date 1906. See attached for information on the company, who occupied the building at least through 1940.

cull headers. First-story openings have large round arches;



H | 109 JOHN BROADWAY INDUSTRIAL SURVEY II.

9440 N. BROADWAY
PACING SE

97.60U15,10

790

ARCHITECTURAL/HISTORIC INVENTORY SURVEY FORM SLC A5013-12-4 MISSOURI OFFICE OF HISTORIC PRESERVATION

1.	No. 111	St. Louis, Inc., 917 Locust, St. Louis, MO 63101 ty/County: ty of St. 4. Prepared by: Cynthia Longwisch & Mary M. Stiritz,			
2.	City/County: City of St. Louis, MO				
5.	Date: 11/90	6. Sources of information: St. Louis Public Records,			
7.	Building? Yes	City Hall; St. Louis Public Library; MO Historical Soc.			
9.	Ownership: Private	8. On National Register or part of estab. district? No			
		10. Visible from public road? Yes 11. Endangered? No			
12.	Street address: 3523 N. Broadway 13. Style: commercial				
14.	Date(s): c. 1870				
15.	Architect: 16. Builder:				
17.	Original Use: commercial? 18. Present Use: commercial				
19.	Owner's name/address if known: O. T. Hodge Chile Parlor				
20.	No. of stories: 2 21. Basement? unk. 22. Wall construction: masonr				
23.	Foundation material: stone 24. Roof type/material: side gable				
25.	No. Bays: Front 4 Side 1 25. Wall treatment: red & painted bri				
26.	Plan shape: rectangular 27. Changes: Addition? yes Altered? yes				
28.	Exterior condition: fair/good 29: Open to public? yes				
30.	Other Surveys in which included: St. Louis Harbor Historic Properties Reconnaissance, 1987, U.S. Army Corps of Engineers survey (partially incl.				
71	Further described as invested fortunary. The fourth of this building has				

- 31. Further description of important features: The front of this building has been altered, perhaps more than once; a building permit to "change front of store" was issued in 1905 to Mr. Kupperschmidt. The front as it is today was probably redone later in this century. Openings have flat arches and brick sills. Side openings infilled with brick. CMU rear addition.
- History and Significance: No building permit could be found for this building; it seems to be on the 1883 Hopkins map. It is probably on the Compton & Dry 1875 map, but it is not possible to discern that positively. The building style is definitely earlier than late 19th century. The building was a men's clothing store and tenement during the 1920s.



HORTH BROADWAY INDUSTRUE SURVEY IT 3523 N. BROADWAY FACILIE WILL

ST. LOURS, MO

SLCA5013-125

(cont'd. below)

ty/County: ty of St. ouis, MO te: 11/90 milding? Yes whership: rivate	4. H 6. S City	Prepared landmarks Sources of Hall; St	oy: Cynthia Associatio	Longwisch on of St. Longon: St. Longon:	uis Public Records,	
nilding? Yes	City	Hall; St.				
vnership:		***	. Louis Fun	TIC LIBRARY		
- 1	8. (In Nationa	City Hall; St. Louis Public Library; MO Historica			
- 1		M Nationa	al Register	or part of	estab. district? No	
	10. V	/isible fi	com public	road? Yes	11. Endangered? No	
Street address: 352-31 N. Broadway 13. Style: Greek Revival				eek Revival		
Date(s): 2/17/1927						
Architect:			16. Buil	der:		
Original Use: bank 18. Present Use: bank						
Owner's name/address if known: Breman Bank						
No. of stories: 2 21. Basement? yes 22. Wall construction: mason			construction: masonry			
Foundation material: concrete 24. Roof type/material: flat			erial: flat			
No. Bays: Front 3 Side 9 25. Wall treatment: brick/stone vene			t: brick/stone veneer			
Plan shape: rectangular 27. Changes: Addition? Altered?			Altered?			
. Exterior condition: good 29: Open to public? yes			ic? yes			
Other Surveys in which included: St. Louis Harbor Historic Properties Reconnaissance, 1987, U.S. Army Corps of Engineers survey (partially incl				-		
	te(s): 2/17/1 chitect: iginal Use: 1 ner's name/add . of stories: undation mater . Bays: Front an shape: rect terior condit: her Surveys in connaissance,	te(s): 2/17/1927 chitect: iginal Use: bank ner's name/address if . of stories: 2 undation material: c . Bays: Front 3 an shape: rectangular terior condition: good her Surveys in which connaissance, 1987, 1	te(s): 2/17/1927 chitect: iginal Use: bank 18 ner's name/address if known: . of stories: 2 21. Base undation material: concrete . Bays: Front 3 Side 9 an shape: rectangular 27 terior condition: good her Surveys in which included connaissance, 1987, U.S. Army	te(s): 2/17/1927 chitect: 16. Buil iginal Use: bank 18. Present ner's name/address if known: Breman Ban of stories: 2 21. Basement? yes undation material: concrete 24. Ro Bays: Front 3 Side 9 25. Wa an shape: rectangular 27. Changes: terior condition: good 29: Changes: her Surveys in which included: St. Louiconnaissance, 1987, U.S. Army Corps of E	te(s): 2/17/1927 chitect: 16. Builder: iginal Use: bank 18. Present Use: bank ner's name/address if known: Breman Bank of stories: 2 21. Basement? yes 22. Wall undation material: concrete 24. Roof type/mat Bays: Front 3 Side 9 25. Wall treatmen an shape: rectangular 27. Changes: Addition? terior condition: good 29: Open to publ her Surveys in which included: St. Louis Harbor Hi	

stone steps lead up to the entrance. Stone griffins are carved above the door-

way, which is flanked by carved classical figures. Above the

History and Significance: front bays are stone shield and swag carvings. Massive side windows are eight-paned. Art Deco metal lamps flank the building front. Rear and south side elevations are not covered with stone, exposing the brick. The Breman Bank has been in continuous operation at this location since 1927.



#112

NORTH BRODDING INDUSTRIAL SURVEY II: 3527-31 N. BRODDING FRING SW

97. LOUIS , MO

790

SLCA803-1210

1.	No. 114 3. Location of Negatives: Landmarks Association of St. Louis, Inc., 917 Locust, St. Louis, MO 63101					
2.	City/County: City of St. Louis, MO	4. Prepared by: Cynthia Longwisch & Mary M. Stiritz, Landmarks Association of St. Louis, Inc.				
5.	Date: 11/90	6. Sources of information: St. Louis Public Records, City Hall; St. Louis Public Library; MO Historical Soc.				
7.	Building? Yes	s				
9.	Ownership: Private	8. On National Register or part of estab. district? No				
		10. Visible from public road? Yes 11. Endangered? No				
12.	. Street address: 3607 N. Broadway 13. Style: vernacular					
14.	Date(s): c. 1870					
15.	Architect:	16. Builder:				
17.	Original Use:	comm./res. 18. Present Use: union hall				
19.	Owner's name/address if known: UAW Local 1887					
20.	No. of stories: 2-1/2 21. Basement? unk. 22. Wall construction: masonry					
23.	Foundation material: limestone 24. Roof type/material: side gable					
25.	No. Bays: Front 4 Side 0 25. Wall treatment: brick/permastone					
26.	Plan shape: rectangular 27. Changes: Addition? yes Altered? yes					
28.	Exterior condition: good 29: Open to public? limited					
30.	Other Surveys in which included: St. Louis Harbor Historic Properties Reconnaissance, 1987, U.S. Army Corps of Engineers survey (partially incl.					

31. Further description of important features: The first story of this building has been covered with permastone, obscuring the original fenestration. The second-story windows have segmental arches and replacement panes. The two dormers have been infilled. A one-story brick rear addition is flat-roofed.

^{32.} History and Significance: No building permit could be located for this building, which was probably a store and tenement. It is probably on the 1875 Compton & Dry map, although is is difficult to tell for certain. It is on the 1883 Hopkins map.



NOTEN BROADWAY INDUSTRIAL SURVEY IN 1607 N. BROADWAY FACING NW


ST. 40419, MO

170

Location of Negatives: Landmarks Association of

3.

1. No. 113



(cont'd. below)

1. N	10. 113	St. Louis, Inc., 917 Locust, St. Louis, MO 63101			
C	City/County: City of St. Louis, MO	4. Prepared by: Cynthia Longwisch & Mary M. Stiritz, Landmarks Association of St. Louis, Inc.			
5. D	Date: 11/90	6. Sources of information: St. Louis Public Records,			
7. B	Building? Yes	City Hall; St. Louis Public Library; MO Historical Soc.			
9. 0	Ownership:	8. On National F	Register or part of estab. district? No		
	Private	10. Visible from	public road? Yes 11. Endangered? No		
12. St	reet address:	3611 rear N. Broadwa	ay 13. Style: flounder		
14. D	Date(s): c. 18	70			
15. A	Architect: 16. Builder:				
17. 0	Original Use: residential 18. Present Use: vacant				
19. 0	Owner's name/ado	dress if known: Mal	llinckrodt Chemical Works		
20. N	No. of stories: 2-1/2 21. Basement? yes 22. Wall construction: masonry				
23. F	Foundation material: stone 24. Roof type/material: flounder				
25. N	No. Bays: Fron	t 3 Side 1	25. Wall treatment: brick & frame		
26. P	Plan shape: rec	tangular 27. (Changes: Addition? yes Altered? yes		
28. E	Exterior condition: fair 29: Open to public? no				
	-		St. Louis Harbor Historic Properties rps of Engineers survey (partially incl.		
brick window	flounder with a	a brick-look asphaltck arches; two have	eatures: This building is a two-bay t-shingled two story addition. Original been altered to flat arches. Functiona ansomed wood doorway is located in the		

32. History and Significance: A two-story wood porch is located across the brick half of the east elevation. It is not possible to be certain whether this building appears on the 1875 Compton & Dry pictorial map; it is on the 1883 Hopkins map. No building permit could be found for it. Since this photo was taken, Mallinckrodt has cordoned it off and has removed some of the roofing around the dormer. It appears that they have plans to demolish the building.

frame portion. A dormer faces south in the frame section.



NORTH BROATHRY INDUSTRIAL GUEVEYS.

JULY REAR N. BROADWAY

FACING NE

ST. LOUB, MO

7/9

SLC A503 129

(cont'd. below)

1.	No. 119	 Location of Negatives: Landmarks Association of St. Louis, Inc., 917 Locust, St. Louis, MO 63101 				
2.	City/County: City of St. Louis, MO	4. Prepared by: Cynthia Longwisch & Mary M. Stiritz, Landmarks Association of St. Louis, Inc.				
5.	Date: 11/90	6. Sources of information: St. Louis Public Records,				
7.	Building? Yes	City Hall; St. Louis Public Library; MO Historical Soc.				
9.	Ownership: Private	8. On National Register or part of estab. district? No. 10. Visible from public road? Yes 11. Endangered? No.				
12.	Street address:	3732 N. Broadway 13. Style: commercial/Craftsman				
14.	Date(s): c. 1905-10					
15.	Architect: 16. Builder:					
17.	Original Use: commercial 18. Present Use: commercial					
19.	Owner's name/address if known:					
20.	No. of stories:	2 21. Basement? unk. 22. Wall construction: masonry				
23.	Foundation mate	rial: stone 24. Roof type/material: flat				
25.	No. Bays: Fron	t 3 Side 5 25. Wall treatment: brick				
26.	Plan shape: squ	are 27. Changes: Addition? Altered? yes				
28.	Exterior condition: good 29: Open to public? limited					
30.	-	n which included: St. Louis Harbor Historic Properties 1987, U.S. Army Corps of Engineers survey (partially incl.)				
31. ra c		tion of important features: A curvilinear parapet with ter- the building; on each elevation, a terra cotta "log" orn-				

32. History and Significance: elevation is a rectangular inset with a terra cotta shield with the letter N. Entrance has ornate, bracketed terra cotta surround. The metal-sided building behind this office has shaped parapets that echo those of this building. Because the siding is new, it is impossible to tell whether the parapets are old or new. Charles Naber's Sons operated a lumber/building materials business at this location into the 1940s. No permit could be found for this building, which Naber was using in the teens, at least.

ament is embedded in the parapet (part of one missing). Profiled terra cotta cornice has egg & dart molding just beneath. Windows have header lintel courses

with terra cotta keystones. At the second story on each



SLC ASO13-129

1.	No. 120	 Location of Negatives: Landmarks Association of St. Louis, Inc., 917 Locust, St. Louis, MO 63101 				
2.	City/County: City of St. Louis, MO	4. Prepared by: Cynthia Longwisch & Mary M. Stiritz, Landmarks Association of St. Louis, Inc.				
5.	Date: 11/90	6. Sources of information: St. Louis Public Records,				
7.	Building? Yes	City Hall; St. Louis Public Library; MO Historical Soc.				
9.	Ownership: Private	8. On National Register or part of estab. district? No 10. Visible from public road? Yes 11. Endangered? No				
12.	Street address:	3748 N. Broadway 13. Style: commercial				
14.	Date(s): 10/20/1894					
15.	Architect:	ect: 16. Builder:				
17.	Original Use: planing mill 18. Present Use: warehouse					
19.	Owner's name/ad	dress if known: Community Wholesale Tire				
20.	No. of stories:	2 21. Basement? unk. 22. Wall construction: masonry				
23.	Foundation mate	rial: stone 24. Roof type/material: flat				
25.	No. Bays: Fron	t 9 Side 25. Wall treatment: painted				
26.	Plan shape: rec	tangular 27. Changes: Addition? Altered? yes				
28.	Exterior condit	ion: good 29: Open to public? no				
30.	Other Surveys in which included: St. Louis Harbor Historic Properties Reconnaissance, 1987, U.S. Army Corps of Engineers survey (partially incl.					

- 31. Further description of important features: Stepped, terra cotta-coped parapet. Piers divide the facade into bays; various types of ornamental pressed brick blocks are inset at the terminations of the six tallest piers. Openings are variously segmentally—, elliptically— or round—arched; they have all been infilled with brick, glass brick or CMU.
- 32. History and Significance: The building permit for this building was taken out by the Mechanic's Planing Mill in 1894 for \$12,000. The company was still in operation at this location in 1930; by 1940, the building was vacant. It has since become a warehouse.



#120

NOTES BROKEWAY FACING

7/90


1.	No. 116	3. Location of Negatives: Landmarks Association of St. Louis, Inc., 917 Locust, St. Louis, MO 63101				
2.	City/County: City of St. Louis, MO	4. Prepared by: Cynthia Longwisch & Mary M. Stiritz, Landmarks Association of St. Louis, Inc.				
5.	Date: 11/90	6. Sources of information: St. Louis Public Records,				
7.	Building? Yes	City Hall; St. Louis Public Library; MO Historical Soc.				
9.	Ownership:	8. On National Register or part of estab. district? No				
	Private	10. Visible from public road? Yes 11. Endangered? No				
12.	Street address:	3749 N. Broadway 13. Style: vernacular				
14.	Date(s): 3/25	/1879				
15.	Architect: 16. Builder:					
17.	Original Use: comm./resid. 18. Present Use: commercial					
19.	Owner's name/address if known:					
20.	No. of stories:	2 21. Basement? yes 22. Wall construction: masonry				
23.	Foundation mate	rial: stone 24. Roof type/material: side gable				
25.	No. Bays: Front 5 Side 7 25. Wall treatment: painted brick					
26.	Plan shape: irregular 27. Changes: Addition? yes Altered? yes					
28.	Exterior condit	ion: fair 29: Open to public? limited				
30.	Other Surveys in which included: St. Louis Harbor Historic Properties Reconnaissance, 1987, U.S. Army Corps of Engineers survey (partially incl.)					

31. Further description of important features: Most of the openings in this building have been infilled with brick. Flat stone lintels are visible. Corner storefront is bricked in; the stone or concrete corner pillar is still in place. Rear of building has a flat roof; 1959 south side addition is CMU.

^{32.} History and Significance: J. Hoffman took out a permit for this store & dwelling in 1879 for \$3,000. The building is on the 1883 Hopkins map as a "livery," a business which may have involved the use of the rear of the building. During the 1930s and 1940s, the building was used as a tavern and dwelling.



MISSOURI OFFICE OF HISTORIC PRESERVATION ARCHITECTURAL/HISTORIC INVENTORY SURVEY FORM 544 ACCURACY SURVEY FORM



1.	No. 138	 Location of Negatives: Landmarks Association of St. Louis, Inc., 917 Locust, St. Louis, MO 63101 				
2.	City/County: City of St. Louis, MO	4. Prepared by: Cynthia Longwisch & Mary M. Stiritz, Landmarks Association of St. Louis, Inc.				
5.	Date: 11/90	6. Sources of information: St. Louis Public Records,				
7.	Building? Yes	City Hall; St. Louis Public Library; MO Historical Soc.				
9.	Ownership:	8. On National Register or part of estab. district? No				
-	Private	10. Visible from public road? Yes 11. Endangered? No				
12.	Street address:	3908-14 N. Broadway 13. Style: commercial				
14.	Date(s): 8/12/1908; 3/2/1904; 1/8/1927; 10/14/1927					
15.	Architect:	16. Builder: F. Hasselman				
17.	Original Use: tannery 18. Present Use: commercial					
19.	Owner's name/address if known: Star Bedding Co.					
20.	No. of stories:	2 21. Basement? yes 22. Wall construction: masonry				
23.	Foundation material: concrete 24. Roof type/material: flat					
25.	No. Bays: Front 5 Side 6 25. Wall treatment: red brick					
26.	Plan shape: rectangular 27. Changes: Addition? yes Altered? yes					
28.	Exterior condition: good 29: Open to public? limited					
30.	Other Surveys in which included: St. Louis Harbor Historic Properties Reconnaissance, 1987, U.S. Army Corps of Engineers survey (partially incl.					

- Further description of important features: A stepped parapet has white terra cotta coping and white diamond insets. Side and upper-story windows have double-rowlock segmental arches and brick sills. The first-story storefront has been infilled with glass brick; two panelled cast-iron pillars remain. A 1904 one-story addition to the north mimicks the roofline of the (cont'd. below)
- History and Significance: larger portion. A plain, painted brick addition of one story is attached to the building at the north side. Frederick L. Kayser took out the permit for this building as part of his tannery in 1908 for \$2,650. He owned the Kayser Raw Hide Co., formerly the Kayser & Nils Raw Hide Co. and, later, the Kayser Tanning Co. The one-story storeroom and office was built in 1904, and the large rear addition was built in two parts in 1927 by Wahlert & Guntzler ("est. 1848; buyers of all kinds of feathers and raw wool").



138 NOTH ERONDUMY INDUSTRIAL SURVEY II
5708-14 N. BROMOWAY
FACING NE

8. LOURS, NO 8/90

5LC AS013-132

(cont'd. below)

No. 155	3. Location of Negatives: Landmarks Association of			
	St. Louis, Inc., 917 Locust, St. Louis, MO 63101			
City/County:	St. Louis, The., 31/ Locust, St. Louis, Mo 03101			
City of St. Louis, MO	 Prepared by: Cynthia Longwisch & Mary M. Stiritz, Landmarks Association of St. Louis, Inc. 			
Date: 11/90	6. Sources of information: St. Louis Public Records, City Hall; St. Louis Public Library; MO Historical Soc.			
Building? Yes				
Ownership: Private	8. On National Register or part of estab. district? No 10. Visible from public road? Yes 11. Endangered? No			
Street address:	address: 4001-05 N. Broadway 13. Style: commercial			
Date(s): 4/4/1888				
Architect: 16. Builder:				
Original Use: comm./resid. 18. Present Use: commercial				
Owner's name/address if known: Vito's Auto Parts, Inc.				
No. of stories:	1 21. Basement? yes 22. Wall construction: masonry			
Foundation mater	rial: limestone 24. Roof type/material: flat			
No. Bays: Fron	t 3 Side 8 25. Wall treatment: painted			
Plan shape: L	27. Changes: Addition? Altered? YES			
Exterior condit	ion: poor 29: Open to public? no			
	which included: St. Louis Harbor Historic Properties 1987, U.S. Army Corps of Engineers survey (partially incl.			
	Louis, MO Date: 11/90 Building? Yes Ownership: Private Street address: Date(s): 4/4/18 Architect: Original Use: of Owner's name/add No. of stories: Foundation mater No. Bays: Front Plan shape: L Exterior condition Other Surveys in			

north that were included in the building permit have been demolished. However, the remaining cast-iron storefront is such a wonderful specimen of the art that

it is included in this survey. Paneled columns feature fields

^{32.} History and Significance: of tiny pyramids, fluting, and bands of hemispheres. Corner column is gridded like a hand grenade. Capitals have floral motifs and rosette medallions. Quatrefoil grillwork below several display windows. Original transomed, wood-panelled double doors, some with Eastlake carving above. Southernmost display bay features Queen Anne windows. No casting imprint. Sidewalk is gone and building has been allowed to deteriorate. Permitwas taken out in 1888 for \$12,000 for 3 adj. bldgs. by Louis Kohrmel = no info.



#165 NORTH BROADWAY INDUSTRIAL SURVEY II
4001-05 N. BROADWAY
FACING SW

8/90

SLC A5013-133

1.	No. 140	3. Location of Negatives: Landmarks Association of St. Louis, Inc., 917 Locust, St. Louis, MO 63101			
2.	City/County: City of St. Louis, MO	4. Prepared by: Cynthia Longwisch & Mary M. Stiritz, Landmarks Association of St. Louis, Inc.			
5.	Date: 11/90	6. Sources of information: St. Louis Public Records,			
7.	Building? Yes	City Hall; St. Louis Public Library; MO Historical Soc.			
9.	Ownership: Private	8. On National Register or part of estab. district? No 10. Visible from public road? Yes 11. Endangered? No			
12.	Street address:	4006 N. Broadway 13. Style: commercial			
14.	Date(s): 5/11/1904				
15.	Architect: Harry Clymer 16. Builder: A. Haenster, Builder				
17.	Original Use: office 18. Present Use: office				
19.	Owner's name/address if known: Harrison Lumber Co.				
20.	No. of stories: 1 21. Basement? yes 22. Wall construction: masonry				
23.	Foundation mate	rial: limestone 24. Roof type/material: flat			
25.	No. Bays: Fron	t 3 Side 4 25. Wall treatment: red brick			
26.	Plan shape: rec	tangular 27. Changes: Addition? yes Altered? yes			
28.	Exterior condition: good 29: Open to public? limited				
30.	Other Surveys in which included: St. Louis Harbor Historic Properties Reconnaissance, 1987, U.S. Army Corps of Engineers survey (partially incl.				
31.	Further descrip	tion of important features: Parapeted cornice with heavy			

^{31.} Further description of important features: Parapeted cornice with heavy terra cotta coping. Large corbelled brick cornice. Front windows have jack arches with brick keys; these have been partially infilled to fit smaller new windows. A stone sill course crosses the front of the building. Side windows have double-rowlock segmental arches adn stone sills and are (cont'd. below)

^{32.} History and Significance: all infilled. The permit for this building was taken out in 1904 by P. Gruner & Bros. for \$2,000. The firm was a lumber company; the property is still a lumberyard.



5CCASO13-174

1.	No. 136	 Location of Negatives: Landmarks Association of St. Louis, Inc., 917 Locust, St. Louis, MO 63101 			
2.	City/County: City of St. Louis, MO	4. Prepared by: Cynthia Longwisch & Mary M. Stiritz, Landmarks Association of St. Louis, Inc.			
5.	Date: 11/90	6. Sources of information: St. Louis Public Records,			
7.	Building? Yes	City Hall; St. Louis Public Library; MO Historical Soc.			
9.	Ownership:	8. On National Register or part of estab. district? No			
J.	Private	10. Visible from public road? Yes 11. Endangered? No			
12.	Street address:	4057 N. Broadway 13. Style: commercial/Second Empire			
14.	Date(s): 2/4/1880				
15.	Architect: 16. Builder:				
17.	Original Use: commercial 18. Present Use: vacant				
19.	Owner's name/add	lress if known:			
20.	No. of stories:	2 21. Basement? yes 22. Wall construction: masonry			
23.	Foundation mate	rial: limestone 24. Roof type/material: mansard & flat			
25.	No. Bays: Fron	t 6 Side 7 25. Wall treatment: painted brick			
26.	Plan shape: irr	egular 27. Changes: Addition? yes Altered? yes			
28.	Exterior condit	ion: fair 29: Open to public? no			
30.	30. Other Surveys in which included: St. Louis Harbor Historic Pro Reconnaissance, 1987, U.S. Army Corps of Engineers survey (part				

- 31. Further description of important features: The mansard on this building has asphalt shingles and boarded dormer windows (traffic prohibited a better photo). Corbelled cornice. Double rowlock segmental arches and stone sills on the windows, which are all infilled. Original corner storefront has been altered and infilled with aluminum & wood. Terra cotta coping. (cont'd. below)
- 32. History and Significance: Portions of building on the south and rear have flat roofs. Building is attached to 812 Angelica (#135) by means of a small passageway. The permit for this "wareroom and wagon house" was taken out in 1880 by A. Ralive. No name for the business was given and Ralive could not be traced. During the 1930s and 1940s, at least, the building was used as a meat store and grocery store.



NORTH BROADWAY INDUSTRIAL SURVEY IT 4057 N. BROADWAY FACING SW #136

SLCA5013-135

(cont'd. below)

1.	No. 157	3. Location of Negatives: Landmarks Association of St. Louis, Inc., 917 Locust, St. Louis, MO 63101					
2.	City/County: City of St. Louis, MO	4. Prepared by: Cynthia Longwisch & Mary M. Stiritz, Landmarks Association of St. Louis, Inc.					
5.	Date: 11/90	6. Sources of information: St. Louis Public Records, City Hall; St. Louis Public Library; MO Historical Soc.					
7.	Building? Yes						
9.	Ownership: Private	8. On National Register or part of estab. district? No 10. Visible from public road? Yes 11. Endangered? No					
12.	Street address:	4222-24 N. Broadway 13. Style: vernacular					
14.	Date(s): 7/21/1876						
15.	Architect: 16. Builder:						
17.	Original Use: comm./resid. 18. Present Use: residential						
19.	Owner's name/address if known:						
20.	No. of stories: 2 21. Basement? unk. 22. Wall construction: mason						
23.	Foundation mate	rial: stone 24. Roof type/material: side gable					
25.	No. Bays: Fron	t 2 Side 25. Wall treatment: red brick					
26.	Plan shape: rec	tangular 27. Changes: Addition? yes Altered? yes					
28.	Exterior condition: fair/good 29: Open to public? no						
30.	-	n which included: St. Louis Harbor Historic Properties 1987, U.S. Army Corps of Engineers survey (partially incl.)					
	ed brick cornice	tion of important features: Front of building has a dentic- . Parapeted chimneys in side walls. Front elevation has red, probably in 1926 when neighboring store (#158) was					

32. History and Significance: building of this age. Storefront was probably all cast-iron; only iron pillars remain; the front has been infilled with wood. The 1876 permit for this building was taken out by D. P. Zeipe for a store and dwelling. The building was used as a furniture store during the 1930s.

built. Windows have flat arches and brick sills and soldier course extends

above storefront, none of which are characteristic of a



1.	No. 158		 Location of Negatives: Landmarks Association of St. Louis, Inc., 917 Locust, St. Louis, MO 63101 			
2.	City/County: City of St. Louis, MO	4. Prepared by: Cynthia Longwisch & Mary M. Stiritz, Landmarks Association of St. Louis, Inc.				
5.	Date: 11/90	6. Sources of information: St. Louis Public Records, City Hall; St. Louis Public Library; MO Historical Soc.				
7.	Building? Yes	_		h		
9.	Ownership: Private	8. On National Register or part of estab. district? No 10. Visible from public road? Yes 11. Endangered? No			11. Endangered? No	
12.					mmercial/Craftsman	
14.	Date(s): 10/22/1926					
15.	Architect:			. Build	ler:	
17.	Original Use: store 18.			Present	Use: stor	age
19.	Owner's name/add	dress if know	n:			
20.	No. of stories: 1 21. Baseme			t? unk.	22. Wall	construction: masonry
23.	Foundation mate	rial: concre	te 2	24. Roo	of type/mat	erial: flat
25.	No. Bays: Front 1 Side 3			25. Wal	ll treatmen	t: textured brick
26.	Plan shape: rectangular 27. Changes: Addition? Altered? ye			Altered? yes		
28.	28. Exterior condition: good/fair 29: Open to public? n			ic? no		
30.	Other Surveys in which included: St. Louis Harbor Historic Properties Reconnaissance, 1987, U.S. Army Corps of Engineers survey (partially incl.					

31. Further description of important features: A parapeted front roofline is highlighted with white vitreous brick. A soldier course extends across the building above the storefront. Storefront has been infilled with wood. Terra cotta coping. See photo #157 for closer view.

^{32.} History and Significance: The permit for this building was taken out by L. Rubin in 1926 for a \$3,000 store. City directories offer no clue as to which of several L. Rubins this might have been. The 1930 city directory lists the occupant of the building as the Western Union Telegraph Co. The 1940 city directory says the building was the "Branch Dispensary No. 1 Hospital Division." It has been used for storage in recent years.



(cont'd. below)

1.	No. 081	3. Location of Negatives: Landmarks Association of				
		St. Louis, Inc., 917 Locust, St. Louis, MO 63101				
2.	City/County: City of St. Louis, MO	4. Prepared by: Cynthia Longwisch & Mary M. Stiritz, Landmarks Association of St. Louis, Inc.				
5.	Date: 11/90	6. Sources of information: St. Louis Public Records, City Hall; St. Louis Public Library; MO Historical Soc.				
7.	Building? Yes					
9.	Ownership:	8. On National Register or part of estab. district? No				
	Private	10. Visible from public road? Yes 11. Endangered? No				
12.	Street address: 210 Buchanan 13. Style: industrial					
14.	Date(s): 9/17/1906; 7/23/1909					
15.	Architect: 16. Builder:					
17.	Original Use: industrial 18. Present Use: industrial					
19.	Owner's name/address if known: Scienco, Inc.					
20.	No. of stories: 1 & 3 21. Basement? yes 22. Wall construction: masonry					
23.	Foundation material: concrete 24. Roof type/material: flat					
25.	No. Bays: Front 11 Side 6 25. Wall treatment: stuccoed/ptd. brid					
26.	Plan shape: rec	tangular 27. Changes: Addition? Altered? yes				
28.	Exterior condition: good 29: Open to public? no					
30.		n which included: St. Louis Harbor Historic Properties 1987, U.S. Army Corps of Engineers survey (partially incl.)				
	separate entitie	tion of important features: This building was built as s; the older part is one-story and the newer, three. A cures about half of the west elevation of the older part.				

32. History and Significance: horizontally by recessed panels. Some window infill.

A low stepped parapet distinguishes the primary (north) elevation of the newer

part. Multipane industrial metal sash windows are separated

Foster Brothers Manufacturing Co. took out a permit for a one-story fireproof foundry for \$11,000 in 1906. This was followed by the three-story fireproof manufacturing building behind it, built by the same company in 1909 for \$35,000.



1.	No. 074	 Location of Negatives: Landmarks Association of St. Louis, Inc., 917 Locust, St. Louis, MO 63101 				
2.	City/County: City of St. Louis, MO	4. Prepared by: Cynthia Longwisch & Mary M. Stiritz, Landmarks Association of St. Louis, Inc.				
5.	Date: 11/90	6. Sources of information: St. Louis Public Records, City Hall; St. Louis Public Library; MO Historical Soc.				
7.	Building? Yes					
9.	Ownership: Private	8. On National Register or part of estab. district? No 10. Visible from public road? Yes 11. Endangered? No				
12.	Street address:	Street address: 910-12 Buchanan 13. Style: Greek Revival				
14.	Date(s): 9/26/1877					
15.	Architect: 16. Builder:					
17.	Original Use: residential 18. Present Use: residential					
19.	Owner's name/address if known:					
20.	No. of stories:	2-1/2 21. Basement? yes 22. Wall construction: masonry				
23.	Foundation mate	rial: limestone 24. Roof type/material: side gable				
25.	No. Bays: Fron	t 4 Side 1 25. Wall treatment: red brick				
26.	Plan shape: rec	tangular 27. Changes: Addition? Altered? yes				
28.	Exterior condition: good 29: Open to public? no					
30.		n which included: St. Louis Harbor Historic Properties 1987, U.S. Army Corps of Engineers survey (partially incl.)				
	openings, which	tion of important features: Shaped stone arches head win- also have bracketed stone lugsills. Replacement panes.				

Single dormer. Parapeted chimneys in east and west walls. Plain wood cornice

Building fronts

(cont'd. below)

probably replaces more ornate original. Stone water table.

directly on sidewalk. Adjoining residence on west side

^{32.} History and Significance: recently demolished; building "shadow" is markedly present on the west wall. The permit for this duplex was taken out in 1877 by T. Sparks. The building has always been used as a residence.



NORTH BROWNEY INDUSTRIAL SURVEY # 910-12 BUCKENIAN
FACING SE

97. LOUB, MO

7/90

1.	No. 009	3. Location of Negatives: Landmarks Association of St. Louis, Inc., 917 Locust, St. Louis, MO 63101	
2.	City/County: City of St. Louis, MO	4. Prepared by: Cynthia Longwisch & Mary M. Stiritz, Landmarks Association of St. Louis, Inc.	
5.	Date: 11/90	6. Sources of information: St. Louis Public Records,	
7.	Building? Yes	City Hall; St. Louis Public Library; MO Historical Soc.	
	0	8. On National Register or part of estab. district? No	
9.	Ownership: Private	10. Visible from public road? Yes 11. Endangered? No	
12.	Street address:	111 Clinton 13. Style: commercial/industrial	
14.	Date(s): 3/24/	1890; 1908; 1944; 1948	
15.	. Architect: 16. Builder:		
17.	Original Use:	foundry 18. Present Use: commercial/industrial	
19.	Owner's name/ad	dress if known: Northwestern Bottle, 123 Clinton	
20.	No. of stories:	5 21. Basement? no 22. Wall construction: masonry	
23.	Foundation mate	rial: limestone 24. Roof type/material: flat/stepped	
25.	No. Bays: Fron	t 12 Side 10 25. Wall treatment: red & multi brick	
26.	Plan shape: rec	tangular 27. Changes: Addition? yes Altered? yes	
28.	Exterior condition: fair 29: Open to public? no		
30.	Other Surveys i	n which included: St. Louis Harbor Historic Properties	

31. Further description of important features: Remaining original windows have segmental arches and stone sills; most are infilled with wood or brick. South elevation has had much replacement brick. A loading dock fronts the east elevation while two garage bays open in the south wall's east end. The Ranken & Fritch or Fritz Foundry took out a building permit in 1890 for (cont. below)

Reconnaissance, 1987, U.S. Army Corps of Engineers survey (partially incl.)


32. History and Significance: \$2,000 for a two-story foundry at this address. The company were no longer in business by the early 20th century. In 1944, the Hard Broad Fab. Co. took out a permit for \$1,000 to alter a "5-story factory." No permit appears in between to indicate when the additional three stories were built. The Monroe Realty & Inv. Co. spent \$35,000 in 1948 to alter a "fivestory storage and sales grocery warehouse."



9 NORTH BROADURY INDUSTRIAL SURVEY # IN CLIMTON FACING NW

57. LOUIS, MO

7/90



1.	No. 008	3. Location of Negatives: Landmarks Association of St. Louis, Inc., 917 Locust, St. Louis, MO 63101	
2.	City/County: City of St. Louis, MO	4. Prepared by: Cynthia Longwisch & Mary M. Stiritz, Landmarks Association of St. Louis, Inc.	
5.	Date: 11/90	6. Sources of information: St. Louis Public Records,	
7.	Building? Yes	City Hall; St. Louis Public Library; MO Historical Soc.	
9.	Ownership:	8. On National Register or part of estab. district? No	
.	Private	10. Visible from public road? Yes 11. Endangered? No	
12.	Street address:	117 Clinton 13. Style: industrial	
14.	Date(s): c. 1900 - 05; 1936; 1954		
15.	Architect:	16. Builder:	
17.	Original Use: comm./indust. 18. Present Use: commercial/industrial`		
19.	Owner's name/address if known:		
20.	No. of stories:	2 21. Basement? no 22. Wall construction: masonry	
23.	Foundation material: stone 24. Roof type/material: flat		
25.	No. Bays: Front 5 Side 25. Wall treatment: red brick		
26.	Plan shape: rec	tangular 27. Changes: Addition? Altered? yes	
28.	Exterior condit	ion: good 29: Open to public? no	
30.	Other Surveys in which included: St. Louis Harbor Historic Properties Reconnaissance, 1987, U.S. Army Corps of Engineers survey (partially incl.		
31.	Further descrip	tion of important features: Five garage bays with no arche	

- 31. Further description of important features: Five garage bays with no arches are located across the ground level. Five 6-over-3 horizontally-hinged windows with brick sills and no arches are located near the roofline. Terra cotta coping.
- 32. History and Significance: The site of this building was included in the late 1900 demolition permit taken out by Thomas & Kelly. No building permit was entered for this building, although a permit dated 2/17/1908 was taken out by Foundry Inv. Co. to alter a factory/warehouse for \$4,000. They additionally took out a permit in 1936 to alter a garage at this address. The original building was evidently one story, because a 1954 permit by Wetterow Grocery Co. was for \$18,000 to add a "one story second floor addition to garage."



NORTH BROADWAY INDUSTRIAL SURVEY IN 107 CLIMBA

31100037110

10 7/90

5LCAS013-14

1.	No. 007	3. Location of Negatives: Landmarks Association of
2.	City/County: City of St. Louis, MO	St. Louis, Inc., 917 Locust, St. Louis, MO 63101 4. Prepared by: Cynthia Longwisch & Mary M. Stiritz, Landmarks Association of St. Louis, Inc.
5.	Date: 11/90	6. Sources of information: St. Louis Public Records,
7.	Building? Yes	City Hall; St. Louis Public Library; MO Historical Soc.
9.	Ownership:	8. On National Register or part of estab. district? No
Private	-	10. Visible from public road? Yes 11. Endangered? No
12.	Street address:	119 Clinton 13. Style: commercial/industrial
14.	Date(s): c. 1900 -1905	
15.	Architect:	16. Builder:
17.	Original Use:	industrial 18. Present Use: commercial/industrial
19.	Owner's name/ad	dress if known: Follman Properties
20.	No. of stories:	3 21. Basement? yes 22. Wall construction: masonry
23.	Foundation mate	rial: stone 24. Roof type/material: flat
25.	No. Bays: Fron	t 2 Side 25. Wall treatment: painted brick
26.	Plan shape: L	27. Changes: Addition? Altered? yes
28.	Exterior condit	ion: good 29: Open to public? no
30.		n which included: St. Louis Harbor Historic Properties 1987, U.S. Army Corps of Engineers survey (partially incl.

- 31. Further description of important features: Small, 6 over 6 windows are punched into the recessed panels formed by a rectangular brick grid on the primary elevation. The recessed panels appear to be infilled larger windows. Terra cotta coping. A short corner wall on the roof appears to allow access to the roof itself.
- 32. History and Significance: Although no building permit could be found for this building, there is a demolition permit for this address by Thomas & Kelly (about whom no information could be located) in December, 1900.



NORTH BROADWAY INDUSTRIAL SURVEY IL 119 CLINTON FACING NE

ST. LOUIS, MO

1/90

54CAS013-142

MISSOURI OFFICE OF HISTORIC PRESERVATION ARCHITECTURAL/HISTORIC INVENTORY SURVEY FORM

-			
1.	No. 006		f Negatives: Landmarks Association of Inc., 917 Locust, St. Louis, MO 63101
2.	City/County: City of St. Louis, MO	4. Prepared by	y: Cynthia Longwisch & Mary M. Stiritz, Association of St. Louis, Inc.
5.	Date: 11/90	1	information: St. Louis Public Records,
7.	Building? Yes		Louis Public Library; MO Historical Soc.
9.	Ownership:	8. On Nationa	l Register or part of estab. district? No
<i>-</i>	Private	10. Visible fro	om public road? Yes 11. Endangered? No
12.	Street address:	123-29 Clinton	13. Style: industrial
14.	. Date(s): 9/26/1922		
15.	Architect:		16. Builder:
17.	7. Original Use: factory 18. Present Use: office/warehouse		. Present Use: office/warehouse
19.	Owner's name/address if known: Northwestern Bottle Co., 2204 N. Second		
20.	No. of stories: 1 & 2 21. Basement? no 22. Wall construction: mason		
23.	Foundation material: concrete		24. Roof type/material: flat
25.	No. Bays: Front 13 Side		25. Wall treatment: painted brick
26.	Plan shape: trapezoid 27.		Changes: Addition? Altered?
28.	Exterior condition: good		29: Open to public? limited
30.	Other Surveys in which included: St. Louis Harbor Historic Properties Reconnaissance, 1987, U.S. Army Corps of Engineers survey (partially incl.		

- 31. Further description of important features: This building is built at an angle across the northeast corner of Clinton and N. Second. Roll-up garage doors predominate across the primary elevation. A shaped brick chimney rises above the building, topped with brick corbelling. Windows are of the multipane industrial type.
- 32. History and Significance: An \$18,000 permit for this building was taken out in 1922 by the Reardon Company. Reardon was a manufacturer of glue. It appears that their interest in this building disappeared c. early 1930s.



123-29 CLINTON FACING NE

1.	No. 085	3. Location of Negatives: Landmarks Association of St. Louis, Inc., 917 Locust, St. Louis, MO 63101	
2.	City/County: City of St. Louis, MO	4. Prepared by: Cynthia Longwisch & Mary M. Stiritz, Landmarks Association of St. Louis, Inc.	
5.	Date: 11/90	6. Sources of information: St. Louis Public Records, City Hall; St. Louis Public Library; MO Historical Soc.	
7.	Building? Yes	City Hall, St. Louis Fublic Library, MO Historical Soc.	
9.	Ownership: Private	8. On National Register or part of estab. district? No	
9.		10. Visible from public road? Yes 11. Endangered? No	
12.	Street address: 64-66 Dock 13. Style: industrial		
14.	Date(s): 11/7/1901		
15.	Architect: E. C. Klipstein 16. Builder: Jean Jameton Const. Co.		
17.	Original Use: warehouse 18. Present Use: warehouse		
19.	Owner's name/address if known: Shanfield Bros. Metal Co.		
20.	No. of stories: 2 21. Basement? yes 22. Wall construction: masonry		
23.	Foundation material: concrete 24. Roof type/material: flat		
25.	No. Bays: Front 13 Side 7 25. Wall treatment: painted brick		
26.	Plan shape: modif. square 27. Changes: Addition? Altered?		
28.	Exterior condition: fair 29: Open to public? no		
30.	Other Surveys in which included: St. Louis Harbor Historic Properties Reconnaissance, 1987, U.S. Army Corps of Engineers survey (partially incl.		
	building are do	tion of important features: The majority of the openings on uble- or triple-rowlock segmentally arched. A stepped paracoping is located across the north elevation. Five loading	

road.

dock bays are spaced across the east elevation, in close proximity to the rail-

^{32.} History and Significance: The Joseph Hefner Realty Co. took out the building permit for this warehouse in 1901 for \$27,000. The company hired noted architect E. C. Klipstein to complete the job.



1.	No. 084	3. Location of Negatives: Landmarks Association of	
2.	City/County: City of St. Louis, MO	St. Louis, Inc., 917 Locust, St. Louis, MO 63101 4. Prepared by: Cynthia Longwisch & Mary M. Stiritz, Landmarks Association of St. Louis, Inc.	
5.	Date: 11/90	6. Sources of information: St. Louis Public Records,	
7.	Building? Yes	City Hall; St. Louis Public Library; MO Historical Soc	
9.	Ownership: Private	8. On National Register or part of estab. district? No 10. Visible from public road? Yes 11. Endangered? No	
12.	Street address:	Street address: 76 Dock 13. Style: industrial	
14.	Date(s): 2/16/1893		
15.	Architect: 16. Builder:		
17.	Original Use: warehouse 18. Present Use: warehouse		
19.	Owner's name/address if known: Cozad		
20.	No. of stories: 1 21. Basement? yes 22. Wall construction: masonry		
23.	Foundation material: stone 24. Roof type/material: flat		
25.	No. Bays: Front 10 Side 10 25. Wall treatment: painted brick		
26.	Plan shape: irregular L 27. Changes: Addition? yes Altered? yes		
28.	Exterior condition: good 29: Open to public? no		
30.	Other Surveys in which included: St. Louis Harbor Historic Properties Reconnaissance, 1987, U.S. Army Corps of Engineers survey (partially incl.		
31. feat		tion of important features: The primary distinguishing ding is a dentilled parapet of fairly substantial height in	

proportion to the building. Segmentally-arched windows have six-over-three panes. A roofed loading dock extends the length of the front elevation. Small

additions exist to the east of the building.

^{32.} History and Significance: The St. Louis Sash & Door Works built this \$3,000 warehouse in 1893. Their main factory was located at 3440 N. Broadway (#109).



ĺ	SLC	A501	'Z-	45
---	-----	------	-----	----

1.	No. 086	3. Location of Negatives: Landmarks Association of			
2.	City/County: City of St.	St. Louis, Inc., 917 Locust, St. Louis, MO 63101 4. Prepared by: Cynthia Longwisch & Mary M. Stiritz,			
	Louis, MO	Landmarks Association of St. Louis, Inc.			
5.	Date: 11/90	6. Sources of information: St. Louis Public Records, City Hall; St. Louis Public Library; MO Historical Soc.			
7.	Building? Yes	8. On National Register or part of estab. district? No			
9.	Ownership: Private	10. Visible from public road? Yes 11. Endangered? No			
2.	Street address:	121 Dock 13. Style: commercial			
4.	Date(s): 4/13/	1898			
5.	Architect:	16. Builder:			
7.	Original Use: factory 18. Present Use: vacant				
9.	Owner's name/address if known:				
20.	No. of stories: 4 21. Basement? yes 22. Wall construction: masonr				
23.	Foundation material: concrete 24. Roof type/material: flat				
25.	No. Bays: Fron	t 9 Side 4 25. Wall treatment: red brick			
26.	Plan shape: rec	tangular 27. Changes: Addition? yes Altered? yes			
28.	Exterior condition: poor 29: Open to public? no				
30.	Other Surveys in which included: St. Louis Harbor Historic Properties Reconnaissance, 1987, U.S. Army Corps of Engineers survey (partially incl.				
	by piers; they a	tion of important features: Inner bays are recessed, set re headed by segmental arches. Remaining bays have indiv- segmentally-arched windows with stone sills. Between the			

32. History and Significance: addition is now mostly demolished; a concrete hopper stands north of the addition. The building permit was taken out in 1898 by F. Christen & Son for \$6,000. The firm made leather bellows; a painted sign, "Christen & Sons, Mfrs. of Blacksmith Bellows" is still faintly visible on the east elevation. Beginning around 1930, the Sterling [wood] Box company occupied the building concurrently with the Christen company. The building has been the victim of vandals and neglect and is in danger of total destruction.

first and second stories is a stringcourse of projecting corbelled brickwork. Corbelled cornice. Terra cotta coping. One-story rear (north) (cont'd. below)



SLCA503-146

1.	No. 166	 Location of Negatives: Landmarks Association of St. Louis, Inc., 917 Locust, St. Louis, MO 63101 	
2.	City/County: City of St. Louis, MO	4. Prepared by: Cynthia Longwisch & Mary M. Stiritz, Landmarks Association of St. Louis, Inc.	
5.	Date: 11/90	6. Sources of information: St. Louis Public Records, City Hall; St. Louis Public Library; MO Historical Soc.	
7.	Building? Yes		
9.	Ownership:	8. On National Register or part of estab. district? No	
J.	Private	10. Visible from public road? Yes 11. Endangered? No	
12.	Street address:	105 Ferry 13. Style: commercial	
14.	Date(s): 7/19/	1927; 12/2/1948	
15.	Architect:	16. Builder:	
17.	Original Use:	office 18. Present Use: office	
19.	Owner's name/address if known: Missouri Dept. of Agriculture/for sale		
20.	. No. of stories: 1 21. Basement? no 22. Wall construction: mas		
23.	Foundation mate	rial: brick 24. Roof type/material: flat	
25.	No. Bays: Fron	t 5 Side 4 25. Wall treatment: multicolored brick	
26.	Plan shape: rectangular 27. Changes: Addition? yes Altered?		
28.	Exterior condit	ion: good 29: Open to public? no	
30.	_	n which included: St. Louis Harbor Historic Properties 1987, U.S. Army Corps of Engineers survey (partially incl.)	

31. Further description of important features: The multi-stepped parapet is coped with white terra cotta. Four round-arched windows across the front elevation are obscured by square screens mounted over them. Flanking the doorway are two white terra cotta medallions with round centers infilled with red brick. Side windows have flat soldier arches and brick sills. (cont'd. below)

^{32.} History and Significance: Attached to the rear of the building is a one-story brick-walled addition with a quonset hut roofline. Puritan Oil took out the permit to build the \$15,000 office in 1927. By 1948, the building belonged to the Walsh Refractories Corporation, who built the rear addition for \$30,000.



5LCAS013-14-7

1.	No. 164	 Location of Negatives: Landmarks Association of St. Louis, Inc., 917 Locust, St. Louis, MO 63101 		
2.	City/County: City of St. Louis, MO	4. Prepared by: Cynthia Longwisch & Mary M. Stiritz, Landmarks Association of St. Louis, Inc.		
5.	Date: 11/90	6. Sources of information: St. Louis Public Records,		
7.	Building? Yes	City Hall; St. Louis Public Library; MO Historical Soc.		
9.	Ownership: Private	8. On National Register or part of estab. district? No 10. Visible from public road? Yes 11. Endangered? No		
12.	Street address:	112-16 Ferry 13. Style: industrial		
14.	Date(s): 5/1/1	906; 1/29/1935; 12/1/1936		
15.	Architect:	16. Builder: Kellerman Const. Co. (1906)		
17.	Original Use:	chem. works 18. Present Use: warehouse?		
19.	Owner's name/ad	dress if known:		
20.	No. of stories:	1 & 2 21. Basement? unk. 22. Wall construction: masonry		
23.	Foundation mate	rial: concrete 24. Roof type/material: flat		
25.	No. Bays: Fron	t 5 Side 10 25. Wall treatment: painted brick		
26.	Plan shape: L	27. Changes: Addition? yes Altered? yes		
28.	Exterior condit	ion: good 29: Open to public? no		
30.	Other Surveys in which included: St. Louis Harbor Historic Properties Reconnaissance, 1987, U.S. Army Corps of Engineers survey (partially inc.)			
31.	Further description of important features: A front short parapet has terra			

- 31. Further description of important features: A front short parapet has terra cotta coping. Soldier lintel and sill courses at second story. Rear loading door has double-rowlock segmental arch; from inset of door it can be seen that the walls are unusually thick, probably relating to its original function as part of a chemical works. Rear part of the building is one story.
- 32. History and Significance: The Grasselli Chemical Company took out the permit to build a one-story, \$8,000 chemical works in 1906, hiring the Kellerman Construction Co. to do the job. Grasselli sold the building to Du Pont between the beginning of 1935 and the end of 1936, when Du Pont took out a \$4,750 permit to alter and add to the building. The second-story sill course probably hides the break between stories.



5LCAS013-144

1.	No. 165	 Location of Negatives: Landmarks Association of St. Louis, Inc., 917 Locust, St. Louis, MO 63101 	
2.	City/County: City of St. Louis, MO	4. Prepared by: Cynthia Longwisch & Mary M. Stiritz, Landmarks Association of St. Louis, Inc.	
5.	Date: 11/90	6. Sources of information: St. Louis Public Records,	
7.	Building? Yes	City Hall; St. Louis Public Library; MO Historical Soc.	
9.	Ownership:	8. On National Register or part of estab. district? No	
	Private	10. Visible from public road? Yes 11. Endangered? No	
12.	Street address:	205 Ferry 13. Style: vernacular	
14.	Date(s): c. 18	70	
15.	Architect: 16. Builder:		
17.	Original Use: residential 18. Present Use: residential		
19.	Owner's name/address if known:		
20.	No. of stories: 2 & 1 21. Basement? yes 22. Wall construction: frame		
23.	Foundation material: stone 24. Roof type/material: side gable		
25.	No. Bays: Front 3 Side 4 25. Wall treatment: asphalt shingle		
26.	Plan shape: rectangular 27. Changes: Addition? yes Altered? yes		
28.	Exterior condition: fair 29: Open to public? no		
30.	Other Surveys in which included: St. Louis Harbor Historic Properties Reconnaissance, 1987, U.S. Army Corps of Engineers survey (partially incl.		
	ing and brick-lo	tion of important features: This frame house has rolled ok asphalt siding. Wood-framed rectilinear windows are sixis very narrow. One-story concrete block and frame gabled,	

32. History and Significance: Although Ferry at Second is not clearly delineated, it appears that this building and the two that formerly adjoined it to the east are shown on the 1875 Compton & Dry map. The three frame buildings are definitely on the 1883 Hopkins map; only this building remains of the three. No permits could be found for frame buildings for Ferry in this city block; permits in general for the north side of Ferry only go back to c. 1879.

enclosed front porch. One-story frame rear porch. West side entrance appears

to be original.



5LCACUZ-149

1.	No. 160	3. Location of Negatives: Landmarks Association of St. Louis, Inc., 917 Locust, St. Louis, MO 63101	
2.	City/County: City of St. Louis, MO	4. Prepared by: Cynthia Longwisch & Mary M. Stiritz, Landmarks Association of St. Louis, Inc.	
5.	Date: 11/90	6. Sources of information: St. Louis Public Records, City Hall; St. Louis Public Library; MO Historical Soc.	
7.	Building? Yes		
9.	Ownership: Private	8. On National Register or part of estab. district? No 10. Visible from public road? Yes 11. Endangered? No	
12.	Street address:	206 Ferry 13. Style: vernacular	
14.	Date(s): 8/8/1	B76	
15.	Architect:	16. Builder:	
17.	Original Use: residential 18. Present Use: residential		
19.	Owner's name/address if known:		
20.	No. of stories: 2 21. Basement? yes 22. Wall construction: masonr		
23.	Foundation mate	rial: limestone 24. Roof type/material: side gable	
25.	No. Bays: Fron	t 2 Side 3 25. Wall treatment: red brick	
26.	Plan shape: rec	tangular 27. Changes: Addition? Altered?	
28.	Exterior condition: good 29: Open to public? no		
30.	Other Surveys in which included: St. Louis Harbor Historic Properties Reconnaissance, 1987, U.S. Army Corps of Engineers survey (partially incl		
31.	Further descrip	tion of important features: Windows have segmental soldier	

32. History and Significance: George Summer took out the permit to build this residence in 1876 for \$1,800. It has been in residential use since then.

wood cornice was once ornamented with scrolled wood brackets, which are now all gone except for a pair on each side. Single dormer. Two-story wood porch at

arches and stone lugsills; panes are two-over-two. West wall is blind.

rear. Parapeted chimneys in west wall only.



NORTH DROADURY MOUSTRIAL SURVEY II.

206 FERRY
FACING SE

37. LOUIS, MO

1.	No. 159	.		egatives: Landmarks Association of c., 917 Locust, St. Louis, MO 63101	L
2.	City/County: City of St. Louis, MO	:	_	Cynthia Longwisch & Mary M. Stiritz	
5.	Date: 11/90	f		Formation: St. Louis Public Record	
7.	Building? Yes				
9.	Ownership:	8. On Nati	lonal ke	egister or part of estab. district	· NO
	Private	10. Visible	e from p	public road? Yes 11. Endangered	1? No
12.	Street address:	210-12 Ferry	7	13. Style: vernacular	
14.	Date(s): c. 18	80			
15.	. Architect: 16.		. Builder:		
17.	Original Use: residential 18.		18. F	Present Use: residential	
19.	Owner's name/address if known:				
20.	No. of stories: 1 21. Baseme		Basement	t? yes 22. Wall construction: fra	ame
23.	Foundation mate	rial: limesto	one 2	24. Roof type/material: hipped	
25.	No. Bays: Fron	t 4 Side 2	2	25. Wall treatment: asphalt shing	le
26.	Plan shape: rec	tangular	27. Ch	hanges: Addition? yes Altered?	yes
28.	Exterior condit	ion: fair	***************************************	29: Open to public? no	
30.	Other Surveys in which included: St. Louis Harbor Historic Properties Reconnaissance, 1987, U.S. Army Corps of Engineers survey (partially incl.)				

- Further description of important features: This frame house has a hipped roof with asphalt shingles and brick-look asphalt siding. A screened porch extends the width of the front elevation with two entrance doors corresponding to the real entrances. Wide overhanging west eave; east elevation has a normal width eave. Rear frame addition.
- History and Significance: This frame house is clearly shown on the Hopkins map of 1883; it doesn't seem to be on the 1875 Compton & Dry map, although the buildings in the vicinity are rather jumbled together, and the original roof may have been different - possibly end-gabled - before the porch was put on. foundation of the porch is rather rickety and suggests that it is a later addi-This house is something of an anomaly in St. Louis city proper; it is not unlike owner-built housing along both sides of the Mississippi above Alton, Ill.



SLCAS013-15/

1.	No. 089	 Location of Negatives: Landmarks Association of St. Louis, Inc., 917 Locust, St. Louis, MO 63101 		
2.	City/County: City of St. Louis, MO	4. Prepared by: Cynthia Longwisch & Mary M. Stiritz, Landmarks Association of St. Louis, Inc.		
5.	Date: 11/90	6. Sources of information: St. Louis Public Records,		
7.	Building? Yes	City Hall; St. Louis Public Library; MO Historical Soc.		
9.	Ownershin	8. On National Register or part of estab. district? No		
٦.	Ownership: Private	10. Visible from public road? Yes 11. Endangered? No		
12.	Street address:	3130 Hall 13. Style: commercial		
14.	Date(s): 3/19/	1898		
15.	Architect:	16. Builder:		
17.	Original Use: warehouse 18. Present Use: warehouse			
19.	Owner's name/address if known:			
20.	No. of stories: 1 21. Basement? yes 22. Wall construction: masonry			
23.	Foundation material: concrete 24. Roof type/material: flat			
25.	No. Bays: Front 3 Side 17 25. Wall treatment: brick & iron			
26.	Plan shape: rec	tangular 27. Changes: Addition? Altered? yes		
28.	Exterior condit	ion: fair 29: Open to public? no		
30.	Other Surveys in which included: St. Louis Harbor Historic Properties Reconnaissance, 1987, U.S. Army Corps of Engineers survey (partially incl.			
corr	ion extends to t rugated iron and	tion of important features: A three-by-five bay brick he west; a section of 12 loading dock bays is covered with extends to the east. Windows have been infilled; they have l parapet rises at the east and west ends of the brick sec-		

^{32.} History and Significance: The Mississippi Valley Storage Co. took out the permit for this warehouse/storage building for \$10,000 in 1898. The building took advantage of its location in the midst of railroad sidings.

tion.



1.	No. 115	3. Location of Negatives: Landmarks Association of St. Louis, Inc., 917 Locust, St. Louis, MO 63101
2.	City/County: City of St. Louis, MO	4. Prepared by: Cynthia Longwisch & Mary M. Stiritz, Landmarks Association of St. Louis, Inc.
5.	Date: 11/90	6. Sources of information: St. Louis Public Records,
7.	Building? Yes	City Hall; St. Louis Public Library; MO Historical Soc.
9.	Ownership:	8. On National Register or part of estab. district? No
	Private	10. Visible from public road? Yes 11. Endangered? No
12.	Street address:	201-07 Mallinckrodt 13. Style: industrial/Romanesque
14.	Date(s): 6/22/	1908
15.	Architect: Isa	ac Taylor 16. Builder:
17.	. Original Use: warehouse 18. Present Use: industrial	
19.	. Owner's name/address if known: Mallinckrodt Chemical Works, Inc.	
20.	No. of stories:	n/a 21. Basement? yes 22. Wall construction: masonry
23.	Foundation mate	rial: limestone 24. Roof type/material: end gable
25.	No. Bays: Fron	t 6 Side 17 25. Wall treatment: red brick
26.	Plan shape: rec	tangular 27. Changes: Addition? Altered? yes
28.	Exterior condit	ion: good 29: Open to public? no
30.	Other Surveys in which included: St. Louis Harbor Historic Properties Reconnaissance, 1987, U.S. Army Corps of Engineers survey (partially incl	
31	Further description of important features. The twin gables of this build-	

- 31. Further description of important features: The twin gables of this building have small monitor roofs. Enormous round-arched bays corresponding to about three stories in height are separated by banded piers down the length of the west side; these have all been infilled. Pressed brick and corbelling ornament the cornice. Stone keys in the round arched bays across (cont'd. below)
- 32. History and Significance: the south end. Bull's-eye windows in the gable ends are of pressed brick, as are the round arches of smaller windows running across either gable. Brick quoining on south elevation. See attached about Mallinckrodt and architect Isaac Taylor.



When BROWNING INDUSTRUM SURVEY II
SOLOT MALINGERODT
FACING NE

St. Lower, MO

1/90


MISSOURI OFFICE OF HISTORIC PRESERVATION SECASO13-153

1.	No. 015	3. Location of Negatives: Landmarks Association of St. Louis, Inc., 917 Locust, St. Louis, MO 63101	
2.	City/County: City of St. Louis, MO	4. Prepared by: Cynthia Longwisch & Mary M. Stiritz, Landmarks Association of St. Louis, Inc.	
5.	Date: 11/90	6. Sources of information: St. Louis Public Records, City Hall; St. Louis Public Library; MO Historical Soc.	
7.	Building? Yes		
9.	Ownership:	8. On National Register or part of estab. district? No	
٠.	Ownership: Private	10. Visible from public road? Yes 11. Endangered? No	
12.	Street address:	215-19 N. Market 13. Style: industrial	
14.	Date(s): 5/25/	1918; 4/1/1924	
15.	Architect: Gus	tav P. Wuest 16. Builder: Nic Schwegler	
17.	Original Use: factory 18. Present Use: commercial		
19.	Owner's name/address if known: Louis Maull Co.		
20.	No. of stories: 3 21. Basement? unk. 22. Wall construction: masonry		
23.	Foundation mate	rial: stone 24. Roof type/material: flat	
25.	No. Bays: Fron	t 4 Side 25. Wall treatment: red brick	
26.	. Plan shape: rectangular 27. Changes: Addition? yes Altered? ye		
28.	Exterior condit	ion: good 29: Open to public? no	
30.	Other Surveys in which included: St. Louis Harbor Historic Properties Reconnaissance, 1987, U.S. Army Corps of Engineers survey (partially incl.		
31	Further description of important features: 1st & 2nd story triple rowlock		

- 31. Further description of important features: 1st & 2nd story triple rowlock elliptically-arched windows have stone sills and are infilled. Remaining non-filled windows have divided transoms and 2-over-2 panes. A concrete loading dock extends the length of the front. Terra cotta cornice. Building is flanked by new additions on its east and west elevations.
- 32. History and Significance: L. Maull took out a permit to build a two-story factory for \$31,000 in 1918. The loading platform was built in 1923 for \$2,000. In 1924, Maull got a permit to built a \$6,000 addition to the factory; since no building height is listed as is customary, it is probable that this permit was for the third story. The interior of the building was damaged by fire in 1959 and 1974, causing extensive repairs to be made. The Maull Company, makers of barbecue sauce and other products, is nationally-known.



N. MARKET FACILIS



1.	No. 012	3. Location of Negatives: Landmarks Association of		
2.	City/County: City of St. Louis, MO	St. Louis, Inc., 917 Locust, St. Louis, MO 63101 4. Prepared by: Cynthia Longwisch & Mary M. Stiritz, Landmarks Association of St. Louis, Inc.		
5.	Date: 11/90	6. Sources of information: St. Louis Public Records,		
7.	Building? Yes	City Hall; St. Louis Public Library; MO Historical Soc.		
	A	8. On National Register or part of estab. district? No		
9.	Ownership: Private	10. Visible from public road? Yes 11. Endangered? No		
12.	Street address:	111-19 Monroe 13. Style: commercial		
14.	Date(s): 11/26	/1910; alterations 1918, 1920, 1948		
15.	Architect: Edward F. Nolte 16. Builder: J. Charles Mueller			
17.	Original Use: warehouse 18. Present Use: warehouse/office			
19.	Owner's name/address if known: Manitoba Corp./Grocer's Terminal Warehouse			
20.	No. of stories: 1 21. Basement? yes 22. Wall construction: masonry			
23.	Foundation material: limestone 24. Roof type/material: flat			
25.	No. Bays: Fron	t 6 Side 12 25. Wall treatment: red brick		
26.	Plan shape: rectangular 27. Changes: Addition? Altered? yes			
28.	Exterior condition: fair 29: Open to public? limited			
30.	Other Surveys in which included: St. Louis Harbor Historic Properties Reconnaissance, 1987, U.S. Army Corps of Engineers survey (partially incl.			

32. History and Significance: A.F.W. Luehrmann built this warehouse in 1910 for \$8,000. He took out permits for very minor alterations to it in 1918 and 1920. It seems likely that the building suffered damage along the roofline at some point, because Mary H. Luehrmann took out a \$3,000 permit to repair the warehouse in 1948 and newer brick can be seen along the cornice line. August F.W. Luehrmann was the president of the Luehrmann Hay and Grain Company, which

31. Further description of important features: Double-rowlock segmentally arched windows are infilled with brick and concrete block. A concrete loading

dock with a frame and iron roof is located along the east elevation.

he located in this building through at least c. 1950.



54CA3013-155

1.	No. 001	3. Location of Negatives: Landmarks Association of St. Louis, Inc., 917 Locust, St. Louis, MO 63101		
2.	City/County: City of St. Louis, MO	4. Prepared by: Cynthia Longwisch & Mary M. Stiritz, Landmarks Association of St. Louis, Inc.		
5.	Date: 11/90			
7.	Building? Yes	City Hall; St. Louis Public Library; MO Historical Soc.		
9.	Ownership:	8. On National Register or part of estab. district? No		
	Private	10. Visible from public road? Yes 11. Endangered? No		
12.	Street address:	908-12 Monroe 13. Style/Design: industrial		
14.	Date(s): 3/20/	1893; 1938, 1962, 1967		
15.	Architect:	16. Builder: B. Storck		
17.	Original Use: stable 18. Present Use: tool & machine shop			
19.	Owner's name/address if known: Ehrhardt Tool & Machine Co.			
20.	No. of stories: 1 & 2 21. Basement? Yes 22. Wall construction: masonry			
23.	Foundation material: stone/conc. 24. Roof type/material: flat			
25.	No. Bays: Fron	t 12 Side 25. Wall treatment: painted brick		
26.	Plan shape: tra	pezoid 27. Changes: Addition? Yes Altered? Yes		
28.	Exterior condition: good 29: Open to public? limited			
30.	Other Surveys in which included: St. Louis Harbor Historic Properties Reconnaissance, 1987, U.S. Army Corps of Engineers survey (partially incl.			
arch Terr	es, brick sills a-cotta coping.	tion of important features: First-story windows have flat and are infilled. Second-story windows are top-hinged. Second-story side windows are segmentally arched. Garage tion. 1962 and 1967 additions to the west and south are of		

^{32.} History and Significance: The original building permit was taken out by Hannibal Brothers in 1893 for \$3,000. Herman and Louis Hannibal operated an ice company next door at 914 Monroe through the mid-1920s, using this building to stable their horses.

concrete block.



908-12 MONROE FACING SW

.....

MISSOURI OFFICE OF HISTORIC PRESERVATION SLCA5013 456

1.	No. 044	3. Location of Negatives: Landmarks Association of St. Louis, Inc., 917 Locust, St. Louis, MO 63101	
2.	City/County: City of St. Louis, MO	4. Prepared by: Cynthia Longwisch & Mary M. Stiritz, Landmarks Association of St. Louis, Inc.	
5.	Date: 11/90	6. Sources of information: St. Louis Public Records, City Hall; St. Louis Public Library; MO Historical Soc.	
7.	Building? Yes	8. On National Register or part of estab. district? No	
9.	Ownership: Private	10. Visible from public road? Yes 11. Endangered? No	
12.	Street address:	817-19 Montgomery 13. Style: commercial	
14.	Date(s): 12/29	/1908	
15.	Architect: owner 16. Builder: owner		
17.	Original Use: warehouse 18. Present Use: warehouse		
19.	Owner's name/address if known: Williams Patent Crusher & Pulverizer Co.		
20.	No. of stories: 3 21. Basement? unk. 22. Wall construction: masonry		
23.	Foundation mate	rial: stone 24. Roof type/material: flat	
25.	No. Bays: Front 10 Side 8 25. Wall treatment: red brick		
26.	Plan shape: rectangular 27. Changes: Addition? yes Altered? yes		
28.	Exterior condition: good 29: Open to public? no		
30.	-	n which included: St. Louis Harbor Historic Properties 1987, U.S. Army Corps of Engineers survey (partially incl.	
	lintels, brick	tion of important features: South elevation features cast- sills, and a corbelled brick cornice. Second-story and evation windows appear to have replacement sash; remaining	

32. History and Significance: arches. Simple cast-iron framing by Christopher & Simpson iron works. Terra cotta coping. A one-story ell of more recent vintage extends from the northwest corner. The Williams Patent Crusher & Pulverizer Co. took out a building permit for the warehouse in 1908. M. F. Williams operated his business in this city block at least as early as 1898, and probably before. The company has expanded to include the bulk of the block.

side windows are infilled with masonry or wood. First-story windows are multi-

(cont'd. below)

pane metal sash. Side windows have triple-rowlock segmental



54CASQ3-157

		· · · · · · · · · · · · · · · · · · ·	
1.	No. 038	3. Location of Negatives: Landmarks Association of St. Louis, Inc., 917 Locust, St. Louis, MO 63101	
2.	City/County: City of St. Louis, MO	4. Prepared by: Cynthia Longwisch & Mary M. Stiritz, Landmarks Association of St. Louis, Inc.	
5.	Date: 11/90	6. Sources of information: St. Louis Public Records,	
7.	Building? Yes	City Hall; St. Louis Public Library; MO Historical Soc.	
9.	Ownership:	8. On National Register or part of estab. district? No	
٠.	Private	10. Visible from public road? Yes 11. Endangered? No	
12.	Street address:	911 Montgomery 13. Style: Craftsman	
14.	Date(s): 8/31/	1910	
15.	Architect: A. Wedemeyer 16. Builder: Peter Schneider & Son		
17.	Original Use: residential 18. Present Use: residential		
19.	Owner's name/address if known:		
20.	No. of stories: 2 21. Basement? yes 22. Wall construction: masonr		
23.	Foundation material: limestone 24. Roof type/material: flat		
25.	No. Bays: Fron	t 2 Side 1/4 25. Wall treatment: red brick	
26.	Plan shape: rec	tangular 27. Changes: Addition? Altered?	
28.	Exterior condition: good 29: Open to public? no		
30.	Other Surveys in which included: St. Louis Harbor Historic Properties Reconnaissance, 1987, U.S. Army Corps of Engineers survey (partially incl.		
 २ 1		tion of important features. Openings have soldier arches	

31. Further description of important features: Openings have soldier arches and stone sills. Entrance is angled. Stone water table above contrasting brick below first-story window. Shaped parapet has green vitreous brick diamond-shaped inset. Simple cornice above dentilled band of ornamental pressed brick. Outstanding short wrought-iron fence.

^{32.} History and Significance: Louis Zwick took out the permit for this residence in 1910 for \$4,000. Zwick was a St. Louis City Inspector working out of City Hall; his place of residence was on the other side of the city. His position may have led to his filling out the building permit form for a friend; it is also possible that he built the house on speculation.



54CAS013-154

1.	No. 037	 Location of Negatives: Landmarks Association of St. Louis, Inc., 917 Locust, St. Louis, MO 63101 	
2.	City/County: City of St. Louis, MO	4. Prepared by: Cynthia Longwisch & Mary M. Stiritz, Landmarks Association of St. Louis, Inc.	
5.	Date: 11/90	6. Sources of information: St. Louis Public Records, City Hall; St. Louis Public Library; MO Historical Soc.	
7.	Building? Yes		
9.	Ownership: Private	8. On National Register or part of estab. district? No 10. Visible from public road? Yes 11. Endangered? No	
12.	Street address:	913 Montgomery 13. Style: vernacular	
14.	Date(s): c. 18	70	
15.	Architect:	rchitect: 16. Builder:	
17.	Original Use: residential 18. Present Use: residential		
19.	Owner's name/address if known:		
20.	No. of stories: 2-1/2 21. Basement? yes 22. Wall construction: masonr		
23.	Foundation material: limestone 24. Roof type/material: side gable		
25.	No. Bays: Front 3 Side 3 25. Wall treatment: red brick		
26.	Plan shape: rectangular 27. Changes: Addition? Altered? yes		
28.	Exterior condition: fair 29: Open to public? no		
30.	Other Surveys in which included: St. Louis Harbor Historic Properties Reconnaissance, 1987, U.S. Army Corps of Engineers survey (partially incl.		
31. stor		tion of important features: Segmentally arched windows have r-two double-hung sash are probably not original. Doorway	

is segmentally arched, slightly recessed. Single dormer. East wall has parapeted chimneys. Rear ell has a relatively new wooden two-story deck/porch. House fronts directly on sidewalk and shares a common wall with 915 Montgomery.

^{32.} History and Significance: This building predates recorded building permits for this city block. It appears on Plate 50 of the 1875 Compton & Dry publication; it has been in continuous residential use.



NORTH SECADULAY INDUSTRIEL SERRY IN 913 MONTBONERY RENT PACING NW

51, 10015, MO

1/90

SLCA5013-15,9

1.	No. 036	 Location of Negatives: Landmarks Association of St. Louis, Inc., 917 Locust, St. Louis, MO 63101
2.	City/County: City of St. Louis, MO	4. Prepared by: Cynthia Longwisch & Mary M. Stiritz, Landmarks Association of St. Louis, Inc.
5.	Date: 11/90	6. Sources of information: St. Louis Public Records, City Hall; St. Louis Public Library; MO Historical Soc.
7.	Building? Yes	
ο	Ormanahin	8. On National Register or part of estab. district? No
9.	Ownership: Private	10. Visible from public road? Yes 11. Endangered? No
12.	Street address:	915 Montgomery 13. Style: vernacular
14.	Date(s): c. 18	70
15.	Architect:	16. Builder:
17.	Original Use:	residential 18. Present Use: residential
19.	Owner's name/address if known:	
20.	No. of stories:	2 21. Basement? yes 22. Wall construction: masonry
23.	Foundation mate	rial: limestone 24. Roof type/material: side gable
25.	No. Bays: Fron	t 2 Side 1 25. Wall treatment: red brick
26.	Plan shape: rec	tangular 27. Changes: Addition? Altered? yes
28.	Exterior condit	ion: fair 29: Open to public? no
30.	-	which included: St. Louis Harbor Historic Properties 1987, U.S. Army Corps of Engineers survey (partially incl.)

It has been in residential use since built.

31. Further description of important features: Openings have flat stone lintels; windows have stone sills. Upper windows partially boarded; doorway has been partially infilled with wood. West wall is parapeted with chimneys. Stone water table. Building fronts directly on sidewalk. It shares a common

wall with 913 Montgomery.

32. History and Significance: This building predates the building permit record for this city block. It appears on Plate 50 of the 1875 Compton & Dry book.



1.	No. 035	 Location of Negatives: Landmarks Association of St. Louis, Inc., 917 Locust, St. Louis, MO 63101 	
2.	City/County: City of St. Louis, MO	4. Prepared by: Cynthia Longwisch & Mary M. Stiritz, Landmarks Association of St. Louis, Inc.	
5.	Date: 11/90	6. Sources of information: St. Louis Public Records,	
7.	Building? Yes	City Hall; St. Louis Public Library; MO Historical Soc.	
9.	Ownership:	8. On National Register or part of estab. district? No	
	Private	10. Visible from public road? Yes 11. Endangered? No	
12.	Street address:	917-19 Montgomery 13. Style: vernacular	
14.	Date(s): c. 1870		
15.	Architect: 16. Builder:		
17.	Original Use: residential 18. Present Use: residential		
19.	Owner's name/address if known:		
20.	No. of stories: 1-1/2 21. Basement? yes 22. Wall construction: masonry		
23.	Foundation material: limestone 24. Roof type/material: side gable		
25.	No. Bays: Front 7 Side 2 25. Wall treatment: red brick		
26.	Plan shape: rec	tangular 27. Changes: Addition? Altered? yes	
28.	Exterior condition: good 29: Open to public? no		
30.	Other Surveys in which included: St. Louis Harbor Historic Properties Reconnaissance, 1987, U.S. Army Corps of Engineers survey (partially incl.		

- Further description of important features: This house is really two buildings together. All but one of the primary elevation's openings have flat stone lintels; the remaining one has a shaped stone lintel. Side windows are segmentally arched. All windows have stone sills. Stone water table. Single dormer in west section. Dentilled cornice. East section has parapeted chimneys.
- History and Significance: These adjoining houses predate the requirement of building permits; however, they clearly appear on Plate 50 of Compton & Dry (1875). They have been in continuous residential use ever since.



NORTH BECADURY INDUSTRIAL SURVEY IN 917-19 MONTGOMERY FACING NE ST. LOUIS, MO

1/20

1.	No. 051	3. Location of Negatives: Landmarks Association of St. Louis, Inc., 917 Locust, St. Louis, MO 63101	
2.	City/County: City of St. Louis, MO	4. Prepared by: Cynthia Longwisch & Mary M. Stiritz, Landmarks Association of St. Louis, Inc.	
5.	Date: 11/90	6. Sources of information: St. Louis Public Records,	
7.	Building? Yes	City Hall; St. Louis Public Library; MO Historical Soc.	
9.	Ownership: Private	8. On National Register or part of estab. district? No 10. Visible from public road? Yes 11. Endangered? No	
12.	Street address:	916-30 Palm 13. Style: industrial	
14.	Date(s): 7/29/	1910	
15.	Architect: G. Becker 16. Builder: Althaus Construction Co.		
17.	Original Use: factory 18. Present Use: factory		
19.	Owner's name/address if known: American Foundry & Mfg. Co.		
20.	No. of stories:	3 21. Basement? yes 22. Wall construction: masonry	
23.	Foundation mate	rial: limestone 24. Roof type/material: flat	
25.	No. Bays: Fron	14 Side 14 25. Wall treatment: red brick	
26.	Plan shape: irr	egular 27. Changes: Addition? yes Altered? yes	
28.	Exterior condit	ion: good 29: Open to public? limited	
30.		which included: St. Louis Harbor Historic Properties 1987, U.S. Army Corps of Engineers survey (partially incl.)	
31	Further degarin	tion of important features. Note: this site has 2 photos	

- 31. Further description of important features: Note: this site has 2 photos. This factory building has a corbelled cornice. Windows in the western section (photo #51a) have double rowlock segmental arches; some have been infilled with wood or corrugated fiberglas. This portion is set at an angle to the eastern segment (photo #51b); a rock-faced covered entrance is located (cont'd. below)
- 32. History and Significance: in the odd angle formed by the unusual orientation of the two parts of the factory to each other. The cornice on this part matches that of the western part, but the windows have flat arches. A small, one-story addition is attached to the east part of this building. The factory was built in 1910 for \$10,742 by F. W. Hanpeter of the Hanpeter Furniture company. Only one permit exists, and it is not known why the two segments were built at such odd angles. American Foundry moved into the building after 1940.





SLC45013-162

1.	No. 153		of Negatives: Landmarks Association of s, Inc., 917 Locust, St. Louis, MO 63101
2.	City/County: City of St. Louis, MO	4. Prepared	by: Cynthia Longwisch & Mary M. Stiritz, as Association of St. Louis, Inc.
5.	Date: 11/90		of information: St. Louis Public Records, St. Louis Public Library; MO Historical Soc.
7.	Building? Yes		onal Register or part of estab. district? No
9.	Ownership: Private		from public road? Yes 11. Endangered? No
12.	Street address:	42 Penrose	13. Style: industrial
14.	Date(s): 5/29/	1919	
15.	Architect:		16. Builder: Fruin Colnon Co.
17.	Original Use:	Eactory 1	18. Present Use: vacant?
19.	Owner's name/address if known:		
20.	No. of stories:	1 21. Bas	asement? yes 22. Wall construction: masonry
23.	Foundation mate	rial: concrete	24. Roof type/material: flat
25.	No. Bays: Front unk. Side 31 25. Wall treatment: brown brick		25. Wall treatment: brown brick
26.	Plan shape: L 27. Changes: Addition? Altered? ye		27. Changes: Addition? Altered? yes
28.	Exterior condit	ion: fair	29: Open to public? no
30.			ed: St. Louis Harbor Historic Properties my Corps of Engineers survey (partially incl.)

31. Further description of important features: The photo shows the west and south elevations of the western portion of this factory; the remainder is inaccessible. The entire factory is one story with terra cotta coping. Windows have brick soldier arches and brick sills and originally had multipane industrial metal sash. CMU or wood has been used to infill many (cont'd. below)

32. History and Significance: of the openings.

The St. Louis Basket & Box Company took out a permit in 1919 for two, one-story factories to be built for \$1,000 (apparently apiece). This section of the complex is one of those specified. St. Louis Basket & Box operated in this location until the 1930s. The building appears to be vacant; because Penrose is privately cordoned off, this cannot be confirmed and the north elevation could not be photographed.



MISSOURI OFFICE OF HISTORIC PRESERVATION ARCHITECTURAL/HISTORIC INVENTORY SURVEY FORM SUCASSISTED
3. Location of Negatives: Landmarks Association of

1.	No. 163	3. Location of Negatives: Landmarks Association of St. Louis, Inc., 917 Locust, St. Louis, MO 63101
2.	City/County: City of St. Louis, MO	4. Prepared by: Cynthia Longwisch & Mary M. Stiritz, Landmarks Association of St. Louis, Inc.
5.	Date: 11/90	6. Sources of information: St. Louis Public Records, City Hall; St. Louis Public Library; MO Historical Soc.
7.	Building? Yes	city hair, St. Louis Fubite Library, Mo historical Soc.
9.	Ownership:	8. On National Register or part of estab. district? No
	Private	10. Visible from public road? Yes 11. Endangered? No
12.	Street address:	131 Penrose 13. Style: commercial/Art Deco
14.	Date(s): 12/4/	1931
15.	Architect:	16. Builder:
17.	Original Use: office 18. Present Use: office	
19.	Owner's name/address if known: Don V. Davis Co.	
20.	No. of stories: 1 21. Basement? yes 22. Wall construction: masonry	
23.	Foundation material: concrete 24. Roof type/material: flat	
25.	No. Bays: Front 7 Side 7 25. Wall treatment: buff & red brick	
26.	Plan shape: T 27. Changes: Addition? yes Altered?	
28.	Exterior condition: good 29: Open to public? limited	
30.	Other Surveys in which included: St. Louis Harbor Historic Properties Reconnaissance, 1987, U.S. Army Corps of Engineers survey (partially incl.	
31.	Further description of important features: The entrance pavilion to this	

- 31. Further description of important features: The entrance pavilion to this building projects slightly and features a Deco stepped parapet highlighted with highly glazed dark terra cotta coping. Soldier courses of red brick provide visual interest above the entrance and in banding around the building. The southwest corner of the building is curved and has a glass (cont'd. below)
- 32. History and Significance: brick window. Other windows are double-hung wood sash (south end) and multipane metal sash (north of entrance). Attached to the north is a 1944 factory building done in the same colors of brick but of strictly functional rectilinear design. The permit was issued to the Grasselli Chemical Co. in 1931 for a \$3,000 office. The attached factory was built by present owner Don V. Davis & Co.



163 NORTH GROADWAY INDUSTRIAL SURVEY IT
181 PENROSE
PACING NE

#7. LOWIS, MO

SLC AS013-164

1.	No. 027	3. Location of Negatives: Landmarks Association of St. Louis, Inc., 917 Locust, St. Louis, MO 63101
2.	City/County: City of St. Louis, MO	4. Prepared by: Cynthia Longwisch & Mary M. Stiritz, Landmarks Association of St. Louis, Inc.
5.	Date: 11/90	6. Sources of information: St. Louis Public Records,
7.	Building? Yes	City Hall; St. Louis Public Library; MO Historical Soc. 8. On National Register or part of estab. district? No
9.	Ownership: Private	10. Visible from public road? Yes 11. Endangered? No
12.	Street address:	911-13 Warren 13. Style: Italianate
14.	Date(s): C. 1885	
15.	Architect:	16. Builder:
17.	Original Use:	residential 18. Present Use: residential
19.	Owner's name/address if known: P. Jeffries & A. Bennett	
20.	No. of stories:	2 21. Basement? yes 22. Wall construction: masonry
23.	Foundation mate	rial: stone 24. Roof type/material: side gabled
25.	No. Bays: Fron	t 6 Side 1 25. Wall treatment: red brick
26.	Plan shape: mod	if. rectang. 27. Changes: Addition? Altered?
28.	Exterior condit	ion: good 29: Open to public? no
30.	-	n which included: St. Louis Harbor Historic Properties 1987, U.S. Army Corps of Engineers survey (partially incl.

- 31. Further description of important features: Returning at the corners, a wood cornice is supported by paired, scrolled brackets separated by wood dentilling. Upper windows feature flalt stone lintels; lowers have shaped stone lintels; all have stone sills. A double recessed entrance features wood pilasters supporting a bracketed wood cornice. Entrances have (cont'd. below)
- 32. History and Significance: 6-paneled walls and ceiling. Paired parapeted chimnies intact on the south elevation. Stone water table. Side windows are segmentally arched with original 6-over-6 double-hung wood sash. No building permit was filed for this duplex.



SLC ASO13-165

1.	No. 026	3. Location of Negatives: Landmarks Association of St. Louis, Inc., 917 Locust, St. Louis, MO 63101
2.	City/County: City of St. Louis, MO	4. Prepared by: Cynthia Longwisch & Mary M. Stiritz, Landmarks Association of St. Louis, Inc.
5.	Date: 11/90	6. Sources of information: St. Louis Public Records,
7.	Building? Yes	City Hall; St. Louis Public Library; MO Historical Soc.
9.	Ownership: Private	8. On National Register or part of estab. district? No 10. Visible from public road? Yes 11. Endangered? No
12.	Street address:	917-23 Warren 13. Style: Italianate
14.	Date(s): c. 19	01
15.	Architect:	16. Builder:
17.	Original Use: flats 18. Present Use: vacant	
19.	Owner's name/address if known:	
20.	No. of stories: 2 21. Basement? yes 22. Wall construction: masor	
23.	. Foundation material: stone 24. Roof type/material: flat	
25.	No. Bays: Front 12 Side 3 25. Wall treatment: red brick	
26.	Plan shape: U	27. Changes: Addition? Altered? yes
28.	Exterior condit	ion: poor 29: Open to public? no
30.	Other Surveys in which included: St. Louis Harbor Historic Properties Reconnaissance, 1987, U.S. Army Corps of Engineers survey (partially incl	

- 31. Further description of important features: This building features the same egg & dart and dentilled cornice as 2600 N. Tenth (#25); the wood supports for the (metal?) profiled cornice now missing are stilll in place, however. Openings have no arches. Stone sills. Most windows have been boarded. Two pairs of recessed doorways provide access to the four-family building.
- 32. History and Significance: No building permit was found for this building; however, next to it (#25) is a building of very similar cornice and opening design, material use and general appearance. It is probable that this building was included in the 1901 permit H. Clark took out for \$7,000 flats built by Christopher Frieling.



NORTH BROWNING INDUSTRIAL SURVEY II. 917-23 WARDED! FACING HE

75,20415, MO

790

ARCHITECTURAL/HISTORIC INVENTORY SURVEY FORM 54-166 MISSOURI OFFICE OF HISTORIC PRESERVATION



1.	No. 050	3. Location of Negatives: Landmarks Association of St. Louis, Inc., 917 Locust, St. Louis, MO 63101
2.	City/County: City of St. Louis, MO	4. Prepared by: Cynthia Longwisch & Mary M. Stiritz, Landmarks Association of St. Louis, Inc.
5.	Date: 11/90	6. Sources of information: St. Louis Public Records,
7.	Building? Yes	City Hall; St. Louis Public Library; MO Historical Soc.
9.	Ownership:	8. On National Register or part of estab. district? No
, ·	Private	10. Visible from public road? Yes 11. Endangered? No
12.	Street address:	812-14 Wright 13. Style: vernacular
l 4 .	Date(s): 4/18/	1882
15.	Architect: 16. Builder:	
17.	Original Use: residential 18. Present Use: residential	
19.	Owner's name/address if known:	
20.	No. of stories: 2-1/2 21. Basement? yes 22. Wall construction: masonr	
23.	Foundation mate	rial: limestone 24. Roof type/material: side gable
25.	No. Bays: Front 6 Side 2 25. Wall treatment: painted brick	
26.	Plan shape: rec	tangular 27. Changes: Addition? Altered? yes
28.	Exterior condition: fair 29: Open to public? no	
30.	Other Surveys in which included: St. Louis Harbor Historic Properties Reconnaissance, 1987, U.S. Army Corps of Engineers survey (partially incl	
31.	Further degarin	tion of important features: Windows have segmental soldier

31. Further description of important features: Windows have segmental soldier arches and stone sills; most have two-over-two double-hung wood sash. An elaborately corbelled brick cornice highlights the roofline. Two dormers. Side walls have parapeted chimneys; west side chimneys have been removed. transomed entrances. Stone water table. Building is really (cont'd. below)

History and Significance: two mirror-image residences with a common wall. They were together on the same building permit taken out by A. Manewal in 1882 for \$4,600 for the pair. The building has been used as a duplex throughout its history.



50

HORSE EXCHOLOGY INDUSTRIAL SURVEYS



