# E FILE C

Form 10-300 (July 1969)

NATIONAL PARK SERVICE

COUNTY

cn	corred o	n NRHP	:	-
	STATE:	_	-	

Missouri

NATIONAL	REGIS"	TER OF	HISTOR	C PLACES
INVEN	TORY	- NOMI	NOITAN	FORM

<u>Lincoln</u> FOR NPS USE ONLY Approved by Advisory Council June 10, 1972 ENTRY NUMBER DATE (Type all entries - complete annlicable sections) 1801172 To J. C. 15 Aug 1972 1. NAME COMMON: "Old Rock House" AND/OR HISTORIC: Ross, Shapley, House 2. LOCATION STREET AND NUMBER: Second and Mill streets CITY OR TOWN: Moscow Mills STATE COUNTY: CODE CODE Missouri 63362 29 <u>Lincoln</u> 113 3. CLASSIFICATION CATEGORY ACCESSIBLE STATUS OWNERSHIP (Check One) TO THE PUBLIC Z. Public Yes: **₩** Bullding Public Acquisition: District Occupied O Restricted X Private ☐ In Process ☐ Site ☐ Structure Dnoccupied ☐ Unrestricted ☐ Both Being Considered Object Preservation work X No in progress PRESENT USE (Check One or More as Appropriate) Agricultural ☐ Government ☐ Park Transportation future □ Commercial Industrial 2 Private Residence (Specify) Military house Educational Religious Museum museum Entertainment OWNER OF PROPERTY Z OWNER'S NAME: Miss Mildred Depping ш STREET AND NUMBER 6930 Jamieson Avenue ш CITY OR TOWN: STATE: CODE St. Louis Missouri 63109 5. LOCATION OF LEGAL DESCRIPTION COURTHOUSE, REGISTRY OF DEEDS. ETC: Office of Recorder of Deeds Lincoln County Courthouse CITY OR TOWN: STATE CODE Troy Missouri 63379 29 6. REPRESENTATION IN EXISTING SURVEYS TITLE OF SURVEY: ENTRY NUMBER Missouri Historic Sites Catalogue FOR NPS USE DATE OF SURVEY: 1963 County DEPOSITORY FOR SURVEY RECORDS State Historical Society of Missouri ONLY Corner, Hitt and Lowry streets CITY OR TOWN: STATE: CODE DATE Columbia\_ Missouri 6520] The Hon. William L. Hungate House of Representatives Congressional District #9:

## UNITED STATES DEPARTMENT OF THE INTERIOR NATIONAL PARK SERVICE

# NATIONAL REGISTER OF HISTORIC PLACES INVENTORY - NOMINATION FORM

TATE	
Missouri	
OUNTY	
Lincoln	
FOR NPS USE ONLY	
ENTRY NUMBER DAT	E

(Continuation Sheet)

(Number all entries)

6. #1

ROSS, SHAPLEY, HOUSE

2. Missouri State Historical Survey

(state)

1972

Missouri State Park Board

P.O. Box 176

1204 Jefferson Building

Jefferson City, Missouri 65101

Code: 29

3. Historic American Buildings Survey

(federal)

1972

(Drawings to be submitted to the Historic American Buildings Survey, 801 19th Street, N. W., Washington, D. C. upon completion of the restoration project in progress) Code: 08

,	DESCRIPTION	5.00						
					(Check One)			
	CONDITION	☐ Excellent	⟨X Goød	☐ Fair	Deteriorated	Ruins	Unexposed	
	CONDITION		(Check O	ne)		(Ch	eck One)	
		X Alte	red .	☐ Unaltered		Moved	Original Site	
	OFSCRIBE THE OF	ESENT AND OR	CINAL CICE	and) Duvele	- ADDEADANCE			

#### ARCHITECTURAL CHARACTER

The "Old Stone House," or Shapley Ross House in Moscow Mills, Lincoln County, Missouri is an early local example of the classic revival style in residential architecture, constructed in stone. The house was built ca. 1818-1821 and has third-quarter nineteenth century remodeling features.

#### EXTERIOR

#### Over-all dimensions

The House is 56'6" (five bays) wide and 46'3 1/2" deep. It faces south-southwest onto Second Street at the north corner of the intersection of Second and Mill streets. The house and its remaining appurtenant structures occupy lots 5, 6, 7, and 8, or the entire south half of Block 6.

It has a rectangular plan, original, front block adjoined by a rectangular-plan rear ell, added ca. 1870 and incorporating the original, free-standing stone kitchen. The ell extends northeastward from the eastern half of the front block's northeast wall. The house is 36 feet high from grade line to chimney top. It has two full stories, a loft over the two primary sections, and a finished basement under the front block only.

#### Foundations

The foundations are made of coursed, squared, rubble limestone masonry. There is no distinctive division line between the foundations and the upper walls.

#### Wall Construction, Finish and Color

The exterior walls are also constructed of cream-colored, coursed, squared, rubble limestone, 1'10 1/2" thick on the main block, and 1'6" thick on the rear ell first story. The second story of the rear ell îs constructed of red brick in less thick, running bond. Stonework at the corners, in the jack arches and chimneys is carefully executed, displaying stones larger than those used elsewhere in the walls. The southeast, first floor, polygonal, bay window is a woodframe addition to the original structure. It is sheathed in stamped, sheet metal simulating stonework.

## UNITED STATES DEPARTMENT OF THE INTERIOR NATIONAL PARK SERVICE

## NATIONAL REGISTER OF HISTORIC PLACES INVENTORY - NOMINATION FORM

Missouri	
COUNTY	
Lincoln	
FOR NPS USE OF	YLY
ENTRY NUMBER	PATE

STATE

(Continuation Sheet)

(Number all entries)

7. #1

ROSS, SHAPLEY, HOUSE

#### Structural System, Framing

Exterior walls and interior partition walls support the wood-frame structural system which, in turn, supports the floors and roof. The northwest, interior, partition wall in the front block is constructed of stone masonry from the foundation level through the first story. At the second story level this wall is frame construction. The southeast interior partition wall in the front block is carried on a support post in the basement, and is wood-frame construction through the two stories above.

#### Porches Porches

The only porch presently extant on the house is a second floor balcony at the south end of the rear ell's southeast wall. A set of straight-run concrete steps leads to a stoop at the southeast side of the house. One steps onto a stone threshold to enter the southwest (front) or northeast (rear) doorways.

#### Chimneys

There are three chimneys. The two, primary, twin chimneys on the front block, are centered on the vertical midline of the northwest and southeast gable ends. These chimneys, constructed of stone, are incorporated into the walls, giving flush masonry end walls. Both chimneys are topped with a simple, stone molding. The third chimney is constructed of brick. It is centered on the vertical midline of the northeast (rear) gable end of the rear wing, also giving a flush masonry surface. An ornamental brick molding on this chimney has been removed.

#### Openings

Doorways and doors. The front door occupies the third, or central bay of the five-bay, southwest facade. A rear (northeast) door is similarly centered on the rear facade of the front block.

A second floor doorway occurs directly above the first floor front door.

The rear ell has three doorways--two on the southeast wall--one on the first floor, and one on the second--and another on the northwest wall, first floor.

Doorways on the southwest facade have stone, jack arch lintels; those on the northeast and northwest facade have monolithic stone

## UNITED STATES DEPARTMENT OF THE INTERIOR NATIONAL PARK SERVICE

# NATIONAL REGISTER OF HISTORIC PLACES INVENTORY - NOMINATION FORM

(Continuation Sheet)

Missouri	
COUNTY	
Lincoln	
FOR NPS USE ONL	Y
ENTRY NUMBER	DATE

(Number all entries)

7. #2

#### ROSS, SHAPLEY, HOUSE

lintels, and those on the southeast wall have brick, segment arch lintels.

The primary entrance is given prominence by having paneled wood jambs. This doorway and the one directly above it both have double-cross doors, and a four-light transom above.

<u>Windows</u>. On the primary facade two windows to each floor frame the central doors. The gable ends, originally blind, have windows inserted ca. third quarter nineteenth century to 1893. On the southeast gable end the windows occur at the east end on both the first and second stories. (The first story window is a 3-window, polygonal bay, put on ca. third-quarter nineteenth century, prior to 1893.) On the northwest gable end the windows occur at the west end on both stories.

Exposed windows on the northern end of the northeast (rear) wall correspond to those on the front wall. Original windows at the southern end of the wall have been masked by the rear ell addition. On the first floor the more easterly window has become an interior doorway between the front room and the rear ell, and the next window is concealed by a stairway to the second floor. The lintels of the second floor windows are visible above the ceiling in the loft.

The ell has two windows on each story, centered on the northeastern half of the southeast and northwest walls. An additional window occupies the second story level of the northwest facade on the ell.

Windows on the primary facade have jack arch lintels, those on the rear facade have monolithic stone lintels, and those on the rear ell have brick segment arch windows.

The windows, except in the basement, have two-over-two light, double-hung sash, except for one window on the rear ell with six-over-six light, double-hung sash. The original nine-over-nine light, sash are stored in the basement. Sash openings for the original windows are 2'10'' x 6'6'' with the sill 28'' high on the first floor and 25'' high on the second floor.

#### Roof

Both main block and ell have simple, ridge roofs, with ridges at right angles to each other. The rear ell roof overlaps the front block roof, but the ridges do not intersect.

## UNITED STATES DEPARTMENT OF THE INTERIOR NATIONAL PARK SERVICE

# NATIONAL REGISTER OF HISTORIC PLACES INVENTORY - NOMINATION FORM

STATE	
Missouri	
COUNTY	
Lincoln	
FOR NPS USE ON	LY .
ENTRY NUMBER	DATE
	1

(Continuation Sheet)

(Number all entries)

7. #3

#### ROSS, SHAPLEY, HOUSE

The present sheathing material is galvanized iron<sup>2</sup> but a section of the original wood shingles is visible on the northeast slope of the main block roof, under the overlap of the rear ell roof.

A simple, boxed cornice, with plain frieze occurs on all walls, (with a partial return on the northeast and southeast gable ends) except the northwest gable end. This end has a simple fascia board ending at the chimney line, probably duplicating the original design. The cornice dates from the late nineteenth century.<sup>3</sup>

#### INTERIOR

Floor plans (refer to drawings)

Basement. The basement is accessible by means of two short, straightrun stairs down from the exterior of the building. One stair is at the south end of the southeast wall, and the other is at the juncture of the front block and the rear ell, on the north side.

The basement is under the entire front part of the house and is divided into two rooms by a two foot thick stone wall, previously described. The floor joists are logs, flattened on top to receive the flooring, at the southeast and northwest ends of the basement. The central section has 3" x 10" joists, 20 1/2 inches apart.

A crawl space is under the rear ell.

<u>First Floor</u>. The front door opens into a 10 feet wide central stairhall. To the southeast and northwest, the hallway opens into rooms averaging 20' x 20' size. The stairway rises from the southeast side of the central hall.

The southeast room connects through the former southernmost first story window on the rear wall, to the rear ell, a kitchen room. A second stairway to the second floor is located in the west corner of the kitchen. The floor to ceiling height is 11'5" in the front block, and nine feet high in the ell.

Second Floor. The second floor repeats the first floor plan, with the exception that a closet wall has been inserted into the rear ell room, dividing it into two small rooms. The floor to ceiling height is 10'2" in the front block, and nine feet high in the ell.

<u>Loft</u>. The loft over the main block is not continuous with that over the rear ell.

## UNITED STATES DEPARTMENT OF THE INTERIOR NATIONAL PARK SERVICE

# NATIONAL REGISTER OF HISTORIC PLACES INVENTORY - NOMINATION FORM

(Continuation Sheet)

TATE	
Missouri	
OUNTY	
Lincoln	
FOR NPS USE OF	NLY_
ENTRY NUMBER	DATE
***************************************	_ <del> </del>

(Number all entries)

7. #4

#### ROSS, SHAPLEY, HOUSE

In the rear ell loft one can see how this portion of the building is laid up against the original front, main block.

#### Stairways

The main stair is a "U" plan with ornamental scroll work on the open string stairs. The balusters are simple, plain, squared pieces except for the turns of the stair, where the balusters are noticeably tapered and rounded. The bannister is simple, turns a right angle at the turning of the stairs, and is rounded on its upper surface.

The secondary stair, from the kitchen to the rear wing loft, is boxed and narrow.

#### Flooring

All floors are random width planks.

#### Wall and Ceiling Finish

Interior walls and ceilings are for the most part, finished in plaster on hand-split wood lathe.

The first floor east room has a stamped, sheet metal ceiling. The second floor west room has a sheet rock ceiling.

A wainscoting occurs in all rooms, except the second floor rear ell.

#### Doorways and doors

Doorways are simply framed with mitered joints at the upper corners, except in the rear wing where simple wood cornices top the doorways. Most doors are the double-cross type, except in the rear ell where there are several plank doors. Interior screen doors were added during a time when the house was subdivided for numerous tenants.

#### Windows

The original windows in the front block have paneled reveals which splay inward at a slight angle on the first floor, and at a broader angle on the second floor.

Later windows have plain reveals.

#### Fireplaces

Fireplaces occur in each interior room, above basement level, except in the second story rear wing which has a stove flue. The fireplaces

## UNITED STATES DEPARTMENT OF THE INTERIOR NATIONAL PARK SERVICE

# NATIONAL REGISTER OF HISTORIC PLACES INVENTORY - NOMINATION FORM

STATE	
Missouri	
COUNTY	
Lincoln	
FOR NPS USE ON	LY
ENTRY NUMBER	DATE
	1

ţ.\_\_

(Continuation Sheet)

(Number all entries)

7. #5

#### ROSS, SHAPLEY, HOUSE

have been closed during conversion to stove heat, but several hand-carved mantles remain in place. The finest remaining fireplace is in the first floor south room. It has three, Adamesque sumburst medallions, fluted pilasters, and a cornice. It is accompanied by a built-in cabinet to the south, displaying the same motifs. A similar cabinet survives in the room above on the second floor. Other cabinets have been removed and/or replaced with later, inappropriate construction, or windows.

#### Hardware

Doorway hardware includes late nineteenth century, surface-mounted (rim) locks. None of the original hardware survives.<sup>5</sup>

#### OUTBUILDINGS

Two non-original outbuildings survive. These structures, northwest of the house, include a cow shed and a privy. They are both of wood frame construction, and in poor condition.

#### SITE

The site is not characterized by any original landscape features. Two cisterns are located near the house--one at the west corner of the main block, the other near the northwest corner of the rear ell.

#### **FOOTNOTES**

- 1. Based on the 1893 old view showing these windows in place.
- 2. William B. Lane, field report, February 12, 1970, p. 7.
- 3. Lane. p. 11.
- 4. Lane. p. 7.
- Lane, p. 9.

This description of the physical appears of the building is based on data included in the field report by William B. Lane, A.I.A., February 12, 1970; and the Historic American Buildings Survey drawings and "Historical Notes on the Shapley Ross House," prepared by Gerhardt Kramer, F.A.I.A., January 26, 1972.

PERIOD (Check One or More as	Appropriate)		·
Pre-Columbian	☐ 16th Century	☐ 18th Century	20th Century
☐ 15th Century	☐ 17th Century	□ 19th Century	
SPECIFIC DATE(\$) (If Applicat	de and Known) CONSTRU	cted ca. 1818-1821	
AREAS OF SIGNIFICANCE (Ch	-		•
Abor iginal	☐ Education	Political	Urban Planning
Prehistoric	Engineering	Religion/Phi	(Specify)
☐ Historic	☐ Industry	losophy	early settlement
Agriculture	nvention	Science	
Architecture	☐ Londscope	Sculpture	
☐ Art	Architecture	Social/Human-	
Commerce	Literature	itarian	
Communications	Military	☐ Theater	
Conservation	Music	Transportation	<del></del>

STATEMENT OF SIGNIFICANCE

The Shapley Ross House is significant as a large-scale, early, rare example of residential architecture in stone, masonry construction in Missouri. The design is a five-bay, two-story, center hall scheme, typical of the early to mid-nineteenth century in Missouri. The original owner-builder had a major role in the development of Moscow Mills. He was one of the town founders, the most wealthy man in the county, and the operator of the local grist and saw mills.

Buford L. Pickens, F.A.I.A., Professor of Architecture, Washington University, St. Louis, Missouri, has pointed out the relatedness of this Missouri example to Virginia antecedents such as the original portion of Tuckahoe in Goochland County, Virginia. Tuckahoe has a 56 foot facade, central hall plan, and flush end walls. Ross came to Missouri from Virginia. 2

The house displays a high order of workmanship in the stonework, and in the remains of original, interior millwork exhibiting the influence of the Adam style.

#### ORIGINAL AND SUBSEQUENT OWNERS

#### Shapley Ross

County records show that Ross purchased from Mackey Wherry 400 Arpens of land in Lincoln County in what is now Moscow Mills, on November 16, 1818 for \$1361.00.3

The 1821 tax list of Lincoln County lists Shapley Ross as the wealthiest man in the county. That year Ross paid taxes on his stone house. A Ross died before October 15, 1822, the day on which Mervin Ross was appointed administrator of his estate. His personal property settlement dated October 16, 1823 listed 29 slaves and other household goods divided among his heirs. The number of slaves, in addition to six heirs bearing the name Ross, indicates a generous supply of labor available to Ross for the construction of the house, as well as for his milling operation. These documents establish the date of construction at 1818-1821.

## UNITED STATES DEPARTMENT OF THE INTERIOR NATIONAL PARK SERVICE

# NATIONAL REGISTER OF HISTORIC PLACES INVENTORY - NOMINATION FORM

TATE	
Missouri	
OUNTY	<u>-</u>
Lincoln	
FOR NPS USE ON	ILY
ENTRY NUMBER	DATE

(Continuation Sheet)

(Number all entries)

8. #1

#### ROSS, SHAPLEY, HOUSE

In June, 1819 Shapley Ross purchased a tract of land containing approximately 160 acres of land from Jeremiah Groshong and his wife, Polly. The tract contained a grist mill and a saw mill.7 Also in June, 1819 Ross together with James Duncan, John Geiger and Morgan Wright purchased additional land from Groshong<sup>8</sup> and platted the town of Moscow, later Moscow Mills, on the tract, on March 17, 1821.9

The State Historical Survey and Planning Office's current theme study of grist mills and related structures, has shown that millers were typically the town founders and wealthiest citizens because of the essential service they offered, and the locations generally selected for mill sites. Mills served as local gathering places, and were frequently the nuclei of new towns.

On September 2, 1831 Mary Ross, widow of Shapley Ross sold lots 7 and 8 of Block 6, including the "stone dwelling House [and] stone meal house...," to Henry Martin. 10

#### Later Owners

The subsequent chain of ownership if vague as no abstract to the property exists.  $\fill$ 

Martin evidently held the property for a long time. One report states he owned a great deal of land, his large, stone house was in an excellent state of preservation, and his numerous slave cabins were located near his house. Reference is made also to his extensive vegetable and flower garden. 12

After 1831 Martin took over the grist milling operation in Moscow Mills.

The Depping family purchased the house in 1946 from a Mr. Parsons to provide shelter for hired help. Miss Mildred Depping, the present owner, plans to restore the house as a public museum. 13

#### CHRONOLOGY OF CONSTRUCTION

Old views, analysis of the structure, and documentary sources indicate at least four and possibly six construction stages for the Shapley Ross House.

## UNITED STATES DEPARTMENT OF THE INTERIOR NATIONAL PARK SERVICE

# NATIONAL REGISTER OF HISTORIC PLACES INVENTORY - NOMINATION FORM

TATE	
Missouri_	
COUNTY	
Lincoln	
FOR NPS USE ON	LY
ENTRY NUMBER	DATE

(Continuation Sheet)

(Number all entries)

8. #2

#### ROSS, SHAPLEY, HOUSE

- 1. There is the possibility that Mackey Wherry built the northwest end of the house which has the unbalanced interior stone partition wall dividing it from the rest of the house. 14 Neither architects Kramer nor, Lane who examined the building in order to establish the chronology of construction mentioned this possibility, however. 15
- 2. Very early the house had its front block and a detached kitchen to the rear. 16
- 3. In an old view dated 1893<sup>17</sup> the house is shown with a two-story, front porch and a shed-roof ell to the rear in the location of the present ell. The first story polygonal bay window, and the southeast gable end window on the second story, are present. This view suggests the attachment of the kitchen to the house, in an enlargement to the rear. The front porch has two-story, neo-classic derivative, round columns. At the west end of the porch there is a board and batten enclosure.

A 7" x 8" x 56'6" hand-hewn beam with a two foot splice near its center, removed from the front porch in the 1968 remodeling project is in storage in Moscow Mills. This support plate spanned the entire width of the primary facade. If this member was not an original feature of the house, its form and construction indicate an early date for its addition to the fabric. 18 Kramer cites ca. 1870 as the date of construction.

An early date for a front porch is further indicated by the framing members of the central door on the second floor. One of these posts, exposed by prying loose the door frame, for examination, is handhewn, with bark covering one side. The post is continuous from the floor to the doorway lintel. This framing member would more likely have been spliced had the doorway been originally a window. An early doorway at second floor indicates an early date for a front porch. The present concrete threshold of this doorway could be a replacement of the original stone threshold.

In the 1893 view the shed-roof ell is partially obscured by a bush, but a crisp line of juncture with the front block indicates a dissimilar building material--possibly wood-frame with board and batten sheathing—abutting the remaining portion of the original stone kitchen walls.

4. The small enclosure on the front porch in the 1893 view may represent a fourth stage in construction.

## UNITED STATES DEPARTMENT OF THE INTERIOR NATIONAL PARK SERVICE

# NATIONAL REGISTER OF HISTORIC PLACES INVENTORY - NOMINATION FORM

STATE	_
Missouri	
COUNTY	
_Lincoln	
FOR NPS USE ON	LY
ENTRY NUMBER	DATE

(Continuation Sheet)

(Number all entries)

8. #3

#### ROSS, SHAPLEY, HOUSE

5. A photograph dated ca. 1895-1900 shows the house in a considerably changed state from that of stages 3-4, exhibiting different, late, nineteenth century remodeling features.

The shed roof has been removed from the rear ell. A second story in brick construction has been added to the first story stone rear ell. The boxed cornice has been put on.

The front of the house has been completely altered. The neo-classic porch has been replaced with a late, nineteenth century model. There are turned posts, instead of round columns, and ornamental balusters, and brackets at the top of the posts. There is a large, front ell wing at the west end of the primary facade. It is a two-story structure under a ridge roof which intersects the main roof. This structure is sheathed in butted, wood siding painted to simulate stone masonry construction. Raised wood pieces at the corners, imitate quoins. An east porch appears under the east balcony.

On the rear of the house one can see the line of a shed-roof structure at the juncture of the ell and the front block. This structure appears in an old view dated ca. 1900.21

6. The front wing, front poch, east porch and rear shed room were all removed in 1968, giving the house its present appearance.

The numerous additions to the house, sealing off windows, disrupted, ventilation and created the need for new openings in the gable ends. Access to the front ell was gained through the two westernmost windows of the front block which were at that time converted to doorways. They have since been reverted to windows. A rear window similarly converted to a doorway has been returned to its original function.

#### COMPARISON WITH OTHER STONE HOUSES IN MISSOURI

In four years of inventorying the historic sites in Missouri, the State Historical Survey and Planning Office has compiled files on 51 nineteenth century residences construced of stone. These houses fall into the following basic categories: 1) 5-bay, 2-story; 2) 5-bay, 1-story; 3) 3-bay, 2-story; 4) 3-bay, 1-story; and 5) variant forms, mostly dating from the late nineteenth century. Of these types there are listed to date: 17 in the first category; 2 in the second category; 9 in the third category; 5 in the fourth category; and 18 in the fifth category.

## UNITED STATES DEPARTMENT OF THE INTERIOR NATIONAL PARK SERVICE

## NATIONAL REGISTER OF HISTORIC PLACES INVENTORY - NOMINATION FORM

STATE Missouri	
COUNTY	<del></del>
Lincoln	
FOR NPS USE ON	LY
ENTRY NUMBER	DATE
	<del> </del>

(Continuation Sheet)

(Number all entries)

8. #4

#### ROSS, SHAPLEY, HOUSE

Geographic distribution is generally tied to the major rivers. No conclusive data have yet been gathered on the origins of the original owner-builders.

The data indicates relative rarity of early, symmetrically designed stone houses in Missouri. No other stone houses, in any of the five categories, have been listed to date for Lincoln County. The Shapley Ross House is one of a diminishing few Missouri examples of early nineteenth century residences constructed of stone.

#### PRESENT STATUS

The owner has retained Gerhardt Kramer, F.A.I.A., Missouri State
Preservation Coordinator, to advise her on development of the house.
Kramer's plan includes 1) adaption of the rear wing for residentcurator living quarters; 2) renovation of the original rock structure,
re-installing the nine-over-nine light, double-hung sash in the windows, and 3) preparation of the main four rooms and central hall as
a historic house museum.

A later stage of the project includes restoration of the front porch based on the study of old views and the surviving structural members of the porch.22

The survey of Missouri's stes of historic and architectural significance is based on the selection of sites as they relate to theme studies in Missouri history as outlined in Missouri's "Comprehensive Statewide Historic Preservation Plan." The Shapley Ross House is therefore being nominated to the National Register of Historic Places under the Residential Architecture Theme Study because (1) it is a rare, early example of the five-bay, two-story, center hall scheme in stone masonry construction, and (2) because, as a large scale house with Virginia antecedents, it manifests the local prominence of the original owner-builder.

#### **FOOTNOTES**

- 1. Buford L. Pickens, statement made at the May 15, 1971 meeting of the Advisory Council on Historic Sites and Buildings to the Missouri State Park Board.
- 2. Ross family genealogy. p. 28.

## UNITED STATES DEPARTMENT OF THE INTERIOR NATIONAL PARK SERVICE

# NATIONAL REGISTER OF HISTORIC PLACES INVENTORY - NOMINATION FORM

STATE	
Missouri	
COUNTY	
Lincoln	
FOR NPS USE ON	(LY
ENTRY NUMBER	DATE

(Continuation Sheet)

(Number all entries)

8. #5

#### ROSS, SHAPLEY, HOUSE

- St. Charles County, Missouri. Deed Book E, 1818-1821, p. 365.
- 4. <u>History of Lincoln County, Missouri</u> (Chicago: The Goodspeed Publishing Co., 1888), p. 417.
- 5. Lincoln County, Missouri, Wills and Letters of Administration, October 15, 1821 to April 4, 1848, p. 3.
- 6. Lincoln County, Missouri, Deed Book C, p. 261.
- 7. Ibid., pp. 16-17.
- 8. Ibid.
- 9. History of Lincoln County, Missouri, 1888, p. 417.
- 10. Lincoln County, Missouri Deed Book B, pp. 222-223.
- 11. Mildred Depping, present owner of the property, interview, May 18, 1971.
- 12. <u>Troy [Missouri] Free Press</u>, January 5, 1917.
- 13. Mildred Depping, letter to the State Historical Survey and Planning Office, December 30, 1969.
- 14. Pickens, 1971.
- 15. William B. Lane, A.I.A., Field Report, February 12, 1970; and Gerhardt Kramer, F.A.I.A., "Historical Notes on the Shapley Ross House," January 26, 1972.
- 16. Kramer, 1972.
- 17. Miss Depping submitted the photograph. Date is based on the age of the baby in arms included in the foreground.
- 18. George A. Feltz, Structural notes on the house, June, 1971. William B. Lane and M. Patricia Holmes, structural examination, May 18, 1971.
- 19. Kramer, 1972.
- 20. Lane and Holmes, May 18, 1971.

## UNITED STATES DEPARTMENT OF THE INTERIOR NATIONAL PARK SERVICE

# NATIONAL REGISTER OF HISTORIC PLACES INVENTORY - NOMINATION FORM

Missouri						
COUNTY						
	Lincoln					
	FOR NPS USE ON	LY				
ENT	RY NUMBER	DATE				

(Continuation Sheet)

(Number	all	entries)	
---------	-----	----------	--

8. #6

#### ROSS, SHAPLEY, HOUSE

- 21. State Historical Society of Missouri, County Photograph files, reference, Lincoln County.
- 22. Gerhardt Kramer, letter to the State Historical Survey and Planning Office, December 10, 1971.

1				•			
	7	Donning	Mildred .nresen		سايد عي	 	•

9. MAJOR BIBLIOGRAPHICAL REFERENCES

- Depping, Mildred, present owner of the property. Interview by M, Patricia Holmes, May 18, 1971.
- 2. Letter to the State Historical Survey and Planning Office, December 30, 1969.
- Feltz, George A. Structural notes on the [Shapley Ross] House. June, 1971.

	11 V 11 V 12 V 1		Togania ya Tanasa Kapinaga	100	2000		70141 11156 10141 11156			eige er er er en en er er		
	DEFINING A RECTARGE EDGATING THE THE ENTE			1	D LATITUDE AND LONGITUDE COORDINATES DEFINING THE CENTER POINT OF A PROPER OF LESS THAN TEN ACRES							
CORNER	L.A	TITUDE	LONGITUDE		K	L	ATITUD	E		ONGITUE	DE	
	Degrees Mi	nutes Seconds	Degrees Minutes	Seconds		Degrees	Minutes	Seconds	Degrees	Minutes	Seconds	
NW	•		,			90 °	54 '	53 N	38 °	56	57 W	
NE	°		• •	,		30	0 1	00 11	50	00	J, 1	
SE	•	, ,	,	*	ļ	<u> </u>						
SW	0	•	0 ,		<u></u>	1			1		<u> </u>	
			INATED PROPE			s than		Cres	UNDARIE		· · ·	
<b></b>	L STATES	AND COUNTIES	FOR PROPERT	CODE		COUNTY	A I E OR C	JUNIT BO	JONDARIE		CODE	
STATE:				- 000	-	COUNTY					CODE	
STATE:				CODE	+	COUNTY:					CODE	
31212.				1002	-	200111						
STATE:			·=-"	CODE		COUNTY:			<del></del>		CODE	
1					-							
STATE:				CODE	+	COUNTY:					CODE	
					7							
II. FORM	DDEPAR	EN RY										
	ND TITLE:			4,	22							
	j	M. Patric	ia Holmes,	Chief	Α	rchited	tural	Histor	ian	11.		
ORGANI	ZATION	Missouri	State Park	Board			<del></del>	<u> </u>	DATE		1.	
	State Historical Survey an					nd Planning Office July 15, 1972						
STREET	AND NUMB	ER:			-							
1		P.O. Box	176, 1204	Jeffer	s 0	n Build	ling				· · · · ·	
CITY OF						TATE		·	;		CODE	
	(	Jefferson	City		_[_	Mis	souri	651	01 !		29	
12. STAT	E LIAISON	OFFICER C	ERTIFICATION					L REGIST	ER VERI	FICATIO	N	
tiona	Historic F	Preservation A	on Officer for th act of 1966 (Pub s property for in	dic Law			certify to the control of the contro	that this pr	roperty is	included	in the	
in the evalu	National lated according the National later according to the N	Register and o ding to the cri ional Park Ser	certify that it hat teria and proceduce. vice. The reco	is been dures set	ll.	Chief, (	Office of	Archeolog	y and His	storic Pre	eservation	
	of signific	ance of this n		<b>X</b>							•	
						Date		· · · · · · · · · · · · · · · · · · ·			·	
Name					_	ATTEST						
Títle		Jaeger, or, Misso	Jr. uri State I	Park		ATTEST		•				
Boar	Board, and Missouri State Liaison Officer					 Date	Keep	er of The l	Vational I	Register	<del></del>	
Date					- U							

## UNITED STATES DEPARTMENT OF THE INTERIOR NATIONAL PARK SERVICE


# NATIONAL REGISTER OF HISTORIC PLACES INVENTORY - NOMINATION FORM

TATE	
Missouri	
COUNTY	
Lincoln	
FOR NPS USE ON	LY
ENTRY NUMBER	DATE

(Continuation Sheet)

(Number all entries)

- 9. #1 ROSS, SHAPLEY, HOUSE
- 4. <u>History of Lincoln County, Missouri</u>. Chicago: The Good-speed Publishing Co., 1888.
- 5. Kramer, Gerhardt, F.A.I.A. "Historical Notes on the Shanley Ross House," and Historical American Buildings Survey drawings, January 26, 1972.
- 6. Letter to the State Historical Survey and Planning Office, December 10, 1971.
- 7. Lane, William B., A.I.A. Architectural Consultant Field Report, February 12, 1970. Contracted by the Missouri State Park Board, and on file at its Central Office, P.O. Box 176, 1204 Jefferson Building, Jefferson City, Missouri 65101.
- 8. and M. Patricia Holmes, Structural examination, May 18, 1971.
- 9. Lincoln County, Missouri. Deed Book B.
- 10. \_\_\_ Deed Book B.
- 11. Wills and Letters of Administration, October 15, 1821 to April 4, 1848.
- 12. Pickens, Buford L., F.A.I.A. Statement, May 15, 1971, before the Advisory Council on Historic Sites and Buildings to the Missouri State Park Board.
- 13. Ross family genealogy. Submitted by Miss Mildred Depping, June, 1972.
- 14. Ross, Shapley, house. Old view, 1893.
- 15. Ross, Shapley, house. Old view ca. 1895--1900.
- 16. St. Charles County, Missouri. Deed Book E, 1818-1819.
- 17. State Historical Society of Missouri. County Photograph Files, ref. Lincoln County.
- 18. Troy [Missouri] Free Press. January 5, 1917.



# OLD ROCK HOUSE (SHAPLEY ROSS HOUSE)

COUNTY: Lincoln

LOCATION: 2nd & Mill streets, Moscow Mills, Mo.

OWNER: ADDRESS: Miss Mildred Depping 6930 Jamieson Ave, St. Louis, Mo.

DATE APPROVED BY A.C.: 06-10-72

DATE SENT TO JEFF. CITY: 08-16-72

DATE OF REC. IN D.C.: DATE SENT TO D.C.: 08-21-72

08-28-72

DATE PLACED ON NATIONAL REGISTER: 10-18-72

DATE AWARDED CERTIFICATE (AND PRESENTOR):

07-29-75 Survey Office staff


DATE FILE REVIEWED:

The Shapley Ross House is significant as a large-scale, early, rare example of residential architecture in stone, masonry construction in Missouri. The design is a five-bay, two-story, center hall scheme, typical of the early to mid-nineteenth century in Missouri. The original owner-builder had a major role in the development of Moscow Mills. He was one of the town founders, the most wealthy man in the county, and the operator of the local grist and saw

SHAPLEY ROSS HOUSE

Moscow Mills, Lincoln County, Mo.
Photographer: James M. Denny
Date: June 22, 1981
Neg. Loc.: Department of Natural Resources
Historic Preservation Program
P.O. Box 176
Jefferson City, Mo. 65102

Primary facade, looking Southeast.




SHAPLEY ROSS HOUSE

Moscow Mills, Lincoln County, Mo.
Photographer: James M. Denny
Date: June 22, 1981
Neg. Loc.: Department of Natural Resources
Historic Preservation Program
P.O. Box 176
Jefferson City, Mo. 65102

Primary facade, looking East.

52



> 5

SHAPLEY ROSS HOUSE

3 of 20

Moscow Mills, Lincoln County, Mo. Photographer: James M. Denny Date : June 22, 1981


Neg. Loc. : Department of Natural Resources

Historic Preservation Program

P.O. Box 176

Jefferson City, Mo. 65102


Looking Southeast.



SHAPLEY ROSS HOUSE
Moscow Mills, Lincoln County, Mo.
Photographer: James M. Denny
Date: June 22, 1981
Neg. Loc.: Department of Natural Resources
Historic Preservation Program
P.O. Box 176
Jefferson City, Mo. 65102


Looking North.

5 6



SHAPLEY ROSS HOUSE
Moscow Mills, Lincoln County, Mo.
Photographer: James M. Denny
Date: June 22, 1981
Neg. Loc.: Department of Natural Resources
Historic Preservation Program
P.O. Box 176
Jefferson City, Mo. 65102

Looking South.



SHAPLEY ROSS HOUSE

6 of 20

Moscow Mills, Lincoln County, Mo. Photographer: James M. Denny Date : June 22, 1981

Date : June 22, 1981 Neg. Loc. : Department of Natural Resources

Historic Preservation Program

P.O. Box 176

Jefferson City, Mo. 65102

Entrance door, looking East.



SHAPLEY ROSS HOUSE

7 of 20

Moscow Mills, Lincoln County, Mo. Photographer: James M. Denny Date : June 22, 1981

: Department of Natural Resources Historic Preservation Program Neg. Loc.

P.O. Box 176

Jefferson City, Mo. 65102

Window, looking East.



SHAPLEY ROSS HOUSE
Moscow Mills, Lincoln County, Mo.
Photographer: James M. Denny
Date: June 22, 1981
Neg. Loc.: Department of Natural Resources
Historic Preservation Program
P.O. Box 176
Jefferson City, Mo. 65102

Basement, looking Northwest.



9 of 20

Moscow Mills, Lincoln County, Mo. Photographer: James M. Denny Date: June 22, 1981

Neg. Loc. : Department of Natural Resources Historic Preservation Program

P.O. Box 176

Jefferson City, Mo. 65102

Interior view, entrance door, looking Northwest.



10 of 20

Moscow Mills, Lincoln County, Mo. Photographer: James M. Denny


Date : June 22, 1981 Neg. Loc. : Department of Natural Resources

Historic Preservation Program

P.O. Box 176

Jefferson City, Mo. 65102

Interior view, stair, looking East.



11 of 20

Moscow Mills, Lincoln County, Mo.

Photographer: James M. Denny

Date : June 22, 1981

Neg. Loc. : Department of Natural Resources

Historic Preservation Program


P.O. Box 176

Jefferson City, Mo. 65102


Detail, stair.



Detail, stair, looking South.



Interior view, south parlor, looking Southwest.



Detail, south parlor mantel, looking Southeast.



15 of 20

Moscow Mills, Lincoln County, Mo. Photographer: James M. Denny Date

: June 22, 1981 : Department of Natural Resources Historic Preservation Program Neg. Loc.

P.O. Box 176

Jefferson City, Mo. 65102

Detail door from south parlor to rear ell looking Southeast.



North parlor looking North.



Detail, north parlor mantel, looking North.

57



2.6

SHAPLEY ROSS HOUSE

18 of 20

Moscow Mills, Lincoln County, Mo. Photographer: James M. Denny Date : June 22, 1981

Neg. Loc. : Department of Natural Resources

Historic Preservation Program

P.O. Box 176

Jefferson City, Mo. 65102

2nd floor looking from south room across hall to north room.




2nd floor north room looking North.





2nd floor south room looking South.





## EXTRA PHOTOS









































































ca. 1895-1900


























. 0

•

